

AD-A156 529


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
BUTTERFIELD POND DAM (..(U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV MAR 88


1/2

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A156 529

CONNECTICUT RIVER BASIN
WASHINGTON, NEW HAMPSHIRE

BUTTERFIELD POND DAM

NH 00233

NHWRB NO. 245.01

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

Copy available to DTIC does not
permit fully legible reproduction



DTIC
SELECTED
JUL 08 1985
S D G

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

DTIC FILE COPY

MARCH 1980

EXEMPTION STATEMENT A
Approved for public release
Distribution Unlimited

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NH 00233	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Butterfield Pond Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE March 1980
		13. NUMBER OF PAGES 80
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Connecticut River Basin, Washington, New Hampshire, and Ashuelot River.		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam is a stone filled gravity structure about 210 ft. long and 12.5 ft. high. The dam is considered to be in very poor condition. It is small in size with a significant hazard potential. The recommendations and remedial measure should be implemented as soon as possible. <i>Keywords wanted:</i>		



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02254

REPLY TO
ATTENTION OF:

NEDED

7 OCT 1980

Honorable Hugh J. Gallen
Governor of the State of New Hampshire
State House
Concord, New Hampshire 03301

Dear Governor Gallen:

Inclosed is a copy of the Butterfield Pond Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam.

Butterfield Pond Dam has been rated as being in very poor condition. The brief assessment and Section 3 of this report contain a discussion as to the condition of the dam. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Water Resources Board, the cooperating agency for the State of New Hampshire. In addition, a copy of the report has also been furnished the owner, The State of New Hampshire Resource and Economic Development Dept., Division of Parks and Recreation.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Water Resources Board for your cooperation in carrying out this program.

Sincerely,

MAX B. SCHEIDER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated

BUTTERFIELD POND DAM
NH 00233
NHWRB 245.01

CONNECTICUT RIVER BASIN
WASHINGTON, NEW HAMPSHIRE

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A/1	23-08

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



**NATIONAL DAM INSPECTION PROGRAM
PHASE I - INSPECTION REPORT
BRIEF ASSESSMENT**

Identification No: NH 00233
Name of Dam: Butterfield Pond Dam
Town: Washington
County and State: Sullivan, New Hampshire
Stream: Ashuelot River
Date of Inspection: December 6, 1979

Butterfield Pond Dam is a stone-filled gravity structure about 210 feet in overall length and 12.5 feet high from crest of dam to toe of slope. Located in the center of the dam is the principal overflow section which is 57 feet long and consists of a concrete capped, stone weir with concrete training walls. Near the middle of the overflow section is a 16.2 feet wide by 0.2 feet deep low flow spillway weir cast into the concrete cap. Located at the right training wall of the overflow section is the outlet structure which consists of a reinforced concrete sluice gate structure containing a wood plank sluice gate. Both the left and right embankments consist of unmortared stone. There is no emergency spillway.

The dam impounds Butterfield Pond and adjoining May Pond and the discharge flows through the Ashuelot River in a southwesterly direction approximately 6.0 miles to Ashuelot Pond. The original purpose of the dam is reported to have been to supply power to a mill, but its present use is recreational. The pond is 1.25 miles in length with a surface area of about 126 acres. The maximum storage capacity is about 590 acre feet.


As a result of the visual inspection of this facility, the dam is considered to be in ~~VERY POOR~~ condition. Major concerns are: a sinkhole in the earthfill on the upstream side of the right stone embankment with pond water flowing into the sinkhole; subsidence of the crest and bulging of the downstream slope of the left stone embankment; severely broken and eroded condition of the concrete cap and the downstream concrete facing of the overflow section; and significant leakage and seepage at numerous locations along the downstream face of the dam.

This dam is classified as SMALL in size and a SIGNIFICANT hazard structure in accordance with the recommended guidelines established by the Corps of Engineers. The test flood for this dam therefore, ranges from a 100-year flood to one-half the Probable Maximum Flood (1/2 PMF). Due to the very poor condition of the dam, the 1/2 PMF was selected for this hydrologic analysis. The test flood inflow was estimated to be 7,500 cfs and resulted in a routed test flood outflow equal to 5,430 cfs which would overtop the dam crest by about 5.3 feet. The maximum

spillway discharge capacity with the water level at the dam crest was estimated to be 160 cfs or about 3 percent of the routed test flood outflow. A major breach with the reservoir surface at the dam crest would overtop New Hampshire Route 31, by 2 to 3 feet, where it crosses the channel 350 feet below the dam. This could result in significant damage to the bridge and roadway. Although the potential for loss of life exists if the bridge were to wash out, no loss of life is anticipated.

It is recommended that the owner engage a qualified engineer to: investigate the sinkhole, crest subsidence, erosion channel on the downstream slope, and seepage at the left end of the right stone embankment; investigate the subsidence of the crest, sinkhole in the upstream earthfill, bulging of the downstream slope and seepage at the downstream toe of the left stone embankment; investigate the structural condition of the overflow section and the sluice gate; and do a detailed hydrologic-hydraulic investigation to assess further the potential of overtopping the dam, the adequacy of the spillway to pass the test flood, and the need for and means to increase project discharge capacity. It is also recommended that the owner clear brush and trees from a zone 25 feet wide on each side of the discharge channel between the dam and the highway bridge downstream of the dam.

The recommendations and remedial measures are described in Section 7 and should be addressed by the owner within one year after receipt of this Phase I Inspection Report.



Kenneth M. Stewart

Kenneth M. Stewart
Project Manager
N.H.P.E. 3531

S E A Consultants Inc.
Rochester, New Hampshire

This Phase I Inspection Report on Butterfield Pond Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Aramast Mahtesian

ARAMAST MAHTESIAN, MEMBER
Geotechnical Engineering Branch
Engineering Division

Carney M. Terzian

CARNEY M. TERZIAN, MEMBER
Design Branch
Engineering Division

Richard J. DiBuono

RICHARD DIBUONO, CHAIRMAN
Water Control Branch
Engineering Division

APPROVAL RECOMMENDED:

Joe B. Fryar

JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and

rarity of such a storm event, finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The Phase I investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespassing and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
Letter of Transmittal	i
Brief Assessment	ii
Review Board Page	iv
Preface	v
Table of Contents	vii
Overview Photo	ix
Location Map	x
1. PROJECT INFORMATION	1-1
1.1 General	1-1
1.2 Description of Project	1-1
1.3 Pertinent Data	1-3
2. ENGINEERING DATA	2-1
2.1 Design	2-1
2.2 Construction	2-1
2.3 Operation	2-1
2.4 Evaluation	2-1
3. VISUAL INSPECTION	3-1
3.1 Findings	3-1
3.2 Evaluation	3-3
4. OPERATIONAL AND MAINTENANCE PROCEDURES	4-1
4.1 Operational Procedures	4-1
4.2 Maintenance Procedures	4-1
4.3 Evaluation	4-1

<u>Section</u>	<u>Page</u>
5. EVALUATION OF HYDROLOGIC/HYDRAULIC FEATURES	5-1
5.1 General	5-1
5.2 Design Data	5-1
5.3 Experience Data	5-1
5.4 Test Flood Analysis	5-1
5.5 Dam Failure Analysis	5-1
6. EVALUATION OF STRUCTURAL STABILITY	6-1
6.1 Visual Observations	6-1
6.2 Design and Construction Data	6-1
6.3 Post-Construction Changes	6-2
6.4 Seismic Stability	6-2
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	7-1
7.1 Dam Assessment	7-1
7.2 Recommendations	7-2
7.3 Remedial Measures	7-2
7.4 Alternatives	7-3

APPENDICES

APPENDIX A - INSPECTION CHECKLIST	A-1
APPENDIX B - ENGINEERING DATA	B-1
APPENDIX C - SELECTED PHOTOGRAPHS	C-1
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1



OVERVIEW PHOTO - BUTTERFIELD POND DAM





Fig. 1
Butterfield Pond Dam
LOCATION PLAN
 2 0 2 4
Scale in Miles

**NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT
BUTTERFIELD POND DAM**

**SECTION 1
PROJECT INFORMATION**

1.1 General

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. S E A Consultants Inc. has been retained by the New England Division to inspect and report on selected dams in the State of New Hampshire. Authorization and notice to proceed were issued to S E A Consultants Inc. under a letter of November 5, 1979 from William Hodgson, Jr., Colonel, Corps of Engineers. Contract No. DACW33-80-C-0008 has been assigned by the Corps of Engineers for this work.

b. Purpose

(1) To perform technical inspection and evaluation of non-federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-federal interests.

(2) To encourage and prepare the states to initiate quickly effective dam safety programs for non-federal dams.

(3) To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

a. Location. The Butterfield Pond Dam is located in the town of Washington, New Hampshire, at the south end of Butterfield Pond, just east of New Hampshire Route 31. The dam impounds water from Butterfield Pond and adjoining May Pond which, after passing over the spillway, flows through the Ashuelot River in a southwesterly direction for approximately 6.0 miles where it discharges into Ashuelot Pond. The dam is shown on U.S.G.S. Quadrangle, Lovewell Mountain, New Hampshire, with coordinates approximately N43°13'33", W72°07'08", Sullivan County, New Hampshire. (See Location Plan)

b. Description of Dam and Appurtenances. Butterfield Pond Dam is a stone-filled gravity structure with a concrete capped overflow section and a reinforced concrete sluice gate structure. The dam is approximately 210 feet in overall length and 12.5 feet high from crest of dam to toe of slope. Both embankments consist of unmortared stone and have a crest width of approximately

6.0 feet. The left embankment has a downstream slope of unmortared stone which extends from crest of dam to toe of slope at approximately 1.5 feet vertical to 1.0 foot horizontal (1.5:1). The right embankment has a downstream slope of earthfill at approximately 1.0 foot vertical to 2.0 feet horizontal (1:2).

Located in the center of the dam is the principal overflow section which is 57 feet long and consists of a concrete capped, stone weir with concrete training walls. Near the middle of the overflow section is a 16.2 feet wide by 0.2 feet deep low flow spillway weir cast into the concrete cap.

Located at the right training wall of the overflow section is the outlet structure which consists of a reinforced concrete sluice gate structure containing a wood plank sluice gate. All mechanical equipment to operate the sluice gate has been removed and the sluice gate is split, leaking and inoperable. Flow passing through the sluice gate structure discharges into a 12 feet wide stone-lined sluiceway that extends approximately 56 feet to the main channel.

c. Size Classification. Small (height - 12.5 feet; storage - 590 acre-feet) based on storage (less than 1,000 acre-feet and greater than or equal to 50 acre-feet) as given in the Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification. Significant Hazard. Failure of the dam could result in damage to a state bridge and highway (NH Route 31), since the capacity of the highway bridge is nearly 2,000 cfs less than the dam failure discharge and the roadway would be overtopped by 2 to 3 feet. There are no dwellings located near the downstream channel until the river discharges into Ashuelot Pond. However, at this point the stage would decrease rapidly to less than a foot and dwellings located on the pond would not be impacted. Although the potential for loss of life would exist if the bridge were to wash out, no loss of life is anticipated.

e. Ownership. No information regarding the original owner was found, but according to the files of the State of New Hampshire Water Resources Board, the original dam was built to create a pond and provide power for what was called Butterfield Mill. The dam was reconstructed in 1934 by the Civilian Conservation Corp., and at that time was owned by the State of New Hampshire Forestry Reservation. Since that time, the dam has always been owned by an agency of the State of New Hampshire, and is presently owned by Pillsbury State Park; more specifically, the State of New Hampshire Resources and Economic Development Department, Division of Parks and Recreation, Post Office Box 856, Concord, New Hampshire 03301. Telephone No. (603) 271-3254.

f. Operator. The dam is maintained and operated by Pillsbury State Park, under the State of New Hampshire Resources and Economic Development Department, Division of Parks and Recreation, Post Office Box 856, Concord, New Hampshire 03301. Telephone No. (603) 271-3254.

g. Purpose of Dam. The original purpose of the dam was to provide power to a mill. The present purpose of the dam is recreational.

h. Design and Construction History. No information regarding the original design or construction of the dam was found. Early records indicate that it was last rebuilt in 1934. A set of plans dated 1934, showing plan, elevation, and section of an existing structure and proposed reconstruction prepared by R. D. Chapin, Civil Engineer, Newport, New Hampshire, are on file at the State of New Hampshire Water Resources Board. None of the details shown on these plans are consistent with the configuration of the present structure. Photographs taken in 1937 that are on file substantially agree with the detail of the present structure.

i. Normal Operating Procedures. The Butterfield Pond Dam is used primarily to retain the waters of Butterfield Pond and adjoining May Pond for recreational use at Pillsbury State Park. There is no normal operating procedure for this dam.

1.3 Pertinent Data

a. Drainage Area. The drainage area above the Butterfield Pond Dam covers nearly 7.15 square miles (approximately 4576 acres), consisting of steeply sloped terrain surrounding Butterfield Pond and adjoining May Pond, and other smaller ponds located upstream from Butterfield Pond. The topography in the drainage basin ranges from 2332 feet (NGVD) on top of Bean Mountain to approximately 1592 feet (NGVD) at the base of the dam. The majority of the basin is heavily wooded and generally undeveloped. The development which does exist consists of structures associated with Pillsbury State Park.

b. Discharge at Damsite. Discharge at the damsite normally occurs over the overflow section located between the two concrete training walls. A 16.2 feet wide by 0.2 foot deep low flow spillway is located near the middle of the overflow section. The invert of the spillway weir is at elevation 1603.0 feet (NGVD) and has a capacity of nearly 4 cfs. A 6.1 foot wide by 6.05 foot high sluice gate is located adjacent to the right training wall. The sluice gate is normally closed, and presently is inoperable and leaking through a split in the gate. This gate, if operable, would allow the reservoir to be lowered to an elevation of 1595.2 feet.

(1) The capacity of the sluice gate was estimated to be 435 cfs with the water surface at the top of dam (elevation 1604.2 feet) and 595 cfs with the water surface at the test flood elevation (elevation 1609.5 feet).

(2) Maximum known flood at damsite - unknown

(3) The ungated spillway capacity with the water surface elevation at the top of the dam (elevation 1604.2 feet) was estimated to be 160 cfs

(4) The ungated spillway capacity with the water surface elevation at the test flood elevation (elevation 1609.5 feet) was estimated to be 2,375 cfs

(5) N/A

(6) N/A

(7) The total spillway capacity at the test flood elevation was estimated to be 2,375 cfs at 1609.5 elevation

(8) The total project discharge at the top of the dam was estimated to be 210 cfs at 1604.2 elevation (with the sluice gate closed) and 630 cfs at 1604.2 elevation (with the sluice gate open)

(9) The total project discharge at the test flood elevation was estimated to be 5,430 cfs at 1609.5 elevation

c. Elevation (feet, NGVD) based on elevation 1603.0 shown on U.S.G.S. quad sheet assumed to be pool elevation at top of permanent spillway crest

(1) Streambed at toe of dam - 1591.9

(2) Bottom of cutoff - unknown

(3) Maximum tailwater - unknown

(4) Recreation pool - 1603.2

(5) Full flood control pool - N/A

(6) Spillway crest - 1603.0

(7) Design surcharge (Original Design) - unknown

(8) Top of dam - 1604.2

(9) Test flood design surcharge - 1609.5

d. Reservoir (length in feet) (Butterfield Pond and adjoining May Pond)

(1) Normal pool - 6,565

(2) Flood control pool - N/A

(3) Spillway crest pool - 6,550

(4) Top of dam - 6,630

(5) Test flood pool - 6,990

e. Storage (acre-feet) (Butterfield Pond and adjoining May Pond)

- (1) Normal pool - 465
- (2) Flood control pool - N/A
- (3) Spillway crest pool - 440
- (4) Top of dam - 590
- (5) Test flood pool - 1,415

f. Reservoir Surface (acres) (Butterfield Pond and adjoining May Pond)

- (1) Normal pool - 126
- (2) Flood control pool - N/A
- (3) Spillway crest - 125
- (4) Test flood pool - 175
- (5) Top of dam - 134

g. Dam

- (1) Type - stone-filled gravity structure with concrete capped overflow section
- (2) Length - 210 feet overall
- (3) Height - 12.5 feet maximum
- (4) Top Width - 6.0 feet (at stone embankments)
8.0 feet (at overflow section)
- (5) Side Slopes - 1.5 V to 1.0 H downstream slope (left embankment)
1.0 V to 2.0 H downstream slope (right embankment)
- (6) Zoning - unknown
- (7) Impervious core - unknown
- (8) Cutoff - unknown
- (9) Grout curtain - none
- (10) Other - none

h. Diversion and Regulating Tunnel

Not applicable (see Section j below)

i. Spillway

(1) Type - stone fill, concrete capped overflow section with concrete training walls

(2) Length of weir - 57 feet (entire overflow section)
16.2 feet (low flow spillway section)

(3) Crest elevation - 1603.0 (invert low flow spillway)
1603.2 (invert main overflow section)

(4) Gates - N/A

(5) U/S Channel - The banks of Butterfield Pond and May Pond are tree lined. For the most part the slopes appear to be stable, although some debris has blocked the sluice gate. Other than the debris blocking the sluice gate, no evidence of significant sedimentation was observed.

(6) D/S Channel. The dam's overflow section discharges into a natural river channel (Ashuelot River) which is about 20 feet wide and 3.5 feet deep. Approximately 350 feet downstream from the dam, the river passes beneath a state highway (NH Route 31). The bridge opening (perpendicular to the centerline of the channel) measures 24.3 feet wide by 10.4 feet high. After passing through the bridge, the river travels in a southerly direction until it discharges into Ashuelot Pond, approximately 6 miles downstream from the dam.

j. Regulating Outlets

(1) Invert - Sluice gate - 1595.2 (bottom of gate opening)

(2) Size - Sluice gate - 6.1 feet wide x 6.05 feet high opening

(3) Description - Sluice gate - 5 inch thick wooden planks, 7.1 feet wide, bolted together to form gate in 6.1 feet wide opening

(4) Control Mechanism - Sluice gate - Manual crank lift by cables. Lifting mechanism removed. Gate planks split and leaking.

SECTION 2 ENGINEERING DATA

2.1 Design

No design data were disclosed for Butterfield Pond Dam. A set of plans dated 1934 showing plan, elevation, and section of an existing structure and proposed reconstruction of the dam by R.D. Chaplin, Civil Engineer, Newport, New Hampshire are on file at the State of New Hampshire Water Resources Board. None of the details shown on those plans were consistent with the configuration of the present structure.

2.2 Construction

No construction records were disclosed.

2.3 Operation

No engineering operational data were found.

2.4 Evaluation

a. Availability. No engineering data were available for Butterfield Pond Dam. A search of the files of the State of New Hampshire Water Resources Board revealed a limited amount of recorded information.

b. Adequacy. The final assessments and recommendations of this investigation are based on the visual inspection and the hydrologic and hydraulic calculations.

c. Validity. The field investigation indicated that the external features of the Butterfield Pond Dam almost completely disagree with the detail shown on the plans on file at the State of New Hampshire Water Resources Board.

SECTION 3 VISUAL INSPECTION

3.1 Findings

a. General. Butterfield Dam impounds a pond of small size. The drainage area above the dam consists of steeply sloped terrain surrounding Butterfield Pond and adjoining May Pond, and other smaller ponds located upstream from Butterfield Pond. The majority of the basin is heavily wooded and generally undeveloped. The development which does exist consists of structures associated with Pillsbury State Park. The downstream area is undeveloped except for the bridge crossing of NH State Route 31.

The field inspection of Butterfield Pond Dam was made on December 6, 1979. The inspection team consisted of personnel from S E A Consultants Inc. and Geotechnical Engineers, Inc. Inspection checklists, completed during the visual inspection, are included in Appendix A. At the time of inspection, water was passing approximately 2-1/2 inches deep over the 16.2 feet wide low flow spillway. The pool elevation was at approximately 1603.2 feet (NGVD). The upstream face of the dam could only be inspected above this water level.

b. Dam. Butterfield Pond Dam is a stone-filled gravity structure about 210 feet in overall length and 12.5 feet high from crest of dam to toe of slope. (See Plans and Detailing in Appendix B.)

The central portion of the dam consists of a stone-masonry overflow section about 57 feet long with concrete training walls and a stone weir, concrete capped on the crest and downstream side. (See Photo Nos. 2 and 7.) The crest of the overflow section is about 8 feet wide and the downstream face is vertical. (See Photo Nos. 3 and 7.) The upstream side of the overflow section is not completely visible beneath the water surface, but does indicate the existence of an unmortared stone apron. Located near the middle of the overflow section cast into the concrete cap is the low flow spillway which is 16.2 feet wide and 0.2 feet deep. (See Photo Nos. 7 and 8.) The concrete cap on the crest of the overflow section is broken and severely eroded at numerous locations. (See Photo Nos. 8 and 10.) At one location there is a small eddy where water is flowing down into a hole on the crest. Water is leaking from the downstream face at the contact between the overflow section and the foundation bedrock. (See Photo No. 9.) Major leakage is discharging from loose rocks at the toe of the right end of the overflow section.

Between the sluice gate at the right training wall of the overflow section and the right abutment, there is a stone embankment which appears to consist of a vertical dry-stone-masonry wall with earthfill against the upstream and downstream sides. In the fill immediately adjacent to the upstream side of the wall, there is a ditch in which water is flowing from the pond toward a sinkhole which is about 15 to 20 feet to the right of the concrete sluice gate structure. (See Plans and Details in Appendix B.) It appears that the water which flows into this sinkhole is discharging at the base of the downstream end of the right training wall of the sluice gate structure. (See Photo No. 13.) About 5 feet to the right of the concrete sluice gate structure, the crest of the stone embankment has subsided about 2 feet. Directly in line with this subsidence, there is an apparent erosion channel that

extends from the crest to the toe of the downstream slope of the embankment. This channel is filled with weeds and brush, and there are stumps of some small trees in the channel. Some brush and one small tree are growing on the earthfill on the upstream side of the stone embankment. Brush and weeds are growing on the earthfill on the downstream side of the stone embankment. (See Photo No. 4.)

Between the left training wall of the overflow section and the left abutment there is a stone embankment which has a downstream slope inclined at about 1.5V:1H and which has an earthfill against its upstream side. There appears to be a major bulge in the downstream slope of this stone embankment close to the overflow section of the dam. (See Photo No. 5.) Major seepage is discharging at the toe of the stone embankment next to the overflow section. The crest of the stone embankment has settled about 1 to 1 1/2 feet within about 10 feet of the overflow section and the crest of the earthfill on the upstream side of the embankment has a sinkhole about 3 to 4 feet deep above pond level at a location about 25 feet to the left of the overflow section. (See Photo No. 6.) Brush and small trees are growing on the earthfill on the upstream side of the embankment. Brush and trees are growing at the downstream toe of the embankment. (See Photo No. 4.)

c. Appurtenant Structures. Located at the right training wall of the overflow section is the dam's outlet structure which consists of a reinforced concrete sluice gate structure that discharges into a 12 foot wide stone-lined sluiceway that extends approximately 56 feet to the main channel. (See Photo Nos. 10 and 11.) The sluice gate itself consists of 5-inch thick wood planks that are secured together by two long vertical bolts. The gate is approximately 6.1 feet wide and 6.05 feet high and is raised and lowered through steel slots embedded in the sides of the concrete sluice gate structure. Near the top of the gate, a severe crack has developed between the wood planks and water is pouring through and discharging into the sluiceway. (See Photo No. 12.)

A 6-inch thick concrete slab cast on top of the sluice gate structure acts as a control tower for the gate. The lifting mechanism has been removed, and the gate is jammed in the closed position. The upstream face of the left wall of the concrete sluice gate structure is being undermined and is deteriorated, exposing reinforcing steel.

d. Reservoir Area. The slopes of the ponds appear to be stable. No evidence of significant sedimentation was observed. The approach channel to the spillway is wide and unobstructed.

e. Downstream Channel. The dry-stone-masonry wall on the right side of the sluiceway downstream of the sluice gate structure is in poor condition. Some brush is growing in the channel downstream of the sluiceway. Some trees overhang the channel downstream of the overflow section of the dam, and one tree has blown over across the channel. (See Photo Nos. 14, 15 and 16.)

3.2 Evaluation

On the basis of the results of the visual inspection, Butterfield Pond Dam is considered to be in very poor condition.

A major sinkhole into which water from the pond is flowing on the upstream side of the stone embankment at the right end of the dam, subsidence of the crest of the right stone embankment, an apparent erosion channel on the downstream slope of the right embankment, and a major discharge of water from the base of the right training wall of the sluice gate structure are all signs of serious stability problems of the right embankment. It is possible that this embankment could fail at any time.

A major subsidence of the crest of the stone embankment at the left end of the dam, a major sinkhole in the earthfill on the upstream side of the left stone embankment, apparent bulging of the downstream slope of the left embankment, and a major discharge of water from the downstream toe of the left embankment are all signs of serious stability problems of the left embankment. It is possible that this embankment could fail at any time.

The broken and eroded condition of the concrete cap and downstream facing of the overflow section of the dam, leakage from cracks in the downstream facing, leakage at the contact between the overflow section of the dam and the bedrock foundation, and the flow of pond water into a hole on the crest of the overflow section are all signs of serious stability problems in the overflow section of the dam.

A large crack between the wood planks of the sluice gate and the water pouring through and discharging into the sluiceway, and the absence of any lifting mechanism are signs of considerable deterioration of the gate. It is possible that the gate could fail at any time.

Trees growing at the downstream toe of the dam, and brush which will eventually attain tree-size on the earthfills on the upstream side of the left stone embankment and on the upstream and downstream sides of the right stone embankment may lead to erosion and seepage problems if a tree blows over and pulls out its roots, or if a tree dies or is cut and its roots rot.

**SECTION 4
OPERATIONAL AND MAINTENANCE PROCEDURES**

4.1 Operational Procedures

a. General. The Butterfield Pond Dam is used primarily to retain the waters of Butterfield Pond and adjoining May Pond. There are no written or routine operational procedures.

b. Description of Any Warning System in Effect. No written warning system exists for the dam.

4.2 Maintenance Procedures

a. General. The owner, the New Hampshire Resources and Economic Development Department, Division of Parks and Recreation, is responsible for the maintenance of the dam. No formal plan for maintenance was discussed.

b. Operating Facilities. No formal plan for maintenance of operating facilities was disclosed.

4.3 Evaluation

The current operation and maintenance procedures for the Butterfield Pond Dam are inadequate to insure that all problems encountered can be remedied within a reasonable period of time. The owner should establish a written operation and maintenance procedure, as well as establish a warning system to follow in event of flood flow conditions or imminent dam failure.

SECTION 5 EVALUATION OF HYDROLOGIC/HYDRAULIC FEATURES

5.1 General. Butterfield Pond Dam is a stone-filled gravity structure approximately 210 feet in overall length and 12.5 feet high from crest of dam to toe of slope. Located near the center of the dam is the principal overflow section which is 57 feet long and consists of a concrete capped, stone weir with concrete training walls. Near the middle of the overflow section is a 16.2 feet wide by 0.2 foot deep low flow spillway weir. Adjacent to the right training wall of the overflow section is a 6.1 feet wide by 6.05 feet high sluice gate housed in a reinforced concrete structure. The sluice gate discharges into a 12 feet wide stone-lined sluiceway which extends approximately 56 feet to the main channel. At this time, the wooden plank sluice gate is inoperable and is severely leaking through a gap between two of the planks.

In addition to Butterfield Pond, five other ponds are located in the drainage area upstream from Butterfield Pond. Consequently, nearly two-thirds of the runoff from the watershed is intercepted by these ponds before flowing into Butterfield Pond.

5.2 Design Data. No hydrological or hydraulic design data were disclosed.

5.3 Experience Data. No experience data were disclosed. Maximum flood flows or elevations are unknown.

5.4 Test Flood Analysis. Due to the absence of detailed design and operational information, the hydrologic evaluation was performed utilizing data gathered during field inspection, watershed size and an estimated test flood determined from the Corps of Engineers guide curves. For this dam (small size and significant hazard) the test flood ranges from a 100-Year Flood to one-half the Probable Maximum Flood (1/2 PMF). Due to the very poor condition of the dam the 1/2 PMF was selected for this analysis. Since the drainage area consists of steeply sloping terrain, the "mountainous" curve, from the Corps of Engineers set of guide curves, was used to estimate the maximum probable peak flow rate.

Based on an estimated maximum probable flood peak flow rate of 2,100 cfs per square mile and a drainage area of 7.15 square miles, the test flood inflow was estimated to be 7,500 cfs. The test flood was routed through the reservoir in accordance with the Corps of Engineers procedure for Estimating Effect of Surcharge Storage on Maximum Probable Discharge. The routed test flood outflow was estimated to be 5,430 cfs. This analysis indicated that the dam crest would be overtopped by approximately 5.3 feet. The maximum spillway capacity (assuming that the sluice gate is closed) with the water level at the dam crest was estimated to be 160 cfs, which is only about 3 percent of the routed test flood outflow.

5.5 Dam Failure Analysis. The impact of dam failure with the reservoir surface at the dam crest was assessed utilizing the "Rule of Thumb" Guidance for Estimating Downstream Dam Failure Hydrographs published by the Corps of Engineers. The analysis covered a reach extending approximately 6 miles downstream to Ashuelot Pond. Based on this analysis, the Butterfield Pond Dam has been classified as a significant hazard.

Failure of the Butterfield Pond Dam would increase the stage along the immediate downstream channel by 7.5 feet, with an associated discharge of 5,950 cfs. Since this discharge exceeds the capacity of the highway bridge by nearly 2,000 cfs, it is probable that the pool formed by the flow restriction of the bridge would overtop the roadway by 2 to 3 feet and could cause significant damage to the bridge and roadway. The stage of the river would be reduced to about 4.5 feet by the time it discharges into Ashuelot Pond. The stage, however, would decrease rapidly, to less than a foot, as the flow passes through the wider portions of the pond. Although the potential for loss of life would exist if the bridge were to wash out, no loss of life is anticipated.

SECTION 6 EVALUATION OF STRUCTURAL STABILITY

6.1 Visual Observations

The visual inspection indicates the following potential structural problems:

- (1) A major sinkhole into which water from the pond is flowing on the upstream side of the stone embankment at the right end of the dam, subsidence of the crest of the right stone embankment, an apparent erosion channel on the downstream slope of the right embankment, and a major discharge of water from the base of the right training wall of the sluice gate structure are all signs of serious stability problems in the right embankment. It is possible that this embankment could fail at any time.
- (2) A major subsidence of the crest of the stone embankment at the left end of the dam, a major sinkhole in the earthfill on the upstream side of the left stone embankment, apparent bulging of the downstream slope of the left embankment, and a major discharge of water from the downstream toe of the left embankment are all signs of serious stability problems in the left embankment. It is possible that this embankment could fail at any time.
- (3) The broken and eroded condition of the concrete cap and downstream facing of the overflow section of the dam, leakage from cracks in the downstream facing, leakage at the contact between the overflow section of the dam and the bedrock foundation, and the flow of pond water into a hole on the crest of the overflow section are all signs of serious stability problems in the overflow section of the dam.
- (4) The large crack between the wood planks of the sluice gate and the water pouring through and discharging into the sluiceway, and the absence of any lifting mechanism are signs of considerable deterioration of the gate. It is possible that the gate could fail at any time.
- (5) Trees growing at the downstream toe of the dam, and brush which will eventually attain tree-size on the earthfills on the upstream side of the left stone embankment and on the upstream and downstream sides of the right stone embankment, may lead to erosion and seepage problems if a tree blows over and pulls out its roots, or if a tree dies or is cut and its roots rot.

6.2 Design and Construction Data

No information regarding the original design or construction of the dam was found.

6.3 Post-Construction Changes

Early records indicate that the dam was rebuilt in 1934. A set of plans dated 1934, showing plan, elevation, and section of an existing structure and proposed reconstruction prepared by R.D. Chapin, Civil Engineer, Newport, New Hampshire, are on file at the New Hampshire Water Resources Board. None of the detail shown on these plans are consistent with the configuration of the present structure. Photographs taken in 1937 that are on file substantially agree with the detail of the present structure.

6.4 Seismic Stability

This dam is located in Seismic Zone 2 and, in accordance with the Phase I guidelines, does not warrant seismic analysis.

SECTION 7
ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition. The visual examination indicates that Butterfield Pond Dam is in very poor condition. The major concerns with respect to the integrity of the dam are:

- (1) Sinkhole in the earthfill on the upstream side of the right stone embankment, with pond water flowing into the sinkhole.
- (2) Major subsidence of the crest of the left stone embankment.
- (3) Bulging of the downstream slope of the left stone embankment.
- (4) Severely broken and eroded condition of the concrete cap and the downstream concrete facing of the overflow section.
- (5) Leakage from cracks in the downstream facing of the overflow section and at the contact between the overflow section and the foundation bedrock.
- (6) Subsidence of the crest of the right stone embankment.
- (7) Erosion channel from the crest to downstream toe of the right embankment.
- (8) Major seepage at the base of the right training wall of the sluice gate structure.
- (9) Sinkhole above pond level in the earthfill on the upstream side of the left stone embankment.
- (10) Major seepage at the downstream toe of the left embankment.
- (11) Leakage through a large crack between the wood planks of the sluice gate.
- (12) Trees overhanging the discharge channel downstream of the overflow section of the dam and one tree which has blown over across the channel.
- (13) Inadequacy of the spillway to pass the test flood.

b. Adequacy of Information. The information available from the visual inspection is adequate to identify the problems that are listed in 7.2. These problems will require the attention of a qualified registered professional engineer who will have to make additional engineering studies to design or specify remedial measures. No additional information is needed for the purpose of this Phase I investigation.

c. Urgency. The owner should implement the recommendations in 7.2 and 7.3 immediately upon receipt of this Phase I report.

7.2 Recommendations

The owner should retain a registered professional engineer qualified in the design and construction of dams to:

- (1) Investigate the sinkhole, crest subsidence, erosion channel on the downstream slope, and seepage at the left end of the right stone embankment, and design remedial measures as needed.
- (2) Investigate the subsidence of the crest, sinkhole in the upstream earthfill, bulging of the downstream slope, and seepage at the downstream toe of the left stone embankment, and design remedial measures as need
- (3) Investigate the structural condition of the overflow section and design remedial measures as needed.
- (4) Investigate the structural condition of the sluice gate and design remedial measures as needed.
- (5) Do a detailed hydrologic-hydraulic investigation to assess further the potential of overtopping the dam, the adequacy of the spillway to pass the test flood, and the need for and means to increase project discharge capacity.

The owner should carry out the recommendations made by the engineer.

7.3 Remedial Measures

a. Operating and Maintenance Procedures. The owner should:

- (1) Clear brush and trees from a zone 25 feet wide on each side of the discharge channel between the dam and the highway bridge downstream of the dam.
- (2) Visually inspect the dam and appurtenant structures once a month.
- (3) Engage a registered professional engineer qualified in the design and construction of dams to make a comprehensive technical inspection of the dam once every year.

- (4) Establish a surveillance program for use during and immediately after heavy rainfall, and also a warning program to follow in case of emergency conditions.

7.4 Alternatives

There are no practical alternatives to the recommendations of Section 7.2 and 7.3 except removal of the dam.

APPENDIX A
INSPECTION CHECKLIST

**INSPECTION CHECK LIST
PARTY ORGANIZATION**

PROJECT: Butterfield Pond Dam, NH

DATE: December 6, 1979

TIME: 9:00 a.m.

WEATHER: Cool, partly cloudy

W.S. ELEV. 1603.2 U.S. 1591.9 D.N.S.
(NGVD)

PARTY:

- | | |
|-----------------------------------|---------------------------------|
| 1. <u>Kenneth Stewart, S E A</u> | 6. <u>Kenneth Stern, NHWRB</u> |
| 2. <u>Robert Durfee, S E A</u> | 7. <u>Richard DeBood, NHWRB</u> |
| 3. <u>Bruce Pierstorff, S E A</u> | 8. _____ |
| 4. <u>Philip Ricardi, S E A</u> | 9. _____ |
| 5. <u>Ronald Hirschfeld, GEI</u> | 10. _____ |

	PROJECT FEATURE	INSPECTED BY	REMARKS
1.	<u>Structural Stability</u>	<u>K. Stewart/R. Durfee</u>	
2.	<u>Hydrology/Hydraulics</u>	<u>B. Pierstorff/P. Ricardi</u>	
3.	<u>Soils and Geology</u>	<u>R. Hirschfeld</u>	
4.	_____	_____	
5.	_____	_____	
6.	_____	_____	
7.	_____	_____	
8.	_____	_____	
9.	_____	_____	
10.	_____	_____	

INSPECTION CHECK LIST

PROJECT: Butterfield Pond Dam, NH DATE: December 6, 1979
 PROJECT FEATURE: Dam Embankment NAME: _____
 DISCIPLINE: _____ NAME: _____

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT</u>	
Crest Elevation	1603.0
Current Pool Elevation	1603.2
Maximum Impoundment to Date	Unknown
Surface Cracks	None observed
Pavement Condition	Not paved
Movement or Settlement of Crest	One sinkhole in crest to right of sluice gate structure, one sinkhole in crest near left end of overflow section
Lateral Movement	Bulging of downstream dry stone masonry wall between left end of overflow section and left abutment in vicinity of sinkhole on crest
Vertical Alignment	Sinkholes, as noted above
Horizontal Alignment	See "Lateral Movement" above
Condition at Abutment and at Concrete Structures	Fair
Indications of Movement of Structural Items on Slopes	None observed
Trespassing on Slopes	No evidence observed
Vegetation on Slopes	Brush and some small trees on upstream side of embankment, on abutments, and downstream of toe of dam
Sloughing or Erosion of Slopes or Abutments	Major erosion channel on downstream slope next to training wall on right side of sluiceway
Rock Slope Protection - Riprap Failures	No riprap
Unusual Movement or Cracking at or near Toe	None observed
Unusual Embankment or Downstream Seepage	Major seepages at several locations
Piping or Boils	None observed
Foundation Drainage Features	None observed
Toe Drains	None observed
Instrumentation System	None observed

INSPECTION CHECK LIST

PROJECT: Butterfield Pond Dam, NH DATE: December 6, 1979
 PROJECT FEATURE: Dike Embankment NAME: _____
 DISCIPLINE: _____ NAME: _____

AREA EVALUATED	CONDITIONS
----------------	------------

<p><u>DIKE EMBANKMENT</u></p> <p>Crest Elevation</p> <p>Current Pool Elevation</p> <p>Maximum Impoundment to Date</p> <p>Surface Cracks</p> <p>Pavement Condition</p> <p>Movement or Settlement of Crest</p> <p>Lateral Movement</p> <p>Vertical Alignment</p> <p>Horizontal Alignment</p> <p>Condition at Abutment and at Concrete Structures</p> <p>Indications of Movement of Structural Items on Slopes</p> <p>Trespassing on Slopes</p> <p>Vegetation on Slopes</p> <p>Sloughing or Erosion of Slopes or Abutments</p> <p>Rock Slope Protection - Riprap Failures</p> <p>Unusual Movement or Cracking at or near Toe</p> <p>Unusual Embankment or Downstream Seepage</p> <p>Piping or Boils</p> <p>Foundation Drainage Features</p> <p>Toe Drains</p> <p>Instrumentation System</p>	<p>No dike</p>
---	----------------

INSPECTION CHECK LIST

PROJECT: Butterfield Pond Dam, NH DATE: December 6, 1979

PROJECT FEATURE: Intake Channel NAME: _____

DISCIPLINE: _____ NAME: _____

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u>	
a. Approach Channel	
Slope Conditions	Good
Bottom Conditions	Not visible beneath pond surface
Rock Slides or Falls	None
Log Boom	None
Debris	Debris built up against sluice gate
Condition of Concrete Lining	Loose stone lining
Drains or Weep Holes	None
b. Intake Structure	
Condition of Concrete	Fair to poor. Exposed reinforcing steel and numerous cracks.
Stop Logs and Slots	Wooden gate (not operable) split and leaking.

INSPECTION CHECK LIST

PROJECT: Butterfield Pond Dam, NH DATE: December 6, 1979

PROJECT FEATURE: Control Tower NAME: _____

DISCIPLINE: _____ NAME: _____

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - CONTROL TOWER</u>	
a. Concrete and Structural	
General Condition	Fair
Condition of Joints	Good
Spalling	Minor
Visible Reinforcing	Visible reinforcement on leading edge of both sides of intake channel
Rusting or Staining of Concrete	Minor
Any Seepage or Efflorescence	Minor
Joint Alignment	Good
Unusual Seepage or Leaks in Gate Chamber	None observed
Cracks	Numerous
Rusting or Corrosion of Steel	Rusting of visible reinforcing steel
b. Mechanical and Electrical	
Air Vents	Not applicable
Float Wells	Not applicable
Crane Hoist	None
Elevator	Not applicable
Hydraulic System	Not applicable
Service Gates	Not accessible - water pouring through apparent split in wooden gate
Emergency Gates	Same as service gates
Lightning Protection System	Not applicable
Emergency Power System	Not applicable
Wiring and Lighting System	Not applicable

INSPECTION CHECK LIST

PROJECT: Butterfield Pond Dam, NH

DATE: December 6, 1979

PROJECT FEATURE: Transition and Conduit

NAME: _____

DISCIPLINE: _____

NAME: _____

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - TRANSITION AND CONDUIT</u> General Condition of Concrete Rust or Staining on Concrete Spalling Erosion or Cavitation Cracking Alignment of Monoliths Alignment of Joints Numbering of Monoliths	Not applicable

INSPECTION CHECK LIST

PROJECT: Butterfield Pond Dam, NH DATE: December 6, 1979
 PROJECT FEATURE: Outlet Structure NAME: _____
 DISCIPLINE: _____ NAME: _____

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u>	
General Condition of Concrete	Fair
Rust or Staining	Minor
Spalling	Minor
Erosion or Cavitation	Both wing walls undermined and eroded. (Left side more serious.)
Visible Reinforcing	None observed
Any Seepage or Efflorescence	Some efflorescence
Condition at Joints	Cracking at lift boundaries
Drain holes	None
Channel	
Loose Rock or Trees Overhanging Channel	Trees overhanging channel. Dry stone masonry wall on the right side of the sluiceway channel is in poor condition.
Condition of Discharge Channel	Fair

INSPECTION CHECK LIST

PROJECT: Butterfield Pond Dam, NH

DATE: December 6, 1979

PROJECT FEATURE: Spillway Weir

NAME: _____

DISCIPLINE: _____

NAME: _____

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	
a. Approach Channel	
General Condition	Good
Loose Rock Overhanging Channel	None observed
Trees Overhanging Channel	None observed
Floor of Approach Channel	Not visible beneath pond surface
b. Weir and Training Walls	
General Condition of Concrete	Extensively deteriorated
Rust or Staining	None observed
Spalling	Large sections of concrete cap broken away
Any Visible Reinforcing	None
Any Seepage or Efflorescence	Extensive seepage
Drain Holes	None
c. Discharge Channel	
General Condition	Fair
Loose Rock Overhanging Channel	None observed
Trees Overhanging Channel	Trees in channel and overhanging channel
Floor of Channel	Boulder-covered
Other Obstructions	One tree has fallen across channel

INSPECTION CHECK LIST

PROJECT: Butterfield Pond Dam, NH

DATE: December 6, 1979

PROJECT FEATURE: Service Bridge

NAME: _____

DISCIPLINE: _____

NAME: _____

AREA EVALUATED

CONDITIONS

OUTLET WORKS - SERVICE BRIDGE

No service bridge

a. Super Structure

Bearings

Anchor Bolts

Bridge Seat

Longitudinal Members

Under Side of Deck

Secondary Bracing

Deck

Drainage System

Railings

Expansion Joints

Paint

b. Abutment & Piers

General Condition of Concrete

Alignment of Abutment

Approach to Bridge

Condition of Seat & Backwall

APPENDIX B
ENGINEERING DATA

AVAILABLE ENGINEERING DATA

No Engineering Data other than past inspection reports from the State of New Hampshire Water Resource Board were available.

PAST INSPECTION REPORTS

M E M O

December 7, 1979

To: Vern Knowlton

From: Ken Stern *KS*

Re: Corps Inspection of May Pond Dam

(Butterfield Dam) 245.01, Washington

On December 6, 1979 I accompanied the inspection team from SEA Consultants. This dam is in poor condition. The concrete is extremely deteriorated, the rock abutments have settled, there is major leakage at several locations.

The only structure threatened should the dam fail is a highway bridge on state route 31. This bridge has a large clear opening. If the dam were to fail gradually there may be no damage to the bridge.

I discussed the dam with Gary, who has been there, and we agree that major reconstruction is needed. Once work is considered, total reconstruction may be inevitable.

I recommend that the stoplogs be removed and the pond lowered until remedial action is taken. This would reduce the hydraulic pressure on the dam and reduce the amount of water discharged should the dam fail. The lowered water level would redistribute the location and magnitude of the ice pressures on the structure.

I recommend lowering the pond. A decision should be made and action taken now.

KS/ln

May Pond, Dam No. 245.01, Washington, New Hampshire

This is a stone-fill, gravity with concrete abutments and spillway cap dam type structure. It is approximately 225' long and with a maximum height of 18'. The present structure has several serious leaks through the stonework, and cracks and holes in the concrete. It also contains a pond drain gate near the base of the dam which also leaks. The present configuration of the dam and spillway does not permit the passage of the estimated 100 year flood flow (1,450cfs) without the dam being overtopped. The Board's proposal includes work to stop the leakage and increase the discharge capacity to equal the 100 year flood flows.

The proposal incorporates constructing an access road, removing the leaking spillway stones and concrete cap, the leaking gate section abutments, constructing steel reinforced concrete face walls and abutments, and a new concrete spillway with flashboards. This will require the removal of accumulated silt and debris from the upstream side of the dam. The project also includes constructing a stoplog section to act as a pond drain which may require some channel excavation to improve the hydraulics of the downstream channel.

The attached cost estimate reflects the materials of construction and labor costs of this proposal to be constructed not later than the end of 1980.

MAY POND DAM (#245.01)

WASHINGTON, NEW HAMPSHIRE

1. Dam originally constructed to create a mill pond, but now used to maintain a recreation pond for users of Pillsbury State Park
2. Pond area - 103 Acres
3. Ratio of net drainage to pond area - 37:1
4. 100 year flood flows - 1450 cfs
5. Shoreline - 3 $\frac{1}{2}$ Miles
6. -Altitude - 1632 feet
7. Watershed - Connecticut
8. River system - Ashuelot River
9. Inlets - Ashuelot River
10. Color of water - colorless
11. Ownership- State, Division of Parks

MAY POND DAM (#245.01)

PILLSBURY STATE PARK

WASHINGTON, N. H.

At the present time, the dam on May Pond does not have capacity to flow the 100 year storm frequency flow without overtopping the dam. The present design standard requires dams to pass storms equal to 100 year frequency flood flows. The dam also has several serious leaks through the stonework.

The design for this project includes:

1. Removing existing spillway and construction a permanent concrete crest with automatic flashboards.
2. Stoplog section construction.
3. New concrete abutments and cut-off and upstream face walls to prevent the leak which is now occurring.

The following is a cost estimate:

1. Access Road	\$ 8,000.00
2. Remove cut brush and grass	2,000.00
3. Remove existing stone spillway, debres and silt	10,000.00
4. Concrete, reinforcements, etc. (200 cy)	70,000.00
5. Stoplog construction	8,000.00
6. Backfill & clean-up	6,000.00
	<hr/>
SUB-TOTAL	\$104,000.00
20% Engineering & Contingencies	20,800.00
	<hr/>
TOTAL	\$124,800.00
ROUNDED TOTAL	\$125,000.00

M E M O

TO: Vernon A. Knowlton
Chief Engineer

DATE: August 16, 1978

FROM: Gary Kerr
Water Resources Engineer

SUBJECT: Dam Inspection #245.01 - Report of Leakage

DATE OF INSPECTION: August 14, 1978

Via a letter from the S.C.S. office in Claremont I was instructed to reinspect the subject dam for a serious leak. Below are listed my observations and please refer to the accompanying photos and file for clarity.

1. Dam is founded on ledge and consists of piled stones embankment and spillway with a concrete cap.
2. A stoplog section with concrete abutments.
3. Serious leakage occurring thru the structure at several places:
 - a. Right embankment
 - b. Left side pier of the stoplog section
 - c. Thru the hole in the spillway cap

This structure is listed as a menace dam because of the pondage (approx. 103 acres), DA of 7.3 mi^2 and downstream development.

The Ashuelot River flows thru May Pond, under Route 31 and into Ashuelot Pond, Washington. There is considerable domestic development around Ashuelot Pond and points South.

In F.C.M.'s inspection report of 1971, he states that the dam's flood capacity is sufficient to pass the estimated 100 flood with 1/2' of freeboard and no gate (now stoplogs) operation. He also indicated "it appeared (through openings in the snow) to be well built, substantial, and water tight." Unfortunately now, these assumptions are not entirely true. The dam has deteriorated, rocks have moved, the spillway cap is broken and the structure does leak seriously.


I strongly suggest that the pond be lowered or the dam sealed, sufficiently enough to stop the leakage thru the embankment and spillway cap. This may require a drawdown of 2-3', and since we are approaching the hurricane season, the drawdown would reduce the potential flooding of a full pond plus runoff from the storm should the dam fail.

CLK/kn

LIGHT STONE EMBANKMENT
ARROWS DENOTE FLOW PATHS



ENTRANCE PATH



EXIT AT BASE OF STONE
EMBANKMENT NEAR STOPLOG
SECTION

MAY POND DAM
245.01



LEAKAGE PROBABLY
FROM STOPLOG
SECTION

HOLE IN SPILLWAY
(CONCRETE CAP)



EXIT FOR HOLE
IN CAP.

STATE OF NEW HAMPSHIRE

INTER-DEPARTMENT COMMUNICATION

DATE August 16, 1978

FROM George M. McGee, Sr.
Chairman

AT (OFFICE)
Water Resources Board

SUBJECT Leakage through dam #245.01 at May Pond

TO Theodore Natti, Director
Division of Resources Development

This office has been alerted to the fact that your "Butterfield Dam" (245.01), at May Pond, Pillsbury State Park is leaking quite badly. An engineer re-inspected this dam and filed his report. Please be aware that this dam was inspected, per your request, in September, 1975 and a copy of the suggested repairs was sent to you. The inspector noted that none of the suggested repairs, short term or otherwise, were implemented and now the dam condition has deteriorated seriously.

As a result of this inspection the following items require your immediate attention:

1. The right hand piled stone embankment (looking downstream) no longer acts as a pond retaining structure as water freely flows through it.
2. This same embankment appears to have sloughed, to the extent that it no longer retains the shape of a stone wall with vertical sides.
3. Because of the present pond elevation and erosion on the upstream side of this embankment, leakage is occurring through the right hand embankment (please see photos).
4. Leakage is also freely flowing through the enlarged hole in the concrete spillway cap (please see photo).
5. Leakage is also evident adjacent to the left hand pier for the stoplog section on the downstream side of the spillway.

All of the above constitute a hazardous condition and threatens the stability of the dam and as such require corrective action.

Because this dam is a menace structure, we require that you send us a schedule of your proposed repairs within 30 days. We do suggest that you reduce the pond level 2-3 feet, or more, effectively immediately and remain lowered until your repairs are completed, or the causes of the leakage eliminated.

If you have any questions, please contact us.

Sincerely yours,

George M. McGee, Sr.

GMMG/GK/kcn
Enclosure

N. H. WATER RESOURCES BOARD
Concord, N. H. 03301

DAM SAFETY INSPECTION REPORT FORM

Town: WASHINGTON Dam Number: 245-01

Inspected by: GARY L. KEER Date: 30 Sep 1975

Local name of dam or water body: MAY POND

Owner: PILLSBURY STATE PARK Address: _____

Owner ~~was~~/was not interviewed during inspection.

Drainage Area: 6.01 sq. mi. Stream: ASHUBIOT RIVER

Fond Area: 103 (^{Fdg}_{Base}) acre, Storage _____ Ac-Ft. Max. Head _____ Ft.

Foundation: Type LEDGE & ROCKS, Seepage present at toe - ~~Yes~~/No, No

Spillway: Type BROAD CRESTED CONCRETE CAP, Freeboard over perm. crest: 2' ±

Width 40' ±, Flashboard height 3' ± MAX

Max. Capacity _____ c.f.s.

Embankment: Type ROCK, Cover ROCKS Width 5' ± 6'

Upstream slope VERT to 1; Downstream slope VERT to 1

Abutments: Type CONCRETE, Condition: ~~Good~~ Fair

Gates or Pond Drain: Size 5' LONG Capacity _____ Type STOP LOGS

Lifting apparatus None Operational condition YES ^{4/8/75}

Changes since construction or last inspection: _____

Downstream development: _____

This dam ~~would~~/would not be a menace if it failed. UNSAT OUT RD

Suggested reinspection date: _____

Remarks: HOLES IN CONCRETE CAP OF SPILLWAY

MINOR EROSION ON ABUTMENTS

APPROX 2" FLOW OVER SPILLWAY

O/L/M/C

DATE: February 8, 1971

FROM: Francis C. Moore, P.E.
Water Resources Engineer

SUBJECT: May Pond at Pillsbury State Park, Washington - #254.01

TO: Vernon A. Knowlton
Chief Water Resources Engineer

On January 25, 1971, I inspected the dam called Butterfield dam that flows back into May Pond in Washington at the head-waters of Ashuelot River. This dam was well rebuilt by C.C.C. forces in 1934, consisting of rock fill dam with concrete capped spillway.

The capacity of the spillway with 1/2 foot freeboard and no overflow through a 6' x 6' gate is once in 100 years. The dam appears, through openings in the snow, to be well built, substantial and water tight. However, there may be some trees to be removed from dam (\$500.), some concrete patching (\$3,500.) and miscellaneous work (\$1,000.) totaling about \$5,000. upon inspection at a later time.

Two views are shown in photos taken at this dam. The gate section could be opened to lower the pond if necessary. This dam is near N. H. H. W. Route #31 midway between Washington and Goshen on the northeast side of the highway.

As seen in the photos, water was going an estimated 4" over the spillway.

FCM/jb



NEW HAMPSHIRE WATER CONTROL COMMISSION
DATA ON DAMS IN NEW HAMPSHIRE

LOCATION

STATE NO. 245.01 ✓

Town Washington ✓ : County Washington ✓
Stream May Pond ✓
Basin-Primary Conn. R. ✓ : Secondary Ashuelot R. ✓
Local Name Old Butterfield Mill ✓
Coordinates—Lat. : Long.

GENERAL DATA

Drainage area: Controlled.....Sq. Mi.: Uncontrolled..... Sq. Mi.: Total 6.01 ✓ Sq. Mi.
Overall length of dam 225 ✓ ft.: Date of Construction rebuilt 1934 ✓
Height: Stream bed to highest elev. 18 ✓ ft.: Max. Structure 15.5 ✓ 15.25 ✓ ft.
Cost—Dam : Reservoir

DESCRIPTION Rockfill-Concrete cap spillway, stone&timber ✓

Waste Gates

Type concrete ✓
Number 1 : Size 6 ✓ ft. high x 6 ✓ ft. wide
Elevation Invert 8.5 ✓ : Total Area 36 sq. ft.
Hoist

Waste Gates Conduit

Number : Materials
Size ft.: Length ft.: Area sq. ft.

Embankment

Type
Height—Max. ft.: Min. ft.
Top—Width : Elev. ft.
Slopes—Upstream on : Downstream on
Length—Right of Spillway : Left of Spillway

Spillway

Materials of Construction concrete cap
Length—Total 47.5' high 17.5' low : Net ft.
Height of permanent section—Max. 15.5' ft.: Min. 15.25' ft.
Flashboards—Type : Height ft.
Elevation—Permanent Crest : Top of Flashboard
Flood Capacity cfs.: cfs/sq. mi.

Abutments

Materials:
Freeboard: Max. 2.75 ft.: Min. 2.5' ft.

Headworks to Power Devel.—(See "Data on Power Development")

OWNER N.H. Forestry Reservation ✓

REMARKS Additional spillway over gate 6' wide, same elevation. /
Use—Recreation. Good Condition

Tabulation By RLT B-13 Date 9/22/39

NEW HAMPSHIRE WATER RESOURCES BOARD

INVENTORY OF DAMS AND WATER POWER DEVELOPMENTS

DAM

BASIN Connecticut No. 245.01
 RIVER May Pond MILES FROM MOUTH D.A.SQ.MI 6.01
 TOWN Washington OWNER N.H. Forestry Reservation
 LOCAL NAME OF DAM Old Butterfield Mill
 BUILT 1934 DESCRIPTION Stone abutment stream covered gate structure
spillway ledge foundation Rock fill - concrete cap spillway
stone, timber & concrete
 POND AREA-ACRES 102.65 PA DRAWDOWN FT. POND CAPACITY-ACRE FT.
 HEIGHT-TOP TO BED OF STREAM-FT. 18 MAX. MIN.
 OVERALL LENGTH OF DAM-FT. 225' MAX. FLOOD HEIGHT ABOVE CREST-FT.
 PERMANENT CREST ELEV. U.S.G.S. LOCAL GAGE
 TAILWATER ELEV. U.S.G.S. LOCAL GAGE
 SPILLWAY LENGTHS-FT. 47.5 high 17.5 low FREEBOARD-FT. 2.5 and 2.75
 FLASHBOARDS-TYPE, HEIGHT ABOVE CREST
 WASTE GATES-NO. 1 WIDTH 6 MAX. OPENING 6 DEPTH SILL BELOW CREST 8.5

REMARKS Condition poor pre good. Dam has been rebuilt
probably WPA project
13 in's Ashuelot River.

POWER DEVELOPMENT

Coordinates Lat. 43° 13.535'
 Long 72° 7.213'

UNITS	NO.	RATED HP	HEAD FEET	C.F.S. FULL GATE	KW	MAKE

USE once power for mill now recreation




REMARKS Additional spillway over gate 6' wide same elevation
P.S.C. says ruins 1922.

DATE 9/28/37 HA & S.H.S.



MAY POND DAM - WASHINGTON
STATE FORESTRY

9/28/37

245.01



MAY POND IN WASHINGTON
N. H. Forestry Dept.
September 28, 1937



Gate

PLANS AND DETAILS

APPENDIX C
SELECTED PHOTOGRAPHS



Photo No. 1 - General view of reservoir from dam.



Photo No. 2 - View of crest of dam from left abutment
looking toward right abutment



Photo No. 5 - View of downstream face of left stone embankment (Note depression in crest of embankment)



Photo No. 6 - Closeup view of 4 feet deep sink hole located to left of overflow section



Photo No. 9 - Closeup of seepage and cracks on downstream face of overflow section.



Photo No. 10 - View of upstream face of sluice gate structure and erosion of concrete cap of overflow section.



Photo No. 13 - Closeup view of seepage at the downstream end of the right training wall of the sluice gate structure.



Photo No. 14 - General view of downstream channel immediately below dam.

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS




Fig. 2
Butterfield Pond Dam
DRAINAGE BASIN
 3000 0 3000 6000
 Scale in Feet

CLIENT Army Corps
PROJECT Pittsfield Pond
DETAIL Hydrologic Calcs

JOB No. 274-7901 PAGE 1 of 5
COMPTD. BY BWP DATE 2/4/80
CK'D. BY KMS DATE 2/3/80

I. Basic Data

A. Drainage Area

1. 7.15 square miles — as defined on U.S.G.S. sheets and then planimetered
2. drainage area would classify as mountainous for estimating MPF Peak Flow Rates

B. Dam and Storage Information

1. Size Classification: SMALL small
on Storage (< 1000 acre-ft and ≥ 50 acre-ft),
as indicated below storage at crest of dam
estimated to be 530 acre-ft

- 2 Hazard Potential: SIGNIFICANT

Failure could result in damage to state
bridge and highway (N.H. Route 31)

3. Storage Information

Descriptive Information	Elevation* (feet)	Cur-ree* Area (acres)	Storage (acre-ft)
1620' contour	1620	255	
Test Flood	1609.5	175	415
Top of left embankment	1606.6	152	935
Top of dam (low point on left stone embankment)	1604.2	134	530
Normal Pool	1603.2	126	465
Spillway weir crest	1603.0	125	440

CLIENT Army Corps JOB No. 274-7901 PAGE 2 of 7
PROJECT Butterfield Pond COMPTD. BY RWP DATE 2/4/90
DETAIL Hydrologic Calc. CK'D. BY KMS DATE 2/8/90

- * Notes: (1) elevations: NGVD
(2) normal pool taken to correspond with pool shown on U.S.G.S sheet, elevation of overflow spillway weir crest equal to 1603.0 feet (NGVD)
(3.) surface area at crest 5- ism determined by interpolating between the surface areas defined by the pool shown on the U.S.G.S sheet and the 1620 feet contour
(4) Storage at spillway weir crest estimated by dividing reservoir into pyramidal frustum sections and determining the volume of each section with the equation for the volume of a pyramidal frustum.

C. Spillway Information

1. Overflow section located near the center of the dam was a concrete cap. Adjacent to the right training wall is a sluiceway. The gate is constructed of wooden planks incised in a poured concrete structure. The gate is presently inoperable, and leaks considerably.
 - a. for the subsequent calculations of spillway capacity it was assumed that the sluiceway was closed and not leaking.
- 2 Discharge over the spillway given by broad-crested weir formula

$$Q = CLH^{3/2} \quad (\text{Standard Handbook for CE's, 1977})$$

where: Q = discharge, cfs
 C = discharge coeff., use 2.6

CLIENT Army Corps JOB NO. 274-7901 PAGE 3 of 47
PROJECT Wetland Pond COMPTD. BY PLP DATE 2/4/90
DETAIL Hydrologic Calcs CK'D. BY KMS DATE 2/3/90

L = weir length, feet
H = head over weir, feet

II Estimate Effect of Surcharge Storage on Maximum Probable Discharge.

A. Develop stage-discharge curve for outflow from dam-complex

1. define sources of outflow

a. discharge over spillway + overflow structure - above elevation 1603.0' as defined above

b. discharge through opening above sluiceway - above elevation 1603.3'

(1) use broad-crested weir equation from elevation 1603.3 to elevation 1607.3. with $C = 2.6$

(2) above elevation 1607.3 flow defined by discharge through an orifice

$$Q = C a \sqrt{2gh} \quad (\text{Standard Handbook - CE's, Merr})$$

where Q = discharge, cfs
 C = coeff of discharge use 0.6
 a = area of orifice, sq. ft
 g = acceleration due to gravity, 32.2 ft/sec²
 h = head on horizontal center line or weir, feet

C. discharge over stone embankment adjacent to left abutment - above elevation 1604.2'

1. use broad-crested weir equation as defined above with $C = 2.6$

CLIENT Army Corps JOB NO. 274-7901 PAGE 4 of 47
 PROJECT Butterfield Pond COMPTD. BY BWP DATE 2/4/90
 DETAIL Hydrologic Calcs CK'D. BY VMS DATE 2-5-90

d. discharge over right stone embankment
above elevation 1606.5

(1) use broad-crested weir equation as defined above with $C = 2.6$

e. discharge over abutments and concrete sluiceway structure - above elevation 1606.6'

(1) use broad-crested weir equation as defined above with $C = 2.6$

f. discharge over gravel road - above elevation 1607.9

(1) use broad-crested weir equation - with $C = 2.6$

2. Discharge over spillway + overflow structure

Elevation (feet NGVD)	C	L (feet)	H (feet)	Q (cfs)
1603.0	—	—	0	0
1604.0	2.6	57	avg ≈ 0.95	137
1605.0	↓	↓	1.95	404
1606.0	↓	↓	2.95	751
1607.0	↓	↓	3.95	1160
1608.0	↓	↓	4.95	1630
1609.0	↓	↓	5.95	2150
1610.0	↓	↓	6.95	2720
1611.0	↓	↓	7.95	3320
1612.0	↓	↓	8.95	3970
1613.0	↓	↓	9.95	4650

e. Discharge through opening above sluiceway
a between elevations 1603.27' and 1607.27'

Elevation (feet NGVD)	C	L (feet)	H (feet)	Q (cfs)
1603.27	—	—	0	0
1604.0	2.6	6.1	0.73	10
1605.0	↓	↓	1.73	36
1606.0	↓	↓	2.73	72
1607.0	↓	↓	3.73	114

CLIENT Army Corps JOB No. 274-7901 PAGE 5 of 17
 PROJECT Butterfield Pond COMPTD. BY BWP DATE 2/4/30
 DETAIL Hydrologic Calcs. CK'D. BY KMS DATE 2.3.30

b. above elevation 1607.27'

Elevation (feet NGVD)	C	a (ft ²)	h (feet)	Q (cfs)
1608.0	0.6	24.4	2.73	194
1609.0	↓	↓	3.73	227
1610.0	↓	↓	4.73	256
1611.0	↓	↓	5.73	281
1612.0	↓	↓	6.73	305
1613.0	↓	↓	7.73	327

4. discharge over left stone embankment

a. triangular x-section

Elevation (feet NGVD)	C	L (feet)	H, avg (feet)	Q (cfs)
1604.17	—	—	0	0
1605.0	2.6	9	0.42	6
1606.0	↓	13	0.92	41
1607.0	↓	↓	1.42	125
1608.0	↓	↓	2.42	234
1609.0	↓	↓	3.42	363
1610.0	↓	↓	4.42	511
1611.0	↓	↓	5.42	674
1612.0	↓	↓	6.42	852
1613.0	↓	↓	7.42	1040

b. remainder of left stone embankment

Elevation (feet NGVD)	C	L (feet)	H, avg (feet)	Q (cfs)
1606.08	—	—	0	0
1607.0	2.6	63	0.75	5
1608.0	↓	74	1.75	45
1609.0	↓	76	2.75	101
1610.0	↓	78	3.75	170

CLIENT Army Corps JOB No. 274-7901 PAGE 6 of 77
 PROJECT Butterfield Pond COMPTD. BY BUP DATE 2/4/80
 DETAIL Hydrologic Calc. CK'D. BY KMS DATE 2/3/80

b. remainder of left stone embankment

Elevation (feet NGVD)	C	L (feet)	H (feet)	Q (cfs)
1611.0	2.6	80	4.75	2150
1612.0	↓	82	5.75	2940
1613.0	↓	84	6.75	3330

5. discharge over right stone embankment

Elevation (feet NGVD)	C	L (feet)	H, avg (feet)	Q (cfs)
1606.48	—	—	0	0
1607.0	2.6	46	0.47	39
1609.0	↓	51	1.47	236
1609.0	↓	↓	2.47	515
1610.0	↓	↓	3.47	857
1611.0	↓	↓	4.47	1250
1612.0	↓	↓	5.47	1700
1613.0	↓	↓	6.47	2180

6. discharge over left training wall & sluice gate structure

a. left training wall

Elevation (feet NGVD)	C	L (feet)	H (feet)	Q (cfs)
1606.58	—	—	0	0
1607.0	2.6	4	0.42	3
1608.0	↓	↓	1.42	13
1609.0	↓	↓	2.42	39
1610.0	↓	↓	3.42	66
1611.0	↓	↓	4.42	97
1612.0	↓	↓	5.42	131
1613.0	↓	↓	6.42	169

CLIENT Army Corps JOB No. 274-7901 PAGE 2 of 47
 PROJECT Butterfield Pond COMPTD. BY BWP DATE 2/4/93
 DETAIL Hydrologic Calcs CK'D. BY KMS DATE 2/3/93

b. Sluiceway structure

Elevation (feet NGVD)	C	L (feet)	H (feet)	Q (cfs)
1607.77	—	—	0	0
1608.0	2.6	17.6	0.23	5
1609.0	↓	↓	1.23	62
1610.0	↓	↓	2.23	152
1611.0	↓	↓	3.23	266
1612.0	↓	↓	4.23	396
1613.0	↓	↓	5.23	547

7. discharge over gravel road to west of right stone embankment

Elevation (feet NGVD)	C	L (feet)	H _{avg} (feet)	Q (cfs)
1607.38	—	—	0	0
1608.0	2.6	32	1.37	19
1609.0	↓	35	1.37	146
1610.0	↓	39	2.37	270
1611.0	↓	42	3.37	676
1612.0	↓	45	4.37	1070
1613.0	↓	49	5.37	1590


CLIENT Army Corps JOB No. 274-7901 PAGE 3 of 22
 PROJECT Bitterfield Pond COMPTD. BY BWP DATE 2/5/90
 DETAIL Hydrologic Calc. CK'D. BY 1115 DATE 2/5/90

3. Total discharge from project site

Elevation (feet NGVD)	Q overland flow	Q from adjacent area	Q total left embankment	Q right embankment	Q from abutment to S. station	Q gravel road	TOTAL
1603.0	0	0	0	0	0	0	0
1604.0	137	10	0	0	0	0	147
1605.0	409	36	6	0	0	0	446
1606.0	751	72	41	0	0	0	864
1607.0	1160	114	240	39	3	0	1560
1608.0	1630	194	679	236	23	19	2790
1609.0	2150	227	1264	515	101	146	4400
1610.0	2720	256	1981	857	219	370	6400
1611.0	3320	231	2324	1250	363	576	9710
1612.0	3970	305	3792	1700	527	1070	11,400
1613.0	4650	327	4870	2180	716	1590	14,300

Discharge vs Elevation shown graphically in Figure 2

FIGURE 1
DISCHARGE VS ELEVATION



CLIENT Army Corps JOB No. 274-2900 PAGE 10 of 77
PROJECT Butterfield Pond Dam COMPTD. BY BWD DATE 2/5/90
DETAIL Hydrologic Calcs CK'D. BY KMS DATE 2/2/90

B. Effect of surcharge storage on max. prob. discharge

1. Pertinent Data

- a. Drainage area = 7.15 square miles
- b. Characteristics of basin - mountainous
- c. Test flood = 1/2 PMF (small size and significant hazard)
- d. Follow Army Corps' procedure

2. STEP 1: Determine Peak Inflow Q_{P1} from Guide Curve

- a. the maximum probable discharge was estimated to be 2100 cfs / sq. mi

$$\therefore \text{PMF} = (2100 \text{ cfs/sq. mi}) (7.15 \text{ sq. mi})$$

$$\approx 15,000 \text{ cfs}$$

$$1/2 \text{ PMF} = 7,500 \text{ cfs}$$

3. STEP 2: Determine surcharge height to pass Q_{P1} , STOR_1 , and Q_{P2}

- a. from Figure 1 determine surcharge height to pass

$$Q_{P1} = 7,500 \text{ cfs}$$

$$\text{surcharge elevation} = 1610.5'$$

$$\text{elev. of overflow spillway weir} = 1603.0'$$

$$\text{surcharge height} = 7.5 \text{ feet}$$


- b. determine volume of surcharge STOR_1 in inches of runoff

first determine volume of storage STOR_1 in inches of runoff

(1) determine surface area of land corresponding to surcharge elevation from Figure 2 = 132 acres

(2) average surface area for surcharge elevation and spillway crest pool (elevation 1603.0')

FIGURE 2
SURFACE AREA VS ELEVATION



DIETZGEN CORPORATION
MADE IN U.S.A.

NO. 341-10 DIETZGEN GRAPH PAPER
10 X 10 PER INCH

ELEVATION, Feet (NGVD)

SURFACE AREA, acres

CLIENT Army Corps JOB No. 274-7301 PAGE 2 of 47
 PROJECT Butterfield Pond COMPTD. BY BWF DATE 2/5/80
 DETAIL Hydrologic Calcs CK'D. BY MS DATE 2/5/80

(3) multiply surcharge (depth above elevation 1603.0 times average surface area to determine volume of storage in acre-ft for input into following equation.

$$STOR_1 = \frac{\text{Volume of storage (in acre-inches)}}{\text{drainage area}}$$

$$STOR_1 = \frac{\left(\frac{132 \text{ acres} + 125 \text{ acres}}{2} \right) (7.5 \text{ feet}) (12 \text{ inches/ft})}{4576 \text{ acres}}$$

$$STOR_1 = 3.02 \text{ inches}$$

c. determine Q_{P2}

$$Q_{P2} = Q_{P1} \left(1 - \frac{STOR_1}{9.5 \text{ inches}} \right)$$

$$Q_{P2} = (7,500 \text{ cfs}) \left(1 - \frac{3.02 \text{ inches}}{9.5 \text{ inches}} \right)$$

$$Q_{P2} \approx 5,120 \text{ cfs}$$

4. STEP 3: Determine surcharge height to pass Q_{P2} and then Q_{P3}

a. From Figure 1 determine surcharge height to pass

$$Q_{P2} = 5,120 \text{ cfs}$$

$$\begin{aligned} \text{surcharge elevation} &= 1609.4 \\ \text{elev. spillway weir crest} &= 1603.0 \\ \text{surcharge height} &= \underline{6.4 \text{ feet}} \end{aligned}$$

$$\text{surface area at } 1609.4' = 174 \text{ acres}$$

CLIENT Army Corps JOB No. 274-7901 PAGE 13 of 42
PROJECT Butterfield Pond COMPTD. BY BWP DATE 2/5/90
DETAIL Hydrologic Calcs. CK'D. BY KMS DATE 2/9/90

b. determine $STOR_2$

$$STOR_2 = \frac{\left(\frac{174ac + 125ac}{2}\right)(6.4 ft)(12"/ft)}{4576 \text{ acres}}$$
$$= 2.51 \text{ inches}$$

c. Average $STOR_1$ and $STOR_2$

$$STOR_{AVG} = \frac{STOR_1 + STOR_2}{2}$$

$$STOR_{AVG} = \frac{3.02'' + 2.51''}{2}$$

$$STOR_{AVG} = 2.77 \text{ inches}$$

d. determine Q_{P3}

$$Q_{P3} = (7,500 \text{ cfs}) \left(1 - \frac{2.77''}{9.5''}\right)$$

$$Q_{P3} = 5,320 \text{ cfs}$$

5. STEP 4: Determine surcharge height for Q_{P3} and $STOR_3$

a. from Figure 1 surcharge height for $Q_{P3} = 5,320 \text{ cfs}$

$$\begin{aligned} \text{surcharge elevation} &= 1609.5' \\ \text{elev spillway weir crest} &= 1603.0' \\ \text{surcharge height} &= 6.5 \text{ feet} \end{aligned}$$

$$\text{surface area at } 1609.5' = 175 \text{ acres}$$

b. determine $STOR_3$

$$STOR_3 = \frac{\left(\frac{175ac + 125ac}{2}\right)(6.5 ft)(12"/ft)}{4576 \text{ acres}}$$

CLIENT Army Corps JOB No. 104-7901 PAGE 14 of
PROJECT Butterfield Pond COMPTD. BY SWE DATE 3/5/9
DETAIL Hydrologic Calcs CK'D. BY AMS DATE 3/5/9

$$STOR_3 = 2.56 \text{ inches}$$

c. determine $STOR_{AVG}$

$$STOR_{AVG} = \frac{2.77'' + 2.56''}{2}$$

$$STOR_{AVG} = 2.67 \text{ inches}$$

d. determine Q_{p4}

$$Q_{p4} = (7,500 \text{ cfs}) \left(1 - \frac{2.67''}{9.5''}\right)$$

$$Q_{p4} = 5,390 \text{ cfs}$$

6. STEP 5: Determine surcharge height for Q_{p4} and $STOR_4$, and Q_{p5}

a. From Figure 1 surcharge height for $Q_{p4} = 5,390 \text{ c}$

$$\begin{aligned} \text{surcharge elevation} &= 1609.5 \\ \text{elev. spillway weir crest} &= 1603.0 \\ \text{surcharge height} &= 6.5 \end{aligned}$$

$$\text{surface area at } 1609.5' = 175$$

b. determine $STOR_4$

$$STOR_4 = \frac{\left(\frac{175 \text{ ac} + 125 \text{ ac}}{2}\right) (6.5 \text{ ft}) (12''/ft)}{4576 \text{ acres}}$$

$$STOR_4 = 2.56 \text{ inches}$$

c. determine $STOR_{AVG}$

$$STOR_{AVG} = \frac{2.67'' + 2.56''}{2}$$

$$= 2.62 \text{ inches}$$

CLIENT <u>Army Corps</u>	JOB No. <u>274-7901</u>	PAGE <u>5 of 47</u>
PROJECT <u>Butterfield Pond Dam</u>	COMPTD. BY <u>RWP</u>	DATE <u>2-5-80</u>
DETAIL <u>Hydrologic Calcs</u>	CK'D. BY <u>KMS</u>	DATE <u>2-5-80</u>

d. determine Q_{P5}

$$Q_{P5} = (7,500 \text{ cfs}) \left(1 - \frac{2.62''}{9.5''}\right)$$

$$Q_{P5} = 5,430 \text{ cfs}$$

6. STEP 6: Determine surcharge height for Q_{P5} and $STOR_5$

a. From Figure 1 surcharge height for $Q_{P5} = 5,430 \text{ cfs}$

$$\begin{aligned} \text{surcharge height} &= 1609.5' \\ \text{elev. spillway weir crest} &= 1603.0 \\ \text{surcharge height} &= 6.5 \text{ feet} \end{aligned}$$

$$\text{Surface area at } 1609.5' = 175 \text{ acres}$$

b. determine $STOR_5$

$$STOR_5 = \frac{\left(\frac{175 \text{ ac} + 125 \text{ ac}}{2}\right) (6.5 \text{ ft}) (12''/ft)}{4,576 \text{ acres}}$$

$$STOR_5 = 2.56 \text{ inches}$$

c. determine $STOR_{AVG}$

$$STOR_{AVG} = \frac{2.62'' + 2.56''}{2}$$

$$STOR_{AVG} = 2.59 \text{ inches}$$

$STOR_5$ and $STOR_{AVG}$ agree to within about 1%, therefore accept test discharge = 5,430 cfs at surcharge elev. = 1609.5 feet

7. In Conclusion

a. Test flood discharge = 5,430 cfs and will overtop over spillway weir crest by 6.5 feet and the dam crest by 5.3 feet

CLIENT Game Corps JOB No. 274-7901 PAGE 16 of 47
PROJECT Butterfield Pond Dam COMPTD. BY BWP DATE 2/5/80
DETAIL Hydrologic Calcs CK'D. BY IMS DATE 2/5/80

b. overflow spillway capacity

(1) water surface at low point on left side embankment - 1604.2'

$$Q = (2.6)(16.2')(1604.2 - 1603.0)^{3/2} + (2.6)(40.9')(1604.2 - 1603.2)^{3/2} \approx \underline{160 cfs}$$

(2) water surface at top of left abutment - 1606.6'

$$Q = (2.6)(16.2')(1606.6 - 1603.0)^{3/2} + (2.6)(40.9')(1606.6 - 1603.2)^{3/2} \approx \underline{450 cfs}$$

(3) water surface at test flood elevation - 1609.5'

$$Q = (2.6)(16.2')(1609.5 - 1603.0)^{3/2} + (2.6)(40.9')(1609.5 - 1603.2)^{3/2} \approx \underline{2375 cfs}$$

c. sluiceway capacity - includes discharge through 6.1' wide by 6.05' high sluiceway - orifice discharge

(1) water surface at low point on left side embankment - 1604.2'

$$Q_{sluiceway} = (0.6)(6.1')(6.05') \left[(2)(33.2) (1604.2 - 1598.25) \right]$$

$$Q_{sluiceway} \approx 435 cfs$$

(2) water surface at top of left abutment - 1606.6'

$$Q_{sluiceway} = (0.6)(6.1')(6.05') \left[(2)(33.2) (1606.6 - 1598.25) \right]$$

$$Q_{sluiceway} \approx 515 cfs$$

SIEIA CONSULTANTS INC.
ENGINEERS / PLANNERS

BOSTON, MASS.
ROCHESTER, N.H.

CLIENT Army Corps JOB No. 274-7901 PAGE 17 of 47
PROJECT Butterfield Pond Dam COMPTD. BY BWP DATE 2/5/90
DETAIL _____ CK'D. BY ... DATE 2/9/90

(3) water surface at test flood elevation - 1609.5'

$$(a) Q_{sluiceway} = (0.6)(6.1')(6.05') \left[(2)(32.2') (1609.5' - 1598.25') \right]^{1/2}$$

$$Q_{sluiceway} \approx 595 \text{ cfs}$$

d capacity of low flow spillway

$$Q = (2.6)(16.2)(0.2)^{3/2} = 3.9 \text{ cfs}$$

CLIENT Army Corps JOB No. 274-7901 PAGE 18 of 47
PROJECT Brightfield Pond Dam COMPTD. BY BWP DATE 2/5/80
DETAIL Hydrologic Calcs CK'D. BY KMS DATE 3/8/80

III. Using "Rule of Thumb" Guidance for Estimating Downstream Dam Failure
Hydrographs examine impact of dam failure

1. Pertinent Data

- a. Failure occurs when reservoir level at crest of dam - elevation = 1604.2 feet
- b. Storage at crest elevation estimated to be approximately 590 acre-feet

A. Reach 1

1. STEP 1: Determine reservoir storage at time of failure

from previous calcs. storage = 590 acre-ft

2. STEP 2: Determine Peak Failure Outflow Q_{P1}

$$Q_{P1} = (8/27) W_b \sqrt{g} Y_o^{3/2}$$

where: W_b = Breach width (use 40% of total length)
= (210 feet)(0.40)
= 84 feet

Y_o = Total height from channel bed to pool level at failure
= 12.2 feet $\frac{1604.2'}{12.2'}$
= 12.2 feet $\approx \frac{1592.0'}{12.2'}$

$$Q_{P1} = (8/27)(84 \text{ feet})(32.2)^{1/2}(12.2 \text{ ft})^{3/2}$$

$$Q_{P1} \approx 6,000 \text{ cfs}$$

The failure flow is negligible compared to the dam failure discharge, and therefore is not included as part of these calculations.

CLIENT Army Corps JOB No. 244-7901 PAGE 19 of 47
PROJECT Butterfield Pond Dam COMPTD. BY BWP DATE 2/5/80
DETAIL Hydrologic Calcs. CK'D. BY XMS DATE 2/8/80

3. STEP 3: Prepare stage-discharge curve for Reach 1

a. Pertinent Data

- (1) Reach length = 350 feet
- (2) Channel slope = 0.0155
- (3) Manning n = 0.05
- (4) Channel shape - trapezoidal
- (5) Base width \approx 20 feet

b. See Figure 3 for stage-discharge curve

4. STEP 4: Estimate Reach Outflow

- a. Determine stage for $Q_{P1} = 6000 \text{ cfs}$ from Figure 3 and find volume in reach

(1) Stage (depth of flow) = 7.6 feet

(2) Volume in reach = (reach length) $\left(\begin{matrix} \text{cross-sectional} \\ \text{area of channel} \end{matrix} \right)$

$$\begin{aligned} \text{x-area} &= (0.5) (7.6 \text{ ft}) (20 \text{ ft} + 133 \text{ ft}) \\ &= 581 \text{ ft}^2 \end{aligned}$$

$$\text{Volume} = V_1 = \frac{(581 \text{ ft}^2) (350 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}}$$

$$= 4.7 \text{ acre-ft}$$

$$V_1 < \frac{S}{2} \therefore \text{reach length OK}$$

- b. Determine Q_P (TRIAL)

$$Q_{P2(\text{TRIAL})} = Q_{P1} \left(1 - \frac{V_1}{S} \right)$$

$$Q_{P2(\text{TRIAL})} = (6000 \text{ cfs}) \left(1 - \frac{4.7 \text{ acre-ft}}{590 \text{ acre-ft}} \right)$$

$$Q_{P2(\text{TRIAL})} = 5950 \text{ cfs}$$

CLIENT Army Corps JOB No. 274-7901 PAGE 20 of 47
PROJECT Butterfield Pond Dam COMPTD. BY BWP DATE 2/5/80
DETAIL Hydrologic Calcs. CK'D. BY KMS DATE 2/9/80

c. Compute V_2 using Q_{P2} (TRIAL)

From Figure 3 determine stage for Q_{P2} (TRIAL)

$$\text{Stage} = 7.5 \text{ feet}$$

$$\begin{aligned} \text{X-area} &= (0.5)(7.5 \text{ ft})(20 \text{ ft} + 132 \text{ ft}) \\ &= 570 \text{ ft}^2 \end{aligned}$$

$$V_2 = \frac{(570 \text{ ft}^2)(350 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}}$$

$$V_2 = 4.6 \text{ acre-ft}$$

d. Average V_1 and V_2 and compute Q_{P2}

$$(1) V_{\text{avg}} = \frac{V_1 + V_2}{2}$$

$$V_{\text{avg}} = \frac{4.7 \text{ ac-ft} + 4.6 \text{ ac-ft}}{2}$$

$$V_{\text{avg}} = 4.7 \text{ acre-ft}$$

$$(2) Q_{P2} = Q_{P1} \left(1 - \frac{V_{\text{avg}}}{S}\right)$$

$$Q_{P2} = (6000 \text{ cfs}) \left(1 - \frac{4.7}{590}\right)$$

$$Q_{P2} = 5950 \text{ cfs}$$

CLIENT Army Corps JOB No. 244-7901 PAGE 21 of 47
PROJECT Butterfield Pond Dam COMPTD. BY BWP DATE 2/5/90
DETAIL Hydrologic Calcs. CK'D. BY AMS DATE 2/2/90

3. Reach 2

3. STEP 3: Prepare stage-discharge curve for Reach 2

a. Pertinent Data

- (1) Reach length = 175 feet
- (2) Channel slope = 0.0375
- (3) Manning n = 0.05
- (4) Channel shape - trapezoidal
- (5) Base width \approx 20 feet

b. See Figure 3 for stage-discharge curve

4. STEP : Estimate Reach Outflow

a. Determine stage for $Q_{P2} = 5950$ cfs from Figure 3 and find volume in reach

(1) Stage (depth of flow) = 6.3 feet

(2) Volume in reach = (reach length) $\left(\begin{matrix} \text{cross-sectional} \\ \text{area of channel} \end{matrix} \right)$

$$\begin{aligned} X\text{-area} &= (0.5)(6.3\text{ft})(20\text{ft} + 115\text{ft}) \\ &\approx 425 \text{ ft}^2 \end{aligned}$$

$$\begin{aligned} \text{Volume} = V_1 &= \frac{(425 \text{ ft}^2)(175 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}} \\ &= 1.7 \text{ ac-ft} \end{aligned}$$

$$V_1 < \frac{S}{2} \therefore \text{reach length OK}$$

b. Determine $Q_{P2(\text{TRIAL})}$

$$Q_{P2(\text{TRIAL})} = Q_{P2} \left(1 - \frac{V_1}{S} \right)$$

$$Q_{P2(\text{TRIAL})} = (5950 \text{ cfs}) \left(1 - \frac{1.7}{590} \right)$$

$$Q_{P2(\text{TRIAL})} = 5930 \text{ cfs}$$

CLIENT Army Corps JOB NO. 274-7901 PAGE 22 of 47
PROJECT Butterfield Pond Dam COMPTD. BY BWP DATE 2/5/80
DETAIL Hydrologic Calcs CK'D. BY WJS DATE - - -

c. Compute V_2 using Q_{P2} (TRIAL)

From Figure 3 determine stage for Q_p (TRIAL)

$$\text{Stage} = 6.3 \text{ feet}$$

$$\begin{aligned} X\text{-area} &= (0.5)(6.3 \text{ ft})(20 \text{ ft} + 115 \text{ ft}) \\ &\approx 425 \text{ ft}^2 \end{aligned}$$

$$V_2 = \frac{(425 \text{ ft}^2)(175 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}}$$

$$V_2 = 1.7 \text{ acre-ft}$$

d. Average V_1 and V_2 and compute Q_{P3}

$$(1) V_{\text{avg}} = \frac{V_1 + V_2}{2}$$

$$V_{\text{avg}} = \frac{1.7 \text{ ac-ft} + 1.7 \text{ ac-ft}}{2}$$

$$V_{\text{avg}} = 1.7 \text{ acre-ft}$$

$$(2) Q_{P3} = Q_{P2} \left(1 - \frac{V_{\text{avg}}}{S}\right)$$

$$Q_{P3} = (5,950 \text{ cfs}) \left(1 - \frac{1.7}{590}\right)$$

$$Q_{P3} = 5,930 \text{ cfs}$$

CLIENT Army Corps JOB No. 244-7901 PAGE 23 of 47
PROJECT Bitterheld Pond Dam COMPTD. BY BWP DATE 2/5/90
DETAIL Hydrologic Calcs. CK'D. BY AMS DATE 2/9/90

C. Reach 3

3. STEP 3: Prepare stage-discharge curve for Reach 3

a. Pertinent Data

- (1) Reach length = 725 feet
- (2) Channel slope = 0.0276
- (3) Manning n = 0.05
- (4) Channel shape - trapezoidal
- (5) Base width \approx 20 feet

b. See Figure 3 for stage-discharge curve

4. STEP 4: Estimate Reach Outflow

a. Determine stage for $Q_{P3} = 5,930$ cfs from Figure 3 and find volume in reach

- (1) Stage (depth of flow) = 6.8 feet

- (2) Volume in reach = (reach length) $\left(\frac{\text{cross-sectional area of channel}}{\text{area of channel}} \right)$

$$\text{X-area} = (0.5)(6.8)(20 + 122 \text{ ft}) \\ \approx 483 \text{ ft}^2$$

$$\text{Volume} = V_1 = \frac{(483 \text{ ft}^2)(725 \text{ ft})}{43.560 \text{ ft}^2/\text{acre}} \\ = 8.0 \text{ acre-ft}$$

$$V_1 < \frac{S}{2} \therefore \text{reach length OK}$$

b. Determine $Q_{P4(\text{TRIAL})}$

$$Q_{P4(\text{TRIAL})} = Q_{P3} \left(1 - \frac{V_1}{S} \right)$$

$$Q_{P4(\text{TRIAL})} = (5,930 \text{ cfs}) \left(1 - \frac{8.0}{590} \right)$$

$$Q_{P4(\text{TRIAL})} = 5,850 \text{ cfs}$$

CLIENT Army Corps JOB No. 274-7901 PAGE 34 of 47
PROJECT Battenheld Pond Dam COMPTD. BY BWP DATE 2/5/90
DETAIL Hydrologic Calcs. CK'D. BY KMS DATE 2/2/90

c. Compute V_2 using $Q_{P4}(\text{TRIAL})$

From Figure 3 determine stage for $Q_{P4}(\text{TRIAL})$

$$\text{Stage} = 6.8 \text{ feet}$$

$$\begin{aligned} X\text{-area} &= (0.5)(6.8 \text{ ft})(20 \text{ ft} + 122 \text{ ft}) \\ &\approx 483 \text{ ft}^2 \end{aligned}$$

$$V_2 = \frac{(483 \text{ ft}^2)(725 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}}$$

$$V_2 = 8.0 \text{ acre-ft}$$

d. Average V_1 and V_2 and compute

$$(1) V_{\text{avg}} = \frac{V_1 + V_2}{2}$$

$$V_{\text{avg}} = \frac{8.0 \text{ acre-ft} + 8.0 \text{ acre-ft}}{2}$$

$$V_{\text{avg}} = 8.0 \text{ acre-ft}$$

$$(2) Q_{P4} = Q_{P3} \left(1 - \frac{V_{\text{avg}}}{S}\right)$$

$$Q_{P4} = (5,930 \text{ cfs}) \left(1 - \frac{8.0}{590}\right)$$

$$Q_{P4} = 5,850 \text{ cfs}$$

CLIENT Army Corps JOB No. 244-7901 PAGE 24
PROJECT B. D. ... COMPTD. BY BWP DATE 2/5/90
DETAIL Hydrologic Calcs. CK'D. BY KMS DATE ...

D, Reach 4

3. STEP 3: Prepare stage-discharge curve for Reach 4

a. Pertinent Data

- (1) Reach length = 1650 feet
- (2) Channel slope = 0.0077
- (3) Manning n = 0.05
- (4) Channel shape - trapezoidal
- (5) Base width \approx 20 feet

b. See Figure 3 for stage-discharge curve

4. STEP 4: Estimate Reach Outflow

a. Determine stage for $Q_{P4} = 5,850 \text{ cfs}$ from Figure 3 and find volume in reach

(1) Stage (depth of flow) = 4.4 feet

(2) Volume in reach = (reach length) $\left(\frac{\text{cross-sectional}}{\text{area of channel}} \right)$

$$\begin{aligned} \text{X-area} &= (0.5)(4.4 \text{ ft})(20 \text{ ft} + 530 \text{ ft}) \\ &= 1320 \text{ ft}^2 \end{aligned}$$

$$\begin{aligned} \text{Volume} = V_1 &= \frac{(1320 \text{ ft}^2)(1650 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}} \\ &= 50.0 \text{ acre-ft} \end{aligned}$$

$$V_1 < \frac{S}{2} \therefore \text{reach length OK}$$

b. Determine $Q_{P5(\text{TRIAL})}$

$$Q_{P5(\text{TRIAL})} = Q_{P4} \left(1 - \frac{V_1}{S} \right)$$

$$Q_{P5(\text{TRIAL})} = (5,850 \text{ cfs}) \left(1 - \frac{50}{590} \right)$$

$$Q_{P5(\text{TRIAL})} = 5,350 \text{ cfs}$$

CLIENT Army Corps JOB No. 274-7901 PAGE 26 of 47
PROJECT Fullerton Pond Dam COMPTD. BY BWF DATE 2/5/90
DETAIL Hydrologic Calcs CK'D. BY 241 DATE 2/5/90

c. Compute V_2 using $Q_{P5}(\text{TRIAL})$

From Figure 3 determine stage for $Q_{P5}(\text{TRIAL})$

$$\text{Stage} = 4.2 \text{ feet}$$

$$\begin{aligned} \text{X-area} &= (0.5)(4.2 \text{ ft})(20 \text{ ft} + 554 \text{ ft}) \\ &\approx 1205 \text{ ft}^2 \end{aligned}$$

$$V_2 = \frac{(1205 \text{ ft}^2)(1650 \text{ feet})}{43,560 \text{ ft}^2/\text{acre}}$$

$$V_2 = 45.7 \text{ acre-ft}$$

d. Average V_1 and V_2 and compute S

$$(1) V_{\text{avg}} = \frac{V_1 + V_2}{2}$$

$$V_{\text{avg}} = \frac{50.0 \text{ ac-ft} + 45.7 \text{ ac-ft}}{2}$$

$$V_{\text{avg}} = 47.9 \text{ acre-ft}$$

$$(2) Q_{P5} = Q_{P4} \left(1 - \frac{V_{\text{avg}}}{S} \right)$$

$$Q_{P5} = (5,850 \text{ cfs}) \left(1 - \frac{47.9}{590} \right)$$

$$Q_{P5} = 5,380 \text{ cfs}$$

CLIENT Army Corps JOB No. 244-7901 PAGE 27 of 47
PROJECT Wetlands Pond Dam COMPTD. BY BWP DATE 2/1/90
DETAIL Hydrologic Calcs. CK'd. BY MS DATE 2/1/90

E. Reach 5

3. STEP 3: Prepare stage-discharge curve for Reach 5

a. Pertinent Data

- (1) Reach length = 950 feet
- (2) Channel slope = 0.0077
- (3) Manning n = 0.05
- (4) Channel shape - trapezoidal
- (5) Base width \approx 20 feet

b. See Figure 3 for stage-discharge curve

4. STEP 4: Estimate Reach Outflow

a. Determine stage for $Q_{P5} = 5,380 \text{ cfs}$ from Figure 3 and find volume in reach

(1) Stage (depth of flow) = 6.8 feet

(2) Volume in reach = (reach length) (cross-sectional area of channel)

$$\begin{aligned} X\text{-area} &= (0.5)(6.8 \text{ feet})(20 \text{ feet} + 234 \text{ feet}) \\ &\approx 864 \text{ ft}^2 \end{aligned}$$

$$\text{Volume} = V_1 = \frac{(864 \text{ ft}^2)(950 \text{ feet})}{43,560 \text{ ft}^2/\text{acre}}$$

$$= 18.8 \text{ acre-ft}$$

$$V_1 < \frac{S}{2} \text{ L reach length OK}$$

b. Determine Q_{P6} (TRIAL)

$$Q_{P6}(\text{TRIAL}) = Q_{P5} \left(1 - \frac{V_1}{S}\right)$$

$$Q_{P6}(\text{TRIAL}) = (5,380 \text{ cfs}) \left(1 - \frac{18.8}{590}\right)$$

$$Q_{P6} = 5,210 \text{ cfs}$$

AD-A156 529

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
BUTTERFIELD POND DAM (..(U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV MAR 80

2/2


UNCLASSIFIED

F/G 13/13

NL



END
FILMED
DTIC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

CLIENT Army Corps JOB No. 274-7901 PAGE 23 of 47
PROJECT Butterfield Pond Dam COMPTD. BY BWP DATE 2/6/80
DETAIL Hydrologic Calcs CK'D. BY XMS DATE 2/2/80

c. Compute V_2 using Q_{P6} (TRIAL)

From Figure 3 determine stage for Q_P (TRIAL)

$$\text{Stage} = 6.7 \text{ feet}$$

$$\begin{aligned} X\text{-area} &= (0.5)(6.7 \text{ feet})(20 \text{ feet} + 230 \text{ feet}) \\ &\approx 838 \text{ ft}^2 \end{aligned}$$

$$V_2 = \frac{(838 \text{ ft}^2)(950 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}}$$

$$V_2 = 18.3 \text{ acre-ft}$$

d. Average V_1 and V_2 and compute Q_6

$$(1) V_{\text{avg}} = \frac{V_1 + V_2}{2}$$

$$V_{\text{avg}} = \frac{18.8 \text{ acre-ft} + 18.3 \text{ acre-ft}}{2}$$

$$V_{\text{avg}} = 18.5 \text{ acre-ft}$$

$$(2) Q_{P6} = Q_{P5} \left(1 - \frac{V_{\text{avg}}}{S}\right)$$

$$Q_{P6} = (5,380 \text{ cfs}) \left(1 - \frac{18.5}{590}\right)$$

$$Q_{P6} = 5,210 \text{ cfs}$$

CLIENT Army Corps JOB No. 244-7901 PAGE 29 of 47
PROJECT Bitterhead Pond Dam COMPTD. BY BWP DATE 2/6/90
DETAIL Hydrologic Calcs. CK'D. BY KMS DATE 2/8/90

F. Reach 6

3. STEP 3: Prepare stage-discharge curve for Reach 6

a. Pertinent Data

- (1) Reach length = 1550 feet
- (2) Channel slope = 0.00457
- (3) Manning n = 0.05
- (4) Channel shape - trapezoidal
- (5) Base width \approx 20 feet

b. See Figure 3 for stage-discharge curve

4. STEP 4: Estimate Reach Outflow

a. Determine stage for $Q_{P6} = 5,210$ cfs from Figure 3 and find volume in reach

(1) Stage (depth of flow) = 7.5 feet

(2) Volume in reach = (reach length) $\left(\begin{array}{l} \text{cross-sectional} \\ \text{area of channel} \end{array} \right)$

$$\begin{aligned} X\text{-area} &= (0.5)(7.5 \text{ feet})(20 \text{ feet} + 255 \text{ feet}) \\ &= 1031 \text{ ft}^2 \end{aligned}$$

$$\text{Volume} = V_1 = \frac{(1031 \text{ ft}^2)(1550 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}}$$

$$= 36.7 \text{ acre-ft}$$

$$V_1 < \frac{S}{2} \therefore \text{reach length OK}$$

b. Determine Q_{P7} (TRIAL)

$$Q_{P7}(\text{TRIAL}) = Q_{P6} \left(1 - \frac{V_1}{S} \right)$$

$$Q_{P7}(\text{TRIAL}) = (5,210 \text{ cfs}) \left(1 - \frac{36.7}{590} \right)$$

$$Q_{P7}(\text{TRIAL}) = 4,890 \text{ cfs}$$

SIEJA CONSULTANTS INC.
ENGINEERS / PLANNERS

BOSTON, MASS.
ROCHESTER, N.H.

CLIENT Army Corps JOB No. 274-7901 PAGE 30 of 47
PROJECT Bullards Pond Dam COMPTD. BY BWP DATE 2/6/90
DETAIL Hydrologic Calcs CK'D. BY JM DATE 2-6-90

c. Compute V_2 using $Q_{P7}(\text{TRIAL})$

From Figure 3 determine stage for $Q_{P7}(\text{TRIAL})$

$$\text{Stage} = 7.3 \text{ feet}$$

$$\begin{aligned} \text{X-area} &= (0.5)(7.3 \text{ feet})(20 \text{ ft} + 249 \text{ ft}) \\ &= 982 \text{ ft}^2 \end{aligned}$$

$$V_2 = \frac{(982 \text{ ft}^2)(1550 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}}$$

$$V_2 = 34.9 \text{ acre-ft}$$

d. Average V_1 and V_2 and compute Q_{P7}

$$(1) V_{\text{avg}} = \frac{V_1 + V_2}{2}$$

$$V_{\text{avg}} = \frac{36.7 \text{ ac-ft} + 34.9 \text{ ac-ft}}{2}$$

$$V_{\text{avg}} = 35.8 \text{ acre-ft}$$

$$(2) Q_{P7} = 0.6 \left(1 - \frac{V_{\text{avg}}}{T} \right)$$

$$Q_{P7} = (5,210 \text{ cfs}) \left(1 - \frac{35.8}{590} \right)$$

$$Q_{P7} = 4,890 \text{ cfs}$$

CLIENT Army Corps JOB No. 244-7901 PAGE 31 of 47
PROJECT Butterfield Pond Dam COMPTD. BY BWP DATE 2/6/90
DETAIL Hydrologic Calcs. CK'D. BY KMS DATE 2/5/90

G Reach 7

3. STEP 3: Prepare stage-discharge curve for Reach 7

a. Pertinent Data

- (1) Reach length = 2825 feet
- (2) Channel slope = 0.00457
- (3) Manning n = 0.05
- (4) Channel shape - trapezoidal
- (5) Base width \approx 20 feet

b. See Figure 3 for stage-discharge curve

4. STEP 4: Estimate Reach Outflow

a. Determine stage for $Q_{p7} = 4,890 \text{ cfs}$ from Figure 3 and find volume in reach

- (1) Stage (depth of flow) = 7.4 feet

- (2) Volume in reach = (reach length) $\left(\begin{array}{l} \text{cross-sectional} \\ \text{area of channel} \end{array} \right)$

$$\begin{aligned} X\text{-area} &= (0.5)(7.4 \text{ feet})(20 \text{ ft} + 245 \text{ ft}) \\ &= 981 \text{ ft}^2 \end{aligned}$$

$$\text{Volume} = V_1 = \frac{(981 \text{ ft}^2)(2825 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}}$$

$$= 63.6 \text{ acre-ft}$$

$$V_1 < \frac{S}{2} \therefore \text{reach length OK}$$

b. Determine $Q_{p8}(\text{TRIAL})$

$$Q_{p8}(\text{TRIAL}) = Q_{p7} \left(1 - \frac{V_1}{S} \right)$$

$$Q_{p8}(\text{TRIAL}) = (4,890 \text{ cfs}) \left(1 - \frac{63.6}{595} \right)$$

$$Q_{p8}(\text{TRIAL}) = 4,360 \text{ cfs}$$

CLIENT Army Corps JOB No. 274-7901 PAGE 32 of 47
PROJECT Batterfield Pond Dam COMPTD. BY BWF DATE 2/6/90
DETAIL Hydrologic Calcs CK'D. BY W/S DATE 2/8/90

c. Compute V_2 using $Q_{p8}(\text{TRIAL})$

From Figure 3 determine stage for $Q_{p8}(\text{TRIAL})$

$$\text{Stage} = 7.0 \text{ feet}$$

$$\begin{aligned} X\text{-area} &= (0.5)(7.0 \text{ feet})(10 \text{ ft} + 232 \text{ ft}) \\ &= 882 \text{ ft}^2 \end{aligned}$$

$$V_2 = \frac{(882 \text{ ft}^2)(2825 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}}$$

$$V_2 = 57.2 \text{ acre-ft}$$

d. Average V_1 and V_2 and compute Q_{p8}

$$(1) V_{\text{avg}} = \frac{V_1 + V_2}{2}$$

$$V_{\text{avg}} = \frac{63.6 \text{ ac-ft} + 57.2 \text{ ac-ft}}{2}$$

$$V_{\text{avg}} = 60.4 \text{ acre-ft}$$

$$(2) Q_{p8} = Q_{p7} \left(1 - \frac{V_{\text{avg}}}{S}\right)$$

$$Q_{p8} = (4,890 \text{ cfs}) \left(1 - \frac{60.4}{590}\right)$$

$$Q_{p8} = 4,390 \text{ cfs}$$

CLIENT Army Corps JOB No. 244-7901 PAGE 33 of 47
PROJECT Bitterfield Pond Dam COMPTD. BY BWP DATE 2/6/90
DETAIL Hydrologic Calcs. CK'D. BY KMS DATE 2-3-90

H. Reach 8

3. STEP 3: Prepare stage-discharge curve for Reach 3

a. Pertinent Data

- (1) Reach length = 5625 feet
- (2) Channel slope = 0.00356
- (3) Manning n = 0.05
- (4) Channel shape - trapezoidal
- (5) Base width \approx 20 feet

b. See Figure 3 for stage-discharge curve

4. STEP 4: Estimate Reach Outflow

a. Determine stage for $Q_{p8} = 4,390$ cfs from Figure 3 and find volume in reach

(1) Stage (depth of flow) = 6.1 feet

(2) Volume in reach = (reach length) $\left(\frac{\text{cross-sectional area of channel}}{\text{area of channel}} \right)$

$$\begin{aligned} X\text{-area} &= (0.5)(6.1 \text{ feet})(20 \text{ feet} + 355 \text{ feet}) \\ &= 1144 \text{ ft}^2 \end{aligned}$$

$$\begin{aligned} \text{Volume} = V_1 &= \frac{(1144 \text{ ft}^2)(5625 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}} \\ &= 148 \text{ acre-ft} \end{aligned}$$

$$V_1 < \frac{S}{2} \therefore \text{reach length OK}$$

b. Determine Q_{p9} (TRIAL)

$$Q_{p9}(\text{TRIAL}) = Q_{p8} \left(1 - \frac{V_1}{S} \right)$$

$$Q_{p9}(\text{TRIAL}) = (4,390 \text{ cfs}) \left(1 - \frac{148}{590} \right)$$

$$Q_{p9}(\text{TRIAL}) = 3,290 \text{ cfs}$$

CLIENT Army Corps JOB No. 274-7901 PAGE 34 of 47
PROJECT Billerfield Pond Dam COMPTD. BY BWP DATE 2/6/80
DETAIL Hydrologic Calcs. CK'D. BY AMS DATE 2/4/80

c. Compute V_2 using $Q_{Pq}(\text{TRIAL})$

From Figure 3 determine stage for $Q_{Pq}(\text{TRIAL})$

$$\text{Stage} = 5.4 \text{ feet}$$

$$\begin{aligned} X\text{-area} &= (0.5)(5.4 \text{ feet})(20 \text{ feet} + 318 \text{ ft}) \\ &= 913 \text{ ft}^2 \end{aligned}$$

$$V_2 = \frac{(913 \text{ ft}^2)(5625 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}}$$

$$V_2 = 118 \text{ acre-ft}$$

d. Average V_1 and V_2 and compute Q_{Pq}

$$(1) V_{\text{avg}} = \frac{V_1 + V_2}{2}$$

$$V_{\text{avg}} = \frac{140 \text{ ac-ft} + 118 \text{ ac-ft}}{2}$$

$$V_{\text{avg}} = 133 \text{ acre-feet}$$

$$(2) Q_{Pq} = Q_{PB} \left(1 - \frac{V_{\text{avg}}}{S} \right)$$

$$Q_{Pq} = (4,390 \text{ cfs}) \left(1 - \frac{133}{590} \right)$$

$$Q_{Pq} = 3,400 \text{ cfs}$$

CLIENT Army Corps JOB No. 244-7901 PAGE 35 of 47
PROJECT Butterfield Pond Dam COMPTD. BY BWP DATE 2/7/90
DETAIL Hydrologic Calcs. CK'D. BY M/S DATE 2/9/90

I Reach 9

3. STEP 3: Prepare stage-discharge curve for Reach 9

a. Pertinent Data

- (1) Reach length = 2875 feet
- (2) Channel slope = 0.0139
- (3) Manning n = 0.08
- (4) Channel shape - trapezoidal
- (5) Base width \approx 40 feet

b. See Figure 3 for stage-discharge curve

4. STEP 4: Estimate Reach Outflow

a. Determine stage for $Q_{P9} = 3,400$ cfs from Figure 3 and find volume in reach

(1) Stage (depth of flow) = 5.5 feet

(2) Volume in reach = (reach length) (cross-sectional area of channel)

$$\begin{aligned} X\text{-area} &= (0.5)(5.5 \text{ feet})(40 \text{ ft} + 720 \text{ ft}) \\ &= 2090 \text{ ft}^2 \end{aligned}$$

$$\begin{aligned} \text{Volume} = V_1 &= \frac{(2090 \text{ ft}^2)(2875 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}} \\ &= 138 \text{ acre-ft} \end{aligned}$$

$$V_1 < \frac{S}{2} \therefore \text{reach length OK}$$

b. Determine $Q_{P10}(\text{TRIAL})$

$$Q_{P10}(\text{TRIAL}) = Q_{P9} \left(1 - \frac{V_1}{S}\right)$$

$$Q_{P10}(\text{TRIAL}) = (3,400 \text{ cfs}) \left(1 - \frac{138}{590}\right)$$

$$Q_{P10}(\text{TRIAL}) = 2610 \text{ cfs}$$

CLIENT Army Corps JOB No. 274-7901 PAGE 35 of 47
PROJECT Butterfield Pond Dam COMPTD. BY BWP DATE 2/7/80
DETAIL Hydrologic Calcs CK'D. BY KMS DATE 2/8/80

c. Compute V_2 using $Q_{P10}(\text{TRIAL})$

From Figure 3 determine stage for $Q_{P10}(\text{TRIAL})$

$$\text{Stage} = 4.9 \text{ feet}$$

$$\begin{aligned} X\text{-area} &= (0.5)(4.9 \text{ ft})(40 \text{ ft} + 600 \text{ ft}) \\ &= 1568 \text{ ft}^2 \end{aligned}$$

$$V_2 = \frac{(1568 \text{ ft}^2)(2875 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}}$$

$$V_2 = 103 \text{ acre-ft}$$

d. Average V_1 and V_2 and compute Q_p

$$(1) V_{\text{avg}} = \frac{V_1 + V_2}{2}$$

$$V_{\text{avg}} = \frac{138 \text{ ac-ft} + 103 \text{ ac-ft}}{2}$$

$$V_{\text{avg}} = 121 \text{ acre-ft}$$

$$(2) Q_{P10} = Q_{T9} \left(1 - \frac{V_{\text{avg}}}{S}\right)$$

$$Q_{P10} = (3,400 \text{ cfs}) \left(1 - \frac{121}{590}\right)$$

$$Q_{P10} = 2,710 \text{ cfs}$$

CLIENT Army Corps JOB No. 244-7901 PAGE 37 of 47
PROJECT Butter Field Pond Dam COMPTD. BY BWP DATE 2/7/95
DETAIL Hydrologic Calcs. CK'D. BY AMS DATE 2/5/95

J. Reach 10

3. STEP 3: Prepare stage-discharge curve for Reach 10

a. Pertinent Data

- (1) Reach length = 5,300 feet
- (2) Channel slope = 0.0011
- (3) Manning n = 0.08
- (4) Channel shape - trapezoidal
- (5) Base width \approx 40 feet

b. See Figure 3 for stage-discharge curve

4. STEP 4: Estimate Reach Outflow

a. Determine stage for $Q_{p10} = 2,710$ cfs from Figure 3 and find volume in reach

(1) Stage (depth of flow) = 6.7 feet

(2) Volume in reach = (reach length) $\left(\begin{smallmatrix} \text{cross-sectional} \\ \text{area of channel} \end{smallmatrix} \right)$

$$\begin{aligned} \text{X-area} &= (0.5) (6.7 \text{ feet}) (40 \text{ ft} + 525 \text{ ft}) \\ &= 1893 \text{ ft}^2 \end{aligned}$$

$$\begin{aligned} \text{Volume} = V_1 &= \frac{(1893 \text{ ft}^2) (5,300 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}} \\ &= 230 \text{ acre-ft} \end{aligned}$$

$$V_1 < \frac{S}{2} \therefore \text{reach length OK}$$

b. Determine Q_{p11} (TRIAL)

$$Q_{p11}(\text{TRIAL}) = Q_{p10} \left(1 - \frac{V_1}{S} \right)$$

$$Q_{p11}(\text{TRIAL}) = (2,710 \text{ cfs}) \left(1 - \frac{230}{590} \right)$$

$$Q_{p11}(\text{TRIAL}) = 1,650 \text{ cfs}$$

CLIENT Army Corps JOB No. 274-7901 PAGE 33 of 47
PROJECT Rattlesnake Pond Dam COMPTD. BY BWP DATE 2/7/90
DETAIL Hydrologic Calcs. CK'G. BY BWP DATE 2/7/90

c. Compute V_2 using Q_{P11} (TRIAL)

From Figure 3 determine stage for Q_p (TRIAL)

$$\text{Stage} = 5.4 \text{ feet}$$

$$\begin{aligned} X\text{-area} &= (0.5)(5.4 \text{ feet})(40 \text{ ft} + 433 \text{ ft}) \\ &= 1277 \text{ ft}^2 \end{aligned}$$

$$V_2 = \frac{(1277 \text{ ft}^2)(5,300 \text{ ft})}{43,560}$$

$$V_2 = 155 \text{ acre-ft}$$

d. Average V_1 and V_2 and compute Q_p

$$(1) V_{\text{avg}} = \frac{V_1 + V_2}{2}$$

$$V_{\text{avg}} = \frac{230 \text{ ac-ft} + 155 \text{ ac-ft}}{43,560 \text{ ft}^2/\text{acre}}$$

$$V_{\text{avg}} = 193 \text{ acre-ft}$$

$$(2) Q_{P11} = Q_{P10} \left(1 - \frac{V_{\text{avg}}}{S}\right)$$

$$Q_{P11} = (2,710 \text{ cfs}) \left(1 - \frac{193}{590}\right)$$

$$Q_{P11} = 1,830 \text{ cfs}$$

CLIENT Army Corps JOB No. 244-7901 PAGE 39 of 47
PROJECT Bitterfield Pond Dam COMPTD. BY BWP DATE 2/7/99
DETAIL Hydrologic Calcs. CK'D. BY ... DATE ...

K. Reach II

3. STEP 3: Prepare stage-discharge curve for Reach II

a. Pertinent Data

- (1) Reach length = 5,000 feet
- (2) Channel slope = 0.0011
- (3) Manning n = 0.08
- (4) Channel shape - trapezoidal
- (5) Base width \approx 40 feet

b. See Figure 3 for stage-discharge curve

4. STEP 4: Estimate Reach Outflow

a. Determine stage for $Q_{P11} = 1,830$ cfs from Figure 3 and find volume in reach

(1) Stage (depth of flow) = 5.7 feet

(2) Volume in reach = (reach length) $\left(\begin{matrix} \text{cross-sectional} \\ \text{area of channel} \end{matrix} \right)$

$$\begin{aligned} \text{X-area} &= (0.5)(5.7 \text{ feet})(40 \text{ ft} + 455 \text{ ft}) \\ &= 1411 \text{ ft}^2 \end{aligned}$$

$$\begin{aligned} \text{Volume} = V_1 &= \frac{(1411 \text{ ft}^2)(5000 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}} \\ &= 162 \text{ acre-ft} \end{aligned}$$

$$V_1 < \frac{S}{2} \therefore \text{reach length OK}$$

b. Determine $Q_{P12(\text{TRIAL})}$

$$Q_{P12(\text{TRIAL})} = Q_{P11} \left(1 - \frac{V_1}{S} \right)$$

$$Q_{P12(\text{TRIAL})} = (1,930 \text{ cfs}) \left(1 - \frac{162}{590} \right)$$

$$Q_{P12(\text{TRIAL})} = 1,330 \text{ cfs}$$

CLIENT Army Corps JOB No. 274-7901 PAGE
PROJECT Butterfield Pond Dam COMPTD. BY BWP DATE
DETAIL Hydrologic Calcs. CK'D. BY JAD DATE

c. Compute V_2 using $Q_{PIZ}(\text{TRIAL})$

From Figure 3 determine stage for $Q_{PIZ}(\text{TRIAL})$

$$\text{Stage} = 5.0 \text{ feet}$$

$$\begin{aligned} \text{X-area} &= (0.5)(5.0 \text{ ft})(40 \text{ ft} + 40 \text{ ft}) \\ &= 1113 \text{ ft}^2 \end{aligned}$$

$$V_2 = \frac{(1113 \text{ ft}^2)(5000 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}}$$

$$V_2 = 128 \text{ acre-ft}$$

d. Average V_1 and V_2 and compute Q_p

$$(1) V_{\text{avg}} = \frac{V_1 + V_2}{2}$$

$$V_{\text{avg}} = \frac{162 \text{ acre-ft} + 128 \text{ acre-ft}}{2}$$

$$V_{\text{avg}} = 145 \text{ acre-ft}$$

$$(2) Q_{PIZ} = Q_{PII} \left(1 - \frac{V_{\text{avg}}}{S} \right)$$

$$Q_{PIZ} = (1,830 \text{ cfs}) \left(1 - \frac{145}{590} \right)$$

$$Q_{PIZ} = 1,380 \text{ cfs}$$

CLIENT Army Corps JOB No. 244-7901 PAGE 41 of 47
PROJECT Walter Herbold Pond Dam COMPTD. BY BWP DATE 2/7/90
DETAIL Hydrologic Calcs. CK'D. BY ... DATE ...

L. Reach 12

3. STEP 3: Prepare stage-discharge curve for Reach 12

a. Pertinent Data

- (1) Reach length = 5,000 feet
- (2) Channel slope = 0.0011
- (3) Manning n = 0.09
- (4) Channel shape - trapezoidal
- (5) Base width \approx 40 feet

b. See Figure 3 for stage-discharge curve

4. STEP 4: Estimate Reach Outflow

a. Determine stage for $Q_{p12} = 1,380 \text{ cfs}$ from Figure 3 and find volume in reach

(1) Stage (depth of flow) = 5.0 feet

(2) Volume in reach = (reach length) (cross-sectional area of channel)

$$\begin{aligned} \text{X-area} &= (0.5)(5.0 \text{ ft})(40 \text{ ft} + 405 \text{ ft}) \\ &= 1113 \text{ ft}^2 \end{aligned}$$

$$\begin{aligned} \text{Volume} = V_1 &= \frac{(1113 \text{ ft}^2)(5000 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}} \\ &= 128 \text{ acre-ft} \end{aligned}$$

$$V_1 < \frac{S}{2} \therefore \text{reach length OK}$$

b. Determine $Q_{p(\text{TRIAL})}$

$$Q_{p(\text{TRIAL})} = Q_{p12} \left(1 - \frac{V_1}{S}\right)$$

$$Q_{p(\text{TRIAL})} = (1,380 \text{ cfs}) \left(1 - \frac{128}{590}\right)$$

$$Q_{p(\text{TRIAL})} = 1,080 \text{ cfs}$$

CLIENT Army Corps JOB No. 274-7901 PAGE 42 of 47
PROJECT Butterfield Pond Dam COMPTD. BY BWP DATE 2/7/90
DETAIL Hydrologic Calcs. CK'D. BY WJD DATE 2/8/90

c. Compute V_2 using Q_{P12} (TRIAL)

From Figure 3 determine stage for Q_{P12} (TRIAL)

$$\text{Stage} = 4.6 \text{ feet}$$

$$\begin{aligned} \text{X-area} &= (0.5)(4.6 \text{ feet})(40 \text{ feet} + 375 \text{ ft}) \\ &\approx 955 \text{ ft}^2 \end{aligned}$$

$$V_2 = \frac{(955 \text{ ft}^2)(5000 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}}$$

$$V_2 = 110 \text{ acre-ft}$$

d. Average V_1 and V_2 and compute Q_{P13}

$$(1) V_{\text{avg}} = \frac{V_1 + V_2}{2}$$

$$V_{\text{avg}} = \frac{129 \text{ acre-ft} + 110 \text{ acre-ft}}{2}$$

$$V_{\text{avg}} = 119 \text{ acre-ft}$$

$$(2) Q_{P13} = Q_{P12} \left(1 - \frac{V_{\text{avg}}}{S}\right)$$

$$Q_{P13} = (1,380 \text{ cfs}) \left(1 - \frac{119}{590}\right)$$

$$Q_{P13} = 1,100 \text{ cfs}$$

CLIENT Army Corps JOB No. 244-7901 PAGE 43 of 47
PROJECT Butterfield Pond Dam COMPTD. BY BWP DATE 2/7/80
DETAIL Hydrologic Calcs. CK'D. BY PHS DATE 2/2/80

M Reach 13

3. STEP 3: Prepare stage-discharge curve for Reach 13 (independent)

a. Pertinent Data

- (1) Reach length = 3,050 feet
- (2) Channel slope = 0.0011
- (3) Manning n = 0.08
- (4) Channel shape - trapezoidal
- (5) Base width \approx 2,080 feet

b. See Figure 3 for stage-discharge curve

4. STEP 4: Estimate Reach Outflow

a. Determine stage for $Q_{P13} = 1,100 \text{ cfs}$ from Figure 3
and find volume in reach

(1) Stage (depth of flow) = 0.7 feet

(2) Volume in reach = (reach length) $\left(\begin{matrix} \text{cross-sectional} \\ \text{area of channel} \end{matrix} \right)$

$$\begin{aligned} \text{X-area} &= (0.5)(0.7 \text{ feet})(2,080 \text{ ft} + 2,110 \text{ ft}) \\ &= 1467 \text{ ft}^2 \\ \text{Volume} = V_1 &= \frac{(1467 \text{ ft}^2)(3050 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}} \\ &= 103 \text{ acre-ft} \end{aligned}$$

$$V_1 < \frac{S}{2} \therefore \text{reach length OK}$$

b. Determine $Q_{P(\text{TRIAL})}$

$$Q_{P(\text{TRIAL})} = Q_{P13} \left(1 - \frac{V_1}{S} \right)$$

$$Q_P (\text{TRIAL}) = (1,100 \text{ cfs}) \left(1 - \frac{103}{550} \right)$$

$$Q_P (\text{TRIAL}) = 910 \text{ cfs}$$

CLIENT Army Corps JOB No. 274-7901 PAGE 14 of 47
PROJECT Butterfield Pond Dam COMPTD. BY BWP DATE 2/7/90
DETAIL Hydrologic Calcs CK'D. BY hms DATE 2/8/90

c. Compute V_2 using $Q_{PM}(\text{TRIAL})$

From Figure 3 determine stage for $Q_{PM}(\text{TRIAL})$

$$\text{Stage} = 0.6 \text{ feet}$$

$$\begin{aligned} X\text{-area} &= (0.5)(0.6 \text{ ft})(2,080 + 2,105 \text{ ft}) \\ &= 1256 \text{ ft}^2 \end{aligned}$$

$$V_2 = \frac{(1256 \text{ ft}^2)(3050 \text{ ft})}{43,560 \text{ ft}^2/\text{acre}}$$

$$V_2 = 88 \text{ acre-ft}$$

d. Average V_1 and V_2 and compute Q_{P14}

$$(1) V_{\text{avg}} = \frac{V_1 + V_2}{2}$$

$$V_{\text{avg}} = \frac{103 \text{ ac-ft} + 88 \text{ ac-ft}}{2}$$


$$V_{\text{avg}} = 95 \text{ acre-ft}$$


$$(2) Q_{P14} = Q_{P13} \left(1 - \frac{V_{\text{avg}}}{S}\right)$$

$$Q_{P14} = (1,100 \text{ cfs}) \left(1 - \frac{95}{590}\right)$$


$$Q_{P14} = 920 \text{ cfs}$$

FIGURE 3
DISCHARGE vs. STAGE





DISTANCE FROM BUTTERFIELD POND DAM, feet



DISTANCE FROM BUTTERFIELD POND DAM, FEET

ELEVATION, Feet (NGVD)



INVENTORY OF DAMS IN THE UNITED STATES

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
IDENTITY NUMBER	STATE	COUNTY	CITY	CONTRACT NUMBER	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE DAY	REPORT DATE MO	REPORT DATE YR					
NH 23 NED	NH	DIST. 019	02		BUTTERFIELD POND DAM	4313.6	7207.1	28	MAR	1980					

17	18	19	20	21	22
POPULAR NAME	NAME OF IMPOUNDMENT				
	BUTTERFIELD POND + MAY POND				
23	24	25	26	27	28
RECORD BASIN	RIVER OR STREAM	NEAREST DOWNSTREAM CITY - TOWN - VILLAGE	DIST FROM DAM (MI.)	POPULATION	
01 06	ASHUELOT RIVER	MARLOW	9	516	

29	TYPE OF DAM	YEAR COMPLETED	PURPOSES	30		31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100	101	102	103	104	105	106	107	108	109	110	111	112	113	114	115	116	117	118	119	120	121	122	123	124	125	126	127	128	129	130	131	132	133	134	135	136	137	138	139	140	141	142	143	144	145	146	147	148	149	150	151	152	153	154	155	156	157	158	159	160	161	162	163	164	165	166	167	168	169	170	171	172	173	174	175	176	177	178	179	180	181	182	183	184	185	186	187	188	189	190	191	192	193	194	195	196	197	198	199	200	201	202	203	204	205	206	207	208	209	210	211	212	213	214	215	216	217	218	219	220	221	222	223	224	225	226	227	228	229	230	231	232	233	234	235	236	237	238	239	240	241	242	243	244	245	246	247	248	249	250	251	252	253	254	255	256	257	258	259	260	261	262	263	264	265	266	267	268	269	270	271	272	273	274	275	276	277	278	279	280	281	282	283	284	285	286	287	288	289	290	291	292	293	294	295	296	297	298	299	300	301	302	303	304	305	306	307	308	309	310	311	312	313	314	315	316	317	318	319	320	321	322	323	324	325	326	327	328	329	330	331	332	333	334	335	336	337	338	339	340	341	342	343	344	345	346	347	348	349	350	351	352	353	354	355	356	357	358	359	360	361	362	363	364	365	366	367	368	369	370	371	372	373	374	375	376	377	378	379	380	381	382	383	384	385	386	387	388	389	390	391	392	393	394	395	396	397	398	399	400	401	402	403	404	405	406	407	408	409	410	411	412	413	414	415	416	417	418	419	420	421	422	423	424	425	426	427	428	429	430	431	432	433	434	435	436	437	438	439	440	441	442	443	444	445	446	447	448	449	450	451	452	453	454	455	456	457	458	459	460	461	462	463	464	465	466	467	468	469	470	471	472	473	474	475	476	477	478	479	480	481	482	483	484	485	486	487	488	489	490	491	492	493	494	495	496	497	498	499	500	501	502	503	504	505	506	507	508	509	510	511	512	513	514	515	516	517	518	519	520	521	522	523	524	525	526	527	528	529	530	531	532	533	534	535	536	537	538	539	540	541	542	543	544	545	546	547	548	549	550	551	552	553	554	555	556	557	558	559	560	561	562	563	564	565	566	567	568	569	570	571	572	573	574	575	576	577	578	579	580	581	582	583	584	585	586	587	588	589	590	591	592	593	594	595	596	597	598	599	600	601	602	603	604	605	606	607	608	609	610	611	612	613	614	615	616	617	618	619	620	621	622	623	624	625	626	627	628	629	630	631	632	633	634	635	636	637	638	639	640	641	642	643	644	645	646	647	648	649	650	651	652	653	654	655	656	657	658	659	660	661	662	663	664	665	666	667	668	669	670	671	672	673	674	675	676	677	678	679	680	681	682	683	684	685	686	687	688	689	690	691	692	693	694	695	696	697	698	699	700	701	702	703	704	705	706	707	708	709	710	711	712	713	714	715	716	717	718	719	720	721	722	723	724	725	726	727	728	729	730	731	732	733	734	735	736	737	738	739	740	741	742	743	744	745	746	747	748	749	750	751	752	753	754	755	756	757	758	759	760	761	762	763	764	765	766	767	768	769	770	771	772	773	774	775	776	777	778	779	780	781	782	783	784	785	786	787	788	789	790	791	792	793	794	795	796	797	798	799	800	801	802	803	804	805	806	807	808	809	810	811	812	813	814	815	816	817	818	819	820	821	822	823	824	825	826	827	828	829	830	831	832	833	834	835	836	837	838	839	840	841	842	843	844	845	846	847	848	849	850	851	852	853	854	855	856	857	858	859	860	861	862	863	864	865	866	867	868	869	870	871	872	873	874	875	876	877	878	879	880	881	882	883	884	885	886	887	888	889	890	891	892	893	894	895	896	897	898	899	900	901	902	903	904	905	906	907	908	909	910	911	912	913	914	915	916	917	918	919	920	921	922	923	924	925	926	927	928	929	930	931	932	933	934	935	936	937	938	939	940	941	942	943	944	945	946	947	948	949	950	951	952	953	954	955	956	957	958	959	960	961	962	963	964	965	966	967	968	969	970	971	972	973	974	975	976	977	978	979	980	981	982	983	984	985	986	987	988	989	990	991
----	-------------	----------------	----------	----	--	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----

END

FILMED

8-85

DTIC

