


Research Laboratory

USACERL TECHNICAL REPORT M-90/04 December 1989 Roofing Maintenance Management System



AD-A218 529

ROOFER: An Engineered Management System (EMS) for Bituminous Built-Up Roofs


by David M. Bailey Donald E. Brotherson Wayne Tobiasson Al Knehans

This report gives instructions for using ROOFER, an engineered management system for bituminous built-up roofs that is designed to help military installations make the best use of roof maintenance and repair (M&R) funds.

This system includes procedures for dividing roofs into manageable sections; collecting and maintaining inventory information; surveying, rating, and evaluating roof condition; and determining general M&R needs and priorities.

The overall roof condition rating procedure is based on the Roof Condition Index, which is composed of separate condition indexes for the membrane, flashing, and insulation.

Approved for public release; distribution is unlimited.



The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official indorsement or approval of the use of such commercial products. The findings of this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

DESTROY THIS REPORT WHEN IT IS NO LONGER NEEDED

DO NOT RETURN IT TO THE ORIGINATOR

REPORT DOCUMENTATION PAGE				Form Approved OMB No 0704 0188 Exp Date Jun 30 1986		
TA HEPORT SECURITY CLASSIFICATION Unclassified	16 RESTRICTIVE MARKINGS					
Tal SECURITY CLASSIFICATION AUTHORITY		3 DISTRIBUTION	N/AVAILABILITY	OF REPORT		
26 DECLASSIFICATION DOWNGRADING SCHED	ULE		for publication is unl		•	
4 PERFORMING ORGANIZATION REPORT NUMB	ER(S)	5 MONITORING	ORGANIZAT ON	REPORT NI	IMRER(S)	
USACERL Technical Report M-90		ondime y		3.0.00		
5a NAME OF PERFORMING ORGANIZATION U.S. Army Construction Engr Research Laboratory	6b OFFICE SYMBOL (If applicable) CECER—EM	7a NAME OF N	ONITORING ORG	JANIZATION		
6c ADDRESS (City, State, and ZIP Code) P.O. Box 4005 Champaign, IL 61824-4005	· • · · · · · · · · · · · · · · · · · ·	7b ADDRESS (City, State, and ZIP Code)				
8a NAME OF FUNDING SPONSORING ORGANIZATION	8b OFFICE SYMBOL (If applicable)	9 PROCUREMEN	IT INSTRUMENT I	DENTIFICAT	ION NUMBER	
8c ADORESS (City, State and ZIP Code)	OCE	10. SOURCE OF	FUNDING NUMB	FPS		
20 Massachusetts Ave, NW.		PROGRAM	PROJECT	TASK	WORK ENIT	
Washington, DC 20314		4A162731	NO AT41	NO	ACCESSIC 1 NO	
11 1112 (Include Security Classification)		4A162/31	A141	C	044	
	OVERED	oiasson, Way 14 DATE OF REPO 1989, Dece	ORT (Year, Monti	is Al h. Day) 15	PAGE COUNT 80	
Copies are available from the Road, Springfield, VA 22161	•					
17 COSATI CODES FIFLO GROUP SUB GROUP 12 13		Continue on rever aintenance m tuminous bu	anagement		by block number)	
This report gives instructions for using that is designed to help military instantion, surveying, rating, and ever the overall roof condition rating procedures for the membrane,	g ROOFER, an engine allations make the bestividing roofs into man caluating roof conditions reduce is based on the	eered management use of roof mageable sections and determin	aintenance and s; collecting an ing general Ma	l repair (M nd maintair &R needs	1&R) funds. ning inventory and priorities.	
TO MODEST ASSESSMENT OF ABSTRACT	PPT □ DTHC USERS	2: ABSTRACT SE Unclassi		CATION		
22 + NAME OF RESPONSIBLE NOISON AL	2 2 2 3 3 5 4 5	1276 TELEPHONE (FICE SYMBOL	
Gloria J. Wienke		(217) 352-6		CECER		

FOREWORD

This project was funded by the Assistant Chief of Engineers, Office of Chief of Engineers (OCE), under project 4A162731AT41, "Military Facilities Engineering Technology"; Task C, "Operations/ Management/Repair"; Work Unit 044, "Roofing Maintenance Management System." The U.S. Army Technical Monitors were Mr. Chester Kirk, Mr. Robert Lubbert, and Mr. Helmut Gramberg. Funds were also provided by the Northern Division Naval Facilities Engineering Command (NAVFACENGCOM), U.S. Naval Base, Philadelphia, PA, under Funding Authorization Documents N62472-85P05008, N62472-85WR00151 and N62472-85WR00132. The U.S. Navy Technical Monitor was Mr. Tom Wallace.

The work was performed by the Engineering and Materials Division (EM), U.S. Army Construction Engineering Research Laboratory (USACERL) with the assistance of the U.S. Army Cold Regions Research and Engineering Laboratory (CRREL) and the U.S. Army Engineering and Housing Support Center (USAEHSC). Dr. R. Quattrone is Chief of USACERL-EM.

Mr. Donald Brotherson is the Director of the Building Research Council, University of Illinois.

Special acknowledgment is due to Dr. Mohamed Y. Shahin who was the Principal Investigator for the development of the visual distress survey and condition evaluation procedure. The assistance of Mr. Robert Tucker, USAEHSC, is acknowledged and appreciated. Special acknowledgement is also due to Mr. Wayne Tobiasson, CRREL, and Mr. Al Knehans, USAEHSC. The Technical Editor was Gloria J. Wienke, USACERL Information Management Office.

COL Carl O. Magnell is Commander and Director of USACERL, and Dr. L. R. Shaffer is Technical Director.



Acces	sion For	
NTIS	GRA&I	9
DTIC	TAB	
Unann	ounced	
Just1	fication_	
By		
Distr	ibution/	
Laval	lability	Coces
	one Lieva	/or
Dist	Special	
1	1	
DV	(!	
r	1 1	
•		

CONTENTS

		Page
	DD FORM 1473 FOREWORD LIST OF FIGURES	1 3 5
1	INTRODUCTION Background Objective Organization of Report Scope Mode of Technology Transfer	7
2	INVENTORY AND DATA MANAGEMENT PROCEDURE	9
3	VISUAL INSPECTION AND EVALUATION PROCEDURE	22
4	INSULATION INSPECTION AND EVALUATION PROCEDURE Insulation Condition Rating Effects of Wet Insulation Roof Moisture Detection Core Sampling and Determining Moisture Content Insulation Severity Factors Calculating the Insulation Condition Index	32
5	ROOF CONDITION EVALUATION AND MAINTENANCE, REPAIR, AND REPLACEMENT (MRR) PROCEDURES	42
6	SUMMARY AND RECOMMENDATION	54
	REFERENCES	56
	APPENDIX A: Blank Worksheets APPENDIX B: Test To Determine Bitumen Type APPENDIX C: Deduct Value Curves	57 67 68
	DICTPIRITION	

FIGURES

Numbe	er	Page
1	Example of a Manual Recordkeeping System	11
2	Completed Building Identification Sheet	12
3	Completed Roof Section Identification Sheet	13
4	Roof Inspection Worksheet With Roof Section Plan	14
5	Symbols To Be Used on Roof Section Plans	15
6	Completed Roof Section Identification Worksheet	17
7	MCI and FCI and Ratings	23
8	Completed Roof Inspection Worksheet	24
9	Example Description of Blister Distress	25
10	List of Distress/Defect Identifiers	26
11	Reverse Side of the Roof Inspection Worksheet	27
12	Completed Roof Section Rating Form	28
13	Steps for Calculating MCI and FCI for a Roof Section	29
14	Typical Infrared Photo	34
15	Conventional Photo of Roof in Figure 14	34
16	Aerial Thermogram of a Roof	35
17	Airphoto Marked To Show Potential Areas of Wet Insulation	35
18	Potentially Wet Areas and Core Sample Locations Mapped Onto Roof Inspection Worksheet	36
19	Insulation Severity Factor (ISF) vs Moisture Content for Cellular Glass, Cork, Glass Fiber, Polyurethane, Polystyrene, and Polyisocyanurate Insulation	38
20	ISF vs Moisture Content for Phenolic, Insulating Concrete, Gypsum, Perlite, and Fiberboard Insulation	38
21	Completed ICI Calculation Sheet	39
22	Insulation Deduct Value (IDV) vs Problem Density	41
23	Completed RCI Calculation Sheet	44

FIGURES (Cont'd)

Numbe	er	Page
24	Deterioration Curves for Built-Up Roofs	46
25	RCI Improved vs. Remaining Service Life	46
26	Relationship Between Age, EL, RSL, RSL', and ASL	49
27	Economic Evaluation of a BUR System	50
28	Corrective Actions Requirement Sheet for Major Repair	52
29	Corrective Actions Requirement Sheet for Replacement	53
	TABLE	
1	MRR Recommendations	43

ROOFER: AN ENGINEERED MANAGEMENT SYSTEM (EMS) FOR BITUMINOUS BUILT-UP ROOFS

1 INTRODUCTION

Background

Each of the U.S. armed services branches has a very large inventory of roofs with bituminous built-up membranes. Roof repairs and reconstruction are steadily increasing as the roofs approach the end of their service lives, making it increasingly important to better manage maintenance funds. Currently, there is need for a systematic procedure to determine priorities and select repair strategies that will ensure a maximum return on investment.

In response to this problem, the U.S. Army Construction Engineering Research Laboratory (USACERL), with the assistance of the U.S. Army Cold Regions Research and Engineering Laboratory (USACRREL) and the U.S. Army Engineering and Housing Support Center (USAEHSC), has developed ROOFER, a roofing maintenance management system. ROOFER provides military installations with a practical decision-making procedure to identify problems and select maintenance and repair strategies for roofs with bituminous membranes.

Objective

This report describes ROOFER, a maintenance management system for bituminous built-up roofs designed to make the best use of maintenance and repair (M&R) funds.

Organization of Report

Chapter 2 discusses the process of dividing the roof network into manageable sections and the procedure for collecting and managing roof inventory information. Chapter 3 summarizes the visual inspection procedure. A complete description of the visual inspection procedure can be found in Membrane and Flashing Condition Indexes for Built-Up Roofs, Volume II: Inspection and Distress Manual.\(^1\) This field-validated procedure is used to determine the severity of existing membrane and flashing distresses and to compute the membrane condition index (MCI) and flashing condition index (FCI). These indexes measure the component's functional condition, M&R requirements, and waterproof integrity. Chapter 4 contains roof moisture detection procedures and a means for computing the insulation condition index (ICI). Chapter 5 discusses the strategies for maintenance and repair based on the Roof Condition Index (RCI), which is computed from the three individual indexes (i.e., MCI, FCI, and ICI).

¹M. Y. Shahin, D. M. Bailey, and D. E. Brotherson, Membrane and Flashing Condition Indexes for Built-Up Roofs, Volume II: Inspection and Distress Manual, Technical Report M-87/13 (U.S. Army Construction Engineering Research Laboratory [USACERL], September 1987).

Scope

Although ROOFER is designed for maintenance management of bituminous built-up roofs, it is adaptable to all types of low-slope roofing systems. This flexibility will allow these other roofing systems to be incorporated into ROOFER in the future.

Mode of Technology Transfer

ROOFER will complement Technical Manual (TM) 5-617, Facilities Engineering Inspection, Maintenance, and Repair of Roofing Systems.² The technology transfer will be through the Facilities Engineering Application Program (FEAP), field demonstrations, and formal training.

²Technical Manual (TM) 5-617, Facilities Engineering Inspection, Maintenance, and Repair of Roofing Systems (Draft).

2 INVENTORY AND DATA MANAGEMENT PROCEDURE

The roof inventory is the foundation of ROOFER. It provides the information needed by engineering personnel to select repair techniques and determine the suitability of replacement systems. A well-maintained inventory will also provide a structural history of each roof and a record of roof performance that can be used to determine which roof system is most suitable for use on a particular building type or occupancy. The inventory data and condition evaluation data (discussed in Chapters 3, 4, and 5) are used to determine maintenance and repair strategies.

Roof Network Identification

A roof network, as defined for the ROOFER system, consists of all the low-slope roofs maintained by an installation. This network is generally divided into the following manageable components:

Building

A building consists of one distinct structure that may include several wings or sections, but generally has one building number or designation. Buildings connected by covered walks or enclosed passageways should be considered separately unless they are designated by the same building number. Building complexes with only one building number or designation should be given subdesignations for easier identification.

Roof Section

A roof section is a roof, or part of a roof, that is identifiable as a separate entity. The section is distinct in that it may represent one level of a building's roof having many levels. A section may also be part of a very large roof that is physically divided by firewalls, expansion joints, area dividers, or some other identifiable boundary. For smaller buildings, the roof section may be the entire roof.

Dividing the roof of a building into sections provides a better means of evaluating the condition and determining Maintenance, Repair, and Replacement (MRR) needs. For example, a roof section that is in poor condition would not detract from the condition assessment of a roof section in good condition on the same building, and a condition evaluation indicating replacement of a section would not signal replacement of the entire roof.

Guidelines for Section Identification

A section is generally delineated by:

- firewalls, expansion joints, or area dividers
- different roof levels
- areas that were built at different times
- areas having different roofing systems, different amounts of roof traffic and/or rooftop equipment, or radically different occupancies below the roof.

A building's roof sections are assigned letter designations (A, B, C, D...).

If a roof is physically divided into many small areas, it may be possible to combine several such areas into one section (e.g., all the canopies over entrances may be grouped into one section provided they are of similar age and construction). However, if areas have different structural systems, roof systems, or environments below the roof (i.e., canopies, freezers, or unheated warehouses), they should be treated as individual sections. Large areas without obvious delineations can be arbitrarily divided into areas of 25,000 to 40,000 sq ft.*

Recordkeeping System

The information needed to successfully manage a roof network must be stored in a way that makes the data accessible and usable. The manual system described in this report affords easy conversion to a computerized system. Once stored, the information about each building and roof section can be used to develop reports that are needed to effectively manage large networks of building roofs or individual roof projects. Figure 1 shows an example of a filing sequence for a typical recordkeeping system. The file should contain a Building Folder for each building and a Roof Section Folder for each roof section on the building.

Building Folder

The Building Folder should contain a completed Building Identification Sheet (Figure 2) which includes a building roof plan. The building roof plan should show overall dimensions and identify each roof section. It should be drawn to a scale that will fit in the space provided on the sheet. For large buildings, a scale of 1 in. = 30 ft or 1 in. = 60 ft will probably be required to show the entire roof. Contract drawings, specifications, and as-built drawings for any work done on the building should also be kept in the building folder, or if they are kept elsewhere, their location should be stated in the folder.

Roof Section Folder

A Roof Section Folder should be established for each roof section containing a completed Roof Section Identification Sheet (Figure 3), and a Roof Inspection Worksheet (Figure 4). A roof section plan should be drawn to scale on the Roof Inspection Worksheet. The plan should show all physical features including perimeter conditions (roof edge, expansion joint, parapet wall, etc.), rooftop equipment, projections through the roof, roof drains, walkways, sign supports, and piping. The standard symbols shown in Figure 5 should be used to identify these items whenever possible.

A master Roof Inspection Worksheet with an unmarked roof section plan should be kept in each folder. Copies of the Roof Inspection Worksheets (discussed in Chapter 3) are used to conduct condition evaluation inspections. They are filled out and stored in the Roof Section Folder. Roof distresses or defects identified during the inspections are noted on the plan for future reference and to help determine maintenance and repair needs.

A blank Roof Inspection Worksheet is included in Appendix A of this report.

Inventory Data Collection

The information on the Building and Roof Section Identification Sheets can come from a variety of sources. At installations with complete building records, most of the information can be taken from

^{*}Metric conversion factors are on page 55.




Figure 1. Example of a manual recordkeeping system.

as-built drawings, record drawings, and specifications. Because these drawings and specifications often do not show actual conditions, all data should be verified during the visual inspection. Core samples taken for the purpose of verifying wet insulation (Chapter 4) should be used to determine the components of the roof sections.

It is important that the collected information be as complete as possible. Missing data will make analysis and planning difficult. Although this phase does require some investment of time and effort, it needs to be done only once and then updated when changes to the roof system occur.

Building Identification Sheet

The Building Identification Sheet (Figure 2) is kept in the Building Folder and gives general information including building name, number, location, and occupancy. The Building Identification Sheet also lists each roof section and its area, and the date of original construction of the building. Although some of the information is not directly related to the roofing system, it does provide essential data for managing the network.




Figure 2. Completed Building Identification Sheet.

ROOF SECTION IDENTIFICATION		AGENCY/INST.:	FT. JONES	
DATE: MAY / 1987 BLDG NO:	68 SECTIO	ON ID: 6	AREA: 16,200	SF
OCCUPANCY:	YEAR ORIG CONST		YEAR LAST REPLACED:	1975
10 GENERAL				
11 PERIMETER:			12 ACCESS:	
PARAPET 243 LF ROOF EDGE TGT LF EXP. JOINT 124 LF	AREA DIVIDER ADJ. WALL OTHER	LF LF	ADJACENT ROCF SECTION F	
20 STRUCTURAL FRAME				
21 TYPE: CONCRETE	- BELINIS			
30 ROOF DECK				
31 TYPE: CONCRETE,	STD (1,45	T-IN-PLACE	<u> </u>	
32 DESIGN LOAD:	33 SLOPE:		34 DRAINAGE:	
LIVE 25 PSF DEAD 50 PSF		<u>√3</u> IN 12	INTERIOR DR.	241
40 VAPOR RETARDER	<u></u>			
41 TYPE: LAMINATED	FELTS			
50 INSULATION				
SITYPE: PERLITE AND	POLY URET A	HANE BOA	KDS	
52 PHYSICAL PROPERTIES:	STOCK FILLS		53 R-VALUE: 15	
THICKNESS (in.) NO. OF LAYERS TAPERED	3 2 N		54 ATTACHMENT: ADHESIVE - HET	-
60 MEMBRANE				
61 PRODUCT:		PROTECTED ME	EMBRANE(Y/N)	
MANUFACTURER (SPECIFCATION NO.	ELOTEX	DESCRIPTION WARRANTY EXP. DATE	BASE SHEET + 3	(Y/N)
62 TYPE:	63 ATTACHMENT:		64 REINFORCEMENT:	
BUILT- UP ASPHALT			GLASS FELTS	
65 SURFACING:	66 WALKWAYS:		<u> </u>	
CRUSHED STENE	Weed	DUCK BO	ARDS	
70 FLASHING				
71 BASE FLASHING:	72 FLASHING ADHI	ESIVE:	73 COUNTERFLASHING:	
MINERAL SURFACED		12-412	NACTAL	
CKGANIC	CLLD M	(*7) I C	METAL	
74 FLASHING TYPES: FARAI'ET, EXI'. ST., PL FITCH PAN	UMBING VE	NT, PIE	UPPORTS - WILLD E	scucksy
80 REMARKS:				

Figure 3. Completed Roof Section Identification Sheet.

ROOF INSPEC	TION WORKSHEET	AGENCY/IN	ST.: <i>FJ.</i>	JONES		_				
BUILDING	68 PER.	FLASHING	527	LF	DAT	E				
SECTION _	6 curi	B FLASHING	36	_LF	NAM	IE .				
BF-BASE FLASH MC-METAL CAP EM-EMBEDD MET FP-FLASHED PEN	PP-PITCH PANS DR-DRAIN & SC BL-BLISTERS RG-RIDGES	SP-SPLITS HL-HOLES SR-SURF D SL-SLIPPAC		PA-PATCHING DV-DEBRIS & VEG EQ-EQ SUPPORT PD-PONDING		 D #	D I S	SEV	D E F	Q T Y
FP-FLASHED PEN	AG-AIDGES AG-AIDGES SEC	SL-SLIPPAC	Ø V	B I o'	754,					
SCALE:	= 30'						N	OR1	тн	

Figure 4. Roof Inspection Worksheet with Roof Section Plan.




Figure 5. Symbols to be used on roof section plans.

Roof Section Identification Sheet

The Roof Section Identification Sheet (Figure 3) is completed for each roof section listed on the Building Identification Sheet and is kept in the corresponding Roof Section Folder. The sheet has eight major divisions and organizes the section data.

Roof Section Identification Worksheet

The three-page Roof Section Identification Worksheet (Figure 6) simplifies the task of collecting the necessary data and ensures uniformity in reporting terminology. Most of the items are self-explanatory and the collection process only requires checking-off items pertaining to the roof section. Much of the data can be obtained from specifications, drawings, core cuts, and visual inspection. Some guidance is provided below. The information from these worksheets is transferred to the Roof Section Identification Sheet.

Descriptions of the collected inventory data follow:

General

Section 11 - Perimeter. The length (in feet) of the perimeter of the roof section categorized into the listed construction "edges."

Section 12 - Access. The method used to gain access to the roof. Note whether the ladder is inside or outside the building and if it is permanently attached to the building. If it is not, a portable ladder will be necessary for inspection. If access is from an adjacent roof section, identify the section.

Structural Frame

Section 21 - Type. The structural framing system which supports the roof section.

Roof Deck

Section 31 - Deck Type. The roof deck construction supporting the roofing system.

Section 32 - Design Load. The live and dead loads for the roof section. This information can usually be found on the building's structural drawings. Check in the general notes or in a special note on the Roof Framing Plan.

Section 33 - Slope. The predominate slope of the roof section. The roof plan will generally indicate the slope (e.g., 1/4 in. in 12 in.). If the slope is not noted on the roof plan, the section drawings may indicate the slope. Measure the major slope if it cannot be found on the roof plan or section drawings.

Section 34 - Drainage. The existing means of removing rainwater from the roof section. Check the roof section for interior drains, gutters, and downspouts. Determine whether leaders and downspouts are connected to the scuppers. Check for overflow scuppers which control the height of ponded water and prevent overloading of the structure. ROOF EDGE indicates that the roof water flows over the building edge to the ground or to a lower roof area without gutters or scuppers.

ROOF S	SECTION IDE	NTIFIC	ATION 1	WORKSHI	EET	AGENCY	/INST.:	Jon	IES		
DATE:	MAY/ 1487	7 BLI	DG NO:	68	SECTIO	N ID:	5	AREA:	14,80	0	SF
OCCUP	ANCY: C	FFICE			UG CONST	:		YEAR L	AST REPLA		1978
10 GEN											
11 PERI	IMETER:										
P.	PARAPET	243		EXP	P. JOINT	124	<u>4</u> LF		ADJ. WALL	_	LF
<u></u>	OOF EDGE	161	LF	ARE	A DIVIDER		LF		OTHER		LF
H	ESS (check one	e);	_								
Perr Terr	RNAL LADDER manent mporary		·	Pem	RNAL LADDER manent nporary	R ·			SSED FROM AI DF SECT (Sec.		·
	UCTURAL FR	AME									
21 TYP	E (check one):										
Lon True Ber	EL ams, Girders, Cols. ng Sp Deck, Beams isses Joists With Beams and C Joists With Bearing Walls Joists With Combination	s Cols. s			CONCRET X Beams Flat Slab WOOD Laminate Trusses Joists Panels	o ed Beams			SPECIAL Dome Space	Frame	
30 ROO	F DECK										
31 TYP	E (check one):		18.3. (1.1.).								
		NONC	OMBUSTIE	BLE				cc	OMBUSTIBLE		
STEE	EL .	•		CONC	CRETE, L.W.			_ wc	OOD BOARDS		
	CRETE, STD.			Cast	t-In-Place niculite			PL\	YWOOD		
	st-in-Place			Cellu Cellu Perli	ular			_ wo	OD FIBER		
Fibe	SUM erboard Form erglass Form osum Form cast			CEME	ENT FIBER						
32 DESI	IGN LOAD:		LIVE	25	PSF						
			DEAD	50	PSF	_ un	IKNOWN				
33 SLOI	PE:	18	IN 12								
34 DRA	INAGE (check	ali):	·		_ ADJACEN	T ROOF SECT	ION				
XINTE	ERIOR DRAINS				SCUPPER	S W/LEADERS	S AND DO	OWNSPOU	TS		
GUT	TTERS & DOWNSE	POUTS			_OVERFLO	W SCUPPERS	3				
scu	JPPERS				_ ROOF EDG	3E					
40 VAP	OR RETARDE	R									
41 TYPE	E (check one):								<u> </u>		
_ NON	IE				COATED RO	LL ROOFING			P\	√ C	
_ALUI	MINUM FOIL				LAMINATED	ASPH/KRAFT			vi	NYL	
POL	YETHYLENE			X	LAMINATED	FELTS			_ Ut	NKNOWN	

Figure 6. Completed Roof Section Identification Worksheet.

50 INSULATION			
51 TYPE (check all):	EXTRUDED POLYST	Υ.	INSULATING FILLS
NONE	FOAMGLASS	-	Vermiculite Perlite Colluler
WOOD FIBERBOARD	PHENOLIC		Cellular Gypsum
GLASS FIBER	POLYISOCYANURAT	re .	Lwt. Concrete Fill Type Unknown
<u>X</u> PERLITE	CORK		UNKNOWN
X POLYURETHANE/BOARD	FOAMED IN PLACE/F	PUF	ļ
EXPANDED POLYSTY.			
52 PHYSICAL PROPERTIES:	N/A (No Ir	nsul.)	
BOARD STOCK		FOAMED IN PLACE	AND INS. FILLS
TOTAL THICKNESS) INCHES	TOTAL THICKNES	ss inches
NO. OF LAYERS	2	TAPERED	(Y/N)
TAPERED	√ (Y/N)		
53 R-VALUE (total):		UNKNOWN	N/A (No Insul.)
54 ATTACHMENT (board stock of	only)(check all):		
MECHANICAL	\underline{X} ADHESIVE-HOT		UNKNOWN
_LOOSE LAID	ADHESIVE-COLD		· ·
60 MEMBRANE			
61 PRODUCT:	UNKNOWN	PROTECTED MEME	BRANE N_ (Y/N)
MANUFACTURER	CELOTEX	DESCRIPTION	BAJE SHEET + 3 PLY
SPECIFICATION NO.		WARRANTY M_(Y	//N) EXP DATE
62 TYPE (check one):	ROLL ROOFING		LIQUID APPLIED
BIT. BUILT-UP	Org/Min. Surface Glass/Min. Surface		Neoprene/Hypaton Acrylic Elastomer
X Asphalt Coal Tar Pitch	Smooth		Butyl Polysulfide
Cold Process\	SINGLE-PLY		Urethane
Emulsion	— EPDM		Silicone
Cold Process\ Cutback	- CPE CSPE		Type Unknown
Bit. Type Unknown	PIB		PUF WITH COATING
	_ PVC		Silicone
MODIFIED BITUMEN SBS	Butyl Neoprene		Urethane Catal. Urethane
APP	Nitrile		Acrylic
Modifier Unknown	Type Unknown		Coating Unknown
63 ATTACHMENT (for Single-Pty	y only)(check one):		
FULLY ADHERED	PLATE/DISK/PARTIA	ILLY ADHERED	
LOOSE/BALLASTED	MECH. FASTENERS Penetrating NonPenetrating		
64 REINFORCEMENT (check on	e):	MODIFIED BITUMEN &	SINGLE-PLY
BIT. BUILT-UP		Polyester, Woven Polyester, Nonwoven	
	-	Glass	
Organic Felt	-		
∑ Giass Feit		Asbestos	
∑ Glass Felt — Asbestos Felt	- -	Fleece, Synthetic	
∑ Glass Feit	: -		
∑ Glass Felt — Asbestos Felt	; - -	Fleece, Synthetic Felt Laminate Backer Polyethylene	
☐ X Glass Felt ☐ Asbestos Felt		Fleece, Synthetic Felt Laminate Backer	ฑ

Figure 6. (Cont'd)

65 SURFACING (check one):		
AGGREGATE	SMOOTH	MINERAL SURF. CAP
River Gravel Crushed Stone	Cutback Emulsion	LATEX COATING
Siag	Hot Asphalt	
Pea Gravel Volcanic Rock	Bit. Type Unknown	PAVERS Concrete
Marble Chip Limestone	REFLECTIVE	Composite
Aluminum Granule	ELASTOMERIC	OTHER
Mineral Granule Agg. Unknown	METAL SKIN	NONE
66 WALKWAYS (check all):		RUBBER MAT
ASPHALT PLANK	$\underline{\times}$ WOOD DUCK BOARDS	OTHER
CONCRETE PAVERS	MINERAL SURFACED FELTS	NONE
70 FLASHING		
71 BASE FLASHING (check all):		
MINERAL SURFACED	MODIFIED BITUMEN	PVC COVERED METAL
	Granule Surface Foil Surface	METAL
Fabric Unknown	Smooth Surface	CPE
REINFORCED ASBESTOS	VINYL	CSPE
FIBERGLASS	PVC	NONE
_cotton	NEOPRENE	
BURLAP	EPDM	
72 FLASHING ADHESIVE (check one):		
HOT MOPPED	TORCH APPLIED	
∠COLD MASTIC	UNKNOWN	
73 COUNTERFLASHING (check all):		
<u> X</u> METAL	FLEXIBLE	
BITUMINOUS	_ NONE	
74 FLASHING TYPES (check all):		
ROOF EDGE	ROOF PENETRATION	XPITCH PAN
Embedded Edge Met. Metal Cap Flash.	ROOF RELIEF VENT	PIPE SUPPORTS
	X PLUMBING VENT	X Wood Blocks Rollers
COPING	EQUIPMENT SUPPORT	_ /845
AREA DIVIDER	Structural Frame Curbs	
EXPANSION JOINT	Conduit Wood Sleepers	
Metal Cover	None (unflashed)	
Z Flexible Cover		
80 REMARKS		
Í		
1		
1		
lj		
L		

Figure 6. (Cont'd)

Vapor Retarder

Section 41 - Type. The material type used in reducing vapor transmission through the roofing system (sometimes referred to as vapor barrier). This information can usually be found in the specifications or on construction drawings. If needed, determine the presence and type of vapor retarder from core cuts.

Insulation

- Section 51 Type. Type(s) of insulation used in the roofing system.
- Section 52 Physical Properties. The total thickness and number of layers of insulation. Also indicate if the insulation system is tapered. Core samples are the best means of determining insulation type and thickness. Check specifications or contracts for information concerning whether insulation was tapered to provide slope, and if multiple layers were used.
- Section 53 R-value. The total R-value (thermal resistance) of the insulation. Check specifications, manufacturer's information, or use industry accepted values.
- Section 54 Attachment. The method used for attachment of the roof insulation. This information should be in the specifications. The insulation on roofs installed before 1982 was frequently attached with mechanical fasteners on the perimeter of steel decks and adhesive on the field of the roof. Enter all methods if more than one method was used. Single-ply ballasted systems are generally installed with the insulation loose-laid.

Membrane

- Section 61 Product. The manufacturer, product description and specification of the roof membrane. Construction drawings or contractor submittals are the only reliable source for this information. Also indicate if the roof assembly is a protected membrane (insulation on top of membrane).
- Section 62 Type. The type of material used as the membrane. The contract specifications or shop drawing file will be the best sources for this data. For built-up roofs, a simple method for determining bitumen type is described in Appendix B.
- Section 63 Attachment. The method of membrane attachment (for single-ply membranes only). The contract specifications or shop drawings are the best sources for this information.
- Section 64 Reinforcement. Type of fabric or reinforcement used in the membrane. Contract specifications and manufacturer's literature are the best sources for this information.
- Section 65 Surfacing. Type of surfacing on the membrane providing protection or ballast. Visual observations or the contract specifications are the best sources for this information. If more than one surfacing appears on the roof section, consider dividing it into multiple sections.
- Section 66 Walkways. Type(s) of walkways used on the roof section. Check the roof section plan to be sure they are shown.

Flashing

Section 71 - Base Flashing. Types of base flashing that are present. The contract specifications or contractor's submittals and visual observation are the best sources for this information.

- Section 72 Flashing Adhesive. The adhesive used to apply the base flashing. The contract specifications should provide this information.
- Section 73 Counterflashing. Types of counterflashing present on the roof section. The contract specification, contractor shop drawings, and visual observation are the best sources for this information.
- Section 74 Flashing Types. Types of flashing details existing on the roof section. There will normally be several flashing types on every roof. Check off all types that are present. Check the roof section plan to be sure that all of the existing flashing, especially penetrations, pitch pans, and pipe supports are shown.

Remarks

Additional information that will be useful to the planners in scheduling maintenance or replacement. If the roof system was placed over an existing roof, it should be stated in this section.

3 VISUAL INSPECTION AND EVALUATION PROCEDURE

The visual roof condition evaluation procedure is the critical component of ROOFER. The data obtained during the procedure is combined with the insulation inspection data (Chapter 4) to provide an overall assessment of the roof condition and determine MRR requirements. This chapter briefly explains the visual inspection procedure and the methods used to calculate the membrane and flashing condition indexes (MCI and FCI). A complete description of the visual inspection procedure can be found in USACERL Technical Report M-87/13³ which provides the necessary guidance to perform the inspections and is the standardized reference for distress/defect identification.

Membrane and Flashing Condition Ratings

The membrane and flashing components are rated separately by direct measurement of the distresses found in each component. Treating each component separately provides a more accurate assessment of component condition, needed repair, and waterproof integrity. MCI and FCI ratings are numerical indicators based on a scale of 1 to 100. The scale and associated ratings are shown in Figure 7.

Inspection Procedure

The inspection and recording can be accomplished by one individual. However, for safety reasons, a second individual should assist the inspector. During initial implementation, a third team member can help develop the roof section plan and take core samples. Each roof section is carefully inspected, and flashing and membrane distresses are recorded on a Roof Inspection Worksheet (Figure 8). The total perimeter flashing length should be determined and recorded in the space provided in the heading. The curb flashing, which includes the length of the base flashing on all curbed projections such as equipment supports, should also be determined and recorded in the heading. The problems are identified by distress type, severity level, specific defect, and quantity. A description of the blister distress and specific defects is shown in Figure 9. Similar detailed descriptions for all other membrane and flashing distresses are presented in USACERL Technical Report M-87/13⁴. Figure 10 contains an abbreviated list of identifiers for all the distresses/defects associated with the ROOFER inspection The list can be attached to the bottom of a long clipboard for ready reference by the inspector to identify specific defects in each distress category (i.e., Base Flashing - High - Holes, splits, and tears, would be identified as BF-H-1 on the Roof Inspection Worksheet). If a roof moisture survey of the insulation (see Chapter 4) was completed before the visual inspection, mark the core sample locations at this time.

As part of the visual inspection, a survey of the interior and exterior conditions should be performed. The inspector shall complete the reverse side of the Roof Inspection Worksheet (Figure 11) and record in the "remarks" section any additional comments that would alert the manager of problems that should be further investigated and corrected.

³M. Y. Shahin, D. M. Bailey, and D. E. Brotherson.

⁴M. Y. Shahin, D. M. Bailey, and D. E. Brotherson.




Figure 7. MCI and FCI and ratings.

Calculating the MCI and FCI from Inspection Results

The MCI and FCI of a roof section is determined from the information recorded on the Roof Inspection Worksheet. The calculations are completed on the Roof Section Rating Form (Figure 12) using the following five step procedure (also shown in Figure 13):

Step 1

Transfer the quantities for each combination of distress type and severity level to the Roof Section Rating Form.





Figure 8. Completed Roof Inspection Worksheet.

BLISTERS

Description: Blisters are round or elongated raised areas of the membrane which are filled with air.

Note: Blisters and ridges are difficult to differentiate at the low and medium severity levels. The rating error will be insignificant because of the similarity in the deduct curves. At high severity, however, it is important to distinguish between the two distresses due to their different leak potentials.



Graphic Representation of Blister

Severity Levels:

Low:

1. The raised areas are noticeable by vision or feel. The surfacing is still in place and the felts are not exposed.

Medium:

1. The felts are exposed or show deterioration.

High:

1. The blisters are broken.

Measurement:

- 1. Measure the length and width of the blister in lineal feet and calculate the area (length times width). If the distance between individual blisters is less than 5 ft, measure the entire affected area in sq ft.
- 2. When large quantities of this problem are present (especially on large roofs), the representative sampling technique can be used.

Density:

$$\frac{A}{B}$$
 x 100 = Problem Density

where A = total area of membrane blisters (sq ft)

B = total area of roof section being rated (sq ft)

Note: The problem density is calculated for each existing severity level.

Causes: Blisters are caused by voids or lack of attachment within the membrane. Moisture and gasses within the void greatly increases the potential for growth.

Figure 9. Example description of blister distress.

FLASHIN	G DISTRESSES/DEFECTS	MEMBRANE DISTRESSES/DEFECTS			
BF-LOW 1. Loss surface-NO DET 2. < 6" high 3. Permanent repairs BF-MED 1. Slip, wrink, loose 2. Loss surface-DET 3. Grease-NO DET 4. Temp. repairs BF-HIGH 1. Holes, splits, tears 2. Gap-top, side 3. Grease-DET MC-LOW 1. Paint, light corrosion 2. Cap deformed 3. CtrFI deformed 4. CtrFI sealed to base MC-MED 1. Holes-vert surface 2. Cap loose, its open 3. Sealant bad 4. CtrFI loose 5. CtrFI not over BaseFI MC-HIGH 1. Cap/CtrFI missing 2. Holes - or surface 3. Jt. Cov missing EM-LOW 1. Exists EM-MED 1. Joints exist 2. Nails backing out	EM-HIGH 1. Felts missing 2. Splits at joints 3. Holes in metal 4. Loose-deteriorated felts 5. Holes-interior gutter FP-LOW 1. Sleeve deformed 2. < 6" FP-MED 1. Felt exposed 2. Top not sealed 3. Sleeve open, no umbrella 4. Metal corrosion FP-HIGH 1. No strip felt 2. Sleeve cracked 3. No sleeve 4. No seal at membrane PP-LOW 1. Exist PP-HIGH 1. Corrosion 2. Seal below rim 3. Felts-DET 4. Seal cracked, separated DR-LOW 1. Bitumen Flow-NO CLOG DR-MED 1. Felt exposed 2. Strainer broken 3. Scupper corroded DR-HIGH	BL-LOW 1. Visible-NOT BARE BL-MED 1. Felts exposed BL-HIGH 1. Felts broken RG-LOW 1. Visible-NOT BARE RG-MED 1. Felts exposed RG-HIGH 1. Break at top 2. Top felt deteriorated SP-HIGH 1. Open split HL-HIGH 1. Hole in membrane SR-LOW 1. Poor aggregate embedment 2. Open laps, fishmouths 3. Alligatoring starting 4. Walkways-cracked, blister SR-MED 1. Flood coat exposed 2. MC-felt exposed 3. SM-no coating 4. SM-alligatoring to felt SR-HIGH 1. Felts exposed 2. MS-felt deteriorated 3. SM-alligatoring thru felt 4. Walkway membrane torn	SL-LOW 1. Exists < 2° SL-HIGH 1. Exists > 2° PA-LOW 1. Visible PA-MED 1. Not equal to existing PA-HIGH 1. Other distress in patch DV-MED 1. Material on roof 2. Solvent/oil/grease-NO DET 3. Vegetation-NO PENETRATION DV-HIGH 1. Solvent/oil/grease-DET 2. Roots in felts EQ-LOW 1. Exists EQ-MED 1. Movement of support-NO DAM 2. Bolts-SEALED EQ-HIGH 1. Movement of support-DAMAGE 2. Bolts-NOT SEALED PD-LOW 1. Exists or evidence		
Nais backing out Corrosion Loose-NO DET	1. Felt-DET 2. Ring loose/missing	INSULATION	I DISTRESS/DEFECT		
4. L0050-NU UE I	Hing loose/missing Clogged Scupper metal has hole	INS-HIGH 1. Wet insulation			

Figure 10. List of distress/defect identifiers.

Step 2

Total the quantities for each distress/severity level combination, calculate the density values, and determine the Deduct Values (DV) from the Deduct Value Curves. Appendix C contains Deduct Value Curves for the 16 distress types.

Step 3

Treating the flashing and membrane distresses separately, list the individual deduct values for each component (flashing and membrane) in descending order and compute the sum of the deduct values (SDV) and the number of deducts greater than 1 (q), as shown on page 30. Determine the corresponding Corrected Deduct Values (CDV) from the Corrected Deduct Value Curves (Appendix C). (Note: different Corrected Deduct Value Curves are used for the membrane and the flashing.) The CDV of maximum value should be used to compute the condition index.


ROOF INSPECTION WORKSHEET - COMMENTS					
INSTRUCTIONS: Circle response, i.e., Y = yes, N = no or U = not observed. If Y (yes), circle the type of	unknown or problem.				
A. EVALUATION OF INTERIOR CONDITIONS	<u>اسواطه بسواه نی کا بیراندر</u>				
1. Does the roof leak? Describe: Yes, NE corner of Room 54	Y N U				
2. Are there water stains on: a. walls	Y N U				
3. Do structural elements show any of the following: a cracks d. alteration g. physical damage b. splits e. rotting h. insect damage c. spalling f. settlement i. other:	Y N U				
4. Does the underside of the deck show any of the following: a. rusting	О и О				
B. EVALUATION OF EXTERIOR CONDITIONS					
 Do the exterior walls shown any of the following: a. cracks b. rusting d. movement f. other: 	Y ()				
2. Does the fascia or soffit show any of the following: a. cracks c. spalling e. water stains b. rusting peeling f. other:	♡ N				
3. Do the gutters or downspouts show any of the following: a. loose c. missing e. clogged b. damaged d. disconnect f. other:	У 🕦 .				
C. EVALUATION OF ROOFTOP CONDITIONS					
 Is there any unauthorized, unnecessary, or improperly installed equipment on the roof? a. equipment antennas e. cables b. signs d. platforms f. other: 	Ф и				
 Do adjacent parapet walls show any of the following: a. cracks c. cap cracked e. sealant b. spalling d. cap missing f. other: 	ч 🐠				
D. REMARKS:					

Figure 11. Reverse side of the Roof Inspection Worksheet.


ROOF SECTION RATING FORM														
BUILDING 68 SECTION					G				DATE ZIMAY 8	7 (ALC. B	Y		
PER. F CURB	LAS FLA	HING SHING	527 _36	LF LF	FLAS TOTA	HING L	_ <u>~</u>	د ح	LI	7	AREA 16,800 SF		нкр	
FLASHING DISTRESS TYPES BF - BASE FLASH MC - METAL CAP EM - EMBEDDED MET FP - FLASHED PEN PP - PITCH PANS							MEMBRANE DISTRESS TYPES BL - BLISTERS RG - RIDGES PA - PATCHING SP - SPLITS DV - DEBRIS & VEG HL - HOLES SR - SURF DET PD - PONDING							
TYP S	3V	QUANTI	ries		тот	DEN	DV		TYP	sv	QUANTITIES	TOT	DEN	DV
BF	L	130	+123		253	45	17		BL	L	4+12	16	010	3
mc	н	10			10	1.8	13		PA	M	10+24	34	0,20	-
BF !	n	.31_			31	5,5	13		ŚΡ	H	123	123	0.73	
mu	۷	5			5	0.89	2		PD	<u>_</u>	20	20	51.0	3
DR	L					0.18	1		SR	M	400 + 120	520	3.1	14
PP	H	1			1	0.18	9		BL	M	6	6	0.036	
FP	Н	1+1			2	0.36	11		HL	H		1	0.608	
DK	H				1	0.18	21		EQ	M	3	3	0.016	
 	_								SR	4	8	18	CACAR	_
-									DV	m	30	30	018	5
ļ	_								<u> </u>				-	
 	_								<u> </u>	 			 	-
 	_								 				┿	
	_									<u> </u>			 	 -
	_													<u> </u>
 	_												 	
}									 -				-	
} +	_												 	
										_			 	 -
 -						<u> </u>						+-	┼	
									<u> </u>		<u> </u>		-	
 									 				-	 -
 -									}	_			 	
 	-								ļ				 	 -
6022						CORPLOTED PROVICE ALL CONTRACTOR OF THE CONTRACTO								
CORRI	CORRECTED DEDUCT VALUE (CDV) 33					CORRECTED DEDUCT VALUE (CDV)								
	FCI = 100 · CDV = 67 FLASHING RATING = 600 D						$MCI = 100 \cdot CDV = 35$ $MEMBRANE RATING = PooR$							
FLASHING RATING = $600D$						M	:MR	$KANE KATING = \underbrace{1}_{}$	OOK					


Figure 12. Completed Roof Section Rating Form.

STEP 1. INSPECT ROOF, DETERMINE DISTRESS TYPES AND SEVERITY LEVELS; DETERMINE QUANTITIES AND CALCULATE DENSITIES.




STEP 2. DETERMINE DEDUCT VALUES.






STEP 5. DETERMINE MEMBRANE CONDITION RATING.

STEP 3. COMPUTE CORRECTED DEDUCT VALUE.





STEP 4. COMPUTE MEMBRANE CONDITION INDEX (MCI). = 100-CDV

Figure 13. Steps for calculating MCI and FCI for a roof section.

Flashing
(Distress data from the Completed Roof Section Rating Form [Figure 10])

DV	SDV	q	CDV flashing
21	21	1	21
17	38	2	24
13	51	3	28
13	64	4	32
11	75	5	33
9	84	6	33
2	86	7	32
1	87	7	31

Maximum CDV_{flashing} = 33

Membrane
(Distress data from the Completed Roof Section Rating Form [Figure 10])

DV	SDV	q	CDV _{membrane}
65	65	1	65
14	79	2	55
7	86	3	53
5	91	4	48
3	94	5	47
3	97	6	43
3	100	7	40
2	102	8	37
2	104	9	38
2	106	10	38

Maximum $CDV_{membrane} = 65$

Step 4

Calculate the condition indexes using the following equations:

$$MCI = 100 - Max. CDV$$
 (membrane) [Eq 2]

Step 5

Determine the corresponding descriptive condition ratings from Figure 7 for both indexes.

Use information from the Roof Inspection Worksheet to complete the heading section of the Roof Section Rating Form. Building, section, and agency/installation data is essential to provide continuity in the various forms. File the completed Roof Section Rating Form in the corresponding Roof Section Folder.

4 INSULATION INSPECTION AND EVALUATION PROCEDURE

A complete evaluation of an insulated roofing system requires that the insulation be inspected to determine if it contains moisture. This chapter describes the effects of wet insulation, the insulation condition rating procedure, moisture detection methods, and the determination of the Insulation Condition Index (ICI).

Insulation Condition Rating

The insulation condition rating is based on the Insulation Condition Index (ICI). The ICI, a numerical indicator between 0 and 100, reflects the condition of the insulation in terms of its ability to perform its function and the level of needed repair. Insulation with an ICI of 100 is in excellent condition.

Effects of Wet Insulation

Insulation is a common component of many low-slope roofing systems. Defects in the membrane and/or flashing components can provide paths for water to enter and wet the insulation. Moisture in the insulation can also be caused by condensation. Moisture reduces the R-value of the insulation and may also reduce the bond between it and the membrane. Roofs with wet insulation are more prone to blow off or split. Water in insulation adds to the weight the structural system must resist and may also promote corrosion of fasteners or metal decks, rotting of wood decks and nailers, and deterioration of cementitious deck materials.

Roof Moisture Detection

Rooftop conditions that could suggest wet insulation include spongy areas, depressions in the roof surface, vegetation growing through the membrane, and leaks that continue to drip long after the source of water has been removed from the roof.

Detecting wet insulation and determining the extent of the wet area can be done using a nondestructive moisture detection technique such as infrared (IR) scans, nuclear meter, or capacitance meter. The results of a moisture survey using any of these techniques must always be verified by core sampling.⁵

Infrared Scanning

IR scanning systems detect the temperature differences that occur on a roof above areas of wet and dry insulation. IR roof scans should be performed at night and can either be accomplished on the roof or from the air. When surveying only a few roofs in an area, on-the-roof scans may be more cost

⁵W. Tobiasson and C. Korhonen, *Roof Moisture Surveys: Yesterday, Today and Tomorrow*, CRREL Miscellaneous Paper 2040 (U.S. Army Cold Regions Research and Engineering Laboratory [CRREL], September 1985).

effective than aerial scans. In many instances, however, an aerial IR scan is more cost effective because all the insulated roofing systems of most military installations can be surveyed in a few hours.⁶

A thermal image (thermogram) of a roof taken during an on-the-roof survey is shown in Figure 14. The bright thermal anomalies indicate where insulation is wet. Figure 15 is a conventional photograph of the same roof. The thermogram in Figure 16 was taken from an Army helicopter about 500 ft above a roof. Bright areas denote potentially wet areas of insulation as well as areas having hot rooftop equipment or exhaust coming from roof vents.

Aerial scans are usually done from a helicopter but can also be done using a fixed-wing aircraft. The thermal images taken from the air are recorded on film or videotape for subsequent review and analysis. Later, the areas that appear to contain wet insulation may be marked on airphotos (Figure 17).

Nuclear Meter

Nuclear meters detect moisture by measuring the increased number of hydrogen atoms that occur in areas of wet insulation. Readings are taken on a grid pattern (the grid is normally 5 ft by 5 ft) established on the roof. The differences in the meter readings are analyzed and interpreted, and a moisture contour map of the roof is drawn to delineate potentially wet areas. Computers are often used to analyze the data and develop the contour map, greatly reducing the time involved.

Capacitance Meter

Capacitance meters measure the differences that occur in dielectric properties between areas of wet and dry insulation. Capacitance meter readings are also taken on a grid pattern that is normally 5 ft by 5 ft. The differences in the meter readings are analyzed and interpreted, and a moisture contour map is drawn.

Core Sampling and Determining Moisture Content

After the moisture detection work is completed, the areas of potentially wet insulation are plotted on the roof section plan of a Roof Inspection Worksheet (Figure 18). The areas of potentially wet insulation are shown by hatchmarks.

Since the moisture detection techniques discussed above provide only relative results, core samples from the roof system must be taken and analyzed to determine the amount of moisture actually present in the insulation.

Proposed core sample locations are selected for areas of potentially wet insulation and marked on the Roof Inspection Worksheet as triangles. Usually, a core sample should be taken for each potentially wet area. However, when small areas are found near a large area, one core sample can be assumed to represent those areas as well. One additional core sample is always taken in a dry area as well, to verify that it is indeed dry and not just less wet. The core sample locations can be very critical. A core sample taken at a presumably wet location on the roof section could easily indicate

⁶W. Tobiasson, Aerial Roof Moisture Surveys, CRREL Miscellaneous Paper 2022 (CRREL, August 1985); W. Tobiasson, A Method for Conducting Airborn Infrared Roof Moisture Surveys, CRREL Miscellaneous Paper 2436 (CRREL, April 1988).




Figure 14. Typical infrared photo.



Figure 15. Conventional photo of roof in Figure 14.



Figure 16. Aerial thermogram of a roof.




Figure 17. Airphoto marked to show potential areas of wet insulation.

ROOF INSPEC	TION WORKSHEET	AGENCY/INS		JONES						
BUILDING	(8 PER. I	LASHING	527 Li	OCMES _	DATE	<u> </u>	ni A	1 2	4 1	98.7
SECTION	6 CURB	FLASHING _	_3/LI	7	NAMI		G.			
BF-BASE FLASH MC-METAL CAP EM-EMBEDD MET FP-FLASHED PEN	PP-PITCH PANS DR-DRAIN & SC BL-BLISTERS RG-RIDGES	SP-SPLITS HL-HOLES SR-SURF DI SL-SLIPPAGI	DV ET EC	-PATCHING -DEBRIS & VEG -EQ SUPPORT -PONDING	!	I D #		S E V	OWL	Q T Y
,66	3 SEC SEC STORES	T. G. D. B. E. CORE "C" REPRESENT TH AREAS ALKWAY 114" E.	TOTH AREAS	B O D	٠ (
SCALE:!'	= 30'						N	ORT	Н	

Figure 18. Potentially wet areas and core sample locations mapped onto Roof Inspection Worksheet.

dry conditions if it is taken on the wrong side of the wet-dry line. Dimensions for the core sample locations are not necessary if an on-the-roof IR survey was made and the potentially wet areas were outlined by spray painting.

Core samples are obtained by cutting and removing plugs of the roof insulation and membrane. The void must then be filled with a combination of spacer plugs and mastic, and the roof membrane patched. From each core sample, each type of insulation is separated and placed into sealed plastic bags or other containers and taken to a laboratory for analysis. The amount of moisture is determined by weighing the sample before and after a period of oven drying at 120 °F. The ratio of the weight of water lost during drying to the weight of the dry sample represents the moisture content of the sample expressed as a "percent of dry weight." It is not unusual to have moisture contents in excess of 100 percent of dry weight, especially in wet cellular plastic insulation materials.

Insulation Severity Factors

Moisture affects the performance of roof insulation in varying degrees depending on the type of insulation. The Insulation Severity Factor (ISF) is a measure of the adverse effect of moisture on the thermal performance of an insulation. Curves that relate the ISF for various types of insulating materials to their moisture contents are presented in Figures 19 and 20. For example, fiberboard, with a moisture content of 20 percent has an ISF of 0.7. The same ISF is reached in urethane insulation at a moisture content of 305 percent and in 1 PCF polystyrene at a moisture content of 440 percent.

Calculating the Insulation Condition Index

The Insulation Condition Index (ICI) for a roof section is calculated on the ICI Calculation Sheet (Figure 21) using the following three steps:

Step 1

Determine the moisture content and insulation severity factors of each area of potentially wet insulation. Section 1 of the ICI Calculation Sheet provides space where the moisture content of the samples can be calculated. Values entered in this section are determined in the laboratory. The notes in the headings of the columns show how the values are calculated. When more than one type of insulation is present, a moisture content calculation (percent of dry weight) is performed for each type of insulation. The ISF for each type of wet insulation in each core sample is determined from Figures 19 and 20.

Step 2

Determine the average ISF for the wet insulation. Section 2 of the ICI Calculation Sheet provides space for this computation. The largest ISF for each core sample is used in the calculation. The total wet area represented by the core is determined and multiplied by its ISF. This is repeated for all core samples, and the values are summed. The sum is entered in Box D of the calculation sheet (Figure 21). The total area of wet insulation is determined and entered in Box C.

The average ISF is calculated by dividing the value in Box D by the value in Box C.




Figure 19. Insulation severity factor (ISF) vs moisture content for cellular glass, cork, glass fiber, polyurethane, polystyrene, and polyisocyanurate insulation.




Figure 20. ISF vs moisture content for phenolic, insulating concrete, gypsum, perlite, and fiberboard insulation.

ICI CALCULATION SHEET AGENCY/INST.: FT. JONES											
		5/1187		NO.: ¿	8 S	ECTION:	6	AREA:	16,80	O SF	7
	ALC, BY			LIAMS		ISF &	ICI CALC.	BY:		KEMP	
1. DE	TERMIN	ATION (F MOIST	URE CON	TENT AN	D INDIVID	U AL ISF O I	CORE SA	MPLES		
CORE	INSULAT		THICK	A TARE WT	B WET+ TARE	C DRY+ TARE	D WET (B-A)	E DRY (C-A)	F WATER (D-E)	%WATER (F/E) X 100	ISF
A	LKET	PANE	2.	8.80	1490	12.50	11.10	3.70	7.40	200	1,41
A	FER	LITE	١	6.76	34.89	16.21	26.13	145	12,68	25	1.99
Ď	LRET	HAVE	2	8.82	12.84	12.47	4.02	3,45	6.37	/0	2
B	FER	LITE	į	6.73	14.27	16:05	7.54	7.32	5.22	3	ر ح
C	UKET	HANE	2	£.75	13.15	12.90	,5,2c	4 15	11.25	266	C.60
ت	PEKI	LITE	}	8.82	33.17	16.20	24.35	73c	16.47	230	1.99
)F AVERA			حصيصابد	TERMINAT				
CORE	ISF (A)	WET A		(A) X	(B)	- 1	EM DENSITY	_	17.1	%	
A	6,49	200	-4	2	c43	(1012	L WET AREA	TOTAL ARE	A) X 100		
3	U	DK			ε	IDV:		70	·		
ت	6.99	51	2	S	04	WAF:		æ			
											
						ICI:		23			
<u></u>				<u> </u>		100 - [(IDV + WAF)	(AVERAGE I	SF]		
TOTAL			16		2847	_		\/~ ~ \	n.	A	
	GE ISF (D				0.99	RATIN		VERY	Pool	<u> </u>	===
						TE INSULATION IN THE A					
2. DO 1	NOT INCL	JDE ANY A	REAS THAT	HAVE AN IS	SF OF ZERO						
3. ROU	IND ICI TO	NEAREST	WHOLE NU	MBER.							
	W	ET AREA	FACTOR	(WAF)		INSULATI	ON COND	ITION RAT	ring	
WE	TAREAS		W	/AF				ICI			
	1		C			ł	8	6 - 100	EXCELL	ENT	
1	2		4	,				'1 - 85		OOD	
	3		9 سر.	· ·				6 - 70			
	(1)	L		ン		1		.1 - 55			
	5 OR MORE 10							6 - 40			
						-		1 - 25		OOR)	
								0 - 10	FAILED		
						· W					

Figure 21. Completed ICI Calculation Sheet.

Step 3

Determine the ICI for the roof section. Section 3 of the ICI Calculation Sheet provides space for the calculation. The problem density is determined using the following equation:

Problem Density =
$$\frac{\text{(C)}}{\text{Area}} \times 100$$
 [Eq 3]

where C = Total area of wet insulation

Area = Total area of roof section being rated.

The Insulation Deduct Value (IDV) is then determined from Figure 22 and the ICI is calculated using the following equation:

$$ICI = 100 - [(IDV + WAF) \times ISF_{Ave}]$$
 [Eq 4]

where IDV = Insulation Deduct Value from Figure 22

WAF = Wet Area Factor, (use the following to adjust the index to account for the number of wet areas present)

No. of wet areas 1 2 3 4 5 or more WAF 0 4 6 8 10

ISF_{Ave} = The Average Insulation Severity Factor determined from Step 2

The insulation condition rating is then selected from the table at the bottom of the calculation sheet (Figure 21). In the example shown, the ICI is 23 (rounded to the nearest whole number), and the rating is "very poor."

Looking at the computation, one can see that a roof section with 17.1 percent wet insulation would be "very poor" in terms of the ability of the insulation to perform. If the wet insulation were all located in one contiguous area, then the WAF would be "0" and the ICI would increase to 31 and the roof section would be rated as "poor" with regard to insulation.

This is the actual number of separate wet areas or potentially wet areas on the roof section and not necessarily the number of core samples used to represent these wet areas. For the example shown in Figure 18, the number of wet areas is four. The core location B found the potential wet area to be dry.




Figure 22. Insulation deduct value (IDV) vs problem density.

5 ROOF CONDITION EVALUATION AND MAINTENANCE, REPAIR, AND REPLACEMENT (MRR) PROCEDURES

The membrane, flashing, and insulation condition indexes, in total, provide an assessment of the condition of a roof section. By combining these three indexes, a roof condition index (RCI) is produced. This single index is useful for evaluating the overall condition of a roof section and for comparing conditions between roof sections. The RCI allows the user to rank individual roof sections in accordance with their ability to perform.

The three component indexes (FCI, MCI, and ICI) have a direct relationship to determining the needs for MRR of the various roof sections. The RCI similarly provides an overall indication of MRR needs for the entire roof network. This chapter will describe the method used to develop the relationship between the RCI and the three component indexes. It will also illustrate how MRR alternatives can be determined for the individual roof sections.

Roof Condition Index Calculation

Each individual index (MCI, FCI, ICI) reflects the component's ability to provide its intended service and indicates MRR needs. Since the components must interact to function as a roof system, they are dependent on each other. This relationship is defined for roof sections with insulation by the following equation:

If a nondestructive moisture survey of an insulated roof section has not been conducted, an ICI of 100 is assumed. In this case, the RCI may not be an accurate index.

If the roof section has no insulation, the RCI is determined by the following equation:

The above equations give the greatest weight to the component with the lowest condition index and then modify it by adding "value" from the remaining indexes.

The following examples illustrate how this relationship works:

Example 1: FCI = 67; MCI = 35; ICI = 23

RCI =
$$(0.7 \times 23) + 0.15 (67 + 35)$$
= $16 + 15$
= 31

Example 2: FCI = 67; MCI = 35; ICI = 100

RCI = $(0.7 \times 35) + 0.15 (67 + 100)$
= $25 + 25$
= 50

Example 3: FCI = 67; MCI = 35; no insulation

$$RCI = (0.7 \times 35) + (0.3 \times 67)$$
$$= 25 + 20$$
$$= 45$$

The flashings for the roof section represented in example 1 are in good condition (FCI = 67). However, when the FCI is combined with an MCI of 35 and an ICI of 23, the RCI is 31, indicating that replacement of the roofing system is probable (Table 1). In example 2, the FCI and MCI are the same as in example 1, but the ICI is 100 (no wet insulation), resulting in an RCI of 50 and indicating that major repairs are needed. If, for this same roof section, there was no insulation present in the roofing system (example 3), the RCI would equal 45.

The RCI calculation sheet (Figure 23) is used to determine the RCI for a roof section. The completed sheet is kept in the roof section folder with other inspection and calculation sheets.

Roof Evaluation Procedure

The evaluation of a building's roof system is made on a section by section basis. Each roof section represents an area uniform in construction and subjected to the same conditions. Each section is unique and should be treated as a unit that can be replaced without affecting adjacent roof areas.

For evaluating a roof section, its overall condition and rate of deterioration must be defined to provide a means of estimating its expected service life.

Overall Condition

The RCI of a roof section describes the overall condition of the section and, as discussed above, combines the condition indexes of the flashing, membrane, and insulation to give the user an indication of the level of repair needed. The RCI, alone, cannot be used to determine detailed MRR requirements for a roof section. However, the RCI does provide a means for comparing the overall needs of many roof sections and aids in developing short- and long-term MRR plans for the roof network.

Table 1

MRR Recommendations

RCI	Corrective Action
86 - 100	Routine Maintenance
71 - 85	Minor Repairs Needed
56 - 70	Moderate Repairs Needed
41 - 55	Major Repairs Needed
26 - 40	Replacement Probable
11 - 25	Replacement Needed
1 - 10	Replacement Critical

RCI CALCULATION SHEET	AGENCY	TNST.:	RT JONES							
DATE: JUN / 1 / 1987 BLDG NO): 68	SECTION ID:	6 ARE	CA: 16,800	SF					
ROOF SECTION WITH INSU	ROOF SECTION WITH INSULATION:									
	VALU	LOWEST	OTHER	7						
M	ici 35		35	7						
FC			67	7						
ıc				7						
_	TOTAL		/02	7						
		X 0.70	X 0.15	7						
		(A) /4.1	(B) /5,3	7						
		(A+B)		7						
		RCI	31							
	RATING: <u>KEPLACEMENT PKOBABLE</u>									
ROOF SECTION WITHOUT	INSULATIO	N:								
	VALU	LOWEST	OTHER	7						
M	CI									
FC	CI									
	TOTA	•								
		X 0.70	X 0.30]						
		(A)	(8)							
		(A+B)								
		RCI								
RAT	ING:									
	MRR RECO	MENDATIONS								
86 -	100	ROUTINE MAINTENA	NCE							
71 -	85	MINOR REPAIRS NEE	DED							
56 -	70	MODERATE REPAIRS	NEEDED							
41 -	55	MAJOR REPAIRS NE	EDED							
26 -	40	REPLACEMENT PRO	BABLE							
11 -	25	REPLACEMENT NEE	DED							
0 -	10	REPLACEMENT CRIT	ICAL							

Figure 23. Completed RCI Calculation Sheet.

Rate of Deterioration

The roof on a building begins deteriorating shortly after it is applied and continues deteriorating until it is replaced. The rate of deterioration is governed by a complex relationship between the physical characteristics of the roofing material, the natural environment, and the level of maintenance and repair being performed. It is also influenced by the design of the building, the use or misuse of the roof surface, and unusual weather phenomena such as windstorms or hailstorms.

Although poorly designed and constructed roofs have been known to fail in less than 2 years, and other roofs have lasted for 30 years or more, the design life of a built-up roof is generally considered by the roofing industry to be 20 years. For the ROOFER system, a 20-year life has been established as "normal." This assumes that after 20 years the RCI will be in the "Replacement Probable" range (26-40). A "normal" deterioration curve, with the RCI set equal to 33 (center of "Replacement Probable" band) and the age equal to 20, is shown in Figure 24. Data taken at three Army installations on a variety of built-up roof systems of different ages confirm the shape of this curve.

Determination of Deterioration Curve, Expected Life (EL) and Remaining Service Life (RSL)

The deterioration rate and expected life for roof sections may vary greatly from that of a theoretically defined "normal" 20-year roof, depending on the previously mentioned factors. A series of curves were developed which represent roof section deteriorating at rates different from the "normal" 20-year roof (Figure 24). The curves falling below the "normal" curve represent roof sections deteriorating at a faster rate and predicted to fail before 20 years. The curves above the "normal" curve are performing better than a 20-year roof.

The predicted deterioration curve for a roof section having an RCI at a given age can be determined using this family of curves. As an example, the deterioration curve for a roof section with RCI equal to 75 at year 15 is shown by the dashed curve (example A). The actual RCI for this roof section is higher than the expected RCI of 63 for a roof section deteriorating at the "normal" rate.

The Expected Life (EL) of a roof section is defined as the time from construction to the time at which the roof is expected to reach an RCI of 33, if no major repair work is performed. Interpolating from the predicted deterioration curve, the EL of the roof section is determined. For example A, EL = 23 years. In this case, the deterioration rate beyond the inspection year is assumed to be the same as the "normal" rate.

The remaining service life (RSL) is the time remaining until the end of service life is reached (RCI = 33) and is determined by the following equation:

$$RSL = EL - Agc$$
 [Eq 7]

From Equation 7, the RSL = 8 years (23-15).

The deterioration curve for a roof section with an RCI equal to 31 at year 9 (example B) is also shown in Figure 24. The actual RCI is lower than the expected RCI of 86 for a roof section deteriorating at the "normal" rate. Interpolating from the deterioration curve, the EL of the roof section is determined to be 8.5 years. In this case, where the EL has already been reached (RCI<33), the EL is assumed to be equal to the age of the roof (EL = 9 years). From Equation 7, the RSL for the roof section of example B equals 0 years (9 - 9).




Figure 24. Deterioration curves for built-up roofs.

Maintenance, Repair, and Replacement Alternatives

Building maintenance managers do not have defined or published minimum performance standards for roof assemblies. Corrective and/or preventive maintenance criteria varies from installation to installation. This section presents MRR alternatives based on the evaluation technique presented in this report.

Routine Preventive Maintenance

Every roofing assembly, like every other physical object, deteriorates with time. As the roof ages, it exhibits various levels of deterioration until it reaches the stage described earlier in the report as "Replacement Probable." Further deterioration reduces the index to "Replacement Needed" or "Critical." The "normal" deterioration rate and 20-year service life, as previously defined, cannot be achieved without routine preventive maintenance.

A preventive maintenance program which includes regular inspections and maintenance and repair of localized problems will ensure an acceptable deterioration rate. These repairs can generally be made "on the spot" by the maintenance team. Removing debris, controlling vegetation growth, and cleaning blocked roof drains are relatively easy maintenance tasks. It is also possible to make simple repairs to flashings (such as open seams) and membranes (such as recoating bare areas and repairing punctures). Without this type of routine maintenance and repair, the roof system will deteriorate at a more rapid rate and never achieve its potential life.

Major Repair

Major repair includes the permanent repair of medium and high severity distresses and removal of areas of wet insulation (as identified by the ROOFER inspection procedures). These repairs should be accomplished on the next routine MRR cycle. However, the high severity distresses require immediate attention and should receive temporary repairs before the condition can spread or damage the system beyond repair. These corrective actions will improve the roof condition index (RCI_{improved}) and increase the roof's life expectancy. Major repair could include replacement of substantial areas of defective membrane, flashings, and wet insulation as well as procedures to correct poor flashing details at roof projections and equipment supports.

Roof Replacement

At times, it may be more economical to replace the roof than repair it. Usually this means replacing the entire roof system including the insulation. An engineer qualified to analyze roofing is needed at this point to fully evaluate the roof system. Depending on the inspection results, it may be possible to salvage the roof insulation if it is not wet. It may also be possible to do partial replacements of poor roof areas (perhaps damaged by workmen or hail) thereby upgrading the roof section to an acceptable RCI.

Selection of Optimal MRR Alternatives

Selecting between "major repair" and "replacement" requires a cost analysis to determine which alternative is more economical. To do the analysis, the additional service life (ASL) of the roof section as a result of performing major repairs must be determined.

Determination of ASL

Performing "major repairs" on a roof section improves the roof condition and increases the RCI. After repairs are completed, the roof section will be assumed to follow the "normal" deterioration rate. The Remaining Service Life assuming major repairs have been completed (RSL') can be determined from Figure 25 if the improved condition of the roof is known (RCI_{improved}). RCI_{improved} can be determined by recalculating the RCI with all medium and high severity distress values eliminated and assuming the ICI to be equal to 100. The ASL is the additional years of service which can be realized by a roof section, if the major repairs are performed and the RCI is improved. The ASL is calculated from the following equation:

$$ASL = RSL' - RSL$$
 [Eq 8]

Using the two examples from page 45 and assuming that major repairs would improve the RCIs to 87, the ASLs are calculated as follows:

Example A.

Example B.

Figure 26 shows the relationship between age, EL, RSL, RSL', and ASL for Example A.

While the RCI can be improved by making the necessary repairs, a cost analysis should be made to determine if the repairs are cost effective.

Cost Analysis

To determine the optimal MRR alternative, the cost to repair per year of ASL is compared to the cost per year of service life to replace the roof.

The cost of the major repair alternative includes the cost of correcting all distresses at the medium and high severity levels. Low severity distresses are not corrected. If wet insulation is detected, the cost also includes removing and replacing wet insulation and the overlying membrane and flashing systems. The cost per year of additional service life is then determined by dividing the total cost of the repairs by the ASL.




Figure 25. RCI_{improved} vs remaining service life.




Figure 26. Relationship between age, EL, RSL, RSL', and ASL.

Figure 27 shows a completed worksheet for determining the economic evaluation of a built-up roofing system. NOTE: The unit costs shown in the worksheet are for the Washington D.C. area using 1988 as a base year. These unit costs can be used with regional cost adjustment factors to develop a general cost comparison, or local costs can be inserted to provide a more detailed cost estimate.

Replacement costs generally include the costs of the removal and disposal of the old roof system and wet insulation, the costs of new membrane and flashings, and any additional cost such as new drains, area dividers, expansion joints, and tapered insulation systems or fills to provide drainage. The total cost of replacement is then divided by 20 years (assumed service life of a new roof) to obtain the cost per year for replacement.

$$$ replace/yr = \frac{total \ replacement \ cost}{service \ life (20 \ yrs)} [Eq 10]$$

The ratio of cost to repair per year to cost to replace per year is determined by:

Cost Ratio =
$$\frac{\text{$repair/yr}}{\text{$replace/yr}}$$
 [Eq 11]

This cost analysis is a simplified approach and does not take into account the cost of money including inflation and discount rates.

			GE	CONOMI	C EVALUATION	OF A BUR I	OOFIN	3 SY	
Agcy/Ins:	FT. JONES			BLDG/S	EC: 68 G	AREA: 168	300 SF	AC	E:
FLASHING	10.FM			mom a r	MEMBRANE	1 BITTO			MVVM A T
DIS-SL-D	OF COST	QTY	_	TOTAL COST	DIS-SL-DF	UNIT	QTY		TOTAL COST
BF-M-1	5.31	0.1		100	BL-M-1	2.31	6	\$	14
BF-M-2 BF-M-3	5.16 6.28	31	\$	160	BL-H-1 RG-M-1 RG-H-1 RG-H-2	$\substack{26.99\\2.33}$			
BF-M-4	20.52				RG-H-1	22.35			
BF-H-1	26.03				RG-H-2	26.99			
BF-H-2	11.20				SP-H-I	18.50	123 1 520	\$	2276
BF-H-3	33.16				HL-H-1 SR-M-1	27.07	52 0	3	27 1212
MC-M-1 MC-M-2	17.35 19.60				SR-M-2	$\substack{2.33\\2.62}$	520	Þ	1212
MC-N-3	8.74				SR-M-2 SR-M-3	1.30			
MC-M-4	4.26				SR-M-4	3.81			
MC-M-5	7.29				SR-H-1	6.63			
MC-H-1	10.89	10		100	SR-H-2 SR-H-3	4.75			
MC-H-2	10.80	10	\$	108	SR-H-3	4.52			
MC-H-3	$\substack{6.19\\7.07}$				SR-H-4 SL-H-1	$\substack{29.79\\20.70}$			
EM-M-2 EM-M-3	7.81				PA-M-1	14.42	34	\$	490
EM-M-4	7.43				PA-H-1	14.42	٠.	•	100
ĔM−H−1	7.20				DV_M_1	6.02			
EM-H-2	9.45				DV-M-2	25.57			
EM-H-3	16.15				DV-M-3	6.02	30	\$	181
EM-H-4	8.51				DV-H-1	39.91	3	_	1010
EM-H-5	25.13				EØ-M-3	337.74 181.08	3	\$	1013
FP-M-1 FP-M-2	5.33 6.43				FQ-H-1	105.90			
FP-M-3	38.32				DV-M-2 DV-M-3 DV-H-1 EQ-M-1 EQ-M-2 EQ-H-1 EQ-H-2	181.08			
FP-M-4	21.43								
FP-II-1	18.57			50	INSULATION:		0070	_	00000
FP-H-2 FP-H-3	56.28 93.95	1	•	56	IN-H-1	8.00	2876		23008
FP-H-4 FP-H-1	24.67 21.43	1	\$	25	REPAIR SET	P CHARGE :	= \$	54	4
FP-H-2 FF-H-3	46.52 23.74				TOTAL REPAI	R COSTS :	= \$ 2	2922	6
PP-H-4 DR-M-1	61.58 23.45	1	\$	62	ADDITIONAL	SERV. LIF	Ξ =	1	1 YRS
DR-M-2	44.90				TOTAL REPAI			265	7 \$/Y
DR-M-3 DR-H-1	21.43 29.13				ADDITIONAL	DERV. LIFT	3 		
DR-H-2	62.65				REPLACEMENT	COST			
DR-H-3	50.23	1	\$	50	6	5.25 SF :	= \$ 8	382 0	0
DR-H-4	111.44				REPLACEMENT		= \$	441	0 \$/ Y
CACTO ANDAR	VOIO				20 YEAR		TINI / 1	0 /1	007
OST ANAL		CUDAR			C	enerated:	•		
RATIO =	REPAIR COST,		=	0.60	ADJ	. RATIO	RECON ACT	MEN 'ION	
	REPLACE COST	YEAR				- 0.8			
DJUSTED RATIO	= RATIO + (0	0.01 x	AGE) = (0.69 0.8	- 1.2 > 1.2	MAR	AIR OIN LAC	AL

Figure 27. Economic evaluation of a BUR system.

It is generally accepted that when the cost ratio exceeds 1.0, for roofs at an early age, then replacement is justified. However, as a roof ages, it eventually reaches a state where it will wear out because of physical changes to the materials. To compensate for this, an aging factor is used to adjust the cost ratio.

Adjusted Cost Ratio = Cost Ratio +
$$(0.01 \text{ x Age})$$
 [Eq 12]

Using example B (building 68 section G) and the economic evaluation in Figure 27:

Cost Ratio =
$$\frac{$2657}{$4410}$$

= 0.60
Adjusted Cost Ratio = 0.60 + (0.01 x 9)
= 0.69

If the adjusted cost ratio is less than 0.8, it is best to repair. If the ratio is greater than 1.2, replacement is the optimal alternative. When the ratio falls within the "optional" range (0.8 and 1.2), the roof engineer has the option to replace or repair. It is in this range that engineering judgement and budget considerations are needed to make the MRR selection. Funds may not always be available for reroofing all roofs with a ratio indicating replacement. The "optional" range allows the engineer the flexibility needed to make decisions.

In the above example, the RCI was low (31) because of a major split in the membrane and wet insulation covering 17 percent of the roof area. The cost for repairing the split and replacing the insulation when compared to the cost of replacement indicates that it is still a better economic choice to repair the roof and extend its life for possibly 11 years at a cost of \$2657 a year than to replace the roof and get an expected life of 20 years at a cost of over \$4400 a year.

Corrective Action Requirements

Once an analysis has been performed to determine whether major repair will be performed on a roof section or whether it will be scheduled for replacement, the work must be programmed. A Corrective Action Requirement sheet (CAR) should be generated to initiate the needed work. The sheet should include general information about the building and roof section and details of the work required. The CAR should be submitted with the completed Roof Inspection Worksheet and a work order form for processing.

Figure 28 shows a completed CAR sheet for the repairs to be accomplished on section G, building 68. The decision to repair is based on the cost analysis shown in Figure 27. The CAR sheet lists all the repairs required to bring the roof to an acceptable condition, thereby improving the RCI and adding life to the roof.

Figure 29 shows a completed CAR sheet for replacement of the roof of section G, building 68. If the cost analysis had indicated that it was more cost effective to replace the roofing system than accomplish the necessary repairs, replacement would be programmed. In completing a CAR sheet for replacement, the initiator should review the comments section of the roof inspection worksheet to ensure that all comments referring to the problems that need to be corrected during redesign are considered.

JUN/12/1987

CORRECTIVE ACTION REQUIREMENT SHEET **MAJOR REPAIR**

(NOTE: ATTACH A COPY OF THIS FORM, ALONG WITH A COPY OF THE ROOF INSPECTION WORKSHEET TO DA FORM 4283)

AGENCY/INST.: FT. JONES FACILITY NO: 00068
BLDG NO./SEC: 68 G BLDG NAME: TROOP TRAINING
BLDG USE: CLASSROOM TRAINING INSPECTION DATE: MAY/1987

MEMBRANE: BUR: Asphalt
SURFACING: AGG.: Crushed Stone
VAPOR RET: LAMINATED FELTS
INSULATION: PERLITE AREA (SF): 16800 AGE (YRS): 9 DECK TYPE: CONCRETE STD Cast-In-Pl EST. REPAIR COST: \$ 29226.00

PÖLYÜRETHANE

CORRECTIVE ACTION RECOMMENDED: Maintenance, Repair and/or Partial Replacement

JUSTIFICATION: An economic analysis of the roof condition, including age, indicates that it is more cost effective to accomplish the necessary maintenance, repairs and/or partial replacement of the roofing components rather than replace the roofing system. Therefore, accomplish the following actions for the above roof section. (Note: paragraphs refer to TM-617, "Inspection, Maintenance, and Repair of Roofing Systems" Draft) [Note: numbers refer to identification numbers of distresses corresponding with the Roof Inspection Worksheet]

- Prime exposed and deteriorated base flashing and coat with heavy bodied asphalt coating. (para 3-4g(3)(a)2) 1. BF-M-2 31 LF
- Remove foreign material clogging roof drains. [10] 2. DR-H-3
- 3. FP-H-2 Remove damaged flashing sleeves or curbs and replace.

 1 (para 3-4g(7)(c)) [8]
- 4. FP-H-4 Prime surface and three course unsealed flashed penetrations. (para 3-4g(8)) [9]
- Replace metal cap flashing with new corrosion resistant material. (para 3-4g(6)(c)) [3] 5. MC-H-2 10 LF
- Fill distressed pitch pans with sealant and crown to assure moisture runoff. (para 3-4g(8)) [7] 6. PP-H-4
- Restore surfacing material on blisters which have exposed felts. (para 3-4g(1)(a)4) [17] 7. BL-M-1 6 SF
- 8. DV-M-3 30 SF Clean surface of all dirt and vegetation. (para 3-4g(4)(a)5) [22]
- Replace improper equipment supports with device allowing for movement of equipment. (para 3-4g(10)) [20] 9. EQ-M-1 3 SF
- 10. HL-H-1 1 SF Repair holes and restore surfacing. (para 3-4g(2)(e)) [19]
- Replace patches having inferior repair material with same or better quality than existing membrane.
 Restore surfacing material. (para 3-4g(2)(b)3) [12,13] 11. PA-M-1 34 SF
- 12. SP-H-1 123 SF Repair splits and restore surfacing material. (para 3-4g(2)(b)) [14]
- 13. SR-M-1 520 SF Reinstall aggregate on exposed membrane surfaces. (para 3-4g(1)(a)) [16,23]
- 14. IN-H-1 2876 SF Remove wet roof insulation. Inspect the deck, and repair, if necessary. Replace the roofing system, including adjacent flashings. (para 3-5b)

Figure 28. Corrective Actions Requirement Sheet for major repair.

JUN/12/1987

CORRECTIVE ACTION REQUIREMENT SHEET ROOF REPLACEMENT

(NOTE: ATTACH A COPY OF THIS FORM, ALONG WITH A COPY OF THE ROOF INSPECTION WORKSHEET TO DA FORM 4283)

AGENCY/INST.: FT. JONES FACILITY NO: 00068
BLDG NO./SEC: 68 G BLDG NAME: TROOP TRAINING
BLDG USE: CLASSROOM TRAINING INSPECTION DATE: MAY/1987

MEMBRANE:

AREA (SF): 16800 AGE (YRS): 9 DECK TYPE: CONCRETE STD Cast-In-Pl EST. REPLACE COST: \$ 88200.00 BUR: Asphalt AGG.: Crushed Stone LAMINATED FELTS SURFACING: VAPOR RET: INSULATION: PERLITE POLYURETHANE

CORRECTIVE ACTION RECOMMENDED: Total replacement of roof in 1987

JUSTIFICATION: An economic analysis of the roof condition, including age, indicates that it is more cost effective to totally replace the roofing system, rather than perform the necessary maintenance, repair, and/or partial replacement of the roofing system.

DESIGN CONSIDERATIONS: The following considerations should be addressed during the design and construction phases of the replacement system:

- pe replacement systems could include bituminous built-up membrane single-ply membrane, such as EPDM, PVC etc.. IF a ballasted system is selected, determine if the structural components can sustain the added weight (approx. 10 lbs/SF).
- b. Ensure that the roof has positive drainage slope of at least 1/4 inch per foot. Correct all areas that now contain ponded water.
- c. Remove all unnecessary roof mounted equipment.
- d. Inspect and repair or replace, as necessary, all remaining roof mounted equipment.
- e. Ensure that all roof mounted equipment and penetrations are properly installed on the roof.
- f. Until the replacement roof is installed, accomplish temporary repairs to ensure that the roof remains leak free.

Figure 29. Corrective Actions Requirement Sheet for replacement.

6 SUMMARY AND RECOMMENDATION

Summary

This report has presented ROOFER, an engineered management system for built-up roofs. The system includes procedures for collecting and managing inventory information, visual inspection and condition evaluation of the membrane and flashing, roof moisture detection and condition evaluation of the insulation, overall roof condition rating, and determination of MRR needs.

The overall roof condition rating procedure is based on the Roof Condition Index. The RCI is composed of three separate condition indexes for the membrane, flashing, and insulation (MCI, FCI, and ICI). These indexes have been field-validated and provide a means of establishing MRR requirements and justification of roof projects. This report has presented ROOFER as a manual system, but as part of this work unit, USACERL has automated the system for a microcomputer application. The automated version improves data storage and retrieval, eliminates calculations, and provides custom designed reports for management use.

Methods of Developing and Collecting Data

The development and collection of data for implementing and maintaining ROOFER at the installation can be accomplished by using one or a combination of the following methods:

- In-house resources, using permanent or a combination of permanent and temporary personnel, supported by USAEHSC.
- Local A/E firm, supported by USAEHSC.
- Indefinite Delivery Type Contract (IDTC), managed by USAEHSC.

Methods of Accomplishing Nondestructive Roof Moisture Surveys

The nondestructive roof moisture surveys outlined in Chapter 4 can be accomplished through one of the following methods:

- Local firms specializing in conducting rooftop surveys using IR scans or nuclear or capacitance moisture meters.
- Aerial IR roof scans accomplished by:
 - direct contract with a firm that specializes in aerial scans
 - IDTC contract managed by USAEHSC
 - USAEHSC directly.

Project Management for Implementation of Roofer

USAEHSC is responsible for providing assistance for implementing and maintaining the ROOFER program at the installation and MACOM level.

Recommendation

It is recommended that Army installations implement ROOFER. The system can be maintained by in-house personnel or contracted to a qualified firm. Contract specifications for implementing ROOFER are available from the Department of the Army, U.S. Army Engineering and Housing Support Center (ATTN: CEHSC-FB-S), Fort Belvoir, VA 22060-5580.

Conversion Factors

1 sq ft = 0.093 m^2 1 in. = 2.54 cm1 ft = 0.305 m

CITED REFERENCES

- Shahin, M. Y., D. M. Bailey, and D. E. Brotherson, Membrane and Flashing Condition Indexes for Built-Up Roofs, Volume II: Inspection and Distress Manual, Technical Report M-87/13 (U. S. Army Construction Engineering Research Laboratory [USACERL], September 1987).
- Tobiasson, W., and Korhonen, C., *Roof Moisture Surveys: Yesterday, Today and Tomorrow*, CRREL Miscellaneous Paper 2040 (U.S. Army Cold Regions Research and Engineering Laboratory [CRREL], September 1985).
- Tobiasson, W., Aerial Roof Moisture Surveys, CRREL Miscellaneous Paper 2022 (August 1985);
- Tobiasson, W., A Method for Conducting Airborn Infrared Roof Moisture Surveys, CRREL Miscellaneous Paper 2436 (CRREL, April 1988).
- Technical Manual (TM) 5-617, Facilities Engineering Maintenance and Repair of Roofs (Department of the Army, January 1974).

UNCITED REFERENCES

- Air Force Manual (AFM) 91-36, Built-Up Roof Management Program (U. S. Air Force, 3 September 1980).
- Griffin, C. W. Manual of Built-Up Roof Systems, 2nd Edition (McGraw Hill Book Company, 1982).
- Knehans, A., S. Bunch, and J. Mose, *Roofing Systems Analysis*, Brochure (U.S. Army Facilities Er gineering Support Agency, December 1985).
- Shahin, M. Y., M. I. Darter, and S. D. Kohn, *Development of Pavement Maintenance and Management System, Volume 1: Airfield Pavement Condition Rating*, Technical Report No. AFCEC-TR-76-27 (U.S. Air Force Civil Engineering Center, November 1976), pp 32, 37.
- Shahin, M. Y. and S. D. Kohn, *Pavement Maintenance Management for Roads and Parking Lots*, Technical Report M-294 (USACERL, October 1981).

APPENDIX A:

BLANK WORKSHEETS

BUILDING IDENTIFICATION	AGENCYЛN	ST. NO.:
DATE:/_/	AGENCY/INST.:	
BUILDING NAME:		
BUILDING NUMBER:	DESIGN CATEGORY CODE	
TYPE CONST.	FACILITY NUMBER	1 1 1 1 1
LOCATION:		
USE:	YEAR B	UILT:
ROOF SECTIONS:		
A SF	FSF	KSF
8SF	G SF	LSF
c sr	H SF	MSF
D SF	ISF	NSF
ESF	JSF	OSF
REMARKS:		
ł		,
	BUILDING ROOF PLAN	SCALE.
	MOLLDING KOOF PLAN	SCALE:

^{&#}x27;These forms have been slightly reduced.

ROOF SECTION IDENTIF	TCATION			AGENCY/INST.:				
DATE:/	BLDG NO:		SECTIO	ON ID:	AREA:	SF		
OCCUPANCY:		YEAR ORIG	CONST	Γ:	YEAR LAST REPLACED:			
10 GENERAL								
11 PERIMETER:					12 ACCESS:			
PARAPET ROOF EDGE EXP. JOINT	LF LF LF	AREA DIN ADJ. WAI OTHER		LF LF LF				
20 STRUCTURAL FRAME								
21 TYPE:								
30 ROOF DECK								
31 TYPE:								
32 DESIGN LOAD:	_	33 SLOPE:			34 DRAINAGE:			
LIVE DEAD	PSF PSF			IN 12				
40 VAPOR RETARDER								
41 TYPE:								
50 INSULATION								
51 TYPE:								
52 PHYSICAL PROPERTI		D STOCK	FILLS	•	53 R-VALUE:			
THICKNESS (in.) NO. OF LAYERS TAPERED				· 	54 ATTACHMENT:			
60 MEMBRANE								
61 PRODUCT: MANUFACTURER				PROTECTED ME	EMBRANE (Y/N)			
SPECIFCATION NO.				WARRANTY (Y/N) EXP. DATE				
62 TYPE:		63 ATTACH	MENT:		64 REINFORCEMENT:			
65 SURFACING:		66 WALKW	AYS:					
70 FLASHING								
71 BASE FLASHING:		72 FLASHIN	G ADHI	ESIVE:	73 COUNTERFLASHING:			
74 FLASHING TYPES:	1			************	1			
80 REMARKS:		 						

ROOF SECTION IDENTI	FICATION W	VORKSHEET	AGENCY/INST.:		
DATE:/	BLDG NO:	SECTION	N ID:	AREA:	SF
OCCUPANCY:	1	YEAR ORIG CONST:		YEAR LAST REPLACED:	
10 GENERAL					
11 PERIMETER:					
PARAPET	LF	EXP. JOINT	LF	ADJ. WALL	LF
ROOF EDGE	LF	AREA DIVIDER	LF	OTHER	LF
12 ACCESS (check one):					
INTERNAL LADDER Permanent Temporary		EXTERNAL LADDER Permanent Temporary	I	PENTHOUSE ACCESSED FROM ADJACENT ROOF SECT (Sec. ID)	
20 STRUCTURAL FRAM	E				
21 TYPE (check one):					
STEEL Beams, Girders, Cols. Long Sp Deck, Beams Trussee Bar Joists With Beams and Cols. Bar Joists With Beanng Walls Bar Joists With Combination		CONCRETI Beams Flat Slab WOOD Laminated Trusses Joists Panels		SPECIAL Dome Space Frame UNKNOWN	
30 ROOF DECK					
31 TYPE (check one): NSTEEL CONCRETE, STD.	IONCOMBUSTIBI	CONCRETE, L.W. Precast Cast-in-Place		COMBUSTIBLE WOOD BOARDS PLYWOOD	
Precast Cast-In-Place GYPSUM Fiberboard Form Fiberglass Form Gypsum Form Precast		Vermiculite Cellular Perlite CEMENT FIBER Bulb-Tees Clipped		WOOD FIBER	
32 DESIGN LOAD:	LIVE	PSF			
	DEAD	PSF	_ UNKNOWN	J	
33 SLOPE:	IN 12				
34 DRAINAGE (check all)		ADJACENT	ROOF SECTION		
_ INTERIOR DRAINS			W/LEADERS AND D	OWNSPOUTS	
GUTTERS & DOWNSPOU	JTS	OVERFLOY	V SCUPPERS		
SCUPPERS		ROOF EDGI			
40 VAPOR RETARDER					
41 TYPE (check one):					
_ NONE		COATED ROL	L ROOFING	PVC	
ALUMINUM FOIL		LAMINATED A	ASPH/KRAFT	VINYL	
_ POLYETHYLENE		LAMINATED F	FELTS	UNKNOWN	

50 INSULATION			والمراكل الأواف المراجع	
51 TYPE (check all):	EXTRUDED POLYST	۲.	INSULATING FILLS	
NONE	FOAMGLASS	-	Vermiculite Perlite	l
WOOD FIBERBOARD	PHENOLIC	- -	Cellular Gypsum	
GLASS FIBER	POLYISOCYANURATI	E .	Lwt. Concrete Fill Type Unknown	
PERLITE	CORK		_ UNKNOWN	
POLYURETHANE/BOARD	FOAMED IN PLACE/P	UF		
EXPANDED POLYSTY.				
52 PHYSICAL PROPERTIES:	N/A (No in	isul.)		
BOARD STOCK		FOAMED IN PLACE	AND INS. FILLS	
TOTAL THICKNESS	INCHES	TOTAL THICKNES	s inches	
NO. OF LAYERS		TAPERED	(Y/N)	ì
TAPERED	(Y/N)			
53 R-VALUE (total):		_ UNKNOWN	N/A (No Insul.)	
54 ATTACHMENT (board stock on	y)(check all):			
MECHANICAL	ADHESIVE-HOT		_UNKNOWN	
_ LOOSE LAID	ADHESIVE-COLD			
60 MEMBRANE				
61 PRODUCT:	JNKNOWN	PROTECTED MEME	BRANE (Y/N)	
MANUFACTURER		DESCRIPTION		
SPECIFICATION NO.		WARRANTY(Y	/N) EXP DATE	
62 TYPE (check one):	ROLL ROOFING		LIQUID APPLIED	
BIT. BUILT-UP	Org./Min. Surface Glass/Min. Surface		Neoprene/Hypalon Acrylic Elastomer	
Asphalt Coal Tar Pitch	Smooth		Butyl Polysulfide	
Cold Process\ Emulsion	SINGLE-PLY EPDM		Urethane Silicone	
Cold Process\	CPE		Silicone Type Unknown	ĺ
Cutback Bit. Type Unknown	- CSPE PIB		PUF WITH COATING	
	_ PVC		Silicone	
MODIFIED BITUMEN SBS	Butyl Neoprene		Urethane Catal. Urethane	
APP	Nitrile		Acrylic	
Modifier Unknown	Type Unknown		Coating Unknown	
63 ATTACHMENT (for Single-Ply o	nly)(check one):			
FULLY ADHERED	PLATE/DISK/PARTIAL	LY ADHERED		
LOOSE/BALLASTED	MECH. FASTENERS Penetrating NonPenetrating			
64 REINFORCEMENT (check one):		MODIFIED BITUMEN &	SINGLE-PLY	
BIT. BUILT-UP	-	_ Polyester, Woven Polyester, Nonwoven		
Organic Felt	Ξ	_ Glass		
Glass Felt	-	Asbestos		
Achaetae Falt	-			•
Asbestos Felt Felt Type Unknown	-	Fleece, Synthetic Felt		
		Fleece, Synthetic Felt Laminate Backer		
	=======================================	Fleece, Synthetic Felt	n	

65 SURFACING (check one):		
AGGREGATE River Gravel Crushed Stone Slag Pea Gravel Volcanic Rock Marble Chip Limestone Aluminum Granule Mineral Granule	SMOOTH Cutback Emulsion Hot Asphalt Bit. Type Unknown REFLECTIVE ELASTOMERIC	MINERAL SURF. CAPLATEX COATING PAVERS Concrete Composite OTHER NONE
Agg. Unknown	METAL SKIN	
66 WALKWAYS (check all):		RUBBER MAT
ASPHALT PLANK	WOOD DUCK BOARDS	OTHER
CONCRETE PAVERS	MINERAL SURFACED FELTS	NONE
70 FLASHING		
71 BASE FLASHING (check all):		
MINERAL SURFACED Organic Glass Fabric Unknown REINFORCED ASBESTOS FIBERGLASS COTTON	MODIFIED BITUMEN Granule Surface Foil Surface Smooth Surface VINYL PVC NEOPRENE	PVC COVERED METAL METAL CPE CSPE NONE UNKNOWN
BURLAP	EPDM	
72 FLASHING ADHESIVE (check one):		
HOT MOPPED	TORCH APPLIED	
COLD MASTIC	UNKNOWN	
73 COUNTERFLASHING (check all):		
METAL	FLEXIBLE	
BITUMINOUS	NONE	
74 FLASHING TYPES (check all):		
ROOF EDGE Embedded Edge Met Metal Cap FlashWALL/PARAPET	ROOF PENETRATION ROOF RELIEF VENT PLUMBING VENT	PITCH PAN PIPE SUPPORTS Wood Blocks Rollers
_COPING	EQUIPMENT SUPPORT Structural Frame	
AREA DIVIDER EXPANSION JOINT Metal Cover Flexible Cover	Curbs Conduit Wood Sleepers None (unflashed)	
80 REMARKS		

ROOF INSPECTION	N WORKSHEET	AGENCY/INST.:							
BUILDING	PER. I	FLASHING	LF	DATE	: [
SECTION	CURB	FLASHING	LF	NAME					
BF-BASE FLASH MC-METAL CAP EM-EMBEDD MET FP-FLASHED PEN	PP-PITCH PANS DR-DRAIN & SC BL-BLISTERS RG-RIDGES	SP-SPLITS HL-HOLES SR-SURF DET SL-SLIPPAGE	PA-PATCHING DV-DEBRIS & VEG EQ-EQ SUPPORT PD-PONDING) D	O I S	S E >	DEF	Q+ Y
						1			
						T	\top	<u> </u>	
					Γ				
					\vdash				
					\vdash	 			
						1			4
SCALE:						!	NOR	тн	

ROOF INSPECTION WORKSHEET - COMMENTS Circle response, i.e., Y = yes, N = no or U = unknown or INSTRUCTIONS: not observed. If Y (yes), circle the type of problem. A. EVALUATION OF INTERIOR CONDITIONS Y N U 1. Does the roof leak? Describe: 2. Are there water stains on: Y N U a. walls c. deck e. structural elements b. ceilings c. floor f. other: Y N U 3. Do structural elements show any of the following: a. cracks d. alteration g. physical damage b. splits e. rotting h. insect damage c. spalling f. settlement 1. other: 4. Does the underside of the deck show any of the following: Y N U Does the underside of the door B. EVALUATION OF EXTERIOR CONDITIONS 1. Do the exterior walls shown any of the following: Y N a. cracks c. spalling e. water stains b. rusting d. movement f. other: 2. Does the fascia or soffit show any of the following: Y N a. cracksb. rustingc. spallingd. peelingf. other: 3. Do the gutters or downspouts snow any of the following: Y N a. loose c. missing e. clogged b. damaged d. disconnect f. other: C. EVALUATION OF ROOFTOP CONDITIONS 1. Is there any unauthorized, unnecessary, or improperly Y N installed equipment on the roof? a. equipment c. antennas e. cables b. signs d. platforms f. other: 2. Do adjacent parapet walls show any of the following: Y N a. cracks c. cap cracked e. sealant b. spalling d. cap missing f. other: D. REMARKS:

ROOF SECTION RATING FORM							
BUILDING	SECTION		DATE	CALC. BY			
PER. FLASHING FT CURB FLASHING FT	FLASHING TOTAL	FT FT	AREASQFT	CHKD. BY			
	DRAIN & SCUPPER	MEMBRANE DISTRESS TYPES BL - BLISTERS RG - RIDGES RG - RIDGES PA - PATCHING SP - SPLITS DV - DEBRIS & VEG HL - HOLES EQ - EQU SUPPORTS SR* SURF DET PD - PONDING					
TYP SV QUANTITIES	TOT DEN DV	TYP SV	QUANTITIES TO	T DEN DV			
		∦					
		▋ ┃					
		▋ ╟──├─					
		∄					
		4		_ _			
	 	┨ ┠──┼─					
		┨ ┠──┼─					
		∦					
		┨ ┠──┼─					
		┨╟──┼─					
		╢╟╌┼╌		_}			
		┨╏					
		┨╟─┼─					
		┨╟╼╌┼─					
	 	╢╟─┼─		_			
CORRECTED DEDUCT VALUE (CDV	/)	CORRECT	TED DEDUCT VALUE (CDV)				
FCI = 100 - CDV = FLASHING RATING =	I	MCI =	100 - CDV =				

ICI CALCULATION SHEET AGENCY/INST.:						ſ.:							
DATE: _/_/ BLDG. NO.: SEC							TION: AREA: SF						
MC C	ALC. B	Y:				ISF &	ISF & ICI CALC. BY:						
1. DETERMINATION OF MOISTURE CONTENT AND INDIVIDUAL ISF OF CORE SAMPLES													
CORE	INSULAT		тніск	A TARE WT	B WET+ TARE	C DRY+ TARE	D WET (B-A)	DRY (C-A)	F WATER (D-E)	%WATER (F/E) X 100	ISF		
	 		 		 -			ļ	<u> </u>	-	-		
<u> </u>			 		 	ļ	 						
 -			 			<u> </u>		 			 		
					 		 	1	1				
2. DE	TERMI	NATION (OF AVER	AGE ISF		3. DE	3. DETERMINATION OF ICI						
CORE ISF WET AREA (A) (B)			(A) 2	X (B)	1	PROBLEM DENSITY: (TOTAL WET AREA / TOTAL AREA) X 100							
									2 1, 1				
						IDV:			 -				
				+	<u> </u>	WAF:							
						ICI:				_			
						100 - [(IDV + WAF)	X AVERAGE	ISF]				
TOTALS (C) (D)							BATWS.						
AVERAGE ISF (DV(C)							RATING:						
DETERMINE THE ISF FOR EACH COMPONENT OF COMPOSITE INSULATION; FOR EACH CORE USE THE LARGEST ISF WHEN DETERMINING THE AVERAGE ISF.													
2. DO NOT INCLUDE ANY AREAS THAT HAVE AN ISF OF ZERO													
3. ROUND ICI TO NEAREST WHOLE NUMBER.							INSULATION CONDITION RATING						
WET AREA FACTOR (WAF)							INSULATION CONDITION RATING						
WET AREAS WAF					{{		86 - 100	EXCEI	LENT				
2			•	4				71 - 8	5 VERY	GOOD			
3 6			6		- 1		56 - 7	o GOOD					
4 8			3				41 - 5	5 FAIR					
5 OR MORE 10				0		1		26 - 4	0 POOR				
)			5 VERY				
								0 - 1	O FAILE	J			

RCI CALCULATION SHEET					AGENCY/INST.:							
DATE:/ BLDG NO:				SECTION ID:			AREA:		SF			
ROOF SECTION WITH INSULATION:												
				ſ	VALUE		LOWEST	OTHER	3			
			МС									
			FCI									
			ICI									
					TOTAL							
							X 0.70	X 0.1	5			
							(A)	(8)				
							(A+B)					
							RCI	<u> </u>				
			RATI!	NG.								
		•		٠٠.								
												
	ROOF SECTION V	WITH)UT I	NSU	LATION:							
				ſ	VALUE		LOWEST	OTHER				
			мс	, -				1				
			FCI									
					TOTAL		 	<u> </u>	 			
				ι			X 0.70	X 0.3	10			
							(A)	(B)				
							(A+B)	 				
							RCI	İ				
							L	<u> </u>				
		E	RATI	NG:								
MRR RECOMMENDATIONS												
		86	- 10	00	RC	UTIN	E MAINTENANC	Ε				
71 - 85 MINOR REPAIRS NE							REPAIRS NEED!	ED				
56 - 70 MODERA						ATE REPAIRS N	EEDED					
41 - 56 MAJOR REPAIRS NEEDED												
26 - 40 REPLACE						EMENT PROBA	BLE					
11 - 25 RE					PLAC	EMENT NEEDE	D					
		0	- 1	0	RE	PLAC	EMENT CRITICA	AL				


APPENDIX B:


TEST TO DETERMINE BITUMEN TYPE


- 1. Obtain a small specimen of the roofing bitumen from the top pouring. The sample should be as clean as possible with uncontaminated surfaces exposed.
- 2. Place sample in a glass jar containing mineral spirits, gasoline or other petroleum based solvent.
- 3. Mix or shake the jar for bout 20 seconds.
- 4. If the solvent turns black or is not transparent, the bitumen is asphalt.
- 5. If the solvent turns yellow or yellow-green, the bitumen is coal-tar pitch.
- 6. Test felt samples in a similar manner using several small torn pieces of felt.


APPENDIX C:


DEDUCT VALUE CURVES






















Corrected deduct values for flashing.





























Corrected deduct values for membrane.

USACERL DISTRIBUTION

Chief of Figureers FORSCOM ATTN: CEIM-SL (2) FORSCOM Engineer, ATTN: Spt Det. ATTN: CECC-P ATTN: Facilities Engineer (27) ATTN: CECW ATTN: CECW-O ATTN: CECW-P ATTN: CECW-RR Ft. Sam Houston AMC 78234 ATTN: HSLO-F ATTN: CECW-R ATTN: CEMP-C Fitzsimons AMC 80045 ATTN: HSHG-DEH ATTN CEMP-E ATTN CERD Walter Reed AMC 20307 ATTN: Facilities Engineer ATTAN CERD4 ATIN CERD-C AITN CERD-M INSCOM - Ch, Instl. Div. Arlington Hall Station (4) 22212 ATTN: CERM ATTN: DAEN-ZCE ATTN: Facilities Engineer Vint Hill Farms Station 22186 ATTN: DAEN-ZCI ATTN: DAEN-ZCM ATTN: IAV-DEIL ATTN: DAEN-ZCZ USA AMCCOM 61299 ATTN: AMSMC-RI ATTN: AMSMC-IS CEHSC ATTN: CEHSC-ZC 22060 ATTN DET III 79906 ATTN: CEHSC-F 22060 ATTN: CEHSC-TF 22060 Military Dist of Washington ATTN: DEH ATTN Canadian Liaison Officer 65473 Cameron Station (3) 22314 ATTN: German Liaison Staff 65473 Fort Lesley I. McNair 20319 Fort Myer 22211 ATTN. French Liaison Officer 65473 ATTN Water Resources Center 22060 Military Traffic Mgmt Command US Army Engineer Districts Falls Church 20315 ATIN: Library (41) Oakland Army Base 94626 Bayonne 07002 US Anny Engi Divisions Sunny Point MOT 28461 AITN Library (14) NARADCOM, ATTN: DRDNA-F 01760 US Army Europe ODCS/Engineer 09403 TARCOM, Fac, Div. 48090 ATTN: AEAEN FE ATTN: AEAEN TRADOC V Corps ATTN DEIL (11) HQ, TRADOC, ATTN: ATEN-DEH 23651 ATTN: DEII (18) VII Corps ATTN DEII (16) TSARCOM, ATTN: STSAS-F 63120 21st Support Command ATTN DEH (12) USAIS USA Berlin Fort Huachuca 85613 ATTN: Facilities Engineer (3) ATTN DEH (9) Allied Command Europe (ACE) Fort Ritchie 21719 ATIN ACSGEB 09011 ATIN SHIHB/Engineer 09055 WESTCOM ATTN AEUES 09081 Fort Shafter 96858 USASETAF ATTN: DEH ATTN AESE/EN D 09019 ATTN: APEN-A 8th USA, Korea (19) SHAPE 09055 ATTN: Survivability Sect. CCB-OPS ROKA S Combined Forces Cmd 96301 ATTN: Infrastructure Branch, LANDA ATTN EUSA HHC CFC/Engr HQ USEUCOM 09128 UNA Japan (USARI) ATIN DOSEN 96343 ATIN bacilities Engr Honshii 96343 ATTN: ECJ 47: LOE Fort Belvoir, VA 22060 ATTA DEH Okinawa 96331 ATTN: British Liaison Officer ATTN: Australian Liaison Officer Area Engineer, AEDC Area Office ATTN: Engr Studies Center ATTN: Engr Topographic Lab ATTN: ATZA TE SW ATTN: STRBE-BLURE Arnold Air Lorce Station, TN 37389 1969; Engineer Command, 60623. ATTS Likelities Engineer ATIN CECC R US Military Academy 10966 CECRL, ATTN: Library 03755 ATTN Facilities Engineer ALIN Dept of Geography & WES, ATTN: 1 ibrary 39180 Computer Science ATTN: MAEN-A HQ, XVIII Airbome Corps and Ft Bragg 28307 ATTN: AFZA-DEH-EE AMC Dir, Inst. & Svcs ATTS DEIL (23) Chanute AFB, II. 61868 DEA AITS DIA-WI 22304 3345 CES/DE, Stop 27

> Norton AFB, CA 92409 ATTN: AFRCE MX/DE

DNA ATTN: NADS 20305

Tyndall AFB, FL 32403
AFESC/Engineering & Service Lab

NAVFAC
ATTN: Division Offices (11)
ATTN: Facilities Engr Cmd (9)
ATTN: Naval Public Works Ctr (9)
ATTN: Naval Civil Engr Lab (3)
ATTN: Naval Constr Battalion Ctr

Engineering Societies Library
New York, NY 10017

National Guard Bureau 20310

Installation Division
US Government Printing Office 22304

Receiving/Depository Section (2)
US Army Env. Hygiene Agency
ATTN: HSHB-ME 21010

Nat'l Institute of Standards & Tech 20899

Defense Technical Info. Center 22314 ATTN: DDA (2)

> 321 12/89

EMC Team Distribution

20214	Far East 96301	Ft. Benning, GA 31905
Chief of Engineers 20314 APIN: CEMP ZA	ATTN: POFED-L	ATTN: ATZB-DEH-BG ATTN: ATZB-EH-E
ATTN: CEMP/ZM (2)	Portland 97208	WITE: WIND-PROF
ATTN: DAEN-ZCP	ATTN: Geotech Engr Br	Ft. Leavenworth, KS 66027
	ATTN: Chief, FM-1 ATTN: Chief, EN-DB-ST	ATTN: ATZLCA-SA
CEHSC CUIEC UP	Principle and the second	
ATIN: CEHSC-FB ATIN: CEHSC-FB-S	Seattle 98124	Ft. Lee, VA 23801 ATTN: AMXMC-D (2)
ATTN: CEHSC-FB-I	ATTN: Chief, NPSCO	ATTN: ASIAMOD (2)
	ATTN: Chief, NPSEN-FM	Ft. McPherson, GA 30330
L'S Army Engineer District	ATTN: CHief, EN-DB-ST Walla Walla 99362	ATTN: AFEN-CD
New York 10278	ATIN: Chief, Engr Div	
ATTN: Chief, Design Br Pittsburgh 15222	Alaska 99506	Ft. Monroe, VA 23651
ATTN: Chief, ORPCD	ATTN: NPAEN-G-M	ATTN: ATEN-AD ATTN: ATEN-FE-ME
AITN: Chief, Engr Div	Tto A Pasiuma Division	ATTN: ATEN-FN (2)
Philadelphia 19106	US Army Engineer Division New England 02154	
ATTN: Chief, NAPEN/D	ATTN: Chief, NEDED-T	Ft. Richardson, AK 99505
Baltimore 21:203 ATTN: Chief, Engr Div	ATTN: Laboratory	ATTN: AFVR-DE-E
Norfolk 23510	ATTN: Chief, NEDCD	Rocky Mountain Arsenal 80022
ATTN: Chief, NAOEN M	North Atlantic 10007	ATTN: SARRM-CO-ITEP
ATTN: Clincf, NAOEN D	ATTN: Chief, NADEN-T Middle East (Rear) 22601	
Huntington 25701	ATTN: Chief, MEDED-T	USAWES 39180
ATING Chief, ORHED G Wilmington 28401	South Atlantic	ATTN: C/Structures
ATTN. Chief, SAWEN-D	ATTN: Laboratory 30060	ATTN: Soils & Pavements Lab
Charleston 20402	ATTN: Chief, SADEN-TC 30303	Naval Facilities Engr Command 22332
ATIN Chief, Engr Div	ATTN: Chief, SADEN-TS 30303 Huntsville 35807	ATTN: Code 2003
Savannah 31402	ATTN: Chief, HNDED-CS	100 PT 200 PT 20
ATTN: Chief, SASAS-L Lecks (wille: 32232)	ATTN: Chief, HNDED-M	COMMANDER (CODE 2636) 93555
ALIN Constr Branch	ATTN: Chief, HNDED-SR	Naval Weapons Center
Mobile 36652	Lower Mississippi 39180	Little Rock AFB 72099
ATTN: Chief, SAMEN-D	ATTN: Chief, LMVED-G Ohio River	ATTN: 314/DEEE
ATTN: Chief, SAMEN C	ATTN: Laboratory 45227	
ATTN: Chief, SAMEN-C Nashville 37202	ATTN: Chief, Engr Div 45201	Building Research Board 20418
ATTN: Chief, ORNED-P	Missouri River	Dept of Transportation Library 20590
Memphis 38103	ATTN: Chief, MRDED-G 68101	pept of Transportation and a
ATIN: Chief, Constr Div	ATTN: Laboratory 68102 Southwestern 75202	Transportation Research Board 20418
ATTN: Chief, LMMED D	ATTN: Laboratory	·
Vicksburg 39180 ATTN: Chief, Engr Div	ATTN: Chief, SWDED-MA	
Louisville 40201	ATTN: Chief, SWDED-TG	109
AUN: Chief, Engr Div	South Pacific 94966	+1
D cont 48231	ATTN: Laboratory Pacific Ocean 96858	2.2/89
ATTN Chef, NChID T	ATTN. Chief, Engr Day	
St. Paul. 58401 ATIN Chief, ED-D	ATTN: FM&S Branch	
ATTN Chief, NCSLD GH	ATUN: PODED-D	
Reck Island 6.200	North Pacific ATTN: Materials Lab 97060	
ATIN Ch. I, NCRID G	ATTN: Chief, Engr Div 97208	
St. Leuis - 6 Vol - ATIN: Chief, ED D	11.11.	
Kansas City 64106	7th US Amiy (19407	
ATIN: Chief, Engr Div	ATTN: AETTM-DTT-MG-EH	
Omaha 68102	HQ, Combined Field Army (ROK/US)	
ATIN: Cho!, Engr Div	ATTN: CFAR-EN 96358	
New Orleans 70160 ATTN Chief, LMNI D-DG		
Line Rock (2001)	US Army Foreign Sci. & Tech Ctr	
ATTN Chief, high Div	ATTN: Charlottesville, VA 22901	
15 (Sa. 74) 21	ATTN Far East Office 96328	
ALIN, Chief, Engr Div	USA ARRADCOM 67801	
Fig. Worth 76.02 ATTN: Chief, SWFED-D	ATTN: DRDAR-LCA-OK	
Galveston		
AUTN Chief, SWGAS-L. 77553	HQ, USAMRDC 21701	
ATTN Chief, SWGCO C 77553	ATTN: SGRD-PLC	
ATTN: Chief, SWGED DC 77550 A!baquerque 87103	West Point, NY 10996	
ATIN Chief, Engr Div	ATTN: Dept of Mechanics	
Los Angeles 20053	ATTN: Labrary	
ATING Charl, SPLED-F	C. B.A. VA 2200	
San Transisco 94105	Fi Belvoir, VA 22060 ATTN: Learning Resources Center	
ATTN Chief, Engr Div Sacramento 98814	Attraction of the state of the	
ATTN Chief, SPKED D		
ALLN Chief, SPKCO C		