

REPORT DOCUMENT

AD-A237 103


Form Approved
OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information, including suggestions for reducing this burden. Send comments to Washington, DC 20503.

Instructions: Searching existing data sources, including the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, Washington, DC 20503.

1. AGENCY USE ONLY (Leave blank)		2. REPORT DATE 14 Aug 89		3. REPORT TYPE AND DATES COVERED Aug 88 - Aug 89	
4. TITLE AND SUBTITLE Technology Insertion (TI)/Industrial Process Improvement (IPI) Task Order No. 1 Data Base Documentation Book <u>WR-ALC/MANPGC (Directional Gyroscopic Repair)</u>				5. FUNDING NUMBERS Contract	
6. AUTHOR(S) McDonnell Douglas Missile Systems Company				8. PERFORMING ORGANIZATION REPORT NUMBER F33600-88-D-0567	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) McDonnell Douglas Missile Systems Company St. Louis, Missouri 63166				10. SPONSORING / MONITORING AGENCY REPORT NUMBER F33600-88-D-0567	
9. SPONSORING / MONITORING AGENCY NAME(S) AND ADDRESS(ES) HQ AFLC/LGME WPAFB OH 45433				11. SUPPLEMENTARY NOTES Prepared in cooperation with <u>WR-ALC & HQ AFLC</u>	
12a. DISTRIBUTION AVAILABILITY STATEMENT Distribution Statement A				12b. DISTRIBUTION CODE	
13. ABSTRACT (Maximum 200 words) Technology Insertion (TI)/Industrial Process Improvement (IPI) Data Base Documentation Book Volume, for <u>WR-ALC/MANPGC (Directional Gyroscopic Repair)</u> This document contains detailed information about layouts equipment and processes for this RCC.					
14. SUBJECT TERMS <u>MAINTENANCE DATA BASE, TECHNOLOGY INSERTION, PROCESS IMPROVEMENT, AIRCRAFT, MANPGC, GYROSCOPES, EQUIPMENT, AFLC, AF</u>				15. NUMBER OF PAGES <u>254</u>	
17. SECURITY CLASSIFICATION OF REPORT Unclassified				18. SECURITY CLASSIFICATION OF THIS PAGE Unclassified	
19. SECURITY CLASSIFICATION OF ABSTRACT Unclassified				20. LIMITATION OF ABSTRACT Unclassified	

DISCLAIMER NOTICE



THIS DOCUMENT IS BEST
QUALITY AVAILABLE. THE COPY
FURNISHED TO DTIC CONTAINED
A SIGNIFICANT NUMBER OF
PAGES WHICH DO NOT
REPRODUCE LEGIBLY.

**TECHNOLOGY INSERTION-ENGINEERING SERVICES
PROCESS CHARACTERIZATION
TASK ORDER NO. 1
(BLOCK 1)**


DATABASE DOCUMENTATION BOOK

WR-ALC

MANPGC

**CONTRACT SUMMARY REPORT
14 AUGUST 1989**

**CONTRACT NO. F33600-88-D-0567
CDRL SEQUENCE NO. B008**



MCDONNELL DOUGLAS
McDonnell Douglas Missile Systems Company
St. Louis, Missouri 63166-0516 (314) 232-0232

Distribution Statement A. Approved for public release
distribution is unlimited.

91 6 19 200

91-02790
XXXXXXXXXX

WR-ALC (MANPGC)

1.0 Identification of RCC

RCC MANPGC has been identified by the statement of work of the contract F33600-88-D-0567 for process characterization.

2.0 General Information

MANPGC is a Resource Control Center under the MANPG section of the Industrial Products Division (MAN) at WR-ALC. MANPGC is located in Building 158. The area is maintained as a 300,000 class clean room though clean room garb is not required. The primary workload is MISTR work. It consists of a variety of directional gyroscope systems and a number of fluid damped rate variety of directional gyroscope systems and a number of fluid damped rate and rate switching gyros. Most product in the area is a 1955 to 1965 design. The workload has been decreasing for some time due primarily to product age.

MANPGC will be discussed in more detail in the following Section 2.1 through 2.8.

2.1 Facility Layout Drawing

The accompanying facility drawing represents MANPGC's portion of Building 158. The RCC is spread into two locations in Building 158 and shares part of its prime area with MANPPC which has moved into the area in the last year. It is not maintained consistent with clean room practices.

2.2 Equipment

MANPGC equipment is mainly individual workbench stations, vacuum and circulating ovens, leak detecting stations, and many manual and semi-programmable test stands. Most of the tooling is standard precision hand tools furnished to the technical operators in complete kit sets. Each separate PCN model does require some special tooling but little is complex enough to require much concern in this study. The circulating and vacuum ovens are minor adaptations of standard units. The leak detection equipment are standard catalog items such as Veeco or Varian, then adapted to specific model gyros or families of gyros. The test sets and stands, except for the contraves rate test stations, are of an age consistent with the product design age. It is doubtful that it can be properly supported much longer.

2.3 Workforce

MANPGC has a stable workforce with little variance. The workforce is comprised of instrument mechanics, three supervisors, a clerk, and a senior supervisor. The following is a breakdown of the mechanics within MANPGC.

<u>Skill Code</u>	<u>Skill Level</u>	<u>Quantity</u>	<u>Experience</u>
WG 3359	G-10	1	25.0 yrs.
WG 3359	G-09	55	20.7 yrs.
WG 3359	G-07	10	7.6 yrs.
WG 7009	G-04	1	12.0 yrs.

It is to be noted that the workforce is shared between the gyro RCCs as workloads vary. A major concern is availability of trained instrument mechanics if increased workload was demanded. The age of the workforce should also be of a concern. Experience is very high but natural attrition is reducing the numbers faster than training is furnishing younger mechanics. Surge conditions would be gated by this constraint.

2.4 Repair Process Technologies

The repair process technologies within MANPGC consist of defining the malfunction causes of gyroscopes, repairing as required, and retesting to verify the completeness of the repair. The gyros are pretested to identify malfunctions, torn down and repaired as required to technical overhaul manuals. Repair is generally accomplished through replacement of worn and/or defective piece parts. The rebuild and acceptance testing is also directed by Technical Orders and test specifications. Some mandatory replacement of high failure items are directed by Technical Orders to extend MTBF. Precision bearing and miniature slip rings/brushes are examples of some 100% replacement parts.

2.5 Workload Volume and Mix


The workload within MANPGC consists of Management of Item Subject To Repair (MISTR) and exchangeables. MISTR represents greater than 98% of the workload. The RCC repairs and tests in excess of 6000 units annually.

2.6 Material Handling


Material handling in MANPGC is mostly accomplished by the repair operator hand carrying the items between stations. The gyroscopes are small, weighing from ounces to a few pounds. Units are repaired by a single mechanic rather than by line flow process. The one exception of this method is rotor repair, which are repaired in groups rather than one at a time. The repair is still accomplished by a mechanic, not a line, but an operation is completed on multi assemblies before moving to the next operation.

2.7 Storage

Storage is on line in MANPGC. It is accomplished on shelved hand trucks between aisles on the repair floor. The items for repair are received, logged in, and placed on the storage trucks for pretest. After pretest, the items are returned to the truck to wait the availability of a mechanic. The item is repaired and calibrated then returned to the truck or another truck for test and ship.



WR-ALC MANPGC PROCESS FLOW CHART
FIGURE



LEGEND:

MA = DIR. OF MAINT.
 MAN = INDUSTRIAL PRODUCTS DIVISION
 MANP = PRODUCTION BRANCH
 MANPG = GYRO SECTION
 MANPGA = GYRO REPAIR UNIT NO. 1
 MANPGB = GYRO REPAIR UNIT NO. 2
 MANPGC = GYRO REPAIR UNIT NO. 3

MANPS = SHEET METAL SECTION
 MANPSA = ADHESIVE BONDING UNIT
 MANPSB = SHEET METAL MANUFACTURING UNIT
 MANPSC = SHEET METAL REPAIR UNIT
 MANPSD = PLASTIC & MISC. SHEET METAL UNIT


LSC-20282


WR-ALC RCC PROCESS CHARACTERIZATION COVERAGE
FIGURE 9.0-1

A

B


B-168 WEST END






C

8074 SHE
10/10/50 10/10/50
10/10/50 10/10/50
10/10/50 10/10/50
10/10/50 10/10/50
10/10/50 10/10/50




B-158 WEST END

CHURCH STREET




MANITO



E

F



F

MANPG

WORKLOAD

INDEX

1. METHODOLOGY FOR WORKLOAD ANALYSIS
2. WORKLOAD BY RCC
3. FY88 WORKLOAD HISTORY
4. FY89 ANNUAL WORKLOAD & CAPABILITY
5. CONTROL PCNS / FAMILY PCNS

RSB 4/6/89

METHODOLOGY FOR MANPG WORKLOAD

ANALYSIS of 80/20

- a. Gyro Workload HAS BEEN DETERMINED TO BE 98% MSTR GENERATED. THEREFORE ONLY MSTR WORK WAS CONSIDERED
- b. ALL LIKE Gyro HOURS WERE GATHERED UNDER A CONTROL Gyro PON TO ESTABLISH FAMILIES of Gyros FOR CHARACTERIZATION
- c. TOTAL HOURS FOR EACH FAMILY of Gyros WAS OBTAINED FROM THE 31, OCT, 88 ISSUE of THE A-GO19C - CAA-CA-MCE REPORT, PAGE 2145 THEN 2212
- d. THE PON HOURS WERE SEPERATED BY RCC & COMPARED TO THE TOTAL HOURS FOR THE RCC TO VERIFY THE 80% WORKLOAD.

THE METHODOLOGY YIELDED THE RESULTS THAT THE PONs PICKED FOR CHARACTERIZATION REPRESENTED 84.5% OF MANPGA WORKLOAD, 78.5% OF MANPGB & 82.9% of MANPGC. A COMBINED CHARACTERIZATION OF 82.3% OF THE MANPG WORKLOAD

C/Ns INCLUDED IN MANPG STUDY

RCC		INCLUDED C/Ns	
CONTROL C/N			
MANPGA			
C/N 74074A		02006A	02007A 74076A 74073A
		74075A	
C/N 74010A		74002A	
C/N 74029A		74034A	74103A
C/N 74126A			
MANPGB			
C/N 20012A	Comp	04791A	20019A R6651A
		R6700A	30832A 30833A
		30834A	
C/N 74051A	Comp	01720A	02634A 03614A
		03620A	03621A 03641A
		03611A	03649A 74017A
		74035A	74043A 74044A
		74048A	74049A
MANPGC			
C/N 06121A	Comp	01970A	03696A 08023A
C/N 74061A	Comp	02387A	02382A 74065A
C/N 74063A	Comp	74000A	74053A 74058A
		74059A	74067A
C/N 74146A	Comp	74282A	
C/N 74148A	Comp		
C/N 74149A	Comp		
		P.D.U. 10/28	

MANPG Week Load

[STUDIED vs FORECAST]

RCC	CIN FAMILY	STUDIED HOURS	RCC HOURS	% OF RCC
MANPGA	C/N 74010A C/N 74074A C/N 74103A C/N 74126A	118,380	140,020	84.5%
<u>RCC TOTAL</u>				
MANPGB	C/N 20012A C/N 74051A	59,449	76,728	78.5%
<u>RCC TOTAL</u>				
MANPGC	C/N 06121A C/N 74061A C/N 74063A C/N 74146A C/N 74148A C/N 74149A	82,723	99,827	82.9%
<u>RCC TOTAL</u>				
<u>MANPG TOTAL</u>		260,552	316,575	82.3%

RCC 11/23/88

NG3

FY88

INDUSTRIAL PRODUCTS DIVISION
WORK LOAD HISTORY DPSH

MNPG

<u>WORK CAT</u>	<u>BOY NET AVAIL</u>	<u>FALLOUT</u>	<u>ADJ BOY NET AVAIL</u>	<u>YTD IND</u>	<u>TOTAL WKLD</u>	<u>YTD PROD</u>	<u>EOY NET AVAIL</u>
A/C	0	0	0	0	0	0	0
MISTR	24765	264	24501	266,656	291,157	256,856	34,301
EXCH	1666	111	1555	6,465	8,020	4,043	3,977
MFG	0	0	0	0	0	0	0
OTHER	8	0	8	635	643	639	4
DME	0	0	0	0	0	0	0
TOTAL	26439	375	26064	273,756	299,820	261,538	38,282

INPG089

FY89

INDUSTRIAL PRODUCTS DIVISION
ANNUAL WORKLOAD VS CAPABILITY DPSH

MNPG

WORK CAT	BOY MOS AVAIL	BOY NET AVAIL	NEG INPUT	TOTAL WKLD	BUDG CAP	EOY NET AVAIL	EOY MOS AVAIL
A/C	0	0	0	0	0	0	0
MISTR	2	34,301	281,292	315,593	210,147	105,446	6
EXCH	16	3,977	3,763	7,740	3,000	4,740	19
MFG	0	0	0	0	0	0	0
OTHER	0	0	0	0	0	0	0
DME	0	0	0	0	0	0	0
TOTAL	2.2	38,282	285,055	323,337	213,147	110,190	6.2

**	ALC - WR	RCC - MANPGC	MODEL WORKLOAD FILE				6/30/1989			
06121A		8119	0	4	149	149	149	16.40	8.50	1A
MULT	681.5	597.1		38		6.1537		0	.070	B
06121ASUB1		7167	50	4	0	0	0	.00	3.50	OA
		.0	.0		0	.0000		0	S	B
74061A		A8119	0	4	343	343	343	7.70	7.50	1A
MULT	81.6	119.9		239		3.9937		0	.142	B
74061ASUB1		A7167	50	4	0	0	0	.00	.70	OA
		.0	.0		0	.0000		0	S	B
74063A		B8119	0	4	244	244	244	9.60	7.60	1A
MULT	997.8	1768.0		192		6.1097		0	.102	B
74146A		8133	0	4	255	255	255	17.50	11.20	1A
MULT	248.3	96.4		105		5.4419		0	.158	B
74146ASUB1		7205	50	4	0	0	0	.00	3.00	OA
		456.3	331.5		169	5.9727		0	S	B
74148A		8271	0	4	175	175	175	28.90	25.50	1A
MULT	897.0	1094.9		316		6.1674		0	.247	B
74148ASUB1		A7205	50	4	0	0	0	.00	6.00	OA
		798.2	486.9		182	6.5126		0	S	B
74149A		C8119	0	4	169	169	169	12.90	9.30	1A
MULT	946.5	1689.9		208		6.0122		0	.087	B
74149ASUB1		6339	50	4	0	0	0	.00	5.50	OA
		.0	.0		0	.0000		0	S	B

(For Internal Use, Not a Model Input)

LSC-20098A

ITEM SUMMARY (For Internal Use, Not a Model Input)

NAME <u>REINFORCED</u> ALC <u>WR</u> DATE <u>4-11-89</u> RCC <u>MA/26C</u> SHEET <u>1</u> OF <u>1</u>					
ITEM NUMBER	WCD	WORKLOAD TYPE	HISTORICAL FLOW TIME	STANDARD HOURS	EXPECTED HOURS
PCN 06121A	N/A	MOTR	18 - 1200 hrs	16.37	11.6
PCN 74061A	N/A	MOTR	18 - 1200 hrs	7.71	8.6
PCN 74063A	N/A	MOTR	18 - 1200 hrs	9.55	9.0
PCN 74146A	N/A	MOTR	18 - 1200 hrs	17.50	16.7
PCN 74148A	N/A	MOTR	18 - 1200 hrs	28.94	30.0
PCN 74149A	N/A	MOTR	18 - 1200 hrs	12.97	13.5

NOTE: HISTORICAL FLOW TIME WILL BE GENERATED BY DATA PROCESSING. IF NO HISTORY IS COLLECTED ON WCD DATA COLLECTION SYSTEM, THIS INFORMATION MUST BE OBTAINED ON-SITE. EXPECTED HOURS WILL BE GENERATED FROM OPS. PROFILES BY DATA PROCESSING.

WORKLOAD PROFILE

NAME <u>John Anderson</u> ALC <u>VR</u> DATE <u>1/24/81</u> RCC <u>MAJPGC</u> SHEET <u>1</u> OF <u>1</u>		ACTUAL PRODUCTION BY QUARTER				FLOATHING STOCK	WORKLOAD TYPE	WCD	AIRCRAFT MODEL	NO. OF ENVELOPE UNITS	MAXIMUM W.P.	STANDARD HOURS
ITEM NUMBER	PCN	1	2	3	4							
06121A	PCN NSH PIN	149	149	149	149	None	MOTR	8119	MULT	1		16.37
74061A	PCN NSH PIN	343	343	343	343	1	MOTR	12819	MULT	1		7.71
74063A	PCN NSH PIN	244	244	244	244	1	MOTR	8819	MULT	1		9.08
74149A	PCN NSH PIN	169	169	169	169		MOTR	0819	MULT	1		12.96
74148A	PCN NSH PIN	175	175	175	175		MOTR	8271	MULT	1		28.93
74146A	PCN NSH PIN	255	255	255	255		MOTR	8133	MULT	1		17.47
06121A	PCN NSH PIN						MOTR	7167				
74061A	PCN NSH PIN						MOTR	17167				
74146A	PCN NSH PIN						MOTR	7205				
74148A	PCN NSH PIN						MOTR	17205				
74149A	PCN NSH PIN						MOTR	17205				
74149A	PCN NSH PIN					None	MOTR	6339				
	PCN NSH PIN											
	PCN NSH PIN											

DATASET: I7S150ED.ALC.WRMANPGC.WORKLD

DATE: 89/03/29
TIME: 07:22
PAGE: 1

START COL	1	2	3	4	5	6	7	8
	PART	WCD	INV	Q1- Q2- Q3- Q4-				
1	06121A	8119		149 149 149 149				
1	74061A	8119		343 343 343 343				
1	74063A	8119		244 244 244 244				
1	74149A	8119		169 169 169 169				
1	741148A	8271		175 175 175 175				
1	74148A	8133		255 255 255 255				
1	74061ASUB1	A7167	0					
1	06121ASUB1	7167	0					
1	74148ASUB1	7205	0					
1	74148ASUB1	A7205	0					
1	74149ASUB1	6339	0					

28 5
6 4
43 4
37 0
37 9
18 2
10 5
92 5
22 9
35 2
3 0

SA

MANPG WEEK LOAD		[STUDIED vs FORECAST]		5.0
RCC	C/N FAMILY	STUDIED HOURS	RCC HOURS	% OF RCC
MANPGA	C/N 74010A C/N 74074A C/N 74103A C/N 74126A	118,380	140,020	84.5%
<u>RCC TOTAL</u>				
MANPGB	C/N 20012A C/N 74051A	59,449	76,728	78.5%
<u>RCC TOTAL</u>				
MANPGC	C/N 06121A C/N 74061A C/N 74063A C/N 74146A C/N 74148A C/N 74149A	82,723	99,827	82.9%
<u>RCC TOTAL</u>				
<u>MANPG TOTAL</u>		260,552	316,575	82.3%

260 11/27/88

C/N₃ INCLUDED IN MANPG STUDY

RCC	CONTROL C/N	INCLUDED C/Ns	3.0
MANPGA			
C/N 74074A		02006A 02007A 74076A 74073A	
C/N 74010A		74075A	
C/N 74029A		74002A	
C/N 74126A		74034A 74103A	
MANPGB			
C/N 20012A	COMP	04791A 20019A 26651A	
		26700A 30832A 30833A	
		30834A	
C/N 74051A	COMP	01720A 02634A 03614A	
		03620A 03621A 03641A	
		03611A 03649A 74017A	
		74035A 74043A 74044A	
		74048A 74049A	
MANPGC			
C/N 06121A	COMP	01970A 03696A 08023A	
C/N 74061A	COMP	02387A 02382A 74065A	
C/N 74063A	COMP	74000A 74053A 74058A	
		74059A 74067A	
C/N 74146A	COMP	74282A	
C/N 74148A	COMP		
C/N 74149A	COMP		

P.S.V. 10/28

SAS

MANPOWER PROFILE

NAME: *Richard Board*

ALC: WR

DATE: *4-18-89*

RCC: MANPGC

SHEET *1* OF *1*

SK CODE	DESCRPTN QTR	QUANTITY AVAILABLE			AVAILABLE HRS (PER SHIFT)			HOLIDAY	ALTERNATE SKILL CD/LVL	NOTES
		1	2	3	WEEK 1	WEEK 2	WEEK 3			

IG07 1 10

IG07 4 10

IG09 1 54 1

IG09 4 54 1

IG10 1 1

IG10 4 1

EQUIPMENT FILE

NAME <u>P. VANCE</u> ALC <u>WLC</u> DATE <u>4-12-87</u> RCC <u>MARCO</u> SHEET <u>1</u> OF <u>5</u>															
EQUIPMENT CODE	EQUIPMENT TYPE/DESCRIPTION	QUANTITY PER SHIFT			PREVENTIVE MAINT.			DOWNTIME			PERCENT USED FOR OTHER RCCS (e.g. TIME NOT AVAILABLE)	ENVELOP UNITS		ALTERNATE EQUIPMENT CODE	SOURCE
		1st	2nd	3rd	FREQ.	SHIFT	DOWN TIME	UNPLANNED BREAKDOWN REPAIR TIME		MIN		MAX			
								MTBF	MTTR						
5925	DL254E2L2 KT519003	2	2	2	999	1st	1.0	999	76			1	1		Maesbach Paper
6849	204222E-- 7050R4	4	4	4	180	1st	10.5	180	83			2	4		Phil Barrett #16-1123
0844	201E2L2 KT519805	2	2	2	999	1st	1.9	999	77			1	1		William Whitte TE. Sample Valve
3346	2E222E2E2 2512, VES00	6	6	6	90	1st	16.6	90	89			1	1		PH #6-5713 Donnell Pate
0766	20492E1253 204E222E2	2	2	2	999	1st	13.5	999	86			1	1		PH #6-9098
5139	MACMINE IS-212E2E2	6	6	6	999	1st	10.5	999	83			1	20		Various operators Recomm. advised
9036	KT419805 204322E--	4	4	4	30	1st	3.0	30	75			1	0		Govt Reports UG 0041098
1022	704908-1 204322E--	2	2	2	180	1st	10.5	180	83			1	1		Bar-log #12 cm) 7118
0450	705B30 ELMBA-13	2	2	2	180	1st	13.5	180	86			1	2		Good AMCOOP
4126	KT426206 14344IE2L	2	2	2	270	1st	5.1	270	78			1	1		
9050	KT426598 2E2C1L2R	2	2	2	999	1st	5.0	999	77			1	1		
9103	KT436215	1	1	1	270	1st	5.1	270	78			1	1		

LSC-210941B

EQUIPMENT FILE

NAME <u>ELANDER</u> ALC <u>VR</u>		DATE <u>4-17-89</u>		RCC <u>MANUSC</u>		SHEET <u>2</u> OF <u>5</u>								
EQUIPMENT CODE	EQUIPMENT TYPE/DESCRIPTION	QUANTITY PER SHIFT			PREVENTIVE MAINT.		DOWNTIME			PERCENT USED FOR OTHER RCCS (i.e. TIME NOT AVAILABLE)	ENVELOP UNITS		ALTERNATE EQUIPMENT CODE	SOURCE
		1st	2nd	3rd	FREQ.	SHIFT	DOWN TIME	BREAKDOWN MTBF	UNSCHEDULED REPAIR TIME		MIN	MAX		
8437	BEZ504IZ - KT4R6R14	2	2	2	120	1st	5.1	120	78		1	1		
1872	AL444-IE4I KT4R6R13	2	2	2	162	1st	1.0	999	76		1	1		
9096	PWR54R-IZ KT4R6R10	2	2	2	999	1st	1.0	999	76		1	1		
9782	IE2IPG4R2 KT4R6R09	1	1	1	999	1st	5.1	999	78		1	1		
1336	FL444IZ4R	1	1	1	162	1st	N/A	300	72		1	4		
9058	IE2IPANFL KT4R6R16	2	2	2	90	1st	3.0	90	15		1	1		
9015	GL4R2-IZ4I KT4R6R19	4	4	4	90	1st	1.0	90	76		1	5		
9073	IE4R-CH44 TEN54/VR	4	4	4	162	1st	0	0	0		1	4		
6183	IE2I-2244 KT3291	3	3	3	300	1st	4.9	300	77		1	1		
0787	IE2I-2244 7439R38	5	5	5	999	1st	5.1	999	78		1	1		
5509	22IZ-IE4I M10117	4	4	4	162	1st	1.9	999	77		1	1		
0001	CL444-2444	12	12	12	162	1st	5.1	300	50		3	8		

LSC-20004B

EQUIPMENT PROGRAM E

NAME <u>R. VANDER KOOIJ ALC</u>		DATE <u>1-19-81</u>		RCC <u>MANREC</u>		SHEET <u>3</u> OF <u>5</u>									
EQUIPMENT CODE	EQUIPMENT TYPE/DESCRIPTION	QUANTITY PER SHIFT			PREVENTIVE MAINT.			DOWNTIME			PERCENT USED FOR OTHER RCCS (e.g. TIME NOT AVAILABLE)	ENVELOP UNITS		ALTERNATE EQUIPMENT CODE	SOURCE
		1st	2nd	3rd	FREQ.	SHIFT	DOWN TIME	UNSCHEDULED BREAKDOWN REPAIR TIME		MIN		MAX			
								MTBF	MTTR						
0002	VAC-OVEN	12	12	12	100				300	172		1	8		
0003	LAM-FLAW-HECK STATION	20	20	20	100	1st	5.0		999	77		N/A			
0004	PL-BEETH	1	1	1	100				300	120		1	1		
0005	LAMP-FLAW-HECK TAYLOR WINDFIELD	1	1	1	100							1	1		
0006	RE-FLAW-HECK BELL LAB CHAMBER	1	1	1	100				300	172		1	4		
0007	RE-FLAW-HECK DIRECTIONAL	1	1	1	100				300	72		1	18		
0008	RE-FLAW-HECK	2	2	2	100				300	72		1	18		
0009	RE-FLAW-HECK RATES	3	3	3	100				300	172		1	18		
0010	12" B-LAW-HECK BELL LAB & METAFOLD	1	1	1	100				300	72		1	4		
9020	24" B-LAW-HECK KT419001	2	2	2	100	1st	3.0		100	1/5		1	1		
9021	N-LAW-HECK KT419807	2	2	2	200	1st	3.0		100	1/5		1	1		
9411	RE-FLAW-HECK KT419182	2	2	2	100	1st	5.1		999	18		1	1		

EQUIPMENT FILE

[illegible]

EQUIPMENT 'FILE'

NAME <u>Phalover</u> ALC <u>WR</u> DATE <u>1-14-89</u> RCC <u>MANAGC</u> SHEET <u>5</u> OF <u>5</u>		EQUIPMENT TYPE/DESCRIPTION		QUANTITY PER SHFT			DOWNTIME				PERCENT USED FOR OTHER RCCs (e.g. TIME NOT AVAILABLE)	ENVELOP UNITS		ALTERNATE EQUIPMENT CODE	SOURCE
EQUIPMENT CODE		1st	2nd	3rd	FREQ	SHIFT	DOWN TIME	UNPLANNED BREAKDOWN REPAIR TIME		MIN		MAX			
7250	IE22222222 317K 19621	1	1	1	12	1st	5.1		180		1	1			
3200	EC22222222 R366266	5	5	5	12	1st	7.3		999		1	1			
7648	IE22222222 704907-1	13	13	13	180	1st	5.1		180		1	1			

WORK CONTROL DOCUMENT					1. DATE 8119		PAGE 1 OF 2 PAGES		
JOB ORDER NUMBER 01970A/06121A		3. QUANTITY 1		4. PRODUCTION SECTION/RCC "O" MNP GC		5. DATE SCHED		6. DATE COMP	
PART NUMBER GG2479AB01			8. TECH DATA 5F10-4-5-53; 5F10-4-5-53-1			9. ITEM SERIAL NUMBER			
10. MODEL - DESIGN - SERIES		11. STOCK NUMBER 6615-00-137-6038 6615-01-006-0050		12. OPTIONAL NOTE: Use QQ-571 type SN60WRP solder and anticorrosive flux MIL-F-14256. Observe all notes, cautions & warnings throughout TO. MDC data required IAW MAOI 66-22.					
13. SERIAL NUMBER		14. NOUN Rate Gyroscope							
15. DISPATCH STATION	16. PDM/OP NO.	17. WORK TO BE ACCOMPLISHED				18. MECHANIC	19. "P"	20. "Q"	
	010	Receive and clean gyro. Ascertain data correctness on forms AFLC 959 and AFTO 349.							
	020 0100	Perform functional analysis. If serviceable, stamp condition tag and proceed to Step 160.						B	
	020 0200 MNPGB	Perform functional analysis. If serviceable, stamp condition tag and proceed to Step 160.						B	
	030	Disassemble only to extent required to repair or replace the faulty parts (TO 5F10-4-5-53, Section III)							
	040	Clean gyro (TO 5F10-4-5-53, Section IV)							
	050	Take rotor and bearing assembly to repair area. See attached Work Control Document.							
	060	Mechanical null and balance adjustments. (TO 5F10-4-5-53, Section VI)							
	070	Temperature cycle (four hours) (TO 5F10-4-5-53, Section VI)							
	080	Complete drift, stop adjustment, and performance checks (TO 5F10-4-5-53, Section VI)							
	090	Clean and cement printed wiring board to gyro. (TO 5F10-4-5-53, Section VI)							
21. FINAL DESTINATION		22. COORDINATION/INITIATING RCC SIGNATURE/DATE				23. DOCUMENT S/N			
DISPATCH	FUNCTIONAL CODE	a. MANPGC MANPGB		c. MAQNG					
		b. MANERG		d. MANSAA					

1. DATE 8119

1. DATE 8119

PAGE 2 OF 2 PAGES

[illegible]

WORK CONTROL DOCUMENT

1. DAY
7167

PAGE 3 OF 4 PAGES

01970A/06121A
02386A

3. QUANTITY

1

4. PRODUCTION SECTION/RCC

"O" MNPCC/MNPGR

5. DATE SCHED

6. DATE COMP

7. PART NUMBER

10063458-102

8. TECH DATA

5F10-4-5-53

9. ITEM SERIAL NUMBER

10. MODEL-DESIGN-SERIES

TRU-2A/2

11. STOCK NUMBER

6615-01-092-7096

12. OPTIONAL

13. SERIAL NUMBER

14. NOUN

Rotor & Bearing Assy

15. DISPATCH STATION

16. PON/OP NO.

17. WORK TO BE ACCOMPLISHED

18. MECHANIC

19. "P"

20. "Q"

05a
10-40

Remove ball bearing form the rotor and ring assembly (TO 5F10-4-5-53, Section V).

05b
10-40

Assemble a new bearing or bearings into the rotor and ring assembly (TO 5F10-4-5-53, Section V).

05c
10-40

Place assembly in Balance Machine and dynamic balance (TO 5F10-4-5-53, Section V)

05d
10-40

Install spinmotor wound stator (TO 5F10-4-5-53, Section VI)

05e
10-40

Install header, primary and secondary coil winding assemblies, and gimbal stop capscrews (TO 5F10-4-5-53, Section VI)

05f
10-40

Install gyro electronic assemblies (TO 5F10-4-5-53, Section VI).

05g
10-40

Install damper assembly (TO 5F10-4-5-53, Section VI).

05h
10-40

Assemble rotor and bearing assembly (TO 5F10-4-5-53, Section VI).

05i
10-40

Install gimbal assembly (TO 5F10-4-5-53, Section VI).

05j
10-40

Position rotor, stator and damper (TO 5F10-4-5-53, Section VI).

21. FINAL DESTINATION

DISPATCH

FUNCTIONAL CODE

22.

COORDINATION/INITIATING RCC SIGNATURE/DATE

23. DOCUMENT S/N

a.

MANERG

b.

MANPCC

a.

MANRG

b.

MANSAA

[illegible]

1. DATE

PAGE 4 OF 4 PAGES

90

**WATCH
= I TION**

10.

**PON/OP
NO.**

17.

WORK TO BE ACCOMPLISHED

18

MECHANIC

12

८३५००

20

“Q”

WORK CONTROL DOCUMENT				1. DATE 7167	PAGE 1 OF 4 PAGES
2. JOB ORDER NUMBER 01970A/66121A		3. QUANTITY 1	4. PRODUCTION SECTION/RCC "O" MNPCC/MNPGB	5. DATE SCHED 896	6. DATE COMP 8256
7. PART NUMBER G2479AB01		8. TECH DATA 5F10-4-5-53; 5F10-4-5-53-1		9. ITEM SERIAL NUMBER 845	10. DATE COMP X18
10. MODEL-DESIGN-SERIES TRU-2A/2		11. STOCK NUMBER 6615-00-137-6038 6615-01-006-0050		12. OPTIONAL NOTE: Use QQ-571 type SN60WRP solder and anticorrosive flux MIL-F-14256. Observe all notes, cautions, and warnings throughout the TO. MDC data required IAW MAOI 66-22.	
13. SERIAL NUMBER		14. HOUR Rate Gyroscope			
15. DISPATCH STATION	16. POM/OP NO.	17. WORK TO BE ACCOMPLISHED	18. MECHANIC	19.	20.
	01 10-10	Receive and clean gyro. Ascertain data correctness on forms AFLC 959 and AFTO 349.	WR PA 7084	15 JUL	1988
	02 10-20	Pretest If serviceable, proceed to Blocks 15 thru 17. If unserviceable, enter brief malfunction description.	WR PA 7084	15 JUL	1988
		NO START			
	03 10-30	Disassemble only to extent required to repair or replace the faulty parts. (TO 5F10-4-5-53, Section III).	WR PA 7084	01 SEP	1988
	04 10-30	Clean gyro (TO 5F10-4-5-53, Section IV).	WR PA 7084	01 SEP	1988
	05 10-30	Take rotor and bearing assembly to repair area. See attached Work Control Document.	WR PA 7084	02 SEP	1988
	06 10-60	Mechanical null and balance adjustments. (TO 5F10-4-5-53, Section VI).	WR PA 7084	02 SEP	1988
	07 10-60	Temperature cycle (four hours) (TO 5F10-4-5-53, Section VI).	WR PA 7084	06 SEP	1988
	08 10-60	Complete drift, stop adjustment, and performance checks (TO 5F10-4-5-53, Section VI).	WR PA 7084	06 SEP	1988
	09 10-70	Clean and cement printed wiring board to gyro. (TO 5F10-4-5-53, Section VI).	WR PA 7084	07 SEP	1988
21. FINAL DESTINATION		22. COORDINATION/INITIATING RCC SIGNATURE/DATE		23. DOCUMENT S/N	
DISPATCH	FUNCTIONAL CODE	a. MANERC <i>David A. Bridges</i> 19 JUN 87 b. MANPCC MANPGB <i>James E. Bost</i> 19 JUN 87 MANSAA <i>Don K. Hottel</i>			

WORK CONTROL DOCUMENT (CONTD)				1. DATE	PAGE 2 OF 4 PAGES	
15. DISPATCH ATION	16. PON/OP NO.	17. WORK TO BE ACCOMPLISHED	18. MECHANIC	19. "P"	20. "Q"	
	10	Certify that this item does not contain any foreign objects such as tools or unattached components:	WR PA 7084	07 SEP 1988	B	
	11 10-70	Clean, inspect and install gyro covers. (TO 5F10-4-5-53, Section VI).	WR PA 7084	07 SEP 1988		
	12 10-80	Immerse gyro in freon and observe for bubbles. Fill and leak check. (TO 5F10-4-5-53, Section IV).	WR PA 7084	07 SEP 1988		
	13 10-90	Assemble electronic inverter. Assemble gyro and inverter if required. (Temperature cycle required if inverter is removed.) (TO 5F10 4-5-53, Section VI).	WR PA 7084	07 SEP 1988		
	14 10-100	Select and install trim resistors and cover assembly. (TO 5F10-4-5-53, Section VI)	WR PA 7084	07 SEP 1988		
	15 10-110	Final visual, paint, check for mod TO compliance. Complete AFTO Form 349.	WR PA 7084	07 SEP 1988		
	16 10-100	Perform Functional Analysis (Final Test) Stamp Serviceable Tag	WR PA 7084	07 SEP 1988	B	
	17 10-110	Attach serviceable tag and install WR-ALC decal. IAW MAOI 66-40. Complete AFLC 959	WR PA 7084	07 SEP 1988		

WR-ALC/MANSAA "OVERPRINT"

\PROGRAM NAME: 300274
 \CPIN: 81H-TRUZA/6038-U001-00A
 \DATE OF LAST REVISION: 22-NOV-87
 \UUT TYPE: RATE GYRO
 \UUT NATIONAL STOCK NUMBER: 6615-00-137-6038
 \UUT MFR/PART NUMBER: HONEYWELL GG2479AB01
 \OPERATOR'S NAME: WILSON
 \TEST STATION: RATE STATION # 2
 \DATE & TIME OF TEST: 07-SEP-88 10:07:57
 #GYRO IN TEST POSITION 1 IS SERIAL NUMBER X18

07 SEP 1988



IMPORTANT NOTE CONCERNING THE STATIC RESISTANCE TESTS

If a failure of Static Resistance should occur, the operator may retest the UUT Static Resistance manually.
 If an in-tolerance measurement is obtained in this manner, then the previous failure is to be ignored.

STATIC RESISTANCE TESTS

Test Item	Count	Unit	Value 1	Value 2	Value 3	Result	Date/Time
PIN A TO CASE J1-A,CASE	1	OHM	.10000E+33	.10000E+07	.10000E+33	PASS	07-SEP-88 10:09:10
PIN B TO CASE J1-B,CASE	1	OHM	.10000E+33	.10000E+07	.10000E+33	PASS	07-SEP-88 10:09:14
PIN C TO CASE J1-C,CASE	1	OHM	.10000E+33	.10000E+07	.10000E+33	PASS	07-SEP-88 10:09:19
PIN D TO CASE J1-D,CASE	1	OHM	.10000E+33	.10000E+07	.10000E+33	PASS	07-SEP-88 10:09:23

SPINMOTOR RUNUP TESTS

Test Item	Count	Unit	Value 1	Value 2	Value 3	Result	Date/Time
STARTING CURRENT	1	AMPS	.53500E+00	.50000E-01	.33300E+00	PASS	07-SEP-88 10:09:41
RUNNING CURRENT	1	AMPS	.32100E+00	.20000E-01	.28725E+00	PASS	07-SEP-88 10:11:05
DC INPUT VOLTAGE	1	VDC	00028.1000	00027.9000	00027.9523	PASS	07-SEP-88 10:11:46

DC NULL TESTS

Test Item	Count	Unit	Value 1	Value 2	Value 3	Result	Date/Time
DC INPUT VOLTAGE	1	VDC	00028.1000	00027.9000	00028.0114	PASS	07-SEP-88 10:21:42
DC NULL VOLTAGE	1	mVDC	00015.0000	-00015.0000	00003.3570	PASS	07-SEP-88 10:21:46

STEADY-STATE RATE TESTS

Test Item	Count	Unit	Value 1	Value 2	Value 3	Result	Date/Time
DC INPUT VOLTAGE	1	VDC	00028.1000	00027.9000	00028.0100	PASS	07-SEP-88 10:21:51
OUTPUT AT .75 D/S CW RATE	1	VOLTS	.27300E+00	.22800E+00	.24930E+00	PASS	07-SEP-88 10:22:10
OUTPUT AT 1.50 D/S CW RATE	1	VOLTS	.53300E+00	.44800E+00	.49656E+00	PASS	07-SEP-88 10:22:30
OUTPUT AT 3.00 D/S CW RATE	1	VOLTS	00001.0650	.93500E+00	00001.0063	PASS	07-SEP-88 10:22:49
OUTPUT AT 6.00 D/S CW RATE	1	VOLTS	00002.1300	00001.8700	00002.0584	PASS	07-SEP-88 10:23:09
OUTPUT AT .75 D/S CCW RATE	1	VOLTS	-.22800E+00	-.27300E+00	-.23874E+00	PASS	07-SEP-88 10:23:51
OUTPUT AT 1.50 D/S CCW RATE	1	VOLTS	-.44800E+00	-.53300E+00	-.48807E+00	PASS	07-SEP-88 10:24:11
OUTPUT AT 3.00 D/S CCW RATE	1	VOLTS	-.93500E+00	-00001.0650	-.99124E+00	PASS	07-SEP-88 10:24:31
OUTPUT AT 6.00 D/S CCW RATE	1	VOLTS	-00001.8700	-00002.1300	-00002.0593	PASS	07-SEP-88 10:24:50
HYSTERESIS	1	VOLTS	.10000E-01	00000.0000	.44015E-02	PASS	07-SEP-88 10:25:13
ZERO OFFSET	1	VOLTS	.50000E-01	-.50000E-01	.38075E-02	PASS	07-SEP-88 10:25:14

VOLTAGE EXTREMES TEST - 21 VOLT EXCITATION

Test Item	Count	Unit	Value 1	Value 2	Value 3	Result	Date/Time
DC INPUT VOLTAGE	1	VDC	00021.1000	00020.9000	00021.0892	PASS	07-SEP-88 10:25:51
OUTPUT AT .75 D/S CW RATE	1	VOLTS	.28000E+00	.20000E+00	.23371E+00	PASS	07-SEP-88 10:26:10
OUTPUT AT 1.50 D/S CW RATE	1	VOLTS	.56000E+00	.40000E+00	.46389E+00	PASS	07-SEP-88 10:26:29
OUTPUT AT 3.00 D/S CW RATE	1	VOLTS	00001.1200	.80000E+00	.93252E+00	PASS	07-SEP-88 10:26:48
OUTPUT AT 6.00 D/S CW RATE	1	VOLTS	00002.2400	00001.6000	00001.9187	PASS	07-SEP-88 10:27:07
OUTPUT AT .75 D/S CCW RATE	1	VOLTS	-.20000E+00	-.28000E+00	-.22023E+00	PASS	07-SEP-88 10:27:49
OUTPUT AT 1.50 D/S CCW RATE	1	VOLTS	-.40000E+00	-.56000E+00	-.45182E+00	PASS	07-SEP-88 10:28:08
OUTPUT AT 3.00 D/S CCW RATE	1	VOLTS	-.80000E+00	-00001.1200	-.91951E+00	PASS	07-SEP-88 10:28:27
OUTPUT AT 6.00 D/S CCW RATE	1	VOLTS	-00001.6000	-00002.2400	-00001.9119	PASS	07-SEP-88 10:28:46
ZERO OFFSET	1	VOLTS	.50000E-01	-.50000E-01	.62015E-02	PASS	07-SEP-88 10:29:09

VOLTAGE EXTREMES TEST - 29 VOLT EXCITATION

Test Item	Count	Unit	Value 1	Value 2	Value 3	Result	Date/Time
DC INPUT VOLTAGE	1	VDC	00029.1000	00028.9000	00028.9181	PASS	07-SEP-88 10:29:49
OUTPUT AT .75 D/S CW RATE	1	VOLTS	.28000E+00	.20000E+00	.25244E+00	PASS	07-SEP-88 10:30:09
OUTPUT AT 1.50 D/S CW RATE	1	VOLTS	.56000E+00	.40000E+00	.50164E+00	PASS	07-SEP-88 10:30:28
OUTPUT AT 3.00 D/S CW RATE	1	VOLTS	00001.1200	.80000E+00	00001.0067	PASS	07-SEP-88 10:30:48
OUTPUT AT 6.00 D/S CW RATE	1	VOLTS	00002.2400	00001.6000	00002.0715	PASS	07-SEP-88 10:31:07

OUTPUT AT 6.00 D/S CCW RATE	1	VOLTS	-00001.6000	-00002.2400	-00002.0663	PASS	07-SEP-88 10:32:49
ZERO OFFSET	1	VOLTS	.50000E-01	-.50000E-01	.60205E-02	PASS	07-SEP-88 10:33:13
/							
CROSS AXIS SENSITIVITY TESTS							
DC INPUT VOLTAGE	1	VDC	00028.1000	00027.9000	00028.0133	PASS	07-SEP-88 10:40:37
SPIN AXIS SENSITIVE-CW ROT.	1	mVDC	00015.0000	-00015.0000	00006.4110	PASS	07-SEP-88 10:42:49
SPIN AXIS SENSITIVE-CCW ROT.	1	mVDC	00015.0000	-00015.0000	-00006.7690	PASS	07-SEP-88 10:43:31
\\END							

NAME <u>R.V. EYKOR</u> ALC <u>NR</u> DATE <u>4-6-81</u> RCC <u>MANREC</u> SHEET <u>1</u> OF <u>1</u>									
PCN <u>06121A</u> WCD <u>WIA</u> WCD DATE <u>8/19</u>									
OPERATION NUMBER	RCC	OPERATION DESCRIPTION	MANDATORY OCCURRENCE FACTOR	OPERATION TYPE	MANDATORY FLOW HOURS	MANPOWER	TIME REQUIRED	EQUIPMENT	DATA SOURCE COMMENTS
0000 MANAGER REC			1	TRANSIT	1	1	0.1	STD	C. DRIVER RANIER MAN MILLER OPER & A SCHEDULED
				SETUP					
				PROCESS					
		↑		TRANSIT					
				SETUP					
				PROCESS					
ALL WOOD OPERATIONS LISTED IN CD OPER PROFILE				TRANSIT					
				SETUP					
				PROCESS					
		↑		TRANSIT					
				SETUP					
				PROCESS					
9999 MANAGER SELL			1	TRANSIT	1	1	0.1	STD	D. HARPER SPECIAL MANAGER MAN MILLER OPERATOR SCHEDULED
				SETUP					
				PROCESS					

LSC-20W92C

Blanchard

9:44 TUESDAY, MARCH 28, 1989 1

SHEET 1 OF 2

OPERATION PROFILE									
NAME		ALC WR		DATE		SAS		RCC MANPGC	
ITEM CD PCN 08121A		WCD		WCDDATE 8119		EQUIP CODE		NOTES	
OPER NUMS	RCC	OPER HIST MAND	OPER MAND	SKILL CD/LVL	QTY	%	HRS	QTY	%
10	MANPGC	REC	1.00	T					
10	MANPGC	REC		S					
10	MANPGC	REC	1.00	P	0.1	IG09	0.1		
20	MANPGC	NDI	1.00	T					
20	MANPGC	NDI		S					
20	MANPGC	NDI	1.00	P	1.00	IG09	0.8	0.8	0.8
20	MANPGC	NDI		P	0.7	IG10	0.5	0.5	0.5
30	MANPGC	DIS	0.99	T					
30	MANPGC	DIS		S					
30	MANPGC	DIS	1.00	P	2.5	IG09	0.7	0.7	0.7
40	MANPGC	REP	1.00	T					
40	MANPGC	REP		S					
40	MANPGC	REP	1.35	P	0.8	IG09	0.8		

9:44 TUESDAY, MARCH 28, 1989 2

SHEET 22 OF 4

SAS 2/19/89

OPERATION PROFILE

DATE

WCDDATE 8119

ALC WR

WCD

ITEM CD PCN 08121A
OPER NOMB
RCC
HIST MAND OPER
DESC OCCR TYPE F HRS CD/LVL

EQUIP CODE

QTY X HRS

NOTES

50 MANPGC REP 1.00 T

50 MANPGC REP S

50 MANPGC REP 1.35
1.00 P 0.2 IG09 0.2

60 MANPGC ASSY 1.00 T

60 MANPGC ASSY S

60 MANPGC ASSY 1.80
1.00 P 2.3 IG09 0.8

70 MANPGC PROC 1.00 T

70 MANPGC PROC S

70 MANPGC PROC 1.85
1.00 P 0.0 IG09 0.1 9573 4.0

80 MANPGC ASSY 1.00 T

80 MANPGC ASSY S

80 MANPGC ASSY 1.80
1.00 P 6.15 IG09 0.3 0787 0.1

80% of wheels require repair

SAS 2/17/89

OPERATION PROFILE

DATE _____

ALC WR

WCDDATE 8119

NAME CLIMON
ITEM CD PCN 08121A

ITEM CD PCN 08121A

[illegible]

90 WAPGC ASSY S

90	MANPGC ASSY	IG09	0.2
	222-P	6/7	

100	MANPGC	NDI	1.00	T
-----	--------	-----	------	---

100	MANPGC	NDI	S
-----	--------	-----	---

100	MANPGC	NOT	100	MANPGC	NOT
100	MANPGC	NOT	100	MANPGC	NOT

110	MANPGC	ASSY	1 00	Y
-----	--------	------	------	---

110 MANROG ASSY C

189

98.

SAS 4/19/89

OPERATION PROFILE

ALC WR DATE

WCDDATE 8119

WCD

NAME *[Signature]*

ITEM CD PCN 08121A

OPER NUMB	RCC	DESC	OPER HIST MAND OCCR TYPE	MAND F HRS	SKILL CD/LVL	QTY	%	HRS	EQUIP CODE	QTY	%	HRS	NOTES
--------------	-----	------	--------------------------------------	---------------	-----------------	-----	---	-----	---------------	-----	---	-----	-------

130	MANPGC	ASSY	S										
130	MANPGC	ASSY	.86 1.00 P	8.0	IG08	1		1.0					
140	MANPGC	ASSY	1.00 T										
140	MANPGC	ASSY	S										
140	MANPGC	ASSY	.85 1.00 P	0.6	IG09	1		0.6	1022	1		0.4	
150	MANPGC	NDI	1.00 T										
150	MANPGC	NDI	S										
150	MANPGC	NDI	1.00 P	0.6	IG09	1		0.4	0450	1		0.4	
150	MANPGC	NDI	1.00 P	0.6	IG10	1		0.4	1022	1		0.4	
160	MANPGC	ASSY	0.99 T										
160	MANPGC	ASSY	S										
160	MANPGC	ASSY	1.00 P	3.0	IG09	1		0.4					

100% of 10 HRS is REPAIR CP Then All op's

[Signature]

9:44 TUESDAY, MARCH 28, 1989 5

SHEET 1 OF 3

OPERATION PROFILE SAS 4/19/89

RCC MANPGC

ALC WR

WCD

WCD

DATE

WCD

DATE

WCD

DATE

WCD

DATE

WCD

DATE

WCD

DATE

WCD

DATE

WCD

DATE

WCD

DATE

WCD

DATE

WCD

DATE

WCD

DATE

WCD

DATE

WCD

DATE

WCD

ITEM CD PCN 06121ASUB1

OPER HIST MAND OPER SKILL

NUMB RCC DESC OCCR TYPE F HRS CD/LVL QTY X HRS EQUIP CODE

SA MANPGC DIS T

SA MANPGC DIS S

SA MANPGC DIS 1.00 P 0.2 IG09 1 0.2

SB MANPGC ASSY T

SB MANPGC ASSY S

SB MANPGC ASSY 1.00 P 0.2 IG09 1 0.2

SC MANPGC ASSY T

SC MANPGC ASSY S

SC MANPGC ASSY 1.00 P 0.4 IG09 1 0.4

SD MANPGC ASSY T

SD MANPGC ASSY S

SD MANPGC ASSY 1.00 P 0.5 IG09 1 0.5

SE MANPGC ASSY T

SE MANPGC ASSY S

SE MANPGC ASSY 1.00 P 0.5 IG09 1 0.5

NOTES

SHEET 2 OF 3

SAS 4/19/84

RCC MANPGC

OPERATION PROFILE

DATE _____

WCDDATE 7167

ALC WR

WCD

	MAND F HRS	SKILL CD/LVL
01	00	00
02	00	00
03	00	00
04	00	00
05	00	00
06	00	00
07	00	00
08	00	00
09	00	00
10	00	00
11	00	00
12	00	00
13	00	00
14	00	00
15	00	00
16	00	00
17	00	00
18	00	00
19	00	00
20	00	00
21	00	00
22	00	00
23	00	00
24	00	00
25	00	00
26	00	00
27	00	00
28	00	00
29	00	00
30	00	00
31	00	00
32	00	00
33	00	00
34	00	00
35	00	00
36	00	00
37	00	00
38	00	00
39	00	00
40	00	00
41	00	00
42	00	00
43	00	00
44	00	00
45	00	00
46	00	00
47	00	00
48	00	00
49	00	00
50	00	00
51	00	00
52	00	00
53	00	00
54	00	00
55	00	00
56	00	00
57	00	00
58	00	00
59	00	00
60	00	00
61	00	00
62	00	00
63	00	00
64	00	00
65	00	00
66	00	00
67	00	00
68	00	00
69	00	00
70	00	00
71	00	00
72	00	00
73	00	00
74	00	00
75	00	00
76	00	00
77	00	00
78	00	00
79	00	00
80	00	00
81	00	00
82	00	00
83	00	00
84	00	00
85	00	00
86	00	00
87	00	00
88	00	00
89	00	00
90	00	00
91	00	00
92	00	00
93	00	00
94	00	00
95	00	00
96	00	00
97	00	00
98	00	00
99	00	00

MAND
F HRS

HIST OCCR	HAND OCCR	OPER TYPE
1	1	1
2	2	2
3	3	3
4	4	4
5	5	5
6	6	6
7	7	7
8	8	8
9	9	9
10	10	10
11	11	11
12	12	12
13	13	13
14	14	14
15	15	15
16	16	16
17	17	17
18	18	18
19	19	19
20	20	20
21	21	21
22	22	22
23	23	23
24	24	24
25	25	25
26	26	26
27	27	27
28	28	28
29	29	29
30	30	30
31	31	31
32	32	32
33	33	33
34	34	34
35	35	35
36	36	36
37	37	37
38	38	38
39	39	39
40	40	40
41	41	41
42	42	42
43	43	43
44	44	44
45	45	45
46	46	46
47	47	47
48	48	48
49	49	49
50	50	50
51	51	51
52	52	52
53	53	53
54	54	54
55	55	55
56	56	56
57	57	57
58	58	58
59	59	59
60	60	60
61	61	61
62	62	62
63	63	63
64	64	64
65	65	65
66	66	66
67	67	67
68	68	68
69	69	69
70	70	70
71	71	71
72	72	72
73	73	73
74	74	74
75	75	75
76	76	76
77	77	77
78	78	78
79	79	79
80	80	80
81	81	81
82	82	82
83	83	83
84	84	84
85	85	85
86	86	86
87	87	87
88	88	88
89	89	89
90	90	90
91	91	91
92	92	92
93	93	93
94	94	94
95	95	95
96	96	96
97	97	97
98	98	98
99	99	99
100	100	100

[illegible]

NAME _____

ITEM CD PCN 00121ASUB1

OPER

3

SE MANPGC ASSY

5

SE MANPGC ASSY

100P

1-2 1G09

0.2

5F MANPGC ASSY

T

SF MANPGC ASSY

5F MANPGC ASSY

1.000

000-1609

5.0

5G MANPGC ASSY

5G MANPGC ASSY

5

5G MANPGC ASSY

1000 P

6091 1.3

0.3

5H MANPGC ASSY

†

5H MANPGC ASSY

5

MANPGC ASSY

P. 20.

6091

4.

MANPGC ASSY

Key

9:44 TUESDAY, MARCH 28, 1989 7

SHEET 3 OF 3

NAME K. J. ANDERSON OPERATION PROFILE SAS 4/10/87
ITEM CD PCN 0612IASUB1 ALC WR DATE RCC MANPGC
WCD WCCDATE 7167

ITEM CD PCN 06121ASUB1

MODDATE / 167									
OPER	HIST	OPER	MAND	SKILL	QTY	%	HRS	EQUIP	NOTES
NUMB	OCGR	OCGR	TYPE	CD/LVL				CODE	
31	MANPGC	ASSY							
OPER									
NUMB									
31	MANPGC	ASSY							

SI	MANPGC	ASSY	LOCOP	IG09	1	0.3

J MANPGC ASSY T

J MANPGC ASSY S

J	MANPGC	ASSY	LOC P	IG09			
			1000 P	1	0.5	0787	1
							0.5

[illegible]

K MANPGC ASSY S

WORK MEASUREMENT STANDARD DATA COMPUTATION SHEET

Page 1 of 1 Pages

DATE
22 Nov 82

JOB ASSIGNED TO
CARL MUCHER

COMPUTED BY
CARL MUCHER

INSTRUCTIONS: Industrial Engineering Division will complete
"Work Measurement Requirements" and furnish cut sheets to appli-
cations using activities for each type of computation sheet as required.

ORDER	PART NUMBER	STOCK NUMBER	JOB STANDARD	STATION NO.
01970A	GG2479AB01	6615-00-137-6038	N/A	MNPG
NOUN	QUANTITY	STD HRS PER	PIECES	TIME PER PIECE
Transmitter, Rate Gyroscope	N/A	N/A	N/A	N/A

WORK MEASUREMENT REQUIREMENTS:

PRODUCTION SUPERVISOR LABOR STANDARD REVIEW

Observations were made 26 Aug 82 through 3 Sep 82 in accordance
with AFLCR 66-4 Work Sampling Techniques. Overall productivity was 91 %.

CATEGORY	BASE HR/OCC	PF&D	STD HR/OCC	OCC FACTOR	STD HR/END ITEM
----------	-------------	------	------------	------------	-----------------

Receive	.044	1.07	.04708	1.00	.04708
---------	------	------	--------	------	--------

Pretest	.067	1.07	.07169	1.00	.07169
---------	------	------	--------	------	--------

Disass & Clean	7.913	1.07	8.46691	.81	6.85820
----------------	-------	------	---------	-----	---------

Ass & Repair	2.657	1.07	2.84299	.81	2.30282
--------------	-------	------	---------	-----	---------

Motor Run	.211	1.07	.22577	.81	.18287
-----------	------	------	--------	-----	--------

Calibration	1.961	1.07	2.09827	.81	1.69960
-------------	-------	------	---------	-----	---------

Clean & Cement	.618	1.07	.66126	.81	.53562
----------------	------	------	--------	-----	--------

PWB & Install Cover

Fill, Seal & Leak Check	.059	1.07	.06313	.81	.05114
-------------------------	------	------	--------	-----	--------

Electronic Inter	2.195	1.07	2.34865	.81	1.90241
------------------	-------	------	---------	-----	---------

Additional	1.769	1.07	1.89283	1.00	1.89283
------------	-------	------	---------	------	---------

Final Visual & Condition tag	.774	1.07	.82618	1.00	.82318
------------------------------	------	------	--------	------	--------

TOTAL 16.37244

This total is manually computed and may vary slightly from E046 output. In accordance with AFLCR 66-4, para 3-10, all standards should be reviewed by affected supervisory personnel for completeness of work content. Production supervisors will be given 10 workdays to express in writing their reasons for nonconcurrency. If, after this time, no reply has been received from the coordinating agency, the standard will be considered coordinated and acceptable.

APPROVALS	DATE	APPROVALS	DATE
INDUSTRIAL ENGINEER		WORK CENTER FOREMAN	
N/A		Sam W. Handlen	4 Nov 82
IS TECHNICIAN		N/A	

SHOP FLOW DAY COMPUTATION FOR PRODUCTION NO: 01970A

AFLCR 66-4 Shop Flow Day Formula was used to establish this flow day standard as follows: Flow Days = A [(B ÷ C) + D + E] where A = 1.45; B = End Item Labor Standard; C = Direct Labor Hours Per Person Per Day adjusted for indirect categories and labor efficiency; D = Routine Delays; E = Unique Delays. Repair is being accomplished as a responsible shop.

STEP	DESCRIPTION	
1	<p>B = Labor Standard of <u>16.37</u> Hrs C = <u>7.66</u> Daily Labor Hrs</p> <p>Value "C" is calculated as follows:</p> <p>MANPG <u>C</u> .24 + .25 + .26 + .29 Indirect Average = <u>.1</u> Hours</p> <p>MANPG <u>C</u> Labor Efficiency = <u>97</u> %</p> <p>C = 8 Hours Minus Indirect Average Times Labor Efficiency</p>	
	<p>D = Routine Delays</p> <p>a. Awaiting Maintenance (AWM) = 3.8 days</p> <p>b. One days supply at station awaiting maintenance = 4 days (average 4 stations for each C/N). This is necessary to maintain uninterrupted flow of items.</p> <p style="text-align: right;">TOTAL</p>	
	<p>E = Unique Delays</p> <p>a. Machine processing <u>3.42</u> Day(s)</p> <p>b. Machine processing delays <u>3.63</u> Day(s)</p> <p>c. Routing to support shops <u> </u> Day(s)</p> <p>d. Others (See Reverse Side) <u> </u> Day(s)</p> <p style="text-align: right;">TOTAL</p>	7
4	Total flow days this shop (1 + 2 + 3)	16
	Work Shift Adjustment (Item 4 ÷ number of shifts). 16.99 ÷ 1	16
6	Sum of flow days for all shops (Item 5 x 1.45) 16.99 x 1.45 = 24.6355	25
	(Final result to be rounded up to next whole day.)	

COMPUTED BY: SYLVIA H. BLACK

DATE: 2 OCT 84

3. E = UNIQUE DELAYS

HOURS


a. Machine Processing - $27.34 \div 8 \text{ hrs/day} = 3.42$

(1) To aid in removing cover, gyroscope & capscrews, heat in oven.	2.00	3-1	3-4, 3-6a, 3-6g
(2) Apply adhesive to stator & place in oven	2.00	6-1	6-4f
(3) Apply adhesive to brg flange & cure	3.00	6-7	6-13e
(4) Run in motor 36 hrs + 3	12.00	6-9	6-16f
(5) Place in temp cycle chamber	4.00	6-10	6-19
(6) Perform drift test by placing in oven	2.00	6-11	6-21a(5)
(7) Warm up gyro (10 min)	.17	6-13	6-22b
(8) Warm up gyro (10 min)	.17	6-13	6-23e
(9) Cure epoxy in oven for 2 hrs	2.00	6-15	6-28h

b. Machine Processing Delays - $29.00 \div 8 \text{ hrs/day} = 3.63$

(1) Let cover, assy & capscrew cool	1.00	3-1	3-4, 3-6a, 3-6g
(2) Cure epoxy	2.00	5-3	5-7e
(3) Let spinmotor wound stator cool	1.00	6-1	6-4f
(4) Cure adhesive on header (24 + 3)	8.00	6-1	6-5d
(5) Cure adhesive on coil winding assy (24 + 3)	8.00	6-1	6-6d
(6) After drift check cool	4.00	6-11	6-21b(4)
(7) Dry at room temp	1.00	6-14	6-24d
(8) Allow silicone rubber to air dry	4.00	6-19	6-40e

PROCESS FLOW CHART PCN 06121A



Rev 1/19/87

PART OPERATION SUMMARY 9:03 FRIDAY, FEBRUARY 24, 1989 1

PN: GQ2479AB01 ALC: WARNER ROBBINS NSN: MANPGC GYRO SHOP, UNIT 3
 OPERATION: ZPRT PCN: 06121A WCD: WCD DATE: 8119
 SAMPLE SIZE: 163 MISSING FLOWTIMES: 1 PRIMARY OPERATION TYPE: ASSY MATERIAL TYPE:
 END ITEMS: OUTLIERS DELETED: 0

----- MANPOWER REQUIRED ----- EQUIPMENT REQUIRED -----
 SKILL QTY FRACTION HOURS TIME FRACTION HOURS TIME BATCH
 MIN MAX

HISTORICAL DATA

ACTUAL FREQ	0	10	20	30	40	50	60	70	80	90	100	CODE	CATEGORY	QTY	FRACTION	HOURS	PARAMETERS	D VALUE	D ALPHA
0	34	10	14	13	13	8	4	5	4	0	0	0	UNIFORM	0.0	0.0	119.0	0.409		
10	14	13	13	8	4	5	4	0	0	0	0	0	TRIANGULAR	0.0	0.5	119.0	0.198		
20	13	8	4	5	4	0	0	0	0	0	0	0	NORMAL	28.2	27.1		0.125		
30	8	4	5	4	0	0	0	0	0	0	0	0	LOGNORMAL	28.2	27.1		0.060	0.01	
40	4	5	4	0	0	0	0	0	0	0	0	0	EXPONENTIAL	28.7			0.049	1.00	
50	5	4	0	0	0	0	0	0	0	0	0	0						1.00	
60	4	0	0	0	0	0	0	0	0	0	0	0							
70	4	0	0	0	0	0	0	0	0	0	0	0							
80	0	0	0	0	0	0	0	0	0	0	0	0							
90	0	0	0	0	0	0	0	0	0	0	0	0							
>=100	5	0	0	0	0	0	0	0	0	0	0	0							

OCCURRENCE FACTOR: OCCURRENCES: 164
 DISTRIBUTION OF CHOICE: EXPONENTIAL

PART OPERATION SUMMARY

PN: 10063458-102
 OPERATION: ZPRT
 SAMPLE SIZE: .
 ALC: WARNER ROBBINS
 NSN:
 RCO: MANPGC
 GYRO SHOP, UNIT 3
 PCN: 06121ASUB1
 WCD: 7167
 WCD DATE: 7167
 PRIMARY
 MISSING FLOWTIMES: .
 END ITEMS: .
 OPERATION TYPE: ASSY MATERIAL TYPE:
 OUTLIERS DELETED: .

----- MANPOWER REQUIRED -----
 SKILL QTY FRACTION TIME HOURS

----- EQUIPMENT REQUIRED -----
 CODE CATEGORY QTY FRACTION TIME HOURS BATCH MIN MAX

HISTORICAL DATA

ACTUAL FREQ	0	10	20	30	40	50	60	70	80	90	100	DISTRIBUTION	PARAMETERS	D VALUE	D ALPHA
0	0	0	0	0	0	0	0	0	0	0	0	UNIFORM	.	.	.
0	0	0	0	0	0	0	0	0	0	0	0	TRIANGULAR	.	.	.
0	0	0	0	0	0	0	0	0	0	0	0	NORMAL	.	.	.
0	0	0	0	0	0	0	0	0	0	0	0	LOGNORMAL	.	.	.
0	0	0	0	0	0	0	0	0	0	0	0	EXPONENTIAL	.	.	.

OCCURRENCE FACTOR: . OCCURRENCES: .
 DISTRIBUTION OF CHOICE: .

WORK CONTROL DOCUMENT						1. DATE 8119		PAGE 1 OF 2 PAGES	
JOB ORDER NUMBER See Block 12		3. QUANTITY 1		4. PRODUCTION SECTION/RCC "O" MNP GC		5. DATE SCHED		6. DATE COMP	
PART NUMBER See Block 12			8. TECH DATA 5F10-4-4-3; 5F10-4-4-3-1				9. ITEM SERIAL NUMBER		
10. MODEL-DESIGN-SERIES A2850-1/A2850-5		11. STOCK NUMBER See Block 12		12. OPTIONAL CIRCLE APPROPRIATE C/N C/N NSN P/N 02387A/74061A 6615-00-857-0828 B2888-01 02382A/74065A 6615-00-869-0825 B2888-02					
13. SERIAL NUMBER		14. NAME TRU-2A/A Rate Gyro							
15. DISPATCH STATION	16. PON/OP NO.	17. WORK TO BE ACCOMPLISHED				18. MECHANIC	19. SPECIAL	20. "Q"	
	010	Receive (Check data on WCD and AFTO Form 349. Clean gyro external surfaces.)							
	020	Remove gyro from bracket. Strip paint from gyro, if damaged; if not, remove paint from solder tube and filler tube areas only.							
	030	Unsolder and remove filling tube; apply heat, to overlap of solder band and pell or roll it off.							
	040	Pull gyroscope out of cover assembly. Disassemble, assemble clean and inspect.							
	050	Take motor to repair area. See attached work control document.							
	060	Install motor in gimbal; install gimbal assy in frame. Install terminal board and dashpot.							
	070	Calibration: Adjust null, set rates, set bumpers and adjust damping time.							
	080	Certify that this item does not contain any foreign objects such as tools or unattached components.						B	
	090	Fill, seal, and leak check gyroscope assy; install mounting strap and mount assy to base.							
	100	Install transmitter assy in fixture and run cross coupling check							
FINAL DESTINATION		22. COORDINATION/INITIATING RCC SIGNATURE/DATE				23. DOCUMENT S/R			
DISPATCH	FUNCTIONAL CODE	a. MANPGC MANPCB		b. MAQNG					
		c. MANERG		d. MANSA A					

WORK CONTROL DOCUMENT (CONTD)

1. DATE 8/19

PAGE 2 OF 4 PAGES

[illegible]

WORK CONTROL DOCUMENT				1. DATE 7167		PAGE 3 OF 3 PAGES	
2. JOB ORDER NUMBER 02387A/74061A 2382A/74065A		3. QUANTITY 1		4. PRODUCTION SECTION/RCC "O" MNPCC		5. DATE SCHED	
PART NUMBER 14038-03		8. TECH DATA 5F10-4-4-3				9. ITEM SERIAL NUMBER	
10. MODEL-DESIGN-SERIES		11. STOCK NUMBER NSL		12. OPTIONAL			
13. SERIAL NUMBER		14. NOUN MOTOR ASSEMBLY					
15. DISPATCH STATION	16. PON/OP NO.	17. WORK TO BE ACCOMPLISHED			18. MECHANIC	19.	20.
	05a 10-40	Disassemble, clean, inspect and repair motor assembly IAW 5F10-4-4-3, Section II.					
	05b 10-50	Rebalance motor if rotor or ball bearings have been replaced IAW 5F10-4-4-3, Section II.					
	05c 10-50	Adjust end play IAW 5F10-4-4-3, Section II.					
	05d 10-50	Secure connections IAW 5F10-4-4-3, Section II.					
	05e 10-50	Run motor bearing test (48 hours) IAW 5F10-4-4-3, Section II.					
21. FINAL DESTINATION		22. COORDINATION/INITIATING RCC SIGNATURE/DATE				23. DOCUMENT S/N	
DISPATCH	FUNCTIONAL CODE	a. MANERC <i>David L. Bridges</i> 19 JUNE 87 b. MANPCC <i>James E. Boyd</i> 22 JUNE 87 <i>MANSA</i> <i>James E. Boyd</i> 19 JUNE 87					

WORK CONTROL DOCUMENT				1. DATE 7167	PAGE 1 OF 3 PAGES
2. ORDER NUMBER 387A/74081A 382A/74065A		3. QUANTITY 1	4. PRODUCTION SECTION/RCC "O" MNPCC/MNPGB	5. DATE SCHED 8053	6. DATE COMP 8215
7. PART NUMBER B2888-01 B2888-02		8. TECH DATA 5F10-4-4-3; 5F10-4-4-3-1		9. ITEM SERIAL NUMBER 65-2757	
10. MODEL-DESIGN-SERIES A2850-1 A2850-5		11. STOCK NUMBER 6615-00-857-0828 6615-00-869-0825		12. OPTIONAL NOTE: Use QQ-S-571, type SN 60WRP solder and anticorrosion flux MIL-E-14256. Observe all notes, cautions, and warnings throughout the TO. 82A	
13. SERIAL NUMBER		14. NOUN TRU-2A/A Rate Gyro			
15. DISPATCH STATION	16. POM/OP NO.	17. WORK TO BE ACCOMPLISHED	18. MECHANIC	19. "P"	20. "Q"
	01 10-10	Receive and clean assembly. Ascertain data correctness on Forms AFLC 959 and AFTO 349.	WR PA 6051	25 JUL 1988	
	02 10-20	Remove gyro from bracket. Strip paint from Gyroscope, if damaged; if not, remove paint from solder tube and filler tube areas only. (5F10-4-4-3, Section I)	WR PA 6051	25 JUL 1988	
	03 10-30	Unsolder and remove filling tube; apply heat to overlap of solder band and peel or roll it off. (5F10-4-4-3, Section II)	WR PA 6051	25 JUL 1988	
	04 10-30	Pull gyroscope out of cover assembly. Disassemble, assemble, clean and inspect. (5F10-4-4-3, Section II)	WR PA 6051	25 JUL 1988	
	05 10-30	Take motor to repair area. See attached Work Control Document. N/A	WR PA 6051	25 JUL 1988	
	06 10-60	Install motor in gimbal; install gimbal assy in frame. Install terminal board and dashpot. (5F10-4-4-3, Section II)	WR PA 6051	25 JUL 1988	
	07 10-70	Calibration: Adjust null, set rates, set bumpers and adjust damping time. (5F10-4-4-3, Section III)	WR PA 6051	26 JUL 1988	
	08	Certify that this item does not contain any foreign objects such as tools or unattached objects.	WR PA 6051	26 JUL 1988 B	
	09 10-80	Fill, seal, and leak check gyroscope assy; install mounting strap and mount assy to base (5F10-4-4-3, Section II).	WR PA 6051	27 JUL 1988	
	10 10-90	Install transmitter assy in fixture and run cross coupling check. (5F10-4-4-3, Section II).	WR PA 6051	27 JUL 1988	
21. FINAL DESTINATION		22. COORDINATION/INITIATING RCC SIGNATURE/DATE		23. DOCUMENT S/N	
DISPATCH	FUNCTIONAL CODE	a. MANERC 19 June 87 b. MANPCC 22 June 87 MANPGB 19 June 87 MANSA 22 June 87 MANSA 19 June 87			

PAGE 2 OF 3 PAGES

[illegible]

PROGRAM NAME: 300320 A
PCPN: 81H-TRU2A/0825-0001-00A
DATE OF LAST REVISION: 22-NOV-87
OUT TYPE: RATE GYRO
OUT NATIONAL STOCK NUMBER: 6615-00-869-0825
OUT MFR/PART NUMBER: R.C.ALLEN A2850-S / B2833-02
OPERATOR'S NAME: WILSON
TEST STATION: RATE STATION # 1
DATE & TIME OF TEST: 27-JUL-88 12:22:24

JUL 27 1988



INSULATION TEST

INS. ON PINS J1-A AND CASE	1	uWHP	00010.0000	00000.0000	.57000E+00	PASS	27-JUL-88	12:23:19
INS. ON PINS J1-B AND CASE	1	uWHP	00010.0000	00000.0000	.53000E+00	PASS	27-JUL-88	12:23:20

#GYRO IN TEST POSITION 1 IS SERIAL NUMBER 65-2757
#GYRO IN TEST POSITION 2 IS SERIAL NUMBER 68-3721
#GYRO IN TEST POSITION 3 IS SERIAL NUMBER 63-1742

SPINMOTOR RUNUP TESTS

STARTING CURRENT	1	Ampt	.52600E+00	.50000E-01	.22892E+00	PASS	27-JUL-88	12:28:46
RUNNING CURRENT	1	Ampt	.25000E+00	.20000E-01	.20903E+00	PASS	27-JUL-88	12:30:13
DC INPUT VOLTAGE	1	VDC	00028.1000	00027.9000	00027.9217	PASS	27-JUL-88	12:35:04

STEADY-STATE RATE TESTS

OUTPUT AT 0.75 D/S CM RATE	1	VOLTS	.28600E+00	.21400E+00	.25896E+00	PASS	27-JUL-88	12:45:14
OUTPUT AT 1.50 D/S CM RATE	1	VOLTS	.55000E+00	.45000E+00	.49492E+00	PASS	27-JUL-88	12:45:42
OUTPUT AT 3.00 D/S CM RATE	1	VOLTS	00001.1000	.90000E+00	00001.0209	PASS	27-JUL-88	12:46:00
OUTPUT AT 6.00 D/S CM RATE	1	VOLTS	00002.1800	00001.8200	00001.9747	PASS	27-JUL-88	12:46:31
OUTPUT AT 0.00 D/S CM RATE	1	VOLTS	.25000E-01	-.25000E-01	.53100E-02	PASS	27-JUL-88	12:47:15
OUTPUT AT 0.75 D/S CCM RATE	1	VOLTS	-.21400E+00	-.28600E+00	-.25274E+00	PASS	27-JUL-88	12:47:43
OUTPUT AT 1.50 D/S CCM RATE	1	VOLTS	-.45000E+00	-.55000E+00	-.49985E+00	PASS	27-JUL-88	12:48:09
OUTPUT AT 3.00 D/S CCM RATE	1	VOLTS	-.90000E+00	-00001.1000	-.99937E+00	PASS	27-JUL-88	12:48:35
OUTPUT AT 6.00 D/S CCM RATE	1	VOLTS	-00001.8200	-00002.1800	-00002.0002	PASS	27-JUL-88	12:49:01
OUTPUT AT 0.00 D/S CCM RATE	1	VOLTS	.25000E-01	-.25000E-01	.71850E-02	PASS	27-JUL-88	12:49:42
HYSTERESIS	1	VOLTS	.25000E-01	-.25000E-01	-.92350E-02	PASS	27-JUL-88	12:49:54
ZERO OFFSET	1	VOLTS	.50000E-01	-.50000E-01	.62475E-02	PASS	27-JUL-88	12:49:55

VOLTAGE EXTREMES TEST - 25 VOLT EXCITATION

DC INPUT VOLTAGE	1	VDC	00025.1000	00024.9000	00025.0707	PASS	27-JUL-88	12:50:19
OUTPUT AT 0.75 D/S CM RATE	1	VOLTS	.23000E+00	.20000E+00	.24373E+00	PASS	27-JUL-88	12:50:40
OUTPUT AT 1.50 D/S CM RATE	1	VOLTS	.56000E+00	.41000E+00	.48663E+00	PASS	27-JUL-88	12:51:00
OUTPUT AT 3.00 D/S CM RATE	1	VOLTS	00001.1000	.83000E+00	.99756E+00	PASS	27-JUL-88	12:51:31
OUTPUT AT 6.00 D/S CM RATE	1	VOLTS	00002.2000	00001.6600	00001.9620	PASS	27-JUL-88	12:52:00
OUTPUT AT 0.75 D/S CCM RATE	1	VOLTS	-.20000E+00	-.28000E+00	-.25244E+00	PASS	27-JUL-88	12:52:50
OUTPUT AT 1.50 D/S CCM RATE	1	VOLTS	-.41000E+00	-.56000E+00	-.48144E+00	PASS	27-JUL-88	12:53:15
OUTPUT AT 3.00 D/S CCM RATE	1	VOLTS	-.83000E+00	-00001.1000	-.97241E+00	PASS	27-JUL-88	12:53:42
OUTPUT AT 6.00 D/S CCM RATE	1	VOLTS	-00001.6600	-00002.2000	-00001.9692	PASS	27-JUL-88	12:54:00
ZERO OFFSET	1	VOLTS	.50000E-01	-.50000E-01	.73643E-02	PASS	27-JUL-88	12:54:39

VOLTAGE EXTREMES TEST - 29 VOLT EXCITATION

DC INPUT VOLTAGE	1	VDC	00029.1000	00028.9000	00028.9305	PASS	27-JUL-88	12:55:05
OUTPUT AT 0.75 D/S CM RATE	1	VOLTS	.28000E+00	.20000E+00	.24053E+00	PASS	27-JUL-88	12:55:24
OUTPUT AT 1.50 D/S CM RATE	1	VOLTS	.56000E+00	.41000E+00	.49533E+00	PASS	27-JUL-88	12:55:52
OUTPUT AT 3.00 D/S CM RATE	1	VOLTS	00001.1000	.83000E+00	00001.0316	PASS	27-JUL-88	12:56:19
OUTPUT AT 6.00 D/S CM RATE	1	VOLTS	00002.2000	00001.6600	00002.0004	PASS	27-JUL-88	12:56:44
OUTPUT AT 0.75 D/S CCM RATE	1	VOLTS	-.20000E+00	-.28000E+00	-.26390E+00	PASS	27-JUL-88	12:57:13
OUTPUT AT 1.50 D/S CCM RATE	1	VOLTS	-.41000E+00	-.56000E+00	-.49919E+00	PASS	27-JUL-88	12:58:00
OUTPUT AT 3.00 D/S CCM RATE	1	VOLTS	-.83000E+00	-00001.1000	-00001.0032	PASS	27-JUL-88	12:58:26
OUTPUT AT 6.00 D/S CCM RATE	1	VOLTS	-00001.6600	-00002.2000	-00002.0094	PASS	27-JUL-88	12:59:52
ZERO OFFSET	1	VOLTS	.50000E-01	-.50000E-01	.79130E-02	PASS	27-JUL-88	12:59:23
DC INPUT VOLTAGE	1	VDC	00028.1000	00027.9000	00028.0608	PASS	27-JUL-88	12:59:32

TRANSIENT RESPONSE TEST

CM & DEG-SEC-RATE	1	VOLTS	00002.2000	00001.6600	00001.9922	PASS	27-JUL-88	12:59:54
CM TRANSIENT RESPONSE	1	SEC	00002.5000	00001.5000	00001.8833	PASS	27-JUL-88	12:59:57
CCW & DEG/SEC RATE	1	VOLTS	-00001.6600	-00002.2000	-00002.0101	PASS	27-JUL-88	13:00:14
CCW TRANSIENT RESPONSE	1	SEC	00002.5000	00001.5000	00001.9499	PASS	27-JUL-88	13:00:17

CROSS AXIS SENSITIVITY TEST

DC INPUT VOLTAGE	1	VDC	00028.1000	00027.9000	00028.0254	PASS	27-JUL-88	13:00:51
SPIN AXIS SENSITIVE-CM ROT.	1	VOLTS	.20000E-01	-.20000E-01	.23440E-02	PASS	27-JUL-88	13:01:36

VERIFICATION SHEET

NAME R.V. VERVOER ALC NR DATE 4-6-8 RCC MANREC SHEET 1 OF 1

PCN 74061A WCD N/A WCD DATE AB119

OPERATION NUMBER	RCC	OPERATION DESCRIPTION	MANDATORY OCCURRENCE FACTOR	OPERATION TYPE	MANDATORY FLOW HOURS		BKKL CODE/ LEVEL	MANPOWER		TIME REQUIRED		EQUIPMENT CODE	EQUIPMENT		DATA SOURCE COMMENTS	
					%	HRS.		QTY.	%	HRS.	QTY.		%	HRS.		
1N Mayas		REC	1	TRANSIT											C. Deiver RANGE MAR MILLER & A SCHEDULE	
				SETUP												
				PROCESS			1	0.1								
		↑		TRANSIT												
				SETUP												
				PROCESS												
ALL WRD OPERATIONS LISTED IN CD OPER PROFILE				TRANSIT												
				SETUP												
				PROCESS												
		↓		TRANSIT												
				SETUP												
				PROCESS												
9999 Mayas		SELL	1	TRANSIT											D. Harper Sched. Mayas MAR MILLER OPERATOR 8 A SCHEDULE	
				SETUP												
				PROCESS			1	0.1								

SAS 4/19/89

OPERATION PROFILE

ALC WR

NAME

DATE

WCD

ITEM CD PCN 74081A

WCDDATE A8119

WCD

OPER NUNB

OPER HIST MAND OPER MAND SKILL

DESC OCCR TYPE F HRS CD/LVL

10 MANPGC REC 0.99 T

10 MANPGC REC S

10 MANPGC REC 1.00 P 0.1 IG09 1 0.1

20 MANPGC DIS 0.99 T

20 MANPGC DIS S

20 MANPGC DIS 1.00 P 1.3 IG09 1 0.3

30 MANPGC DIS 1.00 T

30 MANPGC DIS S

30 MANPGC DIS 1.00 P 0.1 IG09 1 0.1

40 MANPGC DIS 1.00 T

40 MANPGC DIS S

40 MANPGC DIS 1.00 P 0.1 IG09 1 0.1

50 MANPGC DIS 1.00 T

MANPGC REC 0.99 T

MANPGC REC S

MANPGC REC 1.00 P 0.1 IG09 1 0.1

MANPGC DIS 0.99 T

MANPGC DIS S

MANPGC DIS 1.00 P 1.3 IG09 1 0.3

MANPGC DIS 1.00 T

MANPGC DIS S

MANPGC DIS 1.00 P 0.1 IG09 1 0.1

MANPGC DIS 1.00 T

MANPGC DIS S

MANPGC DIS 1.00 P 0.1 IG09 1 0.1

MANPGC DIS 1.00 T

MANPGC DIS S

MANPGC DIS 1.00 P 0.1 IG09 1 0.1

MANPGC DIS 1.00 T

MANPGC DIS S

MANPGC DIS 1.00 P 0.1 IG09 1 0.1

MANPGC DIS 1.00 T

MANPGC DIS S

MANPGC DIS 1.00 P 0.1 IG09 1 0.1

MANPGC DIS 1.00 T

MANPGC DIS S

MANPGC DIS 1.00 P 0.1 IG09 1 0.1

MANPGC DIS 1.00 T

MANPGC DIS S

MANPGC DIS 1.00 P 0.1 IG09 1 0.1

MANPGC DIS 1.00 T

9:44 TUESDAY, MARCH 28, 1989 10

SHEET 3 OF 4

[Signature]

OPERATION PROFILE

SAS

2/10/89

RCC MANPGC

NAME

ITEM CD PCN 74081A

OPER NUMB

RCC

MANPGC

ASSY

90

MANPGC

ASSY

100

MANPGC

ASSY

100

MANPGC

ASSY

110

MANPGC

ASSY

110

MANPGC

ASSY

110

MANPGC

NDI

120

MANPGC

NDI

120

MANPGC

NDI

120

MANPGC

ASSY

130

OPER HIST MAND OPER

DESC OCCR TYPE

90

MANPGC

ASSY

1.00 P

100

MANPGC

ASSY

0.99

100

MANPGC

ASSY

1.00

110

MANPGC

ASSY

1.00

110

MANPGC

ASSY

0.99

120

MANPGC

NDI

1.00 P

120

MANPGC

NDI

1.00 P

130

MANPGC

ASSY

0.99

WCD

MAND

F HRS

90

MANPGC

ASSY

1.00 P

100

MANPGC

ASSY

0.99

100

MANPGC

ASSY

1.00

110

MANPGC

ASSY

1.00

110

MANPGC

ASSY

0.99

120

MANPGC

NDI

1.00 P

120

MANPGC

NDI

1.00 P

130

MANPGC

ASSY

0.99

WCD DATE A8119

QTY

90

1

100

1

1

1

1

1

1

1

1

1

1

1

1

EQUIP CODE

90

IG09

100

IG09

100

IG09

1022

1022

1022

0004

0004

0450

0450

1022

1022

QTY

90

1

100

1

1

1

1

1

1

1

1

1

1

1

1

QTY

90

1

100

1

1

1

1

1

1

1

1

1

1

1

1

QTY

90

1

100

1

1

1

1

1

1

1

1

1

1

1

1

QTY

90

1

100

1

1

1

1

1

1

1

1

1

1

1

1

QTY

90

1

100

1

1

1

1

1

1

1

1

1

1

1

1

QTY

90

1

100

1

1

1

1

1

1

1

1

1

1

1

1

James L. ...

NAME: *James L. ...* OPERATION PROFILE SAS *2/19/89* 9:44 TUESDAY, MARCH 28, 1989 11

ITEM CD PCN 74081A ALC WR DATE ~~2/19/89~~ SHEET *4* OF *4*

OPER NUNB RCC OPER DESC HIST MAND OPER TYPE F HRS CD/LVL WCD WCD DATE A8119 QTY X HRS EQUIP CODE NOTES

130 MANPGC ASSY . . . S QTY X HRS

130 MANPGC ASSY . 1.00 P 0.2 IG09 1 0.2

[Signature]

SAS *2/19/89*

9:44 TUESDAY, MARCH 28, 1989 12

SHEET 1 OF 2

NAME *[Signature]* OPERATION PROFILE ALC WR DATE *[Signature]* RCC MANPGC
ITEM CD PCN 74061ASUB1 WCD WCODE A7167

OPER NUMB	RCC	OPER HIST MAND	MAND F	SKILL CD/LVL	QTY	%	HRS	EQUIP CODE	QTY	%	HRS	NOTES
05A	MANPGC	DIS/	1.00	T								
05A	MANPGC	DIS/		S								
05A	MANPGC	DIS/	1.00	P	0.2		0.2					
05B	MANPGC	ASSY	1.00	T								
05B	MANPGC	ASSY		S								
05B	MANPGC	ASSY	1.00	P	0.2		0.2	5139	1		0.2	
05C	MANPGC	ASSY	1.00	T								
05C	MANPGC	ASSY		S								
05C	MANPGC	ASSY	1.00	P	0.1		0.1					
05D	MANPGC	ASSY	1.00	T								
05D	MANPGC	ASSY		S								
05D	MANPGC	ASSY	1.00	P	0.2		0.2					
05E	MANPGC	ASSY	0.50	T								

9:44 TUESDAY, MARCH 28, 1989 13

SHEET 2 OF 2

SAS 4/19/89

OPERATION PROFILE

ALC WR

DATE

WCD

WCDDATE A7167

NAME *Chambers*
ITEM CD PCN 74061ASUB1

OPER NUMB
RCC
OPER DESC
HIST MAND
OCCR TYPE
MAND
F HRS
SKILL
CD/LVL

EQUIP
CODE

QTY % HRS

NOTES

OSE MANPGC ASSY S

OSE MANPGC ASSY 1.00 P

52.0

1

0.2 0009

1

48.0

WORK MEASUREMENT STANDARD DATA COMPUTATION SHEET				Page 1 of 1 Pages		DATE	
INSTRUCTIONS: Industrial Engineering Division will complete 'Work Measurement Requirements' and furnish cut sheets to applicable using activities for each type of computation sheet as required.				JOB ASSIGNED TO			
				Carl Mucher COMPUTED BY Carl Mucher			
WORK ORDER 74061A	PART NUMBER A2850-1	STOCK NUMBER 6615-00-857-0828	JOB STANDARD N/A	STATION NO. MNPG			
NOUN Rate Gyro TRU-2A/A		QUANTITY N/A	STD HRS PER N/A	PIECES N/A	TIME PER PIECE N/A		
WORK MEASUREMENT REQUIREMENTS: PRODUCTION SUPERVISOR LABOR STANDARD REVIEW							
Observations were made <u>26 Aug 82</u> through <u>3 Sep 82</u> in accordance with AFLCR 66-4 Work Sampling Techniques. Overall productivity was <u>89</u> %.							
CATEGORY	BASE HR/OCC	PF&D	STD HR/OCC	OCC FACTOR	STD HR/END ITEM		
Receive	.049	1.07	.05243	1.00	.05243		
Deseal	.339	1.07	.36273	1.00	.36273		
Disass Gyro	1.541	1.07	1.64887	1.00	1.64887		
D.C.I.R. Motor	.084	1.07	.08988	1.00	.08988		
Bal/Rebal							
Motor/End play	.084	1.07	.08988	1.00	.08988		
Reass Gyro	2.774	1.07	2.96818	1.00	2.96818		
Calibrate	1.061	1.07	1.13527	1.00	1.13527		
Fill/Seal/Leak Check	.177	1.07	.18939	1.00	.18939		
Inst-Trans- E-	.168	1.07	.17976	1.00	.17976		
CC-Check							
Final Functional	.460	1.07	.4922	1.00	.4922		
Fin-Vis-&-Prep	.465	1.07	.49755	1.00	.49755		
TOTAL 7.70614 7.71							
This total is manually computed and may vary slightly from E046 output. In accordance with AFLCR 66-4, para 3-10, all standards should be reviewed by affected supervisory personnel for completeness of work content. Production supervisors will be given 10 workdays to express in writing their reasons for nonconcurrence. If, after this time, no reply has been received from the coordinating agency, the standard will be considered coordinated and acceptable.							
APPROVALS		DATE	APPROVALS		DATE		
INDUSTRIAL ENGINEER			WORK CENTER FOREMAN				
N/A			N/A		10 Jan 83		
N/A		10 Jan 83	N/A				

SHOP FLOW DAY COMPUTATION FOR PRODUCTION NO: 74061A

AFLCR 66-4 Shop Flow Day Formula was used to establish this flow day standard as follows: Flow Days = A [(B ÷ C) + D + E] where A = 1.45; B = End Item Labor Standard; C = Direct Labor Hours Per Person Per Day adjusted for indirect categories and labor efficiency; D = Routine Delays; E = Unique Delays. Repair is being accomplished as a responsible shop.

ITEM	DESCRIPTION	-DA-
1	B = Labor Standard of <u>7.71</u> Hrs C = <u>7.66</u> Daily Labor Hrs Value "C" is calculated as follows: MANPC <u>C</u> .24 + .25 + .26 + .29 Indirect Average = <u>.1</u> Hours MANPC <u>C</u> Labor Efficiency = <u>97</u> % C = 8 Hours Minus Indirect Average Times Labor Efficiency	B 1.0
	D = Routine Delays a. Awaiting Maintenance (AWM) = 3.8 days b. One days supply at station awaiting maintenance = 4 days (average 4 stations for each C/N). This is necessary to maintain uninterrupted flow of items.	
	TOTAL	7
3	E = Unique Delays a. Machine processing <u>2.00</u> Day(s) b. Machine processing delays _____ Day(s) c. Routing to support shops _____ Day(s) d. Others (See Reverse Side) _____ Day(s)	
	TOTAL	2
	(See reverse side for details)	
4	Total flow days this shop (1 + 2 + 3)	10
	Work Shift Adjustment (Item 4 ÷ number of shifts). $10.806 \div 1$	10
	Sum of flow days for all shops (Item 5 x 1.45) $10.806 \times 1.45 = 15.6687$	16
6	(Final result to be rounded up to next whole day.)	

COMPUTED BY: SYLVIA H. BLACK

DATE: 2 OCT 84

TIME


3. E Unique Delays

a. Machine Processing

(1) Run In Motor (48 hrs ÷ 3 = 16)	16.00	2-7	2-24m
---------------------------------------	-------	-----	-------

$16.00 \div 8 \text{ hrs/day} = 2.00 \text{ days}$

PROCESS FLOW CHART PCN 74061A



1/19
RBD

SAS

PN: B2888-01
 OPERATION: ZPRT
 SAMPLE SIZE: 506
 MISSING FLOWTIMES: 2
 MANPOWER REQUIRED: 0
 AL: WARNER ROBBINS
 NSN: 74081A
 RCC: MANPGC
 GYRO SHOP, UNIT 3
 PCN: 74081A
 WCD: 74081A
 WCD DATE: A8119
 9:03 FRIDAY, FEBRUARY 24, 1989 3

PART OPERATION SUMMARY

PCN: 74081A
 WCD: 74081A
 WCD DATE: A8119
 PRIMARY OPERATION TYPE: ASSY MATERIAL TYPE:
 END ITEMS: OUTLIERS DELETED: 0

SKILL QTY FRACTION HOURS
 EQUIPMENT REQUIRED
 TIME FRACTION HOURS BATCH
 MIN MAX

HISTORICAL DATA

ACTUAL	RELATIVE FREQUENCY	DISTRIBUTION	PARAMETERS	D VALUE	D ALPHA
0	0	UNIFORM	0.0	127.0	0.809
2	2	TRIANGULAR	0.0	1.0127.0	0.757
4	4	NORMAL	5.9	13.7	0.333
6	6	LOGNORMAL	5.9	13.7	0.072
8	8	EXPONENTIAL	6.4	0.204	0.01
10	10				
12	12				
14	14				
16	16				
18	18				
20	20				
>=20	>=20				

OCCURRENCE FACTOR: 508
 OCCURRENCES: 508
 DISTRIBUTION OF CHOICE: HISTORICAL DISCRETE

SAS

PART OPERATION SUMMARY

9:03 FRIDAY, FEBRUARY 24, 1989

4

ALC WARNER ROBBINS RCC: MANPGC GYRO SHOP, UNIT 3

PN: 82888-01

OPERATION: ZPRT
SAMPLE SIZE: 1

NSN:

PCN: 74061ASUB1 WCD: WCD DATE: A7167
PRIMARY OPERATION TYPE: ASSY MATERIAL TYPE:
MISSING FLOWTIMES: 1 END ITEMS: OUTLIERS DELETED: 0

MANPOWER REQUIRED

SKILL	QTY	TIME		CATEGORY	QTY	EQUIPMENT REQUIRED		BATCH
		FRACTION	HOURS			FRACTION	HOURS	

HISTORICAL DATA

ACTUAL FREQ	RELATIVE FREQUENCY											D ALPHA
	0	10	20	30	40	50	60	70	80	90	100	
0	0	0	0	0	0	0	0	0	0	0	0	
1	0	0	0	0	0	0	0	0	0	0	0	
2	0	0	0	0	0	0	0	0	0	0	0	
3	0	0	0	0	0	0	0	0	0	0	0	
4	0	0	0	0	0	0	0	0	0	0	0	
5	0	0	0	0	0	0	0	0	0	0	0	
6	0	0	0	0	0	0	0	0	0	0	0	
7	0	0	0	0	0	0	0	0	0	0	0	
8	0	0	0	0	0	0	0	0	0	0	0	
9	0	0	0	0	0	0	0	0	0	0	0	
>=10	0	0	0	0	0	0	0	0	0	0	0	

DISTRIBUTION: UNIFORM
DISTRIBUTION: TRIANGULAR
DISTRIBUTION: NORMAL
DISTRIBUTION: LOGNORMAL
DISTRIBUTION: EXPONENTIAL

PARAMETERS: 0.0 0.0 0.0 0.2

VALUE: 0.0 0.0 0.0 0.2

OCCURRENCE FACTOR: 2

OCCURRENCES: 2

DISTRIBUTION OF CHOICE: HISTORICAL DISCRETE

WORK CONTROL DOCUMENT				1. DATE 8119		PAGE 1 OF 2 PAGES	
JOB ORDER NUMBER 74063A		3. QUANTITY 1		4. PRODUCTION SECTION/RCC "O" MNPGB		5. DATE SCHED	
PART NUMBER T3837-02		8. TECH DATA 5F6-4-3-23; 5F6-4-3-23-1				9. ITEM SERIAL NUMBER	
10. MODEL-DESIGN-SERIES		11. STOCK NUMBER 6615-00-768-5019		12. OPTIONAL NOTE: Use QQ-S-571 type SN60WRP solder. Observe all notes, cautions & warnings throughout the TO. MDC data required IAW MAOI 66-22.			
13. SERIAL NUMBER		14. NAME MC-1 Rate Gyro					
15. DISPATCH STATION	16. PDR/OP NO.	17. WORK TO BE ACCOMPLISHED			18. MECHANIC	19. "P"	20. "Q"
	010	Receive (Check data on WCD and AFTO Form 349. Clean gyro external surfaces.)					
	020 0100	Perform functional analysis. If serviceable, stamp condition tag and proceed to Step 090.					B
	020 0200 MNPGB	Perform functional analysis. If serviceable, stamp condition tag and proceed to Step 090.					B
	030	Unseal					
	040	Gyro Repair					
	050	Calibrate gyro					
	060	Final inside visual. Certify that this item does not contain any foreign objects such as tools or unattached components.					B
	070	Fill, seal and leak check					
	080 0100	Perform functional analysis. Stamp condition tag.					B
	080 0200 MNPGB	Perform functional analysis. Stamp condition tag.					B
21. FINAL DESTINATION		22. COORDINATION/INITIATING RSC SIGNATURE/DATE			23. DOCUMENT S/N		
DISPATCH	FUNCTIONAL CODE	a. MANPGB MANERG		b. MANPGB MANERG			
				c. MANSAA			

[illegible]

1. DATE 8119

PAGE 2 OF 2 PAGES

Dyal

WORK CONTROL DOCUMENT

1. DATE
6329

PAGE 1 OF 1 PAGES

JOB ORDER NUMBER
74063A

3. QUANTITY
1

4. PRODUCTION SECTION/RCC
"O" MNPCC/MNPGC

5. DATE SCHED
813-1

6. DATE COMP
JUL 29 1988

7. PART NUMBER
T383-22

8. TECH DATA
5F6-4-3-28
5F6-4-3-23-1

9. ITEM SERIAL NUMBER
64-962

10. MODEL-DESIGN-SERIES

11. STOCK NUMBER
6615-00-768-5019

12. OPTIONAL
NOTE: Use QQ-S-571 type SN60WRP solder.
Observe all notes, cautions and warnings
throughout T.O. MDC. Required IAW MAOI
66-22.

13. SERIAL NUMBER

14. NOUN
MC-1 RATE GYRO

15. DISPATCH STATION

16. PDR/OP NO.

17. WORK TO BE ACCOMPLISHED

18. MECHANIC

19. "P"

20. "Q"

1
1010

Receive (check data on WCD and AFTO Form 349.
Clean gyro external surfaces.) JUN 13 1988

WR
PA
6013

2
1010

Pretest Essential Repair
My for Overhaul JUN 13 1988

WR
PA
6013

3
1020

Unseal

WR
PA
6245

4
1030

Gyro Repair

WR
PA
7117
7-26-88

B

5
1050

Calibrate Gyro

WR
PA
7117
7-26-88

B

6
1050

Final Inside visual. Certify that this item
does not contain any foreign objects such as
tools or unattached components.

WR
PA
7117
7-26-88

B

7
1060

Fill, Seal and Leak Check

WR
PA
7117
7-26-88

8
1080

Final Functional Analysis, Condition Tag. JUL 29 1988

WR
PA
6204

B

9
1090

Final Prep. Final Visual complete AFLC Form
959, AFTO Form 349. Install WR-ALC Decal,
Attach Condition tag. JUL 29 1988

WR
5615

21. FINAL DESTINATION
DISPATCH FUNCTIONAL CODE

22. COORDINATION/INITIATING RCC SIGNATURE/DATE

23. DOCUMENT S/N

DISPATCH FUNCTIONAL CODE

MANE David J. Blythe
MANPCC James E. Boyd
MANE William D. Boyd
MANSA J. T. Powell

DOCUMENT S/N

Approved 2853 ABC/L
ab 87) (DLN)

PROGRAM NAME: 300294
 \CPIN: 81H-MC1/5019-0001-00A
 \DATE OF LAST REVISION: 08-MAY-87
 \TYPE: SWITCHING RATE GYRO HC-1
 \ATTORNEY STOCK NUMBER: 6615-00-768-5019
 \MFR/PART NUMBER: R.C. ALLEN T3837-02

JUL 29 1988

WR
PA
6204

\OPERATOR'S NAME: FLOYD
 \TEST STATION: RATE STATION # 1
 \DATE & TIME OF TEST: 29-JUL-88 09:11:12
 #GYRO IN TEST MOUNT POSITION 1 IS SERIAL NUMBER 67-7239
 #GYRO IN TEST MOUNT POSITION 2 IS SERIAL NUMBER 64-962

/ SPINMOTOR KURUP TESTS

NORMALLY CLOSED TURN INDICATOR	2	Onms	00050.0000	00000.0000	00002.1550	PASS	29-JUL-88 09:13:10
RUNNING CURRENT PHASE-A	2	mAmps	00087.0000	00000.0000	00063.5730	PASS	29-JUL-88 09:18:45

/ SWITCHING AND UNSWITCHING TIME TESTS

SWITCHING TIME 3.0 D/S CW	2	Sec	00004.0000	00000.0000	00001.2833	PASS	29-JUL-88 09:27:05
UNSWITCHING TIME 3.0 D/S CW	2	Sec	00015.0000	00000.0000	00004.0166	PASS	29-JUL-88 09:27:11
SWITCHING TIME 0.75 D/S CW	2	Sec	00008.0000	00000.0000	00003.0999	PASS	29-JUL-88 09:27:45
UNSWITCHING TIME 0.75 D/S CW	2	Sec	00015.0000	00000.0000	00004.0333	PASS	29-JUL-88 09:27:51
SWITCHING TIME 0.333 D/S CW	2	Sec	00020.0000	00000.0000	00006.1499	PASS	29-JUL-88 09:28:29
UNSWITCHING TIME 0.333 D/S CW	2	Sec	00015.0000	00000.0000	00003.2499	PASS	29-JUL-88 09:28:34
SWITCHING TIME 0.25 D/S CW	2	Sec	00030.0000	00000.0000	00010.3333	PASS	29-JUL-88 09:29:16
UNSWITCHING TIME 0.25 D/S CW	2	Sec	00015.0000	00000.0000	00003.2333	PASS	29-JUL-88 09:29:21
SWITCHING TIME 3.0 D/S CCW	2	Sec	00004.0000	00000.0000	00001.3333	PASS	29-JUL-88 09:29:54
UNSWITCHING TIME 3.0 D/S CCW	2	Sec	00015.0000	00000.0000	00004.7666	PASS	29-JUL-88 09:30:00
SWITCHING TIME 0.75 D/S CCW	2	Sec	00008.0000	00000.0000	00003.6833	PASS	29-JUL-88 09:30:36
UNSWITCHING TIME 0.75 D/S CCW	2	Sec	00015.0000	00000.0000	00004.0333	PASS	29-JUL-88 09:30:41
SWITCHING TIME 0.333 D/S CCW	2	Sec	00020.0000	00000.0000	00010.2166	PASS	29-JUL-88 09:31:23
UNSWITCHING TIME 0.333 D/S CCW	2	Sec	00015.0000	00000.0000	00003.2999	PASS	29-JUL-88 09:31:28
ING TIME 0.25 D/S CCW	2	Sec	00030.0000	00000.0000	00015.6833	PASS	29-JUL-88 09:32:15
CHING TIME 0.25 D/S CCW	2	Sec	00015.0000	00000.0000	00003.2666	PASS	29-JUL-88 09:32:19

/ YAW OSCILLATION TESTS

TURN INDICATOR 1 DEG 0.5 HZ	2	Onms	.10000E+33	00050.0000	.10000E+33	PASS	29-JUL-88 09:39:40
TURN INDICATOR 2 DEG 0.125 HZ	2	Onms	.10000E+33	00050.0000	.10000E+33	PASS	29-JUL-88 09:41:15

/ STEADY-STATE RATE AND YAW OSCILLATION TESTS

TURN INDICATOR CLOSED CW	2	Onms	00050.0000	00000.0000	00002.0400	PASS	29-JUL-88 09:47:01
TURN INDICATOR OPEN CW	2	Onms	.10000E+33	00050.0000	.10000E+33	PASS	29-JUL-88 09:47:23
TURN INDICATOR CLOSED CCW	2	Onms	00050.0000	00000.0000	00002.0410	PASS	29-JUL-88 09:48:00
TURN INDICATOR OPEN CCW	2	Onms	.10000E+33	00050.0000	.10000E+33	PASS	29-JUL-88 09:48:21

/ POWER FAIL TESTS

TURN INDICATOR OPEN CW	2	Onms	.10000E+33	00050.0000	.10000E+33	PASS	29-JUL-88 09:50:47
------------------------	---	------	------------	------------	------------	------	--------------------

\END

OPERATION TIME SHEET

NAME R.V. EYCOOPER ALG WR DATE 4-6-81 RCC MAN/PGC SHEET 1 OF 1

OPERATION NUMBER	RCC	OPERATION DESCRIPTION	MANDATORY OCCURRENCE FACTOR	OPERATION TYPE	MANPOWER			EQUIPMENT			TIME REQUIRED		DATA SOURCE COMMENTS	
					BILL CODE/ LEVEL	QTY.	%	HRS.	EQUIPMENT CODE	QTY.	%	HRS.		
0000 HW MANAGE		REC	1	TRANSIT	1	1							C. DRIVER RANMER MAR MILLER OPER & A SCHEDULED	
				SETUP										
				PROCESS										
		↑		TRANSIT										
				SETUP										
				PROCESS										
		ALL WCD OPERATIONS LISTED IN CD OPER PROFILE		TRANSIT										
				SETUP										
				PROCESS										
		↑		TRANSIT										
				SETUP										
				PROCESS										
9999 MANAGE		SELL	1	TRANSIT									D. HARRELSON SIGNED MANAGE MAR MILLER OPERATOR & A SCHEDULED	
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										
				TRANSIT										
				SETUP										
				PROCESS										

9:44 TUESDAY, MARCH 28, 1989 14

SHEET 1 OF 3

SAS

OPERATION PROFILE

DATE

ALC WR

WCD

ITEM CD PCN 74063A

R. Palmer-Low

WCDDATE B8119

OPER NOMB
10 MANPGC REC 0.97 T

OPER HIST MAND OPER MAND
DESC OCCR TYPE F HRS CD/LVL

EQUIP CODE

QTY

%

HRS

QTY

%

HRS

NOTES

10 MANPGC REC S

10 MANPGC REC 1.00 P

0.1 IG09

1

0.1

20 MANPGC NDI 0.97 T

20 MANPGC NDI S

20 MANPGC NDI 1.00 P

0.2 IG09

1

0.2

6183
2900
2626

20 MANPGC NDI P

IG10

1

0.8

0450

30 MANPGC PROC 0.99 T

30 MANPGC PROC S

30 MANPGC PROC 0.88 P

1.5 IG09

1

1.5

40 MANPGC REP 0.99 T

40 MANPGC REP S

40 MANPGC REP 0.88 P

0.3 IG09

1

2.3

0.2
0.1
0.1

Handwritten signature

45 MANPGC REP

45 MANPGC REP

45 MANPGC REP

45 MANPGC REP

50 MANPGC ASSY 0.99

50 MANPGC ASSY

50 MANPGC ASSY

60 MANPGC NDI 0.98

60 MANPGC NDI

60 MANPGC NDI

70 MANPGC PROC 0.97

70 MANPGC PROC

9:44 TUESDAY, MARCH 28, 1989 16

SHEET 3 OF 3

NAME *Robert...*
 ITEM CD PCN 74083A
 OPER NUMB
 70 MANPGC PROC
 80 MANPGC NDI
 80 MANPGC NDI
 80 MANPGC NDI
 80 MANPGB NDI
 90 MANPGC ASSY
 90 MANPGC ASSY
 90 MANPGC ASSY

OPERATION PROFILE

ALC WR WCD
 DATE WCD DATE B8119
 QTY % HRS
 1 0.8

OPER HIST MAND OPER MAND
 OCCR OCCR TYPE F HRS
 CD/LVL SKILL
 IG09 IG10

QTY % HRS

EQUIP
 CODE

80	MANPGC	NDI	0.99	T	3.0					
80	MANPGC	NDI		S						
80	MANPGC	NDI	1.00	P	6.8	IG09	1	0.5	6183	1
80	MANPGB	NDI		P	1.0	IG10	1	0.8	0450	1
90	MANPGC	ASSY	0.97	T						
90	MANPGC	ASSY		S						
90	MANPGC	ASSY	1.00	P	2.1	IG09	1	0.1		

0.5
 0.5
 0.5
 0.8

WORK MEASUREMENT STANDARD DATA COMPUTATION SHEET		Page 1 of 1 Pages	DATE 21 MAR 80
INSTRUCTIONS: Industrial Engineering Division will complete "Work Measurement Requirements" and furnish cut sheets to applicable using activities for each type of computation sheet as required.		JOB ASSIGNED TO L. HORNE	
		COMPUTED BY L. HORNE	
WORK ORDER 74063A	PAR. NUMBER	STOCK NUMBER 6615-00-768-5019	JOB STANDARD N/A
MOON MC-1 GYRO		QUANTITY N/A	STD HRS PER N/A
WORK MEASUREMENT REQUIREMENTS.		PIECES N/A	TIME PER PIECE N/A
COORDINATION OF LABOR STANDARD WITH PRODUCTION SUPERVISOR			
Observations were made 14 JAN 80 through 1 FEB 80 in accordance with AFLCR 66-4 Work Sampling Techniques. Overall productivity 80%.			
CATEGORY	STANDARD HOURS		OCC FACTOR
RECEIVE - PRETEST	.185		1.00
UNSEAL	.447		.88
GYRO - REPAIR	4.124		.88
BUILDUP - TEST	.596		.88
MOTOR - REPAIR	.718		.74
MOTOR - TEST	.319		.74
CALIBRATE	1.359		.88
SEAL	.694		.88
FINAL - FUNCT - TEST	.331		1.0
FINAL - PREP & TAG	.777		1.00
TOTAL		9.55	
This total is manually computed and may vary slightly from E046 output.			
In accordance with AFLCR 66-4, para 3-10, coordinating agencies are allowed 10 working days from date of this form to express in writing reasons for noncoordination ("insufficient time allowed" is not to be considered). If, after this time, no reply has been received from the coordinating agency, the standard will be considered coordinated and acceptable.			
APPROVALS INDUSTRIAL ENGINEER	DATE	APPROVALS WORK CENTER FOREMAN	DATE
N/A	N/A	<i>[Signature]</i>	28 APR 80
PROCESS TECHNICIAN		N/A	

AFLC FORM 77A
REPLACES AWC FORM 77A, SEP 69, WHICH MAY BE USED.
AFLC-WPAFB-APR 73 213

SHOP FLOW DAY COMPUTATION FOR PRODUCTION NO: 74063A

AFLCR 66-4 Shop Flow Day Formula was used to establish this flow day standard as follows: Flow Days = A [(B ÷ C) + D + E] where A = 1.45; B = End Item Labor Standard; C = Direct Labor Hours Per Person Per Day adjusted for indirect categories and labor efficiency; D = Routine Delays; E = Unique Delays. Repair is being accomplished as a responsible shop.

EP	DESCRIPTION	DAYS
	B = Labor Standard of <u>9.55</u> Hrs C = <u>7.66</u> Daily Labor Hrs Value "C" is calculated as follows: MANPG <u>C</u> .24 + .25 + .26 + .29 Indirect Average = <u>.1</u> Hours MANPG <u>C</u> Labor Efficiency = <u>97</u> % C = 3 Hours Minus Indirect Average Times Labor Efficiency	B ÷ C <u>1.25</u>
	= Routine Delays a. Awaiting Maintenance (AWM) = 3.8 days b. One days supply at station awaiting maintenance = 4 days (average 4 stations for each C/N). This is necessary to maintain uninterrupted flow of items.	
	TOTAL	7.80
	E = Unique Delays a. Machine processing _____ Day(s) b. Machine processing delays _____ Day(s) c. Routing to support shops _____ Day(s) d. Others (See Reverse Side) _____ Day(s)	
	TOTAL	3.32
	Total flow days this shop (1 + 2 + 3)	12.4
	Work Shift Adjustment (Item 4 ÷ number of shifts).	12.4
	Sum of flow days for all shops (Item 5 x 1.45) (Final result to be rounded up to next whole day.)	18

COMPUTED BY: A Bridges / MANEG

DATE: 4 OCT 84

3. Run-in motor 48 HRS Page 2-9 Para t.

Run-in Ball Bearings 12 HRS Page 2-9 para ac

Bake gyro 2 HRS

page 2-9 para ad

allow to cool- 1 HR

Bake ADHESIVE 2 HRS

page 3-11 para aab


connect Vacuum Hose BAKE

1 HR

page 3-12 para aag

COOL gyro 1 1/2 HR.

PROCESS FLOW CHART PCN 74063A



268 4/19/89

SAS

PART OPERATION SUMMARY

9:03 FRIDAY, FEBRUARY 24, 1989 5

ALC: WARNER ROBBINS RCC: MANPGC GYRO SHOP, UNIT 3
 NSN: PCN: 74063A WCD: WCD DATE: 88119

PN: T3837-02
 OPERATION: ZPRT
 SAMPLE SIZE: 292 MISSING FLOWTIMES: 0 PRIMARY OPERATION TYPE: ASSY MATERIAL TYPE: OUTLIERS DELETED: 1

----- MANPOWER REQUIRED ----- EQUIPMENT REQUIRED -----
 SKILL QTY FRACTION HOURS CODE CATEGORY QTY FRACTION HOURS BATCH MIN MAX

HISTORICAL DATA

ACTUAL FREQ	0	10	20	30	40	50	60	70	80	90	100	DISTRICTION	PARAMETERS	D VALUE	D ALPHA
0	0	0	0	0	0	0	0	0	0	0	0	UNIFORM	0.0	460.0	0.724
20	0	0	0	0	0	0	0	0	0	0	0	TRIANGULAR	0.0	1.0460.0	0.620
40	0	0	0	0	0	0	0	0	0	0	0	NORMAL	41.2	69.4	0.281
60	0	0	0	0	0	0	0	0	0	0	0	LOGNORMAL	41.2	69.4	0.065
80	0	0	0	0	0	0	0	0	0	0	0	EXPONENTIAL	41.7		0.139
100	0	0	0	0	0	0	0	0	0	0	0				0.17
120	0	0	0	0	0	0	0	0	0	0	0				
140	0	0	0	0	0	0	0	0	0	0	0				
160	0	0	0	0	0	0	0	0	0	0	0				
180	0	0	0	0	0	0	0	0	0	0	0				
>=00	0	0	0	0	0	0	0	0	0	0	0				

OCCURRENCE FACTOR: OCCURRENCES: 293
 DISTRIBUTION OF CHOICE: LOGNORMAL

WORK CONTROL DOCUMENT					1. DATE 8133		PAGE 1 OF 2 PAGES		
2. ORDER NUMBER 74146A/74282A		3. QUANTITY 1		4. PRODUCTION SECTION/RCC "O" MNP GC		5. DATE SCHED		6. DATE COMP	
7. PART NUMBER 17223-1A/423040-2			8. TECH DATA 5N6-2-9-13/13-1/14; 5N6-2-4-13/13-1/14				9. ITEM SERIAL NUMBER		
10. MODEL-DESIGN-SERIES		11. STOCK NUMBER 6615-00-581-5792 6615-00-515-6000		12. OPTIONAL NOTE: Observe all notes, cautions and warnings throughout T.O. MDS data required IAW MAOI 66-22, Appx 8. Use QQ-571 type SN60WRP solder.					
13. SERIAL NUMBER		14. NAME J-4 Directional Control							
15. DISPATCH STATION	16. PON/OP NO.	17. WORK TO BE ACCOMPLISHED				18. MECHANIC	19. "P"	20. "Q"	
	010	Receive; Ascertain data correctness of WCD and AFTO 349. Clean external surfaces.							
	020 0100	Perform functional test (Pretest) If serviceable, proceed to Step 200.						B	
	020 0200 MNPGB	Perform functional test (Pretest) If serviceable, proceed to Step 200.						B	
	030	Unseal							
	040	Disassemble gyro assembly							
	050	Replace motor (As required)							
	060	Clean, inspect and repair gyro							
	070	Reassemble gyro assembly (Use QQ-S-571 SN60WRP solder)							
	080	Inner gimbal end play						B	
	090	Pre-seal Test							
21. FINAL DESTINATION		22. COORDINATION/INITIATING RCC SIGNATURE/DATE				23. DOCUMENT S/N			
DISPATCH	FUNCTIONAL CODE	MANPGC <i>Raymond D. Liff</i> MANPGB <i>John E. Broy</i> MANERG <i>David L. Broy</i>				MAQNG <i>16 May 88</i> MANSKA <i>16 May 88</i>			

WORK CONTROL DOCUMENT (CONTD)				1. DATE 0119		PAGE 2 OF 2 PAGES	
13. DISPATCH STATION	16. PON/OP NO.	17. WORK TO BE ACCOMPLISHED	18. MECHANIC	19. "P"	20. "Q"		
	100	Calibrate gyro NOTE: Steps 13-16 may be accomplished just prior to step 13 (Ref Note, para 3-61)					
	110	Visual inspection; certify that this item does not contain any foreign objects such as tools or unattached components.			B		
	120	Seal and leak test (Use QQ-S-571 SN 60WRP solder)					
	130	Insulation resistance test					
	140	Azimuth torquer calibration					
	150	Installation of Azimuth torque resistors					
	160	Torquer total circuit resistance test					
	170	Perform functional test			B		
	180	RWT _____ DATE _____ RANDOM _____ POSITION _____ TIME _____ RERUN _____			B		
	190	Paint					
	200 0100	Perform functional analysis (Final test) Stamp condition tag.			B		
	200 0200 MNPGB	Perform functional analysis (Final test) Stamp condition tag.			B		
	210	Final prep, final visual, complete AFLC Form 959, check for TO mod compliance. Complete AFTO 349, install WR-ALC decals IAW MAOI 66-40. Attach condition tag.					

1. DATE 8119

PAGE 2 OF 2 PAGES

WORK CONTROL DOCUMENT				1. DATE 7205	PAGE 1 OF 2 PAGES
2. JOB ORDER NUMBER 74146A & 74282A		3. QUANTITY 1	4. PRODUCTION SECTION/RCC "O" MNPCC	5. DATE SCHED	6. DATE COMP
7. PART NUMBER 5107765-1 AP86A1		8. TECH DATA 5N6-2-4-13 5N6-2-9-13			9. ITEM SERIAL NUMBER
10. MODEL-DESIGN-SERIES		11. STOCK NUMBER 6615-00-832-3196	12. OPTIONAL		
13. SERIAL NUMBER		14. ROOM Gyro Motor (J4)			
15. DISPATCH STATION	16. PWR/OP NO.	17. WORK TO BE ACCOMPLISHED	18. MECHANIC	19.	20.
	5a	Clean and inspect motor			
	5b	Disassemble motor assembly			
	5c	Clean and inspect parts			
	5d	Clean, lubricate and install bearings and set preload			
	5e	Balance rotor assembly			
	5f	Inside visual. Certify that this item does not contain any foreign objects such as tools or unattached components.			B
	5g	Install rotor into housing and cap			
	5h	Bell jar run-in			
	5i	Seal motor assembly			
	5j	Leak check and evacuate motor assembly			
21. FINAL DESTINATION		22. COORDINATION/INITIATING RCC SIGNATURE/DATE		23. DOCUMENT S/N	
DISPATCH	FUNCTIONAL CODE	A. <i>[Signature]</i> MANPCC		B. <i>[Signature]</i> MANSA	
		C. <i>[Signature]</i> MANPCC		D. <i>[Signature]</i> MANSA	

[illegible]

WORK CONTROL DOCUMENT						1. DATE 8193	PAGE 1 OF 2 PAGES	
2. JOB ORDER NUMBER 74146A/7		3. QUANTITY 1	4. PRODUCTION SECTION/RCC "O" MNP GC		5. DATE SCHED 8196	6. DATE COMP 88214		
PART NUMBER 17223-1A/			8. TECH DATA 5N6-2-9-13/13-1/14			7. ITEM SERIAL NUMBER 7669		
10. MODEL-DESIGN-SERIES		11. STOCK NUMBER 6615-00-581-5792		12. OPTIONAL NOTE: Observe all notes, cautions and warnings throughout T.O. MDS data required IAW MAOI 66-22, Appx 8. Use QQ-571 type SN60WRP solder.				
13. SERIAL NUMBER		14. SOIN J-4 Directional Control						
15. DISPATCH STATION	16. PBN/OP NO.	17. WORK TO BE ACCOMPLISHED				18. MECHANIC	19.	20.
	010	Receive; Ascertain data correctness of WCD and AFTO 349. Clean external surfaces.				WR PA 6019		
	020 0100	Perform functional test (Pretest) If serviceable, proceed to Step 200.				WR PA 6019		B
	020 0200 MNPGB	Perform functional test (Pretest) If serviceable, proceed to Step 200.				WR PA 6019		B
	030	Unseal				WR PA 6019		
	040	Disassemble gyro assembly				WR PA 6019		
	050	Replace motor (As required)				WR PA 6019		
	060	Clean, inspect and repair gyro				WR PA 6019		
	070	Reassemble gyro assembly (Use QQ-S-571 SN60WRP solder)				WR PA 6019		
	080	Inner gimbal end play				WR PA 6019		B
	090	Pre-seal Test				WR PA 6019		

21. FINAL DESTINATION		22. COORDINATION/INITIATING RCC SIGNATURE/DATE		23. DOCUMENT S/N
DISPATCH	FUNCTIONAL CODE	MANPGC	MAQNG	
		MANPGB	MANSAA	
		MANERG		

WORK CONTROL DOCUMENT (CONT'D)			1. DATE 8119	PAGE 2 OF 2 PAGES	
15. DISPATCH STATION	16. PDM/OP NO.	17. WORK TO BE ACCOMPLISHED	18. MECHANIC	19.	20. "Q"
	100	Calibrate gyro NOTE: Steps 13-16 may be accomplished just prior to step 13 (Ref Note, para 3-61) JUL 27 1988	WR M 6473		
	110	Visual inspection; certify that this item does not contain any foreign objects such as shrapnel or unattached components. JUL 27 1988	WR PA 6019		B
	120	Seal and leak test (Use QQ-S-571 SN 60WRP solder) 26 JUL 1988	WR PA 6019		
	130	Insulation resistance test JUL 27 1988	WR PA 6019		
	140	Azimuth torquer calibration JUL 27 1988 228	WR M 6473		
	150	Installation of Azimuth torque resistors JUL 27 1988	WR PA 6019		
	160	Torquer total circuit resistance test JUL 27 1988	WR PA 6019		
	170	Perform functional test JUL 27 1988	WR PA 6019		B
	180	RWT RANDOM 2 TIME 0935-1730 DATE 27 JUL 1988 POSITION 13 RERUN	WR PA 6019		B
	190	Paint JUL 23 1988	WR PA 6021		
	200 0100	Perform functional analysis (Final test) Stamp condition tag. 29 JUL 1988	WR PA 6031		B
	200 0200 MNPGB	Perform functional analysis (Final test) Stamp condition tag. 29 JUL 1988	WR PA 6031		B
	210	Final prep, final visual, complete AFLC Form 959, check for TO mod compliance. Complete AFTO 349, install WR-ALC decals IAW MAOI 66-40. Attach condition tag. AUG 1988	WR M 6473		

\PROGRAM NAME: 300175
 \CPIN: 81H-GYR/J4B/DR-U001-00A
 \DATE OF LAST REVISION: 19-OCT-87
 \UUT TYPE: DIRECTIONAL GYRO J-4
 \UUT NATIONAL STOCK NUMBER: 6615-00-581-5792
 \UUT MFR/PART NUMBER: BENDIX 17223-1A
 \OPERATOR'S NAME: DUNNAM
 \TEST STATION: DIRECTIONAL STATION #1
 \DATE & TIME OF TEST: 28-JUL-88 22:46:10

29 JUL 1988

#GYRO IN TEST MOUNT POSITION 1 IS SERIAL NUMBER 7669
 #GYRO IN TEST MOUNT POSITION 2 IS SERIAL NUMBER 807116

*

*

IMPORTANT NOTE CONCERNING THE STATIC RESISTANCE TESTS

*

*

*

If a failure of Static Resistance should occur, the operator may retest the UUT Static
 Resistance manually.

*

*

If an in-tolerance measurement is obtained in this manner, then the previous failure is
 to be ignored.

*

*

\

STATIC RESISTANCE TESTS

AUTOPILOT ROTORS J102-B TO A	1	OHM	00209.0000	00171.0000	00185.1200	PASS	28-JUL-88 22:47:22
AZIMUTH TORQUER J101-U TO V	1	OHM	04203.8000	03250.0000	03582.7800	PASS	28-JUL-88 22:47:31
AZIMUTH TORQUER J101-U TO F	1	OHM	02101.9000	011701.9000	01013.1200	PASS	28-JUL-88 22:47:39
AZIMUTH ROTOR J101-W TO H	1	OHM	00049.5000	00040.5000	00041.2064	PASS	28-JUL-88 22:47:48
BRAKE SOLENOID J101-P TO R	1	OHM	00784.5000	00643.5000	00707.1100	PASS	28-JUL-88 22:47:56
LATITUDE CORRECTION J101 M-U	1	OHM	32025.0000	28975.0000	30733.0500	PASS	28-JUL-88 22:48:04

/

RUN UP TESTS

STARTING CURRENT- PHASE B	1	MA	00170.0000	00000.0000	00147.1330	PASS	28-JUL-88 22:49:04
STARTING OSCILLATION TEST	1	---	00000.0000	00000.0000	00000.0000	PASS	28-JUL-88 22:49:05
SPINMOTOR SPEED	1	RPM	24300.0000	23500.0000	24000.0000	PASS	28-JUL-88 22:57:34
RUNNING CURRENT- PHASE B	1	MA	00130.0000	00000.0000	00099.8650	PASS	28-JUL-88 23:01:05

/

RUN DOWN TESTS

RUN DOWN RATE	1	RPM/H	03000.0000	03000.0000	02099.9999	PASS	28-JUL-88 23:06:01
---------------	---	-------	------------	------------	------------	------	--------------------

/

HEADING STABILITY TESTS

BANK RIGHT ERROR ANGLE	1	DEG	00002.0000	00000.0000	.15000E+00	PASS	28-JUL-88 23:08:11
BANK LEFT ERROR ANGLE	1	DEG	00002.0000	00000.0000	.10000E+00	PASS	28-JUL-88 23:10:22

/

GIMBAL FREEDOM TESTS

BANK RIGHT ERROR ANGLE	1	DEG	00004.0000	00000.0000	.29999E+00	PASS	28-JUL-88 23:12:43
BANK LEFT ERROR ANGLE	1	DEG	00004.0000	00000.0000	.90000E-01	PASS	28-JUL-88 23:15:00

/

SYNCHRO OUTPUT TESTS

AUTOPILOT OUTPUT-VOLTAGE	1	VOLTS	00018.9500	00017.4500	00018.1000	PASS	28-JUL-88 23:16:22
AZIMUTH OUTPUT-VOLTAGE	1	VOLTS	00012.3000	00011.3000	00012.0200	PASS	28-JUL-88 23:17:15
AUTOPILOT PHASING OUTPUT	1	DEG	00048.0000	00042.0000	00045.1400	PASS	28-JUL-88 23:18:03
AZIMUTH PHASING OUTPUT	1	DEG	00048.0000	00042.0000	00045.0600	PASS	28-JUL-88 23:18:51

/

DRIFT TESTS

DRIFT RATE	1	DEG/HR	00003.0000	-00003.0000	00001.6000	PASS	28-JUL-88 23:35:08
------------	---	--------	------------	-------------	------------	------	--------------------

/

LATITUDE CORRECTION TESTS

CORRECTED DRIFT RATE- 30 NORTH	1	DEG/HR	00004.0000	-00004.0000	.28000E+00	PASS	28-JUL-88 23:51:08
CORRECTED DRIFT RATE- 60 NORTH	1	DEG/HR	00004.0000	-00004.0000	00000.0000	PASS	29-JUL-88 00:06:22
CORRECTED DRIFT RATE- 90 NORTH	1	DEG/HR	00004.0000	-00004.0000	00002.7999	PASS	29-JUL-88 00:21:36
CORRECTED DRIFT RATE- 90 SOUTH	1	DEG/HR	00004.0000	-00004.0000	00001.8500	PASS	29-JUL-88 00:36:49

\END

OPERATION LOG

NAME R. VANDERKAM ALC NR DATE 4-6-61 RCC MAN/REC SHEET 1 OF 1

PCN 74146A WCD NA WCD DATE 8/33

OPERATION NUMBER	RCC	OPERATION DESCRIPTION	MANDATORY OCCURRENCE FACTOR	OPERATION TYPE	MANPOWER			EQUIPMENT			DATA SOURCE COMMENTS	
					SKILL CODE/LEVEL	CITY	TIME REQUIRED %	TIME REQUIRED HRS	EQUIPMENT CODE	QTY	TIME REQUIRED %	TIME REQUIRED HRS
IN	MAY 4	REC	1	TRANSIT								
				SETUP								
				PROCESS								
				TRANSIT	1 IG09	1		0.1	STD			
				SETUP								
				PROCESS								
9999	MAY 4	SELL	1	TRANSIT								
				SETUP								
				PROCESS								
				TRANSIT	1 IG09	1		0.1	STD			
				SETUP								
				PROCESS								

C. Decker
RAN/EE
MAR MILLER OPER
& A SCHEDULED

D. HARRISON
OPER/EL MAN/EE
MAR MILLER
OPER/EL
& A SCHEDULED

ALL WCD OPERATIONS
LISTED IN CD OPER PROFILE

SAS

OPERATION PROFILE

ALC WR

DATE _____

WCDDATE 8133

WCD

NAME E. C. Anderson

ITEM CD PCN 74146A

[illegible][illegible]EQUIP
CODE

QTY

SR

381

NOTES

RCC MANPGC

QTY

*

381

NOTES

10 MANPGC. REC. 2

10 MANPGC REC 1.00P

IG09

0.1

20	MANPGC	NDI	0.99	T
----	--------	-----	------	---

20 MANPGC NDI . S

20 MANPGC NDI : 1000 P

145-1609

05 A12E

•

20 MANPGB NDI . P

16
1910

SECRET

:

30	MANPGC	DIS	0.99	T

30 MANPGC DIS . S

30 MANPGC DIS . 1.00 P

0.1 IG09

U

40	MANPGC	DIS	0.99	T
----	--------	-----	------	---

40 MANPGC DIS . S

40 MANPGC DIS : 1020P

✓ 1609

A
C

9:44 TUESDAY, MARCH 28, 1989 18

SHEET 2 OF 2

OPERATION PROJECT
SAS

887
128/151/14

E. J. Connelley

ITEM CD PCN 74146A

DA
WCDDATE 8133

WCD

ALC WR

128/13/1A

[illegible][illegible]

Handwritten signature

9:44 TUESDAY, MARCH 28, 1989 19
SHEET 3 OF 6

OPERATION PROFILE										SAS	
NAME <i>E. Hammer</i>										DATE <i>8/3/89</i>	
ITEM CD PCN 74148A										WCCDATE 8133	
OPER HST MAND OPER MAND										EQUIP	
NUMB RCC DESC OCCR TYPE F HRS CD/LVL										CODE	
90	MANPGC	ASSY	0.99	T						QTY	% HRS
90	MANPGC	ASSY		S							
90	MANPGC	ASSY		1.00P		2.4	IG09			1	0.4
100	MANPGC	ASSY	0.98	T							
100	MANPGC	ASSY		S							
100	MANPGC	ASSY		1.00P		0.5	IG09			1	0.5
100	MANPGC	ASSY		P						1	0.5
110	MANPGC	NDI	0.99	T							
110	MANPGC	NDI		S							
110	MANPGC	NDI		1.00P		0.1	IG09			1	0.1
120	MANPGC	ASSY	1.00	T							
120	MANPGC	ASSY		S							
120	MANPGC	ASSY		1.00P		0.7	IG09			1	0.7

[Signature]

ITEM CD PCN 74146A SHEET 6 OF 6

OPER NUMB OPER HIST MAND OPER MAND SKILL WCD WCD DATE SAS

RCC MANPGC ASSY 1.00 T

210 MANPGC ASSY S

210 MANPGC ASSY 1.00 P 0.4 IG09 0.4

RCC MANPGC

QTY % HRS

EQUIP CODE

QTY % HRS

QTY

CD/LVL

F HRS

MAND

OCOR

TYPE

WCD

WCD

DATE

SAS

NOTES

NAME: *Richard S. Chubb*

ITEM CD PCN 74148ASUB1

OPER NUMB
OPER HIST MAND OPER
DESC OCCR TYPE F HRS
03A MANPGC DIS T

ALC WR
OPERATION PROFILE
DATE

WCDDATE 7205

SKILL
CD/LVL

EQUIP
CODE

SAS

9:44 TUESDAY, MARCH 28, 1989 23

SHEET 1 OF 4

RCC MANPGC

NOTES

QTY % HRS

QTY % HRS

QTY % HRS

QTY % HRS

QTY % HRS

QTY % HRS

QTY % HRS

QTY % HRS

05A MANPGC. DIS S

05A MANPGC DIS 1.00 P 0.1 IG09

05B MANPDA PROC T

05B MANPDA PROC S

05B MANPDA PROC 1.00 P

05C MANPGC DIS T

05C MANPGC DIS S

05C MANPGC DIS 1.00 P 0.1 IG09

05D MANPGC ASSY T

05D MANPGC ASSY S

05D MANPGC ASSY 1.00 P 1.01 IG09

05E MANPGC ASSY T

3.24 hrs

NAME Richard C. Brown

SAS

OPERATION PROFILE

ALC WR

DATE _____

WCD

WCDDATE 7205

ITEM CD PCN 74146ASUB1

OPER NUMB	RCC	OPER DESC	HIST OCCR	MAND OCCR	OPER TYPE	MAND F	HRS	SKILL CD/LVL	QTY	%	HRS	EQUIP CODE
--------------	-----	--------------	--------------	--------------	--------------	-----------	-----	-----------------	-----	---	-----	---------------

OSI MANPGC ASSY

OSI	MANPGC.	ASSY	1.00 P	2.00
-----	---------	------	--------	-----------------

05J MANPGC ASSY

05J MANPGC ASSY

05J MANPGC ASSY 1.00P 17.0

05K MANPGC ASSY

05K MANPGC ASSY S

05K MANPGC ASSY 1020P 60.0

05L MANPGC NDI T

05L MANPGC NDI S

05L MANPGC NDI . 1000P (5.0)

OSM MANPGC ASSY T

05M MANPGC ASSY S

Handwritten signature

9:44 TUESDAY, MARCH 28, 1989 26
SHEET *2* OF *4*

OPERATION PROFILE										SAS	
NAME <i>Handwritten</i>										<i>Handwritten</i>	
ITEM CD PCN 74146ASUB1										RCC MANPGC	
WCD										QTY	
WCD DATE 7205										X HRS	
ALC WR										EQUIP CODE	
OPER HIST MAND OPER SKILL										NOTES	
DESC OCCR TYPE F HRS CD/LVL QTY											
05M	MANPGC	ASSY	1000 P	0.2	IG09	1		0.2			
05N	MANPGC	PROC									
05N	MANPGC	PROC									
05N	MANPGC	PROC	1000 P	1.0	IG09	1		0.2	0.004	1	0.1
05O	MANPGC	ASSY									
05O	MANPGC	ASSY									
05O	MANPGC	ASSY	1000 P	0.2	IG09	1		0.2			

SHOP FLOW DAY COMPUTATION FOR PRODUCTION NO: 74146A

AFLCR 66-4 Shop Flow Day Formula was used to establish this flow day standard as follows: Flow Days = A [(B ÷ C) + D + E] where A = 1.45; B = End Item Labor Standard; C = Direct Labor Hours Per Person Per Day adjusted for indirect categories and labor efficiency; D = Routine Delays; E = Unique Delays. Repair is being accomplished as a responsible shop.

SEP	DESCRIPTION	DAYS
1	<p>B = Labor Standard of <u>17.47</u> Hrs C = <u>706.97</u> Daily Labor Hrs</p> <p>Value "C" is calculated as follows:</p> <p>MANPG <u>C</u> .24 + .25 + .26 + .29 Indirect Average = <u>1.04</u> Hours</p> <p>MANPG <u>C</u> Labor Efficiency = <u>92</u> %</p> <p>C = 8 Hours Minus Indirect Average Times Labor Efficiency</p>	<p>B ÷ C</p> <p><u>2.5</u></p>
2	<p>D = Routine Delays</p> <p>a. Awaiting Maintenance (AWM) = 3.8 days</p> <p>b. One days supply at station awaiting maintenance = 4 days (average 4 stations for each C/N). This is necessary to maintain uninterrupted flow of items.</p> <p style="text-align: right;">TOTAL</p>	<p>7.80</p>
3	<p>E = Unique Delays</p> <p>a. Machine processing <u>1</u> Day(s)</p> <p>b. Machine processing delays _____ Day(s)</p> <p>c. Routing to support shops _____ Day(s)</p> <p>d. Others (See Reverse Side) <u>16.22</u> Day(s) (<i>Attach Sheet</i>)</p> <p style="text-align: right;">TOTAL</p>	<p><u>17.2</u></p>
4	Total flow days this shop (1 + 2 + 3)	<u>27.5</u>
	Work Shift Adjustment (Item 4 ÷ number of shifts).	<u>27.52</u>
	Sum of flow days for all shops (Item 5 x 1.45)	
6	(Final result to be rounded up to next whole day.)	<u>40.0</u>


COMPUTED BY: D. BRIDGES

DATE: 10 DEC 85

<u>OPERATION</u>	<u>T.O. Ref (para)</u>	<u>Time Req'd</u>
Bake after paint	2-18	1.00
Bake (Headers)	2-93k	13.50
Evacuate motor	2-109b	.50
Evacuate motor	2-118h	.25
Heat motor & evac.	2-118i	16.50
Dry motor	2-120c	1.00
Cure paint	2-120e	2.00
Run-in	2-122a	48.00
Route motor	-----	24.00
Bake slipring	2-130	9.00
Motor warmup	3-46c	1.00
Cool down	3-99	4.00
Bake after paint	2-168	1.00
Machine processing (RWT)	11-14	<u>8.00</u>
		129.75

$$129.75 \div 8 = 16.22$$

PROCESS FLOW CHART DCN 74146A



200 4/19/89

PART OPERATION SUMMARY

9:03 FRIDAY, FEBRUARY 24, 1989

6

PN: 172231A
 OPERATION: ZPRT
 SAMPLE SIZE: 444
 MISSING FLOWTIMES: 2
 MANPOWER REQUIRED: 0
 ALC: WARNER ROBBINS
 NSN:
 RCC: MANPGC
 PCN: 74146A
 GYRO SHOP, UNIT 3
 WCD:
 WCD DATE: 8133
 PRIMARY OPERATION TYPE: ASSY
 MATERIAL TYPE:
 OUTLIERS DELETED: 0

SKILL	QTY	TIME		CATEGORY	QTY	TIME		BATCH
		FRACTION	HOURS			FRACTION	HOURS	
EQUIPMENT REQUIRED								
MIN MAX								

HISTORICAL DATA

ACTUAL FREQ	RELATIVE FREQUENCY											D VALUE	D ALPHA
	0	10	20	30	40	50	60	70	80	90	100		
5	1	33	28	13	6	3	2	2	3	45	0	0.673	
10	1	33	28	13	6	3	2	2	3	45	0	0.577	
15	1	33	28	13	6	3	2	2	3	45	0	0.231	
20	1	33	28	13	6	3	2	2	3	45	0	0.115	
25	1	33	28	13	6	3	2	2	3	45	0	0.247	
30	1	33	28	13	6	3	2	2	3	45	0		
35	1	33	28	13	6	3	2	2	3	45	0		
40	1	33	28	13	6	3	2	2	3	45	0		
45	1	33	28	13	6	3	2	2	3	45	0		
>=50	1	33	28	13	6	3	2	2	3	45	0		

OCCURRENCE FACTOR: .
 OCCURRENCES: 446
 DISTRIBUTION OF CHOICE: HISTORICAL DISCRETE

PART OPERATION SUMMARY

9:03 FRIDAY, FEBRUARY 24, 1989

7

PN: 172231A
 OPERATION: ZPRT
 SAMPLE SIZE: 339
 MISSING FLOWTIMES: 1
 END ITEMS: 0
 MANPOWER REQUIRED: 0
 ALLOC: WARNER ROBBINS
 RCC: MANPGC
 GYRO SHOP, UNIT 3
 NSN:
 PCN: 74146ASUB1
 WCD:
 WCD DATE: 7205
 PRIMARY OPERATION TYPE: ASSY
 MATERIAL TYPE:
 OUTLIERS DELETED: 0

SKILL	QTY	MANPOWER REQUIRED		CATEGORY	QTY	EQUIPMENT REQUIRED		FRACTION	HOURS	BATCH MIN MAX
		TIME	FRACTION			TIME	HOURS			
HISTORICAL DATA										

ACTUAL FREQ	RELATIVE FREQUENCY											DISTRIBUTION	PARAMETERS	D VALUE	D ALPHA	
	0	10	20	30	40	50	60	70	80	90	100					
0	1															
5	11															
10	28															
15	19															
20	16															
25	11															
30	4															
35	2															
40	2															
45	0															
>=50	5															

OCCURRENCE FACTOR: 340
 DISTRIBUTION OF CHOICE: LOGNORMAL

WORK CONTROL DOCUMENT				1. DATE 8271		PAGE 1 OF 2 PAGES	
JOB ORDER NUMBER 74148A		3. QUANTITY 1		4. PRODUCTION SECTION/RCC "O" MNP GC		5. DATE SCHED	
7. PART NUMBER 15810-1			8. TECH DATA 5N6-2-3-3 & 4			9. ITEM SERIAL NUMBER	
10. MODEL-DESIGN-SERIES		11. STOCK NUMBER 6615-00-527-9281		12. OPTIONAL			
13. SERIAL NUMBER		14. NOUN N-1 Directional Gyro					
15. DISPATCH STATION	16. PDM/OP NO.	17. WORK TO BE ACCOMPLISHED			18. MECHANIC	19. "P"	20. "Q"
	010	Receive (Check data on WCD and AFTO Form 349. Clean gyro external surfaces.)					
	020 0100	Perform functional analysis. Perform resistance & hipot test. If serviceable, proceed to Step 120. Stamp condition tag.					B
	020 0200	Perform functional analysis. Perform resistance & hipot test. If serviceable, proceed to Step 120. Stamp condition tag.					B
	030	Overhaul and repair (clean and inspect)					
	040	Inner Gimbal end play					B
	050	Outer Gimbal end play					B
	060	Final inside visual. Certify that this item does not contain any foreign objects such as as tools or unattached parts.					B
	070	Electrical test					
	080	Seal, leak test, purge and fill					
	090	Install into chasis, perform resistance and hipot check. Paint gyro.					
21. FINAL DESTINATION		22. COORDINATION/INITIATING RCC SIGNATURE/DATE				23. DOCUMENT S/N	
DISPATCH	FUNCTIONAL CODE	a. MANPGC <i>Raymond T. Smith</i> - MAQNG 29 Sep 88 MANPGB <i>William D. Smith</i> - 29 Sep 88 MANERG <i>David A. Bridges</i> 24 Sep 88 MANSA <i>James E. Smith</i> 29 Sep 88 MANSA <i>James E. Smith</i> 29 Sep 88					

1. DATE 8/27/1

1. DATE 8/27/1

PAGE 2 OF 2 PAGES

PAGE 2 OF 2 PAGES

[illegible]

WORK CONTROL DOCUMENT				1. DATE 7205	PAGE 1 OF 1 PAGES	
JOB ORDER NUMBER 74148A		2. QUANTITY 1	4. PRODUCTION SECTION/RCC "O" MNPGC	3. DATE SCHED	6. DATE COMP	
RT NUMBER 15119		5. TECH DATA 5N6-2-3-3			9. ITEM SERIAL NUMBER	
10. MODEL-DESIGN-SERIES		11. STOCK NUMBER 6615-00-398-0717	12. OPTIONAL			
13. SERIAL NUMBER		14. NOUN Gyro Motor (N-1)				
15. DISPATCH STATION	16. PON/OP NO.	17. WORK TO BE ACCOMPLISHED		18. MECHANIC	19. "P"	20. "Q"
	3a	Disassemble, clean and inspect				
	3b	Install bearings and set preload				
	3c	Dynamic balance rotor				
	3d	Install rotor into housing				
	3e	Inside visual. Certify that this item does not contain any foreign objects such as tools or unattached components.				B
	3f	Perform bearing run-in				
	3g	Seal, leak check and evacuate motor assembly.				
	3h	Final motor run-in				
	3i	Paint motor assembly				
	3j	Final visual and functional test				B
21. DESTINATION		22. COORDINATION/INITIATING RCC SIGNATURE/DATE			23. DOCUMENT S/N	
DISPATCH	FUNCTIONAL CODE	a. MANERO <i>David J. Padgett</i> 7-27-87 b. MANPGC <i>James P. Howell</i> 7-27-87			c. <i>James P. Howell</i> 7-27-87 d. <i>J. T. Howell</i> 7-27-87	

WORK CONTROL DOCUMENT

1. DATE

6108

PAGE 1 OF 2 PAGES

2. JOB ORDER NUMBER

74148A

3. QUANTITY

1

4. PRODUCTION SECTION/RCC

"O" MNPCC/B

5. DATE SERIALIZED

8196

6. DATE COPIED

8214

PART NUMBER

15810-1

8. TECH DATA

5N6-2-3-3 & 4

9. ITEM SERIAL NUMBER

1467

10. MODEL-DESIGN-SERIES

11. STOCK NUMBER

6615-00-527-9281

12. OPTIONAL

13. SERIAL NUMBER

14. NAME

N-1 Directional Gyro

84 A

15. DISPATCH STATION

16. PON/OP NO.

17. WORK TO BE ACCOMPLISHED

18. MECHANIC

19. "P"

20. "J"

01

Receive (Check data on WCD & AFTO 349) 18 JUL 1988
Clean Gyro external surfaces.

WR
M
01610

02

Perform resistance, Hipot Test and Pretest. 18 JUL 1988

WR
M
01610

03

Overhaul and repair (Clean and Inspect). 18 JUL 1988

WR
M
01610

04

Inter Gimbal End Play. 18 JUL 1988

WR
M
01610

05

Outer Gimbal End Play 18 JUL 1988

WR
M
01610

06

Final inside visual. Certify that this item does not contain any foreign objects such as tools or unattached parts. 18 JUL 1988

WR
M
01610

07

Electrical Test 18 JUL 1988

WR
M
01610

08

Seal, Leak test, purge and fill 18 JUL 1988

WR
M
01610

09

Install into chassis, perform resistance and hipot check. Paint Gyro 18 JUL 1988

WR
M
01610

10

RWT Date 19 July 88
Random
Position 9
Time 7:00 - 0500

WR
M
01610

21. FINAL DESTINATION

22. COORDINATION/INITIATING RCC SIGNATURE/DATE

23. DOCUMENT S/N

DISPATCH

FUNCTIONAL CODE

David S. Bridges MANEC 29 APR 86 James E. Bond HAQNC 29 APR 1986

MNPCC James E. Bond MNPCC William C. Bond MANSAA 29 APR 86

APPROVED 2853 ABC (MAY 86) (DLM)

AZIMUTH AND LEVELING SYNCHRO TESTS

WORK MEASUREMENT COMPUTATION SHEET			Page 1 of 1 Pages		25 Feb 85	
INSTRUCTIONS: Industrial Engineering Division will complete "Work Measurement Requirements" and furnish cut sheets to applicable using activities for each type of computation sheet as required.			JOB ASSIGNED TO			
			CARL L. MUCHER			
			COMPUTED BY			
			CARL L. MUCHER			
WORK ORDER	PART NUMBER	STOCK NUMBER		JOB STANDARD	STATION NO.	
74148A	15810-1	6615-00-527-9281		NA	MNPG	
NOUN		QUANTITY	STD HRS PER	PIECES	TIME PER PIECE	
N-1 Directional Gyro		N/A	N/A	N/A	N/A	
WORK MEASUREMENT REQUIREMENTS: PRODUCTION SUPERVISOR LABOR STANDARD REVIEW Observations were made 25 Jan 85 through 8 Feb 85 in accordance with AFLCR 66-4 Work Sampling Techniques. Overall productivity was 89%.						
<u>CATEGORY</u>	<u>BASE HR/OCC</u>	<u>PF&D</u>	<u>STD HR/OCC</u>	<u>OCC FACTOR</u>	<u>STD HR/END ITEM</u>	
Receive	.054	1.07	.058	1.00	.058	
Pretest	.231	1.07	.248	1.00	.248	
O/H & RPR/Clean & Inspect	8.044	1.07	8.607	1.00	8.607	
Motor Repair	7.532	1.07	8.060	1.00	8.060	
B/Up Inr Gim/End Play	2.260	1.07	2.419	1.00	2.419	
B/Up Otr Gim/End Play	1.478	1.07	1.582	1.00	1.582	
Final I/S Visual	.256	1.07	.274	1.00	.274	
Funct Test	.713	1.07	.763	1.00	.763	
Seal/Fill	2.837	1.07	3.036	1.00	3.036	
Instal In Chassis	.490	1.07	.525	1.00	.525	
O/H Random	1.429	1.07	1.529	1.00	1.529	
Elect Test	1.064	1.07	1.139	1.00	1.139	
Final Visual	.657	1.07	.703	1.00	.703	
TOTAL			28.943 = 28.94 M/H			
This total is manually computed and may vary slightly from E046 output. In accordance with AFLCR 66-4, para 3-10, all standards should be reviewed by affected supervisory personnel for completeness of work content. Production supervisors will be given 10 workdays to express in writing their reasons for nonconcurrence. If, after this time, no reply has been received from the coordinating agency, the standard will be considered coordinated and acceptable.						
APPROVALS		DATE	APPROVALS		DATE	
INDUSTRIAL ENGINEER			WORK CENTER FOREMAN			
N/A			N/A See E046 B Print out			
PROCESS TECHNICIAN						
<i>Carl L. Mucher</i>		25 Feb 85	N/A			

SHOP FLOW DAY COMPUTATION FOR PRODUCTION NO: 74148A

AFLCR 66-4 Shop Flow Day Formula was used to establish this flow day standard as follows: Flow Days = A [(B ÷ C) + D + E] where
A = 1.45; B = End Item Labor Standard; C = Direct Labor Hours Per Person Per Day adjusted for indirect categories and labor efficiency;
D = Routine Delays; E = Unique Delays. Repair is being accomplished as a responsible shop.

REP	DESCRIPTION	DAYS
	B = Labor Standard of <u>28.93</u> Hrs C = <u>7.58</u> Daily Labor Hrs Value "C" is calculated as follows: MANPG <u>C</u> .24 + .25 + .26 + .29 Indirect Average = <u>1</u> Hours MANPG <u>C</u> Labor Efficiency = <u>96</u> % C = 8 Hours Minus Indirect Average Times Labor Efficiency	B ÷ C <u>3.82</u>
	a. Routine Delays Awaiting Maintenance (AWM) = 3.8 days b. One days supply at station awaiting maintenance = 4 days (average 4 stations for each C/N). This is necessary to maintain uninterrupted flow of items.	
	TOTAL	7.80
	E = Unique Delays a. Machine processing <u>8.12</u> Day(s) b. Machine processing delays <u>.50</u> Day(s) c. Routing to support shops <u> </u> Day(s) d. Others (See Reverse Side) <u> </u> Day(s)	
	TOTAL	8.62
	Total flow days this shop (1 + 2 + 3)	20.24
	Work Shift Adjustment (Item 4 ÷ number of shifts) ÷ 2 shift/day	10.12
	of flow days for all shops (Item 5 x 1.45) X 10.12	14.67
	final result to be rounded up to next whole day.)	15

COMPUTED BY: CARL MUCHER

DATE: 14 Feb 85

UNIQUE DEALYSTIME PAGE PARA

A. Machine Processing

- | | | | |
|--|---------|------|--------|
| 1. Test Motor
12 Min. | .20 hrs | 2-19 | 2-32b |
| 2. Run-in Motor
48 hrs.
48 hrs ÷ 8 hrs/Day = 6 Days | 6 days | 2-29 | 2-47bc |
| 3. Leak Test
15 Minutes = .25 hrs | .25 hrs | 2-44 | 2-58b |
| 4. Random Wander Drift Test
Warm/Up Gyro 15 min.
2 ea. Warm/Up Required
15 Min X 2 ea. Warm/Up = 30 min | .50 hrs | 3-29 | 3-64 |
| Drift Test
16 hrs.
16 hrs ÷ 8 hrs/Day = 2 Days | 2 days | 3-29 | 3-64 |
| Machine Delay
4 hrs. | 4 hrs | 3-29 | 3-64 |

NAME <u>R.V. 2ERVOER</u> ALC <u>NR</u>		DATE <u>4-6-6</u>		RCC <u>MANPEC</u>		SHEET <u>1</u> OF <u>1</u>								
PCN <u>74148A</u>		WCD <u>4/8</u>		WCD DATE <u>8/8/71</u>										
OPERATION NUMBER	RCC	OPERATION DESCRIPTION	MANDATORY OCCURRENCE FACTOR	OPERATION TYPE	MANDATORY FLOW INQUIRY		MAINPOWER		EQUIPMENT		DATA SOURCE COMMENTS			
					%	INHS.	QTY.	%	INHS.	EQUIPMENT CODE		QTY.	%	INHS.
1N	MAYAG	REC	1	TRANSIT								C. DRIVER RANNEY MAR. MILLER OPER. & A SCHEDULED.		
				SETUP										
				PROCESS										
		↑		TRANSIT										
				SETUP										
				PROCESS										
		ALL WCD OPERATIONS LISTED IN CD OPER PROFILE		TRANSIT										
				SETUP										
				PROCESS										
		↑		TRANSIT										
				SETUP										
				PROCESS										
9999	MAYAG	SELL	1	TRANSIT								D. HARRELSON SUPERV. MANPEC MAR. MILLER OPERATOR SCHEDULED.		
				SETUP										
				PROCESS										

LSC-2M092C

9:44 TUESDAY, MARCH 28, 1989 27

SHEET 1 OF 4

SAS

OPERATION PROFILE

DATE

ALC WR

WCD

ITEM CD PCN 74148A

OPER NOMB

RCC

MANPGC REC

0.99

T

HIST MAND

OCOR

TYPE

F HRS

CD/LVL

SKILL

QTY

%

HRS

EQUIP

CODE

QTY

%

HRS

NOTES

NAME: *[Signature]*

DATE *2/19/89*

WCDDATE 8271

S

1.000

0.1 IG09

0.1

T

S

1.00 P

0.9 IG09

0.6 5925

P

0.9 IG10

0.6 8556

T

S

1.00 P

18.0 IG09

18.5 0844

T

S

1.00 P

0.2 IG09

0.2

NAME *Robert L. ...* OPERATION PROFILE SAS
 ITEM CD PCN 74148A ALC WR DATE *4/19/89*
 OPER NUMB RCC OPER HIST MAND OPER SKILL WCD WCD DATE 8271
 NOMB RCC DESC OCCR TYPE F HRS CD/LVL QTY % HRS EQUIP CODE

RCC MANPGC

NOTES

OPER NUMB	RCC	DESC	OCCR	TYPE	F	HRS	CD/LVL	QTY	%	HRS	EQUIP CODE	QTY	%	HRS	NOTES
50	MANPGC	ASSY	1.00	T											
50	MANPGC	ASSY		S											
50	MANPGC	ASSY	1.00	P		0.2	IG09	1		0.2					
60	MANPGC	NDI	0.99	T											
60	MANPGC	NDI		S											
60	MANPGC	NDI	1.00	P		0.2	IG09	1		0.2					
70	MANPGC	ASSY	0.99	T											
70	MANPGC	ASSY		S											
70	MANPGC	ASSY	1.00	P		0.6	IG09	1		0.6	5925	1		0.6	
80	MANPGC	ASSY	0.98	T											
80	MANPGC	ASSY		S											
80	MANPGC	ASSY	1.00	P		4.0	IG09	1		0.7	0002	1		4.0	

9:44 TUESDAY, MARCH 28, 1989 29

SHEET 3 OF 4

OPERATION PROFILE

NAME *David L. L...*

SAS *4/19/89*

ALC WR DATE

WCDDATE 8271

WCD

ITEM CD PCN 74148A
OPER NUMB
RCC
MANPGC ASSY

HIST MAND OPER
OCCR TYPE F MRS
CD/LVL

EQUIP
CODE

3346

QTY

%

HRS

QTY

%

HRS

NOTES

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1 0.2

1.2

R.B IG09

1.00 P

T

0.94

MANPGC NDI

S

MANPGC NDI

1.00 P

MANPGC NDI

16.0 IG09

1

1.5

0766

1

12.0

T

0.88

MANPGC NDI

S

MANPGC NDI

1.00 P

MANPGC NDI

3.0 IG09

1

3.0

5925

1

3.0

P

MANPGB NDI

3.0 IG10

1

3.0

8556

1

3.0

T

0.87

MANPGB ASSY

S

MANPGB ASSY

9:44 TUESDAY, MARCH 28, 1989 30

SHEET ~~2~~ OF ~~2~~

NAME Linda Lopez

OPERATION PROFILE

SAS

ALC WR

DATE _____

5/5/75

RCC MANPGC

ITEM CD PCN 74148A

WCD

WCDDATE 8271

[illegible][illegible]

HIST	MAND	OPER
OCCR	OCCR	TYPE
1	1	1
2	2	2
3	3	3
4	4	4
5	5	5
6	6	6
7	7	7
8	8	8
9	9	9
10	10	10
11	11	11
12	12	12
13	13	13
14	14	14
15	15	15
16	16	16
17	17	17
18	18	18
19	19	19
20	20	20
21	21	21
22	22	22
23	23	23
24	24	24
25	25	25
26	26	26
27	27	27
28	28	28
29	29	29
30	30	30
31	31	31
32	32	32
33	33	33
34	34	34
35	35	35
36	36	36
37	37	37
38	38	38
39	39	39
40	40	40
41	41	41
42	42	42
43	43	43
44	44	44
45	45	45
46	46	46
47	47	47
48	48	48
49	49	49
50	50	50
51	51	51
52	52	52
53	53	53
54	54	54
55	55	55
56	56	56
57	57	57
58	58	58
59	59	59
60	60	60
61	61	61
62	62	62
63	63	63
64	64	64
65	65	65
66	66	66
67	67	67
68	68	68
69	69	69
70	70	70
71	71	71
72	72	72
73	73	73
74	74	74
75	75	75
76	76	76
77	77	77
78	78	78
79	79	79
80	80	80
81	81	81
82	82	82
83	83	83
84	84	84
85	85	85
86	86	86
87	87	87
88	88	88
89	89	89
90	90	90
91	91	91
92	92	92
93	93	93
94	94	94
95	95	95
96	96	96
97	97	97
98	98	98
99	99	99
100	100	100

OPER	HI
DESC	OC

MANO
F HRS

SKILL
CD/LVL

010

285

EQUIP CODE

3

120 MANPGB ASSY

1.00

✓ TEND

•

:

SAS

OPERATION PROFILE

ALC WR DATE

WCDDATE A7205

NAME Elizabeth

ITEM CD PCN 74148ASUB1

WCD

[illegible]

03A MANPGC DIS

03A MANPGC DIS S

03A	MANPGC	DIS	1000 P	0.7	IG09	1	0.7

03A MANPDA PROC 1.00P 24.0

03B MANPGC ASSY

03B MANPGC ASSY S

UNIT	MANPGC	ASSY	1.00 P	0.7	IG09	1	0.7
03B							

03C MANPGC ASSY . . . T

03C MANPGC ASSY

33C	MANPGC	ASSY	1	0.8	5139	1	0.8
		1.00 P		0.8	IG09		

03D MANPGC ASSY T

03D MANPGC ASSY

3D	MANPGC	ASSY	100 P	103 IG09	1	1.3
----	--------	------	-------	----------	---	-----

Richard

NAME *Richard*
ITEM CD PCN 74148ASUB1

SAS

OPERATION PROFILE

ALC WR

DATE

WCD

WCDDATE A7205

OPER NUMB
RCC
MANPGC

OPER HIST MAND OPER
DESC OCCR TYPE

MAND F HRS
CD/LVL

QTY

X

HRS

EQUIP
CODE

NOTES

03H MANPGC ASSY 1.00P

52.0 IG09

1

0.7

0007

QTY

X

HRS

48.0

03H MANPGC ASSY P

9036

1

0.2

QTY

X

0.2

03I MANPGC PROC T

QTY

X

03I MANPGC PROC S

QTY

X

03I MANPGC PROC 1.00P

1.0 IG09

1

0.5

0004

QTY

X

0.2

9:44 TUESDAY, MARCH 28, 1989 33

SHEET 2 OF 4

RCC MANPGC

[Signature]

NAME *[Signature]* ITEM CD PCN 74148ASUB1

OPERATION PROFILE

ALC WR DATE

SAS

9:44 TUESDAY, MARCH 28, 1989 34

SHEET 4 OF 4

WCD

WCDDATE 7205

RCC MANPGC

OPER HST MAND OPER MAND
NUMB RCC DESC OCCR TYPE F HRS CD/LVL

QTY % HRS EQUIP CODE

NOTES

T

S

1.00P

0.0 IG09

0.2 9038

0.2

1


1

03J MANPGC NDI

03J MANPGC NDI

03J MANPGC NDI

PROCESS FLOW CHART DCN 741418A



20/1/89

PN: 15810-1
 OPERATION: ZPRT
 SAMPLE SIZE: 325
 MISSING FLOWTIMES: 0
 END ITEMS: 1
 PCN: 74148A
 WCD: 8271
 WCD DATE: 8271
 PRIMARY OPERATION TYPE: ASSY MATERIAL TYPE:
 OUTLIERS DELETED: 1

----- MANPOWER REQUIRED -----
 SKILL QTY FRACTION HOURS
 ----- EQUIPMENT REQUIRED -----
 CODE CATEGORY QTY FRACTION HOURS

HISTORICAL DATA

ACTUAL FREQ	0	10	20	30	40	50	60	70	80	90	100	DISTRIBUTION	PARAMETERS	D VALUE	D ALPHA
0	56	12	10	7	6	2	4	0	1	0	1	UNIFORM	0.0	317.0	0.619
20	40	10	7	6	2	4	0	1	0	1	1	TRIANGULAR	0.0	9.0317.0	0.476
40	60	8	2	4	0	1	0	1	0	1	1	NORMAL	36.4	45.5	0.207
60	80	2	4	0	1	0	1	0	1	0	1	LOGNORMAL	36.4	45.5	0.066
80	100	2	4	0	1	0	1	0	1	0	1	EXPONENTIAL	36.9		0.149
100	120	4	0	1	0	1	0	1	0	1	0				0.12
120	140	0	1	0	1	0	1	0	1	0	1				
140	160	0	1	0	1	0	1	0	1	0	1				
160	180	0	1	0	1	0	1	0	1	0	1				
180	200	0	1	0	1	0	1	0	1	0	1				
200															

OCCURRENCE FACTOR: 328
 OCCURRENCES: 328

DISTRIBUTION OF CHOICE: LOGNORMAL

PN: 415119 PART OPERATION SUMMARY 9:03 FRIDAY, FEBRUARY 24, 1989 9

ALC. WARNER ROBBINS RCC: MANPGC GYRO SHOP, UNIT 3 WCD DATE: A7205
 NSN: PCN: 74148ASUB1 WCD:
 OPERATION: ZPRT PRIMARY OPERATION TYPE: PROC MATERIAL TYPE:
 SAMPLE SIZE: 194 MISSING FLOWTIMES: 0 END ITEMS: OUTLIERS DELETED: 0
 ----- MANPOWER REQUIRED -----

SKILL	QTY	TIME		CATEGORY	QTY	TIME		BATCH
		FRACTION	HOURS			FRACTION	HOURS	
EQUIPMENT REQUIRED								
MIN MAX								

HISTORICAL DATA

ACTUAL FREQ	RELATIVE FREQUENCY											D VALUE	D ALPHA
	0	10	20	30	40	50	60	70	80	90	100		
0	5.0	0.435
10	5.0	0.283
20	34.7	0.138
30	35.2	1.000
40		0.262
50		
60		
70		
80		
90		
>=100		

OCCURRENCE FACTOR: OCCURRENCES: 194
 DISTRIBUTION OF CHOICE: HISTORICAL DISCRETE

WORK CONTROL DOCUMENT				1. DATE 8119	PAGE 1 OF 2 PAGES
JOB ORDER NUMBER 74149A		3. QUANTITY 1	4. PRODUCTION SECTION/RCC "O" MNPGB	5. DATE SCHED	6. DATE COMP
PART NUMBER 15150-1		8. TECH DATA 5N6-3-2-3; 5N6-3-2-4; 5N6-3-2-3-1		9. ITEM SERIAL NUMBER	
10. MODEL-DESIGN-SERIES		11. STOCK NUMBER 6615-00-570-4966	12. OPTIONAL		
13. SERIAL NUMBER		14. NOUN Slaving Control (N-1)			
15. DISPATCH STATION	16. PON/OP NO.	17. WORK TO BE ACCOMPLISHED		18. MECHANIC	19. "P"
	010	Receive (Check data on WCD and AFTO Form 349. Clean gyro external surfaces.)			
	020 0100	Perform functional analysis. If serviceable proceed to Step 100. Stamp condition tag.			B
	020 0200 MNPGB	Perform functional analysis. If serviceable proceed to Step 100. Stamp condition tag.			B
	030	Unseal			
	040	Gyro repair			B
	050	Build-up test			B
	060	Calibrate			B
	070	Final inside visual.- Certify that this item does not contain any foreign objects such as tools or unattached components.			B
	080	Seal, leak test, purge and fill			
	090 0100	Perform functional analysis. Stamp condition tag.			B
21. FINAL DESTINATION		22. COORDINATION/INITIATING RCC SIGNATURE/DATE		23. DOCUMENT S/N	
DISPATCH	FUNCTIONAL CODE	a. MANPGC MANPGB	c. MAQNG		
		b. MANERG	d. MANSAA		

[illegible]

WORK CONTROL DOCUMENT					1. DATE 6339	PAGE 1 OF 1 PAGES
2. JOB ORDER NUMBER 74149A ✓		3. QUANTITY 1	4. PRODUCTION SECTION/RCC "O" MNPCC		5. DATE SCHED	6. DATE COMP
7. PART NUMBER 41530.1			8. TECH DATA 5N6-3-2-3; 5N6-3-2-4			9. ITEM SERIAL NUMBER
10. MODEL-DESIGN-SERIES		11. STOCK NUMBER 6615-00-342-3871		12. OPTIONAL		
13. SERIAL NUMBER		14. NOUN N-7 SLAVE MOTOR				
15. DISPATCH STATION	16. PON/OP NO.	17. WORK TO BE ACCOMPLISHED			18. MECHANIC	19. 19. 20. 20.
	4a	ROUTE FOR HULL BLASTING (AS REQUIRED)				
	4b	DISASSEMBLE				
	4c	CLEAN AND INSPECT PARTS				
	4d	BUILDUP AND TEST				
	4e	SEAL, FILL, LEAK CHECK				
	4f	FINAL MOTOR BALANCE				
	4g	PERFORM BEARING RUN-IN				
	4h	PAINT				
	4i	FINAL TEST AND FINAL VISUAL				B
21. FINAL DESTINATION		22. COORDINATION INITIATING RCC SIGNATURE DATE			23. DOCUMENT S/N	
DISPATCH	FUNCTIONAL CODE	<i>Handwritten signatures and dates:</i> MAONG 13 Jan 87 MANSAA 13 Jan 87				

Approved 2853 AB (Feb 87) (DIM)

WORK CONTROL DOCUMENT				1. DATE 6339 Betty		PAGE 1 OF 1 PAGES	
2. JOB ORDER NUMBER 74149A		3. QUANTITY 1		4. PRODUCTION SECTION/RCC "O" MNPCC/MNPGCB		5. DATE SCHED 0106 SEP 02 1988	
7. PART NUMBER 15150-1			8. TECH DATA SN6-3-2-3; SN6-3-2-4; 84 A SN6-3-2-3-1			9. ITEM SERIAL NUMBER 4669	
10. MODEL-DESIGN-SERIES		11. STOCK NUMBER 6615-00-570-4966		12. OPTIONAL NOTE: Use QQ-5-571 type SN60WRP solder. Observe all notes, cautions, and warnings throughout T.O. MDC data, required IAW MAOI 66-22.			
13. SERIAL NUMBER		14. NOUN SLAVING CONTROL (N-1)					
15. DISPATCH STATION	16. PON/OP NO.	17. WORK TO BE ACCOMPLISHED			18. MECHANIC	19. "P"	20. "Q"
	1 1010	Receive (Check data on WCD and AFTO Form 349.) Clean External Surfaces. AUG 12 1988			WR PA 6044		
	2 1010	PRETEST Essential Repair Overhaul AUG 12 1988			WR PA 6044		
	3 1020	UNSEAL AUG 16 1988			WR PA 6044		
	4 1030	GYRO REPAIR AUG 16 1988			WR PA 6044		B
	5 1035	BUILD-Up TEST AUG 19 1988			WR PA 6044		B
	6 1045	CALIBRATE AUG 19 1988			WR PA 6044		B
	7 1030	Final Inside Visual. Certify that this item does not contain any foreign objects such as tools or unattached components. AUG 19 1988			WR PA 6044		B
	8 1060	SEAL, FILL, LEAK CHECK AUG 19 1988			WR PA 6044		
	9 1070	FINAL FUNCTIONAL ANALYSIS. STAMP CONDITION TAG. 22 AUG 1988			WR PA 6335		B
	10 1080	Final Prep. (Final Visual, complete AFLC Form 959, check for T.O. MOD compliance. Complete AFTO 349 and install WR-ALC decal. SEP 02 1988			WR PA 5615		
21. FINAL DESTINATION		22. COORDINATION/INITIATING RCC SIGNATURE/DATE				23. DOCUMENT S/N	
DISPATCH	FUNCTIONAL CODE	MANERC 13 Jan 87					
		MANPGC 13 Jan 87					
		MANPC 13 Jan 87					

AFLC FORM 959
MAR 81

PREVIOUS EDITION WILL BE USED.

WR-ALC/MANSAA "OVERT"

\PROGRAM NAME: 300328
 \CPIN: 81H-GYR/N1/SCONT-U001-00A
 \DATE OF LAST REVISION: 26-MAR-86
 \UUT TYPE: SWITCHING RATE GYRO N1
 \UUT NATIONAL STOCK NUMBER: 6615-00-570-4966
 \UUT MFR/PART NUMBER: KEARFOTT 15150-1
 \OPERATOR'S NAME: WILSON

22 AUG 1988

WR
 PA
 6335

\TEST STATION: RATE STATION # 2
 \DATE & TIME OF TEST: 22-AUG-88 12:53:09
 # GYRO IN TEST MOUNT POSITION 1,
 # SERIAL NUMBER 4669

/ SPINMOTOR RUNUP
 NORMALLY OPEN TURN INDICATOR 1 Ohms .10000E+33 00300.0000 .10000E+33 PASS 22-AUG-88 12:54:00
 RUNNING CURRENT PHASE-A 1 mA 00150.0000 00000.0000 00093.7270 PASS 22-AUG-88 12:57:28
 RUNNING CURRENT PHASE-B 1 mA 00150.0000 00000.0000 00100.3030 PASS 22-AUG-88 12:57:29
 RUNNING CURRENT PHASE-C 1 mA 00150.0000 00000.0000 00100.7400 PASS 22-AUG-88 12:57:30

/ SWITCHING AND UNSWITCHING TIME
 SWITCHING TIME 1.5 D/S CW 1 Sec 00045.0000 00001.0000 00005.0833 PASS 22-AUG-88 12:59:59
 UNSWITCHING TIME 1.5 D/S CW 1 Sec 00008.0000 00004.0000 00006.2833 PASS 22-AUG-88 13:01:19
 SWITCHING TIME 1.5 D/S CCM 1 Sec 00045.0000 00001.0000 00007.1666 PASS 22-AUG-88 13:02:40
 UNSWITCHING TIME 1.5 D/S CCM 1 Sec 00008.0000 00004.0000 00004.7166 PASS 22-AUG-88 13:03:59
 SWITCHING TIME 0.75 D/S CW 1 Sec 00045.0000 00001.0000 00010.3833 PASS 22-AUG-88 13:05:26
 UNSWITCHING TIME 0.75 D/S CW 1 Sec 00006.0000 00002.0000 00004.0833 PASS 22-AUG-88 13:06:44
 SWITCHING TIME 0.75 D/S CCM 1 Sec 00045.0000 00001.0000 00014.3499 PASS 22-AUG-88 13:08:13
 UNSWITCHING TIME 0.75 D/S CCM 1 Sec 00006.0000 00002.0000 00003.9999 PASS 22-AUG-88 13:09:31

/ YAW OSCILLATION
 TURN INDICATOR 2.5 DEG 0.5 HZ 1 Ohms .10000E+33 00300.0000 .10000E+33 PASS 22-AUG-88 13:16:16
 TURN INDICATOR 4 DEG 0.5 HZ 1 Ohms .10000E+33 00300.0000 .10000E+33 PASS 22-AUG-88 13:20:39

/ STEADY STATE RATE AND YAW OSCILLATION
 TURN INDICATOR CLOSED CW 1 Ohms 00300.0000 00000.0000 00001.9940 PASS 22-AUG-88 13:27:26
 TURN INDICATOR OPEN CW 1 Ohms .10000E+33 00300.0000 .10000E+33 PASS 22-AUG-88 13:28:14
 TURN INDICATOR CLOSED CCM 1 Ohms 00300.0000 00000.0000 00002.0580 PASS 22-AUG-88 13:31:29
 TURN INDICATOR OPEN CCM 1 Ohms .10000E+33 00300.0000 .10000E+33 PASS 22-AUG-88 13:32:19

/ RELAY CURRENT, DROPOUT VOLTAGE, AND PICKUP VOLTAGE
 RELAY CURRENT CW 1 mAmps 00043.0000 00028.0000 00038.8220 PASS 22-AUG-88 13:34:12
 RELAY CLOSED 15.0 V CW 1 Ohms 00300.0000 00000.0000 00002.8880 PASS 22-AUG-88 13:34:25
 RELAY DROPOUT 0.5 V CW 1 Ohms .10000E+33 00300.0000 .10000E+33 PASS 22-AUG-88 13:34:39
 RELAY PICKUP 21.0 V CW 1 Ohms 00300.0000 00000.0000 00003.0860 PASS 22-AUG-88 13:34:52
 RELAY CURRENT CCM 1 mAmps 00043.0000 00028.0000 00038.6340 PASS 22-AUG-88 13:36:34
 RELAY CLOSED 15.0 V CCM 1 Ohms 00300.0000 00000.0000 00002.2130 PASS 22-AUG-88 13:36:48
 RELAY DROPOUT 0.5 V CCM 1 Ohms .10000E+33 00300.0000 .10000E+33 PASS 22-AUG-88 13:37:01
 RELAY PICKUP 21.0 V CCM 1 Ohms 00300.0000 00000.0000 00001.8450 PASS 22-AUG-88 13:37:14

/ MOTOR RUNDOWN
 SPINMOTOR RUNDOWN RATE 1 Rpm/H 12000.0000 00000.0000 05342.5671 PASS 22-AUG-88 13:39:48
 \END

NAME R.L. 252 VOOBZ ALC WR

DATE 2-6-5

RCC MAN/PGC

SHEET 7 OF 13

PCII USN-

74149A

WCD 4/18

WCD DATE C 8/19

[illegible]

LSC-21X192C

9:44 TUESDAY, MARCH 28, 1989 35

SHEET 7 OF 3

NAME *Richard L. ...* SAS
ITEM CD PCN 74149A
ALC WR
DATE
WCD
WCDDATE CR119

DATE	4/19/87
ALC WR	
WCD	
WCCDATE	08119
ITEM CD	PCN 74149A

ITEM CD PCN 74149A

OPER NUMING	RCC	OPER DESC	HIST OCCR	MAND OCCR	OPER TYPE	MAND F	HRS	SKILL CD/LVL	QTY	X	HRS	EQUIP CODE
10	MANPGC	REC	1.00		T							

10 MANPC REC S

0	MANPGC	REC			
			1000P	0.1	IG09
				1	0.1

0	MANPGC	NDI	0.99	T

MANPGC NDI S

MANPGC	NDI	IG09	Q.3	1022
		1000 P	0.0	

MANPGB	NDI	P	IG10	1	0.8	0.450
			100			

MANPGC	DIS	0.99	Y

MANPGC DIS . S

MANPGC	DIS						
		<i>70</i>					
		<i>keep</i>					
			O.R.	IGD9	1	0 2	0005

MANPGC DIS 0.99 7

MANPGC DIS S

[illegible]

50% of wheat and
barley.

SAS

OPERATION PROFILE

ALC WR

DATE _____

WCDDATE C8119

WCD

Harvard College

ITEM CD PCN 74149A

OPER NUMB	RCC	OPER DESC	HIST OCCR	MAND OCCR	OPER TYPE
--------------	-----	--------------	--------------	--------------	--------------

OPER DESC	HIST OCCR	MAND OCCR	OPER TYPE
--------------	--------------	--------------	--------------

HIST	MAND	OPER
OCCR	OCCR	TYPE
1	1	1
2	2	2
3	3	3
4	4	4
5	5	5
6	6	6
7	7	7
8	8	8
9	9	9
10	10	10
11	11	11
12	12	12
13	13	13
14	14	14
15	15	15
16	16	16
17	17	17
18	18	18
19	19	19
20	20	20
21	21	21
22	22	22
23	23	23
24	24	24
25	25	25
26	26	26
27	27	27
28	28	28
29	29	29
30	30	30
31	31	31
32	32	32
33	33	33
34	34	34
35	35	35
36	36	36
37	37	37
38	38	38
39	39	39
40	40	40
41	41	41
42	42	42
43	43	43
44	44	44
45	45	45
46	46	46
47	47	47
48	48	48
49	49	49
50	50	50
51	51	51
52	52	52
53	53	53
54	54	54
55	55	55
56	56	56
57	57	57
58	58	58
59	59	59
60	60	60
61	61	61
62	62	62
63	63	63
64	64	64
65	65	65
66	66	66
67	67	67
68	68	68
69	69	69
70	70	70
71	71	71
72	72	72
73	73	73
74	74	74
75	75	75
76	76	76
77	77	77
78	78	78
79	79	79
80	80	80
81	81	81
82	82	82
83	83	83
84	84	84
85	85	85
86	86	86
87	87	87
88	88	88
89	89	89
90	90	90
91	91	91
92	92	92
93	93	93
94	94	94
95	95	95
96	96	96
97	97	97
98	98	98
99	99	99
100	100	100

OPER DESC	HIST OCCR	MAND OCCR	OPER TYPE
--------------	--------------	--------------	--------------

OPER DESC	HIST OCCR	MAND OCCR	OPER TYPE
--------------	--------------	--------------	--------------

OPER DESC	HIST OCCR	MAND OCCR	OPER TYPE
--------------	--------------	--------------	--------------

OPER DESC	HIST OCCR	MAND OCCR	OPER TYPE
--------------	--------------	--------------	--------------

OPER DESC	HIST OCCR	MAND OCCR	OPER TYPE
--------------	--------------	--------------	--------------

OPER DESC	HIST OCCR	MAND OCCR	OPER TYPE
--------------	--------------	--------------	--------------

OPER DESC	HIST OCCR	MAND OCCR	OPER TYPE
--------------	--------------	--------------	--------------

RCC MANPGC

QTY	%	HRS
1	100	1

QTY	%	HRS
1	100	1

QTY	%	HRS
1	100	1

50 MANPGC ASSY 0.99 . T

50 MANPGC ASSY . . . S

50	MANPGC ASSY	IG09	1	0.5
50	MANPGC ASSY	IG09	1	0.5

60 MANPGC ASSY 0.99 T

60 MANPGC ASSY S

QTY	DESCRIPTION	UNIT	PRICE	TOTAL
1	MANPGC ASSY	1.5	1022	1.5
1	MANPGC ASSY	1.5	1022	1.5

	MANPGC	NDI	0.99	T
70				

70 MANPGC NDI S

70	WAMPGC	NDI	1 P	1	0.1
			10/	109	

10 MANPGC ASSY 0.97 T

90 MANPGC ASSY S

NO	MANPGC ASSY	1	0.5	0.002	1	1.0
10	MANPGC ASSY	1	0.5	0.002	1	1.0

[Signature]

9:44 TUESDAY, MARCH 28, 1989 37

OPERATION PROFILE
ALC WR
DATE
WCDDATE C8119

SAS
[Signature]

SHEET 3 OF 3

RCC MANPGC

QTY % HRS

NOTES

EQUIP CODE

3346

0.2

0.4

0.8

ITEM CD PCN 74149A

WCD

WCD

WCD

WCD

WCD

WCD

WCD

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

T

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

OPER NUNG

RCC

MANPGC

ASSY

NDI

1.00

P

P. J. [Signature]

NAME *P. J. [Signature]* OPERATION PROFILE SAS 9:44 TUESDAY, MARCH 28, 1989 40

ITEM CD PCN 74149ASUB1 ALC WR DATE *2/10/87* SHEET *3* OF *3*

OPER NUMB 04G HIST MAND OPER MAND SKILL WCDATE 6339 WCD F HRS CD/LVL QTY % HRS EQUIP CODE

MANPGC ASSY 1.00 P 240 IG09 1 0.2 0008 1 24

MANPGC PROC T

MANPGC PROC S

MANPGC PROC 1.00 P 1.2 IG09 1 0.2 0004 1 0.2

MANPGC NDI T

MANPGC NDI S

MANPGC NDI 1.00 P 0.5 IG09 1 0.2 9420 1 0.2

DATE
21 MAR 80

L. HORNE

STAY LONG

MNPG

TIME PER PIECE

N/A

COORDINATION OF LABOR STANDARD WITH PRODUCTION SUPERVISOR

OCC FACTOR

1.00

.69.

-69

69

.47

.47

• 69

.69

1.00

1.00

TOTAL 12.968

In accordance with AFLCR 66-4, para 3-10, coordinating agencies are allowed 10 working days from date of this form to express in writing reasons for noncoordination ("insufficient time allowed" is not to be considered). If, after this time, no reply has been received from the coordinating agency, the standard will be considered coordinated and acceptable.

DATE _____

28 Apr 80

3/A

SHOP FLOW DAY COMPUTATION FOR PRODUCTION NO: 74149A

AFLCR 66-4 Shop Flow Day Formula was used to establish this flow day standard as follows: $\text{Flow Days} = A [(B \div C) + D + E]$ where A = 1.45; B = End Item Labor Standard; C = Direct Labor Hours Per Person Per Day adjusted for indirect categories and labor efficiency; D = Routine Delays; E = Unique Delays. Repair is being accomplished as a responsible shop.


DESCRIPTION	DAYS
<p>B = Labor Standard of <u>12.96</u> Hrs C = <u>7.66</u> Daily Labor Hrs</p> <p>Value "C" is calculated as follows:</p> <p>MANPG <u>C</u> .24 + .25 + .26 + .29 Indirect Average = <u>.1</u> Hours</p> <p>MANPG <u>C</u> Labor Efficiency = <u>97</u> %</p> <p>C = 8 Hours Minus Indirect Average Times Labor Efficiency</p>	<p>B ÷ C</p> <p><u>1.69</u></p>
<p>D = Routine Delays</p> <p>a. Awaiting Maintenance (AWM) = 3.8 days</p> <p>b. One days supply at station awaiting maintenance = 4 days (average 4 stations for each C/N). This is necessary to maintain uninterrupted flow of items.</p>	
TOTAL	7.80
<p>E = Unique Delays</p> <p>a. Machine processing _____ Day(s)</p> <p>b. Machine processing delays <u>2.84</u> Day(s)</p> <p>(C) Routing to support shops <u>+ 3</u> Day(s)</p> <p>d. Others (See Reverse Side) = <u>5.84</u> Day(s)</p>	
<p>* 1 Day To Shop 1 Day In Process = 3 days TOTAL 1 Day Rwy</p>	TOTAL
	5.84
Total flow days this shop (1 + 2 + 3)	15.3
Work Shift Adjustment (Item 4 ÷ number of shifts).	-
Sum of flow days for all shops (Item 5 x 1.45)	
(Final result to be rounded up to next whole day.)	22

COMPUTED BY: W Bridge

DATE: 10 OCT 84

MIN	HOUR	DESCRIPTION	PAGE	MARK
	1	SOAK	2-18	2-8
	1	BAKE	2-19	d
	2	BAKE	2-19	2
	12(2)	EVAL	2-20	T
15		EVAL	2-20	E
	1.5	BAKE	2-21	2-2
	24(2)	SOAK	2-21	2-3
45		BAKE	2-31	F
15		BAKE	2-31	L
<u>75min</u>	<u>21.5 HRS</u>			
	<u>1.5</u>			
	<u>22.75</u>			

PROCESS FLOW CHART PCN 74149A



2004/18/89

PART OPERATION SUMMARY

PN: 15150-1
 OPERATION: 2PRT
 SAMPLE SIZE: 228
 MISSING FLOWTIMES: 0
 PRIMARY END ITEMS: 0
 PCN: 74149A
 WCD DATE: C8119
 WCD: WCD
 RCC: MANPGC
 GYRO SHOP, UNIT 3
 OUTLIERS DELETED: 0

----- MANPOWER REQUIRED -----
 SKILL QTY FRACTION TIME HOURS
 ----- EQUIPMENT REQUIRED -----
 CATEGORY QTY FRACTION HOURS BATCH
 MIN MAX

HISTORICAL DATA

ACTUAL FREQ	0	10	20	30	40	50	60	70	80	90	100	DISTRIBUTION	PARAMETERS	D VALUE	D ALPHA
0	32	23	21	7	2	2	2	2	2	0	0	UNIFORM	0.0	399.0	0.740
10	20	30	40	50	60	70	80	90	100	0	0	TRIANGULAR	0.0	1.0399.0	0.851
20	30	40	50	60	70	80	90	100	0	0	0	NORMAL	36.5	68.3	0.328
30	40	50	60	70	80	90	100	0	0	0	0	LOGNORMAL	36.5	68.3	0.072
40	50	60	70	80	90	100	0	0	0	0	0	EXPONENTIAL	37.0	0	0.208
50	60	70	80	90	100	0	0	0	0	0	0				0.19
60	70	80	90	100	0	0	0	0	0	0	0				
70	80	90	100	0	0	0	0	0	0	0	0				
80	90	100	0	0	0	0	0	0	0	0	0				
90	100	0	0	0	0	0	0	0	0	0	0				
>=100	0	0	0	0	0	0	0	0	0	0	0				

OCCURRENCE FACTOR: OCCURRENCES: 228

DISTRIBUTION OF CHOICE: LOGNORMAL

SAS

9:03 FRIDAY, FEBRUARY 24, 1989 12

PART OPERATION SUMMARY

PN: 415300
 OPERATION: ZPRT
 SAMPLE SIZE: 86
 MISSING FLOWTIMES: 0
 PCN: 74149ASUB1
 RCC: MANPGC
 GYRO SHOP, UNIT 3
 WCD DATE: 6339

PRIMARY OPERATION TYPE: NDI MATERIAL TYPE:
 END ITEMS: OUTLIERS DELETED: 0

----- MANPOWER REQUIRED ----- EQUIPMENT REQUIRED -----
 SKILL QTY FRACTION HOURS TIME FRACTION HOURS BATCH
 MIN MAX

HISTORICAL DATA

ACTUAL FREQ	0	10	20	30	40	50	60	70	80	90	100	DISTRIBUTION	PARAMETERS	D VALUE	D ALPHA
0	92											UNIFORM	0.0	92.0	0.922
1	0											TRIANGULAR	0.0	0.0	0.903
2	3											NORMAL	2.5	13.4	0.483
3	0											LOGNORMAL			1.000
4	0											EXPONENTIAL	3.0		0.639
5	0														
6	0														
7	2														
8	0														
9	0														
>=10	3														

OCCURRENCE FACTOR: OCCURRENCES: 86
 DISTRIBUTION OF CHOICE: HISTORICAL DISCRETE

5.1 PROFILE DATA FILES

The profile data files for RCC MANPGC were previously submitted under memo number NKE-E016-7603, dated July 6, 1989.

5.2 MODEL INPUT FILES

The model input files for RCC MANPGC were previously submitted under memo number NKE-E016-7603, dated July 6, 1989.

MINUTES OF
MODEL VALIDATION MEETING
June 19 thru June 23, 1989

WR-ALC/MDMSC

6-29-89

WR-ALC MODEL VALIDATION
MEETING MINUTES

19 June 89:

- . Jim Gillis started the meeting by introducing team members:

- . Jim Gillis
- . Gerald Peavy
- . Doug Keene
- . Lott Singletary

AFLC Representative:

- . Trixie Brown

MDMSC Representatives:

- . Bob Bashyan
- . Bill Rich
- . Roger VanderVoord
- . Scott Vroman

- . Jim pointed out that AFLC instructed them not to sign off the Model Validation Form.
- . Reviewed model output for RCC MANPSA. Evaluated throughput, historical flow hours vs. simulated flow hours, expected hours vs. standard hours.
- . This evaluation was performed for each item number. During this process list of major assumptions, action items and concerns were noted.

PCN 01900A: F-15 Speed Brake

- . Historical flow hours 933.5 vs. 466.70 of simulated flow hours.

Assumption:

Method of induction may be a problem. History does reflect 500 hours to complete first operation which is inspection.

Historical backshop hours were greater than simulated hours. We decided to input backshop hours back into the model.

6-29-89

WR-ALC
Model Validation Meeting Minutes
Page Two

PCN 01900A: F-15 Speed Brake (continued)

. Action items:

Doug to verify the manpower utilization.
Bill to review expected and standard hours.

PCN 05502A: C-141 Aileron

- . Simulated throughput 13.2% difference. The difference was due to sporadic induction method.

PCN 51334A: C-141 Leading Edge Horizontal Stabilizer

- . Bill to review expected hours.
- . Increase backshop hours by 180 hours based on historical report.

PCN 51352A: C-141 Access Door

- . Bill to review expected hours.
- . Increase backshop hours based on historical report.

PCN 51418A: C-141 Leading Edge Wing

- . Bill to verify expected hours.

PCN 51454A: C-141 Petal Door

- . Bill to review the subassembly process hours.
- . History had one sample of 698 days - adjusted for this odd occurrence and made hours from 2288 to 1334.
- . This completes the evaluation of model output for RCC MANPSA. At the end of this evaluation, Bob summarized the action items and assumptions. Jim commented that the model

WR-ALC
Model Validation Meeting Minutes
Page Three

seems to be doing what it is suppose to and asked MDHSC team to complete the action item and re-run the output. Jim also stated that either expected or standard hours can be used in establishing baseline of model based on IE's judgment. AFLC's representative, Trixie Brown, disagreed with Jim's comment. Validation team decided that during evaluation of difference between historical vs. simulation, 10% should be used only as a guideline not as a measurement.

Evaluation of RCC HANPGC:

- . Evaluated the model output for the following PCNs: 06121A, 74061A, 74063A, 74146A, 74148A and 74149A.
- . Review of throughput, historical vs. simulated flow hours and expected vs. standard hours revealed the following:
 - . Expected vs. standard hours were within acceptable range.
 - . Throughput was good.
 - . Flow hours showed lot of difference between simulation and history. Review of historical report revealed that an unique pattern of process is being followed in Gyro Shop. Gyros after inspection were stored/held for long period of time before the start of repair operation.
 - . Discussed about this problem. Doug and Jim wanted to have some methodology to show the unique holding process.

20 June 89:

- . Bruce Kirk of MDHSC joined us to facilitate our brainstorming effort.
- . Conducted brainstorming effort at Building 169. Morning session for Sheet Metal RCC's HANPSA, HANPSB, HANPSC, and HANPSD and afternoon for Gyro RCC's HANPGA, HANPGS, and HANPGC.

6-29-89

**WR-ALC
Model Validation Meeting Minutes
Page Four**

- . Due to the nature of process and similarity we decided to have one brainstorming effort for Sheet Metal (4 RCCs) and one for Gyro (3 RCCs).
- . Doug arranged both the sessions by bringing in representatives from manufacturing, scheduling, planning and quality.
- . Both the sessions went out very good with a lot of participation. Developed fish bone - details of fish bone and brainstorming activities are covered in minutes of model validation/brainstorming.

21 June 89:

- . Evaluated the model output for all the RCCs MANPSA, MANPSB, MANPSC, MANPSD, MANPGA, MANPGB, and MANPGC.
- . Redlined the backshop hours and added buffer operations as requested by ALC for Gyro RCCs.
- . Input all the changes and re-run the model.
- . Dick Donnelly and Lou Mavros joined us to support our model validation effort.
- . Dick, Lou, Bob and Gerald had an opportunity to meet Mr. Clinton Lewis. Discussed about the validity of model and about future task orders.
- . Jim Gillis will be on vacation for the rest of the week.

22 June 89:

- . Evaluated the re-run of model output after inputting the redlined corrections.

6-29-89

NAME *John*
 ITEM CD PCN
 OPER RCC
 NUMB
 04G MANPGC
 04G MANPGC
 04H MANPGC
 04H MANPGC
 04H MANPGC
 04I MANPGC
 04I MANPGC
 04I MANPGC

WR-ALC
 Model Validation Meeting Minutes
 Page Five

MANPSA

Q1900A: F-15 Speed Brake

- . Expected vs. standard hours is acceptable.
- . Historical vs. simulated flow hours - still have a problem. History shows operation 10 takes about 500 hours to complete. This is due to induction and priority problem. Operation 40 shows 68 hours to complete (waiting for engineer) whereas model shows 1 hour. One hours represents process hour whereas 68 hours includes waiting time also.

Q5502A: C-141 Aileron

- . This a PDM item. No historical data available. Evaluated the output and verified with mechanics and planners to validate the model output.

Q51334A: C-141 Leading Edge Horizontal Stabilizer

- . Standard vs. expected hours is within acceptable range.
- . Backshop hours were off. Redlined the output.

51454A: C-141 Petal Door

- . Model output does seem to represent as-is condition.

51352A: C-141 Access Door

- . Redlined backshop hours to represent historical data.

MANPSD

Q9193A: F-15 Radome

- . Expected vs. standard hours is within acceptable range.

**WR-ALC
Model Validation Meeting Minutes
Page Six**

- . Simulated flow hours are almost double the historical. Review showed us operation 190 takes about 550 hours to complete.
- . Operation 190 is repair operation performed by one mechanic for about 50 hours. Model shows the manpower availability as a problem.
- . Doug pointed out that the model exaggerates the problem.

41059A: C-130 Radome Assembly

- . Model output does seem to represent the as-is condition.
- . Needed to verify the historical data of 500 hours for operation 10.

51420A: C-141 Wing Leading Edge

- . Evaluated the output and redlined backshop hours.

40208A: C-130 Radome

- . Output does seem to represent the as-is condition except the historical hours for Operation 30.
- . History shows that it takes over 4000 hours to complete Operation 30.
- . Bob to check the historical input data at St. Louis, if available and respond to WR-ALC.

03172A: F-15A Canopy

- . Evaluated model output. History shows that it takes approximately 1180 hours to complete Operation 10.
- . Operation 10 is to inspect and determine what parts are required to perform the repair. It does wait for a long time in getting those required parts.

MANPSB

- . This is a manufacturing RCC.
- . No historical data for analysis. Reviewed only the throughput.
- . Model output was validated based on it's performance on the other 6 RCCs.

MANPG

- . Evaluated the re-run of model out for RCCs MANPGA, MANPGB and MANPGC.
- . Output for these RCCs were reviewed earlier. Buffer operation were added where necessary to represent historical data.
- . Output for PCNs 74010A, 74074A, 74163A, 74126A, 74051A, 20012A, 06121A, 74061A, 74063A, 74146A, 74148A, and 74149A from all the three RCCs were individually evaluated.
- . Flow hours, process hours and throughput were within acceptable range. Model does represent the as-is condition.
- . Doug and Lott questioned the validity of historical data for PCNs 74074A and 20012A. Wanted to verify with manufacturing personnel.

23 June 89:

- . Doug and Lott verified and confirmed the flow hour information.
- . Reviewed the re-runs of model output.
- . Bob compiled the meeting of minutes and reviewed with team members.

6-29-89

WR-ALC
Model Validation Meeting Minutes
Page Eight

- WR-ALC/AFLC/MDMSC validation team agrees that the model seems to represent the approximation of as-is condition of RCCs MANPSA, MANPSB, MANPSC, MANPSD, MANPGA, MANPGB and MANPGC; therefore, the model can be used as a baseline for experimentation.

Doug Keene, WR-ALC/MANEE

Lott Singletary, WR-ALC/MANEE

Jim Gillis, WR-ALC/MAWF

Gerald Peavy, WR-ALC/MAWF

Terrie Brown, AFLC/MAQF



Scott Vroman, MDMSC



Bill Rich, MDMSC


for Roger VanderVoord, MDMSC



Bob Bashyan, MDMSC

7.0 COMPUTER SIMULATION ANALYSIS OF RCC

The computer simulation analysis for RCC MANPGC was previously submitted under memo number NKE-E016-7603, dated July 6, 1989.

8.0 VALIDATION OF SIMULATION ANALYSIS

The validation of simulation analysis for RCC MANPGC was previously submitted under memo number NKE-E016-7603, dated July 6, 1989.

9.0 BRAINSTORMING

The minutes for RCC MANPGC brainstorming were previously submitted under memo number NKE-E016-7603, dated July 6, 1989.

**MINUTES OF
BRAINSTORMING SESSIONS**

June 20, 1989

WR-ALC/MDMSC

**MINUTES OF BRAINSTORMING
SESSION FOR THREE GYRO RCCs
- June 20, 1989 Afternoon Session -**

Doug Keene introduced Bruce Kirk to the members of the afternoon session. The following were in attendance:

Bashyam, Bob	MDMSC
Boyt, James	WR-ALC/HAQNG
Driver, Claude	WR-ALC/MANERG
Floyd, Donald	WR-ALC/MANPGB
Harrelson, Dan	WR-ALC/MANPGA
Hulett, Earmon	WR-ALC/MANSAA
Keene, Doug	WR-ALC/MANEE
Kirk, Bruce	MDMSC
Moriarty, Brenda	WR-ALC/MANERA
Pate, William	WR-ALC/MANPGA
Sessions, David	WR-ALC/MANEE
Smith, Oscar	WR-ALC/MANPGB
VanderVoord, Roger	MDMSC

Bruce started the brainstorming session by briefing the process of brainstorming and round robin solution. Following are the suggestions:

1. Space - Building 158.
2. Turn over of skilled people.
 - Grade structure vs. \$
 - Not being replaced
3. Projected workload - higher actuals than projected.
4. Primarily funding from Oklahoma City - lack of funding so not hiring.
5. Layout - need more space to improve flow.

Minutes of Brainstorming Session
June 20, 1989 Afternoon Session
Page Two


6. Equipment maintenance and calibration - availability of parts/manpower.
7. Induction system problem on assest availability.
8. ATE availability (saturates at 2 shifts).
9. Equipment modernization to improve throughput on rate gyros.
10. Parts availability - need local storage.
11. Quality of parts -
 - Bearings (rusty)
 - Poor part packaging
12. Present prioritizing does not warrant overtime.
13. Poor planning - "critical" end items budget. Receive sufficient people and overtime; everything else falls behind!
14. Space and equipment limitations result in 2nd shift for critical items.
15. Mil-specification parts some variability of quality.
16. Environmental restrictions on chemical cleaning.
17. Power
 - A. Regulated
 - B. Sudden loss (averages 2 times a month)
18. Clean room out of tolerance - power loss (air handlers then need to catch up).

DEVELOPED FISHBONE (CAUSE AND EFFECT) DIAGRAM.

NOTE: AS-IS SIMULATION MODEL WAS LOADED AT WR-ALC's VAX SYSTEM AND THE UDOS PROGRAM RAN SUCCESSFULLY ON 6-23-89.

THESE MINUTES WERE COMPILED BY BASHYAN.

GYRO SHOP FISHBONE - CAUSE & EFFECT DIAGRAM



RCC: MAN PGC SUMMARY OF RE-EVALUATION

- Reformatted the results of L9 taguchi orthogonal array table.
- Evaluated throughput of each run for average throughput of RCC.
- Analyzed and tabulated results of best and worst PCN for each run including surge.
- This approach gives us a better understanding of the RCC's capability, process, and bottlenecks.

MANPGC CONTROL FACTORS
TABLE 10.3.2-1

BASE			BASE+ (AS-IS)			BASE++		
EQUIP. NO.	EQUIPMENT NAME	EQUIP. QTY.	EQUIP. NO.	EQUIPMENT NAME	EQUIP. QTY.	EQUIP. NO.	EQUIPMENT NAME	EQUIP. QTY.
0002	VACUUM OVEN	6	0002	VACUUM OVEN	12	0002	VACUUM OVEN	12
0787	TEST ASSY	3	0787	TEST ASSY	5	0787	TEST ASSY	5
0844	TEST ASSY	1	0844	TEST ASSY	2	0844	TEST ASSY	2
3346	LEAK DETECTOR	3	3346	LEAK DETECTOR	6	3346	LEAK DETECTOR	6
5509	RATE TEST	2	5509	RATE TEST	4	5509	RATE TEST	4
8437	TESTER	1	8437	TESTER	2	8437	TESTER	2
9015	GYRO TEST	2	9015	GYRO TEST	4	9015	GYRO TEST	4
9036	DIRECT TEST SET	2	9036	DIRECT TEST SET	4	9036	DIRECT TEST SET	4
9058	TEST PANEL	1	9058	TEST PANEL	2	9058	TEST PANEL	2
9420	TEST SET	2	9420	TEST SET	4	9420	TEST SET	4
			IG09	MANPOWER	55	IG09	MANPOWER	60

LSC-20620

C
MANPG/ GYRO SHOP TAGUCHI ORTHOGONAL ARRAY
TABLE 10.3.2-2

RUN #	FACTORS & LEVELS					WORKLOAD (THROUGHPUT)		
	MANPOWER		OVERTIME		EQUIPMENT	INDUCTIONS: 6286: 120% OF FY 88		
	1	2	3	SAT	SUN	AVG.	BEST	WORST
1	ALL					BASE	74081A 80.3 %	74148A 101.0 % 4.0 %
2	ALL			YES		BASE +	74146A 98.6 %	74148A 100.4 % 97.5 %
3	ALL			YES	YES	BASE ++	74148A 99.2 %	74148A 100.3 % 97.0 %
4	80% 80%					BASE ++	74148A 99.2 %	74148A 100.0 % 97.5 %
5	80% 80%			YES		BASE	74083A 81.2 %	74148A 100.0 % 5.0 %
6	80% 80%			YES		BASE +	74148A 98.9 %	74148A 100.0 % 97.5 %
7	1/3 1/3 1/3		1/3			BASE +	74146A 99.0 %	74148A 100.0 % 97.5 %
8	1/3 1/3 1/3		1/3	YES	YES	BASE ++	74148A 99.0 %	74148A 100.0 % 97.6 %
9	1/3 1/3 1/3		1/3	YES	YES	BASE	74081A 80.2 %	74148A 100.0 % 6.0 %
SURGE*	80%**	80%**				BASE +	74081A 98.0 %	74083A 100.2 % 97.5 %


NOTES:
 * INDUCTIONS = 4270 (50% OF FY 88) - 2 & 1K
 ** TWO 12 HOUR SHIFTS.

LSC-20621

MANPGC GYRO SHOP TAGUCHI ORTHOGONAL ARRAY
TABLE 10.3.2-1

RUN #	FACTORS & LEVELS					WORKLOAD (THROUGHPUT)			
	MANPOWER		OVERTIME		EQUIPMENT	130% OF FY 88		SURGE	
	1	2	3	SAT	SUN	QTY	%	QTY	%
1	ALL					BASE	4253	80	3408
2	ALL			YES		BASE +	5225	98	
3	ALL			YES	YES	BASE ++	5255	98	
4	50% 50%					BASE ++	5256	98	
5	50% 50%			YES		BASE	4325	81	
6	50% 50%			YES		BASE +	5246	98	
7	1/3 1/3 1/3		1/3			BASE +	5250	98	
8	1/3 1/3 1/3		1/3	YES	YES	BASE ++	5246	98	
9	1/3 1/3 1/3		1/3	YES	YES	BASE	4250	80	

LSC-20353



MANPGC EXPERIMENTATION RESULTS
FIGURE 10.3.2-1

LSC-20354

MANPGC - WRALC

QTY: 5340

MANPOWER:

- 1) $\frac{4253 + 5225 + 5255}{3} = 4911 = 92\%$
- 2) $\frac{5256 + 4325 + 5246}{3} = 4942 = 92.5\%$
- 3) $\frac{5250 + 5246 + 4250}{3} = 4915 = 92\%$

OVERTIME:

- SAT : $\frac{5225 + 5246 + 4325}{3} : 4932 = 92\%$
- SAT+SUN : $\frac{5255 + 5246 + 4250}{3} : 4917 = 92\%$
- 40HRS : $\frac{4253 + 5256 + 5250}{3} : 4920 = 92\%$

EQUIPMENT:

- BASE : $\frac{4253 + 4325 + 4250}{3} = 4276 \quad 80\%$
- BASE + : $\frac{5225 + 5246 + 5250}{3} : 5240 \quad 98\%$
- BASE ++ : $\frac{5255 + 5256 + 5246}{3} : 5252 \quad 98\%$

MANPGC - WRALC

WORKLOAD QTY 5340/YR.

BASE: WORKLOAD IS SAME AS IN AS-IS
CONDITION AND ALSO THE OTHER
RESOURCE FILE - EXCEPT - THE CHANGE
IN QTY OF EQUIPMENT.

EQUIPMENT	CHG. QTY TO
0002	6
0787	3
0844	1
3346	3
5509	2
8437	1
9015	2
9036	2
9058	1
9420	2

BASE+: ALL THE RESOURCE FILE ARE SAME
AS IN AS-IS CONDITION.

BASE++: ALL THE RESOURCE FILE ARE SAME
EXCEPT CHANGE MP- IGO? TO 60 (8%)

SURGE: INCREASE THE FY88 WORKLOAD
BY THE AVG. SURGE FACTOR OF
WEAPON SYSTEMS SERVICED AT WR-ALC
WHICH IS 159%.
SPREAD MANPOWER BETWEEN (2) 12HR:
SHIFT AND 5 DAYS A WEEK SCHEDULE.

MANPEC - WRALC

SUMMARY:

REVIEWED THE RESULTS OF THE OUTPUT ANALYSIS OF THIS EXPERIMENTAL DESIGN FOR RCC MANPEC. EXPERIMENT WAS DESIGNED TO ANALYSE THE SENSITIVITY OF % OF EQUIPMENT REQUIRED AND THE IMPACT ON THROUGHPUT BY INCREASING % OF OPI.

SIMULATION OUTPUT RUNS INDICATES THAT THE REQUIRED % OF EQUIPMENT HAS BEEN OVERSHOT. WITH ALL THE AVAILABLE EQUIPMENT AND MODIFIED MANPOWER, THE THROUGHPUT WOULD GO UP.

RUN #5 WAS EXECUTED FOR ONLY 2000 SLS TO THE EDU TIME. THE THROUGHPUT WAS CALCULATED AT A REPRESENTATIVE PERCENTAGE I.E. 80% THROUGHPUT.
 $2000/2702 = 81\%$. SO 81% OF 5340 IS 4325.

SURGE REQUIREMENT WERE EXECUTED FOR STATE TO SEE THE SENSITIVITY. IT REVEALS THAT 80% OF THROUGHPUT CAN BE ACCOMPLISHED WITH PRESENT RESOURCE.

TECHNOLOGY INSERTION PROGRAM

WR-ALC

MANPG - GYRO SHOP

Bob Bashyam
Roger VanderVoord

Possible Focus Study List

Description

RCC

1. RCC WR/MANPGB and AGMC/MANPGB Automatic Test Equipment vs. Product Optimization
2. RCC WR/MANPGB and AGMC/MANPGB Increase of Automatic Test Equipment Up Time
3. Combine Gyro Rotor Repair to Common Line With Balanced Station Time
4. Develop Program to Attack T. E. Obsolescence [Bench Sets]
5. Fill Procedure for 74074A to Replace Present Station
6. Automate Depaint, Unseal, Reseal Process
7. Improve Bearing Procurement/Handling Procedure
8. Laser Wheel Balancing (Delay/Monitor AGMC)
9. Compare A.T.E. to Manual (Delay for Results From 1)

Page 9

Following are the Potential Improvements for Quick Fix.

10.31 QUICK FIX OPPORTUNITY TO IMPROVE GIMBAL/SPIN BEARING HANDLING (MANPG)

10.31.1 Description of Current Operations

Bearings being removed from repairable gyroscope product are handled as non-reclaimable material. Little or no care is evident in the removal and/or storage of the bearings prior to attempts to refurbish.

10.31.2 Description of Current Process Problems

Bearings are being damaged during removal by pressing operations, open line storage and piling in uncontrolled containers. Storage is accomplished in open tote boxes or plastic bags with many piled loosely on top of each other continuing the opportunity for damage.

10.31.3 Description of New Process

MDMSC recommends tote tray inserts that locate the I.D. bore of the bearings in a manner to prevent contact of adjacent bearings and control vertical stacking. Further action is required in development of personnel training to instill importance of bearing handling during unit teardown. The use of the tote boxes should be continuous through bearing refurbishment and storage, only being discontinued when bearing is defined as scrap.

10.31.4 Rationale Leading to Change

Both WR-ALC and AGMC are presently engaged in bearing refurbishment with varying degrees of success. If handling damage can be eliminated or reduced, refurbishment yields can be improved. The refurbishment procedures remove contaminants but cannot correct physical damage to the bearings. The lack of proper handling of bearings was observed thru all three gyro RCC's.

Reliability/Maintainability Characteristics: Should improve MTBF by reducing possibility of returning physically damaged bearings to product.

Human Factors Design Criteria: Re-establish the importance of proper procedure of teardown on unit acceptance yields.

Generally private industries use special bearing pullers during teardown - tote box inserts are used to handle and store bearings expected to be salvaged and returned to product.

10.31.5 Estimated Cost Savings

Actual line observations and interviews with RCC personnel suggest a yield improvement in refurbished bearings in excess of 20%. The improvement will give double fold savings by yielding more product per refurbishment cycle and reducing induction costs of additional new bearings.

Approximately 12,000 units are repaired in MANPG yearly. Assuming each contains an average of four precision ball bearings and half require refurbishment or replacement, 48,000 precision bearings would be available for consideration. Further if half are replaced, 24,000 are committed to refurbishment. The expected 20% improvement would amount to 4,800 bearings reclaimed over present methods. Using \$2.75 as an average cost per ABEC 5 ball bearing, \$13,200/year savings is available. No additional labor is added because the refurbishment attempt is completed regardless.

10.31.6 Implementation Cost/Schedule

Some MANPG administrative costs will be incurred due to training of personnel and development of a family of tote box inserts. Schedule and performance will improve as availability of critical bearings improves from the high bearing reclamation yield.

The development of the inserts should require approximately 20 labor hours and would require approximately 200 tote box inserts at less than \$5.00 each.

The implementation could be accomplished in three months.

10.32 QUICK FIX OPPORTUNITY TO MOTORIZE DIVIDING HEAD STANDS (HANPG)

10.32.1 Description of Current Operations

The manual test stands for directional and vertical displacement gyros are positioned and/or turned through cranking of hand wheels or hand wheel extenders.

10.32.2 Description of Current Process Problems

The hand cranking is laborous and is avoided by operator using alt. equipment and/or developing methods outside the T.O.

10.32.3 Description of New Process

MDHSC recommends the dividing heads of the manual test stands be motorized in both axis. The motor drives should be frictional to eliminate the need for expensive clutching systems and should allow for final positioning by the operator to eliminate encoders and servo systems. The drives should allow for a smooth constant rate but need not be of great accuracy.

10.32.4 Rationale Leading to Change

Directional gyros were observed waiting the availability of an alternate test set, KT426206, that was motor driven in one axis. Actual interviews of RCC personnel determined this was preferred to hand cranking the manual dividing heads. The hand cranking was very laborous and a smooth rate was difficult to maintain.

Safety Improvements: The hand wheels and extenders are presently in position to allow injury from tripping and/or running into. This hazard should be considered in the design.

Reliability/Maintainability Characteristics: Improvements possible due to closer adherence to T.O.'s.

Human Factors Design Criteria: Less laborous than hand cranking thereby reducing operator fatigue. Improvement in operator concentration.

10.32.5 Estimated Cost Savings

The benefit to be gained in test station capacity and versatility. By removal of the test stand avoidance, adherence to the T.O.'s will improve. Some cost savings are to be realized by reducing operator fatigue but would be difficult to quantify. Throughput should improve by reducing queuing time for the preferred test set.

10.32.6 Implementation Cost/Schedule

A single design would be necessary for all test stands. It would require approximately 75 hours to accomplish. The design could be incorporated into the test stands on a progressive basis to control cost occurrence. It should be incorporated for directional gyros first and then onto the vertical test stands. The actual cost of hardware implementation estimates should be made at completion of design phase. No adverse schedule impact is foreseeable.

The design and build time for the modification could be accomplished within three months for the first group with build of one month for the following groups.

10.33 QUICK FIX OPPORTUNITY TO FIXTURIZE THE INDUCTION MACHINE (HANPG)

10.33.1 Description of Current Operations

To hold unit or subassembly in some hand clamping devise, activating the induction heater to heat the assembly until the solder flows. Strike the assembly on a part of the machine to impart enough energy to the assembly to force it apart.

10.33.2 Description of Current Process Problems

The units or subassemblies are being subjected to uncontrolled heat and shock forces producing damage to the units. The operation produces scrap and additional rework.

10.33.3 Description of New Process

MDHSC recommends that a list of all operations of disassembly performed on the induction machine be accomplished. A fixture designed with clamping devises for the list of units/subassemblies that can apply a separating spring force across the solder joint being heated. The spring force will be variable to allow control for the various units/subassemblies. Staging will be incorporated to assure heating of the separable joint with minimal heating of the rest of the assembly.

10.33.4 Rationale Leading to Change

Many observations of the induction machine operations were made. Much of the product from each of the three RCC's passes across it for disassembly operations. Forces great enough to distort parts and heating great enough to produce flaming insulation and cherry red metallic parts were seen in these observations. The suggested fixturization is used successfully in private industry.

Safety Improvements: Reduce or eliminate danger of injury from burns due to falling parts, burning insulation and solder splashes.

Environmental Hazards/Improvements: Elimination of fumes from burning insulation, solder fluxes and other combustible materials.

Reliability/Maintainability Characteristics: MTBF and MTBR should improve by eliminating structural changes in critical parts due to controlled temperature and reduced shock forces.

10.33.5 Estimated Cost Savings

Approximately 4,500 units pass across the induction heater for opening each year. The amount of scrap and/or damage caused by the present method is not recorded or identified. All units are experiencing unnecessary damage.

Large savings will be realized in greatly reducing unit/subassemble clean-ups, rewiring and part replacement costs. Fixtured disassembly should reduce disassembly damage, half clean-up time and eliminate rewiring due to heat damage. Intangible benefits will be gained through reducing structural change of metallic parts due to reduced heating. Tangible savings should also be obtained from increased MTBF though not quantifiable.

10.33.6 Implementation Cost/Schedule

Preparing a product list and accomplishing a fixture design will require approximately 100 hours with fixture build requiring a like amount. Implementation could be accomplished within two months of turn-on. No adverse schedule impact will be seen. The fixturization is add on causing little or no machine time interruption.

10.34 QUICK FIX OPPORTUNITY TO REMOVAL OF CLEAN ROOM GARB (MANPGA)

10.34.1 Description of Current Operations

MANPGA requires full suits, caped hoods and booties be worn and in place prior to entering the lab area. Air locks are also used for entering or exiting the suiting-up area.

10.34.2 Description of Current Process Problems

The requirement is inconsistent with other controls in the area and with like product in other areas. It is not considered necessary for like product by much of private industry today. The garb is doing little if anything to improve product cleanliness.

10.34.3 Description of New Process

Remove the requirements for the full suits, hoods and booties. Replace the air locks and dressing rooms with tack mats at lab entrances. Reprocess critical operations to laminar flow booths. Remove all excess material from the laminar flow booths. Forbid eating and drinking in the labs. Reduce dirty operations such as unsealing, resealing and filing or restrict them to force ventilated booths. Reduce line storage of product and equipment. NOTE: The restrictions on eating and drinking should be extended to MANPGB and MANPGC. The use of coat smocks might be encouraged to continue importance of cleanliness.

10.34.4 Rationale Leading to Change

Observations of lab conditions, actual interviews with lab personnel, general knowledge of lab requirements through participation in the contamination control working group of the Inertial Guidance Community.

The present laminar flow booths are being badly misused. All are full of parts, tools, personal items. The filter areas are posted with schedules, tech. items, etc. All these items cause air flow restrictions and greatly reduce flow bench effectiveness.

Human Factors Design Criteria: Less restrictive of personnel movement, improved coverage by support functions.

10.34.5 Estimated Cost Savings

Labor savings will be realized from removal of all suit and unsuit up time. This is estimated to be greater than .8 hour per employee per day. Also savings can be realized in eliminated laundry costs of suits, hoods and booties. Additional

cost savings will be realized from elimination of replacement costs. Product improvements will be accomplished by a disciplined cleaning schedule that is not limited to dust count improvement. An intangible savings should be realized through improved product support by removing the reluctance of support personnel to enter the lab areas. Areas presently used for suiting up also become available but building construction may limit it's usability.

10.34.6 Implementation Cost/Schedule

Some front end costs may be experienced by MANPG administration to develop laminar flow booth disciplines and cleaning schedules but these should be minimal and no adverse impact is expected on schedule.

The implementation schedule will be dependent on review of T.O. requirements and possible reluctance of change. AGMC and private industry practices and success rates should encourage acceptance.

10.35 QUICK FIX OPPORTUNITY TO IMPROVE RANDOM DRIFT DECISIONS (MANPGC)

10.35.1 Description of Current Operations

After sealing, units are placed on scorsby tables and connected to the test panel. The unit's heading error value is automatically printed out each half hour. One to twenty units are able to be tested at any time. An operator periodically enters the room and observes each unit's drift trend. As unit deviates from specification the readings are calculated for trending. At some point known only to this operator and influenced by time of day trending units are rejected, removed from test and sent to the sealing room along with test data to be opened and adjusted. The unit is resealed, returned to test and the process is restarted. Procedure is repeated until unit passes the eight hour test or is a hard failure.

10.35.2 Description of Current Process Problems

The rejection rate for first and second attempts appears to be 30%. From limited data, 30% appeared to continue into the third and fourth attempt. The decision to readjust does not seem to be bounded either by amount of trending or length of run time. The units are unsealed and adjusted on the second shift only and this may account for the looseness in decision timing. It does not appear to be controlled well enough to assure consistent product.

10.35.3 Description of New Process

Incorporate a decision devise into the panel to plot trending and automatically discontinue test at time of failure. Add a vented solder station and fill manifold to the test area to allow for immediate readjust and return to test. Use the operator who presently observes and plots the trending to increase his productivity.

10.35.4 Rationale Leading to Change

Discussions with the test personnel and review of available test data lead to the opinion that the control does not assure consistent product. It also lead to the conclusion product flow could be improved if adjustments could be made at the test site.

The approach generally taken by private industry in this type of testing is to tightly describe the acceptance values and allow for automatic rejection at the earliest point. This allows for least false testing time and quickest return to productive work. The approach improves throughput and reduces flow time.

10.35.5 Estimated Cost Savings

Elimination of move time and queue times waiting for second shift operator. Development of adjustment expertise from cause and effect relationship. Efficient usage of testers time. Consistent rejection/acceptance decisions.

10.35.6 Implementation Cost/Schedule

Costs to be incurred would be the addition of a go/no-go device on the present panel plus installation costs of a vented solder station and fill manifold. No adverse impact on schedule.

Schedule time to implement the change should require less than three months.

10.36 QUICK FIX OPPORTUNITY TO REARRANGE CN 74051A TEST/REPAIR AREA (MANPGB)

10.36.1 Description of Current Operations

The repair stations are located on a heavy traffic aisle between the main building corridor and the sealing area. The test panels are located next to the repair stations on a dead end aisle.

10.36.2 Description of Current Process Problems

The repair operators are subjected to many distractions by the heavy traffic pattern through their area. Both their peers from other areas and various support personnel pass the work stations in performance of the daily tasks.

10.36.3 Description of New Process

Exchange the 010 test/calibration panel line with the repair operators line (CN 74051A). The move would remove the repair operators from the traffic pattern and it's accompanying distractions. The distractions would not impact the test/calibration panel line as severely because concentration span time is shorter and unit run times between adjustments is non-productive but necessary.

10.36.4 Rationale Leading to Change

Personnel observations and actual interviews with line supervision and line operators. General knowledge of length of concentration span times for gyro assembly and repair.

Safety Improvements: Do not exist.

Human Factors Design Criteria: Improved concentration times.

10.36.5 Estimated Cost Savings

The repair operators will increase their productivity through less distraction and camaraderie from being outside of the traffic pattern. The test operators should not be adversely effected because their task has inherently more non-productive time.

10.36.6 Implementation Cost/Schedule

Re-layout of the area would require approximately 20 hours and rearrangement approximately 60 hours of labor. It could be accomplished in about two months.

10.37 QUICK FIX OPPORTUNITY TO RELOCATION OF MASS SPECTROMETERS (MANPGB)

10.37.1 Description of Current Operations

Units are solder sealed in the repair area. Hand carried to the mass spectrometer. Leak checked. Hand carried back to the repair area. The two areas are approximately 120 paces apart. The movement is made through other repair areas with the normal distractions that occur.

10.37.2 Description of Current Process Problems

Time is being wasted in non-productive travel. The time wasted is not limited to just the actual walk time but is increased due to socializing, waiting to incorporate the walk with other desired activities. The operator is removed from supervisor's servalance.

10.37.3 Description of New Process

Seal units in the repair area. Leak check in the repair area. Continue work in the repair area.

10.37.4 Rationale Leading to Change

Actual interview with RCC personnel revealed that the mass spectrometers had been placed in this remote area to reduce malfunction of the system due to air contamination in the repair area. If the contamination condition is real, it can be overcome with flushing mass spectrometers with uncontaminated air with proper duct work. This approach is used in general industry where required.

The problem may be exaggerated by increasing sensitivity of the mass spectrometer beyond the rate required to meet the product requirements.

10.37.5 Estimated Cost Savings

MDHSC recommends that the mass spectrometers be relocated in the repair area. Savings to be realized would be 0.1 hour/unit checked. Minimum of 1000 units/year are checked.

10.37.6 Implementation Cost/Schedule

Cost to move the three mass spectrometers would be four hours each or 12 hours. If an air flushing system proves necessary an additional 10 hours of rearrangement cost would be required. The move could be accomplished within one month of turn-on.

10.38 QUICK FIX OPPORTUNITY TO VENTING THE VACUUM PUMPS OF MASS SPECTROMETERS (HANPGA)

10.38.1 Description of Current Operations

Mass spectrometers called out for leak checking of CN 74074A series gyros have been shutdown. The reason given is that the discharge from the rough vacuum pumps increases the dust count in the particulate specification levels. This action forces gyros to be hand carried approximately two hundred feet to a mass spectrometer outside the area.

10.38.2 Description of Current Process Problems

Approximately 0.2 hours of non-productive labor is added to each unit processed. Process flow is further interrupted by the requirement to unsuit and result in clean room garb. Some batching is attempted but it is rather hit and miss than planned.

10.38.3 Description of New Process

Leak check CN 74074A units on specified equipment with venting and/or filtering in place.

10.38.4 Rationale Leading to Change

Simple observation recommended that the discharged air could easily be vented or filtered to eliminate the increase in dust count. The mass spectrometers could then be returned to operation.

10.38.5 Estimated Cost Savings

Reduce labor hours on units leak checked by a minimum of 0.2 hour/assembly. Approximately 2000 units of the CN 74074A family are yielded each year. A minimum yearly savings of $2000 \times 0.2 \text{ hours} \times \$ \text{ /hour}$ is available.

10.38.6 Implementation Cost/Schedule

Costs to vent the mass spectrometers would require less than 2 hours each \times 2 units. Filtering if required could add \$50.00 each. Scheduling would not be impact.

10.39 QUICK FIX OPPORTUNITY TO RE-EVALUATE NEED FOR DIAGNOSTIC CHECKS (MANPG)

10.39.1 Description of Current Operations

Receive unit, perform a complete incoming test (diagnostic check) on C/N 74146A gyroscope, teardown and repair as required, etc. The diagnostic check is performed on final test stand, KT426206, which show a usage rate of 41% at the present.

10.39.2 Description of Current Process Problems

Ninety percent of the units being repaired require complete teardown and rebuild of the gyro wheel. The ninety percent wheel repair figure was established through interview. The standards data sheets, E0468 labor standard operation resource std/method analysis, places the occurrence factor at 100%. With this high a percentage of complete teardown, diagnostic testing prior to teardown is of very limited value.

10.39.3 Description of New Process

Receive the units, teardown through the wheel, rebuild complete as per T.O.'s.

10.39.4 Rationale Leading to Change

If 90% to 100% of the units require teardown through the wheel most failures identified other than wheel failures will be removed or changed in character by the teardown process. The failures that are not found will be identified through the normal build up process. Further, the 10% that do not contain identifiable wheel failure, probably contain wheels of limited remaining life.

Reliability/Maintainability Characteristics: The MTBF and MTBR should both be impacted in a positive manner with removal of early failures of the 10% figure for wheels not presently rebuilt.

10.39.5 Estimated Cost Savings

Removal of diagnostic test time, 0.5 hours/unit offset by the addition of 3.7 hours divided by 0.1 = .37 hours/unit for an overall reduction of .13 hours/unit x 1020 units/year or 133 hours/year.

10.39.6 Implementation Cost/Schedule

No cost to implement should be experienced. No affect on schedule. Change could be implemented immediately.

NOTE: The logic applied to this unit should be refined to develop a percentage number where diagnostic test should be dropped and 100% wheel rebuild demanded for all gyro product.

10.40 QUICK FIX OPPORTUNITY TO REBONDING OF 20012A TAPES (MANPGB)

10.40.1 Description of Current Operations

Replace tapes that have become unbonded in service or tear-down with a new tape. Scrap old tape.

10.40.2 Description of Current Process Problems

The tapes that have become unbonded appear to be unnecessary scrap if a new bond could be accomplished.

10.40.3 Description of New Process

Remove parted tapes, clean, thermo-compression bond and reassemble into unit.

10.40.4 Rationale Leading to Change

Actual interviews with repair line supervisor and general knowledge of thermo-compression bonding. The tapes are not damaged other than separating. No jig or figuring should be necessary. The original parting line is evident for restaging.

10.40.5 Estimated Cost Savings

The present tapes experience 30% replacement. The present production rate for the 20012A family is approximately 1300/year or replacement rate of 500/year. Rebonding costs are .05 hours/tapes. The cost of replacement tapes is \$104.77/tape. (1299/year X 21% replacement rate.) Gross savings/year of \$28.6K. Note: Other like families of indicators should be reviewed for like tape problems.

10.40.6 Implementation Cost/Schedule

The cost of a thermo compression bonder (mico-bonder) is approximately \$2,500.00. Plus two hours installation. Schedule is dependent only on delivery of the bonder as it is a line addition. The installation could be accomplished on delivery.

10.41 QUICK FIX OPPORTUNITY TO RECLAIM C/N 74126A SPIN AXIS BEARINGS (MANPGA)

10.41.1 Description of Current Operations

The outer races of the spin axis bearings of the 74126A gyro rotors are pressed out and scrapped along with the ball complement and shaft.

10.41.2 Description of Current Process Problems

The present operation does not consider re-use of either bearing or bearing races. The races are placed in large boxes which tend to further damage parts.

10.41.3 Description of New Process

Press out outer races place races, shaft and ball complements as a matched set into some type of protective container. Route container to bearing reclamation area for cleaning and evaluation. Route acceptable sets to wheel build area for re-use.

10.41.4 Rationale Leading to Change

Observation of wheel teardown showed races being removed that appeared to show little or no wear. Some of the bearings still contained lubrication with no discolorization. Bearings and races were examined under high magnification and no wear was evident. The bearings and races are replaced in matched pairs. Examination of the unit does not immediately reveal the reason for matching race to bearing. This must be studied but which ever is required, a process for reusing the bearings could be applied.

Reliability/Maintainability Characteristics: These should be re-evaluated for impact after the process is developed. At this point no impact is identified.

10.41.5 Estimated Cost Savings

Greater than 50% of the repaired 74126A gyroscopes require wheel rebuild. No additional cost should be incurred to control and package bearings for possible reclamation. The actual cost savings to be obtained can only be protected with development of a reclamation process and establishment of the process' success rate.

10.41.6 Implementation Cost/Schedule

A reclamation process and evaluation will require the services of a manufacturing engineer for one month and the support of a gyro technician for one to two weeks. The reclamation process could then be implemented after development of this process with no direct impact on repair schedule.

**10.42 QUICK FIX OPPORTUNITY TO REDUCE OPERATOR MOVEMENT
THROUGH FIXTURE IMPROVEMENT. (74126A, OPERATION 100)
(MANPGA)**

10.42.1 Description of Current Operations

Place directional gyroscope into calibration stand. Sit down on very low stool to observe azimuth scale through straight line borescope. Stand to adjust leveling axis, sit on low stool to verify setting. Restand to continue calibration.

10.42.2 Description of Current Process Problems

The standing, sitting, standing, sitting produces both operator fatigue and unsafe conditions. The stool is required to be very low due to eye alignment. The danger to the operator is increased by the stool being castored. Also, necessary to the sighting operation.

10.42.3 Description of New Process

Place directional gyroscope into the calibration stand. Observe azimuth scale through an angled borescope. Establish at standing eye level. Adjust leveling axis. Verify setting. Continue calibration.

10.42.4 Rationale Leading to Change

Observation of the operator performing the directional gyro calibration followed with interviews with the operators and first line supervisor..

Safety Improvements: Removal of injury potential from missing or moving the castored stool while sit-down or standing. Reduction of floor obstruction with the inherent gain in personnel movement freedoms.

Environmental Hazards/Improvements: As described in safety.

Reliability/Maintainability Characteristics: Not affected.

Human Factors Design Criteria: Reduction of operator fatigue from elimination of deep knee bends required to sit and/or stand to the castored stool.

10.42.5 Estimated Cost Savings

Direct dollars savings are not predictable from this change. The savings will be found in reduced operator fatigue. The intangible savings are the reduction of station litter and the removal of a safety hazard of tripping over the stool and/or missing it while attempting to lower one's self to sit down.

10.42.6 Implementation Cost/Schedule

The only cost associated with the change is the purchase of an angled borescope to replace the present in-line borescope. Such a device would not exceed \$250.00. Schedule is not impacted. The change could be implemented immediately after receiving the borescope.

10.43 QUICK FIX OPPORTUNITY TO REDUCE TEST TIME/IMPROVE TEST ACCURACY FOR C/N 74010A VERTICAL GYRO, OPERATIONS 20 & 200 (MANPGA)

10.43.1 Description of Current Operations

Both operation 20 and 200 are performed in the same manner. The gyroscope is tested on the automatic test stand, #704424, contraves vertical console. If the unit fails for drift accuracy, the unit is routed to the manual panel, L.T. 3330, gyro test set to be re-run and accepted if drift accuracy meets specification requirements.

10.43.2 Description of Current Process Problems

Present method required retest of approximately 44% of the product. It does not assure improved accuracy of product being returned to the field.

10.43.3 Description of New Process

Route all product to manual panel, L.T. 3330 gyro test set, for operations 20 and 200. Accept or reject by test results obtained. Correct test program for automatic test stand, #704424 contraves vertical test console before testing any product across it.

10.43.4 Rationale Leading to Change

Actual interview with test personnel revealed the double test procedure. Further discussion exposed the reasoning behind the procedure. The computer program in the contraves vertical console improperly calculates Earth rate drift in one or more headings. When the unit under test fails drift rates, it is assumed that the program error is the reason for the failure and therefore the failure is not valid and re-run is justified. This is valid. However Earth rate correction is a fixed rate at a heading and latitude; therefore, an incorrect value is applicable to both passing and failing units. To re-run only failures does not assure shipping acceptable product.

Reliability/Maintainability Characteristics: Present practices sends marginal to failing product to the field. The proposed method assures product returning to field meets specification. This should effect both reliability and maintainability in a positive manner.

10.43.5 Estimated Cost Savings

Immediate gain will be the elimination of re-tests or 1/3 of test time/unit (44% re-test). This is one labor hour/re-test or 1/2 labor hour/unit tested. Present schedule forecasts 1060 units/year. Total savings to be expected 1/2 hour X 1060 units = 530 labor hours minimum.

10.43.6 Implementation Cost/Schedule

No implementation cost is required to accomplish testing as described. Costs will be incurred if the A.T.E. Program is corrected. This cost should be estimated by Contraves and/or base programmers. Timing is also dependent on contraves input.

10.44 QUICK FIX OPPORTUNITY TO OBSOLESCENCE OF OLD BENCH TEST SETS (74146A WHEEL BLD) (MANPG).

10.44.1 Description of Current Operations

The older bench test sets and ruler supply panels for the C/N 74146A, J4 direction gyro wheel ass'y, KT426193 are no longer supportable. They are of 1950 design age and contain switches and meters no longer available. The devices have been repaired in varying manners just to continue operation. Numerous starts are sometimes required to become operational. Taps or kicks are also used. The condition is general over the older units. Discussion with panel and engineering planners confirmed observations that the conditions are increasing due to age of both design and hardware of the support test stands. Most product is of the mid-fifties to early sixties design.

10.44.2 Description of Current Process Problems

Due to age of both design and hardware of the support test stands. Most product is of the mid-fifties to early sixties design. The product that the test equipment services will continue to be repaired and returned to field for many more years but is very questionable if the present support test equipment will remain supportable over such a time frame.

10.44.3 Description of New Process

10.44.4 Rationale Leading to Change

The goal of the study is identify, plan and execute corrective actions prior to lengthy production interruptions due to unsupportable test equipment. Such a plan must be completed to assure wartime/readiness and/or surge acceptable posture.

10.44.5 Estimated Cost Savings

The benefit to be obtained is continued support of the present product line and their aircraft systems.

The goal is at risk of picking the wrong start point. The goal and condition of the test equipment would predict a line shut down without an alternate test approach is possible any time. The other risk is that a satisfactory alternate method is impractical at all because of expense and/or longevity of the product line.

10.44.6 Implementation Cost/Schedule

The study should be scoped to attack one RCC at a time - possibly even one product line - identification of problems will overlap lines and/or RCC's because of like product, age and design approach. I would suggest that MANPGC be the first RCC. If that is still too large, attack directional gyro first - 74146A, 74148A and 74126A with the 74149A slaving control also included. I would further suggest the study at either level will require 2 to 3 months to general approach and cost trending.

10.45 QUICK FIX OPPORTUNITY TO IMPROVE BEARINGS PROCUREMENT AND HANDLING PROCEDURES (HANPG).

10.45.1 Description of Current Operations

The responsible OC-ALC Item Manager specifies the technical description, requests competitive bids from qualified suppliers, selects vendor(s), establishes shipment schedules and procures the required instrument bearings for annual production requirements for all ALCs. All follow up and status of the procurement is also accomplished by OC-ALC Item Manager. AGMC has no authority at all in the procurement process.

10.45.2 Description of Current Process Problems

Instrument bearing quality related problems are a major cost and schedule impact at AGMC and WR-ALC aircraft gyroscope repair activities. This impact manifests itself in corrosion that is frequently evident visually on packaged bearings when initially received at the MAPGB facility. Currently, significant rework/repair costs occur associated with bearing re-inspection, scrap efforts, and nearly 100% repair/cleaning for salvage.

10.45.3 Description of New Process

10.45.4 Rationale Leading to Change

To improve supplier reliability, procurement specifications and material handling procedures to substantially reduce labor costs and increase throughput in AGMC GRU repair operations.

10.45.5 Estimated Cost Savings

An improvement in the quality of instrument bearings available from the ALC material control inventory will eliminate current rework/repair costs associated with re-inspection and nearly 100% cleaning efforts required to produce acceptable bearings. As an example, AGMC currently plans to purchase and implement another Cyl-Sonic cleaning system to meet capacity requirements. This could be eliminated saving a minimum \$150,000 implementation expense. Also, the technology could be transferred across the Command avoiding similar rework costs at WR-ALC.

There are no technical risks identified with the insertion of this improvement into the repair processes at both ALCs. Only possible risk might be the administrative difficulty of the AFLC Item Management System to quickly respond to procurement revisions.

- . Reduction in ALC bearings repair/salvage/scrap costs.
- . Estimated 50% reduction possible in bearings inventory.
- . Reduced overhead costs.
- . Eliminate the need for an additional Cyl-Sonic cleaning system dedicated to instrument bearings rework. (Cost avoidance of approximately \$150,000 capital expense plus floor space allocation costs.)

10.45.6 Implementation Cost/Schedule

A total review of supplier reliability, procurement specifications and material handling procedures is needed at both ALCs to identify opportunities for quality and productivity improvements. MDHSC will meet with vendors and the item manager to resolve concerns. A two to three month period of time is expected to be sufficient to evaluate both ALCs, the bearings supplier(s) and the OC-ALC item manager.

Bob, I don't know what heading to put this under:


Staffing Estimates (preliminary):

It should be understood that the following estimate overview is preliminary in nature. Further cost analysis details will be available upon submittal of the final Contract Summary Report CDRL B008 (approx. 26 January 1989).

<u>DESCRIPTION</u>	<u>DURATION</u>	<u>EFFORT</u>
MDMSC:		
T.O. MGR.	2-3 Months	50%
SR. I.E.	2-3 Months	100%
I.E.	2-3 Months	100%
M & P Engr.	1-2 Months	50%
Tech Writer	1 Month	50%
T.I. Program Administrative Costs		10%
MDMSC Travel Expenses (Actuals)		

AFLC Estimates:

Air Force Administration Costs
Integration/Implementation Costs
OC-ALC Item Manager Implementation Costs



Following are the Potential Improvements for Focus Studies.

Handwritten:
Appendix 1

TECHNOLOGY INSERTION PROGRAM

ALC: WR-ALC RCC: MANPGA QF: _____

NAME: VANDERVOORD FS: GS-5

HEADING: FILL PROCEDURE FOR 74074A TO REPLACE PRESENT STATION

10.1.1 Description of Current Operation:

Filling. The rate gyroscope is to be filled with damping fluid, part number 113B5890G1 or DS510-100CS \pm 2%, using purging *231E/2761* and filling equipment. Filter through a one-micron filter. Refer to Technical Manual, Operation and Service Instructions, Gyro and Accelerometer Oil Filling Equipment, TO 33D3-9-140-1, for procedures necessary to prepare the purging and filling equipment for filling sensors, and for detailed operation instructions.

a. Uncoil fill tube in bellows end of unit to be filled, being careful not to fracture tube at point where the tube emerges from bellows.

b. Loosen thumbscrew of heater clamp on purging and filling equipment. The heater clamp forms bellows setting for unit to be filled. Insert the sensor, bellows end down, into the heater clamp. Be sure sensor is firmly seated at bottom of clamp because the clamp seat is used to establish final bellows position. Tighten knurled heater clamping screw. Fill tube on the bellows end runs through the hole in seat of the clamp and into oil supply line coupling.

c. Connect knurled vacuum coupling on transparent tubing to oil filler tube at pickoff end of sensor, and tighten coupling.

d. Tighten coupling at bellows end fill tube connection to oil supply line.

e. Energize heater clamp to apply heat to the unit being filled. Operate fill equipment for five hours to evacuate all air, vapor, and other gases from unit. A pressure of 25 microns or less shall be maintained during entire evacuation cycle.

f. Remove heat from the unit by deenergizing heater after five hours of application. Allow unit to cool to room temperature while continuing to evacuate the unit. Allow unit to cool for at least one hour while being evacuated.

g. Pump damping fluid into bellows end of unit at 10 to 15 psig. Maintain vacuum at pickoff end during fill. When fluid can be seen above rate gyro assembly in the fill equipment transparent tube, continue to fill for a least forty-five minutes.

h. Pinch off pickoff end fill tube so that pinched end is no higher than stator pins.

i. Maintain 10 to 15 psig fluid pressure through bellows end fill tube for one hour to ensure that bellows has bottomed against bellows fixture.

j. Pinch off bellows end fill tube about one inch long. Fluid pressure must be at least 8 psig at time of pinch-off.

k. Both fill tube pinch-offs should result in cold-welded joints that are tight enough to prevent leakage of damping fluid. Apply a ball of solder SN-60, to end of each fill tube to completely cover the pinch-off joint.

l. Remove rate gyro assembly from fill equipment.

m. Coil the fill tube at bellows end into bellows. Tube must lie flat against surface of bellows and must not extend into bellows convolutions.

n. Measure depth of bellows into the bellows assembly, using a depth micrometer. Bellows shall be 0.330 to 0.350 inch below outer surface of the bellows assembly. Measure to flat surface of the bellows.

Overall Assessment of Current Operation:

Current Process Problems:

Equipment is a ~~four~~ headed pressure, heat, vacuum system that requires abnormal maintenance time. Seldom are both banks in operation. Present downtime is so great, the work load has been renegotiated to work only a skeleton crew. Personnel has been reassigned to other areas with the RCC.

Shop Organization:

Rationale Leading to Change:

Simplify filling procedures and equipment to reduce time required to perform operation. Greatly improve reliability and availability of station time.

Supporting Data:

Description of New Process:

Mechanically cock the bellows to obtain the .330" to .350" dim. in T.O.

6.44n.

Place unit in bell jar with filters, flap in place.

Pump down to pressure of <25 microns for 5 hours.

Fill filter resv. with DS 570-100CS \pm 2%.

Slide flap to allow silicone oil to enter filter - control rate to fill unit in 1 hour minimum (need to develop)

Over fill to some level in funnel to allow for loss with pressure increase.

Vent to one atmosphere.

Remove bell jar.

Seal as before.

Uncock bellows.

Study required to develop.

1. Cocking method.
2. Length of pump down.
3. Rate of fill.
4. Test approach for comparison.

Productivity Improvements:

Quality Improvements:

Resource Utilization:

Flexibility:

Benefits/Trade-offs:

TECHNOLOGY INSERTION PROGRAM

ALC: WR-ALC RCC: WR/MANPGB & QF: _____
 AGMC/MANPBG
NAME: VANDERVOORD FS: GS-1

HEADING: RCC WR/MANPGB & AGMC/MANPBG ON AUTOMATIC TEST EQUIP-
MENT VS. PRODUCT OPTIMIZATION

Description of Current Operation:

Perform incoming diagnostic test procedure and final acceptance test procedure on the contraves automatic test equipment. Print out unit performance values with product specification limits and accept, reject decisions. Record this same information for storage to the hard disk drives. Store all hard disks. Note: To date no usage of stored data is being planned.

Overall Assessment of Current Operation:

USE AGMC WRITE UP
CHECK WITH BILL BUCHHEIR

Current Process Problems:

Shop Organization:

Rationale Leading to Change:

The data presently stored should be used to develop:

- a) Test stand capabilities
- b) Test stand accuracies
- c) Test stand maintainance schedule
- d) Test equipment error budgets
- e) Test equipment error biasing
- f) Product trending
- g) Product repeatabilities
- h) Necessities of individual tests
- i) Etc.

Supporting Data:

Description of New Process:

Productivity Improvements:

The data can be sorted and compared to give calibration centering data for both test stands and product. This will allow for maximizing product acceptance to the product specification. It will improve product yield in a positive manner. Improved field reliability by assuring middle specification product entering the field. Allow for the development of meanful and timely preventive maintainance schedules. Assure test panel to test panel compatibility is maintained. Product trending can be identified allowing timely corrective actions. Confidence levels can be established that should identify areas that can reduce test times and frequencies. Weak areas of test equipment will be identified, allowing for correction and the inherent decrease in test equipment down time.

Quality Improvements:

Resource Utilization:

Flexibility:

Benefits/Trade-offs:

The data required by the study is available and stored in a usable form at both locations. It is of ample size to satisfy needs for meaningful distribution studies. Navy has developed similar programming through Fletac for A.T.E. capability studies. MDMSC is familiar with the programming through the association with the Harpoon and GMB109B programming.

The unknown required to be established by the study are format of the data stored, number on computer programs required and programming output format for maximizing data usability.

The stability of the study area is stable through 1992 per the forecasted workload report WG324-130.

Cost Savings:

Implementation Cost/Schedule:

The study should develop programs to extract the data from the disk storage, organized the data, sort it for test distribution studies and predict product trending. The study will require the service of the following:

* Site Leader	3 months
* Test Engineer	3 months
* Computer Programmer	?
* Computer Operation Team	?
* Tech Writer	?

* Requires input from compt. people. Time will be required at both sites (WR/AGMC) but AGMC should be used to develop methodology and programming approach.

Impact:

Safety Improvements:

Environmental Hazards/Improvements:

Reliability/Maintainability Characteristics:

Human Factors Design Criteria:

TECHNOLOGY INSERTION PROGRAM

ALC: WR-ALC RCC: WR-MANPGB & QF: _____
 AGMC-MANPGB
NAME: VANDERVOORD FS: GS-2

HEADING: RCC WR-MANPGB & AGMC-MANPGB TO OPTIMIZE UTILIZATION OF
GYRO A.T.E. THRU THE REDUCTION OF TEST EQUIPMENT DOWN TIME

Description of Current Operation:

The preferred method of operation at both locations is to route all incoming and final acceptance testing across the contraves automatic test stations. The desire is to reduce labor input by performing testing on multiple units and test stations with minimum test personnel and to gain maximum product reliability and integrity through reduction of personnel biaing? and test influences. The desire presently cannot be realized because A.T.E. is not usable approximately 50% of the time because of malfunction and/or breakdown or lack of confidence of the test values obtained. Focus study No. _____ will address the confidence problem. This focus study will cover test equipment availability.

Overall Assessment of Current Operation:

USE AGMC WRITE UP
Bill Buchmeier

Current Process Problems:

The low availability of the equipment. The lack of confidence in values obtained causing morale problems and distrust between test and repair areas. Increases in test time because multiple tests cannot be run or validation of failures requires manual testing.

Shop Organization:

Rationale Leading to Change:

The need for the study is the extreme downtime of the A.T.E. and the lack of confidence in the test values obtained. The goal of this study is to reduce the station down enough to realize 90% availability of the A.T.E. for maximum test events of Gyro product. Such improvement will improve measurably the return on investment of vital pram funded equipment and improve confidence level in gyro product returning to service. It will also increase technology consistency between WR-AFLC and AGMC by common solutions to like problems.

Supporting Data:

Description of New Process:

Productivity Improvements:

Quality Improvements:

Resource Utilization:

Both RCC's maintain monthly measurements of auto test equipment availability. AGMC is a formal reporting system referred to as station no. summary all MPBGA, job 4932 A9040A while Warner Robins has an informal report developed by the A.T.E. supervisor for his personal use. Though in different format and completeness both reports show uptime/downtime of test stations.

Flexibility:

Benefits/Trade-offs:

The opportunity to succeed in the stated goals are very possible. The percentage of availability is consistent with availability of like equipment in private industry today. The main risk to not being able to obtain the goal is from lack of detailed knowledge of station design, history of panel failure causes and degree of design margin from panel equipment budgeted error profiles. The A.T.E. presently is the main test equipment for both RCC's and should be capable of testing all present product. Any new inducted systems should be applicable with minor fixturation and fronted computer programming costs.

Cost Savings:

Implementation Cost/Schedule:

(Bill I believe you should write this section with Bashyam's help. You will require services of knowledgeable test engineer, system people and visits to contractors if detailed design and equipment specifications are not available. I would suggest 4/5 months study time with possibly some equipment re-specing and complete maintainance schedules and trouble shooting manuals.)

Impact:

Safety Improvements:

Environmental Hazards/Improvements:

Reliability/Maintainability Characteristics:

Human Factors Design Criteria:

TECHNOLOGY INSERTION PROGRAM

ALC: WR-ALC RCC: WR-MANPG QF: _____

NAME: VANDERVOORD FS: GS-3

HEADING: WR-MANPG TO COMBINE GYRO ROTOR (ASEMBLY) REPAIR TO A
COMMON LINE FLOW

Description of Current Operation:

Gyro units for repair are disassembled and the rotor assemblies removed and set aside for repair and rebuild. The rotor assembly is replaced by a previously repaired rotor assembly and the rebuild of the gyro unit under repair is completed. The removed rotor assemblies are accumulated into batches of ten to twenty assemblies. They are then repaired as a group by some member of the line tech. personnel in the particular gyro repair line. The rebuild action is informally scheduled by line needs and/or tech. availability. The present method is common for all gyro lines and across the three WR-MANPG RCC's.

Overall Assessment of Current Operation:

Current Process Problems:

The present method requires much duplication of equipment. Each product line requires run-in stations, balance machines, leak detectors, filling equipment, ovens, etc. The utilization time of the equipment is generally very light. Rotor assemblies for the gyro assemblies require repair approximately 85% of the time and represent about 2% of the average hours to repair a gyro assembly. The method limits expertise by greatly reducing consecutive repetitive experiences by an operator. It limits common methods for similar assemblies, reduces recognition of common problems. It also increases equipment costs for new technology. The cost of parts inventory is also increased for common parts. The build of rotor assemblies in small quantities and many different technicians and locations encourages deviations from the T.O. methods.

Shop Organization:

Rationale Leading to Change:

The study goals are to substantially reduce labor input for gyro rotor assembly repair, to increase expertise through repetitive operations, reducing attention spans, increasing field reliability through consistent build practices and reduction of reaction time to common problems and/or part deviations. The change will produce improved cross teaming developing rotor repair experts across all gyro product. It will improve production/process flexibility by familiarizing engineering and planning of alternate build methods. The change will also prepare WR-ALC to except and integrate the new laser rotor balancing procedures being developeped by AGMC-MAPBG without having to duplicate the expensive laser balancer on each product line.

Supporting Data:

Description of New Process:

Productivity Improvements:

(Bob, this paragraph will require more field information. The model may help in developing "AS IS" costs and a base for "TO BE" inputs. I suggest parts of the study will be necessary to develop savings. Many may prove intangible and/or required by introduction of laser balance. Some others are quipment and space utilization and in house/field reliability improvement.)

Quality Improvements:

Resource Utilization:

Flexibility:

Benefits/Trade-offs:

One identified risk of combining rotor assembly repair will be schedule compliance. The present method allows each line supervisor to control the availability of repaired rotor assemblies for his product line. However, it does not consider best line load and/or optimize quantity. It does not consider repair quality or training procedures/requirements. It is an "Oh, by the way..." scheduling and has lead to uncontrolled build in many areas.

Cost Savings:

Implementation Cost/Schedule:

(Bob, the effort for F.W. will be identifying area to combine repair, gather all present equipment requirement, produce an area layout and process flow. The study should also suggest a scheduling plan to satisfy F/C line requirements. Some production schedule impact may be experienced during change over.

Impact:

Safety Improvements:

Environmental Hazards/Improvements:

Reliability/Maintainability Characteristics:

Human Factors Design Criteria:

TECHNOLOGY INSERTION PROGRAM

ALC: WR-ALC RCC: _____ QF: _____

NAME: VANDERVOORD FS: GS-4

HEADING: OBSOLESCENCE OF OLD BENCH TEST SETS (74146A WHEEL BLD)

Description of Current Operation:

The older bench test sets and ruler supply panels for the C/N 74146A, J4 direction gyro wheel ass'y, KT426193 are no longer supportable. They are of 1950 design age and contain switches and meters no longer available. The devices have been repaired in varying manners just to continue operation. Numerous starts are sometimes required to become operational. Taps or kicks are also used. The condition is general over the older units. Discussion with panel and engineering planners confirmed observations that the conditions are increasing due to age of both design and hardware of the support test stands. Most product is of the mid-fifties to early sixties design. (C)

Overall Assessment of Current Operation:

Current Process Problems:

Due to age of both design and hardware of the support test stands. Most product is of the mid-fifties to early sixties design. The product that the test equipment services will continue to be repaired and returned to field for many more years but is very questionable if the present support test equipment will remain supportable over such a time frame .

Shop Organization:

Rationale Leading to Change:

The goal of the study is identify, plan and execute corrective actions prior to lengthy production interruptions due to unsupportable test equipment. Such a plan must be completed to assure wartime/readiness and/or surge acceptable posture.

Supporting Data:

Description of New Process:

Productivity Improvements:

The benefits to be obtained ^{are} (is) continued support of the present product line and their aircraft systems.

Quality Improvements:

Resource Utilization:

Flexibility:

Benefits/Trade-offs:

The goal is at risk of picking the wrong start point. The goal and condition of the test equipment would predict a line shut down without an alternate test approach is possible any time. The other risk is that a satisfactory alternate method is impractical at all because of expense and/or longevity of the product line.

Cost Savings:

Implementation Cost/Schedule:

The study should be scoped to attack one RCC at a time - possibly even one product line - identification of problems will overlap lines and/or RCC's because of like product, age and design approach. I would suggest that MANPGC be the first RCC. If that is still too large, attack directional gyro first - 74146A, 74148A and 74126A with the 74149A slaving control also included. I would further suggest the study at either level will require 2 to 3 months to general approach and cost trending.

Impact:

Safety Improvements:

Environmental Hazards/Improvements:

Reliability/Maintainability Characteristics:

Human Factors Design Criteria:

TECHNOLOGY INSERTION PROGRAM

ALC: WR-ALC RCC: MANPGA QF: _____

NAME: VANDERVOORD FS: GS-5

HEADING: FILL PROCEDURE FOR 74074A TO REPLACE PRESENT STATION

Description of Current Operation:

Filling. The rate gyroscope is to be filled with damping fluid, part number 113B5890G1 or DS510-100CS $\pm 2\%$, using purging and filling equipment. Filter through one-micron filter. Refer to Technical Manual, Operation and Service Instructions, Gyro and Accelerometer Oil Filling Equipment, TO 33D3-9-140-1, for procedures necessary to prepare the purging and filling equipment for filling sensors, and for detailed operation instructions.

- a. Uncoil fill tube in bellows end of unit to be filled, being careful not to fracture tube at point where the tube emerges from bellows.
- b. Loosen thumbscrew of heater clamp on purging and filling equipment. The heater clamp forms bellows setting for unit to be filled. Insert the sensor, bellows end down, into the heater clamp. Be sure sensor is firmly seated at bottom of clamp because the clamp seat is used to establish final bellows position. Tighten knurled heater clamping screw. Fill tube on the bellows end runs through the hole in seat of the clamp and into oil supply line coupling.
- c. Connect knurled vacuum coupling on transparent tubing to oil filler tube at pickoff end of sensor, and tighten coupling.
- d. Tighten coupling at bellows end fill tube connection to oil supply line.
- e. Energize heater clamp to apply heat to the unit being filled. Operate fill equipment for five hours to evacuate all air, vapor, and other gases from unit. A pressure of 25 microns or less shall be maintained during entire evacuation cycle.
- f. Remove heat from the unit by deenergizing heater after five hours of application. Allow unit to cool to room temperature while continuing to evacuate the unit. Allow unit to cool for at least one hour while being evacuated.

g. Pump damping fluid into bellows end of unit at 10 to 15 psig. Maintain vacuum at pickoff end during fill. When fluid can be seen above rate gyro assembly in the fill equipment transparent tube, continue to fill for a least forty-five minutes.

h. Pinch off pickoff end fill tube so that pinched end is no higher than stator pins.

i. Maintain 10 to 15 psig fluid pressure through bellows end fill tube for one hour to ensure that bellows has bottomed against bellows fixture.

j. Pinch off bellows end fill tube about one inch long. Flued pressure must be at least 8 psig at time of pinch-off.

k. Both fill tube pinch-offs should result in cold-welded joints that are tight enough to prevent leakage of damping fluid. Apply a ball of solder SN-60, to end of each fill tube to completely cover the pinch-off joint.

l. Remove rate gyro assembly from fill equipment.

m. Coil the fill tube at bellows end into bellows. Tube must lie flat against surface of bellows and must not extend into bellows convolutions.

n. Measure depth of bellows into the bellows assembly, using a depth micrometer. Bellows shall be 0.330 to 0.350 inch below outer surface of the bellows assembly. Measure to flat surface of the bellows.

Overall Assessment of Current Operation:

Current Process Problems:

Equipment is a four headed pressure, heat, vacuum system that requires abnormal maintainance time. Seldom are both banks in operation. Present downtime is so great, the work load has been renegotiated to work only a skeleton crew. Personnel has been reassigned to other areas with the RCC.

Shop Organization:

Rationale Leading to Change:

Simplify filling procedures and equipment to reduce time required to perform operation. Greatly improve reliability and availability of station time.

Supporting Data:

Description of New Process:

Mechanically cock the bellows to obtain the .330" to .350" dim. in T.O.

6.44n.

Place unit in bell jar with filters, flap in place.

Pump down to pressure of <25 microns for 5 hours.

Fill filter resv. with DS 570-100CS \pm 2%.

Slide flap to allow silicone oil to enter filter - control rate to fill unit in 1 hour minimum (need to develop)

Over fill to some level in funnel to allow for loss with pressure increase.

Vent to one atmosphere.

Remove bell jar.

Seal as before.

Uncock bellows.

Study required to develop.

1. Cocking method.
2. Length of pump down.
3. Rate of fill.
4. Test approach for comparison.

Productivity Improvements:

Quality Improvements:

Resource Utilization:

Flexibility:

Benefits/Trade-offs:

Cost Savings:

Implementation Cost/Schedule:

Impact:

Safety Improvements:

Environmental Hazards/Improvements:

Reliability/Maintainability Characteristics:

Human Factors Design Criteria:

TECHNOLOGY INSERTION PROGRAM

ALC: WR-ALC RCC: _____ QF: _____

NAME: VANDERVOORD FS: GS-6

HEADING: AUTOMATE DEPAINT, UNSEAL RESEAL PROCESS

Description of Current Operation:

Gyro units are currently manually unsealed, depainted, resealed and (leak) checked in a semi-enclosed room adjacent to normal displacement gyro repair and test activities.

Overall Assessment of Current Operation:

AGMC
WRITEUP

Current Process Problems:

Environmental, safety, and equipment conditions are substandard as compared to most AGMC facilities. Without an enclosed ventilation system there is a risk of periodic foreign object contamination when processing equipment malfunctions.

Shop Organization:

Rationale Leading to Change:

To substantially reduce labor costs and increase throughput in AGMC GRU repair operations through implementation of modernized equipment, batch processing methods.

Supporting Data:

Description of New Process:

Productivity Improvements:

Eliminate technicians exposure to irritating fumes and high temperature heavy-duty soldering irons with the implementation of semi-automatic processing deseal/reseal equipment and improved facilities.

Quality Improvements:

Resource Utilization:

Flexibility:

Benefits/Trade-offs:

There are technical risks identified with the insertion of this improvement into the repair processes at AGMC. Consider the risks of not being able to successfully automate, obtain adequate seals, etc. Also, some inventory stockpiling may be required in the immediate sealing area prior to production interruption during facility rearrangements.

Cost Savings:

Reduced overhead costs.

Implementation Cost/Schedule:

A thorough review of state-of-the-art commercial aerospace Gyro manufacturers will address the cost effective modernization improvements possible at AGMC sealing, leak checking and finishing operations. A two to three month period of time is expected to be sufficient to evaluate private industry and AGMC. Expand to include others doing automated depaint, unseal, etc.

Impact:

Safety Improvements:

Environmental Hazards/Improvements:

Reliability/Maintainability Characteristics:

Human Factors Design Criteria:

Bob, what heading should this go under?:

Staffing Estimates (preliminary):

It should be understood that the following estimate overview is preliminary in nature. Further cost analysis details will be available upon submittal of the final Contract Summary Report CDRL B008 (approx. 26 January 1989).

	<u>DESCRIPTION</u>	<u>DURATION</u>	<u>EFFORT</u>
MDMSC:	T.O. MGR	2-3 Months	50%
	SR. I.E.	2-3 Months	100%
	I.E.	2-3 Months	100%
	M & P Engr.	1-2 Months	50%
	Tech Writer	1 Month	50%
	T.I. Program Administrative Costs		10%
	MDMSC Travel Expenses (Actuals)		

AFLC Estimates:

Air Force Administration Costs
Integration/Implementation Costs

FS GS-6

TECHNOLOGY INSERTION PROGRAM

ALC: WR-ALC RCC: _____ QF: _____

NAME: VANDERVOORD FS: GS-7

HEADING: IMPROVE BEARINGS PROCUREMENT AND HANDLING PROCEDURES

Description of Current Operation:

The responsible OC-ALC Item Manager specifies the technical description, requests competitive bids from qualified suppliers, selects vendor(s), establishes shipment schedules and procures the required instrument bearings for annual production requirements for all ALCs. All follow up and status of the procurement is also accomplished by OC-ALC Item Manager. AGMC has no authority at all in the procurement process.

Overall Assessment of Current Operation:

Current Process Problems:

Instrument bearing quality related problems are a major cost and schedule impact at AGMC and WR-ALC aircraft gyroscope repair activities. This impact manifests itself in corrosion that is frequently evident visually on packaged bearings when initially received at the MAPGB facility. Currently, significant rework/repair costs occur associated with bearing re-inspection, scrap efforts, and nearly 100% repair/cleaning for salvage.

Shop Organization:

Rationale Leading to Change:

To improve supplier reliability, procurement specifications and material handling procedures to substantially reduce labor costs and increase throughput in AGMC GRU repair operations.

Supporting Data:

Description of New Process:

Productivity Improvements:

An improvement in the quality of instrument bearings available from the ALC material control inventory will eliminate current rework/repair costs associated with re-inspection and nearly 100% cleaning efforts required to produce acceptable bearings. As an example, AGMC currently plans to purchase and implement another Cyl-Sonic cleaning system to meet capacity requirements. This could be eliminated saving a minimum \$150,000 implementation expense. Also, the technology could be transferred across the Command avoiding similar rework costs at WR-ALC.

Quality Improvements:

Resource Utilization:

Flexibility:

Benefits/Trade-offs:

There are no technical risks identified with the insertion of this improvement into the repair processes at both ALCs. Only possible risk might be the administrative difficulty of the AFLC Item Management System to quickly respond to procurement revisions.

Cost Savings:

- align* {
- . Reduction in ALC bearings repair/salvage/scrap costs.
 - . Estimated 50% reduction possible in bearings inventory.
 - . Reduced overhead costs.
 - . Eliminate the need for an additional Cyl-Sonic cleaning system dedicated to instrument bearings rework. (Cost avoidance of approximately \$150,000 capital expense plus floor space allocation costs.)

Implementation Cost/Schedule:

A total review of supplier reliability, procurement specifications and material handling procedures is needed at both ALCs to identify opportunities for quality and productivity improvements. MDMSC will meet with vendors and the item manager to resolve concerns. A two to three month period of time is expected to be sufficient to evaluate both ALCs, the bearings supplier(s) and the OC-ALC item manager.

Impact:

Safety Improvements:

Environmental Hazards/Improvements:

Reliability/Maintainability Characteristics:

Human Factors Design Criteria:

Bob, I don't know what heading to put this under:

Staffing Estimates (preliminary):

It should be understood that the following estimate overview is preliminary in nature. Further cost analysis details will be available upon submittal of the final Contract Summary Report CDRL B008 (approx. 26 January 1989).

<u>DESCRIPTION</u>	<u>DURATION</u>	<u>EFFORT</u>
MDMSC:		
T.O. MGR.	2-3 Months	50%
SR. I.E.	2-3 Months	100%
I.E.	2-3 Months	100%
M & P Engr.	1-2 Months	50%
Tech Writer	1 Month	50%
T.I. Program Administrative Costs		10%
MDMSC Travel Expenses (Actuals)		

AFLC Estimates:

Air Force Administration Costs
Integration/Implementation Costs
OC-ALC Item Manager Implementation Costs

FS: GS-7

~~GS-7~~

TECHNOLOGY INSERTION PROGRAM

ALC: WR-ALC RCC: MANPBG QF: _____
NAME: VANDERVOORD FS: GS-8
HEADING: LASER WHEEL BALANCING (DELAY/MONITOR AGMC)

Description of Current Operation:

A new pram funded dynamic balancing laser system for gyro rotors is scheduled to be installed in the AGMC Gyro Reference Unit Wheel Repair Facility during the first quarter of CY 1989. WR-ALC is not as yet ready to specify or define a specific system.

Overall Assessment of Current Operation:

DROP

Current Process Problems:

A significant material and labor cost is incurred by the frequent rework scrap generated by improper manual drilling of the rotor wheel during the difficult precision balancing process.

Shop Organization:

Rationale Leading to Change:

Once the AGMC Laser Balancing System is operational and an attractive return on investment (ROI) can be verified utilizing Taguchi investigation methods, MDMSC will act as coordinator to accelerate the implementation of a similar Rotor Dynamic Balancing Laser System at WR-ALC to provide technology consistency across AFLC.

Supporting Data:

Description of New Process:

Productivity Improvements:

Accelerate the implementation of AGMC's Laser Balancer and verify attained cost savings and ROI. MDMDSC can perform as technology transfer manager to insert this same process improvement at WR-ALC in the shortest possible amount of time.

Quality Improvements:

Resource Utilization:

Flexibility:

Benefits/Trade-offs:

Once AGMC's Laser Balancing System is operational and accepted by all users there are no technical risks identified with the insertion of this improvement into the repair processes at WR-ALC.

Cost Savings:

Implementation Cost/Schedule:

A relatively quick study is needed at both ALC's to identify opportunities for quality and productivity improvements. A one to two month period of time is expected to be sufficient to evaluate both ALC's involved.

Impact:

Safety Improvements:

Environmental Hazards/Improvements:

Reliability/Maintainability Characteristics:

Human Factors Design Criteria:

Bob, what heading?

Staffing Estimates (preliminary):

It should be understood that the following estimate overview is preliminary in nature. Further cost analysis details will be available upon submittal of the final Contract Summary Report CDRL B008 (approx. 26 January 1989).

	<u>DESCRIPTION</u>	<u>DURATION</u>	<u>EFFORT</u>
MDMSC:	T.O. MGR	1-2 Months	50%
	SR. I.E.	1-2 Months	100%
	I.E.	1-2 Months	100%
	M & P Engr	1 Month	50%
	Tech Writer	1 Month	50%
	T.I. Preogram Administrative Costs		10%
	MDMSC Travel Expenses (Actuals)		

AFLC Estimates:

Air Force Administration Costs
Integration/Implementation Costs
WR-ALC Floorspace Allocation Costs

FS: GS-8

TECHNOLOGY INSERTION PROGRAM

ALC: WR-ALC RCC: _____ QF: _____

NAME: VANDERVOORD FS: GS-9

HEADING: COMPARE A.T.E. TO MANUAL (DELAY FOR RESULTS FROM 1)

Description of Current Operation:

Diagnostic tests and/or final acceptance tests are often performed on both A.T.E. and manual test sets. The duplication of tests is because of lack of confidence in one or both pieces of equipment. The problem is evident at both AGMC-MANPBG and WR-ALC, MANPG. The difference between the bases is AGMC places more faith in the manual stations and accepts product in dispute from manual station values while WR-ALC, MANPG in general uses the A.T.E. as the final acceptance measure.

Overall Assessment of Current Operation:

Current Process Problems:

The basic problem is evident from opposite approaches taken by the separate bases. The acceptability of values from either set of equipment is by opinion or rationale of the acceptor and not from an engineering researched position. Opportunity to compromise product is very great in either method. Both locations perform redundant testing, increasing labor input unnecessarily.

Shop Organization:

Rationale Leading to Change:

Determine quantified statistics through Taguchi* analysis of compatibility and/or differences between the GRU A.T.E. and manual test stations to allow full utilization of the RCC equipment resources. Use distributions and values obtained through Focus Study 6 A.T.E. vs. Product for A.T. E. characteristics.

* - I do not believe that "Taguchi" will do anything toward this end! This should be results of analyses of test data comparisons. A Taguchi array may require number of comparisons necessary and impact weight of some conditions.

Supporting Data:

Description of New Process:

Productivity Improvements:

In addition to the obvious elimination of duplicate testing, reliability of the product and the increase in field time should result in further cost savings. Both will be obtained by shipping more product meet specification allowing maximum field time before failure. There are also positive intangible benefits to be gained in employee morale and product confidence.

Quality Improvements:

Resource Utilization:

(Obvious savings from duplicate test - occurrence factor will vary with product line - data is in model also should have occurrence factor from WCD history.)

Flexibility:

Benefits/Trade-offs:

One risk that must be considered is that an indepth study will result in neither test methods meet the product specification. Another consideration is that product randomness is too great to produce meaningful tests.

Cost Savings:

Implementation Cost/Schedule:

A total review is needed at both ALC's to identify opportunities for quality and productivity improvements. A two to three month period of time is expected to be sufficient to evaluate both ALC's involved.

(Impact:

Safety Improvements:

Environmental Hazards/Improvements:

Reliability/Maintainability Characteristics:

Human Factors Design Criteria:

Bob, what heading?

Staffing Estimates (preliminary):

It should be understood that the following estimate overview is preliminary in nature. Further cost analysis details will be available upon submittal of the final Contract Summary Report CDRL B006 (approx. 26 January 1989).


<u>MDMSC:</u>	<u>DESCRIPTION</u>	<u>DURATION</u>	<u>EFFORT</u>
	T.O. MGR	2-3 Months	50%
	SR. I.E.	2-3 Months	100%
	I.E.	2-3 Months	100%
	M & P Engr	1-2 Months	50%
	Tech Writer	1 Month	50%
	T.I. Program Administrative Costs		10%
	MDMSC Travel Expenses (Actuals)		

AFLC Estimates:


Air Force Administration Costs
Integration/Implementation Costs

FS: GS-9


PROCESS FLOWCHART PCN 74146A




PROCESS FLOWCHART PCN 06121A




PROCESS FLOWCHART PCN 74063A



PROCESS FLOWCHART PCN 74061A



PROCESS FLOWCHART PCN 74148A



PROCESS FLOWCHART PCN 74149A

