


6788 1

Delivery Order No. 0017
Contract Number
DACA31-93-D-0064



**U.S. Army
Environmental
Center**

U.S. ARMY ENVIRONMENTAL CENTER



19951115 175

**WOODBIDGE RESEARCH FACILITY
1995 ASBESTOS SURVEY**

WOODBIDGE, VIRGINIA

Unlimited Distribution
Approved for Public Release

**APPENDIX TO THE
FINAL REPORT**

DTIC QUALITY INSPECTED 5

October 6, 1995

This document is printed on recycled paper

APPENDIX B (addendum)

Copies of the chain of custody forms for all the samples

The laboratory results are also summarized in the body of the report and reflected in the USAEC Asbestos Checklist summary sheets in Appendix C.

Accession For	
NTIS CRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification _____	
By _____	
Distribution / _____	
Availability Codes	
Dist	Avail and/or Special
A-1	

Oneil M. Banks, Inc.

Industrial Hygiene/Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-5-95

JOB SITE WOODBRIIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
<u>A001</u>	<u>Bldg. 102 Single painted Drywall compound</u>	<u>analyze mastic only</u>
<u>A002</u>	<u>Bldg. 102 tan countertop + mastic</u>	
<u>BA003</u>	<u>Bldg. 101 12x12 floor tile</u>	
<u>BA004</u>	<u>Bldg. 101 12x12 floor tile Mastic</u>	
<u>B005</u>	<u>Bldg 101 room 101 12x12 floor tile</u>	
<u>B006</u>	<u>Bldg 101 room 101 12x12 floor tile mastic</u>	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-5-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-5-95

JOB SITE WOODBIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
------	--------------------------------	---

	B007 Bldg 101/rm 102 Drywall + joint compound	
	B008 Bldg 101/rm 103 2'x4' ceiling tile	
	B009 Bldg 101 Lobby 2'x4' ceiling tile	
	B010 Bldg 101 Lobby 5" cove moulding	
	B011 Bldg 101 Lobby black black cove moulding mastic	
	B012 Bldg 101/rm 105 gasketing Material Material	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-5-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-5-95

JOB SITE WOODBIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
------	--------------------------------	-------------------------------------

<u>C013</u>	<u>Bldg. 211/rm. 315 2'x4' ceiling tile</u>	
<u>C014</u>	<u>hallway 3rd floor 2'x4' ceiling tile</u>	
<u>C015</u>	<u>Bldg. 211/rm. 307 Dry wall</u>	
<u>C016</u>	<u>" " Duct Binding Material</u>	
<u>C017</u>	<u>" " rm. 310 +rowelled on window material</u>	
<u>C018</u>	<u>" " rm. 307 4" Brown Cove molding</u>	
<u>C019</u>	<u>" " " Mastic</u>	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-5-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/ Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-5-95

JOB SITE WOODBIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEEDED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
C020	Bldg 211 3rd fl. Hall 2'x4' ceiling tile ^{BAB delete}	
C021	Bldg 211 3rd fl. Hall 2'x4' ceiling tile	
C022	Bldg 211 rm. 310 12x12 floor tile	
C023	" " mastic	
C024	Bldg 211 rm 113 12x12 floor tile	
C025	Bldg 211 rm 112 ceiling Drywall	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-5-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-5-95

JOB SITE WOODBRIIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEEDED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
------	--------------------------------	-------------------------------------

<u>C026</u>	<u>Bldg 211 rm 113 Fire door insulation</u>	
<u>C027</u>	<u>Bldg 211 rm. 103 Brown Mastic</u>	
<u>C028</u>	<u>" / rm 103 3'x3' floor-tiles</u>	
<u>C029</u>	<u>" / mechanical rm. Duct gasketing material</u>	
<u>C030</u>	<u>" " trowelled ceiling material</u>	
<u>C031</u>	<u>" " boiler jacket insulation</u>	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-5-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/ Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-5-95

JOB SITE WOODBRIAGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEEDED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
------	--------------------------------	-------------------------------------

<u>D032</u>	<u>Bldg 203 Main entrance 12x12 floor tile</u>	
<u>D033</u>	<u>" " " " " mastic</u>	
<u>D034</u>	<u>" " " " " Stair Case tread</u>	
<u>D035</u>	<u>" " " " " mastic</u>	
<u>D036</u>	<u>Bldg 203 / rm 117 Plaster wall material</u>	
<u>D037</u>	<u>" " " " " Drywall compound over plaster</u>	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-5-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-5-95

JOB SITE WOODBRIIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
<u>D038</u>	<u>Bldg 202 room 124 Acoustical tile 12"x16"</u>	
<u>D039</u>	<u>" " " " " "</u>	<u>Mastic</u>
<u>D041</u>	<u>" " " " 2'x2' floor tile</u>	
<u>D042</u>	<u>Bldg 201 Main Entrance Cove Molding</u>	
<u>D043</u>	<u>" " " " " "</u>	<u>Cove molding mastic (outer)</u>
<u>D044</u>	<u>" " " " " "</u>	<u>(inner)</u>

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-5-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE _____

DATE _____

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST) _____

DATE _____

Oneil M. Banks, Inc.

Industrial Hygiene/ Toxicology
(301) 879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-5-95

JOB SITE WOODBIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
------	--------------------------------	-------------------------------------

	D045 Bldg 203 room 108	Plaster wall material
	D046 " "	Drywall compound over plaster
	D047 " "	Drywall
	D048 Bldg 203 room 102	Tan Duct Binding Material
	D049 " "	White " "
	D050 " "	Brown Mastic on ceiling

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-5-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/ Toxicology
(301) 879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-5-95

JOB SITE WOODBRIIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
_____	<u>D051 Bldg 203 rm 102 2x4 Ceiling tile</u>	_____
_____	<u>D052 " " rm 125 4" Black Cove Molding</u>	_____
_____	<u>D053 " " " Mastic</u>	_____
_____	<u>D054 Bldg 203 rm 124 4" Brown Cove Molding</u>	_____
_____	<u>D055 " " " Mastic</u>	_____
_____	<u>D056 Bldg 203 rm 125 Dry wall</u>	_____

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY

 7-5-95
SIGNATURE (IH TECH) DATE

BRYANT BULLOCK _____
DELIVERED TO LAB BY & DATE RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST) DATE

Oneil M. Banks, Inc.

Industrial Hygiene/ Toxicology
(301) 879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-5-95

JOB SITE WOODBRIIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
------	--------------------------------	-------------------------------------

<input checked="" type="checkbox"/>	D057 Bldg 20/Rm 225 Ceiling Plaster	
	D058 " " Black Wool Duct binding	
	D059 " " Rm 224 6" Black core Moulding	
	D060 " " " Brown mastic	
	D062 " " Rm 219 Black Cork Mastic	
	D063 " " 2nd floor Hall 2x4' ceiling tile	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY

Bryant Bullock
SIGNATURE (IH TECH)

7-5-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

analyze separate lanes separately

Oneil M. Banks, Inc.

Industrial Hygiene/Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-5-95

JOB SITE WOODBIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
	<u>DOG4 Bldg. 205 2nd floor Hall 2x4 ceiling tile</u>	
	<u>DOG5 " " 2x4 ceiling tile</u>	
	<u>DOG6 " / rm 210 Drywall</u>	
	<u>DOG7 " / rm Drywall</u>	
	<u>DOG8 " / rm 210 2x4 ceiling tile</u>	
	<u>DOG9 " / rm 202 press board</u>	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-5-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE _____

DATE _____

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST) _____

DATE _____

Oneil M. Banks, Inc.

Industrial Hygiene/Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-6-95

JOB SITE WOODBRIIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEEDED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
------	--------------------------------	-------------------------------------

<u>E070</u>	<u>Ridge 20' rm N¹⁰⁰ 2x4 Ceiling Tile</u>	
<u>E071</u>	<u>" " 2x4 Ceiling Tile</u>	
<u>E072</u>	<u>" " Drywall (unpainted)</u>	
<u>E073</u>	<u>" " Debris in Steamline chase</u>	
<u>E074</u>	<u>" " Main Entrance 12x12 floor tile</u>	
<u>E075</u>	<u>" " 2x4 Ceiling tile</u>	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-6-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/ Toxicology
(301) 879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-6-95

JOB SITE WOODBRIIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSTION OF MATERIAL
<u>E 076</u>	<u>Bldg 201 Main Entrance Brown Mastic</u>	
<u>E 077</u>	<u>rm N101A primary ceiling material</u>	
<u>E 078</u>	<u>rm N101 plaster wall material</u>	
<u>E 079</u>	<u>rm N101 Drywall compound over plaster</u>	
<u>E 0801</u>	<u>rm N101A Thermal system pipe insulation sealant</u>	
<u>E 082</u>	<u>rm N107A 12x12 Acoustical tiles</u>	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-6-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/ Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-6-95

JOB SITE WOODBIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
	E083 Bldg 201 rm N107A Brown Mastic	
	E084 " " 2x4 ceiling tile	
	E085 " " rm N107B 2x4 ceiling tile	
	E086 " " 2x4 ceiling tile	
	E087 " " outside N107A 4" Black Cove Molding	
	E088 " " Brown Mastic	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-6-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE _____

DATE _____

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST) _____

DATE _____

Oneil M. Banks, Inc.

Industrial Hygiene/Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-6-95

JOB SITE WOODBRIIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
<u>E089</u>	<u>Bldg. 201 rm N109 6" Black Cove Molding</u>	
<u>E090</u>	<u>" " " Brown Mastic</u>	
<u>E091</u>	<u>1rm N111 Plaster wall</u>	
<u>E092</u>	<u>" " " Debris in electrical chase</u>	
<u>E093</u>	<u>1rm N116 Drywall</u>	
<u>E094</u>	<u>1rm N118 Brown Mastic</u>	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-6-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/Toxicology
(301) 879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-6-95

JOB SITE WOODBRIIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEEDED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
	E095 Bldg. 201 rm N118 12x12 Floor tile	
	E096 " Hallway N. wing Drywall	
	E097 " rm. E157 4" Brown Cove Molding	
	E098 " " " " Mastic	
	E099 " " Drywall	
	E101 " rm E109 12x12 Acoustical Tile	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-6-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-6-95

JOB SITE WOODBRIIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
------	--------------------------------	-------------------------------------

E102	Bldg. 201 rm E1009 Brown Mastic	
E103	" " 12x12 Acoustical Tile	
E104	" " 12x12 Floor Tile	
E105	" rm E106 wall Plaster	
E106	" rm E108 particle Board Mastic	
E107	" rm E106 Duct Binding Material	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY

Bryant Bullock
SIGNATURE (IH TECH)

7-6-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-6-95

JOB SITE WOODBIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
<u>E108</u>	<u>Bldg. 201 Rm E 106 Dry wall</u>	
<u>E109</u>	<u>" " Plaster wall</u>	
<u>E110</u>	<u>" S. wing Hall Dry wall</u>	
<u>E111</u>	<u>" West wing Hall 2x4 Ceiling Tile</u>	
<u>E112</u>	<u>" Rm W 148 Dry wall</u>	
<u>E113</u>	<u>" Rm W 151 2x4 Ceiling Tile</u>	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-6-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/ Toxicology
(301) 879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-6-95

JOB SITE WOODBRIE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEEDED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
<u>E114</u>	<u>Bldg. 201 / rm W140 4" Brown Cove Molding</u>	
<u>E115</u>	<u>" / main Entrance 2x4 Ceiling Tile</u>	
<u>F116</u>	<u>Bldg. 202 / rm 121 4" Black Cove Molding</u>	
<u>F117</u>	<u>" " " "</u>	<u>Mastic</u>
<u>F118</u>	<u>" / above rm 118 Gray fibrous Material</u>	
<u>F119</u>	<u>" / rm 115 Dry wall</u>	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY

Bryant Bullock
SIGNATURE (IH TECH)

7-6-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/ Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-6-95

JOB SITE WOODBRIIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
	F121 Bldg-2nd Arm. 103C 12x12 Acoustical Tile	
	F122 " " 1st Arm 101 ceiling Drywall	
	F123 " " " 12x12 Floor Tile	
	F124 " " Above 1st Arm 103C Drywall like ceiling board.	
	F125 " " 1st Arm 114 4" Black Cove Molding	
	F126 " " " " Mastic	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-6-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/ Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-6-95

JOB SITE WOODBRIAGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
	<u>F127 Bldg. 202 room 120 Drywall</u>	
	<u>G#128 Bldg 210/NA 12x12 Floor Tile</u>	
	<u>G129 " " " Mastic</u>	
	<u>F30 " " " Ceiling board BAB</u>	
	<u>H130 Bldg 204 concrete floor</u>	
	<u>H131 " " ceiling</u>	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-6-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-6-95

JOB SITE WOODBIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
------	--------------------------------	-------------------------------------

I 132	Bldg 306 Bathroom 1st fl. 12x12 floor tile	
I 133	" " " " "	Mastic
I 134	" " between 1st & 2nd floor Stair Tread	
I 135	" " " " "	Mastic
I 136	Maintenance Bay 4" Brown Cove Molding	
I 137	1st floor Drywall BAB Maintenance Bay Brown Mastic	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY


SIGNATURE (IH TECH)

7-6-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE

DATE

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST)

DATE

Oneil M. Banks, Inc.

Industrial Hygiene/Toxicology
(301)879-4676

336 South Main Street
Bel Air, Maryland 21014

ASBESTOS BULK DATA SAMPLING SHEET

NAME OF COMPANY HORNE ENGINEERING SERVICES, INC. DATE 7-6-95

JOB SITE WOODBIDGE RESEARCH FACILITY

REPORT RESULTS TO HORNE ENGINEERING SERVICES, INC.

PHONE # (703) 379-5600 RESULTS NEED BY ASAP

LAB#	SAMPLE# & LOCATION/DESCRIPTION	ESTIMATED % COMPOSITION OF MATERIAL
------	--------------------------------	-------------------------------------

	<u>I138 Bldg 300 2nd floor Dry wall</u>	
	<u>T139 " Stairway Dry wall</u>	
	<u>X141 Culvert Old Chimney</u>	
	<u>X142 Exterior of 203 (southside) Thermal System Insulation</u>	

I CERTIFY THAT THE ABOVE SAMPLES WERE TAKEN IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS AND APPROVED METHODS.

BRYANT BULLOCK/ HORNE ENGINEERING SERVICES, INC.
PRINTED NAME & COMPANY

Bryant Bullock
SIGNATURE (IH TECH)

7-6-95
DATE

BRYANT BULLOCK
DELIVERED TO LAB BY & DATE

RECEIVED AT THE LAB BY & DATE

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED, FOR TYPE AND AMOUNT OF ASBESTOS BY POLARIZED LIGHT OPTICAL MICROSCOPY AND DISPERSION STAINING, USING THE "INTERIM METHOD FOR THE DETERMINATION OF ASBESTOS IN BULK INSULATION SAMPLES" FOUND IN APPENDIX A TO SUBPART F IN 40 CFR 763, IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS, REGULATIONS, AND APPROVED METHODS.

ANALYST SIGNATURE _____

DATE _____

SIGNATURE (CERTIFIED INDUSTRIAL HYGIENIST) _____

DATE _____

APPENDIX C (addendum)

These 144 checklists (142 samples and two additional checklists for the 9"x9" floor tile assumed to contain asbestos) show how each material sampled was assessed by category. These checklists are shortened versions of the USAEC Asbestos Checklist eliminating the explanatory information to compress the six page original form to a single piece of paper. AEC approved the reduced version to make the checklist more convenient for field use and to save paper.

A Summary table of these checklists and copy of the original full version of the checklist are in the Final Report.

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 102/NA

Inspector's Name/Date: Byrd + [unclear] 1/15/95

Sample No.: A001

Sample Description: Painted Drywall and Joint Compound

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition) Notes:
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Percent Asbestos:

- (0) < 1% (1) 1 to 30% (2) 31 to 50% (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Notes:

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Notes:

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1%
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Notes:

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA
Inspector's Name/Date: Byron + Mike 7/15/95
Sample Description: TAN MASTIC

Bldg/Rm. No.: 102/NA
Sample No.: A002

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index : F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 101/102

Inspector's Name/Date: BAE MGB 7/5/95

Sample No.: B003

Sample Description: 12" x 12" Floor Tile (Gray with Gray & White mottling)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 101/102

Inspector's Name/Date: BAB MGB 7/5/95

Sample No.: B009

Sample Description: 12"x12" Floor Tile Black Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index = F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA Bldg/Rm. No.: 101/NA
Inspector's Name/Date: BAB, MGB 7/5/95 Sample No.: 3005
Sample Description: 12"X12" Floor Tile (Gray with white; Gray mottling)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
(1) Minimal
(2) Low
(3) Moderate
(5) High

- (0) None
(1) Minor, < 10%
(2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
(1) > or = to 5 ft.
(2) Between 1 and 5 ft.
(3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
(3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
(1) Miscellaneous ACM
(1) ACM insulation (not accessible)
(2) Non-friable ACM (poor condition)
(2) ACM insulation (accessible)
(3) Friable ACM with airborne potential
(4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
(1) 1 to 30%
(2) 31 to 50%
(3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 101/NA

Inspector's Name/Date: BAB, MEB 7/5/95

Sample No.: B006

Sample Description: Black Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 101/103

Inspector's Name/Date: BATS, MGB 7/5/95

Sample No.: B008

Sample Description: 2'x4' Ceiling Tile (Unpainted, Marble Pattern with Pinholes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1%
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Notes:

Assessment Index: E

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 101/NA

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: B009

Sample Description: 2'x4' Ceiling Tile (Unpainted, marble pattern with Pinholes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: E

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 101/NA

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: B010

Sample Description: 6" Black Cove Molding

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 101/WA

Inspector's Name/Date: BAB, MEB 7/5/95

Sample No.: 3011

Sample Description: Black Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- ~~XXXXX~~ (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 101/105

Inspector's Name/Date: BAB, MGB 7/15/95

Sample No.: B012

Sample Description: Duct Gasketing Material

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/315

Inspector's Name/Date: BAB, MEB 7/5/95

Sample No.: C013

Sample Description: 2x4' Ceiling Tile (worm pattern with large round holes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/Hallway

Inspector's Name/Date: BAB, MLB 7/5/95

Sample No.: C014

Sample Description: 2'x4' Ceiling Tile (Worm Pattern, Small Round Holes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/307

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: C015

Sample Description: Painted Drywall and Joint Compound

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/307

Inspector's Name/Date: BAB, MEB 7/5/95

Sample No.: C016

Sample Description: White Duct Glue

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/310

Inspector's Name/Date: SAB, MEB 7/5/95

Sample No.: C017

Sample Description: Troweled Window Material

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/307

Inspector's Name/Date: BAB, MEB 7/5/95

Sample No.: C018

Sample Description: 4" Brown Cove Molding

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/307

Inspector's Name/Date: BAB, MBR 7/5/95

Sample No.: C019

Sample Description: ~~# Brown~~ Black Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211 / ^{Upper Floor} Hall

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: C020

Sample Description: Duplicate ~~C020~~ C021

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- _____ (0) None
- _____ (1) Minimal
- _____ (2) Low
- _____ (3) Moderate
- _____ (5) High

- _____ (0) None
- _____ (1) Minor, < 10%
- _____ (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- _____ (0) No Repair
- _____ (1) > or = to 5 ft.
- _____ (2) Between 1 and 5 ft.
- _____ (3) < 1 ft. or ceiling tiles

Notes:

: Pipe, boiler, or duct insulation which could be damaged by activity.

- _____ (0) No
- _____ (3) Yes

Notes:

Type of ACM:

- _____ (0) <1% or non-friable (good condition)
- _____ (1) Miscellaneous ACM
- _____ (1) ACM insulation (not accessible)
- _____ (2) Non-friable ACM (poor condition)
- _____ (2) ACM insulation (accessible)
- _____ (3) Friable ACM with airborne potential
- _____ (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- _____ (0) < 1%
- _____ (1) 1 to 30%
- _____ (2) 31 to 50%
- _____ (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- _____ (0) Non-friable
- _____ (1) Low
- _____ (2) Moderate
- _____ (3) High

Accessibility:

- _____ (0) Low
- _____ (1) Moderate
- _____ (4) High

Notes:

Activity/Use:

- _____ (0) None
- _____ (1) Low
- _____ (2) Moderate
- _____ (3) High

Air Stream/Plenum:

- _____ (0) None
- _____ (1) Present/No ACM
- _____ (2) Present/ACMs occasional
- _____ (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- _____ (0) < 10 cubic or linear ft.
- _____ (1) 10 to 100 cubic or linear ft.
- _____ (2) 100 to 1000 cubic or linear ft.
- _____ (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- _____ (1) < 9 or corridors
- _____ (2) 10 to 200
- _____ (3) 201 to 500
- _____ (4) 501 to 1000
- _____ (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- _____ (0) No ACM or <1% Notes:
- _____ (1) Non-friable in good condition
- _____ (2) Non-friable in poor condition
- _____ (3) Friable in good condition
- _____ (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211 / Upper Floor Hallway

Inspector's Name/Date: BAB, MLB 7/5/95

Sample No.: C021

Sample Description: 2'x4' Ceiling Tile (Mottled Pattern with Small Pin Holes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/310

Inspector's Name/Date: BAB MEB 7/5/95

Sample No.: C022

Sample Description: 12"x12" Floor Tile (Light Tan with Brown Mottling)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/310

Inspector's Name/Date: BAB, MEB 7/5/95

Sample No.: C023

Sample Description: Brown Mastix

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/113

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: C024

Sample Description: 12" x 12" Floor Tile (Beige with Brown & white mottling)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/112

Inspector's Name/Date: BAB, M6B 7/5/95

Sample No.: C025

Sample Description: Drywall and Joint Compound

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/113

Inspector's Name/Date: BAB, M.B. 7/5/95

Sample No.: C026

Sample Description: Fire Door Insulation

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/103

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: C027

Sample Description: Brown Mastix

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/103

Inspector's Name/Date: BAB, M.B. 7/5/95

Sample No.: C028

Sample Description: 3x3 Floor Tile

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/Mech. Room

Inspector's Name/Date: BAB, M6B 7/5/95

Sample No.: C029

Sample Description: Duct Gasketing Material

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211 / mech. room

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: C030

Sample Description: Troweled on Surface Material

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or troweled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or troweled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 211/Mech. Room

Inspector's Name/Date: BAB, M&B 7/5/95

Sample No.: C031

Sample Description: Boiler Jacket Insulation

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203 / Main Entrance

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: D032

Sample Description: 12"x12" Floor Tile (Tan with Orange, Brown, and white mottling)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: ~~E~~ F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/Main Entrance

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: D033

Sample Description: Black Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203 / Stairs Main Entrance

Inspector's Name/Date: BAB, NGB 7/5/95

Sample No.: D034

Sample Description: Staircase Tread

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203 / Main Entrance

Inspector's Name/Date: 7/5/95 BAB, MGB

Sample No.: D035

Sample Description: ~~Asbestos~~ Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/117

Inspector's Name/Date: ~~MAB~~ ~~7/15/95~~

Sample No.: 2036

Sample Description: Tan Plaster Base Material

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/117

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: D037

Sample Description: White Drywall Material Over Tan Plaster

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/124

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: D038

Sample Description: Brown Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/124

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: D039

Sample Description: 12"x16" Acoustical Tile (3/8" Dot Pattern)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/124

Inspector's Name/Date: BAB/MEB 7/5/95

Sample No.: D040

Sample Description: Duplicate of D041

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- _____ (0) None
- _____ (1) Minimal
- _____ (2) Low
- _____ (3) Moderate
- _____ (5) High

- _____ (0) None
- _____ (1) Minor, < 10%
- _____ (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- _____ (0) No Repair
- _____ (1) > or = to 5 ft.
- _____ (2) Between 1 and 5 ft.
- _____ (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- _____ (0) No
- _____ (3) Yes

Notes:

Type of ACM:

- _____ (0) <1% or non-friable (good condition)
- _____ (1) Miscellaneous ACM
- _____ (1) ACM insulation (not accessible)
- _____ (2) Non-friable ACM (poor condition)
- _____ (2) ACM insulation (accessible)
- _____ (3) Friable ACM with airborne potential
- _____ (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- _____ (0) < 1%
- _____ (1) 1 to 30%
- _____ (2) 31 to 50%
- _____ (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- _____ (0) Non-friable
- _____ (1) Low
- _____ (2) Moderate
- _____ (3) High

Accessibility:

- _____ (0) Low
- _____ (1) Moderate
- _____ (4) High

Notes:

Activity/Use:

- _____ (0) None
- _____ (1) Low
- _____ (2) Moderate
- _____ (3) High

Air Stream/Plenum:

- _____ (0) None
- _____ (1) Present/No ACM
- _____ (2) Present/ACMs occasional
- _____ (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- _____ (0) < 10 cubic or linear ft.
- _____ (1) 10 to 100 cubic or linear ft.
- _____ (2) 100 to 1000 cubic or linear ft.
- _____ (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- _____ (1) < 9 or corridors
- _____ (2) 10 to 200
- _____ (3) 201 to 500
- _____ (4) 501 to 1000
- _____ (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- _____ (0) No ACM or <1% Notes:
- _____ (1) Non-friable in good condition
- _____ (2) Non-friable in poor condition
- _____ (3) Friable in good condition
- _____ (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/124

Inspector's Name/Date: BAB, MEB 7/5/95

Sample No.: D041

Sample Description: Floor Tile 2'x2'

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/main Entrance

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: D042

Sample Description: 6" Black Cove Molding

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203 / main Entrance

Inspector's Name/Date: BAB, MEB 7/5/95

Sample No.: D043

Sample Description: Tan Cove molding (outer layer) mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%



Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/108

Inspector's Name/Date: BAB, MEB 7/5/95

Sample No.: D045

Sample Description: Ten Plaster Base Material

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/108

Inspector's Name/Date: BAB, MBB 7/5/95

Sample No.: D046

Sample Description: Drywall material (over plaster)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

~~DO46~~ Assessment Index: F
~~251~~

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/108

Inspector's Name/Date: MGB, BAB 7/5/95

Sample No.: 2047

Sample Description: Drywall and Joint Compound

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/162

Inspector's Name/Date: BAB, MEB 7/5/95

Sample No.: 2098

Sample Description: Tan Duct GLE

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/102

Inspector's Name/Date: PAB, MGR 7/5/95

Sample No.: D049

Sample Description: White Duct Glue

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1%
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Notes:

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/102

Inspector's Name/Date: BAB, MEB 7/5/95

Sample No.: 2050

Sample Description: Brown Mastix

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/102

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: D051

Sample Description: 2'x4' Ceiling (Mottled Pattern with small pinholes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/125

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: D052

Sample Description: 4" Black Cove Molding

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/125

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: D053

Sample Description: Brown Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/124

Inspector's Name/Date: MEB, BAB 7/5/95

Sample No.: D054

Sample Description: 4" Brown Cove Molding

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/124

Inspector's Name/Date: MEB, BAB 7/5/95

Sample No.: D055

Sample Description: Brown Mastie

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition) Notes:
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/225

Inspector's Name/Date: BAB, MCB 7/5/95

Sample No.: D056

Sample Description: Drywall and Joint Compound

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/225

Inspector's Name/Date: BAB, MGR 7/5/95

Sample No.: D057

Sample Description: Plaster

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/225

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: D058

Sample Description: Black Duct Binding Material (Glue)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/224

Inspector's Name/Date: BAZ, M.B. 7/5/95

Sample No.: D059

Sample Description: 6" Black Cove Molding

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: _____

Inspector's Name/Date: BAB, MGB

Sample No.: D060

Sample Description: Duplicate of D06061

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- _____ (0) None
- _____ (1) Minimal
- _____ (2) Low
- _____ (3) Moderate
- _____ (5) High

- _____ (0) None
- _____ (1) Minor, < 10%
- _____ (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- _____ (0) No Repair
- _____ (1) > or = to 5 ft.
- _____ (2) Between 1 and 5 ft.
- _____ (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- _____ (0) No
- _____ (3) Yes

Notes:

Type of ACM:

- _____ (0) <1% or non-friable (good condition)
- _____ (1) Miscellaneous ACM
- _____ (1) ACM insulation (not accessible)
- _____ (2) Non-friable ACM (poor condition)
- _____ (2) ACM insulation (accessible)
- _____ (3) Friable ACM with airborne potential
- _____ (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- _____ (0) < 1%
- _____ (1) 1 to 30%
- _____ (2) 31 to 50%
- _____ (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- _____ (0) Non-friable
- _____ (1) Low
- _____ (2) Moderate
- _____ (3) High

Accessibility:

- _____ (0) Low
- _____ (1) Moderate
- _____ (4) High

Notes:

Activity/Use:

- _____ (0) None
- _____ (1) Low
- _____ (2) Moderate
- _____ (3) High

Air Stream/Plenum:

- _____ (0) None
- _____ (1) Present/No ACM
- _____ (2) Present/ACMs occasional
- _____ (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- _____ (0) < 10 cubic or linear ft.
- _____ (1) 10 to 100 cubic or linear ft.
- _____ (2) 100 to 1000 cubic or linear ft.
- _____ (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- _____ (1) < 9 or corridors
- _____ (2) 10 to 200
- _____ (3) 201 to 500
- _____ (4) 501 to 1000
- _____ (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- _____ (0) No ACM or <1%
- _____ (1) Non-friable in good condition
- _____ (2) Non-friable in poor condition
- _____ (3) Friable in good condition
- _____ (5) Friable with damage

Notes:

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/224

Inspector's Name/Date: BAB, MBB 7/5/95

Sample No.: 2061

Sample Description: Brown Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1%
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Notes:

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/219

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: D062

Sample Description: Brown Corkboard Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203 / 2nd Floor Hall

Inspector's Name/Date: BAB, MEB 7/5/95

Sample No.: D063

Sample Description: 2'x4' Ceiling Tile (Mottled Pattern with Pinholes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1%
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Notes:

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203 / 2nd Floor Hall

Inspector's Name/Date: BAB, MGR 7/5/95

Sample No.: D0604

Sample Description: 2x4' Ceiling Tile (Marbled Pattern with Pinholes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203 / 2nd Floor Hall

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: 2065

Sample Description: 2'x4' Ceiling Tile (Worm Pattern with Pinholes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/210

Inspector's Name/Date: BAB, n623 7/5/95

Sample No.: D066

Sample Description: Beige Painted Drywall (2 coats)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/205

Inspector's Name/Date: BAB, MAB 7/5/95

Sample No.: D067

Sample Description: Drywall Joint Compound

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/210

Inspector's Name/Date: BAB, MGB 7/5/95

Sample No.: D068

Sample Description: 2'x4' Ceiling Tiles (Mottled Fatten with Pinholes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/202

Inspector's Name/Date: BAB, N&B 7/5/95

Sample No.: D069

Sample Description: Tan Pressboard

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Notes:

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Notes:

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N106

Inspector's Name/Date: JAB, MEB 7/6/95

Sample No.: E070

Sample Description: 2' x 4' Ceiling Tile (mottled with pinholes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/106^N

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: E071

Sample Description: 2'x4' Ceiling Tile (Marbled with Pinholes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1%
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Notes:

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N106

Inspector's Name/Date: BAB, MEB 7/6/95

Sample No.: E072

Sample Description: Drywall and Joint Compound

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N106

Inspector's Name/Date: BAB, MEB 7/6/95

Sample No.: E073

Sample Description: Debris in Steam Line Chase

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/Lobby

Inspector's Name/Date: BAB, MEB 7/6/95

Sample No.: E074

Sample Description: 12"x12" Floor Tile (Beige with white and Gray mottling)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: E

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/Hallway N

Inspector's Name/Date: CAB, MEB 7/6/95

Sample No.: E075

Sample Description: ~~Rock~~ 2'x4' Ceiling Tile ~~with~~

Pocked with Small and Large Pinholes

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: E

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/Hallway N

Inspector's Name/Date: BAB, MEB 7/6/95

Sample No.: E076

Sample Description: Brown Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N101A

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: E077

Sample Description: 4XB Primary Ceiling Material

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/W101A

Inspector's Name/Date: BAB/TGB 7/6/95

Sample No.: E078

Sample Description: Tan Plaster wall Material

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1%
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Notes:

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N101

Inspector's Name/Date: BAB, MEB 7/6/95

Sample No.: E079

Sample Description: Drywall Plaster Compound

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment INDEX : F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: _____

Inspector's Name/Date: _____

Sample No.: E080

Sample Description: Duplicate E081

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- _____ (0) None
- _____ (1) Minimal
- _____ (2) Low
- _____ (3) Moderate
- _____ (5) High

- _____ (0) None
- _____ (1) Minor, < 10%
- _____ (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- _____ (0) No Repair
- _____ (1) > or = to 5 ft.
- _____ (2) Between 1 and 5 ft.
- _____ (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- _____ (0) No
- _____ (3) Yes

Notes:

Type of ACM:

- _____ (0) <1% or non-friable (good condition) Notes:
- _____ (1) Miscellaneous ACM
- _____ (1) ACM insulation (not accessible)
- _____ (2) Non-friable ACM (poor condition)
- _____ (2) ACM insulation (accessible)
- _____ (3) Friable ACM with airborne potential
- _____ (4) Sprayed or trowelled-on ACM (accessible to occupants)

Percent Asbestos:

- _____ (0) < 1%
- _____ (1) 1 to 30%
- _____ (2) 31 to 50%
- _____ (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- _____ (0) Non-friable
- _____ (1) Low
- _____ (2) Moderate
- _____ (3) High

Accessibility:

- _____ (0) Low
- _____ (1) Moderate
- _____ (4) High

Notes:

Activity/Use:

- _____ (0) None
- _____ (1) Low
- _____ (2) Moderate
- _____ (3) High

Air Stream/Plenum:

- _____ (0) None
- _____ (1) Present/No ACM
- _____ (2) Present/ACMs occasional
- _____ (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- _____ (0) < 10 cubic or linear ft.
- _____ (1) 10 to 100 cubic or linear ft.
- _____ (2) 100 to 1000 cubic or linear ft.
- _____ (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- _____ (1) < 9 or corridors
- _____ (2) 10 to 200
- _____ (3) 201 to 500
- _____ (4) 501 to 1000
- _____ (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- _____ (0) No ACM or <1% Notes:
- _____ (1) Non-friable in good condition
- _____ (2) Non-friable in poor condition
- _____ (3) Friable in good condition
- _____ (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/101A

Inspector's Name/Date: BAB, MBB 7/6/95

Sample No.: E081

Sample Description: Thermal System Pipe Sealant (White)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Notes:

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Notes:

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N107A

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: E08Z

Sample Description: 12" x 12" Acoustical Tile (1/2" Dot pattern)

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Notes:

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1%
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Notes:

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N107A

Inspector's Name/Date: BAE, MGB 7/6/95

Sample No.: E083

Sample Description: Brown Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N107A

Inspector's Name/Date: BAE/MGB 7/6/95

Sample No.: ~~E083~~ E084

Sample Description: 2'x4' Ceiling Tile (Straight wormy pattern with large and small pinholes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/107B

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: E085

Sample Description: 2'x4' Ceiling Tile (Marble and Heavily Pinholed) Pattern

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: E

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/107 C

Inspector's Name/Date: BAB, MLB 7/6/95

Sample No.: E086

Sample Description: 2'x4' Ceiling Tile (Marble with Pinholes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: E

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N107

Inspector's Name/Date: RAB, MEB 7/6/95

Sample No.: E087

Sample Description: Molding

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N107

Inspector's Name/Date: BAZ, MGB 7/6/95

Sample No.: E088

Sample Description: Brown Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N109

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: E089

Sample Description: 6" Black Cove Molding

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N109

Inspector's Name/Date: BAB, MEB 7/6/95

Sample No.: E090

Sample Description: Brown Mastic

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/W111

Inspector's Name/Date: BATB, MGB 7/6/95

Sample No.: E091

Sample Description: Plaster Wall

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: N101

Inspector's Name/Date: BAB/MGB 7/6/95

Sample No.: E092

Sample Description: Electrical Chase Debris

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N116

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: E093

Sample Description: Plywall and Joint Compound

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N118

Inspector's Name/Date: BAB MGB 7/6/95

Sample No.: E094

Sample Description: Brown Mastic above Ceiling

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/N118

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: E095

Sample Description: 12"x12" Floor Tile (Beige with Brown & White mottling)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/new W154

Inspector's Name/Date: FAB, MEB 7/6/95

Sample No.: E096

Sample Description: Drywall and Joint Compound

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1%
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Notes:

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/E157

Inspector's Name/Date: BAB, M&B 7/6/95

Sample No.: E097

Sample Description: 4" Brown Cove Molding

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/E157

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: E098

Sample Description: Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1%
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Notes:

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/E157

Inspector's Name/Date: BAB, MEB 7/6/95

Sample No.: E099

Sample Description: Drywall and Joint Compound

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/E 169

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: E100

Sample Description: Duplicate of E101

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- _____ (0) None
- _____ (1) Minimal
- _____ (2) Low
- _____ (3) Moderate
- _____ (5) High

- _____ (0) None
- _____ (1) Minor, < 10%
- _____ (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- _____ (0) No Repair
- _____ (1) > or = to 5 ft.
- _____ (2) Between 1 and 5 ft.
- _____ (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- _____ (0) No
- _____ (3) Yes

Notes:

Type of ACM:

- _____ (0) <1% or non-friable (good condition)
- _____ (1) Miscellaneous ACM
- _____ (1) ACM insulation (not accessible)
- _____ (2) Non-friable ACM (poor condition)
- _____ (2) ACM insulation (accessible)
- _____ (3) Friable ACM with airborne potential
- _____ (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- _____ (0) < 1%
- _____ (1) 1 to 30%
- _____ (2) 31 to 50%
- _____ (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- _____ (0) Non-friable
- _____ (1) Low
- _____ (2) Moderate
- _____ (3) High

Accessibility:

- _____ (0) Low
- _____ (1) Moderate
- _____ (4) High

Notes:

Activity/Use:

- _____ (0) None
- _____ (1) Low
- _____ (2) Moderate
- _____ (3) High

Air Stream/Plenum:

- _____ (0) None
- _____ (1) Present/No ACM
- _____ (2) Present/ACMs occasional
- _____ (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- _____ (0) < 10 cubic or linear ft.
- _____ (1) 10 to 100 cubic or linear ft.
- _____ (2) 100 to 1000 cubic or linear ft.
- _____ (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- _____ (1) < 9 or corridors
- _____ (2) 10 to 200
- _____ (3) 201 to 500
- _____ (4) 501 to 1000
- _____ (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- _____ (0) No ACM or <1% Notes:
- _____ (1) Non-friable in good condition
- _____ (2) Non-friable in poor condition
- _____ (3) Friable in good condition
- _____ (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/E169

Inspector's Name/Date: EAB, MEB 7/6/95

Sample No.: E101

Sample Description: White 12"x12" Acoustical Tile (1" Dot Spacing)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 2011/E169

Inspector's Name/Date: BAB, MEB 7/6/95

Sample No.: E102

Sample Description: Brown Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/E166

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: E103

Sample Description: 12"x12" Acoustical White Tile (1/2" Spacing)

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/E166

Inspector's Name/Date: BAB, NBB 7/6/95

Sample No.: E104

Sample Description: 12" x 12" Floor Tile (Beige with White and Gray mottling)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: E

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/E166

Inspector's Name/Date: BAB, NGB 7/6/95

Sample No.: E105

Sample Description: Wall Plaster

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: **EF**

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/E/68

Inspector's Name/Date: BAB MGB 7/6/95

Sample No.: E106

Sample Description: Particle Board TAW MASTIC

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/E166

Inspector's Name/Date: BAB, MJB 7/6/95

Sample No.: E107

Sample Description: WHITE DUCT SEALANT MATERIAL

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: E

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/E106

Inspector's Name/Date: BAB/NEB 7/6/95

Sample No.: E108

Sample Description: Drywall and Joint Compound

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/E166

Inspector's Name/Date: BAB/MEB 7/6/95

Sample No.: E109

Sample Description: Green Painted Wall Plaster

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 2011 Hall near S120

Inspector's Name/Date: BAB, NGB 7/6/95

Sample No.: E110

Sample Description: Unpainted Drywall and Joint Compound

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 2011 Hallway near W 148

Inspector's Name/Date: PAB, MGB 7/6/95

Sample No.: E111

Sample Description: 2'x4' Ceiling Tile (Mottled with Pinholes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: E

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/w148

Inspector's Name/Date: RAB MGB 7/6/95

Sample No.: E112

Sample Description: Painted Drywall and Joint Compound

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/W151

Inspector's Name/Date: BAZ, MEB 7/6/95

Sample No.: E113

Sample Description: 2'x4' Ceiling Tile (Pocked with small and large pinholes)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: E

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/W140

Inspector's Name/Date: BAB, NGB 7/6/95

Sample No.: E114

Sample Description: 4" Brown Cove Molding

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 201/^{entrance}

Inspector's Name/Date: BAB, mg 7/6/95

Sample No.: E115

Sample Description: 2x4' Ceiling Tile (Worn with Large Pinholes and Woven texture)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 202/121

Inspector's Name/Date: LAB, MGB 7/6/95

Sample No.: F116

Sample Description: ~~F. Molding~~ 4" Black Cove Molding

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Notes:

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 202/121

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: F117

Sample Description: Brown Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 202/117

Inspector's Name/Date: BAB MGB 7/6/95

Sample No.: F118

Sample Description: Gray Fibrous Debris

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 202/115

Inspector's Name/Date: PAB, MGB 7/6/95

Sample No.: F119

Sample Description: Painted Drywall and Joint Compound

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1%
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Notes:

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 202/103c

Inspector's Name/Date: BATS, MGB 7/6/95

Sample No.: F120

Sample Description: Duplicate of F121

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- _____ (0) None
- _____ (1) Minimal
- _____ (2) Low
- _____ (3) Moderate
- _____ (5) High

- _____ (0) None
- _____ (1) Minor, < 10%
- _____ (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- _____ (0) No Repair
- _____ (1) > or = to 5 ft.
- _____ (2) Between 1 and 5 ft.
- _____ (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- _____ (0) No
- _____ (3) Yes

Notes:

Type of ACM:

- _____ (0) <1% or non-friable (good condition)
- _____ (1) Miscellaneous ACM
- _____ (1) ACM insulation (not accessible)
- _____ (2) Non-friable ACM (poor condition)
- _____ (2) ACM insulation (accessible)
- _____ (3) Friable ACM with airborne potential
- _____ (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- _____ (0) < 1%
- _____ (1) 1 to 30%
- _____ (2) 31 to 50%
- _____ (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- _____ (0) Non-friable
- _____ (1) Low
- _____ (2) Moderate
- _____ (3) High

Accessibility:

- _____ (0) Low
- _____ (1) Moderate
- _____ (4) High

Notes:

Activity/Use:

- _____ (0) None
- _____ (1) Low
- _____ (2) Moderate
- _____ (3) High

Air Stream/Plenum:

- _____ (0) None
- _____ (1) Present/No ACM
- _____ (2) Present/ACMs occasional
- _____ (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- _____ (0) < 10 cubic or linear ft.
- _____ (1) 10 to 100 cubic or linear ft.
- _____ (2) 100 to 1000 cubic or linear ft.
- _____ (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- _____ (1) < 9 or corridors
- _____ (2) 10 to 200
- _____ (3) 201 to 500
- _____ (4) 501 to 1000
- _____ (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- _____ (0) No ACM or <1% Notes:
- _____ (1) Non-friable in good condition
- _____ (2) Non-friable in poor condition
- _____ (3) Friable in good condition
- _____ (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 202/103C

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: F121

Sample Description: Acoustical Tile White 12"x12" with Small Pinholes

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 202/101

Inspector's Name/Date: B. AB, MGB 7/6/95

Sample No.: F122

Sample Description: Dry wall

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 202/101

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: F123

Sample Description: 12" x 12" Greenish and Gray Tile with white streaks

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: E

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 202/101

Inspector's Name/Date: RAB, MGB 7/6/95

Sample No.: F123A

Sample Description: Black Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: E

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 202 / above 103c

Inspector's Name/Date: BAB, NGB 7/6/95

Sample No.: F124

Sample Description: Ceiling Material

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 202/114

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: F125

Sample Description: 4" Black Cove Molding

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 202/119

Inspector's Name/Date: TBA/B, MGT/B 7/6/95

Sample No.: F/26

Sample Description: Brown Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 202/120

Inspector's Name/Date: BAB, NEB 7/6/95

Sample No.: F127

Sample Description: Drywall

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 210/NA

Inspector's Name/Date: BAB, mcb 7/6/95

Sample No.: G128

Sample Description: 12x12" Floor Tile (Beige with Black & White Mottling)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 210/NA

Inspector's Name/Date: BAB, MCB 7/6/95

Sample No.: G129

Sample Description: Tan Mastic

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA
Inspector's Name/Date: BAB, MGB 7/6/95
Sample Description: Concrete Floor

Bldg/Rm. No.: 204/NA
Sample No.: H130

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Notes:

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 204/NA

Inspector's Name/Date: BAB, MEB 7/6/95

Sample No.: H131

Sample Description: Ceiling

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 306

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: I 132

Sample Description: 12x12" ~~Red~~ Colored Floor Tile (Gvst Colored with Brown & Cream Mottling)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 306

Inspector's Name/Date: BAB, MGB 7/6/95

Sample No.: I133

Sample Description: Floor Tile Mastic

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 306

Inspector's Name/Date: BAB, MUB 7/6/95

Sample No.: I 134

Sample Description: Brown Stair Tread

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 306

Inspector's Name/Date: BAB, MEB 7/6/95

Sample No.: I135

Sample Description: Brown Mastic

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 306

Inspector's Name/Date: BAB, m-b 7/6/95

Sample No.: I136

Sample Description: 4" Brown Cove Moldings

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 306

Inspector's Name/Date: BAB MCB 7/6/95

Sample No.: I/37

Sample Description: Mastic

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 306/upper

Inspector's Name/Date: BAB MEB 7/6/95

Sample No.: E-138

Sample Description: Painted Drywall

Part I: DAMAGE ASSESSMENT

Physical:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Notes:

Water:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 300

Inspector's Name/Date: BAE MGB 7/6/95

Sample No.: I-139

Sample Description: Painted Drywall

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1%
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Notes:

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: _____

Inspector's Name/Date: BAB MGB 7/6/95

Sample No.: X-140

Sample Description: Culvert/Old chimney Duplicate

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- _____ (0) None
- _____ (1) Minimal
- _____ (2) Low
- _____ (3) Moderate
- _____ (5) High

- _____ (0) None
- _____ (1) Minor, < 10%
- _____ (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- _____ (0) No Repair
- _____ (1) > or = to 5 ft.
- _____ (2) Between 1 and 5 ft.
- _____ (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- _____ (0) No
- _____ (3) Yes

Notes:

Type of ACM:

- _____ (0) <1% or non-friable (good condition)
- _____ (1) Miscellaneous ACM
- _____ (1) ACM insulation (not accessible)
- _____ (2) Non-friable ACM (poor condition)
- _____ (2) ACM insulation (accessible)
- _____ (3) Friable ACM with airborne potential
- _____ (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- _____ (0) < 1%
- _____ (1) 1 to 30%
- _____ (2) 31 to 50%
- _____ (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- _____ (0) Non-friable
- _____ (1) Low
- _____ (2) Moderate
- _____ (3) High

Accessibility:

- _____ (0) Low
- _____ (1) Moderate
- _____ (4) High

Notes:

Activity/Use:

- _____ (0) None
- _____ (1) Low
- _____ (2) Moderate
- _____ (3) High

Air Stream/Plenum:

- _____ (0) None
- _____ (1) Present/No ACM
- _____ (2) Present/ACMs occasional
- _____ (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- _____ (0) < 10 cubic or linear ft.
- _____ (1) 10 to 100 cubic or linear ft.
- _____ (2) 100 to 1000 cubic or linear ft.
- _____ (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- _____ (1) < 9 or corridors
- _____ (2) 10 to 200
- _____ (3) 201 to 500
- _____ (4) 501 to 1000
- _____ (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- _____ (0) No ACM or <1% Notes:
- _____ (1) Non-friable in good condition
- _____ (2) Non-friable in poor condition
- _____ (3) Friable in good condition
- _____ (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: NA

Inspector's Name/Date: BAB MGB 7/6/95

Sample No.: X-~~141~~ 141

Sample Description: Culvert / old chimney ~~Boiler~~

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: Exterior 203

Inspector's Name/Date: BAB M-B 7/6/95

Sample No.: X-142

Sample Description: South End Exterior (Thermal Insulation)

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Notes:

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: F

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 101, 201, 202, & 203

Inspector's Name/Date: RAB MGB 7/5/95

Sample No.:

Sample Description: General Assessment of all 9x9 floor tile assumed to be ACM per the scope of work

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Notes:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: E

Figure 1a

Modified USAEC ACM Asbestos Checklist

Installation: Army Research Lab, Woodbridge, VA

Bldg/Rm. No.: 203/108

Inspector's Name/Date: BAB MB 7/5/95

Sample No.:

Sample Description: 9x9 Floor Tile

Part I: DAMAGE ASSESSMENT

Physical:

Water:

- (0) None
- (1) Minimal
- (2) Low
- (3) Moderate
- (5) High

Notes:

- (0) None
- (1) Minor, < 10%
- (2) Major, > 10%

Proximity to Items for Repair:

A: Sprayed or trowelled-on friable ACM in areas of routine maintenance.

- (0) No Repair
- (1) > or = to 5 ft.
- (2) Between 1 and 5 ft.
- (3) < 1 ft. or ceiling tiles

Notes:

B: Pipe, boiler, or duct insulation which could be damaged by activity.

- (0) No
- (3) Yes

Notes:

Type of ACM:

- (0) <1% or non-friable (good condition)
- (1) Miscellaneous ACM
- (1) ACM insulation (not accessible)
- (2) Non-friable ACM (poor condition)
- (2) ACM insulation (accessible)
- (3) Friable ACM with airborne potential
- (4) Sprayed or trowelled-on ACM (accessible to occupants)

Notes:

Percent Asbestos:

- (0) < 1%
- (1) 1 to 30%
- (2) 31 to 50%
- (3) > 50%

Figure 1b

Modified USAEC ACM Assessment Checklist

Part II: EXPOSURE ASSESSMENT

Material Friability:

- (0) Non-friable
- (1) Low
- (2) Moderate
- (3) High

Accessibility:

- (0) Low
- (1) Moderate
- (4) High

Notes:

Activity/Use:

- (0) None
- (1) Low
- (2) Moderate
- (3) High

Air Stream/Plenum:

- (0) None
- (1) Present/No ACM
- (2) Present/ACMs occasional
- (3) Present/ACMs routine

Notes:

Area of visible surface or damaged ACM:

- (0) < 10 cubic or linear ft.
- (1) 10 to 100 cubic or linear ft.
- (2) 100 to 1000 cubic or linear ft.
- (3) > 1000 cubic or linear ft.

Notes:

Occupation:

- (1) < 9 or corridors
- (2) 10 to 200
- (3) 201 to 500
- (4) 501 to 1000
- (5) > 1001 or medical facilities, youth centers, day cares, or residential buildings.

Notes:

Unoccupied Facilities:

- (0) No ACM or <1% Notes:
- (1) Non-friable in good condition
- (2) Non-friable in poor condition
- (3) Friable in good condition
- (5) Friable with damage

Assessment Index: E