



**US Army Corps  
of Engineers**  
Waterways Experiment  
Station

# Investigation of Concrete from I-20 Near Monroe, Louisiana

*by G. Sam Wong*



Approved For Public Release; Distribution Is Unlimited

19980414 095

**DTIC QUALITY INSPECTED 4**

**The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official endorsement or approval of the use of such commercial products.**

**The findings of this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.**



**PRINTED ON RECYCLED PAPER**

Miscellaneous Paper SL-98-1  
January 1998

# Investigation of Concrete from I-20 Near Monroe, Louisiana

by G. Sam Wong

U.S. Army Corps of Engineers  
Waterways Experiment Station  
3909 Halls Ferry Road  
Vicksburg, MS 39180-6199

Final report


Approved for public release; distribution is unlimited

Prepared for U.S. Army Corps of Engineers  
Washington, DC 20314-1000

Under Work Unit 32639



**US Army Corps  
of Engineers**  
Waterways Experiment  
Station



FOR INFORMATION CONTACT:  
PUBLIC AFFAIRS OFFICE  
U.S. ARMY ENGINEER  
WATERWAYS EXPERIMENT STATION  
3909 HALLS FERRY ROAD  
VICKSBURG, MISSISSIPPI 39180-6199  
PHONE: (601) 634-2502

**Waterways Experiment Station Cataloging-in-Publication Data**

Wong, G. Sam.

Investigation of concrete from I-20 near Monroe, Louisiana / by G. Sam Wong ; prepared for U.S. Army Corps of Engineers.

80 p. : ill. ; 28 cm. — (Miscellaneous paper ; SL-98-1)

Includes bibliographic references.

1. Pavements, Concrete — Louisiana — Testing. 2. Pavements, Flexible — Louisiana — Testing. 3. Concrete — Deterioration — Louisiana — Testing. I. United States. Army. Corps of Engineers. II. U.S. Army Engineer Waterways Experiment Station. III. Structures Laboratory (U.S. Army Engineer Waterways Experiment Station) IV. Title. V. Series: Miscellaneous paper (U.S. Army Engineer Waterways Experiment Station) ; SL-98-1. TA7 W34m no.SL-98-1

# Contents

---

Preface .....	iv
1—Background .....	1
2—Evaluation Procedures and Results .....	2
Results of Cores .....	3
Results of Samples .....	7
3—Conclusions and Recommendations .....	9
References .....	13
Figures 1-29	
Tables 1-4	
Appendix A: Photographs of Concrete Sections .....	A1
Appendix B: U.S. Army Corps of Engineers Evaluation Data .....	B1
SF 298	

# Preface

---

The research reported in this Miscellaneous Paper was conducted by the Structures Laboratory (SL), U.S. Army Engineer Waterways Experiment Station (WES), under the sponsorship of the Louisiana Transportation Research Center and the Portland Cement Association (PCA Project Index No. 95-04). This investigation was conducted under the general supervision of Messrs. Bryant Mather, Director, SL, and John Ehrgott, Assistant Director, SL. Direct supervision was provided by Dr. Paul F. Mlakar, Chief, Concrete and Materials Division (CMD), SL. Mr. G. Sam Wong, CMD, was the principal investigator of the study and author of this report.

Funds for the publication of the report were provided from those made available for operation of the Concrete Technology Information Analysis Center (CTIAC), SL. This is CTIAC Report No. 92.

The contents of this paper reflect the views of the author, who is responsible for the facts and accuracy of the data presented. The contents do not necessarily reflect the views of Louisiana Transportation Research Center or the Portland Cement Association.

At the time of publication of this report, Director of WES was Dr. Robert W. Whalin. Commander was COL Robin R. Cababa, EN.

*The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official endorsement or approval of the use of such commercial products.*

# 1 Background

---

On 2 December 1994, the Louisiana Department of Transportation (LDOT) asked a representative of the U.S. Army Engineer Waterways Experiment Station (WES), Structures Laboratory, to make a field inspection of concrete deterioration on I-20 west of Vicksburg, MS. The inspection, participated in by Messrs. B. Mather, WES; W. H. Temple and N. A. Rabalais, Louisiana Transportation Research Center; and S. W. Foster and P. J. Arena, Federal Highway Administration, took place on 10 January 1995. Following this inspection, Mr. G. S. Wong, Concrete Technology Division (CTD)<sup>1</sup>, Structures Laboratory, WES, submitted a proposal to LDOT. This report covers the investigation conducted to determine the probable cause of concrete pavement deterioration in certain lanes of I-20 both east and west of Monroe, LA. Field examination of the pavement by the Department of Transportation and Development (DOTD), State of Louisiana, indicated that concrete near joints was more affected than elsewhere. The concrete in the westbound lanes shows less deterioration than in the eastbound lanes. Some sections of the eastbound lane have been repaired with asphalt.

The concrete represented by the cores was placed as part of projects 451-07-29 east of Monroe and 451-05-0060 west of Monroe during the years 1987 to 1991. The cement came from Lone Star, Cape Girardeau, MO, and Ash Grove, Foreman, AR, respectively, for which typical mill test reports indicated  $\text{Na}_2\text{O}_{\text{eq}}$  varying from 0.4 to 0.5 percent. The coarse aggregate was crushed limestone from the Dravo quarry at Smithland, KY. The fine aggregate was natural sand. Class C fly ash from Gifford Hill, Boyce, LA, was used in all of the concrete west of Monroe, represented by cores No. 1 - 6. Fifteen cores were received from the DOTD for use in this investigation. The cores were selected to represent areas of distress as well as non-distressed areas from the different sections of roadway of interest. Each core was given a CTD serial number. The CTD numbers and the accompanying field description of each are provided in Table 1.

---

<sup>1</sup> The former Concrete Technology Division (CTD) is now designated Concrete and Materials Division (CMD).

## 2 Evaluation Procedures and Results

---

Cores were examined and logs made showing the general description of each core. Evaluation specimens also were selected at that time. Evaluations were planned to address the following: (a) the role of alkali-carbonate-rock reaction; (b) the role of alkali-silica reaction; (c) contribution of freezing and thawing action to the deterioration; (d) contribution of fresh concrete properties and construction practices to the deterioration. The evaluation matrix is given in Table 2.

Pulse velocities were determined for 12 of the 15 cores received. Pulse velocities were determined according to American Society for Testing and Materials (ASTM) C 597, "Standard Test Method for Pulse Velocity Through Concrete."

Petrographic examination of the concrete was performed using guidance from ASTM C 856, "Standard Practice for Petrographic Examination of Hardened Concrete." Selected coarse-aggregate particles were extracted from the concrete and examined by X-ray diffraction to determine mineral composition. All photographs were taken of sawed, ground, lapped surfaces prepared essentially as suggested in ASTM C 856 and C 457.

Petrographic examination of the aggregates was performed on coarse-aggregate particles extracted from the concrete as well as from the samples provided. This examination was performed using guidance from ASTM C 295, "Standard Guide for Petrographic Examination of Aggregates for Concrete." All photographs were taken of sawed, ground, and lapped surfaces prepared essentially as suggested in ASTM C 856 and C 457.

Volume stability of the aggregate was determined using ASTM C 586, "Standard Test Method for Potential Alkali Reactivity of Carbonate Rocks for Concrete Aggregates (Rock Cylinder Method)." Small-diameter cylinders were cored from coarse-aggregate particles and subjected to 1N solution of NaOH, and the cylinders were measured periodically to determine changes in length.



Cement-content analyses were performed on four cores. Cores 950617 and 950626 represented concrete from the eastbound lane, and cores 950621 and 950623 represented concrete from the westbound lane. Cement contents were determined using the draft<sup>1</sup> maleic-acid procedure developed by ASTM C 09.69 for inclusion as a revision of "Standard Test Method for Portland-Cement Content on Hardened Hydraulic-Cement Concrete," ASTM C 1084.

## Results of Cores

Cores 950623 and 950624 represented concrete in the westbound lane west of Monroe. Some hairline cracks were observed, and they tended to be near the top surface with vertical extent less than 0.05 ft (0.02 m). Both cores were approximately 1 ft (0.3048 m) in length and were of air-entrained concrete. Limestone coarse-aggregate particles were light gray. The logs for cores 950623 and 950624 are shown in Figures 1 and 2, respectively.

Cores 950625, 950626, 950627, and 950628 represent concrete from the eastbound lane west of Monroe. Cores 950625 and 950626 contained reinforcing steel at approximately 0.5-ft (0.15 m) depth. Some lateral cracks were found associated with the reinforcing steel. Core 950627 was intact throughout. Cores 950625, 950626, and 950628 contained some cracking throughout the length of the cores, with cracking more numerous near the surface of the pavement. Cracks were vertical, horizontal, and diagonal. Cores 950625, 950626, and 950628 contained dark-aggregate particles showing some fracturing, as indicated on the logs given in Figures 3 through 6.

Cores 950620, 950619, 950617, 950614, 950616, 950622, and 950618 were from the eastbound lane east of Monroe. The condition of the cores ranged from heavy cracking to no cracks in the concrete, as shown in the core logs given in Figures 7 through 13.

Cores 950621 and 950615 represent concrete in the westbound lane east of Monroe. These cores contained very light cracking to no cracks. The coarse aggregate was composed mostly of light-gray limestone particles. The darker limestone coarse-aggregate particles tended to be small. There was a small vertical crack at the bottom of core 950621 associated with a dark limestone particle that contained a reaction rim as well as a fracture in the particle. The concrete was in good condition, as described in the core logs given in Figures 14 and 15.

The pulse velocities were generally above 11,000 ft/sec (3,353 m/sec) with two samples, 950626 and 950628, having lower velocities of 10,600 ft/sec

---

<sup>1</sup> The specific draft used was Draft #5, 1 June 1994, but the results are regarded as being insignificantly different from those that would have been obtained had the later draft dated 14 November 1995 been followed.

(3,231 m/sec) and 7,560 ft/sec (2,304 m/sec), respectively. The Table 3 tabulates the data for the individual specimens.

The core logs describe the general condition of each core. The following section describes some notable features of the concrete and includes more detailed information on the structure and the composition.

- a. 950623 - This core was cut along its entire length to expose the interior concrete. A near-surface vertical crack was associated with subsurface dark-gray coarse-aggregate particles with prominent reaction rims. These particles showed some interior cracks. X-ray diffraction examination of one particle indicated that the particle was composed of a fine-grained dolomitic limestone containing some quartz and clay, as shown in Figure 16. Some interior, randomly oriented incipient cracks were also observed associated with dark-gray coarse-aggregate particles with reaction rims, as illustrated in Figure A1, Appendix A. These cracks were located in the lower portion of the core.
- b. 950625 - Vertical cracks from the surface intersected dark-gray coarse-aggregate particles as well as horizontal intermittent fractures, as shown in Figure A2, Appendix A. All fractures could be traced to dark-gray coarse-aggregate particles with dark reaction rims either partially or entirely rimming the particle. No cracking was associated with similar smaller dark coarse-aggregate particles. Cracks in some particles were continuous into the paste while other cracks in the aggregate particles showed no such continuation. The paste was hard and intact.
- c. 950626 - This concrete sustained localized damage. A single horizontal crack and some hairline fracturing were observed on a cut section on one side of the slab (Figure A3a, Appendix A). On the reverse side, heavy fracturing of the concrete associated with dark-gray coarse-aggregate particles was observed. Minor cracking at the bottom of the core associated with cracked dark-gray coarse aggregate is illustrated in Figure A3a, Appendix A. Examination of a thin section containing coarse-aggregate particles showed a linear opening along oriented features. The cracks contained no observed reaction products.
- d. 950627 - This concrete was intact and generally contains medium-grained light-gray limestone coarse aggregate. The paste was hard and intact, as shown in Figure A4, Appendix A.
- e. 950628 - The concrete contained numerous cracks throughout the length of the core. The cracks were vertical, horizontal, and diagonal going through, as well as around, coarse-aggregate particles, as shown in Figures A5a and A5b, Appendix A. There were numerous

dark-gray fine-grained limestone coarse-aggregate particles in the concrete. Some of the pieces were large coarse-aggregate particles and some were small. Cracks were always associated with the larger pieces of aggregate of this nature and were less common with smaller pieces. Many of these pieces of aggregate showed open cracks in the interior of the particle. The X-ray diffraction pattern showed the coarse-aggregate particles to consist of a dolomitic limestone containing some quartz and clay (Figure 17).

- f.* 950620 - The core was cracked throughout its length. The cracks were randomly oriented. There were numerous dark-gray limestone coarse-aggregate particles with dark reaction rims. The rims exhibited radial cracks that extended into the paste. Aggregate particles with these rims were dolomitic limestone containing quartz and clay. X-ray diffraction patterns are presented in Figures 18 and 19. Figure A6, Appendix A, shows the appearance of these aggregate particles.
- g.* 950619 - The core was cracked throughout its length. Cracking in the near-surface concrete was more severe as vertical, horizontal, and diagonal cracks were common and associated with dark-gray limestone coarse-aggregate particles (Figure A7, Appendix A). Thin sections of two coarse-aggregate particles were prepared. Particle #A was a light-colored fine-grained limestone consisting of a fine-grained matrix and rhombohedral dolomite crystals. No cracks associated with this particle were observed. Particle #B was a dark-gray fine-grained limestone with a rim around it and was associated with cracking. No difference could be observed between the material in the rim and the interior of the particle. Fine quartz grains were embedded in a calcite matrix.
- h.* 950617 - This sample consisted of rubble. The core had broken into fragments during the coring process. One large piece was impregnated using an epoxy resin and then cut open for examination. The concrete was highly fractured (Figure A8, Appendix A). There were numerous dark-gray limestone coarse-aggregate particles. Cracks were mostly associated with the larger coarse-aggregate particles. The associated dark-gray coarse-aggregate particles were dolomitic limestone containing some quartz as well as illite (clay-mica). An X-ray diffraction chart showing the relative abundance of the calcite and dolomite is presented in Figure 20.
- i.* 950614 - Hairline vertical cracks were observed to penetrate approximately 1 in. (25.4 mm) into the concrete. Some incipient fractures were observed in the concrete. The coarse aggregate was primarily a light-colored limestone.

- j.* 950616 - The surface cracking was light. However, the interior concrete showed an extensive crack system. A vertical crack extended several inches into the interior concrete going through coarse-aggregate particles as well as around them. The vertical cracks intersected horizontal and diagonal cracks (Figures A9a and A9b, Appendix A). The majority of the cracks were associated with cracked dark-gray fine-grained limestone coarse-aggregate particles. Two particles examined by X-ray diffraction were dolomitic limestone with acid-insoluble materials consisting of quartz and clays. Figures 21 and 22 illustrate the relative abundance of the carbonate phases.
- k.* 950622 - This sample was intact with no visible cracks. The coarse aggregate was light colored and did not contain any reaction rims (Figure A10, Appendix A). A single hairline crack at the bottom of the core, shown in Figure A10, Appendix A, was observed and seems unrelated to dark-gray coarse aggregate.
- l.* 950618 - This concrete was heavily cracked. Vertical, horizontal, and diagonal cracks were abundant throughout the length of core. The cracking was associated with a large dark-gray limestone coarse-aggregate particle (Figure A11, Appendix A). Fractures were observed in the central portion of the aggregate particle as well as in the rim area of the particle. A specimen of this aggregate particle was cored along the paste-to-aggregate interface and prepared for examination as a ground section. The specimen was impregnated using an epoxy resin to reinforce the sample and minimize possible additional cracking in the preparation process. The specimen showed the propagation of cracks through the interface zone. The cracks were not confined to the interface zone of the aggregate particle as they propagated into the interior of the aggregate particle. The interior portion of the aggregate particle was also cracked. High-resolution elemental analysis using the scanning electron microscope (SEM) and energy dispersive X-ray (EDX) showed no migration of elements in this particular aggregate particle, as illustrated in Figure 27.
- m.* 950621 - This concrete had some hairline cracks at the surface. One crack penetrated into the interior concrete approximately 1 in. (25.4 mm) and terminated in the paste. The upper portion of the concrete consisted of lighter colored limestone coarse-aggregate particles. The lower portion of the core contained numerous dark-limestone coarse-aggregate particles with dark reaction rims. Some cracks associated with these limestone aggregate particles are shown in Figure A12, Appendix A. The X-ray diffraction pattern of aggregate particle #A, a dark-gray particle with a prominent dark reaction rim, showed it to be pure limestone, as shown in Figure 23. Light-colored brownish limestone with a reaction rim (particle #B) was pure limestone, as identified in Figure 24. The dark-gray particle

with a prominent reaction rim (Figure A12, Appendix A) (particle #C) was a fine-grained dolomitic limestone also containing insoluble material including clays and quartz (Figure 25). A thin section of a near-surface dark-gray fine-grained impure limestone coarse-aggregate particle showed a rim on this aggregate and micro cracks in the rim propagating into the paste. Etching of coarse-aggregate particle using dilute hydrochloric acid showed no relief in the rim area; i.e., the rim was neither more nor less acid soluble than the unaltered rock.

- n. 950615 - This concrete contained primarily light-colored limestone coarse-aggregate particles; some dark reaction rims were present on some of the coarse-aggregate particles (Figure A13, Appendix A). When etched with dilute hydrochloric acid, the rims showed no relief. The paste was intact and hard.

Thin sections of the reactive aggregate particle 950629B indicated the rock was composed of euhedral to subhedral crystals of dolomite approximately 0.1-mm nominal size floating in a groundmass of calcite and other mineral matter. Crystals in the groundmass were less than 0.015-mm nominal size. Reactive particle 950630B contained subhedral dolomite crystals with a nominal size of 0.04 mm in a fine-grained groundmass. Both were impure dolomitic limestones.

Rock-cylinder expansion measurements indicated that some of the aggregate particles were highly reactive when stored in sodium hydroxide in accordance with ASTM C 586. Figures 28 and 29 show expansion data up to 64 days. The specimens were immersed in water for 7 days and showed no change in length. Specimens from both limestone samples included aggregate materials that expanded significantly. Sample 950629 showed immediate expansion and rose to above 3 percent at 35 days; measurements were terminated for these particular specimens as they began to fall apart. Sample 950630 yielded specimens that expanded to above 0.4 percent in 64 days in sodium hydroxide. Analysis of a highly expansive particle in 950629 (particle B) indicated the sample to be composed of dolomitic limestone containing some quartz and clay. No reaction products were detected by X-ray diffraction analysis, as shown in Figure 26.

Cement-content analysis indicated that three samples contained 420 to 438 lb/yd<sup>3</sup> (249 to 260 kg/m<sup>3</sup>), and one sample had a cement content of over 600 lb/yd<sup>3</sup> (356 kg/m<sup>3</sup>). The results are shown in the Table 4.

## Results of Samples

All cement paste was hard and intact. No evidence of sulfate attack was detected. Although ettringite crystals in voids are not necessarily evidence of sulfate attack, the absence of ettringite in the fracture surfaces and in voids is a positive indication of the absence of sulfate attack.

There was no scaling of the concrete observed, the concrete was adequately air entrained, and the typical freezing and thawing damage caused when paste is critically saturated was not observed. Generally, when the freezing isotherm goes through the concrete, it will create stresses normal to the surface resulting in cracking that tends to be subparallel to parallel to the surface of the concrete. Cracking in the cores that contained cracks tended to be random in orientation. Based on these observations, it was regarded as unnecessary to conduct quantitative work according to ASTM C 457 to develop data on the air-void system of the concrete.

Hairline cracks with only near-surface penetration are most likely drying shrinkage cracks caused by loss of the moisture from the concrete. This was observed in most of the cores examined.

Alkali-silica reaction was minimal. Alkali-silica gel was observed only in isolated voids. No alkali-silica reaction products were observed in the cracks in the concrete.

Carbonate-rock reaction was common throughout the pavement in all sections. The amount of deleteriously reactive aggregate varied from location to location from and within a location. There is significant evidence that much of the cracking is related to dark-gray dolomitic limestone coarse-aggregate particles. Many of the cracks seem to propagate from these coarse-aggregate particles.

It is believed that this reaction is continuing in the pavement in some locations as some of the aggregate particles show major fracturing of the particle itself and fractures into the adjacent paste and concrete. Other particles are only minimally cracked, and it is likely that these have the potential to continue to experience disruptive volume change. In other places, there was no surface expression of deterioration but some reactive aggregates were identified deeper in the pavement with associated cracks. This may reduce the service life of the pavement section in which this is present.

Not all of the cracking is solely attributed to the carbonate-rock reaction. In some areas where cracking is severe, there does not appear to be sufficient reactive aggregates to suggest that this reaction is solely responsible for the deterioration. Because deterioration seems to be observed first along joints, pavement edges, and approach ramps to bridges, the weakening of the concrete by carbonate-rock reaction is most likely aggravated by loading due to traffic.

### 3 Conclusions and Recommendations

---

Deterioration of the concrete is evidenced by cracking and raveling of the pavement. In this investigation, we have identified some deterioration in which there is minimal evidence at the concrete surface. Where there is disruption of the paste, incipient cracks present in the concrete will open during continued loading. It is also envisioned that the cracks can be filled with water and during freezing, wedging action could work to increase damage to the concrete. It is regarded as unlikely that freezing and thawing effects could do more than aggravate deterioration of already distressed concrete. The location is in the moderate weathering region designated in Figure 1 of ASTM C 33, "Standard Specification for Concrete Aggregates." In spite of this categorization, bridge-railing concrete on I-20 in Mississippi developed popouts due to freezing of critically saturated concrete containing porous-chert aggregate particles.

There were numerous dolomitic limestone particles in the smaller size fraction which when observed individually in the concrete appeared to have limited effect on the cracking of the concrete. When present in substantial numbers, deterioration of concrete was observed.

Pulse velocities of the cores, in general, can be separated into categories where above 12,000 ft/sec (3,658 m/sec) is considered good and that below is questionable. There is a lack of correlation in the observed information. The limited pulse-velocity information is not sufficient to categorize the integrity of the various concretes represented. Some of the cores containing cracks had relatively high pulse velocities.

Many of the coarse-aggregate particles reacted in the concrete. Reaction rims partially or entirely surrounded the particles. Not all of the coarse-aggregate particles reacted as some did not have reaction rims. Not all of the dark-gray particles that reacted were expansive. The reactive particles that were identified as expansive were particles of impure dolomitic limestone. Nonreactive dark-gray particles were pure limestone.

Traditional reactive carbonate-rock aggregates have a composition similar to that which is described as expansive in this concrete. There is no doubt that this concrete underwent internal expansion and cracking associated with alkali-carbonate rock reaction (ACR) involving dolomitic carbonate rock with the composition and texture of dolomites that have been identified at other places as associated with expansive deterioration of concrete. In many such cases, the deterioration is believed to have been initiated by a chemical reaction that alters the mineral dolomite ( $\text{CaCO}_3 \cdot \text{MgCO}_3$ ) to  $\text{CaCO}_3$  (calcite) and  $\text{Mg(OH)}_2$  (brucite). The  $\text{CO}_2$  in the  $\text{MgCO}_3$  typically combines with alkali and later with the calcium in the pore fluid of the concrete. It has been suggested that the expansive force is due to reaction of the alkali with clay minerals in the matrix of the rock. Since in the present case, no evidence of alteration of the dolomite (i.e., no production of  $\text{Mg(OH)}_2$  (brucite)) and no migration of elements across the coarse-aggregate paste interface were found, it is assumed that the source of the expansive force that produced the cracks radiating from the reactive coarse-aggregate particles is a chemical reaction and expansion of the clay minerals in the matrix. As noted, no expansion of the rock cylinders taken from the samples of crushed limestone was observed when soaked in water before being exposed to sodium hydroxide (NaOH), but in some cases, a large expansion was noted quite soon when exposed to NaOH.

Carbonate-rock reaction may continue indefinitely or until the moisture content falls below a certain level at which the reaction can no longer continue, since it is a chemical reaction involving diffusion of ions in the pore fluid of the concrete.

Bridge decks were treated as necessary with calcium magnesium acetate (CMA) as a deicing agent. ACR may be accelerated by the addition of sodium chloride, which is a common deicing agent. It is not expected that CMA would cause acceleration of the ACR.

The reactive aggregate particles were found in both aggregate samples examined (950629 and 950630). The testing of the aggregate was limited to particles large enough to obtain test specimens. The testing suggests the presence of alkali-carbonate reactive aggregate, but is not an indication of the amount of deleteriously reactive aggregate nor the reactivity of the aggregate source.

Cement content is a variable in the concrete, but it does not seem to affect the quality of the concrete or the reaction in this situation.

Where the concrete contains fly ash, the measured cement contents are biased towards higher values, particularly if the concrete is old, so that the fly ash hydration is advanced, or if the concrete contains Class C fly ash, or both. All concrete from west of Monroe contained some fly ash.

The insoluble residue of the cement was analyzed in either duplicate or triplicate. This is the part of the analysis that appears to be most prone to



error; however, replication was good enough to indicate that the value for sample 950621 was significantly higher than the cement contents of the other three cores when means were compared in an analysis of variance procedure.

The deterioration of the concrete, samples of which were examined, is believed to be the consequences of a chemical reaction involving a type of rock present in the coarse aggregate that was used. The coarse aggregate is a carbonate rock that comes in a variety of types--both light colored and dark colored, with little or no quartz or clay (insoluble residue), and ranging from pure limestone (no significant amount of magnesium carbonate) to dolomite (about equal amounts of calcium and magnesium carbonate). The chemical reaction causes rims to form on some of these varieties, mostly the dark-colored ones, some dolomitic, some pure limestone. However, unless the rock is not only dark but also dolomitic and with a significant amount of quartz and clay, the rim-forming reaction does not seem to be accompanied by physical distress in the concrete. In the two samples of rock tested, only 2 of 12 and 2 of 10 showed expansion when evaluated as rock cylinders in accordance to ASTM C 586. The physical distress is manifested by cracking radiating from affected coarse-aggregate particles. The literature has suggested that such internal expansion can result from either the de-dolomitization reaction or as a secondary consequence of breakdown in the rock that allows fluid access to the included clay and the swelling of the clay. No evidence of de-dolomitization was developed in the work that was done. No brucite ( $Mg(OH)_2$ ) nor any migration of elements across the paste-coarse aggregate interface was detected. It may, therefore, be that the expansive force is produced by the swelling of the clay in the rock. It is reported that the cement used was low alkali; this may not preclude deleterious alkali-carbonate rock reaction since some scenarios for such reaction contemplate regeneration rather than sequestration of the alkali that participates in the reaction.

Deterioration of the pavement is related to the presence and abundance of deleterious reactive carbonate-rock coarse-aggregate particles reacting with the alkalies in the cement. Some of the pavement not already showing distress may continue to deteriorate, causing future pavement failure in areas not currently showing such distress. To identify portions of pavement with potential for deterioration would require an extensive coring program and the petrographic examination of the cores to identify the presence and absence of deleterious reactive aggregates. This may not be practical as there is variability within cores as well as between the cores examined, which was demonstrated during this investigation.

It is expected that the pavement will continue to be weakened by this reaction and that deterioration will be aggravated by traffic. The degree to which traffic aggravates the deterioration may well be influenced by differences from location to location in the bearing capacity of the foundation. As the pavements deteriorates, those areas should be removed and replaced.

It is recommended that this aggregate type be avoided in planning for future portland-cement concrete construction or precautions should be taken to minimize the alkali-carbonate rock reaction in the concrete if it is necessary to use this rock for aggregate. U.S. Army Corps of Engineers test data on this rock are given in Appendix B.

# References

---

American Society for Testing and Materials. (1995). *1995 Annual Book of ASTM Standards*. Philadelphia, PA.

Designation C 33, "Standard specification for concrete aggregates."

Designation C 295, "Standard guide for petrographic examination of aggregates for concrete."

Designation C 457, "Standard specifications for microscopical determination of parameters of the air-void system in hardened concrete."

Designation C 586, "Standard test method for potential alkali-reactivity of carbonate rocks for concrete aggregates (rock cylinder method)."

Designation C 597, "Standard test method for pulse velocity through concrete."

Designation C 856, "Standard practice for petrographic examination of hardened concrete."

Designation C 1084, "Standard test method for portland-cement content of hardened hydraulic-cement concrete."

DRILLING LOG		DIVISION		INSTALLATION Louisiana Hwy Dept.		SHEET 1 OF 1 SHEETS	
1. PROJECT I-20 Cores				10. SIZE AND TYPE OF BIT 6"			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)			
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		L-1		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED	UNDISTURBED
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT				15. ELEVATION GROUND WATER		16. DATE HOLE	
7. THICKNESS OF OVERBURDEN				STARTED		COMPLETED	
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE			
9. TOTAL DEPTH OF HOLE 0.9 feet				18. TOTAL CORE RECOVERY FOR BORING			
				19. SIGNATURE OF INSPECTOR			
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)	
0	0.0		Drag finished surface HL incipient crack to 0.05-ft.				
-0.9	0.9		EOB 0.90-ft. Flat asphalt interface 1.5-in. max size Ls CA, crushed Siliceous FA, natural No segregation Good consolidation Air entrained CTD #950623				

Figure 1. Log of core 950623


DRILLING LOG		DIVISION		INSTALLATION Louisiana Hwy Dept.		SHEET 1 OF 1 SHEETS	
1. PROJECT I-20 Cores				10. SIZE AND TYPE OF BIT 6"			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)			
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		L-2		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED	UNDISTURBED
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT				15. ELEVATION GROUND WATER		16. DATE HOLE	
7. THICKNESS OF OVERBURDEN				STARTED		COMPLETED	
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE			
9. TOTAL DEPTH OF HOLE 1.1 feet				18. TOTAL CORE RECOVERY FOR BORING			
				19. SIGNATURE OF INSPECTOR			
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)	
0	0.0		Tine grooved surface HL incipient crack No vertical extension				
-1.1	1.1		EOB 1.10-ft. Flat asphalt interface 1.5-in. max size Ls CA, crushed Siliceous FA, natural No segregation Good consolidation Air entrained CTD #950624  Ls CA tend to be lighter color w/no reaction rims				

Figure 2. Log of core 950624



DRILLING LOG		DIVISION		INSTALLATION		SHEET 1 OF 1 SHEETS	
1. PROJECT I-20 Cores				10. SIZE AND TYPE OF BIT 6"			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)			
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		L-3		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED	UNDISTURBED
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT				15. ELEVATION GROUND WATER			
7. THICKNESS OF OVERBURDEN				16. DATE HOLE		STARTED	COMPLETED
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE			
9. TOTAL DEPTH OF HOLE 1.15 feet				18. TOTAL CORE RECOVERY FOR BORING			
				19. SIGNATURE OF INSPECTOR			
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)	
0	0.0		Tine grooved surface HL incipient crack				
			Break at cast of rebar Numerous incipient fractures upper 0.5-ft. Some near 0.9-ft.				
-1.15	1.15		EOB 1.15-ft. Asphalt interface 1.5-in. max size Ls CA, crushed Siliceous FA, natural No segregation Good consolidation Air entrained CTD #950625  Incipient fractures associated with numerous dark Ls CA w/ reaction rims, particles tend to be fractured				

Figure 3. Log of core 950625


DRILLING LOG		DIVISION		INSTALLATION		SHEET 1 OF 1 SHEETS	
1. PROJECT I-20 Cores				10. SIZE AND TYPE OF BIT 6"			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)			
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		L-4		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED	UNDISTURBED
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT				15. ELEVATION GROUND WATER			
7. THICKNESS OF OVERBURDEN				16. DATE HOLE		STARTED	COMPLETED
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE			
9. TOTAL DEPTH OF HOLE 1.1 feet				18. TOTAL CORE RECOVERY FOR BORING			
				19. SIGNATURE OF INSPECTOR			
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)	
0	0.0		Tine grooved surface HL incipient crack  1 3/8-in. steel bar (epoxy coated) incipient fracture				
-1.1	1.10		EOB 1.10-ft. Asphalt interface 1.5-in. max size Ls CA crushed Siliceous FA, natural No segregation Good consolidation Air entrained CTD #950626  Incipient fractures associated with large dark Ls CA w/ reaction rims, fractured				

Figure 4. Log of core 950626


DRILLING LOG		DIVISION		INSTALLATION		SHEET 1 OF 1 SHEETS	
1. PROJECT I-20 Cores				10. SIZE AND TYPE OF BIT 6"			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)			
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		L-5		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED UNDISTURBED	
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT				15. ELEVATION GROUND WATER			
7. THICKNESS OF OVERBURDEN				16. DATE HOLE		STARTED COMPLETED	
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE			
9. TOTAL DEPTH OF HOLE 1.15 feet				18. TOTAL CORE RECOVERY FOR BORING			
				19. SIGNATURE OF INSPECTOR			
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)	
0	0.0		Tine grooved surface				
-1.15	1.15		EOB 1.15' Asphalt Interface  1.5-in max. size Ls CA, crushed Siliceous FA, natural No segregation Good consolidation Air entrained CTD #950627				

Figure 5. Log of core 950627



DRILLING LOG		DIVISION		INSTALLATION Louisiana Hwy Dept.		SHEET 1 OF 1 SHEETS	
1. PROJECT I-20 Cores				10. SIZE AND TYPE OF BIT 6"			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)			
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		L-6		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED	UNDISTURBED
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT				15. ELEVATION GROUND WATER		16. DATE HOLE	
7. THICKNESS OF OVERBURDEN				STARTED		COMPLETED	
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE			
9. TOTAL DEPTH OF HOLE 1.1 feet				18. TOTAL CORE RECOVERY FOR BORING			
				19. SIGNATURE OF INSPECTOR			
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)	
0	0.0		Tine grooved surface Map crack pattern Fractures generally around aggregate Some fractures through CA				
-1.1	1.1		EOB 1.10-ft. Asphalt interface 1.5-in. max size Ls CA, crushed Siliceous FA, natural No segregation Good consolidation Air entrained CTD #950628				

Figure 6. Log of core 950628


DRILLING LOG		DIVISION		INSTALLATION		SHEET 1 OF 1 SHEETS	
1. PROJECT I-20 Cores				10. SIZE AND TYPE OF BIT 6"			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)			
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		L-7		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED UNDISTURBED	
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT				15. ELEVATION GROUND WATER		16. DATE HOLE STARTED COMPLETED	
7. THICKNESS OF OVERBURDEN				17. ELEVATION TOP OF HOLE			
8. DEPTH DRILLED INTO ROCK				18. TOTAL CORE RECOVERY FOR BORING			
9. TOTAL DEPTH OF HOLE 1.1 feet				19. SIGNATURE OF INSPECTOR			
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)	
0	0.0		Tine grooved surface Surface cracked to 0.1-ft.				
-1.1	1.1		Asphalt interface 1.5-in. max size Ls CA, crushed Siliceous FA, natural No segregation Good consolidation Air entrained CTD #950620  Reaction rims around dark CA Near surface voids above CA				

Figure 7. Log of core 950620

DRILLING LOG		DIVISION		INSTALLATION		SHEET 1 OF 1 SHEETS	
1. PROJECT I-20 Cores				10. SIZE AND TYPE OF BIT 6"			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)			
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		L-8		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED	UNDISTURBED
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT				15. ELEVATION GROUND WATER		16. DATE HOLE STARTED _____ COMPLETED _____	
7. THICKNESS OF OVERBURDEN				17. ELEVATION TOP OF HOLE			
8. DEPTH DRILLED INTO ROCK				18. TOTAL CORE RECOVERY FOR BORING			
9. TOTAL DEPTH OF HOLE 1.1 feet				19. SIGNATURE OF INSPECTOR			
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)	
0	0.0		Tine grooved surface Numerous incipient fractures near surface 0.2-ft				
-1.1	1.1		EOB 1.10-ft. Asphalt interface 1.5-in. max size Ls CA, crushed Siliceous FA, natural No segregation Good consolidation Air entrained CTD #950619  Numerous reaction rims on CA, fractures are plentiful in some CA w/ reaction rims				

Figure 8. Log of core 950619


DRILLING LOG		DIVISION		INSTALLATION Louisiana Hwy Dept.		SHEET 1 OF 1 SHEETS	
1. PROJECT I-20 Cores				10. SIZE AND TYPE OF BIT 6"			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)			
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		L-9		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED UNDISTURBED	
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT				15. ELEVATION GROUND WATER		16. DATE HOLE STARTED COMPLETED	
7. THICKNESS OF OVERBURDEN				17. ELEVATION TOP OF HOLE			
8. DEPTH DRILLED INTO ROCK				18. TOTAL CORE RECOVERY FOR BORING			
9. TOTAL DEPTH OF HOLE 0.2 feet				19. SIGNATURE OF INSPECTOR			
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)	
0	0.0		Rubble				
-0.2	0.2		EOB Asphalt interface 1.5-in. max size Ls CA, crushed Siliceous FA, natural Air Entrained Reaction rims on CA observed Some CA are fractured CTD #950617				

Figure 9. Log of core 950617


DRILLING LOG		DIVISION		INSTALLATION		SHEET 1	
1. PROJECT		I-20 Cores		Louisiana Hwy Dept.		OF 1 SHEETS	
2. LOCATION (Coordinates or Station)				10. SIZE AND TYPE OF BIT 6"		11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)	
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		L-10		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED UNDISTURBED	
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE		VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT		15. ELEVATION GROUND WATER			
7. THICKNESS OF OVERBURDEN				16. DATE HOLE		STARTED COMPLETED	
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE			
9. TOTAL DEPTH OF HOLE 0.9 feet				18. TOTAL CORE RECOVERY FOR BORING			
				19. SIGNATURE OF INSPECTOR			
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)	
0	0.0		Finished top surface  Incipient fracture				
-0.9	0.9		EOB 0.9-ft Asphalt surface 1.5-in maximum size Ls CA, crushed (mostly 1-in and smaller) Siliceous FA, natural No segregation Good consolidation Air entrained CTD #950614  Numerous reaction rims on CA, some aggregate are fractured w/cracks extending into paste				

Figure 10. Log of core 950614

DRILLING LOG		DIVISION		INSTALLATION		SHEET 1 OF 1 SHEETS	
1. PROJECT I-20 Cores				10. SIZE AND TYPE OF BIT 6"			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)			
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		L-11		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED	UNDISTURBED
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT				15. ELEVATION GROUND WATER		16. DATE HOLE	
7. THICKNESS OF OVERBURDEN				17. ELEVATION TOP OF HOLE		STARTED	
8. DEPTH DRILLED INTO ROCK				18. TOTAL CORE RECOVERY FOR BORING		COMPLETED	
9. TOTAL DEPTH OF HOLE 1 feet				19. SIGNATURE OF INSPECTOR			
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)	
0	0.0		Fine surface Incipient fracture Incipient fracture				
-1	1.0		EOB 1.0-ft Asphalt interface 1-in maximum size Ls CA, crushed Siliceous FA, natural No segregation Good consolidation Air entrained CTD #950616  Numerous reaction rims on CA, some aggregate are fractured w/cracks extending into paste				

Figure 11. Log of core 950616


DRILLING LOG		DIVISION		INSTALLATION		SHEET 1 OF 1 SHEETS	
1. PROJECT I-20 Cores				10. SIZE AND TYPE OF BIT 6"			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)			
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		L-12		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED	UNDISTURBED
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT				15. ELEVATION GROUND WATER		16. DATE HOLE STARTED _____ COMPLETED _____	
7. THICKNESS OF OVERBURDEN				17. ELEVATION TOP OF HOLE			
8. DEPTH DRILLED INTO ROCK				18. TOTAL CORE RECOVERY FOR BORING			
9. TOTAL DEPTH OF HOLE 0.9 feet				19. SIGNATURE OF INSPECTOR			
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)	
0	0.0		Finished surface				
-0.9	0.9		EOB 0.9-ft Asphalt interface 1-in maximum size Ls CA, crushed Siliceous FA, natural No segregation Good consolidation Air Entrained CTD #950622  Few dark pieces of CA w/ reaction rims, mostly light color Ls pieces				

Figure 12. Log of core 950622


DRILLING LOG		DIVISION		INSTALLATION Louisiana Hwy Dept.		SHEET 1 OF 1 SHEETS	
1. PROJECT I-20 Cores				10. SIZE AND TYPE OF BIT 6"			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)			
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		L-13		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED	UNDISTURBED
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT				15. ELEVATION GROUND WATER			
7. THICKNESS OF OVERBURDEN				16. DATE HOLE		STARTED	COMPLETED
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE			
9. TOTAL DEPTH OF HOLE 0.9 feet				18. TOTAL CORE RECOVERY FOR BORING			
				19. SIGNATURE OF INSPECTOR			
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)	
0	0.0		<p>Tine surface Incipient fractures through out</p>				
-0.9	0.9		<p>EOB 0.9-ft New break 1.5-in maximum size Ls CA, crushed Siliceous FA, natural No segregation Good consolidation Air Entrained CTD #950618</p> <p>Numerous reaction rims on CA, some aggregates are fractured w/cracks extending into paste</p>				

Figure 13. Log of core 950618




DRILLING LOG		DIVISION		INSTALLATION		SHEET 1 OF 1 SHEETS	
1. PROJECT I-20 Cores				10. SIZE AND TYPE OF BIT 6"			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)			
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		L-14		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED UNDISTURBED	
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT				15. ELEVATION GROUND WATER			
7. THICKNESS OF OVERBURDEN				16. DATE HOLE STARTED COMPLETED			
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE			
9. TOTAL DEPTH OF HOLE 1 feet				18. TOTAL CORE RECOVERY FOR BORING			
				19. SIGNATURE OF INSPECTOR			
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)	
0	0.0		Tine surface				
-1	1.0		EOB 1.0-ft Asphalt interface 1-in maximum size Ls CA, crushed Siliceous FA, natural No segregation Good consolidation Air Entrained CTD #950621  Mostly light colored Ls CA Some incipient fractures near bottom of core associated w/ dark Ls particles w/reaction rims and fractures				

Figure 14. Log of core 950621

DRILLING LOG		DIVISION		INSTALLATION		SHEET 1 OF 1 SHEETS			
1. PROJECT I-20 Cores				10. SIZE AND TYPE OF BIT					
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM OR MSL)					
3. DRILLING AGENCY				12. MANUFACTURER'S DESIGNATION OF DRILL					
4. HOLE NO. (As shown on drawing title and file number)		L-15		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED	UNDISTURBED		
5. NAME OF DRILLER				14. TOTAL NUMBER CORE BOXES					
6. DIRECTION OF HOLE VERTICAL <input type="checkbox"/> INCLINED <input type="checkbox"/> _____ DEG. FROM VERT				15. ELEVATION GROUND WATER		16. DATE HOLE		STARTED	COMPLETED
7. THICKNESS OF OVERBURDEN				17. ELEVATION TOP OF HOLE					
8. DEPTH DRILLED INTO ROCK				18. TOTAL CORE RECOVERY FOR BORING					
9. TOTAL DEPTH OF HOLE 0.9 feet				19. SIGNATURE OF INSPECTOR					
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc. if significant)			
0	0.0		Finished surface						
-0.9	0.9		EOB 0.9-ft Asphalt interface 1.5-in maximum size Ls CA, crushed Siliceous FA, natural No segregation Good consolidation Air entrained CTD #950615  Some reaction rims on CA, mostly light colored CA particles, darker pieces tend to be small						

Figure 15. Log of core 950615.

Sample: 950623 LA File: JCT819.RD

13-SEP-95 13:09




Figure 16. X-ray diffraction pattern of reactive coarse-aggregate particle from core 950623




Figure 17. X-ray diffraction pattern of reactive coarse-aggregate particle from core 950628




Figure 18. X-ray diffraction pattern of reactive coarse-aggregate particle #A from core 950620

Sample: 950620B SLURRY + CON File: JCT816.HD 13-SEP-95 09:36




Figure 19. X-ray diffraction pattern of reactive coarse-aggregate particle #B from core 950620.




Figure 20. X-ray diffraction pattern of reactive coarse-aggregate particle from core 950617

Sample: 950616-A LA. File: JCT811.RD

11-SEP-95 09:57




Figure 21. X-ray diffraction pattern of reactive coarse-aggregate particle #A from core 950616






Figure 22. X-ray diffraction pattern of reactive coarse-aggregate particle #B from core 950616




Figure 23. X-ray diffraction pattern of non-expansive reactive coarse-aggregate particle #A from core 950621




Figure 24. X-ray diffraction pattern of non-expansive reactive coarse-aggregate particle #B from core 950621

Sample: 950621C LA File: JCT818.RD

13-SEP-95 11:27




Figure 25. X-ray diffraction pattern of expansive reactive coarse-aggregate particle #C from core 950621




Figure 26. X-ray diffraction pattern of highly reactive coarse-aggregate particle #B from limestone sample 950629 after treatment in sodium hydroxide




Figure 27. High-resolution X-ray elemental map of reactive coarse aggregate interface with paste. No migration of elements is observed

# Length Change

Sample 950629





Figure 28. Rock cylinder test shows two specimens (B1 and B2) from sample 950629 expanding quickly while others did not expand. Cores were taken from five particles (A, B, C, D, and E) representing varieties of rock

# Length Change

## Sample 950630




Figure 29. Rock cylinder test shows two specimens (B1 and B2) from sample 950630 expanding while others did not expand. Cores were taken from five particles (A, B, C, D, and E) representing varieties of rock



**Table 1**  
**Information of I-20 Cores and Aggregate Samples Near Monroe, LA**

Item	CTD Serial No.	DOTD Core No.	Location	Degree of Cracking
Westbound lane west of Monroe, showing little distress; log miles begin at Lincoln PL westward				
1	950623	1	Log mile 1.5, shoulder	very fine, hairline
2	950624	2	Log mile 3.1, outside lane outside wheel path	hairline
Eastbound lane west of Monroe, showing major distress with cracks at joints raveling; log mile begins at LA 145 overpass eastward				
3	960625	3	Log mile 1.5, outside lane, edge	surface cracks
4	950626	4	Log mile 3.38, outside lane outside wheel path	cracks near joint
5	950627	5	Log mile 7, outside lane outside wheel path	no cracks surface
6	950628	6	Log mile 4.7, outside lane outside wheel path	heavy cracking
Aggregates used in construction of I-20				
7	950629	limestone	TL James (451-05060, I-20 west of Monroe) Dravo, Smithland, KY	
8	950630	limestone	Bud Hale (451-07-29, I-20 east of Monroe), Denton Contractor, Dravo, Smithland, KY	
9	950631	sand	Denton Contractor (451-07-29 & 28)	
Eastbound lane east of Monroe, showing major distress; repairs required to prevent raveling; log mile begins at Delhi intersection mile post 153				
10	950620	7	Log mile 1.58 outside lane outside wheel path	cracking
11	950619	8	Log mile 1.7 outside lane outside wheel path	cracking
12	960617	9	Log mile 1.79 outside lane outside wheel path	heavy cracking
13	950614	10	Log mile 1.79 shoulder	cracked
14	950616	11	Log mile 2.38 outside lane	light cracking
15	950622	12	Log mile 2.38 shoulder	no cracks
16	950618	13	Log mile 3.7 edge	heavy cracking
Westbound lane east of Monroe showing little distress; log mile begins at mile post 157 westward				
17	950621	14	Log mile 0.10 outside lane outside wheel path	very light crack
18	950615	15	Log mile 0.10 shoulder	no crack

**Table 2  
Evaluation Matrix**

Item	CTD Serial No.	DOTD Core No.	Pulse Velocity	Petrographic Examination	X-ray Diffraction	Expansion	Cement Content
1	950623	1	✓	✓	✓		✓
2	950624	2	✓				
3	950625	3		✓		✓	
4	950626	4	✓	✓		✓	✓
5	950627	5	✓	✓			
6	950628	6	✓	✓	✓		
7	950629	limestone		✓			
8	950630	limestone		✓			
9	950631	sand					
10	950620	7	✓	✓	✓		
11	950619	8	✓	✓			
12	950617	9		✓			✓
13	950614	10	✓				
14	950616	11	✓	✓	✓		
15	950622	12	✓	✓			
16	950621	13		✓			
17	950621	14	✓	✓	✓		✓
18	950615	15	✓	✓			

**Table 3**  
**Pulse Velocity Data**

Specimen ID	Length, in. (mm)	Diameter, in. (mm)	Time, $\mu$ sec	Velocity, ft/sec (N)
950623	10.625 (270)	6 (152)	59.0	15,000 (66,723)
950626 <sup>1</sup>	12.000 (305)	6 (152)	94.3	10,600 (47,151)
950627	12.063 (306)	6 (152)	69.1	14,550 (64,721)
950628 <sup>1</sup>	12.313 (313)	6 (152)	135.7	7,560 (33,629)
950620	10.875 (276)	6 (152)	77.8	11,650 (51,821)
950614	10.625 (270)	6 (152)	73.7	12,010 (53,423)
950619	10.625 (270)	6 (152)	74.6	11,870 (52,800)
950616	10.625 (270)	6 (152)	67.4	13,140 (58,800)
950622	9.688 (246)	6 (152)	53.8	15,040 (66,901)
950621	10.938 (278)	6 (152)	58.9	15,470 (68,814)
950615	9.625 (244)	6 (152)	53.0	15,130 (67,302)

<sup>1</sup> Specimens were cracked.

**Table 4**  
**Result of Cement-Content Analysis**

Property	Sample No.			
	950623	950626	950617	950621
Combined Water, %	2.32	1.69	2.36	2.25
Insoluble Residue, %	86.20	87.41	86.33	81.53
Free Water, %	4.67	4.13	5.28	3.62
Density, lb/ft <sup>3</sup>	148.6 (2,380)	149.2 (2,390)	148.6 (2,380)	145.5 (2,331)
Cement Content, lb/yd <sup>3</sup>	438 (260)	420 (249)	430 (255)	613 (364)

# **Appendix A**

## **Photographs of Concrete**

### **Sections**

---




Figure A1. Sample 950623 shows reactive particles 1 and 2 near top surface associated with cracks. The top and bottom samples are 6 in. (152 mm) left to right





Figure A2. Sample 950623 shows a random crack pattern with cracks propagating from central reactive coarse aggregate. Other reactive aggregate particles are also present. Top sample is 6 in. (152 mm) left to right




Figure A3a. Sample 950626 shows some interior cracking in the concrete and a few small reactive particles with reaction rims. The sample is 6 in. (152 mm) left to right





Figure A3b. Sample 950626 shows reactive aggregate particles at bottom of core. The sample is 6 in. (152 mm) left to right






Figure A4. Sample 950627 shows no cracks. The sample is 6 in. (152 mm) left to right

A6



Figure A5a. Sample 950628 shows severe cracking in near surface concrete. Epoxy resin fills the cracks. Top sample is 6 in. (152 mm) left to right




Figure A5b. Sample 950628 shows cracking is continuous throughout the entire length of core. Both samples are 6 in. (152 mm) left to right




Figure A6. Sample 950620 shows aggregate reaction at the base of the core. Cracks are visible along the reaction rim. Top sample is 6 in. (152 mm) left to right



Figure A7. Sample 950619 shows random crack pattern with cracks propagating from two central reactive coarse-aggregate particles and cracking in bottom end of sample. Top and bottom samples are 6 in. (152 mm) left to right





Figure A8. Sample 950617 shows a reactive aggregate particle and cracking of rim zone. Diameter core boring is 11 mm




Figure A9a. Sample 950616 shows a central vertical near-surface crack and some incipient cracks associated with aggregate particle A. Samples on left are 6 in. (152 mm) left to right





Figure A9b. Sample 950616 shows bottom of core and crack associated with reactive aggregate particle. Top sample is 6 in. (152 mm) left to right







Figure A10. Sample 950622 shows intact concrete with mostly light-colored aggregate particles. Bottom slice of core contains hairline crack. Both samples are 6 in. (152 mm) left to right




Figure A11. Sample 950618 shows random crack pattern with cracks propagating from central reactive coarse-aggregate particle. Other reactive particles are also evident. Top sample is 6 in. (152 mm) left to right




Figure A12. Sample 960621 shows aggregate particles A, B, and C. A is non-expansive, B is non-expansive, and C is expansive. Top sample is 6 in. (152 mm) left to right





Figure A13. Sample 950615 shows some non-expansive reactive aggregate particles. Top sample is 6 in. (152 mm) left to right

# **Appendix B U.S. Army Corps of Engineers Evaluation Data**

---

Issued Sept 1971

STATE <b>Ky.</b>	INDEX NO <b>29</b>	AGGREGATE DATA SHEET	TESTED BY: <b>ORD Lab.</b>
LAT. <b>370</b>	LONG. <b>880</b>	DATE <b>November 1970</b>	
LAB. SYMBOL NO <b>7196-71100</b>	TYPE OF MATERIAL: <b>Crushed Limestone</b>		
LOCAT ON. <b>Smithland</b>			
PRODUCER <b>Three Rivers Rock Co.</b>			
SAMPLED BY <b>Nashville District C. of E. Personnel</b>			
TESTED FOR <b>Smithland L&amp;D</b>			
PROCESSING BEFORE TESTING.			
GEOLOGICAL FORMATION AND AGE			
GRADING (CRD-C 103) (CUM. % PASSING)		TEST RESULTS	
SIEVE	3-6" 1 1/2-3" 3/4-1 1/2" #4-2" FINE AGG.	3-6"	1 1/2-3"
6" N		0.66	2.70
5" N	84.6	0.80	0.77
4" N	41.5	1.22	0.28
3" N	4.6	1.99	
2 1/2" N	51.4		
2" N	12.5		
1 1/2" N	1.4		
1" N	58.1		
3/4" N	14.2		
1/2" N	4.2		
3/8" N	269.8		
NO. 4	2.7		
NO. 8	40.8		
NO. 16	1.3		
NO. 30	14.8		
NO. 50	82.6		
NO. 100	71.6		
NO. 200	46.4		
- 200 #	29.5		
F.M. (b)	17.9		
(a) CRD-C 105 (b) CRD-C 104		MORTAR:	
MORTAR-BAR EXPANSION AT 100F, % (CRD-C 123):		FINE AGGREGATE	
LOW-ALK. CEMENT: % Na <sub>2</sub> O EQUIVALENT:		COARSE AGGREGATE	
HIGH-ALK. CEMENT: % Na <sub>2</sub> O EQUIVALENT:		3 MO. 6 MO. 9 MO. 12 MO. 3 MO. 6 MO. 9 MO. 12 MO.	
SOUNDNESS IN CONCRETE (CRD-C 40, 114):		F & T HW-CQ HD-CW	
FINE AGG. <b>Newtown</b> COARSE AGG. <b>Three Rivers</b>		DFE <sub>300</sub> <b>79.0</b>	
FINE AGG. <b>Three Rivers</b> COARSE AGG. <b>Melvin</b>		DFE <sub>300</sub> <b>81.9</b>	
PETROGRAPHIC DATA (CRD-C 127):			
Sample consist of varying amounts of dense, hard, particles of Oolitic Limestone, Fossiliferous Limestone, and Dolomitic Limestone. About 1% to 2% of each sample consists of moderately hard to moderately soft, moderately tough Argillaceous Dolomitic Limestone. A trace amount of the 3" max. size aggregate consists of potentially reactive Chert.			
REMARKS:			

WES FORM 726 JAN 1951

Issued Sept 1975

STATE <b>Ky.</b>	INDEX NO <b>29 (supp)</b>	AGGREGATE DATA SHEET	TESTED BY <b>ORDED-FL</b>
LAT <b>37°</b>	LONG <b>88°</b>		DATE
LAB SYMBOL NO <b>75071</b>		TYPE OF MATERIAL <b>Crushed Coarse Aggregate</b>	
LOCATION <b>Smithland, Ky.</b>		<b>(1½"-3")</b>	
PRODUCER <b>Three Rivers Quarry</b>			
SAMPLED BY <b>Nashville District CofE personnel</b>			
TESTED FOR <b>Elementary Acceptance Tests for Smithland Locks &amp; Dam Proj.</b>			
USED AT			
PROCESSING BEFORE TESTING			
GEOLOGICAL FORMATION AND AGE			

GRADING (CRD-C 103) (CLM - PASSING)						TEST RESULTS				
SIEVE	3/4"	1/2"	3/8"	NO. 20	FINE AGG	3-6"	1-3"	1-1/2"	1/4-1"	FINE AGG
										2.62
6 IN.										2.33
5 IN.										
4 IN.										
3 IN.										-0-
2 1/2 IN.										
2 IN.										16.4*
1 1/2 IN.										35.7
1 IN.										
3/4 IN.										
3/8 IN.										
NO. 4										
NO. 8										
NO. 16										
NO. 30										
NO. 50										
NO. 100										
NO. 200										
-200'01										
F.M. 161										

MORTAR		FINE AGGREGATE				COARSE AGGREGATE			
MORTAR-BAR EXPANSION AT 100F. ° (CRD-C 123)		2 MO.	6 MO.	9 MO.	12 MO.	3 MO.	6 MO.	9 MO.	12 MO.
LOW-ALK. CEMENT % H <sub>2</sub> O EQUIVALENT									
HIGH-ALK. CEMENT % H <sub>2</sub> O EQUIVALENT									
SOUNDNESS IN CONCRETE (CRD-C 40, 114)						F&T	HW-CD	HD-CW	
FINE AGG. <b>Lab. Std.</b>						DFE <sub>100</sub>	73%		
FINE AGG.						DFE <sub>100</sub>			

PETROGRAPHIC DATA (CRD-C 127)  
 Material consists of a composite of stone from Ledges 7A, 7B, and 7C of this quarry.

REMARKS  
 \*MgSO<sub>4</sub> grading as per CRD C-3 100% passing 1½" agg.

ENG FORM 6011-R  
 MAR 1964

1988

STATE: KY	INDEX NO.: 29 Suppl 5	AGGREGATE DATA SHEET	TESTED BY: USAE WES															
LAT.: 37	LONG.: 88		DATE: March, 1986															
LAB SYMBOL NO.: VICKS-33 MG-8		TYPE OF MATERIAL: Manufactured Gravel																
LOCATION: 7 miles NE of Smithland, KY, on Hwy 60																		
PRODUCER: Three Rivers Rock Co., Smithland, KY																		
SAMPLED BY: Vicksburg District																		
TESTED FOR: Yazoo Backwater Pumping Plant																		
USED AT:																		
PROCESSING BEFORE TESTING:																		
GEOLOGICAL FORMATION AND AGE:																		
GRADING (CRD-C 103) (CUM. % PASSING):																		
SIEVE	GRADING (CRD-C 103) (CUM. % PASSING):				FINE AGG.	TEST RESULTS					3-6"	1 1/2"	1-1/2"	#4-1/2"	FINE AGG.			
	3-6"	1 1/2"	1-1/2"	#4-1/2"		BULK SP. GR. S.S.D. (CRD-C 107, 108)	ABSORPTION, % (CRD-C 107, 108)	ORGANIC IMPURITIES, FIG. NO. (CRD-C 121)	SOFT PARTICLES, % (CRD-C 130)	% LIGHTER THAN SP GR. (CRD-C 122)						% FLAT AND ELONGATED (CRD-C 119, 120)	WT AV % LOSS, 5 CYC N <sub>2</sub> SO <sub>4</sub> (CRD-C 115)	L.A. ABRASION LOSS, % (CRD-C 117, 145) GRADING <u>A</u>
6 IN.																		
5 IN.																		
4 IN.																		
3 IN.																		
2 1/2 IN.																		
2 IN.																		
1 1/2 IN.			100															
1 IN.			22															
3/4 IN.			2															
1/2 IN.			1															
3/8 IN.			1															
NO. 4			1															
NO. 8																		
NO. 16																		
NO. 30																		
NO. 50																		
NO. 100																		
NO. 200																		
-200 (a)																		
F.M. (b)																		
MORTAR-BAR EXPANSION AT 100F, % (CRD-C 123):	FINE AGGREGATE				COARSE AGGREGATE													
	2 MO.	6 MO.	9 MO.	12 MO.	3 MO.	6 MO.	9 MO.	12 MO.										
LOW-ALK. CEMENT: % N <sub>2</sub> O EQUIVALENT:																		
HIGH-ALK. CEMENT: % N <sub>2</sub> O EQUIVALENT:																		
FINE AGG.	COARSE AGG:	DFE <sub>300</sub>	F&T	HW-CD	MO-CW													
FINE AGG.	COARSE AGG:	DFE <sub>300</sub>																

CNC FORM 6011-R

Encl 17 to Encl 1

B4



1988

STATE: KY	INDEX NO.: 29 Suppl 3	RIPRAP	TESTED BY: SAD Laboratory
LAT.: 37	LONG.: 88	DATA SHEET	DATE: 14 July 1986
LAB SYMBOL NO.: 57/3013	TYPE OF MATERIAL:		
LOCATION: 5.2 miles E. of Smithland KY on US 60			
PRODUCER: Three Rivers Rock Quarry			
SAMPLED BY: Sanders (CESAM-EN-FG)			
TESTED FOR: Oliver L&D Replacement			
USED AT:			
PROCESSING BEFORE TESTING:			
GEOLOGICAL FORMATION AND AGE:			
		<b>TEST METHOD</b>	<b>RESULTS</b>
		BULK SPECIFIC GRAVITY, SSD, (CRD-C 107)	
		ABSORPTION, % (CRD-C 107)	
		WT. AV. % LOSS, 5 CYC. MGSO <sub>4</sub> (CRD-C 137)	
		L.A. ABRASION LOSS, % (CRD C 145 OR RTH-115), GRADING 1.	
		UNIT WT., LB/CU FT (CRD-C 107)	
		WETTING AND DRYING, %, 35 CYCLES	
		FREEZE AND THAW, % (CRD-C 144) 20 CYCLES Avg. of 11 pieces	1.5
		EXPANSION IN ETHYLENE, GLYCOL (CRD-C 148)	
<b>PETROGRAPHIC DATA (CRD-C 127)</b>			
<b>REMARKS</b>			

ENG FORM 6012-R, Jul 81

(ER 1110-1-2005)

(Prepared DAEN-CWE-DC)

1988

STATE: KY	INDEX NO.: 29 Suppl 4	RIPRAP	TESTED BY: USAEWES
LAT.: 37	LONG.: 88	DATA SHEET	DATE: March 1986
LAB SYMBOL NO.: VICKS 33 RR-8		TYPE OF MATERIAL: Limestone	
LOCATION: 7 miles NE of Smithland, KY on Hwy 60			
PRODUCER: Three Rivers Rock Co., Smithland, KY			
SAMPLED BY: Vicksburg District			
TESTED FOR: Yazoo Backwater Pumping Plant			
USED AT:			
PROCESSING BEFORE TESTING:			
GEOLOGICAL FORMATION AND AGE:			
TEST METHOD			RESULTS
BULK SPECIFIC GRAVITY, SSD, (CRD-C 107)			2.73
ABSORPTION, % (CRD-C 107)			0
WT. AV. % LOSS, 5 CYC. $MgSO_4$ (CRD-C 137)			
L.A. ABRASION LOSS, % (CRD-C 145 OR RTH-115), GRADING 1.			27.0
UNIT WT., LB/CU FT (CRD-C 107)			170.1
WETTING AND DRYING, %, 35 CYCLES			0.7
FREEZE AND THAW, % (CRD-C 144) 20 CYCLES			20.7
EXPANSION IN ETHYLENE GLYCOL (CRD-C 148)			
<b>PETROGRAPHIC DATA (CRD-C 127)</b>			
<p>This rock was a light olive gray, fine-grained limestone. The rock is slightly fossiliferous, with bedding planes 0.01 ft apart. The rock is composed of calcite, dolomite, quartz, and kaolinite. This rock should perform adequately for use as riprap.</p>			
<b>REMARKS</b>			

ENG FORM 6012-R, Jul 81

(ER 1110-1-2005)

(Proponent DAEN-CWE-OC)  
Encl 26 to Encl 1

B6

Issued October 1982

STATE: <b>KY</b>	INDEX NO.: <b>29 (Suppl 2)</b>	RIPRAP DATA SHEET	TESTED BY: <b>USAEWES</b>
LAT.: <b>37</b>	LONG.: <b>88</b>		DATE: <b>March 1979</b>
LAP SYMBOL NO.: <b>NO-57 G-136</b>	TYPE OF MATERIAL: <b>Riprap</b>		
LOCATION: <b>1 mile east of Hwy 60 and 4.8 miles north of intersection of Hwys 60 and 70</b>			
PRODUCER: <b>Three Rivers Rock Co., Box 218, Smithland, KY 42081</b>			
SAMPLED BY: <b>Dames &amp; Moore</b>			
TESTED FOR: <b>New Orleans District</b>			
USED AT:			
PROCESSING BEFORE TESTING: <b>As required for testing</b>			
GEOLOGICAL FORMATION AND AGE: <b>Ste. Genevieve Fm. - Meramec Group - Mississippian Age</b>			

TEST RESULTS

<u>TEST METHOD</u>	<u>RESULTS</u>
Bulk Specific Gravity, SSD, (CRD-C 107)	<u>2.69</u>
Absorption, % (CRD-C 107)	<u>0.3</u>
Wt. Av. % Loss, 5 Cyc. MgSO <sub>4</sub> (CRD-C 137)	<u>0.0</u>
L.A. Abrasion Loss, % (CRD-C 145 or RTH-115), Grading 1.	<u>22.8</u>
Unit Wt., lb/cu ft (CRD-C 107)	<u>167.6</u>
Wetting and Drying, %, 35 cycles	<u>6.1</u>
Freeze and Thaw, % (CRD-C 144) 20 cycles	<u>0.3</u>
Expansion in Ethylene, Glycol (CRD-C 148)	<u>--</u>

PETROGRAPHIC DATA (CRD-C 127)

NO-57 G-136 (Three Rivers Rock Co.). All three pieces were medium light gray coarse-grained dolomitic limestone with a minor amount of quartz; two of the three pieces were oolitic. Chert was present as layers between beds. The rock was not substantially affected by freezing and thawing.

REMARKS

New Orleans Sample No. LIV-1-1A, 1B, 1C.

1989

STATE: KY	INDEX NO.: 29 (SUPPL 6)	RIPRAP	TESTED BY: USAEWES
LAT.: 37	LONG.: 88	DATA SHEET	DATE: Jul 88
LAB SYMBOL NO.: LMK-4 RR-16, RR-17, RR-18		TYPE OF MATERIAL: Limestone	
LOCATION: Three River Quarry Bench No. 2, 3, and 4, St. Genevieve Formation Smithland, KY			
PRODUCER: Dravco Basic Materials Co., Inc., Smithland, KY			
SAMPLED BY: Vicksburg District			
TESTED FOR: Lock and Dam No. 4 and No. 5, Red River			
USED AT:			
PROCESSING BEFORE TESTING:			
GEOLOGICAL FORMATION AND AGE:			
		RR-17	RR-16
	TEST METHOD	RESULTS	
	BULK SPECIFIC GRAVITY, SSD, (CRD-C 107)	2.69	2.71
	ABSORPTION, % (CRD-C 107)	0.6	0.7
	WT. AV. % LOSS, 5 CYC. MGSO <sub>4</sub> (CRD-C 137)		
	L.A. ABRASION LOSS, % (CRD-C 145 OR RTH-115), GRADING 1.		
	UNIT WT., LB/CU FT (CRD-C 107)	168	169
	WETTING AND DRYING, %, 35 CYCLES	0.1	0.1
	FREEZE AND THAW, % (CRD-C 144) 20 CYCLES	13.7	3.9
	EXPANSION IN ETHYLENE GLYCOL (CRD-C 148)		
<b>PETROGRAPHIC DATA (CRD-C 127)</b>			
<p>These three samples represent benches 2, 3, and 4 of the same quarry. All three are light olive gray to medium dark gray dolomitic limestones from the St. Genevieve Formation. The rocks are very fine-grained (&lt;0.1 mm), moderately hard to hard, slightly weathered, and massive. Samples LMK-4 RR-16 and RR-17 consist of calcite, dolomite, and quartz. Sample RR-16 contains a minor amount of plagioclase feldspar. RR-18 consists only of dolomite and quartz.</p>			
<b>REMARKS</b>			
<p>These rocks are similar to material previously tested. No physical tests were performed on LMK-4 RR-18; however, petrographic analyses on LMK-4 RR-16, RR-17, and RR-18 do not indicate any specific features that would preclude their use as riprap.</p>			

ENG FORM 6012-R, Jul 81

(ER 1110-1-2005)

(Prepared by DAEN-CWE-DC)

Issued Sept. 1973

STATE Ky.	INDEX NO. 30	AGGREGATE DATA SHEET	TESTED BY: ORDL
LAT. 37	LONG 88		DATE May 1972
LAB SYMBOL NO. 72125 & 72127		TYPE OF MATERIAL. Blending Sand	
LOCATION: Near Ledbetter, off US 60 on bluff overlooking Ohio River - Dubuque Ridge			
PRODUCER Dravo-Groves-Newberg, Contractor			
SAMPLED BY: Nashville District C. of E. Personnel			
TESTED FOR Smithland Locks & Dam			
USED AT			
PROCESSING BEFORE TESTING			
GEOLOGICAL FORMATION AND AGE			
GRADING (CRD-C 103) (CUM. % PASSING)		TEST RESULTS	
SIEVE	3-6" 1 1/2-3 3/4-1 1/2 3/8-1/2 FINE AGG. 72125 72127	3-6" 1 1/2-3 3/4-1 1/2 #4-1" FINE AGG. 72125 72127	
5 IN.		BULK SP GR. S.S.C. (CRD-C 107, 108)	2.53 2.54
5 IN.		ABSORPTION, % (CRD-C 107, 108)	1.2 1.5
4 IN.		ORGANIC IMPURITIES, FIG. NO. (CRD-C 121)	1 1
3 IN.		SOFT PARTICLES, % (CRD-C 130)	
2 1/2 IN.		% LIGHTER THAN SP GR. (CRD-C 122)	
2 IN.		% FLAT AND ELONGATED (CRD-C 119, 120)	
1 1/2 IN.		WT AV. LOSS, 5 CYC M <sub>2</sub> SO <sub>4</sub> (CRD-C 115)	
1 IN.		L.A. ABRASION LOSS, % (CRD-C 117, 145) GRADING	
3/4 IN.		UNIT WT, LB/CU FT (CRD-C 106)	
3/8 IN.		FRIABLE PARTICLES, % (CRD-C 142)	
3/16 IN.		SPEC HEAT, BTU/LB DEG F. (CRD-C 124)	
NO. 4		REACTIVITY WITH NaOH (CRD-C 128)	SC, MM/L RC, MM/L
NO. 8	99.7 98.1		
NO. 16	99.6 96.5	MORTAR-MAKING PROPERTIES (CRD-C 116)	
NO. 30	99.4 94.7	TYPE _____ CEMENT, RATIO: _____ DAYS, _____ DAYS, _____	
NO. 50	97.9 92.1	LINEAR THERMAL EXPANSION MILLIONTHS/DEG F. (CRD-C 125, 126)	
NO. 100	70.1 54.1	ROCK TYPE PARALLEL ACROSS ON AVERAGE	
NO. 200	22.2 13.8		
-200 #			
F.M. #			
a) CRD-C 105 b) CRD-C 104		MORTAR:	
MORTAR-BAR EXPANSION AT 100F, % (CRD-C 123)		FINE AGGREGATE COARSE AGGREGATE	
		2 MO. 6 MO. 9 MO. 12 MO. 3 MO. 6 MO. 9 MO. 12 MO.	
LOW-ALK. CEMENT: % NO <sub>2</sub> O EQUIVALENT:			
HIGH-ALK. CEMENT: % NO <sub>2</sub> O EQUIVALENT:			
SOUNDNESS IN CONCRETE (CRD-C 40, 114):		F&T	HW-CO HD-CW
FINE AGG. COARSE AGG. DFE <sub>100</sub>			
FINE AGG. COARSE AGG. DFE <sub>300</sub>			
PETROGRAPHIC DATA (CRD-C 127)		#72125	#72127
Quartz		85.4%	67.5%
Siltstone		2.4%	1.1%
Igneous Grains		1.4%	0.6%
Clay Lumps		9.7%	30.4%
Mica		1.0%	0.4%
Organic Material		0.1%	trace
REMARKS			
Sample #72125 is a bulk sample while #72127 is an auger sample through the entire stratum.			

DD FORM 501 5-66

Issued Sept. 1973

STATE <b>Ky.</b>	INDEX NO.: <b>31</b>	AGGREGATE DATA SHEET	TESTED BY <b>ORDL</b>									
LAT. <b>37</b>	LONG. <b>88</b>		DATE <b>May '72</b>									
LAB SYMBOL NO. <b>72126</b>	TYPE OF MATERIAL: <b>Blending Sand</b>											
LOCATION: <b>Dubuque Pit near Ledbetter off of U.S.60 overlooking the Ohio River</b>												
PRODUCER <b>Dravo-Groves-Newberg, Contractor</b>												
SAMPLED BY: <b>Nashville Dist. C.ofE. personnel</b>												
TESTED FOR: <b>Smithland L&amp;D</b>												
USED AT: <b>Barkley Dam</b>												
PROCESSING BEFORE TESTING:												
GEOLOGICAL FORMATION AND AGE:												
GRADING (CRD-C 103) (CUM. % PASSING):		TEST RESULTS										
SIEVE	3-6"	1 1/2"	3/4"	2-1/2"	1/4"	FINE AGG.						
							BULK SP GR, S.S.D. (CRD-C 107, 108)				<b>2.60</b>	
2 IN.							ABSORPTION, % (CRD-C 107, 108)				<b>0.7</b>	
5 IN.							ORGANIC IMPURITIES, FIG. NO. (CRD-C 121)				<b>1</b>	
4 IN.							SOFT PARTICLES, % (CRD-C 130)					
3 IN.							% LIGHTER THAN SP GR (CRD-C 122)					
2 1/2 IN.							% FLAT AND ELONGATED (CRD-C 119, 120)					
2 IN.							WT AV. LOSS, 5 CYC M <sub>50</sub> (CRD-C 115)					
1 1/2 IN.							L.A. ABRASION LOSS, % (CRD-C 117, 145) GRADING					
1 IN.							UNIT WT, LB/CU FT (CRD-C 106)					
3/4 IN.							FRIABLE PARTICLES, % (CRD-C 142)					
1/2 IN.							SPEC HEAT, BTU/LB/DEG F. (CRD-C 124)					
NO. 4							REACTIVITY WITH NaOH	SC, MM L:				
NO. 8							(CRD-C 128):	RC, MM L:				
NO. 16							MORTAR-MAKING PROPERTIES (CRD-C 115)					
NO. 30							TYPE _____ CEMENT, RATIO: _____ DAYS _____ DAYS _____ DAYS					
NO. 50							90.4	LINEAR THERMAL EXPANSION MILLIONTHS/DEG F. (CRD-C 125, 126):				
NO. 100							27.7	ROCK TYPE	PARALLEL	ACROSS	ON	AVERAGE
NO. 200							2.3					
-200 <sup>a</sup>												
F.V. <sup>b</sup>												
<sup>a</sup> CRD-C 105		<sup>b</sup> CRD-C 104		MORTAR:								
MORTAR-BAR EXPANSION AT 100F. (CRD-C 123):				FINE AGGREGATE				COARSE AGGREGATE				
				2 MO.	6 MO.	9 MO.	12 MO.	3 MO.	6 MO.	9 MO.	12 MO.	
LOW-ALK. CEMENT. % Na <sub>2</sub> O EQUIVALENT:												
HIGH-ALK. CEMENT. % Na <sub>2</sub> O EQUIVALENT:												
SOUNDNESS IN CONCRETE (CRD-C 40, 114):												
FINE AGG.				COARSE AGG.				DFE <sub>300</sub>				
FINE AGG.				COARSE AGG.				DFE <sub>300</sub>				
PETROGRAPHIC DATA (CRD-C 127):												
Quartz - - - - - 86%												
Siltstone - - - - - 8%												
Igneous Rock Fragments - - - 4%												
Weathered Rock Fragments -- trace												
Mica - - - - - 2%												
REMARKS												

# REPORT DOCUMENTATION PAGE

Form Approved  
OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

<b>1.AGENCY USE ONLY (Leave blank)</b>		<b>2.REPORT DATE</b> January 1998	<b>3.REPORT TYPE AND DATES COVERED</b> Final report	
<b>4.TITLE AND SUBTITLE</b> Investigation of Concrete from I-20 Near Monroe, Louisiana			<b>5.FUNDING NUMBERS</b>	
<b>6.AUTHOR(S)</b> G. Sam Wong				
<b>7.PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)</b> U.S. Army Engineer Waterways Experiment Station 3909 Halls Ferry Road, Vicksburg, MS 39180-6199			<b>8.PERFORMING ORGANIZATION REPORT NUMBER</b> Miscellaneous Paper SL-98-1	
<b>9.SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)</b> U.S. Army Corps of Engineers Washington, DC 20314-1000			<b>10.SPONSORING/MONITORING AGENCY REPORT NUMBER</b>	
<b>11.SUPPLEMENTARY NOTES</b> Available from National Technical Information Service, 5285 Port Royal Road, Springfield, VA 22161.				
<b>12a.DISTRIBUTION/AVAILABILITY STATEMENT</b> Approved for public release; distribution is unlimited.			<b>12b.DISTRIBUTION CODE</b>	
<b>13.ABSTRACT (Maximum 200 words)</b> <p>This report covers an investigation conducted in 1994-1995 to determine the probable cause of concrete pavement deterioration in certain lanes of I-20 east and west of Monroe, LA. The investigation was conducted by the U.S. Army Corps of Engineers Waterways Experiment Station at the request of the Louisiana Department of Transportation. Cores taken from distressed and non-distressed areas from different sections of the roadway were evaluated to determine the following: (a) the role of alkali-carbonate-rock reaction; (b) the role of alkali-silica reaction; (c) the contribution of freezing-and-thawing action to the deterioration; and (d) the contribution of fresh concrete properties and construction practices to the deterioration. The report includes the results of these analyses as well as conclusions and recommendations.</p>				
<b>14.SUBJECT TERMS</b> Concrete Concrete pavement			<b>15.NUMBER OF PAGES</b> 80	
			<b>16.PRICE CODE</b>	
<b>17.SECURITY CLASSIFICATION OF REPORT</b> UNCLASSIFIED	<b>18.SECURITY CLASSIFICATION OF THIS PAGE</b> UNCLASSIFIED	<b>19.SECURITY CLASSIFICATION OF ABSTRACT</b>	<b>20.LIMITATION OF ABSTRACT</b>	