





February 2001

Little Goose Dam Radial Gate Inspection and Testing



US Army Corps of Engineers, Walla Walla District



REPORT DOCUMENTATION PAGE

Form Approved
OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

1. AGENCY USE ONLY (Leave blank)	2. REPORT DATE February 2001	3. REPORT TYPE AND DATES COVERED Inspection
----------------------------------	---------------------------------	--

4. TITLE AND SUBTITLE Little Goose Dam Radial Gate Inspection and Testing	5. FUNDING NUMBERS
--	--------------------

6. AUTHOR(S) HDR Engineering Inc. Wayne Edwards, P.E. Sam Planck, P.E.	
---	--

7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) HDR Engineering Inc. 505 14th Street Suite 940 Oakland, CA. 94612	8. PERFORMING ORGANIZATION REPORT NUMBER
---	--

9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) U.S. Army Corps of Engineers Northwestern Division Walla Walla District 201 North 3rd Avenue Walla Walla, WA. 99362-1876	10. SPONSORING/MONITORING AGENCY REPORT NUMBER
---	--

11. SUPPLEMENTARY NOTES None

12a. DISTRIBUTION AVAILABILITY STATEMENT Distribution Statement A. Approved for public release; distribution is unlimited.	12b. DISTRIBUTION CODE
---	------------------------

13. ABSTRACT (Maximum 200 words) This report is an evaluation of the overall condition of the spillway tainter gates at Little Goose Lock and Dam, Snake River Washington.

20030313 194

14. SUBJECT TERMS spillway, tainter, gates, inspection, testing	15. NUMBER OF PAGES 240
	16. PRICE CODE

17. SECURITY CLASSIFICATION OF REPORT Unclassified	18. SECURITY CLASSIFICATION OF THIS PAGE Unclassified	19. SECURITY CLASSIFICATION OF ABSTRACT Unclassified	20. LIMITATION OF ABSTRACT UL
---	--	---	----------------------------------

AQ M03-05-1168

LITTLE GOOSE DAM

Contents

LITTLE GOOSE DAM RADIAL GATE INSPECTION AND TESTING.....	1 ✓
INTRODUCTION.....	1 ✓
Purpose	1 ✓
Scope of Investigation	1 ✓
Limitations	1 ✓
PROJECT BACKGROUND.....	2 ✓
Project Description	2 ✓
Gate Design and Construction	2 ✓
Gate Operation.....	3 ✓
Gate Maintenance	5 ✓
Inspection.....	5 ✓
General.....	5 ✓
Procedures	6 ✓
Member Designations	9 ✓
General Inspection Observations	9 ✓
Radial Gate – Operation, Testing and Measurements	22 ✓
Individual Gate Inspection Observations.....	25 ✓
Hoists – Operation, Testing and Measurements.....	31 ✓
RECOMMENDATIONS.....	35 ✓
REFERENCES.....	36 ✓
APPENDICES	
A - Gate Inspection Sheets ✓	
B - Hoist Inspection Sheets ✓	
C - Inspection Photographs ✓	
D - As-built Drawings ✓	

LITTLE GOOSE DAM RADIAL GATE INSPECTION AND TESTING

INTRODUCTION

Purpose

The Corps of Engineers, Walla Walla District, requires a comprehensive evaluation of the radial gates at Little Goose Dam. The District retained HDR Engineering, Inc. to perform inspection and testing of the radial gates through Task Order No. 5 under Contract DACW68-00-D-0001. The task order scope of work includes review of project information, an initial meeting and inspection, comprehensive field inspection of the radial gates, testing of gate hoist machinery, recording trunnion movement, and preparation of a report.

Scope of Investigation

The scope of this investigation includes:

- Review of design, construction, maintenance and operations information provided by the District.
- Hands-on visual inspection of accessible upstream and downstream portions of eight radial gates.
- Visual inspection of the hoists and hoist equipment.
- Testing of gates and hoists while operating.
- Recording trunnion movements while raising gates in both loaded and unloaded condition.
- A report including documentation of the design and operation of the gates and hoists, inspection and testing results, conclusions, and recommendations.

Limitations

The services under this contract include the professional opinion and judgment on the data and information reviewed. The conclusions and recommendations presented in this report are based on the information provided by the District and the inspection of the radial gates and hoists. The inspection was visual only and only accessible portions of the components were inspected. No nondestructive tests or laboratory testing was conducted in the course of the inspection.

PROJECT BACKGROUND

Project Description

Little Goose Dam is located in southeastern Washington on the Snake River, 28.7 river miles upstream of Lower Monumental Dam, and 70.3 miles above its confluence with the Columbia River.

The main project structures include a powerhouse, concrete spillway, navigation lock, fish facilities, concrete non-overflow sections, and a rockfill embankment on the north shore. The dam is 2,655 feet long including the embankment. Construction of the project began in June 1963 and was completed in January 1970.

The spillway is 512-feet-long and is located about mid-river. The spillway consists of eight radial gate controlled bays separated by 14-foot-wide piers. The radial gates are each 50-feet wide by 60-feet high. The gates are numbered 1 to 8 from left to right looking downstream. The spillway structure has a maximum height of 204.4 feet with the deck at Elev. 651.0. The spillway crest is at Elev. 581.0 and the top of gates at Elev. 640.0. The reservoir stores 565,000 acre-feet at normal full pool (Elev. 638.0).

The Spillway Design Flood (SDF) is 850,000 cfs. The spillway has a design capacity of 850,000 cfs at reservoir level Elev. 646.5. The maximum spillway capacity at normal full pool (Elev. 638.0) is 676,000 cfs. At Little Goose Lock and Dam for the period from 1951 to 2000 the maximum flood of record was 306,700 cfs on June 18th, 1974. Peak flow outside the period of record is 409,000 cfs on June 5th 1894. This value was computed from flood marks by the U.S. Weather Bureau.

Gate Design and Construction

The Corps of Engineers designed the gates and project facilities. The gates were fabricated by Pacific Car and Foundry of Seattle, Washington.

The Walla Walla District provided copies of the engineering drawings and shop drawings for the gates. The gate and hoist specifications were also provided as well as design calculations for the gates. The following information was obtained from these documents.

The 3/8-inch to 1/2-inch thick skin plate is supported by vertical ST10WF31 purlins. The skin plate is 3/4-inch thick on each end of the gate to act as a wear surface for the lifting cables. The purlins are connected to three horizontal plate girders. Each horizontal girder is supported by 14WF gate arms. The gate arms are braced with 14 WF members and there are ST7WF15 braces between the downstream flanges of the horizontal girders. The gate end frames were assembled in

LITTLE GOOSE DAM

the field. The skin plate was installed in five vertical sections and joined by full penetration welds.

Cable attachment brackets are mounted on the skin plate at the bottom corners. The skin plate, purlins, horizontal girders and cable attachment brackets are A441 high strength / low alloy steel (Carbon - Magnesium - Vanadium, Heat Treated for Pressure Vessels). All other members are A-36 steel.

Each trunnion has a 24-inch diameter forged steel pin with a cast aluminum bronze bushing. The trunnion pin was designed to limit the bearing pressure to 4 ksi based on the reaction from the gate of 3,005 kips.

The trunnions rest on a concrete girder that is anchored to the spillway piers with two groups of 48 - 1-1/4 inch diameter prestressed bars. The trunnion girder and anchor bars were designed for two loading conditions: balanced and unbalanced. In the balanced condition with two adjacent gates closed, the total load on each group of anchor bars is 3,040 kips. When one gate is unloaded, the load on the anchor bars increases to 4,180 kips. The bars were designed for 0.6 of ultimate and a total prestress force of 5,122 kips.

The gates are raised and lowered by electric hoist units mounted on the deck above the gates. Eight, 1-inch diameter wire ropes on each side of the gate wind on separate drums mounted on a common shaft. The hoist operating speed is approximately 1.16 feet per minute.

The gates have rubber J-bulb side seals and rubber wedge bottom seals. The side seal plates and sill beams are heated to prevent ice formation. The heating system consists of piping embedded below the seal plates through which electrically heated oil is circulated. The seal heaters are manually started and thermostatically controlled when the air temperature drops to 32 degrees F. There are also air bubblers at three elevations on each pier for ice and debris clearing. They are manually operated from the service gallery.

A trunnion friction coefficient of 0.3 was used to design the yoke anchorage but there is no indication that trunnion friction was considered in the design of the gate arms.

Gate Operation

The gates may be operated by manual control from stations located near each hoist, but normally the gates are remotely controlled from the powerhouse. All of the hoists can be powered from a diesel generator set.

The spillway is operated to pass the desired discharge with the best hydraulic conditions in the stilling basin. The gates are opened in one-foot increments during the fish passage season from March 1 through December 31 according to the operating sequence in Table 1.

LITTLE GOOSE DAM

Gate Number / Gate Stops								Total	Spill
1	2	3	4	5	6	7	8	Stops	(kcfs) ¹

(1) Forebay El. 638

1	0	0	0	0	0	0	1	2	4
1	1	0	0	0	0	1	1	4	8
1	1	1	0	0	1	1	1	6	11
1	1	1	1	1	1	1	1	8	15
1	1	2	1	1	2	1	1	10	19
1	1	2	2	2	2	1	2	13	25
2	1	2	2	2	2	1	2	14	27
2	2	2	2	2	2	2	2	16	31
3	2	2	2	2	2	2	2	17	33
3	2	3	3	2	2	2	3	20	39
3	3	3	3	2	3	2	3	22	43
3	3	3	3	2	3	3	4	24	47
3	3	3	4	3	3	3	4	26	52
4	3	4	4	3	3	3	4	28	56
4	4	4	4	3	3	4	4	30	60
5	5	4	4	3	3	4	4	32	64
5	5	5	4	4	3	4	4	34	68
5	5	5	4	4	4	4	5	36	72
5	6	5	5	4	4	4	5	38	76
5	6	5	5	4	4	5	6	40	80
6	6	5	5	4	5	5	6	42	84
6	6	5	5	5	5	6	6	44	88
7	6	5	5	5	5	6	7	46	92
7	6	5	6	6	5	6	7	48	96
7	6	6	6	6	6	6	7	50	100
7	6	6	7	7	6	6	7	52	104
7	7	6	7	7	7	6	7	54	108
7	7	7	7	7	7	7	7	56	112
8	7	7	7	7	7	7	8	58	116
8	7	8	7	8	7	7	8	60	120
8	7	8	8	8	8	7	8	62	124
8	8	8	8	8	8	8	8	64	128
9	8	8	8	8	8	8	9	66	132
9	8	9	8	9	8	8	9	68	136
9	8	9	9	9	9	8	9	70	140

Table 1 - Gate Operating Sequence

LITTLE GOOSE DAM

Gate Maintenance

The District performs routinely inspects, tests, and lubricates the gates and hoists. Recent significant maintenance activities consist of:

- Gate 1 – In August 1981, placed stoplogs and repaired hoist cable grooves in face plate with Belzona. Gate was sandblasted and painted. Also repaired hoist cable anchors by welding with stainless steel wire. Two 2-inch-diameter by 24-inch-long anodes were installed adjacent to each anchor block. These repairs were inspected in October 1987 and found to be in good condition.
- Gate 5 – Took gate out of service in June 1980 and inspected cables and anchors. Sandblasted damaged areas, repaired by welding, and painted with vinyl system. Inspected repairs in February 1988. South side of gate had severe corrosion under one wire rope with pits up to ¼ inch deep.
- Gate 8 – In September 1982 placed stops and repaired cable anchors by welding. Installed magnesium anodes adjacent to each block. Repaired corrosion under the cable with Devcon "A". Sandblasted and painted gate with standard vinyl system. Inspected in May 1992 and found that the repairs were in good condition. The anodes appeared to be preventing corrosion under the wire ropes. The south side shows more corrosion and the wear plates have small pinholes over the full length. The worst corrosion is occurring where the side seals connect to the gate face. The bolts are stainless steel. The center portion of the gate is showing pinhole corrosion.
- In 1983 all gates were reconditioned and repainted under contract DACW68-83-C-0111.

Inspection

General

Wayne Edwards and Mike Haynes of HDR Engineering performed an initial site visit and inspection on April 5, 2000. Based on information collected during the initial inspection, HDR prepared an inspection plan and inspection sheets that were submitted to the District for review prior to the detailed inspection.

The inspection and testing of the spillway radial gates was performed from October 2nd through 9th, by Sam Planck, P.E., Heather Yee and Tony Barela, of HDR Engineering, Inc. Steve Schmidkofer and Jim Knowles of K&N Electric inspected the hoists, took amperage measurements, and recorded observations during testing. Gary Struthers Associates were responsible for operation of the gates during the loaded and unloaded testing and moved the stoplogs between gate testing. Emerald Services, Inc., as a sub-contractor to Gary Struthers, provided water blast cleaning of the skin plate during the upstream face inspection. The weather was clear with temperatures ranging from 50 to 75 degrees F for the inspection of Gates 2

LITTLE GOOSE DAM

through 8. The upstream inspection of Gate 1 was performed in rainy conditions and a temperature of 40 to 50 degrees. Due to the wet and unsafe conditions, the racking measurements, inspection of the bottom of the upstream face and the trunnion dial gage measurements were not performed. Sam Planck, P.E. Amy Akins and Marv Brammer, P.E. of HDR returned to the site on November 20th to complete the inspections for Gate 1. The reservoir was full during all of the inspections.

Procedures

Upstream Inspection & Testing

For the upstream inspections, stoplogs were placed in front of the gates prior to the inspection. The upstream face of Gates 1 through 8 were inspected from the spillway deck as each gate was raised to the full open position. The first part of the inspection was a rope access inspection of the bottom seal, bottom of the upstream surface of the skin plate and the hoist connections. At certain gates, the inspection under the bottom of the gate could not be made due to excessive leakage through the stoplogs, see Photo. 1. Racking measurements between the bottom seal and the spillway were also made at this time.




Photo. 1: Heavy leakage from stoplogs preventing inspection of bottom upstream face of Gate 3.

The second part of the upstream inspection consisted of the transverse, operational measurements at the trunnion, amperage readings while opening and closing the gate, and the inspection of the upstream surface of the skin plate. Measurements were made to determine transverse movement of the trunnion hub versus the trunnion yoke at the initial, full open, and final closed position. During the gate opening, visible corrosion, debris and surface inconsistencies were waterblasted from the gate face for better condition assessment, see Photo 2. Amperage readings for the hoist were recorded at initial opening, during opening and during closing.

LITTLE GOOSE DAM




Photo. 2:
*Waterblasting
of upstream
surface of skin
plate during
full opening of
gate.*

Downstream Inspection

The downstream portions of all gates were inspected by climbing along the horizontal girders and radial struts, see Photo. 3. Inspection rigging for the downstream inspections was anchored to the gate hoist equipment and torque tubes. Visual observations were made for excessive sweep and camber of the main struts and were recorded only if an abnormal condition was observed.




Photo. 3: *Rope access downstream inspection.*

LITTLE GOOSE DAM

Operational Testing – Unloaded vs. Loaded

At the completion of the upstream inspection, with the stoplogs in place and the gate unloaded, dial gages were set at the trunnion to measure the vertical and lateral movement of the trunnion hub versus the trunnion yoke. Steel rulers were used to measure the transverse movement of the trunnion hub versus the trunnion yoke. After initial readings were taken, the top stoplog was cracked open and the void was flooded, loading the gate. When the void between the stoplogs and the gate was completely full, final movement readings were taken. There was no gap present at the bearing between the trunnion yoke and the trunnion support beam, therefore, movement readings between the two surfaces were not made.

Operational Testing – Loaded

With the stoplogs removed and the gate fully loaded, the gates were opened to two feet. Amperage reading for the hoists were recorded at the initial opening, during the opening of the gate and during closing.

Ultrasonic Testing

Non-destructive, ultrasonic testing was not performed at Little Goose Dam. At Lower Granite Dam the locations of field weld splices were indicated on the plans and were ultrasonically tested during the inspection. There were no indications of field weld splices in primary members on the design or shop plans for Little Goose Dam and none were found in the field.

Nomenclature

The gates are identified as Gate 1 to 8, with 1 on the south end near the powerhouse looking downstream. Unless noted otherwise, all locations of observations, and notes pertaining to the radial gates are identified as right or left looking downstream.

In the inspection sheets and this report, corrosion is classified as light, moderate or heavy as follows:

- Light - Surface rust with no flaking or packing. Rust can not be scraped off by hand.
- Moderate - Some flaking, beginning to pack, but thickness of the pack is less than approximately 1/16". There is no observable loss of section.
- Heavy – Pack rust with measurable or observable section loss to the member.

Member Designations

For the radial gate inspection observations and the photographs, the member designations indicated in Figure 1 apply.




Figure 1: Radial gate member designations.

General Inspection Observations

The majority of condition observations found during the inspection are consistently found at all of the gates. The following section of the report pertains to those general observations or conditions which were found to apply to all of the gates. Specific observations or deficiencies for individual gates begin on page 25. No significant deviations from the as-built plans were observed for the radial gates. Field inspection sheets for the gates are included in Appendix A. Hoist operation and inspection sheets can be found in Appendix B.

Upstream Surface of Skin Plate

The condition of the upstream surface of the skin plate varies from generally good to extremely poor depending on the gate and the locations on the skin plate. On average, the pits are approximately one inch in diameter and 1/4-inch to 5/16-inch deep. Some appear to be greater than 1/4-inch deep in the 3/8-inch thick portion of the skin plate and greater than 3/8-inch deep in

LITTLE GOOSE DAM

the 1/2-inch thick portion. See Figure 2, and photos 4 and 5. There is moderate to heavy, scattered pitting on the 3/4-inch wear plates on most of the gates. There is pitting present in excess of 1/2-inch deep at some locations, see Photo. 6. At many locations the pitting on both the skin plate and wear plates appears to be associated with scratches or dings in the plates original protective coating, see Photo. 5 and Photo 7. Based on the hemispherical shape of the pitting, the corrosion appears to be microbially influenced. It is likely that increased acid levels due to microbial activity have created a concentration cell within the pits and accelerated the corrosion.

There is significant delamination of the vinyl coating on the wear plate at Gates 2 and 6 with smaller spots of delamination at other gates. See Photo. 8.




Figure 2: Typical pitting profile in 3/8 inch plate.




Photo. 4: Typical, generally good condition of skin plate.



Photo. 5: Skin plate pitting, typical.




Photo. 6: Wear plate pitting - heavy, typical. Hemispherical shape is indication of microbially influenced corrosion.

LITTLE GOOSE DAM




Photo. 7: Pitting on wear plate. Pitting appears to be associated with scratches in coating, typical.



Photo. 8: Delamination of vinyl coating on wear plate, typical Gates 2 and 6.

LITTLE GOOSE DAM

Hoists Connections

The hoist connections are in generally good condition with light to moderate corrosion present on the lifting lug plates. The U-bolts, socket blocks and connection pin, which appear to be stainless steel, are in very good condition, see Photo. 9. The design or material type for the U-bolts, socket blocks and connection pin are not listed in the available plans. The sacrificial anodes appear to be in too good of a condition given their installation date of 1981 and 1982. It is likely that they were painted or in some way protected after their installation and ceased functioning as anodes.



Photo. 9: Hoist connection, typical condition.

Downstream Surface of Skin Plate

The downstream surface of the skin plate is in generally good condition. Isolated spots of light to moderate surface corrosion and previous (painted over) pitting can be found at various locations. There is also evidence of previous weld and grind repairs made to some gates indicating earlier penetration of the skin plate by corrosion. The weld and grind repairs are in good condition and show no signs of further corrosion from the downstream side. See Individual Gate Inspection Observations on Page 25 for locations and photographs of weld repairs.

LITTLE GOOSE DAM

Vertical Purlins

The vertical purlins are in generally good condition. At the bottom of the gate there is standing water between the bottom seal closure plate, the web of the purlins and the downstream side of the skin plate. Light to moderate corrosion is forming on all surfaces. There is no drainage for this space and it is consistently full of water and debris at all gates, see Figure 3 and Photo. 10.




Figure 3: Standing water at bottom of gate between skin plate, purlin webs and bottom seal closure plate, typical.




Photo. 10: Standing water at bottom of gate between skin plate, purlin webs and bottom seal closure plate, typical.

LITTLE GOOSE DAM

Horizontal Girders and Braces

The horizontal girders and bracing are in generally good condition. There are isolated spots of light to moderate corrosion, mostly at locations with poor drainage.

The top and middle horizontal girders are divided into twelve drainage areas due to the web stiffeners. The area at either end of the girders is free to drain off the end of the web. The remaining ten areas have only three drain holes and require water to flow horizontally through at least one notch in the stiffeners in order to reach a drain hole. There are debris lines and evidence of standing water on nearly all of the horizontal girder flanges and webs.

The worst corrosion occurs on the bottom horizontal girder, between the multiple stiffeners, at each end of the girder. There are six stiffeners in close proximity to one another with drainage only provided horizontally through a notch at the upstream (low) end of the stiffener. In order for the last space to drain, the water must travel horizontally under five stiffeners. These notches are typically clogged and the area between the stiffeners is consistently full of water and debris, see Photo. 11.




Photo. 11: Standing water between stiffeners at ends of bottom horizontal girder, typical.

LITTLE GOOSE DAM



Photo. 12: Standing water or debris lines between stiffeners at ends of bottom horizontal girder, typical.

Immediately upstream and slightly above the end of the bottom horizontal girders, there are stiffeners between the skin plate, purlins and upstream flange of the horizontal girders. There is no drainage from this location and the enclosed area is either full of water and/or debris on all gates. See Photo. 13.




Photo. 13: Standing water and debris between purlins, skin plate and upstream horizontal girder flange, typical.

LITTLE GOOSE DAM

On the underside of the bottom horizontal girder, at the connection to the radial struts, there is delaminated paint and light to moderate corrosion around the drain hole in the girder web and near the adjacent stiffeners. See Photo. 14.




Photo. 14: Corrosion beneath bottom horizontal girder. Looking up at girder flange and drain hole. Stiffener at right, typical.

Radial Struts and Braces

The radial struts are in generally good condition with only light surface corrosion at isolated locations, see Photo 15.

There is very poor drainage from the upstream end of the bottom radial strut and ponding or debris lines (evidence of previous ponding) are found at every gate.

There is very poor drainage from the downstream end of the top radial strut at the trunnion. The three radial struts become an enclosed box section at the trunnion. Since there is no drainage vertically from between the flanges of the top strut, a small drain hole is provided horizontally through the strut flange. The drain hole is consistently clogged and standing water is present at most trunnions. See Photo. 16.

LITTLE GOOSE DAM




Photo. 15: Light surface corrosion on radial struts and braces, typical.




Photo. 16: Standing water at downstream end of top radial strut at trunnion hub, typical.

LITTLE GOOSE DAM

Trunnions

The trunnion hubs, yokes and bearing material are in generally very good condition and appear well lubricated. Lubricant was observed being expelled between the yoke and hub, around the circumference of all of the trunnions.

Side and Bottom Seals

The side and bottom seals are in generally good condition. Small side and bottom seal leaks are visible on many of the gates, although no major leaks were observed. There is a leak at the bottom seal, at the spillway monolith construction joint at nearly every gate, see Photo. 17. There is light to moderate corrosion on the downstream side of the skin plate at the side seals and side seal bolts, see Photo 19.



Photo. 17: Leak at spillway monolith construction joint, typical.

LITTLE GOOSE DAM




Photo. 19: Side seal from upstream side with no signs of cracking or deterioration, typical condition.



Photo. 18: Side seal from downstream side, light to moderate corrosion on skin plate, seal angles, nuts and bolts, typical condition.

There is moderate corrosion on the skin plate on the upstream side of the bottom seal. The downstream side of the bottom seal is in good condition with little occurrence of corrosion. See Photo. 20 and Photo. 21. The rubber seals are in good condition with only hairline cracking visible.

LITTLE GOOSE DAM



Photo. 20: Upstream side of bottom seal with light to moderate corrosion on skin plate, typical.




Photo. 21: Downstream side of bottom seal, typical

Radial Gate – Operation, Testing and Measurements

Member Section Dimensions

Section dimensions of main structural members were measured to verify conformance with the design drawings. These members included radial struts, radial strut bracing, horizontal girders, horizontal girder bracing and purlins. Measured dimensions were recorded on field data sheets found in Appendix A. The data sheets also contain nominal section dimensions from the American Institute of Steel Construction (AISC) *Steel Construction Manual, Seventh Edition, 1970*. Section measurements typically include the depth, d (measured at the edges of the flanges), the flange width, b_f and the flange thickness, t_f . Web thickness, t_w , was only measured if there was an exposed portion of the web or drain holes large enough for calipers.

Differences between the design drawings and the actual field conditions of $1/16^{\text{th}}$ inch or less were deemed to be insignificant. Nearly all members in the field were found to be greater or equal in dimension than what was required in the design drawings. The larger dimensions were probably due to inaccuracies of the field measurements resulting from difficult access or with the thickness of the paint on the members. Those that were smaller were all within the fabrication tolerances. Of those measurements that were out of fabrication tolerance range, none were consistently out of range to conclude that a member other than what was specified in the design drawings was used.

Racking Measurements

Racking measurements for the gates were made at the beginning of the upstream inspection of the gates. Measurements were recorded for the distance between the bottom of the gate at the bottom corner of the bottom seal plate, and the embedded spillway sill plate. Measurements were made as far as possible to the left and right side of the gate depending on stoplog leakage and flow on the spillway. The gates were typically between two and four feet open when the measurements were made. The measurements for racking are as follows:

	Left (inches)	Right (inches)
Gate 1	39 – 1/2	39 – 1/2
Gate 2	39 – 1/2	39 – 1/2
Gate 3	42	42
Gate 4	Too much stoplog leakage to measure	
Gate 5	39 – 1/4	39
Gate 6	41	41
Gate 7	38 – 1/2	39
Gate 8	45	45

Table 1: Gate racking measurements.

LITTLE GOOSE DAM

The gates were also observed at the moment of first opening to look for signs of water release beginning from one side of the gate or the other. In most cases, water release would begin at both sides of the gate simultaneously and move towards the middle of the gate at equal rates. Based on the recorded measurements and observations, there is no apparent racking of the gates.

Trunnion Hub Movement: Closed - Full Open - Closed

With the stoplogs in place, measurements were made of the transverse gap between the trunnion hub and the trunnion yoke, at both sides of the trunnion, at both trunnions. The measurements were made with the gate at the initial opening, full open, and again when closed. The maximum transverse movement recorded between any two positions is as follows:

	Left Trunnion		Right Trunnion	
	Inside (inches)	Pier Side (inches)	Inside (inches)	Pier Side (inches)
Gate 1	1/32	1/32	0	0
Gate 2	0	1/32	0	1/32
Gate 3	0	0	0	0
Gate 4	0	1/32	0	1/32
Gate 5	1/32	1/32	0	0
Gate 6	0	0	1/32	1/32
Gate 7	1/32	2/32	1/32	1/32
Gate 8	1/32	2/32	1/32	0

Table 2: Transverse trunnion hub movement through full opening and closing

Based on the surface irregularities of the trunnion hub and the casting tolerances, the transverse measurements between the hub and the yoke can only be considered accurate to $\pm 1/16$ -inch. The recorded measurements indicate there is no appreciable lateral movement of the trunnion hubs with respect to the trunnion yoke during either opening or closing of the gate.

LITTLE GOOSE DAM

Trunnion Hub Movement: Unloaded vs. Loaded

Dial gages were installed at both trunnion to record the vertical, transverse and upstream / downstream movement of the trunnion hub with respect to the trunnion yoke. The initial measurement was made with the stoplogs in place and no load on the gate. The final reading was made after the top stoplog was removed and the gate was fully loaded. The maximum movements recorded at the trunnion hubs are as follows:

	Vertical (1 / 1000 inch)	Upstream / Downstream (1 / 1000 inch)	Transverse (1 / 1000 inch)
Gate 1	7	34	0
Gate 2	4	22	0
Gate 3	12	31	31
Gate 4	8	32	0
Gate 5	10	31	31
Gate 6	0	45	0
Gate 7	11	37	31
Gate 8	1	30	0

Table 3: Loaded versus unloaded trunnion movements

For the vertical movements shown in Table 4, the hub moved upward with respect to the yoke during loading. The upstream / downstream movement of the hub was in the downstream direction and the transverse movement was outward, toward the piers.

The design tolerance for the 24-inch diameter trunnion pin is listed in the plans as +0.000 inches and -0.005 inches. The tolerances for the 24-inch diameter trunnion bushing is listed as +0.012 inches and -0.000 inches. The shop plans for the pin indicate the pin should be 23.98 inches in diameter with tolerances of +0.000 inches and -0.008 inches.

Based on the recorded movements and the tolerances, there is no significant displacements of the trunnion hub with respect to the trunnion yoke occurring during the loading process.

LITTLE GOOSE DAM

Individual Gate Inspection Observations

The observations in the following section pertain only to the gates indicated and were not typically found on all of the gates.

Gate 1

- There is an apparent weld and grind repair on the downstream side on the skin plate at approximately 5 feet above the middle horizontal girder near the left side of the gate.




Photo. 22: Apparent previous weld and grind repair as seen from downstream side of skin plate on Gate 1.

LITTLE GOOSE DAM

Gate 2

- On the downstream side of the skin plate, along the wear plate, there is delamination of the vinyl coating on the plate. Large sheets of vinyl are peeling off of the wear plate and hanging loosely on the gate face.



Photo. 23: Delaminated vinyl coating on wear plate, right side of Gate 2.

Gate 3

- See General Inspection Observations

LITTLE GOOSE DAM

Gate 4

- There is a large deformation in the web of the top horizontal girder at the left end.



Photo. 24: Deformation in web of top horizontal girder.

LITTLE GOOSE DAM

Gate 5

- There is a line of light to moderate corrosion on the downstream side of the skin plate just above the top horizontal girder approximately 10 feet from the left side of the gate.



Photo. 25: Moderate corrosion on downstream surface of skin plate.



Photo. 26: Moderate surface corrosion on downstream surface of skin plate.

LITTLE GOOSE DAM

Gate 6

- On the downstream side of the skin plate at approximately half way between the middle and top horizontal girder, twelve feet from the left side, there is an apparent weld and grind repair from a previous leak. The plug weld is approximately ½-inch in diameter.




Photo. 27: Apparent, previous weld and grind repair on downstream surface of skin plate.

- On the downstream side of the skin plate, along the wear plate, there is delamination of the vinyl coating on the plate. Large sheets of vinyl are peeling off of the wear plate and hanging loosely on the gate face.



Photo. 28: Delaminated vinyl coating on wear plate, left side of Gate 6.

LITTLE GOOSE DAM

Gate 7

- See General Inspection Observations

Gate 8

- See General Inspection Observations

Hoists – Operation, Testing and Measurements

Hoist Operation Inspection

External portions of the hoist equipment, support platforms and gate connections were visually inspected for signs of excessive corrosion, wear or damage. The hoist and hoist machinery are in generally good condition, however, excessive motor and bearing noises were observed at many of the hoists. See Photos 30, 31 and 32.



Photo. 29: Recording hoist amperage readings.




Photo. 30: Gate hoist, typical.

LITTLE GOOSE DAM




Photo. 31: Hoist motors, typical. Note fluid leaking from beneath motor.



Photo. 32: Hoist manufacture's plate.

LITTLE GOOSE DAM

The following observations were made at individual gate hoists:

Hoist and Motor Observations	
Gate 1	None
Gate 2	The motor bearings are noisy.
Gate 3	The motor lead wires and heater wires are frayed.
Gate 4	The motor bearings are noisy and sound dry.
Gate 5	None
Gate 6	The hoist brake seized during operation and was adjusted.
Gate 7	The motor bearings are in need of replacement.
Gate 8	None

Table 4: Hoist operation observations.

Hoist Amperage Measurements:

Hoist amperage readings were recorded during opening and closing of the gates in both the loaded and unloaded condition. The readings include the start up and running amperage. Running amperages were recorded for Phase A, B and C. Table 5 lists the opening and closing start up amperage and the average of the three phases for the running amperage for the gates in the unloaded condition. Table 6 lists the same information for the loaded condition.

	Start up Opening	Start up Closing	Running Opening	Running Closing
Gate 1	87.6	72.0	10.8	6.5
Gate 2	92.8	81.6	10.8	6.6
Gate 3	96.0	85.6	10.9	6.2
Gate 4	94.4	84.0	11.3	5.5
Gate 5	84.8	78.0	11.6	6.2
Gate 6	99.2	80.0	13.4	6.5
Gate 7	102.0	80.0	11.7	6.1
Gate 8	84.0	74.0	12.1	6.3

Table 5: Unloaded Gate - Hoist Amperage Readings

LITTLE GOOSE DAM

	Start up Opening	Start up Closing	Running Opening	Running Closing
Gate 1	112.0	110.0	16.0	9.6
Gate 2	103.0	93.6	12.0	6.8
Gate 3	101.0	94.0	11.6	6.4
Gate 4	96.0	75.0	11.7	5.8
Gate 5	93.0	88.0	12.4	6.1
Gate 6	104.0	99.2	13.6	7.5
Gate 7	101.5	86.0	10.9	6.4
Gate 8	102.0	80.0	11.5	6.1

Table 6: Loaded Gate - Hoist Amperage Readings

Based on the consistency of the readings the hoists are in generally good condition. The amperage data indicates that the tainter gate hoist motors are operating well within their design operating limits that normally allow the starting amperage to be in the range of 5 to 8 times the nameplate value. The current draw for all motors were in acceptable range and the gates appeared to be free with no apparent binding. The motors on the hoists are all noisier than would be expected for these units. The motors all have sealed bearings with no lube ports. During the opening of Gate 6 the hoist motor brake seized and adjustments to the brake were made in order to continue operation, see Photo. 33. The field inspection sheets for the hoist measurements can be found in Appendix B.




Photo. 33: Seized brake on Gate 6 hoist.

RECOMMENDATIONS

Recommended in the next year or as necessary:

- Repair pitting on skin plate and repaint (or recoat) upstream surface of gate face.
- Install new sacrificial anodes on upstream side of gate. A corrosion expert should be consulted to determine the number and location of anodes required. Existing anodes may remain in place.

These repairs can be undertaken sequentially on all of the gates at once or the repairs could be made on an as-needed basis as the pitting penetrates the skin plate and leaks develop at individual gates.

Recommended in the next 2 years:

- Analyze the hoist gearboxes per the manufactures recommendation and remanufacture or replace as required.
- Replace the main gearbox seals on the hoist motors.


Recommended in the next 5 years:

- Install drain hole between the multiple stiffeners at ends of the bottom horizontal girders. The recommended size for these drain holes is 1-inch in diameter.
- Install drain holes in the purlin stiffeners near the ends of the bottom horizontal girders (Plate perpendicular to skin plate, above multiple stiffeners on bottom horizontal girder). The recommended size for these drain holes is 1-inch in diameter.
- Install drain holes in the downstream portion of the bottom seal plate between every purlin. Note: the rubber bottom seal is located between the bottom seal plate and the bottom seal keeper plate. The hole should not be flame cut with the rubber bottom seal in place. The recommended size for these drain holes is 1-inch in diameter.
- Enlarge the drain holes at upstream end of lower radial struts. The recommended size for these drain holes is 1 1/2 - inch in diameter.
- For all new and enlarged drain holes, the holes should be drilled, not flame cut, to reduce jagged edges which snag debris. If drilling holes is not feasible, then the edges of the flame cut holes should be reamed smooth.

REFERENCES

1. Water Control Manual, Little Goose Lock and Dam, U.S. Army Corps of Engineers, Walla Walla District, February 1988.


Gate No. 1
 Left Elevation B-B



Member	Type	Depth		Web		Flange(s)			
		d		t _w		b _f		t _f	
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 3/4	15/16	5/16	15 3/4	15 3/4	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16	5/16	16 3/8	16 3/8	2 7/16	2 1/2
Strut 1	14 WF 398	18 1/4	18 1/4	1 13/16	5/16	16 5/8	16 5/8	2 13/16	2 3/4
Brace A	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace B	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace C	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace D	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace E	14 WF 30	13 7/8	13 15/16	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace F	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace G	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace H	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace J	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace K	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace L	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8

21) MOD COR-


Gate No. 1
 Right Elevation
 A-A



Member	Type	Depth		Web		Flange(s)			
		d		t _w		b _f		t _f	
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 5/8	15/16	—	15 3/4	5 3/4	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16	—	16 3/8	16 3/8	2 7/16	2 1/2
Strut 1	14 WF 398	18 1/4	18 1/4	1 13/16	1 15/16	16 5/8	16 3/8	2 13/16	2 13/16
Brace A	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace B	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace C	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace D	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace E	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace F	14 WF 30	13 7/8	13 15/16	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace G	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace H	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace J	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace K	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace L	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8

LEFT FROME MORE COR THAN RIGHT

Gate No. 1 Downstream Elevation



Member	Type	Depth d		Web t _w		Flange - End			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Horiz. Girder 3	PL Girder	49 3/4	49 7/8	7/16	7/16	16	16	7/8	7/8
Horiz. Girder 2	PL Girder	60 1/2	60 1/2	3/4	13/16	16 1/2	16 1/2	1 1/4	1 5/16
Horiz. Girder 1	PL Girder	60 1/2	60 1/2	1	1	16 1/2	16 1/2	1 1/4	1 5/16
Purlins	ST 10 WF 31	10 1/2	10 1/2	13/32	-	8 1/4	8 1/4	5/8	5/8
Skin Plate Bracing	ST 7 WF 15	7	7 1/8	1/4	1/4	6 3/4	6 3/4	3/8	3/8


LIGHT SURFACE COR - EVIDENCE STANDING WATER

2) TYP TOP GIRDER

3) TYP LIGHT COR

4) POSSIBLE PREV. WELD & GRIND PATCH

Gate No. 1 Upstream Elevation _____



Gate No. 1 Operation and Trunnion Measurements

Racking Measurements: Bottom of Gate and Spillway

LEFT	RIGHT
39 1/4	39 1/4


Transverse Trunnion Hub Movement, No Load on Gate: Closed-Open-Closed

	LEFT		RIGHT	
	Inside	Outside (pier)	Inside	Outside (pier)
Initial Gate Closed	20/32	14/32	20/32	15/32
Gate Full Open	19/32	15/32	20/32	15/32
Final Gate Closed	20/32	14/32	20/32	15/32

3-D Trunnion Hub Movements - Unloaded vs. Loaded

	LEFT				RIGHT			
	No Load Void Dry		Full Load Void Full		No Load Void Dry		Full Load Void Full	
Vertical	0.0000		-0.0065		0.0000		0.0000	
US / DS	0.0000		+0.0335		+0.0065		+0.0365	
Transverse	29/32	15/32	29/32	15/32	29/32	14/32	21/32	14/32
	Inside	Outside	Inside	Outside	Inside	Outside	Inside	Outside

Gate No. 2
 Left Elevation B-B




⑨ US side of brace N
 typical light
 surface rust

⑭ entire frame
 from bottom
 horiz


Member	Type	Depth d		Web t _w		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b _f		t _f	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 5/8	15/16		15 3/4	15 3/4	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 3/4	1 9/16		16 3/8	16 3/8	2 7/16	2 7/16
Strut 1	14 WF 398	18 1/4	18 5/16	1 13/16	1 3/4	16 5/8	16 1/2	2 13/16	2 3/4
Brace A	14 WF 30	13 7/8	14	5/16		6 3/4	6 7/8	3/8	3/8
Brace B	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace C	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace D	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 7/8	3/8	3/8
Brace E	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace F	14 WF 30	13 7/8	14	5/16		6 3/4	6 7/8	3/8	3/8
Brace G	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace H	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace J	14 WF 30	13 7/8	14	5/16		6 3/4	6 7/8	3/8	3/8
Brace K	14 WF 30	13 7/8	14	5/16		6 3/4	6 7/8	3/8	3/8
Brace L	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8

Gate No. 2
 Right Elevation
 A-A



Member	Type	Depth d		Web t _w		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b _f		t _f	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8		15/16		15 3/4		1 1/2	
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16		16 3/8	16 3/8	2 7/16	2 7/16
Strut 1	14 WF 398	18 1/4	18 3/8	1 13/16	1 3/4	16 5/8	16 1/2	2 13/16	2 13/16
Brace A	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace B	14 WF 30	13 7/8		5/16		6 3/4		3/8	
Brace C	14 WF 30	13 7/8		5/16		6 3/4		3/8	
Brace D	14 WF 30	13 7/8		5/16		6 3/4		3/8	
Brace E	14 WF 30	13 7/8		5/16		6 3/4		3/8	
Brace F	14 WF 30	13 7/8		5/16		6 3/4		3/8	
Brace G	14 WF 30	13 7/8		5/16		6 3/4		3/8	
Brace H	14 WF 30	13 7/8		5/16		6 3/4		3/8	
Brace J	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace K	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace L	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8

Gate No. 2 Downstream Elevation



light surface mat on stem of purlins most near flange

* pics noted looking upstream

leak in skin plate? NOT seal near pier

fine w/mud clogs from grid 2 (also btw last 3 purlins)

standing water in fins & bitwn last 3 purlins

small med seal, leaks

moderate leak


bottom seal

Small side seal leak - standing water w/ algae/mud bwn

All purlins & bottom lip

Member	Type	Depth		Web		Flange - End			
		d		t _w		b _f		t _f	
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Horiz. Girder 3	PL Girder	49 3/4	50	7/16	7/16	16	16	7/8	30/32
Horiz. Girder 2	PL Girder	60 1/2	60 1/2	3/4	3/4	16 1/2	16 1/2	1 1/4	1 1/4
Horiz. Girder 1	PL Girder	60 1/2	60 1/2	1	1	16 1/2	16 1/2	1 1/4	1 1/4
Purlins	ST 10 WF 31	10 1/2	10 1/2	13/32		8 1/4	8 1/4	5/8	9/16
Skin Plate Bracing	ST 7 WF 15	7	7	1/4	5/16	6 3/4	6 7/8	3/8	3/8

Gate No. 2 Upstream Elevation



Handwritten notes area consisting of ten horizontal lines.

Gate No. 2 Operation and Trunnion Measurements

Racking Measurements: Bottom of Gate and Spillway

LEFT	RIGHT
39 1/2	39 1/2


Transverse Trunnion Hub Movement, No Load on Gate: Closed-Open-Closed

	LEFT		RIGHT	
	Inside	Outside (pier)	Inside	Outside (pier)
Initial Gate Closed	22/32	9/32	17/32	21/32
Gate Full Open	22/32	10/32	17/32	21/32
Final Gate Closed	22/32	10/32	17/32	22/32

3-D Trunnion Hub Movements - Unloaded vs. Loaded

	LEFT				RIGHT			
	No Load Void Dry		Full Load Void Full		No Load Void Dry		Full Load Void Full	
Vertical	0.0000		+0.0020		-0.0005		-0.0045	
US / DS	0.0000		+0.0219		+0.0005		+0.0225	
Transverse	22/32	10/32	22/32	10/32	17/32	22/32	18/32	22/32
	Inside	Outside	Inside	Outside	Inside	Outside	Inside	Outside


Gate No. 3
 Left Elevation B-B



Member	Type	Depth d		Web t _w		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b _f		t _f	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 3/4	15/16		15 3/4	15 3/4	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 7/16	1 9/16		16 3/8	16 3/16	2 7/16	2 7/16
Strut 1	14 WF 398	18 1/4	18 1/4	1 13/16		16 5/8	16 1/2	2 13/16	2 13/16
Brace A	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 13/16	3/8	3/8
Brace B	14 WF 30	13 7/8	14	5/16		6 3/4	6 7/8	3/8	3/8
Brace C	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace D	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace E	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace F	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 7/8	3/8	3/8
Brace G	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace H	14 WF 30	13 7/8	14 3/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace J	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 7/8	3/8	3/8
Brace K	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace L	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8

- 3. Splattered concrete on second strut.
- 4. Overall shot of LFT frame note. Concrete splatter and light rust
- 5. Vert Brace light rust typ. All braces
- 2. Concrete splatter on bot. strut


Gate No. 43
 Right Elevation
 A-A



Member	Type	Depth d		Web t _w		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b _f		t _f	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 15/16	15/16		15 3/4	15 3/4	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16		16 3/8	16 3/4	2 7/16	2 7/2
Strut 1	14 WF 398	18 1/4	18 3/16	1 13/16		16 5/8	16 7/16	2 13/16	2 1/16
Brace A	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace B	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace C	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 15/16	3/8	3/8
Brace D	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 10/16	3/8	3/8
Brace E	14 WF 30	13 7/8	13 3/4	5/16		6 3/4	6 15/16	3/8	3/8
Brace F	14 WF 30	13 7/8	13 1/8	5/16		6 3/4	6 15/16	3/8	3/8
Brace G	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace H	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace J	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace K	14 WF 30	13 7/8	14	5/16		6 3/4	6 13/16	3/8	3/8
Brace L	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 5/4	3/8	3/8
Brace N	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8

14. Shot of FRM. NOTE Light Rust on most Members


Gate No. 3 Downstream Elevation



Member	Type	Depth d		Web t _w		Flange - End			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b _r		t _f	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Horiz. Girder 3	PL Girder	49 3/4	50	7/16	7/16	16	16	7/8	7/8
Horiz. Girder 2	PL Girder	60 1/2	60 7/16	3/4	3/4	16 1/2	16 9/16	1 1/4	1 1/4
Horiz. Girder 1	PL Girder	60 1/2	60 1/2	1	1 1/16	16 1/2	16 1/2	1 1/4	1 1/4
Purlins	ST 10 WF 31	10 1/2	10 1/2	13/32	9/16	8 1/4	8 5/16	5/8	5/8
Skin Plate Bracing	ST 7 WF 15	7	7	1/4	3/16	6 3/4	6 2/4	3/8	3/8

- 2. LEFT Purlin light rust w/ min deposits
- 6. Light rust on Bracing top.
- 8. Standing H₂O on bot. Girder NOTE light rust
- 9. Drain hole w/ continuous flow from above
- 10. Side Seal leak. (LEFT)
- 11. Standing H₂O and muck @ Bot. Pt.
- 12. looking RT. Along bottom seal
- 13, 14. Moderate to heavy rust @ Bot Girder @ Brace Pts

Gate No. 3 Upstream Elevation



- VERY LITTLE COR.

- NOT PITS TOP 20'

Gate No. 3 Operation and Trunnion Measurements

Racking Measurements: Bottom of Gate and Spillway

LEFT	RIGHT
42	42


Transverse Trunnion Hub Movement, No Load on Gate: Closed-Open-Closed

	LEFT		RIGHT	
	Inside	Outside (pier)	Inside	Outside (pier)
Initial Gate Closed	28/32	18/32	18/32	14/32
Gate Full Open	28/32	18/32	18/32	14/32
Final Gate Closed	28/32	18/32	18/32	14/32

3-D Trunnion Hub Movements - Unloaded vs. Loaded

	LEFT				RIGHT			
	No Load Void Dry		Full Load Void Full		No Load Void Dry		Full Load Void Full	
Vertical	+0.0005		+0.0070		-0.0010		-0.0130	
US / DS	0.0000		+0.0308		-0.0025		+0.0250	
Transverse	28/32	18/32	28/32	18/32	18/32	14/32	19/32	13/32
	Inside	Outside	Inside	Outside	Inside	Outside	Inside	Outside


Gate No. 4
 Left Elevation B-B



Member	Type	Depth		Web		Flange(s)			
		d		t _w		b _f		t _f	
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 1/4	15/16	—	15 3/4	✓	1 1/2	✓
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16	—	16 3/8	✓	2 7/16	✓
Strut 1	14 WF 398	18 1/4	✓	1 13/16	—	16 5/8	11 1/2	2 13/16	✓
Brace A	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	5/16
Brace B	14 WF 30	13 7/8	13 5/16	5/16	—	6 3/4	✓	3/8	5/16
Brace C	14 WF 30	13 7/8	13 5/16	5/16	—	6 3/4	✓	3/8	5/16
Brace D	14 WF 30	13 7/8	13 5/16	5/16	—	6 3/4	✓	3/8	5/16
Brace E	14 WF 30	13 7/8	14	5/16	—	6 3/4	13 1/2	3/8	✓
Brace F	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	5/16
Brace G	14 WF 30	13 7/8	✓	5/16	—	6 3/4	6 3/4	3/8	✓
Brace H	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓ 5/16	3/8	5/16
Brace J	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	1/4
Brace K	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace L	14 WF 30	13 7/8	13 5/16	5/16	✓	6 3/4	16 1/2	3/8	✓
Brace M	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace N	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓

- (20) Fine layer of mud flaking off, top
- (21) Bottom Seal, left.
- (22) Seeping water, left.
- (23) Gate face - notice paint
- (24) Sid seals, left.


Gate No. 4
 Right Elevation
 A-A



Member	Type	Depth d		Web t _w		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b _f		t _f	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	✓	15/16	✓	15 3/4	✓	1 1/2	✓
Strut 2	14 WF 342	17 1/2	17 7/16	1 9/16	✓	16 3/8	16 1/2	2 7/16	✓
Strut 1	14 WF 398	18 1/4	✓	1 13/16	✓	16 5/8	✓	2 13/16	✓
Brace A	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace B	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace C	14 WF 30	13 7/8	3 13/16	5/16	✓	6 3/4	✓	3/8	✓
Brace D	14 WF 30	13 7/8	3 13/16	5/16	✓	6 3/4	✓	3/8	✓
Brace E	14 WF 30	13 7/8	14	5/16	✓	6 3/4	✓	3/8	✓
Brace F	14 WF 30	13 7/8	3 5/16	5/16	✓	6 3/4	10 1/16	3/8	5/16
Brace G	14 WF 30	13 7/8	3 5/16	5/16	✓	6 3/4	6 1/16	3/8	5/16
Brace H	14 WF 30	13 7/8	14	5/16	✓	6 3/4	✓	3/8	5/16
Brace J	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace K	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace L	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	10 7/16	3/8	✓
Brace M	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	5/16
Brace N	14 WF 30	13 7/8	14	5/16	✓	6 3/4	✓	3/8	✓

(7) Strange raised marks, like canning buttons on skin plate also.
 (8) BO
 (9) Corrosion patch, bad alignment.

Gate No. 4 Downstream Elevation




(10) Left Drain hole
 (11) Drainage hole
 (12) Ponding water
 (13) Bottom seal

Member	Type	Depth		Web		Flange - End			
		d		t _w		b _f		t _f	
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Horiz. Girder 3	PL Girder	49 3/4	✓	7/16	✓	16	✓	7/8	✓
Horiz. Girder 2	PL Girder	60 1/2	10 3/16	3/4	✓	16 1/2	✓	1 1/4	15/16
Horiz. Girder 1	PL Girder	60 1/2	✓	1	✓	16 1/2	✓	1 1/4	15/16
Purlins	ST 10 WF 31	10 1/2	✓	13/32	✓	8 1/4	✓	5/8	✓
Skin Plate Bracing	ST 7 WF 15	7	15 1/4	1/4	5/16	6 3/4	✓	3/8	✓

- (1) Gate ID
- (2) Light rust on purlins + riv.
- (3) Stiffeners not welded to gate face, + riv. connecting on ends.
- (4) Rivets, Bottom seal.
- (5) Stamps, Divits and paintless marks on skin plate.
- (6) Light rust on vertical bracing.
- (7) Ponding water bottom girder.
- (8) Before, corrosion spots + (5).
- (9) After.
- (10) Corrosion water, Bot seal, center.

Gate No. 4 Upstream Elevation




- TYPICAL PITTING, LIGHTER THAN USUAL

Handwritten notes on lined paper:

- TYPICAL PITTING, LIGHTER THAN USUAL


Gate No. 5
 Left Elevation B-B



Member	Type	Depth		Web		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	13 13/16	15/16		15 3/4	15 3/4	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16		16 3/8	16 3/16	2 7/16	2 7/16
Strut 1	14 WF 398	18 1/4	18 1/4	1 13/16		16 5/8	16 1/2	2 13/16	2 3/4
Brace A	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 7/8	3/8	3/8
Brace B	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace C	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 7/8	3/8	3/8
Brace D	14 WF 30	13 7/8	13 13/16	5/16		6 3/4	6 7/8	3/8	3/8
Brace E	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace F	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 7/8	3/8	3/8
Brace G	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 7/8	3/8	3/8
Brace H	14 WF 30	13 7/8	14	5/16		6 3/4	6 13/16	3/8	3/8
Brace J	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 13/16	3/8	3/8
Brace K	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 13/16	3/8	3/8
Brace L	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/16	3/8	3/8
Brace N	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 7/8	3/8	3/8

- 5. Paint Failure w/ Light Rust (Typ All braces)
- 9. Light Rust on Dia. Braces (Typ)
- 13. Overall shot of Left Frame Note Bad Paint

Gate No. 5
 Right Elevation
 A-A




Member	Type	Depth d		Web t _w		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b _f		t _f	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 1/8	15/16		15 3/4	15 3/4	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16		16 3/8	16 3/16	2 7/16	2 7/16
Strut 1	14 WF 398	18 1/4	18 3/8	1 13/16		16 5/8	16 1/2	2 13/16	2 7/8
Brace A	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 15/16	3/8	3/8
Brace B	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 15/16	3/8	3/8
Brace C	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 7/8	3/8	3/8
Brace D	14 WF 30	13 7/8	13 5/8	5/16		6 3/4	6 7/8	3/8	3/8
Brace E	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 15/16	3/8	3/8
Brace F	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace G	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace H	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace J	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace K	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace L	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8

14. Overall Pic of Gate

15. Left Trunnion

16. RT. Trunnion w/ clogged Drain hole


Gate No. 5 Downstream Elevation



Member	Type	Depth d		Web t _w		Flange - End			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b _r		t _f	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Horiz. Girder 3	PL Girder	49 3/4	49 7/8	7/16	7/16	16	16	7/8	7/8
Horiz. Girder 2	PL Girder	60 1/2	60 1/2	3/4		16 1/2	16 1/2	1 1/4	1 1/4
Horiz. Girder 1	PL Girder	60 1/2	60 1/2	1	1 1/16	16 1/2	16 1/2	1 1/4	1 1/4
Purlins	ST 10 WF 31	10 1/2	10 1/2	13/32		8 1/4	8 1/4	5/8	5/8
Skin Plate Bracing	ST 7 WF 15	7	7	1/4	5/16	6 3/4	6 3/4	3/8	3/8


- 2, 3. Delaminated Plat and light rust ON GATE FACE
- 4. Light Rust TOP GIRDER
- 6. Light Rust ON GIRDERS AND BRACES NOTE Delam ON GATE FACE
- 7. Delam. ON GATE FACE w/ light Rust. These Delam spots ARE TYP ACROSS ENTIRE GATE FACE.
- 8. SIDE SEAL LEAK @ Bot GIRDER NOTE Light Rust & MINORAL Dep.
- 10. Bottom Seal looking Right
- 11. LEFT CORNER leak
- 12. Bottom Plate w/ STANDING H₂O

Gate No. 5 Upstream Elevation



- BEST CONDITION OF ANY GATES SEEN
- MINIMAL PITTING
- EXCESSIVE STOP LOS WEAR, COULD NOT GO UNDER SILL DO TO FALLING WATER -


Gate No. 6
 Left Elevation B-B



Member	Type	Depth d		Web t _w		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b _r		t _f	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	✓	15/16	—	15 3/4	✓	1 1/2	✓
Strut 2	14 WF 342	17 1/2	✓	1 9/16	—	16 3/8	16 1/4	2 7/16	✓
Strut 1	14 WF 398	18 1/4	18 1/8	1 13/16	—	16 5/8	16 1/2	2 13/16	✓
Brace A	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	✓
Brace B	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	✓
Brace C	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	✓
Brace D	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	5/16
Brace E	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	✓
Brace F	14 WF 30	13 7/8	13 15/16	5/16	—	6 3/4	✓	3/8	5/16
Brace G	14 WF 30	13 7/8	13 15/16	5/16	—	6 3/4	✓	3/8	5/16
Brace H	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	5/16
Brace J	14 WF 30	13 7/8	✓	5/16	—	6 3/4	16 1/4	3/8	5/16
Brace K	14 WF 30	13 7/8	14	5/16	—	6 3/4	7	3/8	✓
Brace L	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	✓
Brace M	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	✓
Brace N	14 WF 30	13 7/8	13 5/8	5/16	—	6 3/4	✓	3/8	✓


- (1) Damage to
- (2) Rust on B, top on gate.
- (3) Light rust on A
- (4) Weld 2 on inside of 4th purlin
- (5) Flaking paint / lime deposits
- (6) Paint line from previous.
- (7) Pitting / coat / rust / strut.
- (8) Part of gate release seals.

Gate No. 10
 Right Elevation
 A-A



Member	Type	Depth		Web		Flange(s)			
		d		t _w		b _f		t _f	
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 15/16	15/16	—	15 3/4	15 5/8	1 1/2	✓
Strut 2	14 WF 342	17 1/2	✓	1 9/16	—	16 3/8	15 1/4	2 7/16	✓
Strut 1	14 WF 398	18 1/4	✓	1 13/16	—	16 5/8	16 1/2	2 13/16	✓
Brace A	14 WF 30	13 7/8	✓	5/16	—	6 3/4	10 1/10	3/8	5/16
Brace B	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	✓
Brace C	14 WF 30	13 7/8	13 5/16	5/16	—	6 3/4	✓	3/8	5/16
Brace D	14 WF 30	13 7/8	13 5/16	5/16	—	6 3/4	✓	3/8	5/16
Brace E	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	5/16
Brace F	14 WF 30	13 7/8	14	5/16	—	6 3/4	10 1/8	3/8	5/16
Brace G	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	5/16
Brace H	14 WF 30	13 7/8	13 5/16	5/16	—	6 3/4	10 3/4	3/8	5/16
Brace J	14 WF 30	13 7/8	✓	5/16	—	6 3/4	10 1/8	3/8	5/16
Brace K	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	5/16
Brace L	14 WF 30	13 7/8	✓	5/16	—	6 3/4	10 1/8	3/8	5/16
Brace M	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	5/16
Brace N	14 WF 30	13 7/8	14	5/16	—	6 3/4	10 1/8	3/8	5/16

Gate No. U Downstream Elevation



(19) (20) Leak in middle, water coming through hole

Member	Type	Depth		Web		Flange - End			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Horiz. Girder 3	PL Girder	49 3/4	✓	7 1/16	✓	16	✓	7/8	15/16
Horiz. Girder 2	PL Girder	60 1/2	20 1/2	3/4	✓	16 1/2	✓	1 1/4	✓
Horiz. Girder 1	PL Girder	60 1/2	17 3/4	1	—	16 1/2	✓	1 1/4	✓
Purlins	ST 10 WF 31	10 1/2	✓	13/32	—	8 1/4	✓	5/8	✓
Skin Plate Bracing	ST 7 WF 15	7	17 1/4	1/4	✓	6 3/4	✓	3/8	✓

(1) Strange divits in skin plate

(2) Bottom member time

(3) (4) (5) (6) (7) (8) (9) (10) (11) (12) (13) (14) (15) (16) (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35) (36) (37) (38) (39) (40) (41) (42) (43) (44) (45) (46) (47) (48) (49) (50) (51) (52) (53) (54) (55) (56) (57) (58) (59) (60) (61) (62) (63) (64) (65) (66) (67) (68) (69) (70) (71) (72) (73) (74) (75) (76) (77) (78) (79) (80) (81) (82) (83) (84) (85) (86) (87) (88) (89) (90) (91) (92) (93) (94) (95) (96) (97) (98) (99) (100)

(11) (12) (13) (14) (15) (16) (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35) (36) (37) (38) (39) (40) (41) (42) (43) (44) (45) (46) (47) (48) (49) (50) (51) (52) (53) (54) (55) (56) (57) (58) (59) (60) (61) (62) (63) (64) (65) (66) (67) (68) (69) (70) (71) (72) (73) (74) (75) (76) (77) (78) (79) (80) (81) (82) (83) (84) (85) (86) (87) (88) (89) (90) (91) (92) (93) (94) (95) (96) (97) (98) (99) (100)

(16) Lacked advance on bottom seal


(17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35) (36) (37) (38) (39) (40) (41) (42) (43) (44) (45) (46) (47) (48) (49) (50) (51) (52) (53) (54) (55) (56) (57) (58) (59) (60) (61) (62) (63) (64) (65) (66) (67) (68) (69) (70) (71) (72) (73) (74) (75) (76) (77) (78) (79) (80) (81) (82) (83) (84) (85) (86) (87) (88) (89) (90) (91) (92) (93) (94) (95) (96) (97) (98) (99) (100)

(17) (18) Drainage hole from bottom girder

(21) Drainage hole from side seal, right


22 23

Gate No. 6 Upstream Elevation



BRAKE MOTOR LOCKED & BUENING @ 25' OPEN 45 min delay

Gate No. 7
 Left Elevation B-B
 Right




Member	Type	Depth d		Web t _w		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b _f		t _f	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 5/8	15/16		15 3/4	15 3/4	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16		16 3/8	16 1/2	2 7/16	2 7/16
Strut 1	14 WF 398	18 1/4	18 5/16	1 13/16		16 5/8	16 1/2	2 13/16	2 3/4
Brace A	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace B	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace C	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace D	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace E	14 WF 30	13 7/8	13 13/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace F	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace G	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 13/16	3/8	3/8
Brace H	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace J	14 WF 30	13 7/8	13 1/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace K	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace L	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 7/8	3/8	3/8
Brace M	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	13 13/16	5/16		6 3/4	6 3/4	3/8	3/8

2. PEELER RUST @ DA F


↳ Deflection in Flange vert. "L" ± 1/4" Deflection

Gate No. 7
 Right Elevation
 A-A



Member	Type	Depth		Web		Flange(s)			
		d		t _w		b _f		t _f	
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 5/8	15/16	15/16	15 3/4	15 3/4	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16	1 9/16	16 3/8	16 7/16	2 7/16	2 7/16
Strut 1	14 WF 398	18 1/4	18 1/4	1 13/16	1 13/16	16 5/8	16 1/2	2 13/16	2 13/16
Brace A	14 WF 30	13 7/8	13 15/16	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace B	14 WF 30	13 7/8	13 15/16	5/16	5/16	6 3/4	6 13/16	3/8	3/8
Brace C	14 WF 30	13 7/8	13 15/16	5/16	5/16	6 3/4	6 7/8	3/8	3/8
Brace D	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace E	14 WF 30	13 7/8	13 15/16	5/16	5/16	6 3/4	6 1/8	3/8	3/8
Brace F	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace G	14 WF 30	13 7/8	13 15/16	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace H	14 WF 30	13 7/8	13 13/16	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace J	14 WF 30	13 7/8	13 15/16	5/16	5/16	6 3/4	6 13/16	3/8	3/8
Brace K	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 13/16	3/8	3/8
Brace L	14 WF 30	13 7/8	13 15/16	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	13 15/16	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8

Gate No. 7 Downstream Elevation





NOTE. PAINT ON GATE FAILING. FLAKY W/ LIGHT RUST

Member	Type	Depth d		Web t _w		Flange - End			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b _r		t _r	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Horiz. Girder 3	PL Girder	49 3/4	49 3/8	7/16	7/16	16	16	7/8	7/8
Horiz. Girder 2	PL Girder	60 1/2	60 1/2	3/4	3/4	16 1/2	16 1/2	1 1/4	1 5/16
Horiz. Girder 1	PL Girder	60 1/2	60 3/8	1	1 1/16	16 1/2	16 1/2	1 1/4	1 5/16
Purlins	ST 10 WF 31	10 1/2	10 3/8	13/32		8 1/4	8 3/16	5/8	5/8
Skin Plate Bracing	ST 7 WF 15	7	7	1/4	1/4	6 3/4	6 3/16	3/8	3/8

- 3. LEAK IN SIDE SEAL W/ STANDING H₂O IN Bot. GIRDER
- 4. Rt. FRAME LIGHT RUST
- 5. Looking left NOTE LIGHT RUST ON ALL MEMBERS
- 6. Standing H₂O ON Bot. GIRDER
- 7. GATE FACE PAINT FAILURE
- 10. SIDE SEAL LEAK W/ LIGHT RUST AND MIN. DEPOSIT
- 11. Bottom Plt. Full of H₂O w/ muck
- 12. Along Bot GIRDER LIGHT RUST ON ALL MEMBERS
- 13. Moderate Rust on Purlin web DUE TO STANDING H₂O
- 14. Moderate Rust on BRACE Pts.

Gate No. 7 Upstream Elevation _____



MUCH BETTER CONDITION THAN GRANITE

EVIDENCE OF PAST WEAR & GRIND

Gate No. 7 Operation and Trunnion Measurements

Racking Measurements: Bottom of Gate and Spillway

LEFT	RIGHT
38 1/2	39


Transverse Trunnion Hub Movement, No Load on Gate: Closed-Open-Closed

	LEFT		RIGHT	
	Inside	Outside (pier)	Inside	Outside (pier)
Initial Gate Closed	23/32	21/32	15/32	23/32
Gate Full Open	24/32	23/32	14/32	24/32
Final Gate Closed	23/32	21/32	15/32	23/32

3-D Trunnion Hub Movements - Unloaded vs. Loaded

	LEFT				RIGHT			
	No Load Void Dry		Full Load Void Full		No Load Void Dry		Full Load Void Full	
Vertical	+0.002		-0.0025		-0.001		-0.012	
US/DS	+0.0005		+0.037		0.0000		+0.0300	
Transverse	23/32	20/32	23/32	21/32	15/32	23/32	16/32	22/32
	Inside	Outside	Inside	Outside	Inside	Outside	Inside	Outside

Gate No. 8
 Left Elevation B-B



Member	Type	Depth d		Web t _w		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b _f		t _f	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 7/16	15/16		15 3/4	15 3/4	1 1/2	1 7/16
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16		16 3/8	16 3/16	2 7/16	2 1/2
Strut 1	14 WF 398	18 1/4	18 1/2	1 13/16		16 5/8	16 3/8	2 13/16	2 15/16
Brace A	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace B	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace C	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 13/16	3/8	3/8
Brace D	14 WF 30	13 7/8	13 11/16	5/16		6 3/4	6 5/16	3/8	3/8
Brace E	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace F	14 WF 30	13 7/8	13 7/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace G	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace H	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace J	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/16	3/8	3/8
Brace K	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace L	14 WF 30	13 7/8	13 3/4	5/16		6 3/4	6 7/8	3/8	3/8
Brace M	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8


2. Light Rust on Vert. Rib "C"

3. Light Flaky Rust on Diagonal "D"

4. Light Rust Contin. Flaking Areas

5. OVER ALL Pic of LEFT Struts Light Rust & Delam. Contin.


Gate No. 8
 Right Elevation
 A-A



Member	Type	Depth d		Web t _w		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b _f		t _f	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 7/8	15/16		15 3/4	15 3/4	1 1/2	1 7/16
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16		16 3/8	16 3/16	2 7/16	2 1/16
Strut 1	14 WF 398	18 1/4	18 1/4	1 13/16		16 5/8	16 4/2	2 13/16	2 1/8
Brace A	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace B	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace C	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace D	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace E	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace F	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace G	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace H	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace J	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace K	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace L	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8

14. Typ Detail on gate
 15, 16 Gate on 2nd sheet from Detail A-B-E

Gate No. 8 Downstream Elevation




NOTE. ENTIRE GATE is peeling w/ light RUST. there is evidence of NEW PAINT @ V. GATE FACE PL.

Member	Type	Depth d		Web t _w		Flange - End			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b _r		t _f	
Horiz. Girder 3	PL Girder	49 3/4	49 3/4	7/16	7/16	16	16	7/8	7/8
Horiz. Girder 2	PL Girder	60 1/2	60 1/2	3/4	3/4	16 1/2	16 1/2	1 1/4	1 1/4
Horiz. Girder 1	PL Girder	60 1/2	60 3/4	1	1 1/16	16 1/2	16 7/16	1 1/4	1 1/4
Purlins	ST 10 WF 31	10 1/2	10 1/2	13/32		8 1/4	8 1/4	5/8	9/16
Skin Plate Bracing	ST 7 WF 15	7	7	1/4	1/4	6 3/4	6 3/4	3/8	3/4

- 6. FAR LEFT Purlins MINERAL Deposits & Light Rust.
- 7. Purlin web Bents.
- 8. GRINDING MARKS AROUND welds (TYP.)
- 9. Brace Plts w/ Debris and evidence of STANDING H₂O
- 10. Along Bot SEAL
- 11. Muck @ Bot. Plt.
- 12. Leak @ Center of gate
- 13. Leak @ LEFT CORNER

Gate No. _____ Upstream Elevation _____



- SOME PITS HAVE BEEN FILLED W/ WELD MATERIAL
- RECORDS SHOULD BE REFERENCED
- OTHER PITS ARE EXISTING
- SMALL PITS
- WEAR PLATES LOOK CLEAN

Gate No. 2 Operation and Trunnion Measurements

Racking Measurements: Bottom of Gate and Spillway


LEFT	RIGHT
45'	45'

Transverse Trunnion Hub Movement, No Load on Gate: Closed-Open-Closed

	LEFT		RIGHT	
	Inside	Outside (pier)	Inside	Outside (pier)
Initial Gate Closed	24/32	14/32	16/32	19/32
Gate Full Open	23/32	16/32	15/32	19/32
Final Gate Closed	23/32	15/32	16/32	19/32

3-D Trunnion Hub Movements - Unloaded vs. Loaded

	LEFT				RIGHT			
	No Load Void Dry		Full Load Void Full		No Load Void Dry		Full Load Void Full	
Vertical	+0.0008		+0.0008		0.0000		-0.0010	
US / DS	+0.0020		+0.0315		+0.0010		+0.0250	
Transverse	23/32	15/32	23/32	14/32	16/32	19/32	16/32	19/32
	Inside	Outside	Inside	Outside	Inside	Outside	Inside	Outside




Little
Goose
Dam

Gate 1
Top horizontal girder looking toward
right frame, typical.

10/16/00

1-1




Little
Goose
Dam

Gate 1
Downstream surface of skin plate.
Light corrosion, typical.

10/16/00

1-2




Little
Goose
Dam

Gate 1
Skin plate at center of gate, 5' above
top horizontal girder. Apparent
previous weld and grind repair.

10/16/00

1-3




Little
Goose
Dam

Gate 1
Top horizontal girder, downstream
flange at connection to left top radial
strut. Light corrosion.

10/16/00

1-4




Little
Goose
Dam

10/16/00

1-5

Gate 1
Left frame, brace C. Light corrosion
beneath connection to top radial strut




Little
Goose
Dam

10/16/00

1-6

Gate 1
Right trunnion block. Light cracking
in concrete.




Little
Goose
Dam

Gate 1
Outside of left trunnion and trunnion
yoke, typical.

10/16/00

1-7




Little
Goose
Dam

Gate 1
Inside of left trunnion and yoke,
typical.

10/16/00

1-8



Little
Goose
Dam
10/16/00
1-9

Gate 1
Side seal, typical. Light to moderate
corrosion on skin plate, side seal
angle, nuts and bolts.



Little
Goose
Dam
10/16/00
1-10

Gate 1
Side seal, typical. Light to moderate
corrosion on skin plate, side seal
angle, nuts and bolts.




Little
Goose
Dam

10/16/00

1-11

Gate 1
Middle horizontal girder looking
toward right frame, typical.




Little
Goose
Dam

10/16/00

1-12

Gate 1
Closure plate inside left trunnion.
Light corrosion.




Little
Goose
Dam

Gate 1
Corner leak at bottom left side of
gate.

10/16/00

I-13



Little
Goose
Dam

Gate 1
Bottom seal closure plate looking
upstream. Standing water between
closure plate, purlin webs and
skinplate. Typical.


10/16/00

I-14



Little
Goose
Dam
10/16/00
1-15

Gate 1
Bottom horiz. girder. Standing
water, no drainage between multiple
stiffeners, typical.




Little
Goose
Dam
10/16/00
1-16

Gate 1
Bottom horiz. girder. Standing
water, no drainage between multiple
stiffeners, typical.



Little
Goose
Dam
10/16/00
1-17

Gate 1
Bottom seal closure plate looking
upstream. Standing water between
closure plate, purlin webs and
skinplate. Typical.



Little
Goose
Dam
10/16/00
1-18


Gate 1
Bottom seal keeper plate and
embedded bottom seal plate, typical.



Little Goose Dam	Gate 1 Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate. Typical.
10/16/00	
1-19	



Little Goose Dam	Gate 1 Bottom of bottom horizontal girder at stiffeners for bottom left radial strut. Light to moderate corrosion due to horiz. girder drain hole above.
10/16/00	
1-20	




Little
Goose
Dam

Gate 1
Left trunnion block. Light cracking
in concrete.

10/16/00

1-21




Little
Goose
Dam

Gate 1
Gate face, typical.

10/16/00

1-22




Little
Goose
Dam

Gate 1
Left frame, typical.

10/16/00

1-23




Little
Goose
Dam

Gate 1
Leak at center construction joint in
spillway monolith.

11/21/00

1-24




Little
Goose
Dam

Gate 1
Typical condition of skin plate.
Scattered pitting.

10/20/00


1-25



Little
Goose
Dam

Gate 1
Top of hoist connection. Note:
Good condition of stainless steel U-
bolts and socket blocks.

10/20/00



Little
Goose
Dam

10/20/00

1-27

Gate 1

Top of hoist connection. Note:
Good condition of stainless steel U-
bolts and socket blocks.




Little
Goose
Dam

10/20/00

1-28


Gate 1

Skin plate pitting, typical.




Little
Goose
Dam
10/20/00
1-29

Gate 1
Bottom of right side of gate at 3'
open. Note: Heavy falling water due
to stop log leakage precludes
inspection of hoist connections.



Little
Goose
Dam
10/20/00
1-30

Gate 1
Bottom of left side of gate at 3'
open. Note: Heavy falling water due to
stop log leakage precludes inspection
of hoist connections.



Little
Goose
Dam

Gate 2
Right frame, typical.

10/17/00

2-1




Little
Goose
Dam

Gate 2
Top of top horizontal girder looking
towards right frame, typical.

10/17/00

2-2




Little
Goose
Dam

10/17/00

2-3

Gate 2
Outside of left trunnion and yoke,
typical.



Little
Goose
Dam

10/17/00

2-4

Gate 2
Right trunnion and trunnion block,
typical.




Little
Goose
Dam
10/17/00
2-5

Gate 2
Bottom horizontal girder, left end.
Standing water, no drainage between
multiple stiffeners, typical.



Little
Goose
Dam
10/17/00
2-6

Gate 2
Side seal leak, right end of bottom
horizontal girder.




Little
Goose
Dam

Gate 2
Right frame, typical.

10/17/00

2-7



Little
Goose
Dam

Gate 2
Brace H, left frame. Light corrosion
on web.

10/17/00

2-8




Little
Goose
Dam

Gate 2
Leak at center construction joint in
spillway monolith.

10/17/00

2-9



Little
Goose
Dam

Gate 2
Left frame between brace J and K.
Debris at upstream end of bottom
radial strut.

10/17/00

2-10




Little
Goose
Dam
10/17/00
2-11

Gate 2
Bottom horizontal girder, left end.
Standing water, no drainage between
multiple stiffeners, typical.



Little
Goose
Dam
10/17/00
2-12

Gate 2
Bottom horizontal girder, Right end.
Standing water, no drainage between
multiple stiffeners, typical.



Little
Goose
Dam

Gate 2
Left frame, typical.

10/17/00

2-13



Little
Goose
Dam


Gate 2
Leak, bottom left corner of gate.
Bottom seal closure plate. Standing
water between closure plate, purlin
webs and skinplate. Typical.

10/17/00


2-14



Little Goose Dam	Gate 2 Leak at center construction joint in spillway monolith.
10/17/00	
2-15	




Little Goose Dam	Gate 2 Bottom seal keeper plate, light corrosion. Embedded bottom seal plate, typical.
10/17/00	
2-16	




Little
Goose
Dam
10/17/00
2-17

Gate 2
Inside closure plate at right trunnion.
Light corrosion and staining from
drain hole above.



Little
Goose
Dam
10/17/00
2-18

Gate 2
Side seal leak, right side of gate.



Little
Goose
Dam

Gate 2
Right trunnion block, typical.

10/17/00

2-19



Little
Goose
Dam

Gate 2
Extraneous holes, top plate at
purlins.

10/17/00

2-20



Little
Goose
Dam

Gate 2
Bottom seal keeper plate, typical.

10/20/00

2-21




Little
Goose
Dam

Gate 2
Bottom seal, typical.

10/20/00

2-22



Little
Goose
Dam

10/20/00

2-23

Gate 2
Right hoist connection and zinc
anodes. Light corrosion on lifting
lugs.



Little
Goose
Dam

10/20/00

2-24

Gate 2
Zinc anodes, good condition.



Little
Goose
Dam

Gate 2
Bottom of hoist connection. Light
corrosion on plates.

10/20/00

2-25



Little
Goose
Dam

Gate 2
Unidentified metal clamp near hoist
connection.

10/20/00

2-26



Little
Goose
Dam

10/20/00

2-27

Gate 2

Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate. Typical.




Little
Goose
Dam

10/20/00

2-28

Gate 2

Skin plate pitting, typical.



Little
Goose
Dam

Gate 2
Skin plate pitting, typical.

10/20/00

2-29




Little
Goose
Dam

Gate 2
Skin plate pitting, typical.

10/20/00

2-30



Little
Goose
Dam

Gate 2
Skin plate condition, typical.

10/20/00

2-31



Little
Goose
Dam

Gate 2
Top of hoist connection.


10/20/00

2-32




Little
Goose
Dam
10/20/00
2-33

Gate 2
Delaminates vinyl, right side of wear
plate, just below skin plate transition
from 3/8" to 1/2".



Little
Goose
Dam
10/20/00
2-34

Gate 2
Skin plate pitting adjacent to wear
plate, typical.



Little
Goose
Dam

Gate 3
Left side of gate. Light corrosion on
members.

10/12/00

3-1




Little
Goose
Dam

Gate 3
Left frame, middle radial strut,
typical.

10/12/00

3-2



Little
Goose
Dam

Gate 3
Left frame, typical.

10/12/00

3-3




Little
Goose
Dam

Gate 3
Left frame, Brace A. Light corrosion
on upstream side.

10/12/00

3-4




Little
Goose
Dam

Gate 3
Middle horizontal girder bracing.
Light corrosion on braces.

10/12/00

3-5



Little
Goose
Dam

Gate 3
Middle radial strut, left frame. Light
corrosion on strut.

10/12/00

3-6



Little
Goose
Dam

10/12/00

3-7

Gate 3

Bottom horiz. girder, left end.
Standing water, no drainage between
multiple stiffeners, typical.




Little
Goose
Dam

10/12/00

3-8

Gate 3

Standing water between closure plate,
purlin webs and skinplate, typical.
Light corrosion around drain hole at
upstream side of bottom radial strut.



Little
Goose
Dam

10/12/00

3-9

Gate 3
Side seal leak, bottom left corner of gate. Standing water between closure plate, purlin webs and skinplate, typical.



Little
Goose
Dam

10/12/00

3-10

Gate 3
Standing water between closure plate, purlin webs and skinplate, typical.



Little
Goose
Dam

Gate 3
Leak at center construction joint in
spillway monolith.

10/12/00

3-11



Little
Goose
Dam

Gate 3
Bottom horizontal girder, right end.
Standing water, no drainage between
multiple stiffeners, typical.

10/12/00

3-12




Little
Goose
Dam

10/12/00

3-13

Gate 3

Close-up, bottom horizontal girder.
Standing water, no drainage between
multiple stiffeners, typical.



Little
Goose
Dam

10/12/00

3-14

Gate 3

Bottom side of right frame, typical.




Little
Goose
Dam

Gate 3
Top of side seal, typical.

10/12/00

3-15



Little
Goose
Dam

Gate 3
Top upstream skinplate at hoist
cables. Moderate corrosion on
unidentified metal.

10/12/00

3-16



Little
Goose
Dam

10/19/00

3-17

Gate 3

Bottom of left side of gate at 3' open.
Note: Heavy falling water due to stop log leakage precludes inspection of hoist connections.




Little
Goose
Dam

10/19/00

3-18

Gate 3

Bottom of right side of gate at 3' open. Note: Heavy falling water due to stop log leakage precludes inspection of hoist connections.




Little
Goose
Dam

Gate 3
Skin plate condition, typical.
Minimal pitting.

10/19/00

3-19




Little
Goose
Dam

Gate 3
Hoist connection, right side of gate.

10/19/00

3-20




Little
Goose
Dam

Gate 3
Hoist connection, left side of gate.

10/19/00

3-21




Little
Goose
Dam

Gate 4
Skin plate purlin, right side of gate
above top horizontal girder. Light
corrosion on purlin flange.

10/12/00

4-1



Little
Goose
Dam

Gate 4
Top horizontal girder. Light
corrosion, typical.

10/12/00

4-2




Little
Goose
Dam

10/12/00

4-3

Gate 4

Downstream side of skin plate, right side of gate above top horizontal girder. Possible previous skin plate repair.




Little
Goose
Dam

10/12/00

4-4

Gate 4

Bottom horizontal girder, left side. Standing water, no drainage between multiple stiffeners, typical. Side seal leak.



Little
Goose
Dam

Gate 4
Right frame, brace K. Light corrosion
on brace.

10/12/00

4-5




Little
Goose
Dam

Gate 4
Downstream side of skin plate, above
middle horizontal girder, right side of
gate. Small circular protrusion in
vertical line on skin plate.

10/12/00

4-6



Little
Goose
Dam

10/12/00

4-7

Gate 4
Downstream side of skin plate, right
side of gate above bottom horizontal
girder. Possible previous skin plate
repair.



Little
Goose
Dam

10/12/00

4-8

Gate 4
Brace J, left frame. Small scratches
on web.



Little
Goose
Dam

10/12/00

4-9

Gate 4

Bottom horizontal girder, right side.
Standing water, no drainage between
multiple stiffeners, typical. Side seal
leak.




Little
Goose
Dam

10/12/00

4-10


Gate 4

Bottom seal closure plate looking
upstream. Standing water between
closure plate, purlin webs and
skinplate. Typical.




Little
Goose
Dam
10/12/00
4-11

Gate 4
Standing water between closure plate,
purlin webs and skinplate, typical.
Bottom right corner seal leak.



Little
Goose
Dam
10/12/00
4-12

Gate 4
Leak at center construction joint in
spillway monolith.




Little
Goose
Dam

Gate 4
Leak at center construction joint in
spillway monolith.

10/12/00

4-13



Little
Goose
Dam

Gate 4
Bottom of bottom horizontal girder,
upstream flange and stiffener.
Moderate corrosion due to horizontal
girder drain hole above.

10/12/00

4-14



Little
Goose
Dam
10/12/00
4-15

Gate 4
Bottom of bottom horizontal girder.
Drain hole for upstream side of
bottom horizontal girder. Light to
moderate corrosion on surrounding
members.



Little
Goose
Dam
10/12/00
4-16

Gate 4
Bottom of bottom horizontal girder.
Drain hole for upstream side of
bottom horizontal girder. Light to
moderate corrosion on surrounding
members.




Little
Goose
Dam
10/12/00
4-17

Gate 4
Bottom of bottom horizontal girder,
light corrosion on girder, stiffeners
and purlins.



Little
Goose
Dam
10/12/00
4-18

Gate 4
Bottom horizontal girder, left side.
Standing water, no drainage between
multiple stiffeners, typical. Side seal
leak.



Little Goose Dam	Gate 4 Brace N, left frame. Light corrosion on brace web and flanges.
10/12/00	
4-19	



Little Goose Dam	Gate 4 Bottom horizontal girder, left side. Standing water, no drainage between multiple stiffeners, typical. Side seal leak.
10/12/00	
4-20	




Little
Goose
Dam

Gate 4
Side seal leak, left side of gate.

10/12/00

4-21




Little
Goose
Dam

Gate 4
Side seal plates, nuts and bolts,
typical.

10/12/00

4-22




Little
Goose
Dam

Gate 4
Downstream side of skin plate.
Evidence of previous repairs.

10/12/00

4-23



Little
Goose
Dam

Gate 4
Top horizontal girder, left side. 2" to
3" deformation upward in girder
web.

10/19/00

4-24



Little
Goose
Dam

Gate 4
Waterblasting and skin plate
condition, minimal pitting, typical.

10/19/00

4-25




Little
Goose
Dam

Gate 4
Bottom left corner of gate, typical.

10/19/00

4-26




Little
Goose
Dam

Gate 4
Bottom seal keeper plate, typical.

10/19/00

4-27




Little
Goose
Dam

Gate 4
Right hoist connection. Moderate
corrosion on lifting lugs, and plates.

10/19/00

4-28




Little
Goose
Dam

Gate 4
Right hoist connection. Moderate
corrosion on lifting lugs, and plates.

10/19/00

4-29




Little
Goose
Dam

Gate 4
Bottom seal and bottom upstream
side of skin plate. Moderate
corrosion at bottom edge of skin
plate.

10/19/00

4-30




Little
Goose
Dam

10/19/00

4-31

Gate 4
Bottom seal, typical.




Little
Goose
Dam

10/19/00

4-32

Gate 4
Skin plate condition, minimal pitting,
typical.




Little
Goose
Dam

Gate 4
Skin plate pitting, where present,
typical.

10/19/00

4-33



Little
Goose
Dam

Gate 4
Side seal angles, wear plate and side
seal, typical.

10/19/00


4-34



Little Goose Dam	Gate 4 Side seal angles, side seal, and side seal, typical
------------------------	--

10/19/00

4-35



Little
Goose
Dam


Gate 5

Downstream side of skin plate, left
side of gate, above top horiz. girder.
Peeling pain, light corrosion.

10/11/00

Appears to be possible paint blister
due to upstream skin plate welding.

5-1



Little
Goose
Dam


Gate 5

Downstream side of skin plate, left
side of gate, above top horiz. girder.
Peeling pain, light corrosion.

10/11/00


Appears to be possible paint blister
due to upstream skin plate welding.

5-2




Little
Goose
Dam
10/11/00
5-3

Gate 5
Top horizontal girder, left side of
gate. Light corrosion on girder web,
purlins, braces.



Little
Goose
Dam
10/11/00
5-4

Gate 5
Left frame, Brace D. light corrosion
and brace.



Little
Goose
Dam

10/11/00

5-5

Gate 5

Middle horizontal girder, left end.
Light corrosion on girder, braces and
skin plate.



Little
Goose
Dam

10/11/00

5-6

Gate 5

Downstream side of skin plate, left
side of gate, above middle horiz.
girder. Peeling pain, light corrosion.
Appears to be possible paint blister
due to upstream skin plate welding.




Little
Goose
Dam

10/11/00

5-7

Gate 5

Bottom horizontal girder, left end.
Standing water, no drainage between
multiple stiffeners, typical.




Little
Goose
Dam

10/11/00

5-8

Gate 5

Let frame, Brace J. Light corrosion
on bottom radial strut and brace.




Little
Goose
Dam

Gate 5
Leak at center construction joint in
spillway monolith.

10/11/00

5-9



Little
Goose
Dam

Gate 5
Bottom left corner of gate, bottom
seal leak. Bottom seal closure plate.
Standing water between closure plate,
purlin webs and skinplate, typical.


10/11/00

5-10




Little
Goose
Dam
10/11/00
5-11

Gate 5
Bottom seal closure plate. Standing
water between closure plate, purlin
webs and skinplate, typical.



Little
Goose
Dam
10/11/00
5-12

Gate 5
Left frame, typical.




Little
Goose
Dam

Gate 5
Gate face, typical.

10/11/00

5-13




Little
Goose
Dam

Gate 5
Left trunnion block. Light cracking
in concrete.

10/11/00

5-14




Little
Goose
Dam

10/11/00

5-15

Gate 5

Top of right trunnion. Standing water due to inadequate drainage in top radial strut web.




Little
Goose
Dam

10/18/00

5-16

Gate 5

Top of right hoist connection. Light corrosion on lifting lugs and plates.




Little
Goose
Dam

Gate 5

10/11/00

5-17



Little
Goose
Dam

Gate 5


10/11/00

5-18




Little
Goose
Dam
10/11/00
5-19

Gate 5



Little
Goose
Dam
10/11/00
5-20

Gate 5




Little
Goose
Dam

Gate 5
Bottom seal keeper plate, typical.

10/18/00

5-21




Little
Goose
Dam

Gate 5
Waterblasting and typical skin plate
condition. Minimal pitting on skin
plate (except for wear plates).


10/18/00

5-22




Little
Goose
Dam
10/18/00
5-23

Gate 5
Heavy pitting on wear plate, typical.



Little
Goose
Dam
10/18/00
5-24

Gate 5
Heavy pitting on wear plate, typical.




Little
Goose
Dam

Gate 5
Heavy pitting on wear plate, typical.

10/18/00

5-25



Little
Goose
Dam

Gate 6
Left frame, Brace B. Light corrosion
on brace (see photo 6-2).

10/11/00

6-1




Little
Goose
Dam

Gate 6
Left frame, Brace B. Light corrosion
on brace.


10/11/00

6-2




Little
Goose
Dam
10/11/00
6-3

Gate 6
Downstream side of skin plate, left
side of gate, above middle horizontal
girder. Apparent skin plate repair.



Little
Goose
Dam
10/11/00
6-4


Gate 6
Left frame, brace D. Light corrosion.



Little
Goose
Dam

10/11/00
6-5

Gate 6
Downstream side of skin plate, left
side of gate, above middle horizontal
girder. Discolorization due to
apparent repainting and possible skin
plate repair.




Little
Goose
Dam

10/11/00
6-6


Gate 6
Left frame, middle radial strut. Light
pitting on outside flange.



Little Goose Dam 10/11/00 6-7	Gate 6 Downstream side of skin plate, apparent skin plate repair grinding.
---	---



Little Goose Dam 10/11/00 6-8	Gate 6 Light corrosion and debris coating on braces, typical.
---	--




Little
Goose
Dam

10/11/00

6-9

Gate 6
Gate face and spillway, typical. Leak
at center construction joint in spillway
monolith.



Little
Goose
Dam

10/11/00


6-10

Gate 6
Bottom horizontal girder. Standing
water, no drainage between multiple
stiffeners, typical. Horizontal girder
to skin plate stiffeners, standing
water, debris and no drainage.




Little
Goose
Dam
10/11/00
6-11

Gate 6
Bottom horizontal girder. Standing
water, no drainage between multiple
stiffeners, typical. Horizontal girder
to skin plate stiffeners, standing
water, debris and no drainage.




Little
Goose
Dam
10/11/00
6-12

Gate 6
Bottom horizontal girder. Evidence
of standing water on girder web and
flange.




Little
Goose
Dam
10/11/00
6-13

Gate 6
Bottom seal keeper plate, typical.
Bottom seal closure plate, standing
water between closure plate, purlin
webs and skinplate, typical.



Little
Goose
Dam
10/11/00
6-14

Gate 6
Leak at center construction joint in
spillway monolith.



Little
Goose
Dam

10/11/00

6-15

Gate 6

Bottom seal closure plate, standing
water between closure plate, purlin
webs and skinplate, typical.




Little
Goose
Dam

10/11/00

6-16

Gate 6

Bottom of bottom horizontal girder
at radial strut connection and girder
drain hole. Light corrosion on girder
web and stiffeners.




Little
Goose
Dam

10/11/00

6-17

Gate 6

Bottom of bottom horizontal girder
at radial strut connection and girder
drain hole. Light corrosion on girder
web and stiffeners.



Little
Goose
Dam

10/11/00

6-18

Gate 6

Leak at center construction joint in
spillway monolith. Light corrosion
on bottom seal keeper plate.




Little
Goose
Dam

10/11/00

6-19

Gate 6

Bottom of bottom horizontal girder
at radial strut connection and girder
drain hole. Light corrosion on girder
web and stiffeners.




Little
Goose
Dam

10/11/00

6-20

Gate 6

Bottom seal closure plate, standing
water between closure plate, purlin
webs and skinplate, typical.




Little
Goose
Dam

10/11/00

6-21

Gate 6
Side seal leak, bottom left side of
gate. Light corrosion on purlin,
horizontal girder and girder
stiffeners.




Little
Goose
Dam

10/11/00

6-22

Gate 6
Side seal leak, bottom right side of
gate. Light corrosion on purlin,
horizontal girder and girder
stiffeners.




Little
Goose
Dam

10/11/00

6-23

Gate 6

Bottom horizontal girder. Standing water, no drainage between multiple stiffeners, typical. Horizontal girder to skin plate stiffeners, standing water, debris and no drainage.




Little
Goose
Dam

10/11/00

6-24

Gate 6

Bottom horizontal girder. Standing water, no drainage between multiple stiffeners, typical. Horizontal girder to skin plate stiffeners, standing water, debris and no drainage.



Little
Goose
Dam

Gate 6
Bottom seal keeper plate, typical.

10/18/00

6-25




Little
Goose
Dam


Gate 6
Bottom seal keeper plate, typical.

10/18/00


6-26



Little Goose Dam	Gate 6 Left hoist connection and anodes. Light to moderate corrosion on lifting lugs and plates. Note: Extra anode under hoist connection not found on other gates.
10/18/00	
6-27	



Little Goose Dam	Gate 6 Hoist connection anodes, typical.
10/18/00	
6-28	




Little
Goose
Dam

10/18/00

6-29

Gate 6
Close-up hoist connection. Light to moderate corrosion on lifting lugs and plates.




10 18 00

Little
Goose
Dam

10/18/00

6-30

Gate 6
Close-up, embedded bottom seal in spillway.




Little
Goose
Dam

10/18/00

6-31

Gate 6

Right hoist connection. Light to moderate corrosion on lifting lugs and plates.



Little
Goose
Dam

10/18/00

6-32

Gate 6

Right hoist connection. Light to moderate corrosion on lifting lugs and plates. Note: Generally good condition of anodes.



Little
Goose
Dam

10/18/00

6-33

Gate 6
Apparent previous anode bracket.



Little
Goose
Dam

10/18/00

6-34

Gate 6
.Skin plate pitting, typical.




Little
Goose
Dam

Gate 6
Skin plate condition, typical.
Minimal skin plate pitting.

10/18/00

6-35



Little
Goose
Dam

Gate 6
Skin plate condition, typical.
Minimal skin plate pitting.

10/18/00

6-36



Little
Goose
Dam

Gate 6
Left wear plate. Delaminated vinyl
coating.

10/18/00

6-37




Little
Goose
Dam

Gate 6
Left wear plate. Delaminated vinyl
coating.

10/18/00

6-38




Little
Goose
Dam

Gate 6
Upstream side of side seal, typical.

10/18/00

6-39



Little
Goose
Dam

Gate 6
Light pitting along skin plate weld,
typical.

10/18/00

6-40



Little
Goose
Dam

10/11/00

7-1

Gate 7
Right frame, brace F. Loose moderate
corrosion on brace.




Little
Goose
Dam

10/11/00


7-2

Gate 7
Bottom horizontal girder, right end.
Standing water, no drainage between
multiple stiffeners, typical.




Little
Goose
Dam
10/11/00
7-3

Gate 7
Left frame, Brace A. Light corrosion
on brace, radial strut and horizontal
girder.



Little
Goose
Dam
10/11/00
7-4

Gate 7
Middle horizontal girder, typical.




Little
Goose
Dam

Gate 7
Right frame, Brace L. Small
deformation in brace flange.

10/11/00

7-5




Little
Goose
Dam

Gate 7
Bottom horizontal girder, right end.
Standing water on girder web due to
inadequate drainage and side seal
leak.

10/11/00

7-6



Little
Goose
Dam

10/11/00

7-7

Gate 7
Skin plate purlins, typical.



Little
Goose
Dam

10/11/00


7-8

Gate 7
Bottom right corner of gate, side seal
leak.




Little
Goose
Dam
10/11/00
7-9

Gate 7
Bottom seal closure plate looking
upstream. Standing water between
closure plate, purlin webs and
skinplate. Typical.



Little
Goose
Dam
10/11/00
7-10


Gate 7
Bottom of bottom horizontal girder,
typical.



Little Goose Dam	Gate 7 Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate, typical.
10/11/00	
7-11	



Little Goose Dam	Gate 7 Bottom horizontal girder, left end. Standing water, no drainage between multiple stiffeners, typical.
10/11/00	
7-12	



Little
Goose
Dam

10/17/00

7-13

Gate 7
Bottom seal closure plate. Standing
water between closure plate, purlin
webs and skinplate, typical.




Little
Goose
Dam

10/17/00

7-14

Gate 7
Bottom seal closure plate. Standing
water between closure plate, purlin
webs and skinplate, typical.




Little
Goose
Dam

10/17/00

7-15

Gate 7

Stop log leakage precluding
inspection of hoist connections from
bottom.




Little
Goose
Dam

10/17/00

7-16

Gate 7

Bottom of gate and bottom seal
keeper plate, typical. Stop log
leakage precluding inspection of
hoist connections from bottom.



Little
Goose
Dam

10/17/00

7-17

Gate 7
Bottom seal keeper plate, typical.
Stop log leakage precluding
inspection of hoist connections from
bottom.




Little
Goose
Dam

10/17/00

7-18

Gate 7
Skin plate condition, typical.




Little
Goose
Dam

Gate 7
Skin plate pitting, typical.

10/17/00

7-19




Little
Goose
Dam

Gate 7
Skin plate pitting, typical.

10/17/00

7-20



Little
Goose
Dam

Gate 7
Skin plate pitting, typical.

10/17/00

7-21




Little
Goose
Dam

Gate 7
Skin plate pitting, typical.

10/17/00

7-22



Little
Goose
Dam

Gate 7
Upstream side of side seal, typical.

10/17/00

7-23



Little
Goose
Dam

Gate 7
Wear plate condition, typical.

10/17/00

7-24



Little
Goose
Dam

Gate 7
Waterblasting skin plate.

10/17/00

7-25




Little
Goose
Dam

Gate 7
Hoist connection, from above.

10/17/00

7-26



Little
Goose
Dam

10/17/00

7-27

Gate 7

Hoist connection from above. Light to moderate corrosion on lifting lugs and plates. Stainless steel U-bolts and socket blocks in good condition.




Little
Goose
Dam

Gate 8
Left frame Brace C. Light corrosion
on brace, typical.

10/10/00

8-1




Little
Goose
Dam

Gate 8
Close-up, left frame Brace D. Light
corrosion on brace, typical.

10/10/00

8-2



Little
Goose
Dam

Gate 8
Left frame Brace G. Light corrosion
on brace, typical.

10/10/00

8-3




Little
Goose
Dam

Gate 8
Outside of left frame, typical.

10/10/00

8-4




Little
Goose
Dam

Gate 8
Left end, middle horizontal girder.
Light corrosion on girder, purlins.

10/10/00

8-5




Little
Goose
Dam

Gate 8
Downstream surface of skin plate, left
side of gate above middle horizontal
girder. Apparent grind marks from
weld repair.

10/10/00

8-6



Little
Goose
Dam

10/10/00

8-7

Gate 8
Downstream surface of skin plate, left
side of gate above middle horizontal
girder. Apparent grind marks from
weld repair.




Little
Goose
Dam

10/10/00

8 8

Gate 8
Bottom horizontal girder. Standing
water, no drainage between multiple
stiffeners, typical. Girder flange to
skin plate stiffeners, standing water,
no drainage.



Little
Goose
Dam

10/10/00

8-9

Gate 8

Bottom seal keeper plate, light corrosion, typical. Leak at center construction joint in spillway monolith.




Little
Goose
Dam

10/10/00


8-10

Gate 8

Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate, typical.




Little Goose Dam	Gate 8 Bottom seal closure plate, standing water between closure plate, purlin webs and skinplate, typical. Leak at center construction joint in spillway monolith.
10/10/00	
8-11	



Little Goose Dam	Gate 8 Side seal leak, bottom left side of gate.
10/10/00	
8-12	

c




Little
Goose
Dam

Gate 8
Outside of right frame, typical.

10/10/00

8-13




Little
Goose
Dam

Gate 8
Right frame, middle radial strut,
standing water between girder
flanges due to drain above (see photo
8-15).

10/10/00

8-14



Little
Goose
Dam

Gate 8
Drain in right pier wall, draining on
gate members.

10/10/00

8-15




Little
Goose
Dam

Gate 8
Typical upstream skin plate
condition, heavy concentration of
pitting.

10/10/00

8-16




Little
Goose
Dam

10/10/00

8-17

Gate 8

Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate, typical.




Little
Goose
Dam

10/10/00

8-18

Gate 8

Bottom seal keeper plate, typical.




Little
Goose
Dam

10/10/00

8-19

Gate 8
Embedded bottom seal plate. Note:
heavy flow due to stop log leakage.



Little
Goose
Dam

10/10/00

8-20

Gate 8
Bottom left corner of gate. Bottom
seal closure plate looking upstream.
Standing water between closure
plate, purlin webs and skinplate,
typical.



Little
Goose
Dam

Gate 8
Skin plate pitting, typical.

10/10/00

8-21




Little
Goose
Dam

Gate 8
Skin plate, typical.

10/10/00

8-22




Little
Goose
Dam

10/10/00

8-23

Gate 8

Cable wear plate, typical condition.
Light to moderate corrosion, minimal
cable wear.



Little
Goose
Dam

Hoist and Mechanical
Hoist, typical.


M-1



Little
Goose
Dam

Hoist and Mechanical
Amperage readings during
operational testing, typical.


M-2



Little
Goose
Dam

Hoist and Mechanical
Amperage readings during
operational testing, typical.


M-3



Little
Goose
Dam

Hoist and Mechanical
Seized motor brake on Gate 6 during
operational testing.


M-4



Little
Goose
Dam

Hoist and Mechanical
Seized motor brake on Gate 6 during
operational testing.


M-5




Little
Goose
Dam

Hoist and Mechanical
Hoist, typical.

M-6



<p>Little Goose Dam</p>	<p>Hoist and Mechanical Hoist, name plate, typical.</p>
<p>M-7</p>	




<p>Little Goose Dam</p>	<p>Hoist and Mechanical Hoist, typical.</p>
<p>M-8</p>	



Little
Goose
Dam

Hoist and Mechanical
Hoist, name plate, typical.


M-9



Little
Goose
Dam

Hoist and Mechanical
Hoist, typical.

M-10



Little
Goose
Dam

Hoist and Mechanical
Hoist, typical.


M-11

REVISIONS
 Δ REVISED TO SUIT
 APPL 10-3-66
 CANILL
 QW

Δ ADDED WORK POINT DIM'S FOR STEEL BRACING TO ELEVATION VIEW
 4-19-67
 H. DUB.
 CANILL

Δ ADDED SECT X-X & GENERAL DIMENSIONS AT ELEV 6-18-67
 JED
 CANILL

Δ ADDED SECT MARKS TO SUIT E31
 7/27-67 CANILL
 H. DUB.




D/S ELEVATION

NOTE: SKIN & BRACES MK44A, 44B, 44C, 44D, 43A, 43B, 43C, 43D. SHOP WILL CHECK FOR FIT AT SHOP ASSY, TACK WELDING ONLY AS NECESSARY. MATCH MARK FOR SHIPPING

①

MK 30B SHALL BE LOCATED SO THAT THEY WILL ALIGN WITH EMBEDDED REFERENCE MEMBER (ITEM 99 DWG 79) WHEN VERTICAL DISTANCE BETWEEN BOTTOM OF GATE & SILL IS 6'0" & 12'0".



U/S ELEVATION

REFERENCE CONT'D.
CORP. OF ENGR DWG N° LGD1-5-8/4, SHT 89 VOL1 REV A
SPEC'5: PAGE TP-16-1, SECT 16

REFERENCE
CORP. OF ENGR DWG N° LGD1-5-8/1 SHT 85 VOL1 REV B
LGD1-5-8/2 86 REV B
LGD1-5-8/3 87 REV B
LGD1-5-8/4 88 REV B

- * THIS WELD SHALL BE 100% INSPECTED BY RADIOGRAPHY
- * ALL SKIN PLATE VERTICAL SPLICES SHALL BE INSPECTED BY RADIOGRAPHY IN WAY OF GIRDES

CONTRACT N° DA-45-164 CIVENG-65-560

APPROVED

Subject to conformity with plans and specifications, correction of errors or omissions, and to all future of any required work. Approval does not cover detail distortion, or acceptability for assembling and casting.

OFFICE OF RESIDENT ENGINEER
LITTLE GOOSE LOCK AND DAM

ras
Date: 18 Aug 67

NOTE: ERECT PIECES WITH MARKS ON STEEL AT SAME END AS SHOWN ON PLAN.
FIELD CONNECTIONS:

PACIFIC CAR AND FOUNDRY COMPANY
80 S. HUDSON ST. PA. 2-3000
SEATTLE, WASHINGTON 98134

LITTLE GOOSE LOCK & DAM
ITEM 101- SPILLWAY GATE
CONNINELL, MANNIX, FULLER, DILLINGHAM
DR. HILL DATE 7/16/66 CON. DATE 5-18-66

ERECTION 6670-10101

DATE: 8/18/67
DRAWN BY: ras
CHECKED BY: ras
APPROVED BY: ras
DATE: 18 Aug 67

E 30

322-LTG-65-560-101-D01-188


(3)

MAR 19 1968


REVISIONS
 Δ REVISED TO SUIT APPL
 10-3-66
 CAHILL
 CW

Δ REVISED DETAIL M.F.N.
 @ SHOP REQ.
 4-9-67 H.Bos
 CAHILL

Δ REVISED ERECT. DETAIL
 7/27/67 CAH
 H.Bos




SECT. A-A



SECT C-C

TYP.




DETAIL B


①

BOLT (ST. 9TL) X 0-2 1/2
NUT (M. 9TL) & FLATWASHER (ST 9TL)


BOLT (ST 9TL) X 0-3/4
NUT (M. 9TL) & LOCKWASHER (ST 9TL)



SECT D-D




DETAIL P
TYPICAL FOR U/S END OF A
SPlice TO GIRDERS AS SH




SECT F-F
TYP. FOR SKIN R SPLICE


NOTE: REMOVE ERECTION
CLIPS & PLUG WELD HOLES



DETAIL M
TYP FOR LOWER STRUT




DETAIL N
TYP FOR CENTER STRUT
UPPER STRUT. SIM. EXCEPT
AS NOTED




SECT. H'-H' (SHT. E. 30)
TYPE SPLICES OF SKIN SECTIONS

NOTE: REMOVE BOLT
& PLUG WELD HOLES



SECT H-H
SHT. E. 30

NOTE: REMOVE STUD & CLIP.
TO COMPLETE
FIELD WELD.



DETAIL K

CONTRACT NO DA-45-164 CIVENG-65-560

APPROVED
AS CORRECTED


Subject to conformity with plans and specifications
on which all errors or omissions, and to fulfillment
of any special tests Approved does not bear any
liability, or responsibility for accepting and
installing.

OFFICE OF RESIDENT ENGINEER
LITTLE ROCK LOCK AND DAM

18 Aug 67


Date: 18 Aug 67

2




REMOVE CLIPS TO COMPLETE FIELD WELD; PLUG WELD HOLES IN STRUT FLANGE

1" MACH BOLT X 0-4 1/2 (LOWER STRUT)
 1" MACH BOLT X 0-4 1/2 (CENTER STRUT)
 1" MACH BOLT X 0-3 1/2 (UPPER STRUT)




DETAIL P
 TYPICAL FOR U/S END OF ALL STRUT
 SPLICE TO GIRDERS AS NOTED



DETAIL M
 TYP FOR LOWER STRUT

STUD & CLIP
 MOVE BOLT
 PLUG WELD HOLES



DETAIL N
 TYP FOR CENTER STRUT
 UPPER STRUT SIM. EXCEPT
 AS NOTED


NOTE: REMOVE ERECTION CLIPS & PLUG WELD HOLES

AS BUILT

REFERENCE

CORPS OF ENGR DWG	LGDI-5-81	SHT 85	VOLI	REV B
1-5-82	86			B
1-5-83	87			B
1-5-84	88			B
1-5-85	89			A

SPECS: PAGE TP-16-1, SECT. 16



CONTRACT NO DA-45-164 CIVENG-65-560

**APPROVED
 AS CORRECTED**

Subject to conformity with plans and specifications, as
 correction of errors or omissions, and to satisfaction
 of any required tests. Approval does not cover details
 dimensions, or accessibility for inspection and
 fastenings.

OFFICE OF RESIDENT ENGINEER
 LITTLE GOOSE LOCK AND DAM

Date: 18 Aug 62

NOTE: ERECT PIECES WITH MARKS ON STEEL AT
 SAME END AS SHOWN ON PLAN.

FIELD CONNECTIONS:

PACIFIC CAR AND FOUNDRY COMPANY
 80 S. HUDSON ST. PA. 3-0228
 SEATTLE, WASHINGTON 98126

LITTLE GOOSE LOCK & DAM
 ITEM 101, SPILLWAY GATE
 FOR VINNELL, MANNIX, ELLER, DILLINGHAM
 DR. HILL DATE 4/6/61 CONC. BY DATE 5-14-66

ERECTOR: **ERECTOR** C610-10101
 APPROVED: *P.O. Knudson* E 313

LTG-65-560-002 383


3

MAR 19 1960

REVISIONS
 Δ REVISED PERCONE
 44
 10-3-66
 CA Hill
 000

Δ ADDED FIELD WELD DETAILS
 CA Hill 9/23/67

TRUNNION (MK39A^R)



REMOVE CLIP TO COMPLETE FIELD WELD-PLUG WELD HOLES IN WEB


Δ LIFT ROPE (NOT BY P.)

SECT 9-9

MK41C
 1/2" MACH BOLT x 0-1 1/2" (NON)

SPACERS (N BY P.C. & F.C)

TENSION STUDS TO A 80 KIP LOAD, CUT OFF EXCESS STUD AFTER TENSIONING & COVER WITH 1" MIN CONCRETE OVER ENDS OF STUDS. (AFTER GROUTING)




SECT.



Δ DETAIL

①


x 0-4 (LOWER STRUT)
 x 0-3 1/4 (CENTER STRUT)
 x 0-3 1/4 (UPPER STRUT)



DETAIL W



DETAIL A-A
 TYPICAL FOR ALL SPLICES





SECT. V-V

CONTRACT NO. DA45-164 CIVENG 657

APPROVED
 Subject to a copy of this plan and specifications, correction of errors, or other changes, need no addition of any required details, and no change of detail dimensions, or material, or finish, or color, and fastenings.
 OFFICE OF THE ENGINEER
 LITTLE ROCK, ARK.
 Date: 21 Sep 67

2

LTC



DETAIL A-A
TYPICAL FOR ALL SPLICES

AS BUILT

REFERENCE: CORPS OF ENGR DWG LGD 1-5-81, SHT 85, VOL I, REV B
 1-5-8/2
 1-5-8/3
 1-5-8/4
 1-5-8/5
 B
 B
 B
 A
 SPECS; PAGE TP-101, 526-16

CONTRACT NO DA45-164 CIVENG 65-560

APPROVED
 Subject to conformity with plans and specifications, correction of errors or substitutions and to additions of any required details, the work shall conform to detail drawings as shown on the drawings and fastenings.
 OFFICE OF SUPERVISOR OF DAMS FOR
 LITTLE GOOSE LOCK AND DAM
 21 Sep 67

NOTE: ERECT PIECES WITH MARKS ON STEEL AT SAME END AS SHOWN ON PLAN.
 FIELD CONNECTIONS:

PACIFIC CAR AND FOUNDRY COMPANY
 80 S. HUDSON ST. PA. 2-6386
 SEATTLE, WASHINGTON 98134

LITTLE GOOSE LOCK E DAM
 ITEM 101 SPILLWAY GATE
 VINNELL, MANNIX, FULLER, DILLINGHAM
 DR. MILL DATE 4/7/69 CIV. 6601 DATE 3-28-66

ISSUED
 DATE 5/28/67
 DRAWN BY
 CHECKED BY

ERECTOR ERECTION 6670-10101
 APPROVED
 DATE 5/28/67
 E322

LIG-65-560-101-003

MAR 19 1980

3

REVISIONS
 △ REVISED
 ERECT DET
 TO SUIT ESI
 10-1-66 CAH
 AW

△ REVISED
 ERECTION
 DETAIL

7/27/67 JAG
 H BOD

△ CHANGED
 HOLE TO SLOT
 FOR DISMANTLE
 & FIELD ASSY
 7/31/67 CAH

△ ADDED
 BACKUP BAR
 FOR REMOVED
 FIELD WELD
 8/22/67 CAH


SQCUT 4:1
 5/8" 1"

No holes permitted in rib


△ TEMPLATE ASSY FROM MK 252

△ TEMPLATE ASSY FROM MK 25A

ERECTOR CLIPS 215PCS @ 10.5" (ON 60° ARC)



WELDER (REP)




NOTE: FOLLOW UP TO BASE
 FOR WELDING AND INSULATION
 FOR WELDING CLEARANCE (SEE MK 25)
 8 MK 30A AS 5
 8 MK 20A OFF



SECT. X-X △

①

SQCUT 4'0" ± 1/8" SQCUT
5 1/2" 1-7/16" 1-7/16" 7 3/8"



△ 16 MK 30B



NOTE: FOLLOW UP TO BASE
FOR ALL DIMENSIONS
FOR FABRICATION OF SKIN PLATE @ MIDDLE GIRDER


8 MK 30A AS 540/711 SKIN PLATE ASSY
8 MK 20A L OPP HAND

TEMPLATE AT ASSY FROM MK46A


WORK TH

2

16 MK 30B



WORK THIS DWG WITH DWG N° 32



BILL OF MATERIAL

ITEM NO.	ITEM NAME	TYPE	QTY	UNIT	REMARKS	WEIGHT
8	30A	Ø 2" R 48x 3/4	10	ROLL	SAFTM	77.79
8	30A	Ø 2" R 48x 3/4	2	ROLL	SAFTM	54.71
48	C	ST 10W FAL 1/2" x 2"	40	ROLL	SAFTM	45.212
16	d	R 11 1/2	3	ROLL	STOCK	9.14
16	f	R 14 1/2	4	ROLL	BENDERS	23.84
17	h	L 4 1/2 x 3 1/2	0	3		27.4
16	k	R 30 1/2 x 3/4	3	ROLL	SAFTM	32.3
32	m	R 2 1/2 x 1/4	2	4	Ø	1.25
44	n	R 2 1/2 x 1/4	1	3 1/2	Ø	3.75
16	p	BAR 4 1/2 x 3/4	2	3		3.7
16	s	R BAR 4 1/2 x 3/4	1	3 1/2		2.91
32	t	R 2 1/2 x 1/4	2	4	Ø	4.51
16	v	BAR 3 1/2 x 3/4	3	1 1/2		8.5
16	w	L 6 1/2 x 3 1/2	1	2 1/2		14.02
16	ac	BAR 2 1/2 x 1/4	0	Ø		2.5
16	w	L 6 1/2 x 3 1/2	0	Ø		14.1
		SHOP WELD				64
TOTAL						263.841

MATERIAL SPEC:

PLATE & SHAPES; ASTM-A36 EXCEPT AS NOTED
 PLATE & SHAPES; LOW ALLOY STL. - SEE PG TP-938
 PARA. 9-09 OF GEN. SPEC.
 ST. STL. - ASTM A276-TYPE 410, HOT ROLLED, PICKLED,
 ANNEALED & PASSIVATED

NOTE:

* THESE WELDS TO BE 100% INSPECTED BY RADIOGRAPHY EXCEPT WHERE WELD GEOMETRY PROHIBITS. ULTRASONIC TESTING MAY BE USED.
 ** 100% SHOP WELD; GRIND NEARSIDE SMOOTH. GRIND FARSIDE FLUSH IN WAY OF RIBS.

REFERENCE:

CORPS OF ENGR DWG N° LGD 1-5-87/1 SHT 85 VOL 1 REV B
 1-5-87 86 B
 1-5-85 87 B
 1-5-84 88 B
 SPECS PAGE TP16-1 SECT 16
 TPO-38 PARA 9-09

AS BUILT

No. of Pcs. No. of Pcs. No. of Pcs. No. of Pcs. No. of Pcs. No. of Pcs. No. of Pcs.	CON. WELDED, REQ. INSPECTION CORPS OF ENGR. DIMS. TO OPEN HOLES EXCEPT AS NOTED DIMS. AND EDGE DISTANCES EXCEPT AS NOTED SPACING NOT SHOWN EXCEPT AS NOTED PAINT NO. SHOP PAINT PACIFIC CAR AND FOUNDRY COMPANY 80 S. HUDSON ST. PL. 5-6000 SEATTLE, WASHINGTON 98124 LITTLE GOOSE LOCK & DAM ITEM 101 - SPILLWAY GATE WINNELL MANNING FULLER BILLINGHAM OR CANFIELD 3/26/62 2/28/62 DATE 3-10-62 TITLE SKIN FLATE ASSY C670-10101 DATE 30
---	---


LTC 64 325 60-65-56(101-00)4-385

REVISIONS
△ REVISED
ERECTION DET
TO SUIT APPL
10-1-66 C.A.M.
C.M.



△ REVISED
ERECTION
DETAIL

7/27-67 C.A.M.

50 CUT



①




ERECTOR CLIPS 21 SPCS @ 3'-0" = 63'-0" (ON 60'-0" ARC)

3 1/2"	45PCS @ 1'-5 1/2"	1'-5 1/2"	45PCS @ 1'-5 1/2"	3 1/2"
10 3/8"	85PCS @ 1'-5 1/2" = 11'-9 1/2"		85PCS @ 1'-5 1/2" = 11'-9 1/2"	1'-2 1/8"


DETAIL-D DWG N°32 FOR MK 31B

FOR MK 31A

- 8 MK **31A** AS SHOWN
- 8 MK **31A'** OPP HAND SKIN PLATE ASSY
- 8 MK **31B** AS NOTED



2



BILL OF MATERIAL									
NO. IN QUANTITY	DESCRIPTION	SIZE	UNIT	REMARKS	WEIGHT				
8	M 31A	8 1/2 x 8 3/4	PLATE	38 1 1/2	124.2				
8	M 31A	8 1/2 x 8 3/4	PLATE	26 9 3/4	124.2				
144	C	ST10WF31	ANGLE	60 10 1/2	332.5				
16	F	8 1/2 x 3 1/2	ANGLE	13 10	3.25				
16	F	8 1/2 x 3 1/2	ANGLE	13 10	BEND				
104	H	4 x 3 x 3/8	ANGLE	0 3	1.4				
394	OP	2 x 3 x 3/8	ANGLE	1 2 1/2	1.2				
16	N	BAR 3 x 1/2	ANGLE	12 1 1/2	1.5				
8	M 31B	16	K	8 1/2 x 8 3/4	39 1 1/2	167.3			
16	M	8 1/2 x 3 1/2	ANGLE	26 9 3/4	63.193				
80	C	ST10WF31	ANGLE	60 10 1/2	150.31				
8	F	8 1/2 x 3 1/2	ANGLE	13 10	1.612				
8	S	8 1/2 x 3 1/2	ANGLE	13 10	BEND				
352	H	4 x 3 x 3/8	ANGLE	0 3	4.4				
216	OP	2 x 3 x 3/8	ANGLE	1 2 1/2	74.5				
8	P	BAR 3 x 1/2	ANGLE	12 0 3/4	3.23				
			SHOP WELD STYL						
			SHOP WELD						
			SHIP						
118		3/4\" M.B		0 2					

MATERIAL SPEC:
 PLATE & SHAPES - A57M-A36 EXCEPT AS NOTED
 PLATE & SHAPES - LOWALLOY STL - SEE PG TP-9-38
 TP 9-09 OF GENERAL SPEC.
 M.B A57M-A307 GRA
 ST. STL A57M-A176 TYPE 410 NOT ROLLED,
 ANNEALED, PICKLED & PASSIVATED

NOTE
 BOTH VERTICAL EDGES OF M 31B SHALL BE PREPARED FOR FIELD WELD BY CUTTING A DOUBLE CHAMFER: 45° x 1/8\" IN WAY OF 3/8\" & 45° x 1/4\" IN WAY OF 1/2\" R. NO EDGE PREPARATION FOR WELD REQD FOR MK 31A. LIKE WISE BOTH EDGES OF P 22 SHALL BE DOUBLE CHAMFERED 45° x 1/8\" AND P 22'S SHALL BE DOUBLE CHAMFERED 45° x 3/8\" IN WAY OF FIELD SPICES

REFERENCE:
 CORPS OF ENGR DWG N° LGD 1-5-8/1, SHT 85, VOL I REV B
 1-5-8/2, SHT 86, E
 1-5-8/3, SHT 87, E
 1-5-8/4, SHT 88, B
 SPECS PAGE TP16-1, SECT 16
 PAGE TP9-38, PARA 9-09

WORK THIS DWG WITH DWG N° 32

AS BUILT

APPROVED AS CORRECTED

Subject to conformity with plans and specifications, correction of errors or changes and to the extent of any required tests. Approval does not constitute a guarantee, warranty, or acceptance by the issuing authority.

OFFICE OF RESIDENT ENGINEER
 LITTLE GOOSE LOCK AND DAM

18 Aug 67


No. of Pkts. MA. LB. LF. SF. SH. No. of Sp. No. of Pkts.	CERT. WELDERS REQD. _____ INSPECTION CORPS OF ENGR. BOLTS _____ OPEN HOLES _____ EXCEPT AS NOTED END AND EDGE DISTANCE _____ EXCEPT AS NOTED SPACING NOT SHOWN _____ PAINT: NO SHOP PAINT. _____ PACIFIC CAR AND FOUNDRY COMPANY 80 S. HUDSON ST. P.O. 2-9288 SEATTLE, WASHINGTON 98134 LITTLE GOOSE LOCK AND DAM ITEM 101 - SPILLWAY GATE FOR VINNELL MANNIX, BULLER, BRUNINGHAM OR CALL DATE 12/16/66 COM. 2111 DATE 5-18-67 ISSUED: SKIN PLATE C670-10101 BY: J. S. [Signature] ASSY APPROVED: [Signature] 31 2 SHOP COORDINATOR: [Signature] DATE: 5/18/67
---	--

LIG 67-560-101-005 386


MAR 19 1980

3

REVISIONS
 Δ ADDED
 ERECTION
 CLIP DETAIL
 10-1-66 CAN
 JMF
 Δ DELETED
 ERECTION
 DETAIL
 7/11/67 CAN
 Δ REVISED
 EDGE DETAIL
 FC 5/2-539
 FIELD WELD
 8/25/67 CAN



SECT K-K DWG NO 30




DETAIL D AS SHOWN
 DETAIL D' OPP HAND
 DWGS NO 30 & 31


GRIND SMOOTH

D


1




SECT K-K DWG NO 30




SECT H-H DWG NO 30




DETAIL F TYPICAL



DETAIL D AS SHOWN
DETAIL D' OP PHAND
DWG NO 30 & 31



DETAIL M DWG NO 30




DETAIL A DWG NO 31


2

BILL OF MATERIAL

ITEM NO.	QTY	DESCRIPTION	UNIT	REMARKS	WEIGHT




DETAIL F DWG NO 30E31
TYPICAL



DETAIL OF REWORK

NOTE:
* THESE WELDS TO BE 100% INSPECTED BY RADIOGRAPHY EXCEPT WHERE WELD GEOMETRY PROHIBITS ULTRASONIC TESTING MAY BE USED
** ST. 5TL ELECTRODE



WORK THIS DWG WITH DWGS NO 30E31

DETAIL M DWG NO 30

APPROVED.
Subject to correction of errors and modification of any required parts, dimensions, or details.
Drawing:
OFFICE OF E.
LITTLE
Date: 21 Sep 67


No. Field No. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50.	QTY. WELDING REQD. INSPECTION CORP. OF ENGR GIVES _____ OPEN HOLES _____ EXCEPT AS NOTED DIMS AND EDGE DISTANCE _____ EXCEPT AS NOTED SPACING NOT SHOWN _____ PAINT _____ NO SHOP PAINT PACIFIC CAR AND FOUNDRY COMPANY 60 S. HUDSON ST. PA. 2-0222 SEATTLE, WASHINGTON 98124 LITTLE GOOSE LOCKE DAM ITEM 101- SPILLWAY GATE VINNELL MANNING FULLER GILGINGHAM BY CAHILL DATE 7/69 CHG. 200 DATE 5-10-62 CHECKED SKIN PLATE P.A. J. APPL. MISC DETAIL C670-10101 - SMDAR - F. Paul - S. M. Mac - SFD - SFD APPROVED R.O. Hudson 323 387
--	--

415-67-564-101-0006

MAR 19 1980


3

REVISIONS
Δ DELETED
ALL DIMENSIONS
FROM WEB OF
OF MK 33A.
33B & 33C.
4-13-67
M. B. C.
CAG





16 MK 33A AS SH

16 MK 33B AS NC



16 MK 33C 14WI



(1)



CONTRACT N#

APPR
Subject to delivery of
certificates of work or an
of any required work. All
drawings, or similar
drawings.
OFFICE OF REC
LITTLE GANGE
Date: 6-5-

2



BILL OF MATERIAL						
QTY	ITEM NO.	DESCRIPTION	UNIT	QTY	REMARKS	ISSUE
16	33A	14 WF 348	45°	16	SEE E-4872	2/73/6
16	33B	14 WF 342	45°	16	SEE E-4872	2/73/6
16	33C	14 WF 202	26°	16	SEE E-4872	2/73/6
Total: 6 14, 500						

MATERIAL SPEC:
SHAPE9 ASTM-A36

REFERENCE:
CORPS OF ENGR DWG N° LGD-1-5-8/1 SMT 85 VOLI REV. B
SPEC9: PG TP-16-1, SECT 16

AS BUILT

CONTRACT NR DA45-164-CIVENG 65-560

APPROVED

Subject to conformity with plans and specifications, correction of errors or omissions, and to fulfillment of any required tests. Approved does not imply exact dimensions, or responsibility for assembling and bolting.

OFFICE OF ASSISTANT ENGINEER
LITTLE GOOSE LAKE AND DAM

Date: 6-5-67

Mr. [Name] [Title] [Address] [City] [State] [Zip]

ORDER DELIVERED REQD APPROVED CORPS OF ENGR

QUANTITY 16 OPEN HOLES --- EXCEPT AS NOTED

DRILL AND EDGE FINISHING --- EXCEPT AS NOTED

SPACING NOT SHOWN ---

PAINT NO SHOP PAINT

PACIFIC CAR AND FOUNDRY COMPANY
60 S. HENSON ST. PO. BOX 2000
SEATTLE, WASHINGTON 98104

LITTLE GOOSE LOCKED DAM
ITEM 101 - SPILLWAY GATE
MINNELL, MANNIX, FULLER, BILKINGHAM
200 CARROLL AVE. SEATTLE, WA 98104

DATE 5-10-67

STRUTS
DETAILS C670-11101

33'


65-560-101-007

MAR 19 1960


3

REVISIONS
 Δ REVISED
 TO SUIT CC#48
 10-3-66 CANAL

Δ REVISED
 FROM WELDED
 TO BOLTED
 & SHOP REC.
 1-18-67 H.B.D.
 CANAL






8 MK 74A ^R AS SHOWN	14" x 16" x 16"	16'-2 1/2"	16'-4 1/2"
8 MK 74A ^L OPP HAND			
8 MK 74B ^R AS SHOWN	14" x 12" x 12"	12'-9 3/8"	12'-11 3/8"
8 MK 74B ^L OPP HAND			
8 MK 74C ^R AS SHOWN	14" x 5" x 5"	5'-10 1/8"	6'-0 1/8"
8 MK 74C ^L OPP HAND			
8 MK 74D ^R AS SHOWN			
8 MK 74D ^L OPP HAND			



TEMPLATE AT
 A95Y MK 35E
 MK34I

8 MK 74F ^R AS SHOWN	14" x 19" x 19"	19'-7 1/2"	19'-9 1/2"	14'
8 MK 74F ^L OPP HAND				
8 MK 74H ^R AS SHOWN	14" x 15" x 15"	15'-7 1/8"	15'-7 1/8"	14'
8 MK 74H ^L OPP HAND				
8 MK 74K ^R AS SHOWN	14" x 11" x 11"	11'-5 1/8"	11'-5 1/8"	14'
8 MK 74K ^L OPP HAND				
8 MK 74M ^R AS SHOWN	14" x 7" x 7"	7'-3 1/2"	7'-3 1/2"	14'
8 MK 74M ^L OPP HAND				

①



AS

CONTR


APPR

AS COR

Subject to conformity of correction of errors or of any required tests in dimension, or approved material.

OFFICE OF THE LITTLE 127-20

2



BILL OF MATERIAL

ITEM	QTY	MATERIAL	SIZE	LENGTH		REMARKS	WEIGHT
				FT.	IN.		
△	8	34A ¹⁶	14WF30	16	2 1/2	①	548711 1791
△	8	34A ³²	a. R 7 x 1/4	0	7 1/2	BEND	125
							7926
△	8	34B ¹⁶	14WF30	12	0 3/4	①	548711 6330
△	8	34B ³²	a. R 7 x 1/4	0	7 1/2	BEND	125
							7926
△	8	34C ¹⁶	14WF30	9	3 1/2	①	548711 4430
△	8	34C ³²	a. R 7 x 1/4	0	7 1/2	BEND	125
							7926
△	8	34D ¹⁶	14WF30	9	10 1/2	①	548711 2313
△	8	34D ³²	a. R 7 x 1/4	0	7 1/2	BEND	125
							7926
△	8	34E ¹⁶	14WF30	19	7 1/2	①	548711 7422
△	8	34E ³²	b. R 7 x 1/4	0	7 1/2	BEND	62
							62
							9546
△	8	34F ¹⁶	14WF30	15	5 1/2	①	548711 7421
△	8	34F ³²	b. R 7 x 1/4	0	7 1/2	BEND	62
							62
							7545
△	8	34G ¹⁶	14WF30	11	7 1/2	①	548711 5429
△	8	34G ³²	b. R 7 x 1/4	0	7 1/2	BEND	62
							62
							5548
△	8	34H ¹⁶	14WF30	7	11 1/2	①	548711 3432
△	8	34H ³²	b. R 7 x 1/4	0	7 1/2	BEND	62
							62
							13536
△	16	34N	14WF30	17	8 1/2	①	548711 8510
△							62
							62
							8634
57L	583					TOTAL	56509

MATERIAL SPEC:
R & SHAPES ASTM-A36

REFERENCE
CORPS OF ENGR DWGN# LGD1-5-B/1 SHT 85 VOL1 REV B
SPEC# PAGE TR-16-1, SECT 16

AS BUILT

CONTRACT NO. DA45-164 CVENG65-500
APPROVED AS CORRECTED
 Subject to conformity with plans and specifications, correction of errors or omissions, and to fulfillment of any required tests approved there in or under their direction, or acceptability for assembling or fitting.
 OFFICE OF INCHMENT ENR DIVISION
 LITH & OFR OF IAA II DIVISION
 6-5-67

No. RAJ MA SA PA QA RA SA TA VA WA XA YA ZA	CON. WELDING REQD	INSPECTION CORPS OFFENSE
	DELTA OPEN HOLES 13/16" ACCEPT AS NOTED	GRIND AND EDGE FINISHING ACCEPT AS NOTED
	SPACING NOT SHOWN	PAINT NO SHOP PAINT
PACIFIC CAR AND FOUNDRY COMPANY 60 S. HUDSON ST. PH. 3-8888 SEATTLE, WASHINGTON 98124		
LITTLE GOOSE LOCK & DAM ITEM 101- SPILLWAY GATE FOR VINNELL, MANNIX, RILLER, DILLINGHAM BY CAHILL DATE 5/16/61 COM. 249 DATE 5-16-61		
ISSUED STRUT BRACING		ORDER NO. C67011101
DETAILS		34 ²



LV 5-560-101-008 389

MAR 19 1980



3

REVISIONS
 Δ REVISED TO
 SUIT C.O.#46
 10-3-66 CAH:LL
 DM

Δ REVISED
 ERCT. CLIPS
 FROM WELDED
 TO BOLTED
 @ SHOP REQ.
 4-19-67, W BOB
 CAH:LL




1



* NOTE: THESE DIMENSIONS
 MAY BE ADJUSTED BY
 SHOP TO FACILITATE
 ERECTION

FACE OF STRUT WEB
 TYP BEND
 DETAIL





CONTRACT NEDA 45
APPROVE
AS CORRECT
 Subject to conformity with plans and
 correction of errors or omissions, and
 of any required tests. Approval does not
 constitute, or acceptability for use
 or restraining.
 OFFICE OF REIDENT ENGRS
 LITTLE HOUSE LOCK AND
 100
 6-5-67

2


REVISIONS
 Δ REVISED
 ERECTION
 DET TO SUIT
 10-3-66
 CANILL
 DW

Δ DELETED
 1/2" DIA. HOLES
 FROM WELD
 OF GIRDER.
 @ SHIP REQ.
 4-19-67
 @ BOB
 CANILL



Δ DELETED
 B-CP STUDS
 ADDED @
 1/2" DIA. HOLES
 TO SUIT
 HIGH BOB
 CHINA




NOTE:
 SUGGESTED PROCEDURE
 @ @ @ @ AT SHCP ASSY
 ARMS TO GIRDER



8 MK 36A GIRDER ASSY (IN)





(1)





(TO FIT STRUTS)
MK 73A

NOTE
SUGGESTED PROCEDURE: WELD @ CC & ad¹ AT SHOP ASSY OF STRUT ARMS TO GIRDER



5A GIRDER ASSY (NO 1)




CONTRACT NO. DMS-144 (01) 16390
APPROVED AS CORRECTED
 Subject to Authority with plans and specifications, correction of errors or omissions, and the fulfillment of any required tests, drawings, and other field data, are, or may be, necessary to the successful completion and maintenance of the project.
 OFFICE OF STRUCTURAL ENGINEER
 LITTLE ROCK, ARKANSAS
 Date: 18 Aug 67

REVISIONS
 Δ REVISED TO SUIT
 ERECTION DET
 10-2-66
 CAHILL
 CW


Δ DELETED
 1/2" DIA. HOLES
 FROM WEB
 OF GIRDER
 @ SHOP EQ.
 4-19-67 H.B.S.
 CAHILL

Δ DELETED
 2" COP. STUDS
 & ADDED 2"
 1/2" DIA. HOLES
 TO SUIT
 7-22-67 H.B.S.
 CAHILL





NOTE:
 SUGGESTED PROC
 AT SHOP ASSY C
 GIRDER

8 MK 37A GIRDER




①



NOTE:
 SUGGESTED PROCEDURE: WELD R "m" & R "K"
 AT SHOP ASSY OF STRUT ARMS TO
 GIRDER

8 MK 37A GIRDER ASSY (N2)



CONTRACT NO CA-45-164 CIVENG I


**APPROVED
AS CORRECTED**

Subject to conformity with plans and specifications and the correction of errors in contracts and to fulfillment of any required tests. Approval does not constitute an assumption of responsibility for any errors or omissions.

OFFICE OF RESIDENT ENGINEER
LITTLE CHASE LOCK AND DAM

Date: 18 Aug 67

(2)



BILL OF MATERIAL							
NO. TO ORDER	QTY	SIZE	LENGTH	REMARKS	WEIGHT		
8	37A	8" x 16"	24' 11 1/2"		5,587	30,373	
		8" x 16"	28' 10 1/4"			15,523	
		8" x 16"	47' 4 1/2"			24,332	
	64	2" x 1/4"	14' 10"	SNIPER	54650	12,613	
	56	1" x 3/8"	4' 10"	SNIPER		1,735	
	272	1/2" x 1/4"	0' 8 1/2"		54990	1,649	
SHOP WELD:							
	1	1/2" x 1/4"	1' 1"			437	
	1	1" x 1/4"	1' 0"			414	
	8	1" x 3/8"	24' 5 1/4"		54070	25,473	
	3	1" x 1/4"	20' 6 1/4"			11,793	
	235	1/2" x 1/4"	0' 2 1/2"	CPF		100	
SHIP							
	133	1" x 1/4"	0' 13"				
	204	1" x 1/4"	0' 4 1/2"				

MATERIAL SPEC: 126762
 PLATE & BAR ASTM-A36 EXCEPT AS NOTED
 PLATE LOW ALLOY-SEE PG TP-9-78, P9-09
 OF GENERAL SPECS.
 MACH. BOLTS ASTM A307, GRA
 STUDS MFES STD

REFERENCE:
 CORP OF ENGR DWG N2 LGD 1-5-B/2 SHT 86 VOL I RE 7 B
 1-5-B/3 87 1 B
 SPECS PAGE TP-16-1, SECT 16
 PAGE TP-9-78, PARA. 9-09

AS BUILT

CONTRACT NO CA45-164 CIVENG 65-560

**APPROVED
AS CORRECTED**

Subject to conformity with plans and specifications, correction of errors or omissions and to fulfillment of any required tests, approval does not constitute a warranty, or acceptability for any purpose not intended.

OFFICE OF RESIDENT ENGINEER
LITTLE GOOSE LOCK AND DAM

[Signature]

Date: 18 Aug 67




No. of Sub No. No. of Sub No. No. of Sub No. No. of Sub No. No. of Sub No. No. of Sub No.	CONF. WELDING REQD. _____ INSPECTION CORP OF ENGR GATE _____ OPEN WELDS _____ EXCEPT AS NOTED END AND EDGE DISTANCE _____ EXCEPT AS NOTED SPACING NOT SHOWN _____ PAINT _____ NO SHOP PAINT
	PACIFIC CAR AND FOUNDRY COMPANY 80 S. HUDSON ST. PA. 2-6386 SEATTLE, WASHINGTON 98134
	LITTLE GOOSE LOCK EDAM ITEM 101- SPILLWAY GATE VINNELL MANNIX FULLER DILLINGHAM BRCAHILL DATE 7-26-65 CDR DATE 7-26-65
P. 1 30 FCK SHIP CONVENIENCE	GIRDER #2 DETAIL C670-12101 APPROVED <i>[Signature]</i> 37 1/2 DATE 1-18-67

116-65-560-101-011 392


3

MAR 19 1980


REVISIONS
 Δ REVISED SECTION
 DETAIL TO
 S01T 631
 10-1-66 CANAL
 ON
 Δ DELETED
 OFF STUD
 ADDED 2"
 DR. HOLE
 TO SUIT
 7/26/67 H BOB
 CANAL



8 MK 38A GIRDER ASSY (IN)




①



SUGGESTED SHOP PROCEDURE: WELD R.M.V. & K.V. AT SHOP ASSY OF STRUT ARMS TO GIRDER

MK 38A GIRDER ASSY (Nº 3)



SECT B-B TYPICAL


CONTRACT NO. DA-49-1

APPROVED AS CORRECT

Subject to conformity with plans & correction of errors or omission, if of any required tests Approval the dimension, or usability for drawings.

OFFICE OF RESIDENT ENGINEER
LITTLE ROCK, AR

DATE: 1/8/51



BILL OF MATERIAL										
ITEM NO.	QTY.	ITEM	SIZE	UNIT	REMARKS	WEIGHT				
8	38A	A	2411 1/4	PLATE	S4500	14677				
		B	2610 1/4	PLATE		11176				
		C	42 3/4	PLATE		16340				
	64	d	4	1/2" X 3/8"	SHIP	5034				
	56	f	4	3/8" X 1/2"	SHIP	1434				
	272	h	4	3/8" X 1/2"	SHIP	1660				
	24	k	1	3/8" X 1/2"		534				
	24	m	1	3/8" X 1/2"		424				
	8	n	74 5/8	PLATE	S4500	14382				
	8	p	20 1/8	PLATE		7440				
				SHIP WELD		1600				
	220			WELD STUDS	1/2" COP	156				
SHIP										
33			1/2" M.B.	0 2%						
133			1" M.B.	0 1%						
66			3/8" M.B.	0 2%						
224					total	71,688				

MATERIAL SPEC:
 PLATE & BAR ASTM-A76 EXCEPT AS NOTED.
 PLATE LOW ALLOY STL. SEE PG TP-9-78,
 PARA 9-09 OF GEN. SPEC.
 WELD STUDS - 1/2" COP.

REFERENCE:
 CORPS OF ENGR DWGN LGD 1-5/8/2 SHT 86 VOLI REV B
 1-5/8/3 87
 SPEC: PG TP-16-1, SECT. 16
 PG TP-16-1, P.

AS BUILT

CONTRACT NO. 61-45-144 CIVIL (45-38)

APPROVED AS CORRECTED

Subject to conformity with plans and specifications, correction of errors or omissions, and to fulfillment of any required tests Approval does not imply design, construction, or responsibility for checking and reworking.

OFFICE OF RESIDENT ENGINEER
 LITTLE COUSE LOCK AND DAM

[Signature]
 DATE: 1/8/67

Mat. Req. Dets. - No. _____

DATE _____

NO AND DATE INVOICE _____

SPECIFY THE SHIP _____

PAINT: **NO SHOP PAINT**

PACIFIC CAR AND FOUNDRY COMPANY
 80 S. HUDSON ST. PA. 2-2000
 SEATTLE, WASHINGTON 98104

LITTLE COUSE LOCK & DAM
 ITEM 101 - SPILLWAY GATE
 WINNELL, MANNING, DYLER, DILLINGHAM
 611 1st St. Seattle, Wash. 98101
 5/10/66

BM 30 FOR SHIP CONVEYER

GIRDER # 7
 DETAILS 6670-12101

38


1/6/67 560-101-012 393

3

MAR 19 1968


REVISIONS
 Δ REVISED
 TO SUIT
 C.O. # 418
 10-3-66
 CAHILL
 CW

REVIS
 WELD DET. M
 TO SUIT COE
 DESIGN DWG
 JS. 10/4/67
 CAN



NOTE:
 MACHINING TO BE COMPLETED
 AFTER WELDMENT HAS BEEN
 STRESS RELIEVED

SECT A-A
 MACHINING DETAIL



SECT D-D








DETAIL B
 WELDMENT ASSY

STRESS RELIEVE AFTER ALL
 WELDING HAS BEEN COMPLETED

8/8 AS SHOWN
 8/8 OPP HAND


NOTE
 SEE
 TO F
 REI

1



DETAIL B
WELDMENT ASSY
RELIEVE AFTER ALL HAS BEEN COMPLETED
AS SHOWN
OPP HAND

NOTE: ERECTION CLIPS NOT SHOWN; SEE SECT F-F, H-H, & K-K. CLIPS TO BE REMOVED TO COMPLETE REQUIRED FIELD WELD



8 MK 39A^R AS SHOWN TRUNNION
8 MK 39A^L OPP HAND HUB ASSY
SEE DET B FOR WELDMENT ASSY

WORK THIS SHEET WITH N240

CONTRACT NO DA45-164 CIVENG 65-260


APPROVED

Subject to conformity with plans and specifications, correction of errors or omissions, and to satisfaction of any required tests. Approved does not confer design, construction, or assembly responsibility for consulting and engineering.

OFFICE OF RESIDENT ENGINEER
LITTLE COCKE LOCK AND DAM

1000

Date: 31 Oct 67



DET DWG NOS		BILL OF MATERIAL									
QTY	UNIT	ITEM	DESCRIPTION	QTY	UNIT	ITEM	DESCRIPTION	QTY	UNIT	ITEM	DESCRIPTION
40A	8	79A	16 a7r R 2 1/2 x 3/4	9	0	0					14578L
40A	8	79A	16 b7r R 2 1/2 x 3/4	8	10	0					15050L
40			16 c7r R 1 1/2 x 1	7	4	0					4723
40			16 d7r R 1 1/2 x 1 1/4	7	4	0					7848
40			16 e7r R 1 1/2 x 1 1/2	7	4	0					18857
40			16 h R 1 1/2 x 1	3	0	7					2772
40			16 k R 1 1/2 x 1	2	7	2					1701
40			48 m R 3/4 x 1 1/2	1	7	0					2625
—			116 n HUB FORGING								8872a
			1 1/2 OD x 2 1/2 ID Z 8								
40			16 p7r BUSHING BRZ								11200
40			16 s7r BUSHING BRZ								11200
40			25 t 1/2 DOWEL	0	3						451
—			16 v 1 1/2 x 3/4	1	7	2					446
—			16 w 1 1/2 x 3/4	1	7	2					473
—			16 x 1 1/2 x 3/4	1	7	2					473
—			QC BAR 1 1/2	72	0						61
—			Shop WELD								271
Total 435 B12											
SHIP											
64			1" MB	0	3						
64			1" MB	0	3						
64			1" MB	0	3						

MATERIAL SPECS:
 PLATE & BAR ASTM-A36
 HUB FORGING ASTM-A235, CL. C1 (R025-1030)
 BUSHING S ALUMINUM BRZ ASTM-B148
 CL. 9-C HT.
 DOWEL COML COLD FIN STL (CIGS)
 MACH BOLTS ASTMA307, G-A

REFERENCE:
 CORPS OF ENGR DWG NO LGD-1-5-8/5, SHT 89, VOLT, REV B.
 SPECS: PG TP-16-1, SECT 16

AS BUILT

DOWN TRUNNION
 HAND HUB ASSY
 OR WELDMENT
 95Y

WORK THIS SHEET WITH N940

CONTRACT NO DA45-164 CIVENG 65-960

APPROVED

Subject to conformity with plans and specifications, correction of errors or omissions, and to addition of any required work. Approved does not cover detail, dimension, or assembly for assembling and fitting.

OFFICE OF RESIDENT ENGINEER
 LITTLE GOOSE LOCK AND DAM


31 Oct 67

MFR No MFG REV DATE BY APPR CHECKED DATE	CONF. HOLDING REQD. INSPECTION CORPS OF ENGRS EXCEPT AS NOTED DIM AND EDGE FINISH EXCEPT AS NOTED SPACING AND NUMBER FINISH NO SHOP PAINT PACIFIC CAR AND FOUNDRY COMPANY 60 S. HUDSON ST. PA. 2-2000 SEATTLE, WASHINGTON 98134 LITTLE GOOSE LOCK & DAM ITEM 101 SPILLWAY GATE FOR VINNELL MAUNIX FULLER DILLINGHAM BRACELL, DATE 7/20/64 CON. CND. DATE 2-18-66 TRUNNION HUB ASSY ORDER NO. C670-19101 392 APPROVED R.D. Hudson DATE 5/20/67 BY 5/20/67
---	---


LIG 69-360-101-013

3 MAR 19 1980


REVISIONS
 Δ REVISED TO SUIT
 CO HS 44
 10-3-66
 CA HILL
 248



S79^R AS SHOWN MAKE 8
 S79^L OPP HAND MAKE 8
 P79^R AS NOTED MAKE 8
 P79^L AS NOTED $\frac{1}{2}$ OPP HAND MAKE 8
 TRUNN MACH MATC




2^{PH} DOWEL PIN $1 \frac{1}{8}''$ DIA x $0 \frac{3}{8}''$ MAKE 256




m79 R 8






16 MK 41A TRUNNION PIN



B LIFTING PIN BAR $3 \frac{1}{2} \times 2 \times 4$




C KEEPER BAR BAR $1 \frac{1}{2} \times \frac{1}{2} \times 0-6 \frac{1}{2}$

AS BUILT
CONTRACT NO. DAM-164 CIVIL-656


APPROVED AS CORRECTED
Subject to contract and specifications, correction of errors and omissions in fulfillment of contract. All other details discussed or approved by the Engineer and fastened.
OFFICE OF RESIDENT ENGINEER
LITTLE ROCK LOCK AND DAM
Date: 18 Dec 66

(2)



BILL OF MATERIAL									
QTY	ITEM NO	DESCRIPTION	UNIT	QTY	WEIGHT	REMARKS	QTY	WEIGHT	
8	47A	16 d	243 x 1	9	0			42.311	
8	49A	16 c	18 x 3	3	13			10.315	
		32 d	BAR 3x3	2	82			26.73	
		64 f	BAR 6x3	0	9			2.335	
		16 k	R 30x3	2	16			15.55	
		32 m	R 34x3	2	10	GRIND		9.541	
		48 n	BAR 2x1	3	0			9.79	
			SHOP WELD					7305	
			1/4" F.M. CAP SCREW	0	2	AS REQ		28	
16	47B	BAR 6 x 3	3	2				2587	
SHIP									
33		1" M.B. 4" THK	0	6		AS REQ		61K	
33		1 1/2" M.B. 5" THK	0	9		AS REQ		61K	
33		2" M.B.	0	9		AS REQ		61K	
17		2" M.B.	0	8		AS REQ		61K	
17		1" M.B.	0	8		AS REQ		61K	
33		2 1/2" M.B.	0	6		AS REQ		61K	
								Total	179,310

MATERIAL SPEC:
 PLATE & BAR ASTM A76 EXCEPT AS NOTED
 PLATE, ST. STL. QQ-S-766B TYPE 304 COND A
 BOLTS, HIGH STRENGTH STL ASTM A328 GRBB



NOTES
 ① WELD AFTER MACHING HAS BEEN COMPLETED
 ② WELD AT FINAL SHOP ASSEMBLY WITH TRUNNION PIN KEYS; BAR IN PLACE. SHEAR BARS ARE TO BEAR FIRMLY AGAINST KEYS.
 ③ THESE SURFACES TO BE FLAT AND PARALLEL WITHIN .002" AND NORMAL TO C OF BORE.
 ④ THESE SURFACES TO BE FLAT AND PARALLEL WITHIN .002".
 ⑤ THESE HOLES TO BE REBORED AFTER STRESS RELIEF.
 WELDMENT SHALL BE STRESS RELIEVED BY HEAT TREATMENT AFTER ALL WELDING IS COMPLETE AS INDICATED BY NOTE ①. THIS HAS BEEN DONE.
 REFERENCE: CORP. OF ENGR'G INC. NO. 15-1/4, SHIPYARD REPAIR SPEC. PG. 10, SEC. 11.6

AS BUILT

APPROVED

OFFICE OF GENERAL ENGINEERING
 LITTLE GOOSE LOCK AND DAM

REVISIONS

NO SHOP PAINT

PACIFIC CAR AND FOUNDRY COMPANY
 1000 1st Ave. Seattle, Wash.




LITTLE GOOSE LOCK DAM
 ITEM 101 - 5011 WAY GATE
 WINNELL MANNING FURBER DRILLING CO.
 ON CALL

TRUNNION YONE
 ASSY & DETAIL




DATE: 10/15/60

16-65-560-101-016

REVISIONS
 DELETED HOLES PER
 DWG E31
 10-1-66 CANNON
 CW





8 MK 43A^R AS SHOWN
 8 MK 43A^L OPP HAND



8 MK 43B^R AS SHOWN
 8 MK 43B^L OPP HAND


①




3A^R AS SHOWN
 3A^L OPP HAND
 ST7WF15 x 20'-11 3/4"

23'-8 3/8"
 22'-1 5/8"

9/12



43B^R AS SHOWN
 43B^L OPP HAND
 ST7WF15 x 23'-8 3/8"



AS BUILT
 CONTRACT NO DA 45164 CVENG 65-560

APPROVED
 Subject to conformity with plans and specifications, correction of errors or omissions, and to fulfillment of any required tests. Approved does not cover detail dimensions or accountability for assembling and fastening.
 OFFICE OF RESIDENT ENGINEER
 LITTLE GOOSE LOCK AND DAM
 JRS
 Date: 28 Oct 66

2

