

**REPORT DOCUMENTATION PAGE**

Form Approved  
OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1216 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.


<b>1. AGENCY USE ONLY (Leave blank)</b>		<b>2. REPORT DATE</b> Febraruy 2001	<b>3. REPORT TYPE AND DATES COVERED</b> Inspection	
<b>4. TITLE AND SUBTITLE</b> Lower Granite Dam Radial Gate Inspection and Testing			<b>5. FUNDING NUMBERS</b>	
<b>6. AUTHOR(S)</b> HDR Engineering Inc. Wayne Edwards P.E. Sam Planck P.E.				
<b>7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)</b> HDR Engineering Inc. 505 14rh Street, Suite 940 Oakland, CA 94612			<b>8. PERFORMING ORGANIZATION REPORT NUMBER</b>	
<b>9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)</b> U.S. Army Corps of Engineers Northwestern Division, Walla Walla District 201 North 3rd Ave. Walla Walla, WA 99362-1876			<b>10. SPONSORING/MONITORING AGENCY REPORT NUMBER</b>	
<b>11. SUPPLEMENTARY NOTES</b> None				
<b>12a. DISTRIBUTION AVAILABILITY STATEMENT</b> Approved for public release; distribution is unlimited			<b>12b. DISTRIBUTION CODE</b>	
<b>13. ABSTRACT (Maximum 200 words)</b> This report is an evaluation of the overall condition of the spillway tainter gates at Lower Granite Lock and Dam, Snake River Washington.				
<b>14. SUBJECT TERMS</b> Spillway tainter gates inspection testing			<b>15. NUMBER OF PAGES</b> 250	
			<b>16. PRICE CODE</b>	
<b>17. SECURITY CLASSIFICATION OF REPORT</b> Unclassified	<b>18. SECURITY CLASSIFICATION OF THIS PAGE</b> Unclassified	<b>19. SECURITY CLASSIFICATION OF ABSTRACT</b> Unclassified	<b>20. LIMITATION OF ABSTRACT</b> UL	

20030313 195


AQM03-05-1167

February 2001

# Lower Granite Dam Radial Gate Inspection and Testing



US Army Corps of Engineers, Walla Walla District



## Contents

---

### LOWER GRANITE DAM RADIAL GATE INSPECTION AND TESTING..... 1

#### INTRODUCTION.....1

Purpose .....	1
Scope of Investigation .....	1
Limitations .....	1

#### PROJECT BACKGROUND.....2

Project Description .....	2
Gate Design and Construction .....	2
Gate Operation.....	3
Gate Maintenance .....	3

#### INSPECTION.....5

General.....	5
Procedures .....	5
Member Designations .....	8
General Inspection Observations .....	8
Radial Gate – Operation, Testing and Measurements .....	19
Individual Gate Inspection Observations.....	22
Ultrasonic Testing Results.....	29
Hoists – Operation, Testing and Measurements .....	31

#### RECOMMENDATIONS.....34

#### REFERENCES.....35

#### APPENDICES

- A - Gate Inspection Sheets
- B - Hoist Inspection Sheets
- C - Ultrasonic Testing Inspection Sheets
- D - Inspection Photographs
- E - As-built Drawings

# **LOWER GRANITE DAM RADIAL GATE INSPECTION AND TESTING**

## **INTRODUCTION**

### **Purpose**

The Corps of Engineers, Walla Walla District, requires a comprehensive evaluation of the radial gates at Lower Granite Dam. The District retained HDR Engineering, Inc. to perform inspection and testing of the radial gates through Task Order No. 5 under Contract DACW68-00-D-0001. The task order scope of work includes review of project information, an initial meeting and inspection, comprehensive field inspection of the radial gates, testing of gate hoist machinery, recording trunnion movement, nondestructive testing of field welds, and preparation of a report.

### **Scope of Investigation**

The scope of this investigation includes:

- Review of design, construction, maintenance and operations information provided by the District.
- Hands-on visual inspection of accessible upstream and downstream portions of eight radial gates.
- Visual inspection of the hoists and hoist equipment.
- Nondestructive testing of field splice welds.
- Testing of gates and hoists while operating.
- Recording trunnion movements while raising gates in both loaded and unloaded condition.
- A report including documentation of the design and operation of the gates and hoists, inspection and testing results, conclusions, and recommendations.

### **Limitations**

The services under this contract include the professional opinion and judgment on the data and information reviewed. The conclusions and recommendations presented in this report are based on the information provided by the District and the inspection and testing of the radial gates and hoists. The inspection was visual only and only accessible portions of the components were inspected. Nondestructive testing was performed on field splice welds, but no laboratory testing was conducted in the course of the inspection.

## PROJECT BACKGROUND

### Project Description

Lower Granite Dam is located in southeastern Washington on the Snake River, 37.2 river miles upstream of Little Goose Dam, and 107.5 miles above its confluence with the Columbia River. The main project structures include a powerhouse, navigation lock, fish facilities, concrete non-overflow sections, and a rockfill embankment on the north shore. The dam is 3,200 feet long including the embankment. Construction of the project began in August 1965 and was completed in November 1975.

The spillway is 512-feet-long and is located about mid-river. The spillway consists of eight radial gate controlled bays separated by 14-foot-wide piers. The radial gates are each 50-foot wide by 60.15-foot-high. The gates are numbered 1 to 8 from left to right looking downstream. The spillway structure has a maximum height of 204.4 feet with the deck at Elev. 751.0. The spillway crest is at Elev. 681.0 and the top of gates at Elev. 740.0. The reservoir stores 483,800 acre-feet at normal full pool (Elev. 738.0).

The Spillway Design Flood (SDF) is 850,000 cfs. The spillway has a design capacity of 850,000 cfs at reservoir level Elev. 746.5. The maximum spillway capacity at normal full pool (Elev. 738.0) is 680,000 cfs. For the period from 1951 to 2000, the maximum flood of record was 332,000 cfs on June 18<sup>th</sup>, 1974. Peak flow outside the period of record was 409,000 cfs on June 5<sup>th</sup>, 1894. These values are computed from the flood marks by the U.S. Weather Bureau.

### Gate Design and Construction

The Corps of Engineers designed the gates and project facilities. The gates were fabricated by Flint Steel Corporation of Tulsa, Oklahoma and Pacific Car and Foundry of Seattle, Washington. Stewart Machinery supplied the hoists.

The Walla Walla District provided copies of the engineering drawings and shop drawings for the gates. The gate and hoist specifications were also provided. The gates are very similar to the gates at Little Goose Dam. Notes in the District file indicate that the Little Goose calculations were used at Lower Granite Dam. See *Little Goose Dam Radial Gate Inspection and Testing* report for details on design. The following information was obtained from the Lower Granite Dam documents.

The 3/8-inch to 1/2-inch thick skin plate is supported by vertical ST10.5WF31 purlins. The skin plate is 3/4-inch thick on each end of the gate to act as a wear surface for the lifting cables. The purlins are connected to three horizontal plate girders. Each horizontal girder is supported by 14WF gate arms. The gate arms are braced with 14 WF members and there are ST7WF15 braces between the downstream flanges of the horizontal girders. Cable attachment brackets are mounted on the skin plate at the bottom corners. The horizontal plate girders, skin plate and cable

# LOWER GRANITE DAM

attachment brackets are A537 Gr. A steel (Carbon-Magnesium-Silicon, Heat Treated for Pressure Vessels). All other members are A-36 steel.

The gate end frames were fabricated in two parts connected in the field with full penetration splice welds in the middle arms. The skin plate was installed in five vertical sections and joined by full penetration welds.

Each trunnion has a 24-inch diameter forged steel pin with a cast aluminum bronze bushing. The trunnions rest on a concrete girder that is anchored to the spillway piers with two groups of 48, 1-1/4 inch diameter prestressed bars.

The gates are raised and lowered by electric hoist units mounted on the deck above the gates. Eight 1-inch diameter wire ropes on each side of the gate wind on separate drums mounted on a common shaft. The hoist operating speed is approximately 1.1 feet per minute.

The gates have rubber J-bulb side seals and rubber wedge bottom seals. The side seal plates and sill beams are heated to prevent ice formation. The heating system consists of piping embedded below the seal plates. Electrically heated oil is automatically circulated through the piping when the ambient temperature drops below 32 degrees F.

## Gate Operation

The gates may be operated by manual control from stations located near each hoist, but normally the gates are remotely controlled from the powerhouse. All of the hoists can be powered from a diesel generator set.

The spillway is operated to pass the desired discharge with the best hydraulic conditions in the stilling basin. Through experience it has been shown that the most desirable stilling basin conditions are achieved with uniform discharge through all eight gates. The gates are opened in one-foot increments during the fish passage season from March 1 through December 31 according to the operating sequence in Table 1. If the desired spill exceeds the capacity of all eight gates for this spill pattern, then the gate opening sequence is repeated.

## Gate Maintenance

The District performs routinely inspects, tests, and lubricates the gates and hoists. Recent significant maintenance consists of:

- In the mid 1980s the upstream face of all gates were inspected and significant corrosion and wear was noted on the cable wear plates.
- The original coating for upstream and downstream portions of the gates was a four coat vinyl system. With the exception of spot painting, there is no indication that the gates have been recoated.

# LOWER GRANITE DAM

Gate Number / Gate Stops								Total	Spill
1	2	3	4	5	6	7	8	Stops	(kcfs) <sup>1</sup>

(1) Forebay El. 737

1	0	0	0	0	0	0	0	1	1.75
1	0	0	0	0	0	0	1	2	3.50
1	0	0	0	0	0	1	1	3	5.25
1	1	0	0	0	0	1	1	4	7.00
1	1	0	0	0	1	1	1	5	8.75
1	1	1	0	0	1	1	1	6	10.50
1	2	1	0	0	1	1	1	7	12.37
1	2	1	0	0	1	2	1	8	14.25
1	2	1	1	0	1	2	1	9	15.99
1	2	2	1	0	1	2	1	10	17.86
1	2	2	1	1	1	2	1	11	19.61
1	2	2	2	1	1	2	1	12	21.48
1	2	2	2	2	1	2	1	13	23.35
1	2	2	3	2	1	2	1	14	25.27
2	2	2	3	2	1	2	1	15	27.14
2	2	2	3	3	1	2	1	16	29.06
2	2	2	3	3	2	2	1	17	30.93
2	2	3	3	3	2	2	1	18	32.85
2	3	3	3	3	2	2	1	19	34.77
2	3	3	4	3	2	2	1	20	36.67
3	3	3	4	3	2	2	1	21	38.61
3	3	4	4	3	2	2	1	22	40.53
3	3	4	4	3	3	2	1	23	42.45
3	4	4	4	3	3	2	1	24	44.37
3	4	4	4	4	3	2	1	25	46.29
3	4	4	5	4	3	2	1	26	48.21
3	4	5	5	4	3	2	1	27	50.13
4	4	5	5	4	3	2	1	28	52.05
4	5	5	5	4	3	2	1	29	53.97
4	5	5	5	4	4	2	1	30	55.89
4	5	5	5	5	4	2	1	31	57.81
4	5	5	6	5	4	2	1	32	59.73
4	5	6	6	5	4	2	1	33	61.65
4	6	6	6	5	4	2	1	34	63.57

**Table 1: Gate operating sequence**

## INSPECTION

### General

Wayne Edwards and Mike Haynes of HDR Engineering performed an initial site visit and inspection on April 5, 2000. Based on information collected during the initial inspection, HDR prepared an inspection plan and inspection sheets that were submitted to the District for review prior to the detailed inspection.

The inspection and testing of the spillway radial gates was performed from October 2nd through 9th, by Sam Planck, P.E., Heather Yee and Tony Barela, of HDR Engineering, Inc. Steve Schmidlkofer and Jim Knowles of K&N Electric inspected the hoists, took amperage measurements, and recorded observations during testing. Destry Hall and Jim Fisher of Kleinfelder performed nondestructive testing of field splice welds. Gary Struthers Associates was responsible for operation of the gates during the loaded and unloaded testing and moved the stoplogs between gate testing. Emerald Services, Inc., as a sub-contractor to Gary Struthers, provided water blast cleaning of the skin plate during the upstream face inspection. Gus Hernandez and Frank Gates (USACE) were present during the inspections and provided on site assistance. The weather was clear with temperatures ranging from 50 to 75 degrees F. The reservoir was full during the inspection. The upstream inspection of Gate 1 was not able to be performed initially because the surface collector was in place. Sam Planck and Amy Akins of HDR Engineering returned to the site on November 20<sup>th</sup> to complete the upstream inspection of Gate 1.

### Procedures


#### Upstream Inspection & Testing

For the upstream inspections, stoplogs were placed in front of the gates prior to the inspection. The first part of the inspection was a rope access inspection of the bottom seal, bottom of the upstream surface of the skin plate and the hoist connections. During the inspection the gates were opened approximately three feet. At certain gates, the inspection under the bottom of the gate or measurements for racking could not be made due to excessive leakage through the stoplogs and heavy flows on the spillway. Racking measurements were recorded between the bottom seal plate on the gate and the embedded spillway seal. The upstream face of the gates was inspected from the spillway deck as each gate was raised to the full open position.

The second part of the upstream inspection consisted of the transverse, operational measurements at the trunnion, amperage readings while opening and closing, and the inspection of the upstream surface of the skin plate. Measurements were made to determine transverse movement of the trunnion hub versus the trunnion yoke at the initial, full open, and final closed position. During the gate opening, visible corrosion, debris and surface inconsistencies were waterblasted from the gate face for better condition assessment, see Photo 1. Amperage readings for the hoist were recorded at initial opening, during opening and during closing.




## LOWER GRANITE DAM



**Photo. 1: Waterblasting of upstream surface of skin plate during full opening of gate.**

### **Downstream Inspection**

The downstream portions of all gates were inspected. The downstream gate members were inspected by climbing along the horizontal girders and radial struts, see Photo. 2. Inspection rigging for the downstream inspections was anchored to the gate hoist equipment and torque tubes. Visual observations were made for excessive sweep and camber of the main struts and were recorded only if an abnormal condition was observed.




**Photo. 2: Rope access downstream inspection.**

## LOWER GRANITE DAM

### Operational Testing – Unloaded vs. Loaded

At the completion of the upstream inspection, with the stoplogs in place and the gate unloaded, dial gages were set at the trunnion to measure the vertical, transverse, and lateral movement of the trunnion hub versus the trunnion yoke. After initial readings were taken, the top stoplog was cracked open and the void was flooded, loading the gate. When the void between the stoplogs and the gate was completely full, final movement readings were taken. There was no gap present at the bearing between the trunnion yoke and the trunnion support beam, therefore, movement readings between the two surfaces were not made.



*Photo. 3: Installation of dial gages at trunnion .*

### Operational Testing – Loaded

With the stoplogs removed and the gate fully loaded, the gates were opened to two feet. Amperage reading for the hoists were recorded at the initial opening, during the opening of the gate and during closing.

### Nomenclature

The gates are identified as Gate 1 to 8, with 1 on the south end near the powerhouse looking downstream. Unless noted otherwise, all locations of observations, and notes pertaining to the radial gates are identified as right or left looking downstream.


# LOWER GRANITE DAM

In the inspection sheets and this report, corrosion is classified as light, moderate or heavy as follows:

- Light - Surface rust with no flaking or packing. Rust can not be scraped off by hand.
- Moderate - Some flaking, beginning to pack, but thickness of the pack is less than approximately 1/16". There is no observable loss of section.
- Heavy - Pack rust with measurable or observable section loss to the member.

## Member Designations

For the radial gate inspection observations and the photographs, the member designations indicated in Figure 1 apply.



**Figure 1: Radial gate member designations.**


## General Inspection Observations

The majority of condition observations found during the inspection are consistently found at all of the gates. The following section of the report pertains to those general observations or conditions which were found to apply to all of the gates. Specific observations or deficiencies for individual gates begin on page 22. No significant deviations from the as-built plans were observed for the radial gates. Field inspection sheets for the gates are included in Appendix A. Hoist operation and inspection sheets can be found in Appendix B.

## LOWER GRANITE DAM

### Upstream Surface of Skin Plate

The upstream surface of the skin plate is in extremely poor condition. There is large, scattered pitting on the entire surface of every gate. On average, the pits are approximately two inches in diameter and 1/4-inch to 5/16-inch deep. Many appear to be greater than 1/4-inch deep in the 3/8-inch thick portion of the skin plate and greater the 3/8-inch deep in the 1/2-inch thick portion. See Figure 2, and photos 4 through 7 below. The 3/4-inch thick cable wear plates are in good condition with respect to cable wear, however, there is pitting present in excess of 1/2-inch deep at some locations, see Photo. 8. At many locations the pitting on both the skin plate and wear plates appears to be associated with scratches or dings in the plates original protective coating. Based on the hemispherical shape of the pitting, the corrosion appears to be microbially influenced. It is likely that increased acid levels due to microbial activity have created a concentration cell within the pits and accelerated the corrosion.




**Figure 2: Typical pitting profile.**



**Photo. 4: Typical distribution of pitting.**


**LOWER GRANITE DAM**




*Photo. 5: Pitting, typical.*



*Photo. 6: Pitting, typical.*



*Photo. 7: Pitting, typical.*




*Photo. 8: Condition of cable wear plates, typical.*

# LOWER GRANITE DAM

## Hoists Connections

The hoist connections are in generally good condition with light to moderate corrosion present on the lifting lug plates. The U-bolts, socket blocks and connection pin, which appear to be stainless steel, are in very good condition, see Photo. 9. The design or material type for the U-bolts, socket blocks and connection pin are not listed in the available plans.



*Photo. 9: Hoist connection, typical condition.*


## Downstream Surface of Skin Plate

The downstream surface of the skin plate is in generally good condition. Isolated spots of light surface corrosion and previous (painted over) pitting can be found at various locations.


## Vertical Purlins

The vertical purlins are in generally good condition. At the bottom of the gate there is standing water between the bottom seal closure plate, the web of the purlins and the downstream side of the skin plate. Light to moderate corrosion is forming on all surfaces. There is no drainage for this space and it is consistently full of water and debris at all gates, see Figure 3 and Photo. 10.

## LOWER GRANITE DAM



**Figure 3: Standing water at bottom of gate between skin plate, purlin webs and bottom seal closure plate, typical.**



**Photo. 10: Standing water at bottom of gate between skin plate, purlin webs and bottom seal closure plate, typical.**




# LOWER GRANITE DAM

## Horizontal Girders and Braces

The horizontal girders and bracing are in generally good condition. There are isolated spots of light to moderate corrosion, mostly at locations with poor drainage.

The top and middle horizontal girders are divided into twelve drainage areas due to the web stiffeners. The area at either end of the girders is free to drain off the end of the web. The remaining ten areas have only three drain holes and require water to flow horizontally through at least one notch in the stiffeners in order to reach a drain hole. There are debris lines and evidence of standing water on nearly all of the horizontal girder flanges and webs.


The worst corrosion occurs on the bottom horizontal girder, between the multiple stiffeners, at each end of the girder. There are six stiffeners in close proximity to one another with drainage only provided horizontally through a notch at the upstream (low) end of the stiffener. In order for the last space to drain, the water must travel horizontally under five stiffeners. These notches are typically clogged and the area between the stiffeners is consistently full of water and debris, see Photo. 11.



**Photo. 11: Standing water between stiffeners at ends of bottom horizontal girder, typical.**

Immediately upstream and slightly above the end of the bottom horizontal girders, there are stiffeners between the skin plate, purlins and upstream flange of the horizontal girders. There is no drainage from this location and the enclosed area is either full of water and/or debris on all gates. See Photo. 12.

## LOWER GRANITE DAM



**Photo. 12: Standing water and debris between purlins, skin plate and upstream horizontal girder flange, typical.**

On the underside of the bottom horizontal girder, at the connection to the radial struts, there is delaminated paint and light to moderate corrosion around the drain hole in the girder web and near the adjacent stiffeners. See Photo. 13.



**Photo. 13: Corrosion beneath bottom horizontal girder. Looking up at girder flange (behind hammer) and stiffener (right), typical.**


# LOWER GRANITE DAM

## Radial Struts and Braces

The radial struts are in generally good condition with only light surface corrosion at isolated locations.

There is very poor drainage from the upstream end of the bottom radial strut and ponding or debris lines (evidence of previous ponding) are found at every gate, see Photo. 14.

There is very poor drainage from the downstream end of the top radial strut at the trunnion. The three radial struts become an enclosed box section at the trunnion. Since there is no drainage vertically from between the flanges of the top strut, a small drain hole is provided horizontally through the strut flange. The drain hole is consistently clogged and standing water is present at most trunnions.



**Photo. 14: Standing water at upstream end of bottom radial strut, typical.**

## Trunnions

The trunnion hubs, yokes and bearing material are in generally very good condition and appear well lubricated. Lubricant was observed being expelled between the yoke and hub, around the circumference of all of the trunnions.

## Side and Bottom Seals


The side and bottom seals are in generally good condition. Small side and bottom seal leaks are visible on many of the gates, although no major leaks were observed. There is a leak at the bottom seal, at the spillway monolith construction joint at nearly every gate. Photo. 15. The

## LOWER GRANITE DAM

bottom and side seal material is in good condition with very little cracking or deterioration present.




**Photo. 15: Leak at spillway monolith construction joint, typical.**




**Photo. 16: Side seal from upstream side with no signs of cracking or deterioration, typical.**

## LOWER GRANITE DAM

There is moderate corrosion on the skin plate on the upstream side of the bottom seal. The downstream side of the bottom seal is in good condition with little occurrence of corrosion. See Photo. 17 and Photo. 18.



**Photo. 17: Upstream side of bottom seal with light to moderate corrosion on skin plate, typical.**



**Photo. 18: Downstream side of bottom seal, typical**

## Radial Gate – Operation, Testing and Measurements Member Section Dimensions

Section dimensions of main structural members were measured to verify conformance with the design drawings. These members included radial struts, radial strut bracing, horizontal girders, horizontal girder bracing and purlins. Measured dimensions were recorded on field data sheets found in Appendix A. The data sheets also contain nominal section dimensions from the American Institute of Steel Construction (AISC) *Steel Construction Manual, Seventh Edition, 1970*. Section measurements typically include the depth,  $d$  (measured at the edges of the flanges), the flange width,  $b_f$ , and the flange thickness,  $t_f$ . Web thickness,  $t_w$ , was only measured if there was an exposed portion of the web or drain holes large enough for calipers.

Differences between the design drawings and the actual field conditions of 1/16<sup>th</sup> inch or less were deemed to be insignificant. Nearly all members in the field were found to be greater or equal in dimension than what was required in the design drawings. The larger dimensions were probably due to inaccuracies of the field measurements resulting from difficult access or with the thickness of the paint on the members. Those that were smaller were all within the fabrication tolerances. Of those measurements that were out of fabrication tolerance range, none were consistently out of range to conclude that a member other than what was specified in the design drawings was used.

## Racking Measurements

Racking measurements for the gates were made at the beginning of the upstream inspection of the gates. Measurements were recorded for the distance between the bottom of the gate at the bottom corner of the bottom seal plate, and the embedded spillway plate. Measurements were made as far as possible to the left and right side of the gate depending on stoplog leakage and flow on the spillway. The gates were typically between two and three feet open when the measurements were made. The measurements for racking are as follows:

	Left (inches)	Right (inches)
Gate 1	-	-
Gate 2	35 - 3/4	36 - 1/2
Gate 3	47	47
Gate 4	14 - 1/2	14 - 3/4
Gate 5	24 - 3/4	24 - 3/4
Gate 6	30 - 1/4	30 - 1/4
Gate 7	24 - 3/4	24 - 3/4
Gate 8	26	25 - 3/8

**Table 2: Gate racking measurements.**

# LOWER GRANITE DAM

The gates were also observed at the moment of first opening to look for signs of water release beginning from one side of the gate or the other. In most cases, water release would begin at both sides of the gate simultaneously and move towards the middle of the gate at equal rates. Based on the recorded measurements and observations, there is no apparent racking of the gates.

## Trunnion Hub Movement: Closed - Full Open - Closed

With the stoplogs in place, measurements were made of the transverse gap between the trunnion hub and the trunnion yoke at both trunnions. The measurements were made with the gate at the initial opening, full open, and again when closed. The maximum transverse movement recorded between any two positions is as follows:

	Left Trunnion		Right Trunnion	
	Inside (inches)	Pier Side (inches)	Inside (inches)	Pier Side (inches)
Gate 1	0	0	0	0
Gate 2	1/32	0	1/32	0
Gate 3	0	0	0	0
Gate 4	0	0	0	0
Gate 5	1/16	0	0	0
Gate 6	0	0	1/32	0
Gate 7	0	0	0	0
Gate 8	0	0	0	0

**Table 3: Transverse trunnion hub movement through full opening and closing**

Based on the surface irregularities of the trunnion hub and the casting tolerances, the transverse measurements between the hub and the yoke can only be considered accurate to  $\pm 1/16$ -inch. The recorded measurements indicate there is no appreciable lateral movement of the trunnion hubs with respect to the trunnion yoke during either opening or closing of the gate.

# LOWER GRANITE DAM

## Trunnion Hub Movement: Unloaded vs. Loaded

Dial gages were installed at one trunnion to record the vertical, transverse and upstream / downstream movement of the trunnion hub with respect to the trunnion yoke. The initial measurement was made with the stoplogs in place and no load on the gate. The final reading was made after the top stoplog was removed and the gate was fully loaded. The maximum movements recorded at the trunnion hubs are as follows:

	Vertical (1 / 1000 inch)	Upstream / Downstream (1 / 1000 inch)	Transverse (1 / 1000 inch)
Gate 1	4	25	0
Gate 2	2	39	33
Gate 3	4	29	10
Gate 4	2	33	0
Gate 5	16	54	18
Gate 6	9	36	6
Gate 7	6	35	2
Gate 8	3	25	9

**Table 4: Loaded versus unloaded trunnion movements**

For the vertical movements shown in Table 4, the hub moved upward with respect to the yoke during loading. The upstream / downstream movement of the hub was in the downstream direction and the transverse movement was outward, toward the piers.

The tolerance for the 24-inch diameter trunnion pin is listed in the design plans as +0.000 inches and -0.005 inches. The tolerances for the 24-inch diameter trunnion bushing is listed as +0.012 inches and -0.000 inches. The shop plans for the pin indicate the pin should be 23.980 inches in diameter with tolerances of +0.000 inches and -0.008 inches.

Based on the tolerances listed either in the design plans or the shop plans, there is no significant displacements of the trunnion hub with respect to the trunnion yoke occurring during the loading or opening process.




# LOWER GRANITE DAM

## Individual Gate Inspection Observations

The observations in the following section pertain only to the gates indicated and were not typically found on all of the gates.

### Gate 1

- Due to the presence of the surface collector installed in the stoplog slots at Gate 1, the upstream inspection and operational tests were not performed until November 20th, see Photo. 19. The upstream surface of the skin plate was in generally the same condition as the previously inspected gates.



*Photo. 19: Surface collector installed at Gate 1 during initial inspection.*

## **LOWER GRANITE DAM**

### **Gate 2**

- Flange and web at the top left vertical brace at connection to middle girder is deformed. The web is deformed toward the middle of the gate approximately 1 inch. See Photo. 20 and Photo. 21.



***Photo. 20: 1 inch deflection in web of top left vertical brace at middle girder.***




***Photo. 21: 1/4 inch deflection in flange of top left vertical brace middle girder.***

## LOWER GRANITE DAM

### Gate 3

- At the upstream end of the bottom right radial strut there are indentations on the outside surface of the inside (spillway side) flange. The indentations appear to be due to previous grinding which occurred prior to the most recent painting. See Photo. 22



*Photo. 22: Grinding marks on lower strut flange.*

- There appears to be a small lubrication leak in the lubrication line to the right (looking downstream trunnion). There is a bulge of lubricant at the angle coupling between the flexible line and the trunnion hub. See Photo. 23.



*Photo. 23: Lubricant bulb at connection to trunnion.*

## LOWER GRANITE DAM

### Gate 4

- Prior to the inspection of the upstream face of the gate and waterblasting, an approximately 10-inch diameter paint blister was observed on the downstream side of the skin plate. The blister was located between the middle and top horizontal girders, approximately 7-feet from the left side of the gate (looking downstream) and approximately 6-feet above the transition between the 1/2-inch and 3/8-inch skin plate. The blister did not appear to be leaking water at the time, however, rust stains were observed on and beneath the blister. After waterblasting the upstream surface of the gate, the blister developed several leaks, see Photo. 24 and Photo 25. During the downstream inspection of the gate the blistered paint was removed to expose the hole in the skin plate, see Photo 26. The actual hole through the skin plate was roughly oblong and approximately 1/4-inch wide and 1/8-inch tall.
- The leak was patched by Gus Hernandez, USACE, on October 17th using META-LOX™ Industrial-Grade Metallic Patching Compound, a 2-part epoxy and resin compound.



**Photo. 24: Paint blister and leakage downstream side of skin plate, prior to removal of paint.**

## LOWER GRANITE DAM



*Photo. 25: Skin plate leak  
prior to removal of  
paint.*




*Photo. 26: Skin plate leak  
after removal of  
paint.*

## LOWER GRANITE DAM

### Gate 5

- There is a indentation in radial strut brace H on the right side frame. The indentation is approximately 2 inches long, ½ inch wide, and ¼ inch deep. The indentation appears old and probably occurred during construction. There is no sign of distress or corrosion associated with it, see Photo. 27.



*Photo. 27: Deformation in Brace H.*


### Gate 6

- See general condition observations.

## LOWER GRANITE DAM

### Gate 7

- The web of the top right vertical bracing at connection to middle girder is deformed. The web is deformed towards the middle of the gate approximately 2 inches. This is similar to deformation on Gate 2. See Photo. 28.



*Photo. 28: 2 inch deflection in top right vertical bracing at middle girder.*


### Gate 8

- See general condition observations.

## Ultrasonic Testing Results

### Description

The field welds on the gates were tested ultrasonically to determine the amount of discontinuity present and the integrity of the welds. The location of the tested welds is shown in Figure 4.



**Figure 4: Ultrasonic Weld Test Locations.**

A total of 352 welds were tested, of which 54 welds were rejected in accordance with the requirements of ANSI / AASHTO / AWS D1.5, 1995 Bridge Welding Code. Of the welds which failed the testing, 69% were located at the upstream end of the radial struts. Only one weld at the connection between the downstream end of the radial struts and the trunnions was found to fail the testing.

Table 5 lists the rejected welds by gate number and location on the gate. The letter 'f' indicates a flange weld, 'w' a web weld. Approximately 75% of the rejected welds were located on the flanges of the members. Figure 5 illustrates the percentage of welds which failed testing and the total number of welds which failed for each location tested.


The extent and depth of the rejected welds are marked on each of the tested welds in the field. At each rejected weld there will be a start and end mark along the weld and a number indicating the depth of the flaw. For individual gate weld test sheets, see Appendix C.



# LOWER GRANITE DAM

Gate	Welds Accepted	Welds Rejected	Flaw Severity Class				Locations
			A	B	C	D	
1	41	3	1	2	0	0	33w, 34f, 35f
2	42	2	2	0	0	0	58fo, 59fo
3	37	7	6	1	0	0	25f, 26f, 27f, 28f, 29f, 30f, 31w
4	27	17	12	2	0	3	36w, 37fo, 38fi, 39fi, 40fi, 42fo, 43w, 44fi, 45w, 36fo, 47fi, 48w, 49fo, 50fo,
5	41	3	3	0	0	0	78fi, 79fi, 80fi
6	41	3	2	1	0	0	60fo, 61fo, 62fi
7	29	15	15	0	0	0	63fo, 64fo, 65fi, 66w, 67fi, 68fi, 69w, 70fo, 71fi, 72fo, 73fi, 74w, 75fo, 76w,
8	40	4	4	0	0	0	54, 55w, 56fi, 57w

**Table 5: Ultrasonic Testing Summary.**




**Figure 5: Ultrasonic Weld Test Locations and Percentage of Welds Failing Testing at Each Location.**


## Hoists – Operation, Testing and Measurements

### Hoist Operation Inspection

External portions of the hoist equipment, support platforms and gate connections were visually inspected for signs of excessive corrosion, wear or damage. See Photos 29, 30 and 31 below. The hoist and hoist machinery are in generally good condition.




*Photo. 29: Hoist, typical.*



*Photo. 30: Hoist motors, typical.*

# LOWER GRANITE DAM



*Photo 31: Hoist manufactures plate, typical.*

The following observations were made at individual gate hoists:

Hoist and Motor Observations	
Gate 1	Loaded test only performed due to surface collector.
Gate 2	There is a high level of noise from the right angle gearbox. The coupling should be checked and lubricated.
Gate 3	Right angle gearbox - high level of noise -check coupling and lube. Main gearbox has severe oil leak at output shaft.
Gate 4	There is bearing noise at the motor output shaft. The main gearbox shaft seals are weeping.
Gate 5	The main gearbox output shaft seals are leaking.
Gate 6	The main gearbox seals are weeping.
Gate 7	The main gearbox seals are weeping.
Gate 8	The main gearbox seals are weeping.

**Table 6: Hoist operation observations.**

# LOWER GRANITE DAM

## Hoist Amperage Measurements:

Hoist amperage readings were recorded during opening and closing of the gates in both the loaded and unloaded condition. The readings include the start up and running amperage. Running amperages were recorded for Phase A, B and C. Table 7 lists the opening and closing start up amperage and the average of the three phases for the running amperage for the gates in the unloaded condition. Table 8 lists the same information for the loaded condition.

	Start up Opening	Start up Closing	Running Opening	Running Closing
<b>Gate 1</b>	No unloaded test performed due to surface collector			
<b>Gate 2</b>	106.0	102.0	13.5	9.0
<b>Gate 3</b>	114.4	111.2	15.6	10.6
<b>Gate 4</b>	112.0	105.0	15.9	10.2
<b>Gate 5</b>	115.0	111.2	14.5	10.2
<b>Gate 6</b>	110.5	110.0	15.5	9.9
<b>Gate 7</b>	124.1	110.0	15.8	9.4
<b>Gate 8</b>	110.4	110.6	15.3	10.3

**Table 7: Unloaded Gate - Hoist Amperage Readings**

	Start up Opening	Start up Closing	Running Opening	Running Closing
<b>Gate 1</b>	112.0	110.0	16.0	9.4
<b>Gate 2</b>	108.0	104.5	15.3	9.9
<b>Gate 3</b>	117.6	114.4	16.3	10.1
<b>Gate 4</b>	116.2	104.8	15.7	9.6
<b>Gate 5</b>	108.8	112.0	15.9	10.1
<b>Gate 6</b>	113.6	106.4	15.7	10.2
<b>Gate 7</b>	116.8	110.8	15.5	9.9
<b>Gate 8</b>	114.0	108.0	15.7	10.0

**Table 8: Loaded Gate - Hoist Amperage Readings**

Based on the consistency of the readings the hoists are in generally good condition. The amperage data indicates that the tainter gate hoist motors are operating well within their design operating limits that normally allow the starting amperage to be in the range of 5 to 8 times the nameplate value. The current draw for all motors were in acceptable range and the gates appeared to be free with no apparent binding. The field inspection sheets for the hoist measurements can be found in Appendix B.

## RECOMMENDATIONS

### **Recommended in the next year or as necessary:**

- Repair pitting on skin plate and repaint (or recoat) upstream surface of gate face.
- Install sacrificial anodes on upstream side of gate. Based on the condition of the skin plate at Little Goose Dam (which has sacrificial anodes) sacrificial anodes will significantly reduce the amount and severity of pitting of the skin plate. A corrosion expert should be consulted to determine the number and location of anodes required.

These repairs can be undertaken sequentially on all of the gates at once or the repairs could be made on an as-needed basis as the pitting penetrates the skin plate and leaks develop at individual gates.

### **Recommended in the next 2 years:**

- Perform a structural analysis of the gates to determine capacity for trunnion friction, operating loads and the demand on the welded joints which were found to contain flaws.
- Analyze the hoist gearboxes per the manufactures recommendation and remanufacture or replace as required.
- Replace the main gearbox seals on the hoist motors.


### **Recommended in the next 5 years:**

- Install drain hole between the multiple stiffeners at ends of the bottom horizontal girders. The recommended size for these drain holes is 1-inch in diameter.
- Install drain holes in the purlin stiffeners near the ends of the bottom horizontal girders (Plate perpendicular to skin plate, above multiple stiffeners on bottom horizontal girder). The recommended size for these drain holes is 1-inch in diameter.
- Install drain holes in the downstream portion of the bottom seal plate between every purlin. Note: the rubber bottom seal is located between the bottom seal plate and the bottom seal keeper plate. The hole should not be flame cut with the rubber bottom seal in place. The recommended size for these drain holes is 1-inch in diameter.
- Enlarge the drain holes at upstream end of lower radial struts. The recommended size for these drain holes is 1 1/2 - inch in diameter.
- For all new and enlarged drain holes, the holes should be drilled, not flame cut, to reduce jagged edges which snag debris. If drilling holes is not feasible, then the edges of the flame cut holes should be reamed smooth.

## REFERENCES


1. Water Control Manual, Lower Granite Lock and Dam, U.S. Army Corps of Engineers, Walla Walla District, May 1987.
2. Lower Granite Lock and Dam, Operations Manual, SCM Consultants , Inc.

Gate No. 1  
 Left Elevation B-B



Member	Type	Depth d		Web t <sub>w</sub>		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>r</sub>		t <sub>r</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8		15/16	=====	15 3/4	✓	1 1/2	✓
Strut 2	14 WF 342	17 1/2	17 3/4	1 9/16	=====	16 3/8	✓	2 7/16	✓
Strut 1	14 WF 398	18 1/4		1 13/16	=====	16 5/8		2 13/16	
Brace A	14 WF 30	13 7/8	13 3/4	5/16	=====	6 3/4	✓	3/8	✓
Brace B	14 WF 30	13 7/8	✓	5/16	=====	6 3/4	✓	3/8	✓
Brace C	14 WF 30	13 7/8	13 3/4	5/16	=====	6 3/4	✓	3/8	✓
Brace D	14 WF 30	13 7/8	13 7/8	5/16	=====	6 3/4	✓	3/8	✓
Brace E	14 WF 30	13 7/8	14	5/16	=====	6 3/4	✓	3/8	✓
Brace F	14 WF 30	13 7/8	14	5/16	=====	6 3/4	✓	3/8	✓
Brace G	14 WF 30	13 7/8	✓	5/16	=====	6 3/4	✓	3/8	✓
Brace H	14 WF 30	13 7/8	14 3/16	5/16	=====	6 3/4	✓	3/8	✓
Brace J	14 WF 30	13 7/8	✓	5/16	=====	6 3/4	✓	3/8	✓
Brace K	14 WF 30	13 7/8	13 3/4	5/16	=====	6 3/4	✓	3/8	✓
Brace L	14 WF 30	13 7/8	14	5/16	=====	6 3/4	✓	3/8	✓
Brace M	14 WF 30	13 7/8	14	5/16	=====	6 3/4	✓	3/8	✓
Brace N	14 WF 30	13 7/8	14	5/16	=====	6 3/4	✓	3/8	✓


Gate No. 1  
 Right Elevation A-A



Member	Type	Depth d		Web t <sub>w</sub>		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>r</sub>		t <sub>r</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 3/8	15/16	—	15 3/4	15 3/4	1 1/2	1 3/8
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16	—	16 3/8	16 3/8	2 7/16	2 1/2
Strut 1	14 WF 398	18 1/4	18 1/4	1 13/16	—	16 5/8	16 5/8	2 13/16	2 7/8
Brace A	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace B	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace C	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace D	14 WF 30	13 7/8	13 3/4	5/16	—	6 3/4	✓	3/8	✓
Brace E	14 WF 30	13 7/8	14 1/8	5/16	—	6 3/4	10 7/8	3/8	✓
Brace F	14 WF 30	13 7/8	14	5/16	—	6 3/4	10 7/8	3/8	✓
Brace G	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace H	14 WF 30	13 7/8	14 1/8	5/16	—	6 3/4	✓	3/8	✓
Brace J	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	✓
Brace K	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	✓
Brace L	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace M	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace N	14 WF 30	13 7/8	14	5/16	—	6 3/4	10 7/8	3/8	✓



Gate No. 1 Downstream Elevation



① leaking Gate @ Bottom ②

Member	Type	Depth		Web		Flange - End			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Horiz. Girder 3	PL Girder	49 3/4	✓	7/16	✓	16	✓	7/8	✓
Horiz. Girder 2	PL Girder	60 1/2	✓	3/4	5/8	16 1/2	✓	1 1/4	✓
Horiz. Girder 1	PL Girder	60 1/2	✓	1	✓	16 1/2	✓	1 1/4	✓
Purlins	ST 10 WF 31	10 1/2	✓	13/32	✓	8 1/4	✓	5/8	✓
Skin PL Bracing	ST 7 WF 15	7	10 7/8	1/4	✓	6 3/4	✓	3/8	✓

① Corrosion, due to standing water

② Corrosion between splice plates due to water

③ Leak in 1. side seal

④ Corrosion in 2nd girder


⑤ Ponding water on bottom strut to bottom girder

⑥ Bottom Girder, left

⑦ Standing Water @ Purlins

⑧ Center @ Gate Missing concrete at Bottom Plate


Gate No. 1 Upstream Elevation



HEAVY PITTING @ 10' BELOW SPICE / TOP OF OTHER GATES

Gate No. 1 Operation and Trunnion Measurements

Racking Measurements: Bottom of Gate and Spillway




Transverse Trunnion Hub Movement, No Load on Gate: Closed-Open-Closed

	LEFT		RIGHT	
	Inside	Outside (pier)	Inside	Outside (pier)
Initial Gate Closed	22/32	16/32	21/32	14/32
Gate Full Open	22/32	16/32	21/32	14/32
Final Gate Closed	22/32	16/32	21/32	14/32

3-D Trunnion Hub Movements - Unloaded vs. Loaded


	LEFT				RIGHT			
	No Load Void Dry		Full Load Void Full		No Load Void Dry		Full Load Void Full	
Vertical	0.0000		+0.0035		0.0000		0.0000	
US/DS	+0.0015		+0.0260		+0.0010		+0.0185	
Transverse	22/32	16/32	22/32	16/32	21/32	14/32	21/32	14/32
	Inside	Outside	Inside	Outside	Inside	Outside	Inside	Outside



GATE IS SHIFTED TO RIGHT AT FACE

CRANE NOT AVAILABLE, VOID FILLED VIA GRAVITY, NOT FULL WHEN MEASURED  $\approx$  3 LOGS SHOWING


Gate No. 2  
 Left Elevation B-B



Member	Type	Depth		Web		Flange(s)			
		d		t <sub>w</sub>		b <sub>f</sub>		t <sub>f</sub>	
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 3/4	15/16		15 3/4	15 3/4	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 5/8	1 9/16		16 3/8	16 3/16	2 7/16	2 1/2
Strut 1	14 WF 398	18 1/4	18 1/4	1 13/16		16 5/8	16 5/8	2 13/16	2 13/16
Brace A	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/16	3/8	3/8
Brace B	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace C	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace D	14 WF 30	13 7/8	14	5/16		6 3/4	6 13/16	3/8	3/8
Brace E	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace F	14 WF 30	13 7/8	14	5/16		6 3/4	6 13/16	3/8	3/8
Brace G	14 WF 30	13 7/8	14	5/16		6 3/4		3/8	
Brace H	14 WF 30	13 7/8	14	5/16		6 3/4		3/8	
Brace J	14 WF 30	13 7/8	14	5/16		6 3/4	6 13/16	3/8	3/8
Brace K	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace L	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 3/4	3/8	3/8


- 6. Weld cutweld in top strut.
- 18. RT. Trunnion
- 17. OVERLAIN GATE Pic.
- 16. LFT Trunnion

Gate No. 2  
 Right Elevation A-A



Member	Type	Depth d		Web t <sub>w</sub>		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>r</sub>		t <sub>f</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 3/4	15/16		15 3/4	15 3/4	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16		16 3/8	16 3/8	2 7/16	2 1/2
Strut 1	14 WF 398	18 1/4	18 1/4	1 13/16		16 5/8	16 5/8	2 13/16	2 7/8
Brace A	14 WF 30	13 7/8	14	5/16		6 3/4	6 13/16	3/8	3/8
Brace B	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 13/16	3/8	
Brace C	14 WF 30	13 7/8	14	5/16		6 3/4	6 13/16	3/8	
Brace D	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 3/4	3/8	
Brace E	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 3/4	3/8	
Brace F	14 WF 30	13 7/8	14	5/16		6 3/4	6 13/16	3/8	
Brace G	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 13/16	3/8	
Brace H	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace J	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 3/4	3/8	7/16
Brace K	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 3/4	3/8	7/16
Brace L	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 5/16	3/8	3/8
Brace N	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 3/4	3/8	3/8

Gate No. 2 Downstream Elevation




14, 15 Mock in Bot. Girder

Member	Type	Depth d		Web t <sub>w</sub>		Flange - End			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>f</sub>		t <sub>f</sub>	
Horiz. Girder 3	PL Girder	49 3/4	49 3/4	7/16	1/2	16	16	7/8	7/8
Horiz. Girder 2	PL Girder	60 1/2	60 5/8	3/4	1/2	16 1/2	16 1/2	1 1/4	1 1/4
Horiz. Girder 1	PL Girder	60 1/2	60 1/2	1		16 1/2	16 1/2	1 1/4	1 1/4
Purlins	ST 10 WF 31	10 1/2	10 9/16	13/32		8 1/4	8 1/4	5/8	5/8
Skin PL Bracing	ST 7 WF 15	7	7	1/4	5/16	6 3/4	6 3/4	3/8	3/8

- 2, 3 Delam. Coating (Paint?)
- 4. Sway int vert bracing ≈ 1/4". The weld is Bent. @ Splice
- 5. Same as 4 ≈ 1"
- 7, 8 Bottom Seal Leaks
- 9. Bot. Girder Moderate to Heavy Rust ON FLTG UNDER ENT. (TYP PICTURE)
- This is also seal on LFT Bot. Strut Flg
- 10. LFT Bot Girder Brace Pts w/ MOD and evidence of standing H<sub>2</sub>O
- 11, 12 LEAKS @ Bot. Seal
- 13 STANDING H<sub>2</sub>O @ Bot. Plate

Gate No. 2 Upstream Elevation



- Paint Flaking off due to pressure wash ( $\frac{15}{14}$  pic)  
16: Top Potting hole  $\approx \frac{1}{8}$ " to  $\frac{1}{4}$ " depth

17  
18

MORE COR? PITTING IN.  $\frac{1}{2}$ " R TAKEN OTHER GATES (TVA)

20 Corroded weld on left of gate,  $\frac{1}{4}$ " deep.  
21, 22

Gate No. 2 Operation and Trunnion Measurements

Racking Measurements: Bottom of Gate and Spillway

LEFT	RIGHT
35 3/4	36 1/2

Transverse Trunnion Hub Movement, No Load on Gate: Closed-Open-Closed

	LEFT		RIGHT	
	Inside	Outside (pier)	Inside	Outside (pier)
Initial Gate Closed	24/32	16/32	21/32	17/32
Gate Full Open	23/32	16/32	22/32	17/32
Final Gate Closed	24/32	16/32	21/32	17/32


3-D Trunnion Hub Movements - Unloaded vs. Loaded

	LEFT				RIGHT			
	No Load Void Dry		Full Load Void Full		No Load Void Dry		Full Load Void Full	
Vertical					0.0000		-0.0020	
US/DS					0.0000		+0.0390	
Transverse	23/32	16/32	23/32	16/32	21/32	17/32	21/32	17/32
	Inside	Outside	Inside	Outside	Inside	Outside	Inside	Outside

ROCK POCKET / VOID IN SPILLWAY. 10 FT FROM BT PIER




Gate No. 3  
 Left Elevation B-B



Member	Type	Depth		Web		Flange(s)			
		d		t <sub>w</sub>		b <sub>f</sub>		t <sub>f</sub>	
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 3/4	15/16	-	15 3/4	15 3/4	1 1/2	1 9/16
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16	-	16 3/8	16 3/16	2 7/16	2 1/2
Strut 1	14 WF 398	18 1/4	18 1/4	1 13/16	-	16 5/8	16 5/8	2 13/16	2 13/16
Brace A	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 7/8	3/8	3/8
Brace B	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 7/8	3/8	3/8
Brace C	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace D	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 7/8	3/8	3/8
Brace E	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace F	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace G	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace H	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 13/16	3/8	2/8
Brace J	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace K	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace L	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8


Gate No. 3  
 Right Elevation A-A



Member	Type	Depth d		Web t <sub>w</sub>		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>r</sub>		t <sub>f</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 11/16	15/16	—	15 3/4	15 3/4	1 1/2	1 9/16
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16	—	16 3/8	16 3/8	2 7/16	2 1/2
Strut 1	14 WF 398	18 1/4	18 3/8	1 13/16	—	16 5/8	16 3/8	2 13/16	2 3/16
Brace A	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace B	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace C	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace D	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace E	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace F	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace G	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace H	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace J	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace K	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace L	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8

13) GRIND MARKS

Gate No. 3 Downstream Elevation




Member	Type	Depth d		Web t <sub>w</sub>		Flange - End			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>f</sub>		t <sub>f</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Horiz. Girder 3	PL Girder	49 3/4	50	7/16	7/16	16	16	7/8	7/8
Horiz. Girder 2	PL Girder	60 1/2	60 1/2	3/4	3/4	16 1/2	16 1/2	1 1/4	1 5/10
Horiz. Girder 1	PL Girder	60 1/2	60 3/4	1	1	16 1/2	16 1/2	1 1/4	1 1/4
Purlins	ST 10 WF 31	10 1/2	10 1/2	13/32	-	8 1/4	8 1/4	5/8	5/8
Skin PL Bracing	ST 7 WF 15	7	7	1/4	1/4	6 3/4	6 3/4	3/8	3/8

2) DELTA LIGHT COR.

3) TYP NOTE: NO WELDS U.S. STIFF

4) NO DIRECT DRAINAGE

Gate No. 3 Upstream Elevation




- HEAVY PITTING

- APPROX 4' GRID AVERAGED

- AVG 2'-3' Ø 1/4" + IN 3/8 R ; 3/8" DEEP IN 1/2" R



Gate No. 4  
 Left Elevation B-B  
 Right




Member	Type	Depth d		Web t <sub>w</sub>		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>f</sub>		t <sub>f</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 5/8	15/16		15 3/4	15 3/4	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16		16 3/8	16 1/8	2 7/16	2 1/2
Strut 1	14 WF 398	18 1/4	18 1/4	1 13/16		16 5/8	16 3/8	2 13/16	2 7/8
Brace A	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 15/16	3/8	3/8
Brace B	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 1/16	3/8	3/8
Brace C	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace D	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 15/16	3/8	3/8
Brace E	14 WF 30	13 7/8	14	5/16		6 3/4	6 7/8	3/8	3/8
Brace F	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace G	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 15/16	3/8	3/8
Brace H	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 7/8	3/8	3/8
Brace J	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/4	3/8	3/8
Brace K	14 WF 30	13 7/8	13 7/16	5/16		6 3/4	6 9/16	3/8	3/8
Brace L	14 WF 30	13 7/8	14	5/16		6 3/4	6 7/16	3/8	3/8
Brace M	14 WF 30	13 7/8	14	5/16		6 3/4	6 9/16	3/8	3/8
Brace N	14 WF 30	13 7/8	14	5/16		6 3/4	6 7/16	3/8	3/8

11. Clogged Drain Hole w/ moss growth (STANDING H<sub>2</sub>O ABOVE)


13. Small Deflection in Flange Against Pier ± 1/16" - 1/8"

Gate No. 4  
 Right Elevation A-A  
 LEFT



Member	Type	Depth		Web		Flange(s)			
		d		t <sub>w</sub>		b <sub>r</sub>		t <sub>f</sub>	
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 3/8	15/16		15 3/4	15 3/8	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16		16 3/8	16 3/16	2 7/16	2 1/2
Strut 1	14 WF 398	18 1/4	18 5/16	1 13/16		16 5/8	16 5/16	2 13/16	2 13/16
Brace A	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 3/16	3/8	3/8
Brace B	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 7/8	3/8	3/8
Brace C	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	6 3/16	3/8	3/8
Brace D	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace E	14 WF 30	13 7/8	14	5/16		6 3/4	6 1/8	3/8	3/8
Brace F	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 1/2	3/8	3/8
Brace G	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace H	14 WF 30	13 7/8	14 1/4	5/16		6 3/4	6 7/8	3/8	3/8
Brace J	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 7/8	3/8	3/8
Brace K	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace L	14 WF 30	13 7/8	13 7/8	5/16		6 3/4	10 1/2	3/8	3/8
Brace M	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	12 1/2	3/8	3/8
Brace N	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	10 3/4	3/8	3/8

Gate No. 4 Downstream Elevation




Member	Type	Depth d		Web t <sub>w</sub>		Flange - End			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>f</sub>		t <sub>f</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Horiz. Girder 3	PL Girder	49 3/4	49 5/16	7/16	1/2	16	16	7/8	7/8
Horiz. Girder 2	PL Girder	60 1/2	60 1/2	3/4		16 1/2	16 1/2	1 1/4	1 1/4
Horiz. Girder 1	PL Girder	60 1/2	60 3/8	1		16 1/2	16 1/2	1 1/4	1 1/4
Purlins	ST 10-WF 31	10 1/2	10 3/8	13/32		8 1/4	8 1/4	5/8	5/8
Skin PL Bracing	ST 7 WF 15	7	7	1/4	5/16	6 3/4	6 13/16	3/8	3/8

2-9 Holes in Gate Face.  $\approx 1/4" \times 1/8"$   
 10: Muck and evidence of standing H<sub>2</sub>O  
 12: Muck @ Bot. Seal Plat. NO DRAINING HOLES



Gate No. 4 Upstream Elevation



- HEAVY PITTING  $> 1/4"$  IN  $3/8$  R ISOLATED SPOTS

- APPEARS TO FOLLOW SCRATCHES IN R

- TYP 2-3'  $\emptyset$

- AVG, PITT ON 4'-5' GRID

Gate No. 4 Operation and Trunnion Measurements

**Racking Measurements: Bottom of Gate and Spillway**

LEFT	RIGHT
14 1/2	14 3/4

**Transverse Trunnion Hub Movement, No Load on Gate: Closed-Open-Closed**

	LEFT		RIGHT	
	Inside	Outside (pier)	Inside	Outside (pier)
Initial Gate Closed	21/32	16/32	22/32	18/32
Gate Full Open	21/32	16/32	22/32	18/32
Final Gate Closed	21/32	16/32	22/32	18/32

**3-D Trunnion Hub Movements - Unloaded vs. Loaded**

	LEFT				RIGHT			
	No Load Void Dry		Full Load Void Full		No Load Void Dry		Full Load Void Full	
Vertical	0.0000		-0.0020					
US/DS	-0.0020		+0.0305					
Transverse	21/32	16/32	21/32	16/32	22/32	18/32	22/32	18/32
	Inside	Outside	Inside	Outside	Inside	Outside	Inside	Outside

---

---

---

---

---

---

---

---

---

---

---


---

---

---

---


Gate No. 5  
 Left Elevation B-B



Member	Type	Depth d		Web t <sub>w</sub>		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>f</sub>		t <sub>f</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 3/8	15/16	15/16	15 3/4	15 3/8	1 1/2	✓
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16	1 9/16	16 3/8	16 3/8	2 7/16	✓
Strut 1	14 WF 398	18 1/4	18 3/16	1 13/16	1 13/16	16 5/8	16 5/8	2 13/16	✓
Brace A	14 WF 30	13 7/8	14 1/8	5/16	5/16	6 3/4	6 3/4	3/8	✓
Brace B	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	✓
Brace C	14 WF 30	13 7/8	14 1/8	5/16	5/16	6 3/4	6 3/4	3/8	✓
Brace D	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	✓
Brace E	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	✓
Brace F	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	✓
Brace G	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	✓
Brace H	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	✓
Brace J	14 WF 30	13 7/8	14 1/16	5/16	5/16	6 3/4	6 3/4	3/8	✓
Brace K	14 WF 30	13 7/8	14 1/16	5/16	5/16	6 3/4	6 3/4	3/8	✓
Brace L	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	✓
Brace M	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	✓
Brace N	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	✓

(15) Left, bottom member @ cables.  
 (16) Rounding @ bottom strut


Gate No. 5  
 Right Elevation A-A



Member	Type	Depth		Web		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>f</sub>		t <sub>f</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	✓	15/16	—	15 3/4	15 3/4	1 1/2	✓
Strut 2	14 WF 342	17 1/2	17 1/2	1 9/16	—	16 3/8	16 3/8	2 7/16	✓
Strut 1	14 WF 398	18 1/4	✓	1 13/16	—	16 5/8	16 5/8	2 13/16	2 5/8
Brace A	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	✓
Brace B	14 WF 30	13 7/8	✓	5/16	—	6 3/4	✓	3/8	✓
Brace C	14 WF 30	13 7/8	14 1/8	5/16	—	6 3/4	✓	3/8	✓
Brace D	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace E	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace F	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace G	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace H	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace J	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace K	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace L	14 WF 30	13 7/8	14 1/8	5/16	—	6 3/4	✓	3/8	✓
Brace M	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓
Brace N	14 WF 30	13 7/8	14	5/16	—	6 3/4	✓	3/8	✓

- ③ Corrosion on top strut
- ④ Ponding water on 2nd girder
- ⑤ Nick in strut
- ⑥ Nick in triangular member
- ⑦ Ponding water @ bottom strut


Gate No. 5 Downstream Elevation



Member	Type	Depth		Web		Flange - End			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>r</sub>		t <sub>r</sub>	
Horiz. Girder 3	PL Girder	49 3/4	50	7/16	✓	16	✓	7/8	✓
Horiz. Girder 2	PL Girder	60 1/2	✓	3/4	✓	16 1/2	✓	1 1/4	✓
Horiz. Girder 1	PL Girder	60 1/2	✓	1	✓	16 1/2	✓	1 1/4	✓
Purlins	ST 10 WF 31	10 1/2	✓	13/32	✓	8 1/4	✓	5/8	✓
Skin PL Bracing	ST 7 WF 15	7	✓	1/4	✓	6 3/4	✓	3/8	✓

(1) Leak in side seal on top girder  
 (2) ponding water @ middle  
 (3) ponding water overall  
 (4) ponding water in bottom girder  
 (1) side seal, rivet  
 (2) bottom seal ✓ from R → L  
 (3) (4) ponding in purlins & bottom gate

Gate No. 5 Upstream Elevation \_\_\_\_\_



WATER LINE  
TOP 3"  
1/16"-1/8" Pitting

Pitting  $\approx$  1/16" to 1/8"  
Along Searches

Localized  
Pitting 1/8" to 1/4"

Even Patch

③

②


①

LARGE  
PITS, UP TO  
1/4" ABOUT  
2"-3" DIAM.

Blank lined area for notes or additional drawings.



Gate No. 6  
 Left Elevation B-B




Member	Type	Depth d		Web t <sub>w</sub>		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>r</sub>		t <sub>f</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 5/8	15/16	—	15 3/4	15 3/4	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 5/8	1 9/16	—	16 3/8	16 3/8	2 7/16	2 1/2
Strut 1	14 WF 398	18 1/4	18 5/16	1 13/16	—	16 5/8	16 3/8	2 13/16	2 7/8
Brace A	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace B	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace C	14 WF 30	13 7/8	13 15/16	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace D	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace E	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace F	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace G	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace H	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace J	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace K	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace L	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 3/4	3/8	3/8

13) LIGHT COR, POST STANDING WATER




Gate No. 6  
 Right Elevation A-A



Member	Type	Depth d		Web t <sub>w</sub>		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>r</sub>		t <sub>f</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 5/8	15/16	←	15 3/4	15 3/4	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 3/8	1 9/16	←	16 3/8	16 1/8	2 7/16	2 1/2
Strut 1	14 WF 398	18 1/4	18 1/4	1 13/16	←	16 5/8	16 3/8	2 13/16	2 13/16
Brace A	14 WF 30	13 7/8	14 1/16	5/16	5/16	6 3/4	6 7/8	3/8	3/8
Brace B	14 WF 30	13 7/8	14 1/16	5/16	5/16	6 3/4	7	3/8	3/8
Brace C	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 15/16	3/8	3/8
Brace D	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	7	3/8	3/8
Brace E	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	7	3/8	3/8
Brace F	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 7/8	3/8	3/8
Brace G	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 7/8	3/8	3/8
Brace H	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	7	3/8	3/8
Brace J	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 7/8	3/8	3/8
Brace K	14 WF 30	13 7/8	13 5/16	5/16	5/16	6 3/4	7	3/8	3/8
Brace L	14 WF 30	13 7/8	14	5/16	5/16	6 3/4	6 7/8	3/8	3/8
Brace M	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	6 15/16	3/8	3/8
Brace N	14 WF 30	13 7/8	13 7/8	5/16	5/16	6 3/4	7	3/8	3/8

10) STANDING WATER, CLOGGED DRAIN

Gate No. 6 Downstream Elevation



Member	Type	Depth		Web		Flange - End			
		d		t <sub>w</sub>		b <sub>f</sub>		t <sub>f</sub>	
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Horiz. Girder 3	PL Girder	49 3/4	50 1/16	7/16	15/32	16	16	7/8	7/8
Horiz. Girder 2	PL Girder	60 1/2	60 9/16	3/4	3/4	16 1/2	16 1/2	1 1/4	1 5/16
Horiz. Girder 1	PL Girder	60 1/2	60 1/2	1	1	16 1/2	16 1/2	1 1/4	1 5/16
Purlins	ST 10 WF 31	10 1/2	10 7/16	13/32	→	8 1/4	8 1/4	5/8	5/8
Skin PL Bracing	ST 7 WF 15	7	7	1/4	1/4	6 3/4	6 2/8	3/8	3/8


2) TOP HORIZ (TYP) EVID. POST STANDING WATER

4) DS FLANGE, LIGHT COR, EVID STANDING WATER

11) EVIDENCE CLOGGED DRAIN/ STANDING WATER

14) STANDING WATER (TYP)

Gate No. 6 Upstream Elevation



NOTE: THERE appears to be  
 Scratches along Corrosion  
 lines.  
 CORR. Varies from 1/8" to 1/4"

- ① Gate Div. ID.
- ② Ponding @ Bottom of Gate
- ③ Bottom Seal
- ④ Bottom Seal Gate L → R
- ⑤ Water up of ponding.

- the gate is tight on LEFT SIDE w/o gap on Right SIDE.

Gate No. 6 Operation and Trunnion Measurements

Racking Measurements: Bottom of Gate and Spillway

LEFT
30 1/4

RIGHT
30 1/4

Transverse Trunnion Hub Movement, No Load on Gate: Closed-Open-Closed

	LEFT		RIGHT	
	Inside	Outside (pier)	Inside	Outside (pier)
Initial Gate Closed	30/32	16/32	21/32	23/32
Gate Full Open	30/32	16/32	20/32	23/32
Final Gate Closed	30/32	16/32	21/32	23/32

3-D Trunnion Hub Movements - Unloaded vs. Loaded

	LEFT				RIGHT			
	No Load Void Dry		Full Load Void Full		No Load Void Dry		Full Load Void Full	
Vertical	-0.0005		-0.0095					
US / DS	-0.0005		+0.0350					
Transverse	30/32	16/32	30/32	16/32	21/32	23/32	21/32	23/32
	Inside	Outside	Inside	Outside	Inside	Outside	Inside	Outside

---



---



---



---



---



---



---



---




---




---

Gate No. 7  
 Left Elevation B-B




Member	Type	Depth d		Web t <sub>w</sub>		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>r</sub>		t <sub>r</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 5/8	15/16		15 3/4	15 5/8	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 7/16	1 9/16		16 3/8	16 3/16	2 7/16	2 7/16
Strut 1	14 WF 398	18 1/4	18 1/4	1 13/16		16 5/8	16 3/16	2 13/16	2 7/8
Brace A	14 WF 30	13 7/8	14	5/16		6 3/4	6 7/8	3/8	3/8
Brace B	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 7/8	3/8	3/8
Brace C	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace D	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 12/16	3/8	3/8
Brace E	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 7/8	3/8	3/8
Brace F	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace G	14 WF 30	13 7/8	13 1/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace H	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8
Brace J	14 WF 30	13 7/8	14 1/16	5/16		6 3/4	6 3/4	3/8	7/16
Brace K	14 WF 30	13 7/8	13 11/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace L	14 WF 30	13 7/8	13 11/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	13 15/16	5/16		6 3/4	6 7/8	3/8	3/8
Brace N	14 WF 30	13 7/8	14	5/16		6 3/4	6 3/4	3/8	3/8

Gate No. 7  
 Right Elevation A-A



Member	Type	Depth		Web		Flange(s)			
		d		t <sub>w</sub>		b <sub>r</sub>		t <sub>f</sub>	
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	15 5/8	15/16		15 3/4	15 1/8	1 1/2	1 1/2
Strut 2	14 WF 342	17 1/2	17 1/8	1 9/16		16 3/8	16 1/16	2 7/16	2 1/2
Strut 1	14 WF 398	18 1/4	18 1/4	1 13/16		16 5/8	16 3/16	2 13/16	2 1/16
Brace A	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace B	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace C	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace D	14 WF 30	13 7/8	13 1/16	5/16		6 3/4	6 7/8	3/8	3/8
Brace E	14 WF 30	13 7/8	13 1/16	5/16		6 3/4	6 7/8	3/8	3/8
Brace F	14 WF 30	13 7/8	13 1/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace G	14 WF 30	13 7/8	13 1/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace H	14 WF 30	13 7/8	13 1/16	5/16		6 3/4	6 13/16	3/8	3/8
Brace J	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace K	14 WF 30	13 7/8	13 1/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace L	14 WF 30	13 7/8	13 5/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace M	14 WF 30	13 7/8	13 1/16	5/16		6 3/4	6 3/4	3/8	3/8
Brace N	14 WF 30	13 7/8	13 1/16	5/16		6 3/4	6 3/4	3/8	3/8


Gate No. 7 Downstream Elevation



Member	Type	Depth		Web		Flange - End			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)	Plan (in)	Measured (in)
Horiz. Girder 3	PL Girder	49 3/4	49 13/16	7/16	7/16	16	16	7/8	7/8
Horiz. Girder 2	PL Girder	60 1/2	60 1/2	3/4	3/4	16 1/2	16 1/2	1 1/4	1 1/4
Horiz. Girder 1	PL Girder	60 1/2	60 1/4	1		16 1/2	16 1/2	1 1/4	1 1/4
Purlins	ST 10 WF 31	10 1/2	10 1/2	13/32		8 1/4	8 1/4	5/8	5/8
Skin PL Bracing	ST 7 WF 15	7	7	1/4	1/4	6 3/4	6 3/4	3/8	3/8

- 22. Brace plates @ 2nd strut to girder. NOT WELDED @ back of GIRDER (Typ.)
- 23. Evidence of standing H<sub>2</sub>O w/ Debris
- 24. Standing H<sub>2</sub>O AND Muck in Bot. SEAL Plt.
- 25. LEAKS ALONG Bot. SEAL
- 26. Bot. LEFT STRUT @ Bot Girder Light Rust
- 27. BENT WEB OF T beam
- 28. Light Rust & Delam Pmt.

Gate No. 7 Upstream Elevation \_\_\_\_\_



- EROSION PITS ARE IN GROUPS. 1/2 - 1/4" DEEP
- Cables on LEFT SIDE: High Vibrations
- BOTTOM 3rd PITS ARE EVERY 1 1/2 - 2' ON AVE.



Gate No. 7 Operation and Trunnion Measurements

Racking Measurements: Bottom of Gate and Spillway

LEFT	RIGHT
24 3/4	24 3/4

Transverse Trunnion Hub Movement, No Load on Gate: Closed-Open-Closed

	LEFT		RIGHT	
	Inside	Outside (pier)	Inside	Outside (pier)
Initial Gate Closed	28/32	20/32	22/32	17/32
Gate Full Open	28/32	20/32	22/32	17/32
Final Gate Closed	28/32	20/32	22/32	17/32


3-D Trunnion Hub Movements - Unloaded vs. Loaded

	LEFT				RIGHT			
	No Load Void Dry		Full Load Void Full		No Load Void Dry		Full Load Void Full	
Vertical	+0.0028		+0.0075					
US / DS	-0.0005		+0.0340					
Transverse	28/32	20/32	28/32	20/32	22/32	17/32	22/32	17/32
	Inside	Outside	Inside	Outside	Inside	Outside	Inside	Outside

HEAVY VIBRATION & HAMMER ≈ 18'-19' OPEN

BOTTOM GIRDER, RIGHT SIDE APPEARS TO BE  
 DRAGGING ON PIER


right. Gate No. 8  
 Left Elevation B-B  
 A-A.



Member	Type	Depth d		Web t <sub>w</sub>		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>f</sub>		t <sub>f</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	✓ 15 3/8	15/16	—	15 3/4	✓	1 1/2	✓
Strut 2	14 WF 342	17 1/2	✓ 17 3/8	1 9/16	—	16 3/8	✓	2 7/16	✓
Strut 1	14 WF 398	18 1/4	✓ 18 3/4	1 13/16	—	16 5/8	✓ 16 5/8	2 13/16	✓
Brace A	14 WF 30	13 7/8	✓ 14	5/16	—	6 3/4	✓	3/8	✓
Brace B	14 WF 30	13 7/8	✓ 14	5/16	—	6 3/4	✓	3/8	✓
Brace C	14 WF 30	13 7/8	✓ 14	5/16	—	6 3/4	✓ 6 3/4	3/8	✓
Brace D	14 WF 30	13 7/8	✓ 14	5/16	—	6 3/4	✓	3/8	✓
Brace E	14 WF 30	13 7/8	✓ 14	5/16	—	6 3/4	✓	3/8	✓
Brace F	14 WF 30	13 7/8	✓ 14	5/16	—	6 3/4	✓	3/8	✓
Brace G	14 WF 30	13 7/8	✓ 14	5/16	—	6 3/4	✓	3/8	✓
Brace H	14 WF 30	13 7/8	✓ 14	5/16	—	6 3/4	✓	3/8	✓
Brace J	14 WF 30	13 7/8	✓ 14 1/2	5/16	—	6 3/4	✓ 6 3/4	3/8	✓
Brace K	14 WF 30	13 7/8	✓ 14	5/16	—	6 3/4	✓	3/8	✓
Brace L	14 WF 30	13 7/8	✓ 14	5/16	—	6 3/4	✓ 6 3/4	3/8	✓
Brace M	14 WF 30	13 7/8	✓ 14	5/16	—	6 3/4	✓	3/8	✓
Brace N	14 WF 30	13 7/8	✓ 14	5/16	—	6 3/4	✓	3/8	✓

Ⓜ cable slots, left, dry


Gate No. 8  
~~Right Elevation AA~~  
 left. BB



Member	Type	Depth d		Web t <sub>w</sub>		Flange(s)			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>f</sub>		t <sub>f</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Strut 3	14 WF 202	15 5/8	✓	15/16	✓	15 3/4	✓	1 1/2	✓
Strut 2	14 WF 342	17 1/2	✓	1 9/16	✓	16 3/8	✓	2 7/16	✓
Strut 1	14 WF 398	18 1/4	✓	1 13/16	✓	16 5/8	✓	2 13/16	✓
Brace A	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace B	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace C	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace D	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace E	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace F	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace G	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace H	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace J	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace K	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace L	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace M	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓
Brace N	14 WF 30	13 7/8	✓	5/16	✓	6 3/4	✓	3/8	✓

- (15) Left side seal, ponding water, leak, bottom.
- (16) Purlin on second girder, pitting, top
- (17) Gateface on second girder, pitting, top
- (18) left. trunnion, top strut, corrosion, before
- (19) after, light corrosion
- (20) overall gate face


Gate No. 3 Downstream Elevation



Member	Type	Depth d		Web t <sub>w</sub>		Flange - End			
		Plan (in)	Measured (in)	Plan (in)	Measured (in)	b <sub>r</sub>		t <sub>f</sub>	
						Plan (in)	Measured (in)	Plan (in)	Measured (in)
Horiz. Girder 3	PL Girder	49 3/4	✓	7/16	✓	16	✓	7/8	✓
Horiz. Girder 2	PL Girder	60 1/2	✓	3/4	✓	16 1/2	✓	1 1/4	✓
Horiz. Girder 1	PL Girder	60 1/2	✓	1	✓	16 1/2	✓	1 1/4	✓
Purlins	ST 10 WF 31	10 1/2	✓	13/32	✓	8 1/4	8 1/2	5/8	✓
Skin PL Bracing	ST 7 WF 15	7	✓	1/4	5/16	6 3/4	12 13/16	3/8	✓

- ③ ponding in second girder, no corrosion
- ④ leak on left
- ⑤ side seals, right, look good
- ⑥ leaking bottom seal, left
- ⑦ ponding water in bottom seal
- ⑧ ponding water, right, bottom girder, cable slots
- ⑨ leaking bottom seal
- ⑩ leak in bottom seal, by pier
- ⑪ middle leak
- ⑫ leak in bottom seal, - left

Gate No. 8 Upstream Elevation



DEEP PITTING UP TO 1/4" AT TOP





Gate No. 2

**Hoist Amperage Readings**

<b>Name Plate Data</b>	<u>WESTINGHOUSE</u>	
<b>Horsepower</b>	<u>15</u>	
<b>Voltage</b>	<u>460/3 PHASE/60 HZ</u>	<u>DESIGN C</u>
<b>Current</b>	<u>19.50</u>	<u>1760 RPM</u>
<b>Type</b>	<u>71D14371</u>	
<b>Frame</b>	<u>254T</u>	

Amperage		Loaded		Unloaded	
		Opening	Closing	Opening	Closing
<b>Starting</b>		108.0	104.5	106.0	102.0
<b>Running</b>	<b>Phase A</b>	15.2	9.9	13.5	9.0
	<b>Phase B</b>	15.7	10.6	14.6	9.2
	<b>Phase C</b>	14.9	9.7	14.1	10

RIGHT ANGLE GEAR BOX NOISY

---



---



---



---



---



---



---



---



---



---



---



---



Gate No. 3

**Hoist Amperage Readings**

Name Plate Data	WESTINGHOUSE	
Horsepower	15	
Voltage	460/3 PHASE/60 HZ	DESIGN C
Current	19.50	1760 RPM
Type	71D14371	
Frame	254T	

Amperage	Loaded		Unloaded		
	Opening	Closing	Opening	Closing	
<b>Starting</b>	117.6	114.4	114.4	111.2	
<b>Running</b>	<b>Phase A</b>	16.1	10.1	15.5	10.6
	<b>Phase B</b>	16.3	11.2	15.5	10.5
	<b>Phase C</b>	16.6	10.4	15.8	10.6

PRIMARY WORMGEAR REDUCER NOISY (SOUNDS DRY)  
 MAIN REDUCER HAS SEVERE LEAK (@ OUTPUT SHAFT ODE)

ODE (OPPOSITE DRIVE END)













**KLEINFELDER**

*An employee owned company*

# Ultrasonic Testing Technique Report Steel Group

Client Name: HDR Engineering  
Project Name: Walla Walla Lower Granite Dam  
Contractor: HDR Engineering  
Technique Performed By : Destry K. Hall

UT Report No.: 1  
Date: October 2, 2000  
KA Project No.: 21-6149-01-001  
Client Contact: Wayne Edwards  
Level : 2

Type of Inspection (check one):      Straight Beam       Angle Beam       Other   
If other please specify : Evaluation of moment resisting frames.

Drawings Referenced: Walla Walla District Corps of Engineers, Draft Scope Outline, Radial Gate Inspection, Analysis and Testing, Lower Granite Dam.

Equipment: Krautkramer Branson      USN 52L      s/n: 00D94J ;      Date of Calibration: 4/26/00

Transducer: SWS, Gamma, 2.25 X .75 X .625, BNC      s/n : 00CM4P      : Wedge, SF-AWS, 70 DEG. , s/n: 00D0JB

Test Block: IIW, Type 1, Steel ; s/n: 7856      /      DSC, Steel ; s/n: 98-6331

Method Used: Procedure # 1, Top quarter 70°, Middle half 70°, Bottom quarter 70°; Face A and Face B when possible

Scanning Method: Pattern E w/ A, B and C movement      Scanning Level: 20 dB above Zero Reference.

Material Type: ASTM A36 / ASTM A572

Temp. of Material: Ambient      Sensitivity Level: 80% FSH      Surface Condition: Tight adhering paint

Examination Standard: ASTM E 164-94      Acceptance Standard: AWS D1.5-95      NDT Procedure No.: KA-NDETP-UT-001

Quality requirements - section no. : AWS D1.5-98 Section # 9.21.3 and Table 9.1; and Section 9 Part C

Weld joint AWS: TC-U5-GF, TC-U4b-GF, B-U4b-GF, B-U5-GF      Welding process : GMAW / FCAW / SMAW

Material Thickness : 3/4 through 1-5/8

Weld identification: Each weld was identified on drawings by HDR Representative Sam Planck; All testing was performed for information only.

**CERTIFICATION PAPERS ARE AVAILABLE UPON REQUEST.**

We, the undersigned, certify that the statements in this record are correct and that the welds were prepared and tested in accordance with the requirements of ANSI/AASHTO/AWS D1.5 (1995) Bridge Welding Code.  
year

**Kleinfelder, Inc.**

Inspector Signature: 

Inspector Name: Destry K. Hall

Page 1 of 10.

**KLEINFELDER**

An employee owned company

**ULTRASONIC TEST REPORT**

CLIENT NAME HDR Engineering  
 PROJECT NAME Walla Walla; Lower Granite Dam  
 CONTRACTOR C.O.E  
 GATE NO.: 1 through 8

DATE: 10-2/10-13/00  
 PROJECT NO.: 21-6149-01  
 UT REPORT NO.: 001  
 PAGE 2 OF 10

**REPORT OF ULTRASONIC TESTING OF MATERIALS**

COUPLANT	Ultragel II	INSTRUMENT SN#:	00D94J	JOINT DESCRIPTION:	
CAL BLOCK SN#	IIW (7856)	REFERENCE LEVEL:	48 Db	BUTT JOINT:	B-U4b-GF / B-U5-GF
TRANSDUCER SN#	00CM4P	SCANNING LEVEL:	+20 Db	CORNER JOINT:	TC-U5-GF
ANGLE/MODE:	70 & 60 deg.	SURFACE CONDITION:	Painted	T-JOINT:	TC-U4b-GF
ACCEPT CRITERIA AWS TBL:	9.1	MATERIAL THICKNESS:	3/4" / 1-5/8"	COMMENTS: Welding process used: SMAW/GMAW/FCAW. Tested through painted surface. Information only.	
EXAMINATION FROM FACE:	A & B	VOLUMETRIC EXAM IN LEG:			
ZERO DEGREE TRANSDUCER:		DIAMETER: 1"	FREQUENCY: 2.25 Mhz		

ITEMS EXAMINED / TESTED: 3-strut arm splices and center strut mid-span splice  
 ITEM DESIGNATION: Gate 1, Gate 2, Gate 3, Gate 4, Gate 5, Gate 6, Gate 7 and Gate 8  
Strut 1(a), Strut 2(a), Strut 3(a), Trunnion (a), Strut 1(b), Strut 2(b), Strut 3(b) and Trunnion (b)

WELD IDENTIFICATION	ACCEPTED	REJECTED	REMARKS
1. Gate 1	41	3	
2. Gate 2	42	2	
3. Gate 3	37	7	
4. Gate 4	27	17	
5. Gate 5	41	3	
6. Gate 6	41	3	
7. Gate 7	29	15	
8. Gate 8	40	4	
9.			
10.			

TOTAL WELDS TESTED: 352  
 TOTAL WELDS ACCEPTED: 298  
 TOTAL WELDS REJECTED: 54

COMMENTS and/or SKETCH:

5%





**KLEINFELDER**

*An employee owned company*


# ULTRASONIC TEST REPORT GATE 1

PROJECT NAME Walla Walla; Lower Granite Dam  
PROJECT NO.: 21-6149-01


DATE: 10-2/10-13/00  
PAGE 3 of 10

### INFORMATION ON REJECTED WELDS

LINE NUMBER	INDICATION NUMBER	TRANSDUCER ANGLE	FROM FACE	LEG	DECIBALS				DISCONTINUITY					Discontinuity Evaluation	Remarks
					Indication Level	Reference Level	Attenuation Factor	Indication Rating	Length	Angular Distance (Sound Path)	Depth from "A" Surface	DISTANCE			
												a	b		
1	336	70	A	1 & 2	52dB	48 Db	.562	3.438	1.25	1.281	.832			B	
2	348	70	A	1 & 2	54dB	48 Db	2.794	3.206	2.625	2.397	1.296			B	
3	356	70	A	1 & 2	49dB	48 Db	1.594	-.594		1.797	1.034			A	
4															
5															
6															
7															
8															
9															
10															
11															
12															
13															
14															
15															
16															
17															
18															
19															
20															



**GATE 1 (Outer Left)**



**GATE 1 (Inner Right)**



**KLEINFELDER**

*An employee owned company*


# ULTRASONIC TEST REPORT GATE 2

PROJECT NAME: Walla Walla; Lower Granite Dam  
PROJECT NO.: 21-6149-01


DATE: 10-2/10-13/00  
PAGE: 4 of 10

### INFORMATION ON REJECTED WELDS

LINE NUMBER	INDICATION NUMBER	TRANSDUCER ANGLE	FROM FACE	LEG°	DECIBALS				DISCONTINUITY				Discontinuity Evaluation	Remarks	
					Indication Level	Reference Level	Attenuation Factor	Indication Rating	Length	Angular Distance (Sound Path)	Depth from "A" Surface	DISTANCE			
												From X			From Y
a	b	c	d												
1	58fo	70	A	1+2	48db	48db	5.016	-5.016		3.508	1.200			A	
2	59fo	70	A	1+2	52dB	48db	4.886	-886		3.443	1.178			A	
3															
4															
5															
6															
7															
8															
9															
10															
11															
12															
13															
14															
15															
16															
17															
18															
19															
20															



**GATE 2 (Outer Left)**



**GATE 2 (Inner Right)**



**KLEINFELDER**

An employee owned company


# ULTRASONIC TEST REPORT GATE 3

PROJECT NAME: Walla Walla; Lower Granite Dam  
PROJECT NO.: 21-6149-01


DATE: 10-2/10-13/00  
PAGE: 5 of 10

### INFORMATION ON REJECTED WELDS

LINE NUMBER	INDICATION NUMBER	TRANSDUCER ANGLE	FROM FACE	LEG	DECIBALS				DISCONTINUITY				Discontinuity Evaluation	Remarks	
					Indication Level	Reference Level	Attenuation Factor	Indication Rating	Length	Angular Distance (Sound Path)	Depth from "A" Surface	DISTANCE			
												a			b
1	25f	70	A	1 & 2	50dB	48 Db	1.014	1.986		1.507	1.758			A	
2	26w	70	A	1 & 2	54dB	48 Db	4.35	1.65		3.175	1.034			A	
3	27f	70	A	1 & 2	52dB	48 Db	4.014	1.014		3.004	1.234			A	
4	28f	70	A	1 & 2	49dB	48 Db	1.268	1.268		1.634	1.978			A	
5	29f	70	A	1 & 2	50dB	48 Db	1.718	1.282		1.859	1.937			A	
6	30f	70	A	1 & 2	54dB	48 Db	3.014	2.98	1.125	2.507	1.878			B	
7	31w	70	A	1 & 2	54dB	48 Db	<del>3.906</del> 3.094	<del>2.094</del> 2.094	1.875	2.253	1.178			A	
8															
9															
10															
11															
12															
13															
14															
15															
16															
17															
18															
19															
20															



**GATE 3 (Outer Left)**



**GATE 3 (Inner Right)**

**KLEINFELDER**


An employee owned company

# ULTRASONIC TEST REPORT


## GATE 4

PROJECT NAME: Walla Walla; Lower Granite Dam  
PROJECT NO.: 21-6149-01DATE: 10-2/10-13/00  
PAGE: 6 of 10**INFORMATION ON REJECTED WELDS**

LINE NUMBER	INDICATION NUMBER	TRANSDUCER ANGLE	FROM FACE	LEG	DECIBALS				DISCONTINUITY				Discontinuity Evaluation	Remarks	
					Indication Level	Reference Level	Attenuation Factor	Indication Rating	Length	Angular Distance (Sound Path)	Depth from "A" Surface	DISTANCE			
												From X			From Y
a	b	c	d												
1	36w	70	A	1+2	54dB	48dB	3.906	2.094		2.953	1.010			A	
2	37fo	70	A	1+2	54dB	48dB	.802	6.802	1.5	.599	.205			D	Acceptable
3	38fi	70	A	1+2	54dB	48dB	5.01	.99		3.505	1.198			A	
4	39fi	70	A	1+2	54dB	48dB	4.35	1.65		3.175	1.086			A	
5	40fi	70	A	1+2	54dB	48dB	4.542	1.458		3.271	1.119			A	
6	42fo	70	A	1+2	54dB	48dB	-.404	6.404	3.5"	.798	.272			D	Acceptable
7	43w	70	A	1+2	54dB	48dB	.562	5.438	2.5"	1.281	.438			D	Acceptable
8	44fi	70	A	1+2	50dB	48dB	-.294	2.294	.375"	.853	.285			A	
9	45w	70	A	1+2	54dB	48dB	2.542	3.458	.375"	2.271	.777			B	Acceptable by length
10	46fo	70	A	1+2	48dB	48dB	5.582	-5.582		3.791	1.296			A	
11	47fi	70	A	1+2	54dB	48dB	2.794	3.206	.875"	2.397	.820			B	
12	48w	70	A	1+2	50dB	48dB	3.014	-1.014		2.507	.857			A	
13	49fo	70	A	1+2	49dB	48dB	-.406	1.406		.797	.272			A	HAZ
14	50fo	70	A	1+2	48dB	48dB	.026	-.026		1.013	.346			A	HAZ
15	51fo	70	A	1+2	48dB	48dB	1.706	.204		1.853	.375			A	ind. out of gate, 60% fish
16	52fi	70	A	1+2	49dB	48dB	5.788	-4.788		3.894	1.331			A	
17	53fo	70	A	1+2	48dB	48dB	4.158	-4.158		3.079	1.053			A	
18															
19															
20															



**GATE 4 (Outer Left)**



**GATE 4 (Inner Right)**





**KLEINFELDER**

*An employee owned company*


# ULTRASONIC TEST REPORT GATE 5

PROJECT NAME: Walla Walla; Lower Granite Dam  
PROJECT NO.: 21-6149-01


DATE: 10-2/10-13/00  
PAGE: 7 of 10

### INFORMATION ON REJECTED WELDS

LINE NUMBER	INDICATION NUMBER	TRANSDUCER ANGLE	FROM FACE	LEG	DECIBALS				DISCONTINUITY				Discontinuity Evaluation	Remarks	
					Indication Level	Reference Level	Attenuation Factor	Indication Rating	Length	Angular Distance (Sound Path)	Depth from "A" Surface	DISTANCE			
												From X			From Y
a	b	c	d												
1	78fi	70	A	1+2	50dB	48dB	3.118	-1.118	3.5"	2.559	.857			A	
2	79fi	70	A	1+2	52dB	48dB	2.652	1.348	1.850	2.326	.855			A	no data logged
3	80fi	70	A	1+2	52dB	48dB	4.084	-.084		3.024	1.034			A	
4															
5															
6															
7															
8															
9															
10															
11															
12															
13															
14															
15															
16															
17															
18															
19															
20															



**GATE 5 (Outer Left)**



**GATE 5 (Inner Right)**



**KLEINFELDER**

*An employee owned company*


# ULTRASONIC TEST REPORT GATE 6

PROJECT NAME: Walla Walla; Lower Granite Dam  
PROJECT NO.: 21-6149-01


DATE: 10-2/10-13/00  
PAGE: 8 of 10

### INFORMATION ON REJECTED WELDS

LINE NUMBER	INDICATION NUMBER	TRANSDUCER ANGLE	FROM FACE	LEG	DECIBALS				DISCONTINUITY				Discontinuity Evaluation	Remarks	
					Indication Level	Reference Level	Attenuation Factor	Indication Rating	Length	Angular Distance (Sound Path)	Depth from "A" Surface	DISTANCE			
												a			b
1	60fo	70	A	1+2	48dB	48dB	1.67	-1.67	2.75"	1.835	.897			A	no data logged
2	61fo	70	A	1+2	50dB	48dB	-272	2.272	full	.864	.295			B	
3	62fi	70	A	1+2	50dB	48dB	4.67	-2.67	3.5"	3.335	1.141			A	
4															
5															
6															
7															
8															
9															
10															
11															
12															
13															
14															
15															
16															
17															
18															
19															
20															



**GATE 6 (Inner Right)**



**GATE 6 (Outer Left)**



**KLEINFELDER**

An employee owned company


# ULTRASONIC TEST REPORT GATE 7

PROJECT NAME: Walla Walla; Lower Granite Dam  
PROJECT NO.: 21-6149-01


DATE: 10-2/10-13/00  
PAGE: 9 of 10

### INFORMATION ON REJECTED WELDS

LINE NUMBER	INDICATION NUMBER	TRANSDUCER ANGLE	FROM FACE	LEG°	DECIBALS				DISCONTINUITY				Discontinuity Evaluation	Remarks	
					Indication Level	Reference Level	Attenuation Factor	Indication Rating	Length	Angular Distance (Sound Path)	Depth from "A" Surface	DISTANCE			
												From X			From Y
a	b	c	d												
1	63fo	70	A	1+2	48dB	48dB	5.664	-5.664		3.832	1.310			A	
2	64fo	70	A	1+2		48dB									no data loged
3	65fi	70	A	1+2	48dB	48dB	5.944	-5.944		3.972	1.343			A	
4	66w	70	A	1+2	48dB	48dB	4.694	-4.694		3.347	1.144			A	
5	67fi	70	A	1+2	48dB	48dB	4.416	1.584		3.308	1.131			A	
6	68fi	70	A	1+2	48dB	48dB	-.118	.118		.941	.322			A	
7	69w	70	A	1+2	44dB	48dB	-.608	-3.392		.696	.238			A	
8	70fo	70	A	1+2	49dB	48dB	-.312	1.312		.844	.298			A	
9	71fi	70	A	1+2		48dB									no data loged
10	72fo	70	A	1+2	48dB	48dB	1.298	-1.298		1.649	.564			A	
11	73fi	70	A	1+2		48dB									no data loged
12	74w	70	A	1+2	48dB	48dB	-.704	.704		.648	.222			A	
13	75fo	70	A	1+2	48dB	48dB	-.256	.256		.872	.298			A	
14	76w	70	A	1+2	48dB	48dB	.734	-.734		1.367	.467			A	
15	77fo	70	A	1+2	50dB	48dB	3.002	-1.002		2.501	.855			A	
16															
17															
18															
19															
20															



**GATE 7 (Outer Left)**



**GATE 7 (Inner Right)**



**KLEINFELDER**

*An employee owned company*

# ULTRASONIC TEST REPORT GATE 8

PROJECT NAME: Walla Walla; Lower Granite Dam  
PROJECT NO.: 21-6149-01

DATE: 10-2/10-13/00  
PAGE: 10 of 10

### INFORMATION ON REJECTED WELDS

LINE NUMBER	INDICATION NUMBER	TRANSDUCER ANGLE	FROM FACE	LEG	DECIBALS				DISCONTINUITY				Discontinuity Evaluation	Remarks	
					Indication Level	Reference Level	Attenuation Factor	Indication Rating	Length	Angular Distance (Sound Path)	Depth from "A" Surface	DISTANCE			
												a			b
1	54	70	A	1+2	48dB	48dB	.016	-.016	2"	.922	.315			A	
2	55w	70	A	1+2	50dB	48dB	1.9	.1	1.125"	1.950	.667			A	
3	56fi	70	A	1+2	48dB	48dB	-.246	.246		.877	.300			A	
4	57w	70	A	1+2	48dB	48dB	3.196	-3.196	2.75"	2.598	.888			A	
5															
6															
7															
8															
9															
10															
11															
12															
13															
14															
15															
16															
17															
18															
19															
20															

We the undersigned, certify the statements in this record are correct and the welds were prepared and tested in accordance with the requirements of ANSI/AASHTO/AWS D1.5 (1995) Bridge Welding Code.


year

INSPECTED BY: Destry K. Hall / Jim Fisher


ASNT LEVEL: 2 / 2

SIGNATURE: 

TEST DATE: 10-2/10-13/00



**GATE 8 (Inner Right)**



**GATE 8 (Outer Left)**





Lower  
Granite  
Dam

10/06/00

1-1

**Gate 1**

Top horizontal girder, right side,  
between stiffeners at radial strut  
connection. Delaminated paint and  
light corrosion due to poor drainage.



Lower  
Granite  
Dam

10/06/00

1-2

**Gate 1**

Top horizontal girder, right side,  
between stiffeners at radial strut  
connection. Delaminated paint and  
light corrosion due to poor drainage.



Lower  
Granite  
Dam

Gate 1  
Side seal leak, left side.

10/06/00

1-3



Lower  
Granite  
Dam

Gate 1  
Middle horizontal girder, right side,  
between stiffeners at radial strut  
connection. Delaminated paint and  
light corrosion due to poor drainage.

10/06/00

1-4




Lower  
Granite  
Dam  
10/06/00  
1-5

Gate 1  
Upstream end, bottom radial strut.  
Ponding water between strut flanges  
and horizontal girder flange due to  
poor drainage.




Lower  
Granite  
Dam  
10/06/00  
1-6

Gate 1  
Left end of bottom horizontal girder.  
Standing water, no drainage between  
multiple stiffeners. Horizontal girder  
to skin plate stiffeners, standing  
water, debris and no drainage




Lower  
Granite  
Dam  
10/06/00  
1-7

Gate 1  
Bottom seal closure plate looking  
upstream. Standing water between  
closure plate, purlin webs and  
skinplate. Typical.



Lower  
Granite  
Dam  
10/06/00  
1-8

Gate 1  
Leak at center construction joint in  
spillway monolith.




Lower  
Granite  
Dam

**Gate 1**  
Leak at center construction joint in  
spillway monolith.

10/06/00

1-9




Lower  
Granite  
Dam

**Gate 1**  
Bottom of bottom horizontal girder at  
radial strut stiffeners. Delaminated  
paint, light corrosion on girder flange  
and stiffener plates. Typical.


10/06/00

1-10




Lower Granite Dam  
10/06/00  
1-11

**Gate 1**  
Top horizontal girder, right side, between stiffeners at radial strut connection. Delaminated paint and light corrosion due to poor drainage.



Lower Granite Dam  
10/07/00  
1-12

**Gate 1**  
Exposed portion of upstream gate face. Note: Surface collector installed at this time.




Lower  
Granite  
Dam

**Gate 1**  
Exposed portion of upstream gate  
face. Note: Surface collector  
installed at this time.

10/07/00

1-13



Lower  
Granite  
Dam

**Gate 1**  
Exposed portion of upstream gate  
face. Note: Surface collector  
installed at this time.

10/07/00

1-14




Lower  
Granite  
Dam

**Gate 1**  
Exposed portion of upstream gate  
face. Note: Surface collector  
installed at this time.

10/07/00

1-15




Lower  
Granite  
Dam

**Gate 1**  
Typical skin plate condition. Light  
pitting near normal water surface.  
Note: Surface collector removed.

11/20/00

1-16






Lower  
Granite  
Dam

11/20/00

1-17

**Gate 1**

Typical wear plate condition. Light grooves due to cable wear, light to moderate corrosion.




Lower  
Granite  
Dam

11/20/00


**Gate 1**

Typical skin plate condition. Light pitting near normal water surface.  
Note: Surface collector removed.



Lower  
Granite  
Dam  
11/20/00  
1-19

**Gate 1**  
Typical wear plate condition. Light grooves due to cable wear, light to moderate corrosion.



Lower  
Granite  
Dam  
11/20/00  
1-20


**Gate 1**  
Right side hoist connection. Light corrosion on lifting lugs and plates.



Lower  
Granite  
Dam

**Gate 1**  
Right side hoist connection. Light  
corrosion on lifting lugs and plates.  
Note: excellent condition of stainless  
steel U-bolts.


11/20/00  
1-21



Lower  
Granite  
Dam

**Gate 1**  
Left side hoist connection. Light  
corrosion on lifting lugs and plates.  
Note: excellent condition of stainless  
steel U-bolts.

11/20/00  
1-22




Lower  
Granite  
Dam

Gate 1  
Surface collector installed at Gate 1.

10/07/00

1-23




Lower  
Granite  
Dam

Gate 1  
Surface collector installed at Gate 1.

10/07/00

1-24




Lower  
Granite  
Dam

Gate 1  
Gate 1 top stop log with surface  
collector attached to upstream side.

10/07/00

1-25



Lower  
Granite  
Dam

Gate 1  
Surface collector installed at Gate 1.

10/07/00

1-26



Lower  
Granite  
Dam

**Gate 2**  
Left end, middle horizontal girder.  
Peeling paint on purlins, light  
corrosion.

10/05/00

2-1




Lower  
Granite  
Dam

**Gate 2**  
Left end, middle horizontal girder.  
Peeling paint on purlins, light  
corrosion.

10/05/00

2-2




Lower  
Granite  
Dam  
10/05/00  
2-3

**Gate 2**  
Left frame, vertical Brace A at middle  
horizontal girder. Approx. 3/4"  
deformation in ST



Lower  
Granite  
Dam  
10/05/00  
2-4

**Gate 2**  
Left frame, vertical Brace A and K at  
middle horizontal girder.  
Misalignment in vertical braces due to  
1" deformation in Brace A.




Lower  
Granite  
Dam

**Gate 2**  
Left frame, Brace H. Coping in brace  
at weld to top radial strut. Light  
corrosion at isolated spots.

10/05/00

2-5



Lower  
Granite  
Dam

**Gate 2**  
Bottom / side seal leak at bottom left  
corner of gate.

10/05/00

2-6





Lower  
Granite  
Dam

10/05/00

2-7

**Gate 2**  
Leak at center construction joint in  
spillway monolith.



Lower  
Granite  
Dam

10/05/00

2-8

**Gate 2**  
Left end of bottom horizontal girder.  
Standing water, no drainage between  
multiple stiffeners.



Lower  
Granite  
Dam

10/05/00

2-9

**Gate 2**

Left end of bottom horizontal girder. Standing water, no drainage between multiple stiffeners. Horizontal girder to skin plate stiffeners, standing water, debris and no drainage




Lower  
Granite  
Dam

10/05/00

2-10

**Gate 2**

Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate. Typical. Leak at center const. joint in spillway monolith.



Lower Granite Dam Gate 2 Bottom seal keeper bar and closure plate, typical.

10/05/00

2-11



Lower Granite Dam Gate 2 Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate. Typical.

10/05/00

2-12




Lower  
Granite  
Dam

Gate 2  
Close-up, right end of bottom  
horizontal girder. Standing water, no  
drainage between multiple stiffeners.

10/05/00

2-13




Lower  
Granite  
Dam

Gate 2  
Right end of bottom horiz. girder.  
Standing water, no drainage between  
multiple stiffeners. Horizontal girder  
to skin plate stiffeners, standing  
water, debris and no drainage

10/05/00

2-14




Lower  
Granite  
Dam

**Gate 2**  
Left trunnion, typical.

10/05/00

2-15



Lower  
Granite  
Dam

**Gate 2**  
Gate face and side frames, typical

10/05/00

2-16




Lower  
Granite  
Dam

**Gate 2**  
Top of right trunnion, typical.

10/05/00

2-17



Lower  
Granite  
Dam

**Gate 2**  
Bottom seal closure plate looking  
upstream. Standing water between  
closure plate, purlin webs and  
skinplate. Typical.

10/09/00

2-18



Lower  
Granite  
Dam

10/09/00

2-19

**Gate 2**

Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate. Typical.




Lower  
Granite  
Dam

10/09/00

**Gate 2**

Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate. Typical.



Lower  
Granite  
Dam


10/09/00

2-21

**Gate 2**

Left side hoist connection. Light  
corrosion on lifting lugs and plates.

Note: Excellent condition of stainless  
steel U-bolts.



Lower  
Granite  
Dam

10/09/00


2-22

**Gate 2**

Left side hoist connection. Light  
corrosion on lifting lugs and plates.

Note: Excellent condition of stainless  
steel U-bolts.






Lower  
Granite  
Dam

Gate 2  
Upstream side of left side seal. Light  
corrosion and pitting on skin plate.

10/09/00

2-23




Lower  
Granite  
Dam

Gate 2  
Upstream side of left side seal. Light  
corrosion and pitting on skin plate.

10/05/00

2-24




Lower  
Granite  
Dam

Gate 2  
Close-up, skin plate, typical.

10/05/00

2-25




Lower  
Granite  
Dam

Gate 2  
Close-up skin plate, typical.

10/09/00


2-26



Lower Granite Dam Gate 2 Embedded bottom seal plate, looking down at spillway, typical.

10/09/00

2-27



Lower Granite Dam Gate 2 Upstream side of bottom seal and bottom of skin plate. Light to moderate corrosion on skin plate.

10/09/00

2-28




Lower  
Granite  
Dam

**Gate 2**  
Downstream side of bottom seal,  
typical.

10/09/00

2-29



Lower  
Granite  
Dam

**Gate 2**  
Skin plate pitting, typical.

10/09/00

2-30



Lower  
Granite  
Dam

Gate 2  
Waterblasting of skin plate pitting,  
typical.

10/09/00

2-31




Lower  
Granite  
Dam

Gate 2  
Typical pitting.

10/09/00

2-32



Lower  
Granite  
Dam

Gate 2  
Typical pitting.

10/09/00

2-33




Lower  
Granite  
Dam

Gate 2  
Typical wear plate condition. Light  
grooves due to cable wear, light to  
moderate corrosion.

10/09/00

2-34




Lower  
Granite  
Dam

10/09/00

2-35

**Gate 2**

Skin plate pitting and corrosion along construction joint weld at left side of gate.



Lower  
Granite  
Dam

10/09/00

2-36

**Gate 2**

Close-up, skin plate pitting and corrosion along construction joint weld at left side of gate




Lower  
Granite  
Dam

Gate 3  
Left end of top horizontal girder.  
Chipped paint and light surface  
corrosion.

10/04/00

3-1




Lower  
Granite  
Dam

Gate 3  
Left end of top horizontal girder.  
Chipped paint and light surface  
corrosion. Note: Debris line on  
downstream flange of girder  
indicating inadequate drainage.

10/04/00


3-2






Lower  
Granite  
Dam  
  
10/04/00  
  
3-3

Gate 3  
Right end of top horizontal girder,  
typical.



Lower  
Granite  
Dam  
  
10/04/00  
  
3-4


Gate 3  
Middle horizontal girder, typical.



Lower  
Granite  
Dam

**Gate 3**  
Left frame, top end of Brace H.  
Coping in brace at weld to top radial  
strut, typical.


10/04/00  
3-5



Lower  
Granite  
Dam


**Gate 3**  
Left frame, typical.

10/04/00  
3-6



Lower  
Granite  
Dam  
10/04/00  
3-7

**Gate 3**  
Skin plate approx. 5' above middle  
horiz. girder, near left frame. Small  
pitting in skin plate, < 1/6" deep.




Lower  
Granite  
Dam  
10/04/00  
3-8

**Gate 3**  
Inside closure plate at right trunnion,  
looking downstream. Staining and  
light corrosion due to drain above.




Lower  
Granite  
Dam  
  
10/04/00  
  
3-9

**Gate 3**  
Outside of left trunnion and yoke,  
looking downstream. Note:  
lubrication lines and expelled  
lubrication beneath trunnion.



Lower  
Granite  
Dam  
  
10/04/00  
  
3-10


**Gate 3**  
Left end of bottom horizontal girder.  
Standing water, no drainage between  
multiple stiffeners. Horizontal girder  
to skin plate stiffeners, debris and no  
drainage



Lower  
Granite  
Dam

Gate 3  
Top of left trunnion, typical.


10/04/00  
3-11



Lower  
Granite  
Dam

Gate 3  
Purlins and skin plate, typical.

10/04/00  
3-12



Lower  
Granite  
Dam


10/04/00

3-13

**Gate 3**

Upstream end of right frame, bottom  
radial strut. Grind marks in flange.

Note: Discoloration at welded joint  
to girder due to ultrasonic weld test  
gel.




Lower  
Granite  
Dam

10/04/00

3-14

**Gate 3**

Right end of bottom horizontal  
girder. Horizontal girder to skin  
plate stiffeners, standing water,  
debris and no drainage




Lower  
Granite  
Dam

10/04/00

3-15

**Gate 3**

Outside of right trunnion and yoke  
looking downstream, typical.




Lower  
Granite  
Dam

10/04/00

3-16

**Gate 3**

Right frame, typical.




Lower  
Granite  
Dam

10/04/00

3-17

**Gate 3**  
Right trunnion and yoke looking  
downstream. Light corrosion on  
trunnion.




Lower  
Granite  
Dam

10/04/00

3-18

**Gate 3**  
Gate face and left frame, typical.






Lower  
Granite  
Dam

10/04/00

3-19

**Gate 3**

Close-up of upstream side of right trunnion and yoke. Note: Small lubrication leak at connection to trunnion.




Lower  
Granite  
Dam

10/08/00

3-20

**Gate 3**

Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate. Typical.




Lower  
Granite  
Dam

10/08/00

3-21

**Gate 3**

Upstream side of skin plate at  
bottom seal. Light to moderate  
corrosion of skin plate, typical.




Lower  
Granite  
Dam

10/08/00

3-22

**Gate 3**

Upstream side of skin plate at  
bottom seal. Light to moderate  
corrosion of skin plate, typical.




Lower  
Granite  
Dam

10/08/00

3-23

**Gate 3**

Left side hoist connection. Light corrosion on lifting lugs and plates.  
Note: excellent condition of stainless steel U-bolts.




Lower  
Granite  
Dam

10/08/00

3-24

**Gate 3**

Left side hoist connection. Light corrosion on lifting lugs and plates.  
Note: excellent condition of stainless steel U-bolts.




Lower  
Granite  
Dam

**Gate 3**  
Skin plate pitting, looking up,  
typical.

10/08/00

3-25



Lower  
Granite  
Dam

**Gate 3**  
Downstream side of bottom seal and  
keeper plate looking upstream.


10/08/00

3-26



Lower Gate 3  
Granite Bottom seal closure plate looking  
Dam upstream. Standing water between  
10/08/00 closure plate, purlin webs and  
skinplate. Typical.


3-27



Lower Gate 3  
Granite Waterblasting and typical skin plate  
Dam condition.

10/08/00


3-28



Lower Gate 3  
Granite Skin plate pitting, typical.  
Dam

10/08/00

3-29



Lower Gate 3  
Granite Skin plate pitting, typical.  
Dam

10/08/00


3-30



Lower Gate 3  
Granite Skin plate pitting, typical.  
Dam

10/08/00


3-29



Lower Gate 3  
Granite Skin plate pitting, typical.  
Dam

10/08/00

3-30




Lower  
Granite  
Dam

10/08/00

3-31

Gate 3  
Skin plate pitting, typical.




Lower  
Granite  
Dam

10/08/00

3-32

Gate 3  
Typical wear plate condition. Light  
grooves due to cable wear, light to  
moderate corrosion.






Lower  
Granite  
Dam

Gate 3  
Skin plate pitting apparently  
associated with scratches.

10/08/00

3-33




Lower  
Granite  
Dam

Gate 3  
Skin plate pitting apparently  
associated with scratches.

10/08/00

3-34




Lower  
Granite  
Dam

Gate 3  
Waterblasting upstream surface of  
skin plate.


10/08/00

3-35




Lower  
Granite  
Dam  
10/08/00  
4-1

**Gate 4**  
Paint blister and apparent skin plate  
leak approximately 7' from left side  
of gate and 6' above 1/2" to 3/8" skin  
plate transition. Photo taken after  
waterblasting of upstream side.



Lower  
Granite  
Dam  
10/08/00  
4-2

**Gate 4**  
Paint blister and apparent skin plate  
leak approximately 7' from left side  
of gate and 6' above 1/2" to 3/8" skin  
plate transition. Photo taken after  
waterblasting of upstream side.




Lower  
Granite  
Dam

**Gate 4**  
Close-up of paint blister / skin plate  
leak.

10/08/00


4-3



Lower  
Granite  
Dam

**Gate 4**  
Skin plate leak after removal of paint  
blister.

10/08/00




Lower  
Granite  
Dam

10/08/00

4-5

Gate 4  
Skin plate leak after removal of paint  
blister.




Lower  
Granite  
Dam

10/08/00


4-6

Gate 4  
Left side frame, along outside of  
frame looking downstream, typical.  
Note: Skin plate leak landing on  
middle radial strut.



Lower  
Granite  
Dam  
  
10/08/00  
  
4-7

**Gate 4**  
Skin plate leak after removal of paint  
blister.



Lower  
Granite  
Dam  
  
10/08/00  
  
4-8

**Gate 4**  
Right end of bottom horiz. girder.  
Evidence of standing water, no  
drainage between multiple stiffeners.  
Horiz. girder to skin plate stiffeners,  
debris and no drainage




Lower  
Granite  
Dam

**Gate 4**  
Bottom of upstream end of bottom  
radial strut, drain hole, typical.

10/08/00

4-9




Lower  
Granite  
Dam

**Gate 4**  
Bottom seal closure plate looking  
upstream. Standing water between  
closure plate, purlin webs and  
skinplate. Typical.

10/08/00

4-10




Lower  
Granite  
Dam

Gate 4  
Right frame, Brace F. Small  
deformation, approx. 1/8" on outside  
flange.

10/08/00

4-11




Lower  
Granite  
Dam

Gate 4  
Bottom seal closure plate looking  
upstream. Standing water between  
closure plate, purlin webs and  
skinplate. Typical.

10/07/00

4-12






Lower  
Granite  
Dam

10/07/00

4-13

**Gate 4**  
Bottom seal closure plate looking  
upstream. Standing water between  
closure plate, purlin webs and  
skinplate. Typical.




Lower  
Granite  
Dam

10/07/00

4-14

**Gate 4**  
Bottom seal and keeper plate,  
looking upstream, typical.



Lower  
Granite  
Dam

**Gate 4**  
Bottom of downstream side of gate,  
typical.

10/07/00

4-15




Lower  
Granite  
Dam

**Gate 4**  
Waterblasting of skinplate.  
Distribution of pitting, typical.

10/07/00

4-16



Lower  
Granite  
Dam

Gate 4  
Skin plate pitting, typical.

10/07/00

4-17




Lower  
Granite  
Dam

Gate 4  
Skin plate pitting, typical.

10/07/00

4-18



Lower  
Granite  
Dam

10/07/00

4-19

**Gate 4**

Typical wear plate condition. Light grooves due to cable wear, light to moderate corrosion.



Lower  
Granite  
Dam

10/08/00

5-1

**Gate 5**

Right frame, upstream end of top  
radial strut. Delaminated paint and  
light corrosion on web.



Lower  
Granite  
Dam

10/08/00

5-2

**Gate 5**


Side seal leak, right side of gate.



Lower Granite Dam Gate 5  
Right end of middle horizontal girder.  
Light corrosion due to side seal leak.

10/08/00


5-3



Lower Granite Dam Gate 5  
Right frame, middle radial strut,  
between braces G and E. Small  
deformation on top, inside flange.

10/08/00

5-4




Lower  
Granite  
Dam

Gate 5  
Right frame, Brace H. Small  
deformation on inside flange.

10/08/00

5-5



Lower  
Granite  
Dam

Gate 5  
Right frame, upstream end of bottom  
radial strut. Ponding due to  
inadequate drainage.

10/08/00

5-6



Lower  
Granite  
Dam  
10/08/00  
5-7


**Gate 5**  
Right end of bottom horizontal girder.  
Standing water, no drainage between  
multiple stiffeners. Horizontal girder  
to skin plate stiffeners, standing  
water, debris and no drainage



Lower  
Granite  
Dam  
10/08/00  
5-8

**Gate 5**  
Left end of bottom horizontal girder.  
Standing water, inadequate drainage  
between stiffeners.





Lower  
Granite  
Dam

Gate 5  
Side seal, typical.

10/08/00

5-9




Lower  
Granite  
Dam


Gate 5  
Bottom of gate at spillway, typical.

10/08/00


5-10



Lower Granite Dam	<b>Gate 5</b> Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate. Typical.
10/08/00	
5-11	



Lower Granite Dam	<b>Gate 5</b> Left end of bottom horizontal girder. Evidence of standing water, no drainage between multiple stiffeners.
10/08/00	
5-12	




Lower  
Granite  
Dam

10/08/00

5-13

Gate 5  
Left frame, upstream end of bottom  
radial strut. Ponding due to  
inadequate drainage.



Lower  
Granite  
Dam

10/06/00

5-14

Gate 5  
Waterblasting upstream surface of  
skin plate.




Lower  
Granite  
Dam

10/06/00

5-15

Gate 5  
Skin plate pitting, typical.




Lower  
Granite  
Dam

10/06/00

5-16

Gate 5  
Skin plate pitting, typical.



Lower  
Granite  
Dam

10/06/00

5-17

**Gate 5**

Typical wear plate condition. Light grooves due to cable wear, light to moderate corrosion.



Lower  
Granite  
Dam

10/06/00


5-18

**Gate 5**

Skin plate pitting apparently associated with scratches in protective coating.



Lower Granite Dam  10/06/00  5-19	<b>Gate 5</b> Typical wear plate condition. Light grooves due to cable wear, light to moderate corrosion.
---	--




Lower  
Granite  
Dam

Gate 6  
Top horizontal girder looking toward  
left frame, typical

10/06/00

6-1




Lower  
Granite  
Dam

Gate 6  
Right frame, Brace C. Coping in  
brace at weld to top radial strut.

10/06/00

6-2




Lower  
Granite  
Dam

10/06/00

6-3

**Gate 6**  
Middle horizontal girder, downstream  
flange at connection to radial strut.  
Light corrosion on girder flange.




Lower  
Granite  
Dam

10/06/00

6-4

**Gate 6**  
Downstream surface of skin plate,  
approx 5' above middle horizontal  
girder, near left frame. Small surface  
pitting.






Lower  
Granite  
Dam

Gate 6  
Right frame and trunnion, typical.

10/06/00

6-5



Lower  
Granite  
Dam

Gate 6  
Left frame, inside trunnion closure  
plate, typical.

10/06/00

6-6




Lower  
Granite  
Dam

10/06/00

6-7

**Gate 6**  
Outside of right trunnion and yoke.  
Note: Lubrication lines.




Lower  
Granite  
Dam

10/06/00


6-8

**Gate 6**  
Leak at center construction joint in  
spillway monolith.




Lower  
Granite  
Dam  
10/06/00  
6-9

**Gate 6**  
Right frame, bottom radial strut.  
Standing water at upstream end of  
strut due to inadequate drainage.



Lower  
Granite  
Dam  
10/06/00  
6-10

**Gate 6**  
Right end of bottom horizontal girder,  
standing water at upstream side of  
girder web and flange.




Lower  
Granite  
Dam

10/06/00

6-11

**Gate 6**

Right end of bottom horiz. girder.  
Standing water, no drainage between  
multiple stiffeners. Horizontal girder  
to skin plate stiffeners, standing  
water, debris and no drainage




Lower  
Granite  
Dam

10/06/00

6-12


**Gate 6**

Left frame, bottom radial strut.  
Evidence of standing water at  
upstream end of strut due to  
inadequate drainage. Light  
corrosion.




Lower  
Granite  
Dam  
10/06/00  
6-13

**Gate 6**  
Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate, typical.




Lower  
Granite  
Dam  
10/06/00  
6-14

**Gate 6**  
Leak at center construction joint in spillway monolith, additional bottom seal leaks.




Lower  
Granite  
Dam  
  
10/06/00  
  
6-15

**Gate 6**  
Bottom seal keeper plate, looking  
upstream, typical.



Lower  
Granite  
Dam  
  
10/06/00  
  
6-16

**Gate 6**  
Side seal, typical.




Lower  
Granite  
Dam

**Gate 6**  
Bottom of left frame horizontal  
girders, typical.

10/06/00

6-17




Lower  
Granite  
Dam

**Gate 6**  
Outside of left trunnion and yoke.  
Note: Lubrication lines and expelled  
lubrication between trunnion and  
yoke.

10/06/00

6-18




Lower  
Granite  
Dam

Gate 6  
Left frame, typical.

10/06/00

6-19




Lower  
Granite  
Dam

Gate 6  
Right frame, typical.

10/06/00

6-20






Lower  
Granite  
Dam

10/05/00

6-21

**Gate 6**

Bottom seal closure plate and skin plate looking upstream. Standing water between closure plate, purlin webs and skinplate, typical.




Lower  
Granite  
Dam

10/05/00

6-22

**Gate 6**

Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate, typical.




Lower  
Granite  
Dam

**Gate 6**  
Embedded bottom seal plate, typical.

10/05/00

6-23



Lower  
Granite  
Dam

**Gate 6**  
Bottom seal closure plate looking  
upstream. Standing water between  
closure plate, purlin webs and  
skinplate, Note: good condition of  
stainless steel bolts and nuts.

10/05/00

6-24




Lower  
Granite  
Dam

**Gate 6**  
Skin plate pitting, typical.

10/05/00

6-25




Lower  
Granite  
Dam

**Gate 6**  
Typical skin plate condition.

10/05/00


6-25



Lower Gate 6  
Granite Waterblasting of skin plate, typical.  
Dam

10/05/00


6-27



Lower Gate 6  
Granite Waterblasting of skin plate, typical.  
Dam

10/05/00


6-28



Lower Gate 6  
Granite Skin plate pitting, typical.  
Dam

10/05/00


6-29



Lower Gate 6  
Granite Typical wear plate condition. Light  
Dam grooves due to cable wear, light to  
moderate corrosion.

10/05/00

6-30



Lower  
Granite  
Dam

10/07/00

7-1

**Gate 7**

Horizontal girder stiffeners at left frame middle radial strut. Note: upstream end of stiffeners not welded to girder flange. Correct per plans.



Lower  
Granite  
Dam

10/07/00

7-2


**Gate 7**

Left end of bottom horizontal girder. Standing water, no drainage between multiple stiffeners. Horizontal girder to skin plate stiffeners, standing water, debris and no drainage




Lower  
Granite  
Dam  
10/07/00  
7-3

**Gate 7**  
Bottom seal closure plate looking  
upstream. Standing water between  
closure plate, purlin webs and  
skinplate. Typical.



Lower  
Granite  
Dam  
10/07/00  
7-4

**Gate 7**  
Leak at center construction joint in  
spillway monolith.




Lower  
Granite  
Dam

10/07/00

7-5

**Gate 7**

Bottom of bottom left radial strut.  
Light corrosion at connection to  
bottom girder. Note: Discolorization  
on strut flange due to ultrasonic  
testing gel.



Lower  
Granite  
Dam

10/07/00

7-6

**Gate 7**

Right horizontal girder bracing A to  
K. Deformed web in brace K.






Lower  
Granite  
Dam

Gate 7  
Top horizontal girder near right radial  
strut connection. Light corrosion

10/07/00

7-7




Lower  
Granite  
Dam

Gate 7  
Upstream surface of skin plate,  
typical. Note: Weld lines for purlins  
visible through 3/8" skin plate.

10/07/00

7-8




Lower  
Granite  
Dam

10/04/00

7-9

**Gate 7**

Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate. Typical.




Lower  
Granite  
Dam

10/04/00

7-10

**Gate 7**

Close up embedded bottom seal plate, typical.



Lower  
Granite  
Dam

10/04/00

7-11

**Gate 7**

Bottom seal keeper plate and  
embedded bottom seal plate, typical.




Lower  
Granite  
Dam

10/04/00

7-12

**Gate 7**

Skin plate pitting, typical.




Lower  
Granite  
Dam

**Gate 7**  
Skin plate pitting, typical.

10/04/00

7-13




Lower  
Granite  
Dam


**Gate 7**  
Typical skin plate condition. Heavy  
pitting. Note: Pitting often appears  
to be oriented in lines associated  
with scratches.

10/04/00


7-14



Lower Granite Dam	Gate 7 Skin plate pitting, typical. Note: Pitting appears to be oriented in line associated with scratch.
10/04/00	
7-15	



Lower Granite Dam	Gate 7 Typical wear plate condition. Light grooves due to cable wear, light to moderate corrosion.
10/04/00	
7-16	




Lower  
Granite  
Dam

10/07/00

8-1

**Gate 8**

Middle horizontal girder at  
connection to middle right strut.  
Debris and evidence of standing  
water, light corrosion.




Lower  
Granite  
Dam

10/07/00

8-2

**Gate 8**

Bottom corner leak at left frame.



Lower  
Granite  
Dam

10/07/00

8-3

Gate 8  
Side seal, typical.




Lower  
Granite  
Dam

10/07/00

8-4

Gate 8  
Bottom right corner seal leak.



Lower  
Granite  
Dam

Gate 8  
Upstream end of bottom right strut.  
Standing water due to inadequate  
drainage.

10/07/00

8-5




Lower  
Granite  
Dam

Gate 8  
Right upstream end of bottom  
horizontal girder. Standing water at  
upstream flange and web.

10/07/00

8-6






Lower  
Granite  
Dam  
10/07/00  
8-7

**Gate 8**  
Right end of bottom horiz. girder.  
Standing water, no drainage between  
multiple stiffeners. Horizontal girder  
to skin plate stiffeners, standing  
water, debris and no drainage




Lower  
Granite  
Dam  
10/07/00  
8-8

**Gate 8**  
Bottom seal keeper plate and leak at  
center construction joint in spillway  
monolith.




Lower  
Granite  
Dam  
10/07/00  
8-9

**Gate 8**  
Bottom seal closure plate looking  
upstream. Standing water between  
closure plate, purlin webs and  
skinplate. Typical.



Lower  
Granite  
Dam  
10/07/00  
8-10

**Gate 8**  
Downstream side of embedded  
bottom seal plate and small bottom  
left corner leak.



Lower  
Granite  
Dam

**Gate 8**  
Spillway looking toward left side of  
gate. Bottom corner leak.

10/07/00

8-11




Lower  
Granite  
Dam

**Gate 8**  
Left end of bottom horiz. girder.  
Standing water, no drainage between  
multiple stiffeners. Horizontal girder  
to skin plate stiffeners, debris and no  
drainage.

10/07/00

8-12



Lower  
Granite  
Dam

Gate 8  
Bottom left corner leak.

10/07/00

8-13




Lower  
Granite  
Dam

Gate 8  
Purlin flange small pitting, typical.

10/07/00

8-14




Lower  
Granite  
Dam

**Gate 8**  
Downstream surface of skin plate  
pitting, typical.

10/07/00

8-15



Lower  
Granite  
Dam

**Gate 8**  
Top left radial strut near trunnion.  
Light corrosion on top of web  
(before scraping).

10/07/00

8-16




Lower  
Granite  
Dam

10/07/00

8-17

**Gate 8**  
Top left radial strut near trunnion.  
Light corrosion on top of web (after  
scraping).




Lower  
Granite  
Dam

10/07/00

8-18

**Gate 8**  
Gate looking upstream, typical.




Lower  
Granite  
Dam

10/03/00

8-19

**Gate 8**

Embedded bottom seal plate, typical.




Lower  
Granite  
Dam

10/03/00

8-20

**Gate 8**

Bottom left corner of gate.




Lower  
Granite  
Dam

10/03/00

8-21

**Gate 8**

Bottom seal closure plate looking upstream. Standing water between closure plate, purlin webs and skinplate. Typical.



Lower  
Granite  
Dam


10/03/00

8-22

**Gate 8**

Embedded bottom seal plate, typical.






Lower  
Granite  
Dam

10/03/00

8-23

**Gate 8**

Upstream surface of skin plate and  
wear plate at normal water surface  
line.




Lower  
Granite  
Dam

10/03/00

8-24

**Gate 8**

Close-up upstream surface of skin  
plate and wear plate at normal water  
surface line. Light pitting, scratches  
and scrapes above and below water  
surface line.




Lower  
Granite  
Dam

Gate 8  
Skin plate pitting, typical.

10/03/00

8-25




Lower  
Granite  
Dam

Gate 8  
Skin plate pitting near wear plate,  
typical.

10/03/00


8-26



Lower Gate 8  
Granite Skin plate pitting, typical.  
Dam  
10/03/00  
8-27



Lower Gate 8  
Granite Skin plate pitting along weld line.  
Dam  
10/03/00  
8-28




Lower Gate 8  
Granite Typical wear plate condition. Light  
Dam grooves due to cable wear, light to  
10/03/00 moderate corrosion.

8-29



Lower Gate 8  
Granite Right hoist connection. Moderate  
Dam pitting on lifting lugs and plates.  
10/03/00 Stainless steel U-bolts in good  
condition.

8-30




Lower  
Granite  
Dam

**Hoist & Mechanical**

Hoist, typical

M-1



Lower  
Granite  
Dam

**Hoist & Mechanical**

Hoist motor, typical.


M-2

00.0211




Lower Granite Dam  
**Hoist & Mechanical**  
 Hoist motor name plate, typical.

M-3



Lower Granite Dam  
**Hoist & Mechanical**  
 Hoist drum, typical.

M-4



PROPERTY OF  
 THE U.S. GOVERNMENT  
 GPO: 1967 O - 348-200  
 OFFICIAL BUSINESS

A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	V	W	X	Y	Z


SCALE: AS SHOWN  
 ALL DIMENSIONS IN INCHES  
 UNLESS OTHERWISE SPECIFIED  
 THIS DRAWING IS THE PROPERTY OF THE U.S. GOVERNMENT  
 IT IS TO BE KEPT UNCLASSIFIED  
 PERMANENTLY UNLESS INDICATED OTHERWISE

**GENERAL ARRANGEMENT.**  
**FOR ELEVATIONS & DETAILS SEE DWG'S E34E6**



THIS DRAWING AND INFORMATION IT CONTAINS ARE THE PROPERTY OF THE FLAT STEEL CORPORATION. THIS DRAWING IS NOT TO BE REPRODUCED, COPIED, EITHER WHOLLY OR IN PART, WITHOUT THE EXPRESS PERMISSION OF THE FLAT STEEL CORPORATION.

FASTENERS: AS SHOWN  
 WELDS: ALL AROUND

①



AFTER GROUT HAS BEEN PLACED BEHIND YOKE, TENSION STUDS BY MEANS OF A JACK TO A LOAD OF 80 KIIPS PER STUD. CUT OFF EXCESS STUD & COVER WITH 1" MIN. CONCRETE OVERENDS OF STUDS



L ARRANGEMENT  
 NS & DETAILS SEE DWG'S E34E4


ERECTOR NOTE - STRUTS, GIRDERS MUST BE ASSEMBLED FIN-UP CLIPS ARE TO WELD TOGETHER DURING WELD CARRY THE WEIGHT OF

(2)

TITLE: _____ PROJECT: _____ DRAWN BY: _____ CHECKED BY: _____ DATE: _____	UNLESS NOTED OTHERWISE, ALL DIMENSIONS ARE IN FEET AND INCHES. FRACTIONS SHALL BE IN 16THS OF AN INCH. DECIMALS SHALL BE IN THOUSANDS OF AN INCH.	1 2 3 4 5 6 7 8 9 10 11 12	DESIGNED BY: <u>PC</u> DATE: <u>12/18/10</u> CHECKED BY: <u>AM</u> DATE: <u>12/18/10</u> APPROVED BY: _____ DATE: _____
---	---	---	---



ACED  
LOAD  
UT  
WITH  
DS



**ERECTION NOTE -**  
 STRUTS, GIRDERS AND SKIN PLATE SECTIONS  
 MUST BE ADEQUATELY SUPPORTED DURING ERECTION.  
 PIN-UP CLIPS ARE TO HOLD THE VARIOUS SECTIONS  
 TOGETHER DURING WELDING AND ARE NOT DESIGNED TO  
 CARRY THE WEIGHT OF THE MEMBERS.

3

NO PER NUMBER 182  
 CONTRACT NUMBER DACW-66-70-C-0008

APPROVAL STAMP  
**APPROVED**  
 Subject to compliance with plans and specifications,  
 erection of steel as described, and to fullness of  
 steel material tests, Contractor shall not accept liability of  
 installation or responsibility for erecting and bolting.  
 LOWER SNAKE RIVER  
 RESIDENT OFFICE  
 25 SEP 1960

LSR70-0088-132-004

DESIGNED BY	DATE
TRACED BY	DATE
CHECKED BY	DATE
APPROVED BY	DATE

STEEL CORPORATION  
 1228, TULSA, OKLAHOMA 74101  
 ENGINEERING DEPARTMENT

SPILLWAY PARTS BOX ARRANGEMENT  
 LOWER GRANITE LOCK DAM  
 LOWER GRANITE CONTR.  
 BULLMAN, WASH.  
 70-0544  
 E-2

70-C-88-351

PROJECT NO. \_\_\_\_\_  
 DRAWING NO. \_\_\_\_\_

SCALE: \_\_\_\_\_  
 DATE: \_\_\_\_\_

DESIGNED BY: \_\_\_\_\_  
 CHECKED BY: \_\_\_\_\_

APPROVED BY: \_\_\_\_\_

DATE: \_\_\_\_\_


SCALE: \_\_\_\_\_

DATE: \_\_\_\_\_

SCALE: \_\_\_\_\_



DATE: \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z






(1)

THE DRAWING AND SPECIFICATIONS IT CONTAINS ARE THE PROPERTY OF THE PLANT AND OPERATOR. THE DRAWING IS NOT TO BE REPRODUCED, COPIED, OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, WITHOUT THE WRITTEN PERMISSION OF THE PLANT AND OPERATOR.



SECTION A-A





SECTION B-B


2

HOLE: _____ UNLESS NOTED PART: _____ UNLESS NOTED FINISH: _____ UNLESS NOTED	NOTES: 1. CHECK DET. B' B DIMENSIONS ELEV. 18-18 2. REEL ORIENTATION OF BRACE ON INSIDE OF GIRDER 3. FINISH BRACE SURFACE TO MATCH BR. LATERAL BR. DET. 2-2	DRAWN BY: PC CHECKED BY: RLB:7 DATE: 11/27/57 PROJECT: _____ SHEET: _____ OF _____
--	--	--

REFERENCE ANGLES-BIG-SHALL BE LOCATED SO THAT THEY WILL ALIGN WITH EMBEDDED REFERENCE MEMBER WHEN VERTICAL. DISTANCE BETWEEN BOTTOM OF GATE & SILL 13'-0" & 15'-0" - SEE SPECS 17-17.10



UPSTREAM ELEVATION



SECTION B-B

DRAWING NUMBER 132  
CONTRACT NUMBER 70-C-88-0088

APPROVAL STAMPS

**APPROVED**

Subscribed to, executed, and specified by the Engineer, in accordance with the contract and by authority of the Board of Directors, and by authority of the Board of Directors, in accordance with the contract, to certify the design and construction of the work.

FLINT STEEL CORPORATION  
RESIDENT OFFICE

By: [Signature]  
Date: 25 SEP 1970

3


LSR 70-0088-132-005

DATE OF SUBMITTAL	DATE OF REVIEW	DATE OF APPROVAL	DATE OF REVISION

FLINT STEEL CORPORATION  
1000 WEST WYOMING AVENUE  
ANN ARBOR, MICHIGAN 48106  
TELEPHONE (313) 963-1000


70-C-88-352

DRILL HOLES IN  
AT 5/16"  
USE A15 FOR TEM




SECTION C-C - THUS

SECTION X-X-REV.



SECTION G-G



DETAIL "A"

POSITION  
PAGE MARK

SCALE  
1/4" = 1'-0"

A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

POSITION  
PAGE MARK



SCALE  
1/4" = 1'-0"

WELD LENGTH  
WELD ALL AROUND

THIS DRAWING AND SPECIFICATION IT CONTAINS ARE THE PROPERTY OF THE PLANT OPERATOR. THE DRAWING IS NOT TO BE REPRODUCED, COPIED, OR TRANSMITTED IN ANY FORM OR BY ANY MEANS WITHOUT THE EXPRESS PERMISSION OF THE PLANT OPERATOR.

HOLES  
FASTENERS  
PARTS







DRILL HOLES IN CLOSURE PL.  
AT SHOP ASSEMBLY,  
USE A15 FOR TEMPLATE



SECTION C-C - THUS  
SECTION X-X - REV.

SECTION H-H

DETAIL "D"  
(TYPICAL STRUT TO GIRDER SPLICE)



2


THIS DRAWING AND INFORMATION IT CONTAINS ARE THE PROPERTY OF THE PLANT STEEL CORPORATION. THE DRAWING IS NOT TO BE REPRODUCED, COPIED, OR USED FOR ANY PURPOSE WITHOUT THE EXPRESS PERMISSION OF THE PLANT STEEL CORPORATION.

HOLES: UNLESS NOTED OTHERWISE  
FASTENERS: UNLESS NOTED OTHERWISE  
FINISH: UNLESS NOTED OTHERWISE

NOTES


ADD DETAIL 'H'	DATE	BY
CORRECT SEAL EDGES IN SEAL C-D & E-F	DATE	BY
REMOVED WELD SYMBOLS, PAR. 1 & 2, FROM DRAWING	DATE	BY
SHOW PL. IN REV.	DATE	BY
REV. FOR APPROVAL SIGNATURE 3-15-77	DATE	BY

DRAWN BY: J.C. DATE: 10-27-76  
CHECKED BY: C.M. DATE: 11-1-76  
APPROVED BY: DATE: 11-1-76




REMOVE CLIPS TO COMPLETE FIELD WELD; PLUG WELD HOLES IN STRUT FLANGE

- 3/4" M. BOLT x 0'-0" 1/4 (LOWER STRUT)
- 3/4" M. BOLT x 0'-0" 3/4 (CENTER STRUT)
- 3/4" M. BOLT x 0'-0" 2 3/4 (UPPER STRUT)




DETAIL "D"  
(TYPICAL STRUT TO GIRDER SPLICE)




REMOVE CLIP ANGLES TO COMPLETE FIELD WELD

SECTION D-D  
SKIN PL SPLICE




REMOVE CLIP ANGLES TO COMPLETE FIELD WELD

SECTION E-E  
SKIN PL SPLICE




NOTE: DO NOT REMOVE AFTER FIELD ASS'Y

DETAIL "C"  
TYP. RIG TO GIRDER FLG.




ST-7 W 15 BRACING

SECTION F-F  
TYP BRACING CONN.



DETAIL "G" THUS  
DETAIL "H" REV.  
CLOSURE PL & FILLER ARE  
WELDED - SEALS NOT SHOWN



SECTION K-K

BOI SPEC NUMBER 132  
CONTRACT NUMBER DRCW-23-70-C-006

APPROVAL STAMPS

**APPROVED**

LOWER SHIMMER RIVER  
RESIDENT OFFICE

DATE: 22 SEP 1973

LSR70-0088-132-006


QUANTITY NUMBER 132	DATE 12-18-70	FLINT STEEL CORPORATION	SECTION 4 FIELD ERECTION
DESIGNED BY PC	DATE 12-18-70	BOX 1280, TULSA, OKLAHOMA 74101	TOWER GRANITE LOCK AREA
DRAWN BY	DATE	ENGINEERING DEPARTMENT	LOWER GRANITE COAST
CHECKED BY C.L.P.	DATE 12-23-70		PULLMAN HARD
APPROVED BY	DATE		

70-C-88-352







DRILL & TAP 1/2-13 NC x 3 DEEP  
 TEMPLATE FROM PL F2 (NOT SHOWN)  
 FOR 2 x 3 CRS. BOLTS - g2




- B - THUS  
 - C - REV



DETAIL "A" - THRUST WASHER - F2  
 CORR. RES. STL. QQ-S-7636, CLASS 300, COND. A.

SECTION A-A



B-TRUNNION YOKES - THUS - A2  
 B-TRUNNION YOKES - REV - RA2

NOTE  
 TAG ALL MATERIAL  
 WITH ITEM NO 152

DESIGN AND INFORMATION OF CONTAINS ARE THE PROPERTY  
 OF THE COMPANY. NO PART OF THIS DRAWING IS TO BE  
 REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY  
 MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING,  
 RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL  
 SYSTEM, WITHOUT PERMISSION IN WRITING FROM THE COMPANY.

NOTES:  
 1. NONE

NOTES:  
 1. NONE

REVISOR	WELD SYMBOLS	R. HARRIS	DATE
DESIGNED	DATE	11-12-71	
CHECKED	DATE		
APP. FOR DESIGN	DATE		





1-TRUNNION HUB- 0.3"  
 SEE DETAILS SHIP 4

1-16W.378 STRU.  
 SEE DETAILS 5


A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z

1-TRUNNION HUB- 0.3"  
 SEE DETAILS SHIP 4

1-16W.378 STRU.  
 SEE DETAILS 5



SECTION A-A




SECTION C  
TYP. STRU. TO H

**SHOP NOTE**  
 PICTURE IS DRAWN  
 BUT THEY ARE NOT  
 PLANE PASSING TH  
 IS CU. ON A BEVE

①

THE DRAWING AND INFORMATION OF DETAILS ARE THE PROPERTY  
 OF THE PLANT OPERATOR. THE DRAWING IS NOT TO BE  
 REPRODUCED, COPIED, OR USED FOR ANY PURPOSES WITH-  
 OUT THE WRITTEN PERMISSION OF THE PLANT OPERATOR.



DETAIL "A"  
CONN TYP @ BOTH ENDS OF D31 F3

SECTION A-A  
TYP. STRUT TO HUB. CONN

(2)

NOTE:  
1. WORK THIS SHY W/  
2. TAG ALL MAT'L N.

8- TRUNNION ARM SECTIONS - THIS - A3  
8- TRUNNION ARM SECTIONS - REV - RA3

SHOP NOTE

PICTURE IS DRAWN LOOKING AT BOTH ARMS FROM A RIGHT AT THE SAME TIME. EACH ARM IS A TRUE VIEW BUT THEY ARE NOT SHOWN IN A TRUE RELATION TO ONE ANOTHER. THE BEAMS ARE TILTED SLIGHTLY TO A PLANE PASSING THRU THEIR & PER SECTION A-A. A LINE PASSING THRU THE WEB ON THE LEFT END THAT IS CUT ON A BEVEL SHOULD BE PERFECTLY HORIZONTAL. ALL DIM. MUST BE WORKED OFF & OF WEB DEPTH


REVISIONS OF DRAWING ARE THE PROPERTY OF CONTRACTOR. THE DRAWING IS NOT TO BE REPRODUCED OR USED FOR ANY PURPOSE WITH THE EXCEPTION OF THE PLANT OPERATOR

NO.	DATE	BY	REVISION
1			
2			


NO.	DATE	BY	REVISION
1			
2			

NO.	DATE	BY	REVISION
1			
2			

DESIGNED BY	DATE
TRACED BY	DATE
CHECKED BY	DATE
APPROVED BY	DATE



DETAIL "A"  
CONN TYP @ BOTH ENDS OF D31 13



NOTE:  
1. WORK THIS SHIT W/ SHIT 4 THRU 7  
2. TAG ALL MAT'L W/ ITEM N° 132

3

A3  
RA3  
EACH ARM IS A TRUE VIEW,  
ARE TILTED SLIGHTLY TO A  
WEB ON THE LEFT END THAT  
BROKE OFF @ OF WED. DEPTH

NO. PCS.	MARK	MATERIAL	LENGTH	
			FT.	IN.
A	A3	TRUNNION ARM SECTIONS		
B	RA3	TRUNNION ARM SECTIONS		
B	B334	TRUNNION HUB		
B	B332	TRUNNION HUB		
16	B3	STRUTS (N°2)	1/8	
16	C3	STRUTS (N°2)	3/8	
B	B374	BRACE	3/8	
B	B372	BRACE	3/8	
B	B372	BRACE	3/8	
B	B372	BRACE	3/8	
G	G	3/4" N BOLTS	0.5	DN-12
SHOP WELD				
		3/8" FILLET	32	0 LIN FT.
		1/4" FILLET	150	0
		3/16" S.M. BR	67	0
		1/8" S.D. REV	17	0
		1/8" S.D. REV	17	0
		1/8" S.D. REV	17	0
		1/8" S.D. REV	17	0

NO ITEM NUMBER 132  
CONTRACT NUMBER DACH-68-70-C-0238

APPROVAL STAMP  
**APPROVED**  
Subj to authority with plans and specifications  
verification of work as executed, and its compliance with  
the material and approved drawings and specifications  
and its suitability for service and safety.  
LOWER SHAKA RIVER  
RESIDENT OFFICE  
Date 25 SEP 1970

LSR70-0088-132-008


STANDARDS	DATE 12-22-70
DESIGNED BY	DATE 12-22-70
CHECKED BY C.M.	DATE 12-22-70
APPROVED BY	DATE

FLINT STEEL CORPORATION  
BOX 1280, TULSA, OKLAHOMA 74101  
ENGINEERING DEPARTMENT

TRUNNION ARM SECTIONS  
LOWER GRANITE LOCK & DAM  
LOWER GRANITE CENTER  
PULLMAN, WASH

JOB NO. 70-0566  
PAGE NO. 3

70-C-88-354



SCALE: AS SHOWN  
 1" = 1'-0"  
 ALL DIMENSIONS IN FEET AND INCHES  
 UNLESS OTHERWISE SPECIFIED

WELDING SYMBOLS  
 AS PER AWS A5.1  
 UNLESS OTHERWISE SPECIFIED



A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	



SCALE: AS SHOWN  
 1" = 1'-0"  
 ALL DIMENSIONS IN FEET AND INCHES  
 UNLESS OTHERWISE SPECIFIED

THIS DRAWING AND ANY INFORMATION CONTAINED HEREIN IS THE PROPERTY OF THE UNITED STATES GOVERNMENT AND IS LOANED TO YOU BY THE NATIONAL ARCHIVES. IT IS TO BE REPRODUCED AND TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM, WITHOUT PERMISSION IN WRITING FROM THE NATIONAL ARCHIVES.


(1)



3-12 GREASE HOLES -  
DRILL AFTER BUSHING IS  
INSTALLED, REAM 1/2  
TAP 1/2 L.F.S. FOR FITTING


NOTE:  
MACHINING TO BE COMPLETE  
AFTER WELDMENT HAS BEEN  
STRESS RELIEVED

SECTION A-A  
MACHINING DETAIL




DRILL & REAM FOR  
1-DOWEL-174 x 0.3-V4  
(16 RPD'S PER HUB)  
SEE DET. Y.  
1-BRONZE BUSHING-MB (MS)  
1-BRONZE BUSHING-PB (FS)  
SEE DETAILS-SHT G

SECTION B-B



DETAIL Y



SECTION C-C

NOTE-  
1- WORK T.  
2- THIS S  
3- TAG A

B - TRUNNION WELDMENTS - THUS - 0.30  
B - TRUNNION WELDMENTS - REV - 0.30



2

STANDARD AND IDENTIFICATION OF CHANGES AND THE PROJECT  
AND THE PROJECT AND IDENTIFICATION OF CHANGES AND THE PROJECT  
AND THE PROJECT AND IDENTIFICATION OF CHANGES AND THE PROJECT

NO.	DESCRIPTION	DATE
1	AS SHOWN	
2	AS SHOWN	
3	AS SHOWN	


NO.	DESCRIPTION	DATE
1	AS SHOWN	
2	AS SHOWN	
3	AS SHOWN	

APPROVED BY: [Signature]  
DATE: [Date]




NOTE:  
MACHINING TO BE COMPLETED  
AFTER WELDMENT HAS BEEN  
STRESS RELIEVED

SECTION A-A  
MACHINING DETAIL




DRILL & REAM FOR  
1-DOWEL-1/4" x 0.8-V4  
(16 REQ'D PER HUB)  
SEE DET. 'I'

1-BRONZE BUSHING-M8 (NS)  
1-BRONZE BUSHING-P8 (FS)  
SEE DETAILS - SHT G



NOTE-  
1- WORK THIS SHT W/ SHT 3, 5 & 6  
2- THIS SHT DETAIL MAT'L ONLY - DO NOT SHIP -  
3- TAG ALL MAT'L WITH ITEM NO. 132



NO. PCS.	MARK	MATERIAL	LENGTH		
			FT.	IN.	
8	Q3	TRUNNION			
8	Q3	TRUNNION			
16	Q4	3/8 DIA	2	7 1/2	FADING
8	A4	PL 802 x 3/4	6	1 1/2	BEND 1/8
8	A4	PL 772 x 3/4	7	1 1/2	BEND 3/4
8	A4	PL 113 x 1	6	7 1/2	1/8
16	F4	PL 113 x 1/2	6	6 3/4	1/8
8	H4	PL 113 x 1/2	6	6 3/4	1/8
8	H4	PL 113 x 1	2	6 3/4	1/8
8	H4	PL 124 x 1	2	2 1/2	1/8
16	M4	BRONZE BUSHING	1	3 1/2	
16	O4	BRONZE BUSHING	1	3 1/2	
CAST ALUMINUM BRONZE					
PRO SPACES 90-D-071A CLASS 3000					
OR 90-D-071A CLASS 9-C-N3					
25	S4	PL 802 x 1/2	1	3 1/2	1/8
16	L4	PL 7 x 3/4	0	7 1/2	3/4
1	D	256 V4 DOWEL 1/2 x 8	0	8	3/4

SHOPWELD		
4	PHLET	30 0 LIN FT.
1	45° SIM BEV	840 0
1	45° SIM BEV	224 0
1	45° SIM BEV	84 0
1	45° DEL BEV	716 0
1	45° DEL BEV	160 0

775 LINE FT OF 3/8 BACKUP BAR  
MAT'L ATTR 570 GRADE B  
TOTAL FOR IS TRUNNION

MAT'L 136 UNK.

ITEM NUMBER 132  
CONTRACT NUMBER DACH-68-70-C-0088

APPROVAL STAMP

**APPROVED**

LOWER SNAKE RIVER  
RESIDENT OFFICE

3

LSR70-0088-132-009

NO.	REV.	DATE	BY	CHKD.	APP'D.
1	1				

FLINT STEEL CORPORATION	DESIGNED BY	DATE
	CHECKED BY	DATE
	APPROVED BY	DATE

LOWER SNAKE RIVER RESIDENT OFFICE	DATE




70-C-88-355



PROJECT NO. \_\_\_\_\_  
 SHEET NO. \_\_\_\_\_  
 DATE \_\_\_\_\_  
 DRAWN BY \_\_\_\_\_  
 CHECKED BY \_\_\_\_\_  
 APPROVED BY \_\_\_\_\_  
 TITLE \_\_\_\_\_  
 SCALE \_\_\_\_\_  
 UNIT \_\_\_\_\_



A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	V	X	Y	Z	

THIS DRAWING IS THE PROPERTY OF THE COMPANY AND IS NOT TO BE REPRODUCED OR COPIED IN ANY MANNER WITHOUT THE WRITTEN PERMISSION OF THE COMPANY.





①

THIS DRAWING IS THE PROPERTY OF THE COMPANY AND IS NOT TO BE REPRODUCED OR COPIED IN ANY MANNER WITHOUT THE WRITTEN PERMISSION OF THE COMPANY.



B-R-79 3/4 x 3/4 x 7'-11 1/2\"/> TH  
 B-R-79 3/4 x 3/4 x 7'-11 1/2\"/> RE



B-R-80 3/4 x 3/4 x 8'-1 1/2\"/> THUS:  
 B-R-80 3/4 x 3/4 x 8'-1 1/2\"/> REV


2

NOTES AND INFORMATION OF CONTRACTOR AND THE PROPERTY  
 OWNER. THIS DRAWING IS THE PROPERTY OF THE PROPERTY  
 OWNER. IT IS TO BE USED ONLY FOR THE PROJECT AND NOT TO BE  
 REPRODUCED OR COPIED IN ANY MANNER WITHOUT THE WRITTEN  
 PERMISSION OF THE PROPERTY OWNER.

SCALE: 1/8\"/> = 1'-0\"/>  
 UNLESS NOTED OTHERWISE  
 PARTS: UNLESS NOTED OTHERWISE  
 FINISH: UNLESS NOTED OTHERWISE


NOTES:  
 1. REVISED WELD SYMBOLS  
 2. UNLESS NOTED OTHERWISE  
 3. UNLESS NOTED OTHERWISE  
 4. UNLESS NOTED OTHERWISE

NO.	REVISION	DATE	BY	CHECKED
1	REVISED WELD SYMBOLS			
2	UNLESS NOTED OTHERWISE			
3	UNLESS NOTED OTHERWISE			
4	UNLESS NOTED OTHERWISE			



~ END VIEW ~  
TYP FOR R'S 60" & 64"

8-R-79 1/2 x 3/4 x 7'-11 3/8" - THUS - 64"  
8-R-79 1/2 x 3/4 x 7'-11 3/8" - REV. - 64"



8-R-80 1/2 x 3/4 x 8'-11 3/8" - THUS - 64"  
8-R-80 1/2 x 3/4 x 8'-11 3/8" - REV - 64"

3

NO ITEM NUMBER 132  
CONTRACT NUMBER DAWG 68-70-C-0088

APPROVAL STAMPS

<b>APPROVED</b>	
Checked in conformity with plans and specifications. I warrant the accuracy and correctness of the stated facts appearing hereon and I warrant the same are a true and correct copy of the original.	
LOWER SHAKA RIVER REPERT OFFICE	
21 SEP 1970	

LSR70-0088-132-010  
WORK THIS DWG W/ DWG NO 3, 4 & 5

SYMBOLS	REVISIONS	DATE	DESCRIPTION

COMPANY OF \_\_\_\_\_ DATE 12-3-70  
 DRAWN BY \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE 12-3-70  
 DESIGNED BY \_\_\_\_\_ APPROVED BY \_\_\_\_\_ DATE 12-3-70

**FLINT STEEL CORPORATION**  
 BOX 1290 TULSA, OKLAHOMA 74101  
 ENGINEERING DEPARTMENT

70-0578  
70-C-88-356


REVISIONS  
 NO. DATE BY  
 1 11/15/54 J.S.

CHECKED BY  
 J.S.  
 DATE 11/15/54


A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z

REVISIONS  
 NO. DATE BY  
 1 11/15/54 J.S.


CHECKED BY  
 J.S.  
 DATE 11/15/54




B-PL-11 1/2 x 1 1/2 x 1 1/2 - THIS - 3/4" R  
 B-PL-11 1/2 x 1 1/2 x 1 1/2 - REV - 0 1/4" R



16-PL-11 1/2 x 1 1/2 x 1 1/2 - C-3/8" R




B-PL-11 1/2 x 1 1/2 x 1 1/2 - THIS - 3/4" R  
 B-PL-11 1/2 x 1 1/2 x 1 1/2 - C-3/8" R






B-PL-12 1/2 x 1 x 2 1/2 - THIS - 1/4" R  
 B-PL-12 1/2 x 1 x 2 1/2 - REV - 1/4" R

①

THIS DRAWING AND INFORMATION BY CUTTING ARE THE PROPERTY OF THE PLANT OPERATOR. THE DRAWING IS NOT TO BE REPRODUCED, COPIED OR USED FOR ANY PURPOSES WITHOUT THE EXPRESS PERMISSION OF THE PLANT OPERATOR.







HOLE: \_\_\_\_\_  
 FASTENER: \_\_\_\_\_  
 FINISH: \_\_\_\_\_




16-TRUNNION BUSHINGS - m4  
 16-TRUNNION BUSHINGS - p4

CAST ALUMINUM BRONZE  
 FED. SPECS OO-B-6718 CLASS 3 H.T.  
 OR ASTM B146 CLASS 7-C H.T.





2

HOLE: _____ UNLESS NOTED PARTS: _____ UNLESS NOTED FROM: <u>None</u>	NOTES: _____	DRAWN BY: <u>EC</u> DATE: <u>12-22-70</u> CHECKED BY: <u>C.M.</u> DATE: <u>12-22-70</u> APPROVED BY: _____ DATE: _____
--	--------------	--




GREASE GROOVE (FOR M4) DETAIL A

B. GREASE GROOVES (DETAIL A) @ 20° = 100°



SECTION A-A

ON DUSHINGS - M4  
ON DUSHINGS - P4  
ALUMINUM BRONZE  
OO-B. GT10 CLASS 3 H.T.  
100 CLASS 9-C H.T.



(3)

DWG ITEM NUMBER 132  
CONTRACT NUMBER DACW-68-70-C-0008

APPROVAL STAMPS

<b>APPROVED</b>	
<small>SALES TO UNLESS OTHERWISE SPECIFIED, THE FOLLOWING CONDITIONS APPLY: 1. APPROVED FOR THE PURPOSE OF THE PROJECT ONLY. 2. APPROVED FOR THE PURPOSE OF THE PROJECT ONLY. 3. APPROVED FOR THE PURPOSE OF THE PROJECT ONLY.</small>	
LOWER SHAKA RIVER RESIDENT OFFICE	
23 SEP 1978	

LSR70-0088-132-011  
WORK THIS DWG W/DWG NO 3-445

DRAWN BY	DATE	12-6-78
CHECKED BY	DATE	12-22-78
APPROVED BY	DATE	

FLINT STEEL CORPORATION  
BOX 1200, TULSA, OKLAHOMA 74101  
ENGINEERING DEPARTMENT

TERMINATION DETAILS  
LOWER GRANITE LOCK & DAM  
LOWER GRANITE CENTER  
PULLMAN, WASH.

DWG NO.	70-0500
SHEET NO.	6


70-C-88-357

1

THIS DRAWING IS TO BE USED FOR THE CONSTRUCTION OF THE STRUCTURE SHOWN HEREON. IT IS THE RESPONSIBILITY OF THE CONTRACTOR TO OBTAIN ALL NECESSARY PERMITS AND TO VERIFY THE ACCURACY OF ALL DIMENSIONS AND CONDITIONS OF THE SITE. THE CONTRACTOR SHALL BE RESPONSIBLE FOR THE PROTECTION OF ALL UTILITIES AND ADJACENT STRUCTURES. THE CONTRACTOR SHALL MAINTAIN ACCESS TO ALL ADJACENT PROPERTIES AT ALL TIMES. THE CONTRACTOR SHALL BE RESPONSIBLE FOR THE PROTECTION OF ALL ADJACENT PROPERTIES. THE CONTRACTOR SHALL MAINTAIN ACCESS TO ALL ADJACENT PROPERTIES AT ALL TIMES.

PROJECT NO. 100-100-100  
 SHEET NO. 100-100-100  
 DATE 10/10/10

A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z




- B - 18W20 x 5'-7 1/2 - THRU 4 NOTED - CB
- B - 18W30 x 5'-7 1/2 - REV 4 NOTED - CB
- B - 18W30 x 7'-1 1/2 - THRU 4 NOTED - FB
- B - 18W30 x 7'-1 1/2 - REV 4 NOTED - FB


FOR USE IN CONNECTION WITH THE DRAWING AND INFORMATION IT CONTAINS AND THE PROPERTY OF THE DRAWING ENGINEER. THE DRAWING IS NOT TO BE REPRODUCED, COPIED, OR USED FOR ANY PURPOSES WITHOUT THE WRITTEN PERMISSION OF THE DRAWING ENGINEER.

WELD ALL AROUND

DATE: 10/10/10  
 DRAWN BY: [Signature]  
 CHECKED BY: [Signature]




WORK POINT DIMS FOR  
STRUT BRACING




1G-STRUTS - 14 WF 398 x 46'-8 3/4 - b3

- 1 - 14 WF 30 x 5'-7 3/4 - THIS IS NOTED - c13 1/2
- 2 - 14 WF 30 x 5'-7 3/4 - REV. IS NOTED - c13 1/2
- 3 - 14 WF 30 x 7'-1 3/4 - THIS IS NOTED - F3 1/2
- 4 - 14 WF 30 x 7'-1 3/4 - REV. IS NOTED - F3 1/2

WORK POINT DIMS FOR  
STRUT BRACING



1G-STRUTS - 14 WF 342 x 26'-0 - c3




1- WCA  
2- THIS  
3- TAG

2

THIS SHEET IS PART OF A SET OF DRAWINGS FOR THE PROJECT OF THE ABOVE DESCRIBED WORK. THE DRAWING IS NOT TO BE REPRODUCED OR COPIED IN ANY MANNER WITHOUT THE WRITTEN PERMISSION OF THE PROJECT MANAGER.		MOLES: <u>12 1/2</u> UNLESS NOTED PARTS: <u>NONE</u> PANEL: <u>NONE</u>	NOTES:	<table border="1"> <tr><td>A</td><td></td><td></td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td><td></td><td></td></tr> <tr><td>D</td><td></td><td></td><td></td><td></td></tr> <tr><td>E</td><td></td><td></td><td></td><td></td></tr> <tr><td>F</td><td></td><td></td><td></td><td></td></tr> </table>	A					B					C					D					E					F					DRAWN BY: <u>PC</u> DATE: <u>12-1-70</u> TRACED BY: _____ DATE: _____ CHECKED BY: <u>C.M.</u> DATE: <u>12-22-70</u> APPROVED BY: _____ DATE: _____
A																																			
B																																			
C																																			
D																																			
E																																			
F																																			





1G-STRUTS - 14 WF 398 x 46'-8 1/2\"/>

1G-STRUTS - 14 WF 342 x 26'-0\"/>

**NOTE:**  
 1- WORK THIS SHG W/ SHG NR 3  
 2- THIS SHG DETAIL MAT'L - DO NOT SHIP  
 3- TAG ALL MAT'L W/ ITEM NO 132

NO. PCS.	MARK	MATERIAL	LENGTH		REMARKS	WEIGHT	
			FT.	IN.			
28	117	14 WF 30	5	7 1/2		1/8	
28	117	14 WF 30	7	1 1/2		1/8	
16	63	14 WF 398	46	8 1/2		1/8	
16	63	14 WF 342	26	0		1/8	
16	67	BAR A7	2	9			
SHOP WELD							
4 FILLET 12 0 L.I.N.E.							

END ITEM NUMBER 132  
 CONTRACT NUMBER D4CU-68-70-C-0088

APPROVAL STAMP

APPROVED

Subject to conformity with plans and specifications, I certify that I have examined and approved the work shown hereon, and that the same complies with the contract documents and the drawings and specifications thereon, and that the materials and workmanship are in accordance with the contract documents and the drawings and specifications thereon.

LOWER SNAKE RIVER  
RESIDENT OFFICE

Date: 25 SEP 1978

3

LSR 70-0088-132-012

DRAWN BY: <u>EC</u>	DATE: <u>12-7-70</u>	
TRACED BY: _____	DATE: _____	
CHECKED BY: <u>CM</u>	DATE: <u>12-12-70</u>	
APPROVED BY: _____	DATE: _____	

FLINT STEEL CORPORATION

BOX 1586, TULSA, OKLAHOMA 74104  
 ENGINEERING DEPARTMENT

STRUT & BRACE DETAILS

LOWER GRANITE JACK & DAM  
 LOWER GRANITE CENTER  
 PULLMAN, WASH.

JOB NO. 70-0560  
 SHEET NO. 7

70-C-88-358



MATCH MARK W/C3 (SHT#7)  
FOR CUTTING

WORK POINT DIMS FOR  
STRUT BRACING

20'-7 1/2" (14W 348 x 20'-8 3/4")

8'-9 3/8"

11'-7 1/8"



SECTION A1-A1

16- STRUTS- AB



W	V	U	T	S	R	Q	P	O	N	M	L	K	J	I	H	G	F	E	D	C	B	A
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23




WORK POINT DIMS. FOR  
STRUT BRACING

47'-4 1/2" (C)

11'-8 3/8"

11'-9 1/8"




16- 5

FOR WELD - WELD LENGTH  
SIZE - PITCH  
WELD ALL AROUND



THIS DRAWING AND INFORMATION IT CONTAINS ARE THE PROPERTY  
OF THE PLANT STEEL CORPORATION. THE DRAWING IS NOT TO BE  
REPRODUCED, COPIED, REPRODUCED OR USED FOR ANY PURPOSES  
WITHOUT THE EXPRESS PERMISSION OF THE PLANT STEEL CORPORATION.

NO  
FAC  
FOR


(1)



16-STRUTS-AB




16-BRACES-CB



16-STRUTS-BB

2

THIS DRAWING AND INFORMATION IT CONTAINS ARE THE PROPERTY OF THE PLANT STEEL CORPORATION. THE DRAWING IS NOT TO BE REPRODUCED, COPIED, FORWARDED OR USED FOR ANY PURPOSES WITHOUT THE EXPRESS PERMISSION OF THE PLANT STEEL CORPORATION.	HOLER: <u>12-78</u> UNLESS NOTED	NOTES:	1	DESIGNED BY: <u>PC</u>
	PARTISHERS: UNLESS NOTED		2	TRACED BY:
	FINISH: <u>NONE</u>		3	CHECKED BY: <u>LD</u>
			4	APPROVED BY:
			REVISION DESCRIPTION	MADE BY: DATE:



16-BRACES-CB

NOTE  
TAG ALL MAT'L W/  
ITEM NO. 132

3

NO. PCS.	MARK	MATERIAL	LENGTH		REMARKS	WEIGHT
			FT.	IN.		
16	AB	14WF342	20	8 3/4		
16	BA	14WF202	47	5 3/4		
16	CA	14WF30	17	7 3/4		
16	DA	PL-5 x 3	0	7		19 1/2
16	DB	PL-5 x 3	0	7		19 1/2
60		3/8 M.B.	0	11 1/2	PIN-UP	

NO ITEM NUMBER 132  
CONTRACT NUMBER DACW 68-76-C-0068

APPROVAL STAMP

**APPROVED**

Subject to conditions with item and work  
completion of work or units, etc., and to full  
any required tests. Approval does not constitute  
warranty, or responsibility for construction and for

LOWER SNAKE RIVER  
RESIDENT OFFICE

Date: 25 SEP 1973

CUSTOMER'S P.O. NO.  
CUSTOMER'S DRAW. NO.

LSR 70-0088-132-013


DRAWN BY <u>PC</u> DATE <u>12-2-70</u> CHECKED BY <u>C.M.</u> DATE <u>12-22-70</u> APPROVED BY _____ DATE _____	<b>FLINT STEEL CORPORATION</b> BOX 1280, TULSA, OKLAHOMA 74101 ENGINEERING DEPARTMENT	<b>STRUTS &amp; BRACES</b> LOWER GRANITE CORE TEAM LOWER GRANITE CORE DULLMAN WASH.	JOB NO. <u>70-0540</u> SHEET NO. <u>8</u>
---	---	--	--

70-C-88-359


PROJECT NO. \_\_\_\_\_  
 DRAWING NO. \_\_\_\_\_  
 DATE \_\_\_\_\_  
 SCALE \_\_\_\_\_  
 SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_  
 TITLE \_\_\_\_\_  
 DRAWN BY \_\_\_\_\_  
 CHECKED BY \_\_\_\_\_  
 APPROVED BY \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z

SECTION A-A  
 SECTION E-E  
 SECTION F-F  
 SECTION G-G  
 SECTION H-H  
 SECTION I-I  
 SECTION J-J  
 SECTION K-K  
 SECTION L-L  
 SECTION M-M  
 SECTION N-N  
 SECTION O-O  
 SECTION P-P  
 SECTION Q-Q  
 SECTION R-R  
 SECTION S-S  
 SECTION T-T  
 SECTION U-U  
 SECTION V-V  
 SECTION W-W  
 SECTION X-X  
 SECTION Y-Y  
 SECTION Z-Z




- 8 - BRACES - THUS & NOTED - A9
- 8 - BRACES - REV & NOTED - RA9
- 8 - BRACES - THUS & NOTED - B9
- 8 - BRACES - REV & NOTED - RB9



- 8 - DIAGONAL BRACES - THUS - H9
- 8 - DIAGONAL BRACES - REV - RH9


(1)

WELD LENGTH  
 THIS DRAWING AND INFORMATION IT CONTAINS ARE THE PROPERTY OF THE PLANT OPER. CORPORATION. THE DRAWING IS NOT TO BE REPRODUCED, COPIED, REPRODUCED OR USED FOR ANY PURPOSES WITHOUT THE EXPRESS PERMISSION OF THE PLANT OPER. CORPORATION.




VIEW A-A

- B - BRACES - THUS & NOTED - A9
- B - BRACES - REV & NOTED - RA9
- B - BRACES - THUS & NOTED - B9
- B - BRACES - REV & NOTED - RB9




VIEW D-D

- B - BRACES - THUS & NOTED - C9
- B - BRACES - REV & NOTED - RC9
- B - BRACES - THUS & NOTED - D9
- B - BRACES - REV & NOTED - RD9
- B - BRACES - THUS & NOTED - E9
- B - BRACES - REV & NOTED - RE9



VIEW E-E

- B - DIAGONAL BRACES - THUS - H9
- B - DIAGONAL BRACES - REV - RH9




VIEW D-D

- B - DIAGONAL BRACES - THUS - K9
- B - DIAGONAL BRACES - REV - RK9



2

NO.	REVISION	DATE	BY	CHKD.
1				
2				
3				
4				
5				

NOTES:  
 UNLESS NOTED OTHERWISE, ALL DIMENSIONS ARE IN FEET AND INCHES.  
 UNLESS NOTED OTHERWISE, ALL CONNECTIONS ARE TO BE MADE BY BOLTING.  
 UNLESS NOTED OTHERWISE, ALL BRACES ARE TO BE MADE OF A36 STEEL.  
 UNLESS NOTED OTHERWISE, ALL BRACES ARE TO BE MADE OF A36 STEEL.  
 UNLESS NOTED OTHERWISE, ALL BRACES ARE TO BE MADE OF A36 STEEL.



NO. PCS.	MARK	MATERIAL	LENGTH FT. IN.	REMARKS	WEIGHT
8	A9	14 W 30	12 7 3/4		1 1/2
8	RA9	14 W 30	12 7 3/4		1 1/2
8	B9	14 W 30	16 1 3/8		1 3/8
8	RB9	14 W 30	16 1 3/8		1 3/8
60	A9	3/4 M.A.	0 7		3/8
120		3/4 M.A.	0 1 1/2	FIN-UP	
8	C9	14 W 30	6 9		1 1/2
8	RC9	14 W 30	6 9		1 1/2
8	D9	14 W 30	10 10 5/8		1 5/8
8	RD9	14 W 30	10 10 5/8		1 5/8
8	E9	14 W 30	15 0 3/4		1 3/4
8	RE9	14 W 30	15 0 3/4		1 3/4
48	B9	1/2 M.A.	0 7		3/8
48	RB9	1/2 M.A.	0 7		3/8
192		3/4 M.A.	0 1 1/2	FIN-UP	
8	F9	14 W 30	19 1 1/2		1 1/2
8	RF9	14 W 30	19 1 1/2		1 1/2
16	B9	1/2 M.A.	0 7		3/8
16	RB9	1/2 M.A.	0 7		3/8
60		3/4 M.A.	0 1 1/2	FIN-UP	
8	H9	14 W 30	11 9 3/8		1 3/8
8	RH9	14 W 30	11 9 3/8		1 3/8
16	B9	1/2 M.A.	0 7		3/8
16	RB9	1/2 M.A.	0 7		3/8
60		3/4 M.A.	0 1 1/2	FIN-UP	
8	K9	14 W 30	14 5 1/4		1 1/4
8	RK9	14 W 30	14 5 1/4		1 1/4
32	m9	1/2 M.A.	0 3/2		3/8
60		3/4 M.A.	0 1 1/2	FIN-UP	



NOTE  
TAG ALL MAT'L WITH  
ITEM N# 132

ALL MAT'L A36

3

LSR 70-0088-132-014

NO ITEM NUMBER 132  
CONTRACT NUMBER DACH 68-74-C-0008

APPROVAL STAMP

**APPROVED**

Subject to compliance with the use and control of the material of work as specified, and the use of the material of work as specified, and the use of the material of work as specified, and the use of the material of work as specified.

LOWER SNAKE RIVER  
RESIDENT OFFICE

70-0584


83 SEP 1973

FLINT STEEL CORPORATION  
BOX 1248, TULSA, OKLAHOMA 74101  
ENGINEERING DEPARTMENT


TECHNICAL ARM BRACING  
LOWER SNAKE RIVER  
1. SNAKE RIVER  
TULSA, OKLA.

70-0584

70-C-88-360



B-DIAGONAL BRACES - THUS - A  
 B-DIAGONAL BRACES - REV - RA



B-DIAGONAL BRACES - THUS - B  
 B-DIAGONAL BRACES - REV - RB

PROPERTY OF  
 ENGINEER  
 DRAWN BY  
 CHECKED BY  
 DATE  
 SCALE  
 SHEET NO. OF TOTAL SHEETS

A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	V	W	X	Y	Z








SECTION LINE  
 SECTION A-A  
 SECTION B-B

WELD ALL AROUND

①


<p>WELD LENGTH</p> <p>PITCH</p> <p>WELD ALL AROUND</p>	<p>THIS DRAWING AND INFORMATION IT, CONTAINS AND THE PROPERTY OF THE FIRM OR CORPORATION. THE DRAWING IS NOT TO BE REPRODUCED, COPIED, OR TRANSMITTED IN ANY FORM OR BY ANY MEANS WITHOUT THE EXPRESS PERMISSION OF THE FIRM OR CORPORATION.</p>	<p>NO. 13</p> <p>PARTIAL</p> <p>FINAL</p>
--	--	---






2

AND INFORMATION BY, LISTING AND THE PROPERTY OF THE COMPANY. THE COMPANY IS NOT TO BE RESPONSIBLE OR LIABLE FOR ANY DAMAGE OR LOSS OF PROPERTY OF THE USER, OPERATOR		HOLE: 1 1/2" $\phi$ UNLESS NOTED PARTS: UNLESS NOTED FINISH: NONE	NOTES:	DRAWN BY: PL DATE: 12-6-70 CHECKED BY: DATE: APPROVED BY: DATE:
SHOW WELD SYMBOL & PROCEDURE		DRINK DOWN (1/2) (1/2)		




24 - BRACES - C10  
24 - BRACES - D10



B - BRACES - THUS & NOTED - E10  
B - BRACES - REV & NOTED - RE10  
B - BRACES - THUS & NOTED - F10  
B - BRACES - REV & NOTED - RF10

10' E10  
9' F10

SECTION E-E



B - BRACES - THUS & NOTED - H10  
B - BRACES - REV & NOTED - RH10  
B - BRACES - THUS & NOTED - K10  
B - BRACES - REV & NOTED - RK10

SECTION H-H

NOTE  
TAG ALL MATERIAL  
WITH ITEM # 132

NO. PCL	MARK	MATERIAL	LENGTH		REMARKS	WEIGHT
			FT.	IN.		
B	A10	14WF30	17	6 1/2		720
B	R10	14WF30	17	6 1/2		720
16	C10	PL 5/8 X 3/4	0	7		37
16	D10	PL 5/8 X 3/4	0	5		47
64		3/4 X 1/2	0	1/2		
B	B10	14WF30	20	10 1/2		720
B	R10	14WF30	20	10 1/2		720
16	C10	PL 5/8 X 3/4	0	7		37
16	D10	PL 5/8 X 3/4	0	7		37
64		3/4 X 1/2	0	1/2		
24	C10	ST 7WF15	16	6	BEND 1/4	
24	D10	ST 7WF15	19	6	BEND 3/4	
B	F10	ST 7WF15	20	10	BEND 1/4	
B	R10	ST 7WF15	20	10		
B	F10	ST 7WF15	23	3/4		76
B	R10	ST 7WF15	23	3/4		77
B	H10	ST 7WF15	17	0 1/2	BEND 1/4	
B	R10	ST 7WF15	17	0 1/2		
B	K10	ST 7WF15	19	11 1/2		76
B	R10	ST 7WF15	19	11 1/2		77
1/2 BUT WELD 65 0						

NO ITEM NUMBER 132  
CONTRACT NUMBER DACH-68-70-C-0088

APPROVAL STAMPS

**APPROVED**

LOWER SNAKE RIVER  
RESIDENT OFFICE

DATE 25 SEP 1973

3

LSR70-0088-132-015


DESIGNED BY	DATE	12-8-70
TRACED BY	DATE	
CHECKED BY	DATE	12-22-70
APPROVED BY	DATE	

FLINT STEEL CORPORATION  
BOX 1286, TULSA, OKLAHOMA 74101  
ENGINEERING DEPARTMENT

TRUNNION ARM BRACING  
LOWER GRANITE LOCK & DAM  
LOWER GRANITE CONTR  
PULLMAN, WASH


JOB NO. 70-0544  
SHEET NO. 10

70-C-88-361




16 SPACS C

A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---



SECTION A-A  
(TIP OF PL'S 311)



SECTION  
(TYP FOR HII)








DETAIL

①

UNLESS SHOWN OTHERWISE THIS DRAWING IS TO BE CONSIDERED AS A WORKING DRAWING AND IS NOT TO BE USED FOR ANY PURPOSE WITHOUT THE APPROVAL OF THE DRAWING ENGINEER


THIS DRAWING IS THE PROPERTY OF THE AIR FORCE AND IS TO BE KEPT SECRET. IT IS TO BE RETURNED TO THE AIR FORCE AT THE END OF THE PROJECT AND IS NOT TO BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM. THIS DRAWING IS TO BE KEPT SECRET AND IS NOT TO BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM.




2

NO.	REVISION	DATE	BY	CHKD.
1	REVISED WELD SYMBOLS	11-15-77	...	...
2	REV. FOR APPROX. SPACING DATA	3-15-77	...	...





A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	V	W	X	Y	Z




SECTION A-A  
(TYP. @ R/S d/2)



SECTION B-B

WELDED JOINTS  
 THIS DRAWING AND SPECIFICATIONS OF MATERIALS ARE THE PROPERTY OF THE FINE ARTS CORPORATION. THE DRAWING IS NOT TO BE REPRODUCED, COPIED, OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM, WITHOUT THE WRITTEN PERMISSION OF THE FINE ARTS CORPORATION.

①




**8-GIRDERS - AIR**  
(GIRDER NO 8)



2

THIS DRAWING AND SPECIFICATIONS IF CHANGED ARE THE PROPERTY OF THE ENGINEERING CORPORATION. THIS DRAWING IS NOT TO BE REPRODUCED, COPIED, REPRINTED OR USED FOR ANY PURPOSES WITHOUT THE EXPRESS PERMISSION OF THE ENGINEERING CORPORATION.	DESIGNER: <i>[Signature]</i> DRAWN BY: <i>[Signature]</i> CHECKED BY: <i>[Signature]</i> IN CHARGE: <i>[Signature]</i>	NOTES: (1) REVISED WELD SYMBOL (2) REV. FOR APPROVAL, SANTA PETER 3-15-71	DRAWN BY: <i>[Signature]</i> CHECKED BY: <i>[Signature]</i> APPROVED BY: <i>[Signature]</i>	
	TITLE: <i>[Blank]</i> PROJECT: <i>[Blank]</i> DATE: <i>[Blank]</i>	SCALE: <i>[Blank]</i> SHEET NO.: <i>[Blank]</i> TOTAL SHEETS: <i>[Blank]</i>	DATE: <i>[Blank]</i> TIME: <i>[Blank]</i>	LOCATION: <i>[Blank]</i> CLIENT: <i>[Blank]</i>
	REVISIONS:	COMMENTS:	APPROVALS:	SIGNATURES:



NO. PCS.	MARK	MATERIAL	LENGTH		REMARKS	WEIGHT
			FT.	L. IN.		
<b>RAIL GIRDERS</b>						
8	012	PL-58 x 3 1/2	49	4 1/2	LOW ALLOY	41
8	012	PL-16 1/2 x 1 1/4	49	4 1/2	A537-670	46
8	012	PL-16 1/2 x 1 1/4	42	4 1/2	A537-670	42
64	012	PL-7 1/2 x 1 1/4	4	10	LOW ALLOY	175
56	111	PL-5 x 3 1/2	4	10		47
16	112	PL-5 x 3 1/2	0	11 1/2		137
16	112	PL-5 x 3 1/2	0	11 1/2		166
472	0011	BAR-2 x 4	0	8 1/2		199
304	0111	BAR-3 x 2	0	3		169
<b>SHIPWELD</b>						
5/8		FILLET	560	0	LINE IT	
3/8		FILLET	32	0		
1/2		FILLET	1344	0		
1/2		DBL BEV	76	0		
10		DBL BEV	342	0		
<b>ALL MAT'L A 36 U.M.</b>						

NOTE:  
TAG ALL MATERIAL  
WITH ITEM N<sup>o</sup> 132

3

NO ITEM NUMBER 132  
CONTRACT NUMBER DRCN 68-70-C-0088

APPROVAL STAMP

**APPROVED**

LOWER SHAKE RIVER  
RESIDENT OFFICE

DATE 25 SEP 1970

LSR 70-0088-132-017

DESIGNED BY EC	DATE 12-10-70
TRACED BY	DATE
CHECKED BY C.M.	DATE 12-22-70
APPROVED BY	DATE


FLINT STEEL CORPORATION  
BOX 1888, TULSA, OKLAHOMA 74101  
ENGINEERING DEPARTMENT

GIRDER N<sup>o</sup> 2  
100% GRANITE LOCAL  
LOWER SHAKE RIVER  
RESIDENT OFFICE  
PULASKI, WASH. C.

JOB NO. 70-0566  
SHEET NO. 12


70-C-88-364






PROJECT NO. \_\_\_\_\_  
 DRAWING NO. \_\_\_\_\_  
 DATE \_\_\_\_\_  
 SCALE \_\_\_\_\_  
 SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_  
 DESIGNER \_\_\_\_\_  
 CHECKER \_\_\_\_\_  
 APPROVER \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26




SECTION A-A  
TIP OF PL'S d13





SECTION B-B

WELDED LENGTH: \_\_\_\_\_  
 THIS DRAWING AND INFORMATION IS CONFIDENTIAL AND THE PROPERTY OF THE PLANT OPERATOR. THE OPERATOR IS NOT TO BE TRACED, COPIED, REPRODUCED OR USED FOR ANY PURPOSES WITHOUT THE WRITTEN PERMISSION OF THE PLANT OPERATOR.  
 INDEX: 13-0  
 PARTS: \_\_\_\_\_  
 NAME: \_\_\_\_\_

①



**8-GIRDERS - A13**  
(GRADE 113)




2

THE CONTRACTOR SHALL BE RESPONSIBLE FOR OBTAINING THE PERMITS AND NECESSARY APPROVALS. THE CONTRACTOR IS NOT TO BE RESPONSIBLE FOR THE DESIGN OF THE STRUCTURE OR THE PERMITS OF THE STATE OR FEDERAL AGENCIES.

NO. 12-0	DATE: 12-10-70
DESIGNED BY: [Signature]	CHECKED BY: [Signature]
DRAWN BY: [Signature]	DATE: 12-22-70

REVISER: WELD SYMBOL	DATE: 3-12-71
BY: [Signature]	DATE: 3-12-71

PROJECT: [Blank]	DATE: 12-10-70
DESIGNED BY: [Signature]	CHECKED BY: [Signature]
DRAWN BY: [Signature]	DATE: 12-22-70



NO.	MARK	MATERIAL	LENGTH		REMARKS	WEIGHT
			FT.	IN.		
<b>A&amp;B GIRDERS</b>						
B	Q13	R-481 7/8	49	2 1/2	Non Alloy	91
B	B13	R-16 1/2	49	4 1/2	SA537-72	82
B	C13	R-16 1/2	42	8 1/2	SA537-72	72
60	D13	R-72 x 3/4	4	0		199
50	F13	R-5 x 3/4	4	0		197
16	G13	R-5 1/2 x 3/4	0	11 1/2		36
16	H13	R-7 1/2 x 3/4	0	11 1/2		46
30	K13	BAR 3/4" x 2"	0	3 1/2		199
22	Q11	BAR 2 x 1/4"	0	8 1/2		199
<b>SHOP WELD</b>						
3/8" FILLET			1940	0		
3/8" FILLET			32	0		
1/2" DEEP BEV			76	0		
3/8" DEEP BEV			283	0		
<b>ALL MAT'L A 36 W.M.</b>						

**NOTE**  
TAG ALL MATERIAL  
WITH ITEM NO 132

ITEM NUMBER 132  
CONTRACT NUMBER DFCW G8-70-0088

APPROVAL STAMP

**APPROVED**

LOWER SHAKE RIVER  
RESIDENT OFFICE

By: *[Signature]*  
Date: 23 SEP 1970

3

LSR 70-0088-132-018


DRAWN BY: <i>[Signature]</i> DATE: 12-10-70 CHECKED BY: <i>[Signature]</i> DATE: 12-22-70 APPROVED BY: <i>[Signature]</i> DATE:	<b>FLINT STEEL CORPORATION</b> BOX 1288, TULSA, OKLAHOMA 74101 ENGINEERING DEPARTMENT	<b>GIRDER No. 3</b> LOWER GRANITE LOCK & DAM LOWER GRANITE CANALS FLEETMAN, WASH.	JOB NO. <b>70-0544</b> SHEET NO. <b>13</b>
---	---	--	---

70-C-89-365



SECTION A-A

1/2" x 1/8"



A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z




B - SIDE SEAL ANGLES - THUS - A1A  
B - SIDE SEAL ANGLES - REV. - RA1A

DATE: _____	SCALE: _____	THIS DRAWING AND REPRESENTATION OF CONTAINS ARE THE PROPERTY OF THE PLANT OPERATOR. THE DRAWING IS NOT TO BE LOANED, COPIED, REPRODUCED OR USED FOR ANY PURPOSES WITHOUT THE WRITTEN PERMISSION OF THE PLANT OPERATOR.	MOLES: <u>174-4</u> <u>174-4</u>
DESIGNED BY: _____	DRAWN BY: _____		
CHECKED BY: _____	APPROVED BY: _____		

(1)




SECTION A-A





SIDE SEAL ANGLES - THUS - A1A  
 SIDE SEAL ANGLES - REV. - RA1A

3 - SIDE SEAL CLAMPING BARS - THUS - B1A  
 3 - SIDE SEAL CLAMPING BARS - REV. - RB1A




2

CHECKED BY: [Signature] DATE: 12-1-70	DRAWN BY: [Signature] DATE: 12-1-70
REVISIONS: 1 REVISED WITH SYMBOLS 2 REV. FOR REVISIONS SET BY DETAIL 3-15-70	TITLE: [Blank]



OFFSET DIAGRAM



SECTION B-B

NOTE  
TAG ALL MAT'L WITH  
ITEM NO 132

3

NO. PCS.	MARK	MATERIAL	LENGTH		REMARKS	WEIGHT
			FT.	IN.		
		B 1A 1 1/2 x 1/2	66	7 3/4	2-0 ADD 1/4\"/>	
		B 1A 1 1/2 x 1/2	66	7 3/4	2-0 ADD 1/4\"/>	
		1C 6 1/4 x 1 1/2	0	2	2-0 ADD 1/4\"/>	
		B 1A 1 1/2 x 1/2				
		B 1A 1 1/2 x 1/2				
		1C 2 1/2 x 1 1/2	0	4 1/2	2-0 ADD 1/4\"/>	
		B 1A 1 1/2 x 1/2	23	7 3/4	(A.S.T.M. A-216, TYPE 410)	
		B 1A 1 1/2 x 1/2	23	8 1/2	CHEMICALS TO CONFORM TO A-176, TYPE 410S	
		B 1A 1 1/2 x 1/2	23	3 1/4		
SWAP WELD						
		1/2\"/>				
		1/2\"/>				

DESIGN NUMBER 132  
CONTRACT NUMBER DCM 68-70-C-0088

APPROVAL STAMP

**APPROVED**

Subject to good workmanship and specifications...  
LOWER SHAKE RIVER  
RESIDENT OFFICE

Date: 24 SEP 1970

LSR 70-0088-132-019


DESIGNED BY	DATE
DRAWN BY	DATE
CHECKED BY	DATE

FLINT STEEL CORPORATION  
BOX 1800, TULSA, OKLAHOMA 74101  
ENGINEERING DEPARTMENT

SIDE BRAL ANGLES & BARS  
LOWER GRANITE LOCK DAM  
LOWER GRANITE CONCRETE  
CHICKEN WASH



70-0540  
14

70-C-88-366



**16-BOTTOM SEAL CLAMPING BARS-A15**  
(CORROSION RESISTANT STEEL)

PROJECT NO.	DATE
DESIGNER	CHECKED
APPROVED	DATE
SCALE	BY
REVISED	BY
REVISIONS	DATE
NO.	DESCRIPTION
1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	



**SECTION A-A**  
HORIZ LINE (REF)

J SEAL-5/8\"/>


**8-RUBBER 'J' SEALS-THUS- B15**  
**8-RUBBER 'J' SEALS-REV-RB15**

DATE	SCALE	BY	CHECKED
PROJECT NO.	DATE	DESIGNER	CHECKED
APPROVED	DATE	SCALE	BY
REVISIONS	BY	DATE	
NO.	DESCRIPTION		
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			
29			
30			
31			
32			
33			
34			
35			
36			
37			
38			
39			
40			
41			
42			
43			
44			
45			
46			
47			
48			
49			
50			

24' 9 1/2"

16 Spcs @ 1'-5 1/2" = 23'-7"



SYM. A&B 8  
92




CLAMPING BARS - A15  
(CORROSION RESISTANT STEEL)

16 - BOTTOM SEAL CLAMPING BARS - E15  
(CORROSION RESISTANT STEEL)

B - BOTTOM SEAL CLAMPING BARS - F15  
(CORROSION RESISTANT STEEL)



B - RUBBER BOTTOM SEALS - C15



16 - GASKETS - D15

NOTE  
TAG ALL  
WITH IT.





2

SEALS - THUS - A15

SEALS - REV - RB15

HOLDER: <u>462</u> PAINTWORK: <u>None</u> FINISH: <u>None</u>	NOTES:	DRAWN BY: <u>PC</u> DATE: <u>12-2-70</u> CHECKED BY: <u>GMS</u> DATE: <u>12-22-70</u>	FLINT 5 BOX 100 ENG 10
---	--------	--	------------------------------





NO. PCS.	MARK	MATERIAL	LENGTH		REMARKS	WEIGHT
			FT.	IN.		
16	A15	BAR 6 3/4 x 5/8	2	0 1/2	ASTM A176 3/16	
16	E15	BAR 6 3/4 x 5/8	13	9 3/4	TYPE 410S	
8	F15	BAR 6 3/4 x 5/8	13	9 3/4	CHEMICALS TO LOWMAN 5 A 176, TYPE 410S	
8	B15	RUBBER "I" SEALS	5 3/4	2 1/2	STEM 65 0	
8	B15	RUBBER "I" SEALS	5 3/4	2 1/2	STEM 65 0	
8	C15	RUBBER SECS	4 1/2	1	47 9 3/8	
16	D15	NEOPRENE GASKETS	3	2	3/8	NEOPRENE
16	H15	RUBBER FILLER PIECES	5	3	0-7	

NOTE  
TAG ALL MATERIAL  
WITH ITEM NO 132

(3)

NO ITEM NUMBER 132  
CONTRACT NUMBER DDCW 68-70-C-0088

APPROVAL STAMP

**APPROVED**

LOWER SHAKE RIVER  
RESIDENT OFFICE

25 SEP 1978

LSR 70-0088-132-020

DRAWN BY: <u>RE</u> DATE: <u>12-8-70</u> CHECKED BY: <u>G.M.</u> DATE: <u>12-22-70</u>	<b>FLINT STEEL CORPORATION</b> BOX 1289, TULSA, OKLAHOMA 74101 ENGINEERING DEPARTMENT	JOB NO.: <u>70-0544</u> SHEET NO.: <u>15</u> OF <u>3</u>
---	---	---

70-C-88-367

PROPERTY  
PAGE NAME

DESIGNER  
DATE  
CHECKED  
DATE


SCALE  
PROJECT NO.  
SHEET NO.

A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z

DATE  
SCALE  
PROJECT NO.  
SHEET NO.

DESIGNER  
DATE  
CHECKED  
DATE

PROPERTY  
PAGE NAME



ANCHOR NO. 1 (SEE)

ANCHOR NO. 2 (SEE)

ANCHOR NO. 3 (SEE)

1-PL 1/2" x 4'-0 1/2" x 3/16" - V16  
SEE DETAIL A SHEET 17


TRIM LINE  
FOR R16 & V16  
ONLY

DOWNSTREAM ELEVATION

ERECTOR SUPPLY - 11 SHEET 10 (SEE SHEET 10)  
6'-11 1/2" x 4'-0 1/2" x 3/16" (DOWNSTREAM END OF BEAM, FIG. 10)

THIS DRAWING AND SPECIFICATION IS THE PROPERTY OF THE CLIENT AND IS NOT TO BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM. WITHOUT THE WRITTEN PERMISSION OF THE ENGINEER.

1




(2)

8-SKIN PLATE ASSEMBLIES ~ THUS ~ AIG  
 8-SKIN PLATE ASSEMBLIES ~ RET ~ RAIG

WORK THIS OWS

<p>THIS DRAWING AND INFORMATION IS THE PROPERTY OF THE FURTHER DEVELOPMENT OF THIS DRAWING, REVISIONS OR MODIFICATIONS SHALL BE THE RESPONSIBILITY OF THE DRAWING ENGINEER.</p>	<p>NO. _____ UNLESS NOTED OTHERWISE</p> <p>DATE _____</p> <p>BY _____</p> <p>APP. _____</p>	<p>NO. _____ UNLESS NOTED OTHERWISE</p> <p>DATE _____</p> <p>BY _____</p> <p>APP. _____</p>	<p>REMOVED SECTION B-B</p> <p>REVERSE WELD SYMBOL</p> <p>ADD EXTRA 2 SKIN PLATE SECTION B-B</p> <p>CHANGED FROM 3/4" TO 1/2" WELD</p> <p>REV. FOR WELDING SEQUENCE 3-15-77</p>	<p>DATE _____</p> <p>BY _____</p> <p>APP. _____</p>
---	---	---	--	---



16-L.G.C. - 3/8" - 0'2" - BIG

NO. PCS.	MARK	MATERIAL	LENGTH		REMARKS	QUANTITY
			FT.	IN.		
		BIG SKIN PL ASSY'S				
		BIG SKIN PL ASSY'S				
71	BEND	3/8" ANG R-51 x 3/4	2.6	4	A337 GR.A	
72	BEND	1/2" ANG ST103W-31	6.8	10	A337 GR.3	
73	BEND	1/2" ANG PL 30 x 1 1/2	3	8	A337 GR.A	
74	BEND	1/2" ANG PL 1 1/2 x 1 1/2	2.4	4	A337 GR.A	
75	BEND	1/2" ANG PL 1 1/2 x 1 1/2	2.4	4	A337 GR.A	
76	1/2" ANG BAR 4 x 3/8		2.3	3		
77	1/2" ANG BAR 2 x 1		0.9	1		
78	1/2" ANG PL 10 x 1		1	5 1/4		
79	1/2" ANG PL 11 x 3/4		3	11		
80	1/2" ANG PL 12 x 3/4		4	3 1/2		
81	3/8" ANG L 4 x 3 x 3/4		0.3	3		
82	1/2" ANG BAR 3 x 2		0.3	3		
83	1/2" ANG BAR 3 x 1 5/16		4	3 1/2		
84	1/2" ANG BAR 3/4 x 1		0.9	1		
85	1/2" ANG BAR 3/4 x 1		2.4	4	A337 GR.A	
86	3/8" ANG BAR 3/4 x 1/2		0.6	2	A337 GR.A	
87	BEND	3/8" ANG R-51 x 3/4	3.8	1 1/2	A337 GR.A	
88	1/2" ANG LG.C. 1 x 3/8		0.2	2		
89	1/2" ANG BAR 7/16 x 1/4		0.6	2		

NO.	MARK	MATERIAL	LENGTH	REMARKS	QUANTITY
94		1/4" ANG PL 1/2" x 1/2"	0.1	FF-5-87	1
95		1/2" ANG PL 1/2" x 1/2"	0.1	FF-5-87	1

SHORWELD

3/8" FILLET	532	0	LIN.FT.
1/2" FILLET	4320	0	
3/4" FILLET	64	0	
1" FILLET	173	0	
1 1/2" FILLET	270	0	
1/4" BEV	70	0	
3/8" BEV	274	0	
1/2" BEV	75	0	
1" BEV	68	0	
1 1/2" BEV	72	0	
1 3/4" BEV	75	0	

ALL MATL. A36 UN.

NOTE - TAG ALL MATERIAL WITH ITEM # 132

(3)

ITEM NUMBER 132  
CONTRACT NUMBER OACN G-70-C-0088

APPROVAL STAMP

**APPROVED**

LOWER SHAKE RIVER  
RESIDENT OFFICE

22 SEP 1971

DATE	DESCRIPTION	BY
12/17/70	DESIGNED	J.P.M.
12/17/70	DRAWN	J.P.M.
12/17/70	CHECKED	J.P.M.
12/17/70	APPROVED	J.P.M.

WORK THIS ONE WITH NO. 17


LSR 70-0088-132-021

FLINT STEEL CORPORATION  
BOX 1200, TULSA, OKLAHOMA 74102


SIGNATURE ASSEMBLIES  
LOWER GRANITE LOCK ASSEMBLIES  
LOWER GRANITE LOCK COOPER  
7100 MAIN ST. TULSA, OKLA. 74106

70-0088  
16


70-C-88-368



DETAIL "A"



DETAIL "C"




SECTION A-A  
SECTION B-B

A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26


(1)

**FIELD LENGTH**  
FOR SIZE AND SPACING OF MEMBERS AND THE POSITION OF THE PLATE STEEL CONNECTION, THE DRAWING IS NOT TO BE TAKEN, COPIED, REPRODUCED OR USED FOR ANY PURPOSE UNLESS THE DRAWING REPRESENTS THE PLANT STEEL CONNECTION.


**HOLES**  
PATTERNING  
PUNCH *AL*







DETAIL "A"  
(TYP RIB TO GIRDER CONN)



SECTION D-D




DETAIL "E"  
ERECTION CLIP DETAIL




2


THE PROJECT NO WAY TO BE ASSUMED FROM INFORMATION	HOLDER _____ FASTENERS _____ FINISH <u>NONE</u>	REVISIONS NOTED UNLESS NOTED	NOTES 1	SHOW WL SIZE OF SECT. D-D REV. DIRECTION OF BONDING HARDENED STEEL REVISE WELD SYMBOLS REV. PER APPROVAL SEP 18 1971	102572 102571 102570 102569	DRAWN BY <u>PE</u> DATE <u>12-9-70</u> CHECKED BY _____ DATE _____ APPROVED BY <u>C.M.</u> DATE <u>12-12-70</u>	FLINT STEEL 2nd BOX 1990, TULSA ENGINEERING
--	---	---------------------------------	------------	---	--------------------------------------	---	---




SECTION D-D



DETAIL "E"  
ERECTION CLIP DETAIL



5-TG3 TYPE A10, COND. T.  
(ORDER 3 3/8\"/>



32-BAR - 1 1/2\"/>

3

NO ITEM NUMBER 132  
CONTRACT NUMBER DHEW-68-70-C-0088

APPROVAL STAMPS

**APPROVED**

LOWER SNAKE RIVER  
RESIDENT OFFICE

23 SEP 1973

LSR70-0088-132-022

SECTION D-D  
DRAWN BY PE  
DATE 12-9-70

FLINT STEEL CORPORATION  
BOX 1288, TULSA, OKLAHOMA 74101  
ENGINEERING DEPARTMENT

SKIN PLATE ASS'Y DETAILS  
LOWER GRANITE LOCK & DAM  
LOWER GRANITE CANAL  
FULLMAN, WASH.

70-0544  
FT

70-C-88-369

①


SHEET NO. 10  
 PROJECT NO. 1032  
 DRAWING NO. 1032-10  
 DATE 10/10/60  
 SCALE 1" = 10'-0"

A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z

SHEET NO. 10  
 PROJECT NO. 1032  
 DRAWING NO. 1032-10  
 DATE 10/10/60  
 SCALE 1" = 10'-0"

DETAIL "A"  
THIS SHWT.

1-5 STDS # 31 X 6 @ 10' C 13 (TYP) LOW ALLOY  
 1-5 SKIN # 1/2 X 12 @ 10' C 13 (TYP) LOW ALLOY  
 1-5 SKIN # 1/2 X 12 @ 10' C 13 (TYP) LOW ALLOY  
 1-5 SKIN # 1/2 X 12 @ 10' C 13 (TYP) LOW ALLOY



DOWNSTREAM ELEVATION FOR A18



THIS DRAWING AND SPECIFICATIONS IS PROPERTY OF THE FLETCHER STEEL COMPANY AND IS NOT TO BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM.





15-9 1/2  
 (1/2" ADDED FOR SHRINKAGE)

15-10

1-PL-11 1/2 x 3/8 = 13-9 1/8 x 18"

1-PL-11 1/2 x 3/8 = 13-10-6 1/8"

DETAIL "X" THIS SHIP




STREAM ELEVATION FOR A18

DOWNSTREAM ELEVATION FOR B18

- 8 - SKIN PLATE ASSEMBLIES - THUS 4 NOTED - A18
- 8 - SKIN PLATE ASSEMBLIES - REV 4 NOTED - RA18
- 8 - SKIN PLATE ASSEMBLIES - THUS 4 NOTED - B18

SECTION B-B THUS  
 SECTION C-C REV.




2

THIS DRAWING AND INFORMATION IS CONTAINED AND THE PROPERTY OF THE PLANT OFFICE, MANAGEMENT AND CONTROL IS NOT TO BE REPRODUCED, COPIED, OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, WITHOUT THE WRITTEN PERMISSION OF THE PLANT OFFICE, MANAGEMENT.

HOLE: UNLESS NOTED  
 FASTENER: UNLESS NOTED  
 FINISH: NONE

NOTES


ADD DETAILS "X" & M. G. ON	DATE: 1-27-71
REVISE SECT. B-B & CORRECT DET. C'S FOR ON	GENERAL REV. 1-27-71
EXAMINE WELD PROCEDURES	REWORK LOWER 2'-0"
REWORK SKIN REV. WITH PER. LETTER B18B-2	DATE: O.N. 1-27-71
GENERAL REVISION	BY: [Signature]



NO.	MARK	MATERIAL	LENGTH	REMARKS
PCS.			FT. IN.	
<b>A115 SKIN PL ASSYS</b>				
<b>A115 SKIN PL ASSYS</b>				
② BEND	16	118 PL 125 x 1/2	76 4	A115 GR. A 74
BEND	16	118 PL 125 x 1/2	38 1/2	A115 GR. A 74
① BEND	16	118 PL 125 x 1/2	64 10	A115 GR. A 74
①	16	118 PL 11 x 3/8	13 10	86
①	16	118 PL 125 x 1/2	13 10	285
①	16	118 BAR 3 x 1/2	13 10	299
		204 SKL L 4 x 3 x 3/8	0 3	149
		440 1/2 BAR 3 x 1/2	0 3	149
<b>A110 SKIN PL ASSYS</b>				
② BEND	8	110 PL 166 x 1/2	76 4	A110 GR. A 74
BEND	8	110 PL 166 x 1/2	38 1/2	A110 GR. A 74
① BEND	8	110 PL 166 x 1/2	64 4	A110 GR. A 74
		110 PL 11 x 3/8	13 10	86
		110 PL 125 x 1/2	13 10	285
		110 BAR 3 x 1/2	13 10	299
		110 SKL L 4 x 3 x 3/8	0 3	149
		220 1/2 BAR 3 x 1/2	0 3	149
<b>SHOP WELD</b>				
		3/8 FILLET 2900	0	LIN. 5"
		1/4 FILLET 29155	0	
		3/8 FILLET 660	0	
		1/2 FILLET 330	0	
		1/4 BEV 530	0	
		3/8 BEV 330	0	
		3/8 BEV 330	0	
		1/4 BEV 160	0	
ALL MAT'L A36 UN.				

SECT A-A

NOTE  
TAG ALL MATERIAL  
WITH ISEN NO 132



DETAIL "K" THIS  
DETAIL "M" REV.  
WORK THIS DWG W/ DWG NO 19

3

NO ITEM NUMBER 132  
CONTRACT NUMBER D4CV 68-70-C-0088

APPROVAL STAMP

**APPROVED**

LOWER SHAKA RIVER  
RESISTANCE

DATE: 25 SEP 1970

NOTED - A18  
NOTED - RA15  
NOTED - B10

NO.	DATE	BY	REVISION
1	10-1-70	EC	ISSUE FOR CONSTRUCTION
2	10-1-70	EC	REVISION

FLINT STEEL CORPORATION  
ENGINEERING DEPARTMENT



70-088-132-023

70-088-132-023


18

70-C-88-370







**SECTION A-A**  
(FOR SKIN SECT. A18)



**DETAIL "C"**





**DETAIL "D"**



2


WORK THIS WITH SHEET

NAME: _____ PARTS: _____ DATE: _____	DRAWN BY: _____ CHECKED BY: _____ DATE: _____	REVISIONS: _____ DATE: _____	PROJECT: _____ SHEET: _____
--	---	---------------------------------	--------------------------------



**SECTION 8-B**  
(FOR SKIN SECT. B18)

A  
A18)



NO ITEM NUMBER 132  
CONTRACT NUMBER DCW-68-70-C-0088

APPROVAL STAMP  
**APPROVED**  
Subject to conformity with plans and specifications, completion of work or other work, and to fulfillment of any required tests, material tests, and other tests or reports as applicable for this work and for the Lower Snake River Resident Office.  
Date: 25 SEP 1963

Work This Sheet  
WITH SHEET 1A

3

ESR 70-0088-132-024


SECTION 8-B	DATE	BY
SECTION 8-B	DATE	BY
SECTION 8-B	DATE	BY
SECTION 8-B	DATE	BY
SECTION 8-B	DATE	BY

DESIGNED BY: R-118-10  
CHECKED BY: R-118-10

BLIND STEEL CORPORATION  
1000 10th St. N.E.  
Grand Rapids, Michigan 49503


RESIDENT OFFICE  
LOWER SNAKE RIVER  
RESIDENT OFFICE  
25 SEP 1963

70-C-88-371



128 - STUD BOLTS

DRILL & TAP 1/4" UNF  
x 2" DEEP - 1/4" x 2" H.A.





16 - TRU

STL  
USE 1/2"  
MADE IN  
(SPECS)


A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z																																																																										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100

(1)



128-PL-6 1/2 x 10-G-B20 (A490)

128 - STUD BOLTS - A20



**16-TRUNNION PINS - C20**

STEEL FORGING ASTM A588 CLASS C1.  
 USE 3/8\"/>

2

THE DESIGN AND DIMENSIONS OF MEMBER ARE THE PROPERTY OF THE PLANT AND COMPANY AND SHOULD NOT BE REPRODUCED OR COPIED WITHOUT THE WRITTEN PERMISSION OF THE PLANT AND COMPANY.

DESIGNER: \_\_\_\_\_  
 PARTNER: \_\_\_\_\_  
 FROM: NONE

NOTES:

REVISED: \_\_\_\_\_  
 BY: \_\_\_\_\_  
 DATE: \_\_\_\_\_

00 (A490)

NO.	MARK	MATERIAL	LENGTH		REMARKS
			FT.	IN.	
108	A20	2" $\phi$ STUD BOLT	9	10	A490 7/8"
122	B20	FL. G. #34	0	6	A490
16	C20	PIN 2" $\phi$	3	7/8	SEE DETAIL
32		1" $\phi$ NUT	0	2	TRIAL 1014 NO. 1017 FPA-6156
<b>FIELD BOLTS (ACTUAL COUNT)</b>					
32		1" $\phi$ NUT	0	2	HEX HD. 3 THD. 3/4" NONHEX FPA-5726
204		3/4" NUT	0	24	HEX HD. NUT
204		3/4" NUT	0	24	LOCK WASHER
204		3/4" NUT	0	24	HEX HD. NUT
204		3/4" NUT	0	24	LOCK WASHER
204		3/4" FLAT WASH			WASHER
204		3/4" LOCK WASH			WASHER
226	D20	2" $\phi$ NUT			A490
122	E20	2" $\phi$ FLAT WASH			A490
<b>SHOP ASSEMBLY &amp; FIELD PIN-UP BOLTS (ACTUAL COUNT)</b>					
104		3/4" NUT	0	2	
32		3/4" NUT	0	24	
64		3/4" NUT	0	24	
32		3/4" NUT	0	3	
64		3/4" NUT	0	54	
64		3/4" NUT	0	24	
704		3/4" NUT	-	-	
TO BE REMOVED FROM TAGS (SPACES AFTER SHOP ASSEMBLY)					
712		3/4" U.S.S. ASSE-0	2		

NOTE:  
TAG ALL MATERIAL  
WITH ITEM NO 132

NO ITEM NUMBER 132  
CONTRACT NUMBER D7C11-68-70-C-0088

3

LSR70-0088-132-025

APPROVAL DEVICE

**APPROVED**

Subject to conformity with plans and specifications, and to the satisfaction of the Engineer, the Contractor shall be responsible for the accuracy and quantity of the work.

LOWER SHAKE RIVER  
RESIDENT OFFICE

DATE: 10/13/81

70-C-88-372