



Presented to:

Army Corrosion Summit

Army Aviation Corrosion Engineering Case Studies

Approved for public release; distribution unlimited. Review completed by the
AMRDEC Public Affairs Office 1 Feb 2010; FN4398



TECHNOLOGY DRIVEN. WARFIGHTER FOCUSED.

Presented by:

Dan Groner

Corrosion and Environmental Team Lead

**Aviation and Missile Research,
Development and Engineering Center**

Date: 10 February 2010

Report Documentation Page				Form Approved OMB No. 0704-0188	
Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to a penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.					
1. REPORT DATE 10 FEB 2010		2. REPORT TYPE		3. DATES COVERED 00-00-2010 to 00-00-2010	
4. TITLE AND SUBTITLE Army Aviation Corrosion Engineering Case Studies				5a. CONTRACT NUMBER	
				5b. GRANT NUMBER	
				5c. PROGRAM ELEMENT NUMBER	
6. AUTHOR(S)				5d. PROJECT NUMBER	
				5e. TASK NUMBER	
				5f. WORK UNIT NUMBER	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U.S. Army Aviation and Missile Research, Development and Engineering Center,Bldg 4488,Redstone Arsenal,AL,35898				8. PERFORMING ORGANIZATION REPORT NUMBER	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)	
				11. SPONSOR/MONITOR'S REPORT NUMBER(S)	
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution unlimited					
13. SUPPLEMENTARY NOTES 2010 U.S. Army Corrosion Summit, Huntsville, AL, 9-11 Feb					
14. ABSTRACT					
15. SUBJECT TERMS					
16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT Same as Report (SAR)	18. NUMBER OF PAGES 14	19a. NAME OF RESPONSIBLE PERSON
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified			

- **Introduction**
- **H-47 FRIES Bar Support Rod Corrosion**
- **H-60 SAS Link SCC Failure**

- **AMC**
 - **RDECOM**
 - **AMRDEC**
 - **AED**
 - » **Structures and Materials Division**
 - » **Materials Branch**
 - » **Corrosion and Environmental Team**

- **Core Competencies**
 - **Coatings**
 - **Corrosion**
 - **Sealants**
 - **Adhesives**
 - **NDI**
 - **Operational Chemicals and Processes**
 - **Environmental Issues**
- **Customer Base**
 - **Aviation PMOs**
 - **Corrosion Program Office**
 - **Environmental Technology Integration Group**

- **Problem**



- A Category I Quality Deficiency Report (QDR) investigation of the FWD Fast Rope Insertion Extraction (FRIES)/External Rescue Hoist support rod (P/N LEX-1583-05), consisting of microscopic, ultrasound, and metallurgic examination revealed severe corrosion of the inside surface of the rod. Subsequent investigation of additional ship sets revealed several support rods within the FWD FRIES/External Rescue Hoist truss assembly exhibiting similar corrosion.


- **The Investigation**
- Multiple bars were dissected and inspected
- Structural analysis to determine effect of corrosion loss
- Conformance of hardware to the drawings?
- Categorized severity

Interior view of severely corroded Support Rod



- **Resolution**
- ASAM H-47-09-ASAM-04 is issued
- Requires inspection and grading of the corrosion severity
- Thoroughly dry the rod and treat interior with MIL-C-16173, Grade 3
- Restrict usage of the FRIES station based on corrosion severity


Example of rod end threads of a seized in place rod end. Notice the extent of the corrosion and pitting



- Result – The rest of the story
- Aircraft were restricted until support rods were replaced
- All support rods have been replaced
- The old rods have been scrapped



- **The Problem**
- During ground taxi of a Navy aircraft, it would not turn right despite full right pedal input. Inspection of the aircraft revealed the Stability Augmentation System (SAS) Link, PN 70410-02334-044, on the Yaw Boost Servo was fractured. Analysis determined that the Link failed due to Stress Corrosion Cracking (SCC), and indicated the material to be 7075-T6 Temper.



H-60 SAS Link

Problem: HS-11 reported that during preflight flight control checks, pilot noticed a thump. Pilot continued with preflight checks and noted that all flight controls felt normal and that the anomaly did not return. During ground taxi aircraft would not turn right despite full right pedal input. The aircraft was shutdown at which time the SAS Link, P/N 70410-02334-044, on Yaw Boost Servo, P/N 70410-22910-045, was found fractured.

Cause: Lab analysis determined that the link failed due to stress corrosion cracking (SCC) through its cross section. Subsequent to this failure, the link further fractured due to overload. Hardness and conductivity testing indicate a -T6 temper condition which has poor resistance to SCC. Newer SAS Links (-045) are manufactured in the -T73 temper condition which is less susceptible to SCC. However, drawing for older SAS Links (-044) allows manufacture in the T-6 temper condition. SAS Link is used on Yaw and Collective Boost Servo Assemblies (P/N 70410-22910-045) and Pitch and Roll Trim Assemblies (P/Ns 70410-22760-050/-051/-053).

Risk Assessment: HRI = 12. Medium Safety Risk

- Severity: Catastrophic (1).
- Frequency: Improbable (E).

Required Action: Bulletin for one-time inspection:

- Inspect for and remove all -044 SAS Links .
- Inspection to be conducted either visually if link p/n is legible or via eddy current conductivity testing if p/n is not legible.

Compliance time: NLT next 56 Day Special




Application: All Naval H-60 aircraft

Supply Data:



- Bulletin is logistically supportable.
- 157 SAS Link Assemblies, P/N 70410-02334-045, on hand.

Follow-On Action:


- Ensure all SAS Link Assemblies, P/N 70410-02334-044, are purged from supply system.
- Ensure references to SAS Link Assembly, P/N 70410-02334-044, are removed from applicable manuals.



- **The Investigation**
- Drawing review – the link was not to print
 - 7075-T651 versus 7075-T73
 - Press fit versus adhesive and staked
- Structural Analysis
- Failure Analysis
- Risk Analysis



- **The Resolution**
- Issue a message H060-10-ASAM-04
- Inspect all subject links for evidence of corrosion
- Conductivity check to determine alloy
- Touch up and apply CPC MIL-C-81309 Type II
- Ongoing inspections of T6 links



- The Outcome
- As of 13 Jan, 1052 aircraft, 3165 links inspected
- 999 links failed (T6)
- 362 Aircraft with new links



- Introduction
- H-47 FRIES Bar Support Rod Corrosion
- H-60 SAS Link SCC Failure