

# Coating Performance in Duluth Superior Harbor—Part 2

RICHARD I. RAY AND BRENDA J. LITTLE, FNACE,  
Naval Research Laboratory, Stennis Space Center, Mississippi

*Nine coatings were evaluated for corrosion protection of carbon steel coupons and I-beams around Duluth Superior Harbor after 46 and 35 months, respectively. Coupons were intentionally scribed to metal before exposure. Part 1 (September 2012 MP) described the coatings used and the locations of coupons and I-beams. Part 2 discusses the results of the evaluation.*

Sixteen miles (26 km) of carbon steel (CS) sheet piling (12-mm thick ASTM A328<sup>†</sup> cold rolled) used for docks, bridges, and bulkheads in the Duluth Superior Harbor (DSH) in Minnesota and Wisconsin are corroding at an accelerated rate of 3 mm/y or higher. The corroded pilings have an orange rusty appearance characterized by tubercles (i.e., corrosion products and deposits covering areas of localized corrosion). Barrier coatings provide one option for protection of extensive structures in fresh water, and nine coatings were evaluated for corrosion protection of CS coupons and I-beams around DSH after 46 and 35 months, respectively. Part 1 (September 2012 MP) described the coatings used and the locations of coupons and I-beams. Part 2 discusses the results of the evaluation.

## Products

The following coatings were selected for this evaluation:

- 1 Aquapure HR<sup>†</sup>
- 2 Chevron Phillips TZ9043<sup>†</sup>
- 3 Standard epoxy
- 4 Humidur ML<sup>†</sup>
- 5 Wasser MC-zinc/MC-tar<sup>†</sup>
- 6 Sherwin-Williams Fast clad ER<sup>†</sup>
- 7 Poly-Spec LPE 5100<sup>†</sup>
- 8 Coal tar epoxy
- 9 Zinc-rich primer VZ108/V766

These products are identified throughout the article by number.

## Coupons

There were no corrosion products or tubercles on any of the painted coupon surfaces like those that covered areas of localized corrosion on unprotected piling surfaces. The outward-facing coated surfaces were colonized with zebra mussels and a freshwater sponge. Zebra mus-

<sup>†</sup>Trade name.

*2012107080*

FIGURE 1



(Side A) Coating 1 (Side B)  
**U.S. Coast Guard Cell B**  
 White two-part solvent-free polyamine epoxy  
 Total exposure time 46 months

**Observations**  
 Few byssal threads still attached  
 Both sides covered in sponge material  
 Top layer of coating peeling in places  
 Corrosion evident in scribe (artificial defect)  
 Muddy coating on surface

(Side A) Coating 1 (Side B)  
**U.S. Coast Guard Cell C**  
 White two-part solvent-free polyamine epoxy  
 Total exposure time 46 months

**Observations**  
 Few byssal threads still attached  
 Algae growing on one side of coupon  
 Top layer of coating peeling from scribe  
 Corrosion evident in scribe (artificial defect)  
 Muddy coating on surface

Coating 1 coupons.

FIGURE 2



(Side A) Coating 4 (Side B)  
**U.S. Coast Guard Cell B**  
 Green two-part solvent-free polyamine epoxy  
 Total exposure time 46 months

**Observations**  
 Few byssal threads still attached  
 Coating appears intact even in scribe area  
 Corrosion evident in scribe  
 Muddy coating on surface

(Side A) Coating 4 (Side B)  
**U.S. Coast Guard Cell C**  
 Green two-part solvent-free polyamine epoxy  
 Total exposure time 46 months

**Observations**  
 Few byssal threads still attached  
 Coating appears intact even in scribe area  
 Corrosion evident in scribe  
 Muddy coating on surface except where silicone caulk used to attach Teflon holder

Coating 4 coupons.

sels were removed prior to digital imaging to accommodate the shipping container size. Algae colonized the backside. Both sides were covered in a thin film of mud. There were no indications of coating degradation caused by the fouling. Localized corrosion on the coupons was limited


to the intentional scribe area. The topcoat of Coating 1 was peeling from the scribe. Coatings 4, 5, 6, 7, and 9 remained intact and there were no indications of delamination even in the scribe area. Figures 1 through 4 present descriptions and observations.

### I-Beams

Table 1 summarizes I-beam coating performance after exposure.

The topcoat of Coating 1 delaminated and peeled from the surface of the I-beam (Figure 5).

**FIGURE 3**



**Coating 5**  
(Side A) (Side B)

**U.S. Coast Guard Cell C**  
Red urethane micaceous iron oxides  
and refined coal tar  
Total exposure time 46 months

**Observations**  
Few byssal threads still attached  
Some algae on coating surface  
Coating appears intact even in scribe area  
Corrosion evident in scribe  
Muddy coating on surface

**Coating 9**  
(Side A) (Side B)

**U.S. Coast Guard Cell C**  
Blue/grey zinc primer/vinyl copolymers  
Total exposure time 46 months

**Observations**  
Few byssal threads still attached  
Some algae on coating surface  
Coating appears intact even in scribe area  
Corrosion evident in scribe  
Muddy coating on surface

Coatings 5 and 9 coupons.

**FIGURE 4**



**Coating 6**  
(Side A) (Side B)

**U.S. Coast Guard Cell B**  
White amine epoxy (one coat)  
Total exposure time 46 months

**Observations**  
Few byssal threads still attached  
Coating appears intact even in scribe area  
Coating lumpy and thick  
Corrosion evident in scribe  
Muddy coating on surface

**Coating 7**  
(Side A) (Side B)

**U.S. Coast Guard Cell C**  
Black polysulfide modified epoxy novolac  
Total exposure time 46 months

**Observations**  
Few byssal threads still attached  
Some algae on coating surface  
Coating appears intact even in scribe area  
Corrosion evident in scribe  
Muddy coating on surface

Coatings 6 and 7 coupons.

The I beams were not scribed so the intentional defect was not necessary to initiate the delamination. The base coat remained intact and no localized corrosion was obvious. Coating 7 peeled from the surface in large sections, exposing uncoated steel with corrosion and tubercles (Figure 6).

All other coatings performed adequately. Chips along the edges of the I-beams may have occurred during transport.

## Conclusions

Over a three- to four-year period, coatings prevented the formation of tubercles and localized corrosion on CS surfaces. Coating performance varied among the products and two products (Coatings 1 and 7) failed due to peeling. None of the coatings protected the substratum at an intentional defect.

Details showing all coating results are available from the authors.

## Reference

- 1 ASTM Standard A328/A328M-07, "Standard Specification for Steel Sheet Piling" (West Conshohocken, PA: ASTM International, 2007).

**RICHARD I. RAY** is a physical scientist at the Naval Research Laboratory, Code 7332, Stennis Space Center, MS 39529-5004. He has worked for the Naval Research Laboratory for 29 years, operating scanning electron microscopes for research on biodeterioration and biodegradation of materials in marine environments. He has a B.S. degree in biology from the University of Southern Mississippi and received four Alan Berman Research Publication Awards and the Sigma Xi Award.

**BRENDA J. LITTLE, FNACE**, is a senior scientist at the Naval Research Laboratory. She uses surface analytical chemistry, electron microscopy, and electrochemical techniques to investigate adsorption, biofouling, biodegradation, bioremediation, and corrosion in marine environments. She is a NACE International Fellow and has been a NACE member since 1984. *MP*

TABLE 1

### Coating performance after exposure

Product/Chemistry	Pass/Fail	Description
1—white two-part solvent-free polyamine epoxy	Fail	Delamination, blistering, peeling
2—light green/white two-part epoxy	Pass	Thick, uneven, intact, chips
3—grey two-part polyamide epoxy/zinc primer	Pass	Thick, smooth, intact, chips
4—dark green two-part polyamine epoxy	Pass	Thick, lumpy, intact, chips
5—red urethane micaceous iron oxides/refined coal tar	Pass	Thin, intact, fingerprints, chips
6—white amine epoxy (one coat)	Pass	Thick, lumpy, intact, chips
7—black polysulfide modified epoxy novolac	Fail	Broken, peeling, corrosion
8—black two-part coal tar polyamide epoxy	Pass	Thin, smooth, intact, few chips
9—blue/grey zinc primer/vinyl copolymers	Pass	Thin, rough, intact, chips

FIGURE 5



Coating 1 shown on the I-beams.

FIGURE 6



Coating 7 shown on the I-beams.

**REPORT DOCUMENTATION PAGE**

*Form Approved*  
OMB No. 0704-0188

The public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to the Department of Defense, Executive Services and Communications Directorate (0704-0188). Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.

**PLEASE DO NOT RETURN YOUR FORM TO THE ABOVE ORGANIZATION.**

<b>1. REPORT DATE (DD-MM-YYYY)</b> 14-11-2012		<b>2. REPORT TYPE</b> Journal Article		<b>3. DATES COVERED (From - To)</b>	
<b>4. TITLE AND SUBTITLE</b> Coating Performance in Duluth Superior Harbor - Part 2				<b>5a. CONTRACT NUMBER</b>	
				<b>5b. GRANT NUMBER</b>	
				<b>5c. PROGRAM ELEMENT NUMBER</b> W56MES00404548	
<b>6. AUTHOR(S)</b> Richard I. Ray and Brenda Little				<b>5d. PROJECT NUMBER</b>	
				<b>5e. TASK NUMBER</b>	
				<b>5f. WORK UNIT NUMBER</b> 73-9776-00-5	
<b>7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)</b> Naval Research Laboratory Oceanography Division Stennis Space Center, MS 39529-5004				<b>8. PERFORMING ORGANIZATION REPORT NUMBER</b> NRL/JA/7330--12-1384	
<b>9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)</b> US Army Engineer District Detroit PO Box 1027 Detroit, MI 48231-1027				<b>10. SPONSOR/MONITOR'S ACRONYM(S)</b> Army	
				<b>11. SPONSOR/MONITOR'S REPORT NUMBER(S)</b>	
<b>12. DISTRIBUTION/AVAILABILITY STATEMENT</b> Approved for public release, distribution is unlimited.					
<b>13. SUPPLEMENTARY NOTES</b>					
<b>14. ABSTRACT</b> Sixteen miles (26 km) of carbon steel (CS) sheet piling (12-mm thick ASTM A3281 cold rolled) used for docks, bridges, and bulkheads in the Duluth Superior Harbor (DSH) in Minnesota and Wisconsin are corroding at an accelerated rate of 3 mm/y or higher. The corroded pilings have an orange rusty appearance characterized by tubercles (i.e., corrosion products and deposits covering areas of localized corrosion). Barrier coatings provide one option for protection of extensive structures in fresh water, and nine coatings were evaluated for corrosion protection of CS coupons and I-beams around DSH after 46 and 35 months, respectively. Part 1 (September 2012 MP) described the coatings used and the locations of coupons and I-beams. Part 2 discusses the results of the evaluation.					
<b>15. SUBJECT TERMS</b> carbon steel, coatings, evaluation, corrosion, protection					
<b>16. SECURITY CLASSIFICATION OF:</b>			<b>17. LIMITATION OF ABSTRACT</b> UL	<b>18. NUMBER OF PAGES</b> 4	<b>19a. NAME OF RESPONSIBLE PERSON</b> Richard Ray
<b>a. REPORT</b> Unclassified	<b>b. ABSTRACT</b> Unclassified	<b>c. THIS PAGE</b> Unclassified			<b>19b. TELEPHONE NUMBER (Include area code)</b> (228) 688-4690