


PHOTOGRAPH THIS SHEET


AD A951237

DTIC ACCESSION NUMBER



LEVEL

Watertown Arsenal Labs. MA



INVENTORY

Rept. No. 312/63

DOCUMENT IDENTIFICATION

3 Jan. 34

DISTRIBUTION STATEMENT A

Approved for public release;
Distribution Unlimited

DISTRIBUTION STATEMENT

ACCESSION FOR	
NTIS	GRA&I <input checked="" type="checkbox"/>
DTIC	TAB <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION	
(3 Jan. 1934)	
BY	
DISTRIBUTION /	
AVAILABILITY CODES	
DIST	AVAIL AND/OR SPECIAL
A	

Released



DATE ACCESSIONED

DISTRIBUTION STAMP

UNANNOUNCED

81 7 02 068

DATE RECEIVED IN DTIC

PHOTOGRAPH THIS SHEET AND RETURN TO DTIC-DDA-2

AD A951237

Approved for publication
in accordance with the
Department of Defense
policy on the release of
information.

January 3, 1936

Pitted Pawls, Fuse Setter M5

Reference: Letter C. O. 471.825/569, dated
Oct. 25, 1934

Material

Two pitted and one new left hand, two pitted and one new right hand pawls for Fuse Setter M5 assigned to the 62nd A. A. C. A., Fort Totten, N. Y., were submitted to ascertain the cause of pitting.

Conclusions

1. The pitting and markings of the unserviceable pawls indicated corrosion, probably the result of improper cleaning after use or insufficient protection while not in use.
2. The steel was of good quality, commercially well forged and heat treated.
3. The hardness probably varied somewhat from piece to piece as the micro structure of the various pawls showed variations in the amounts of martensite and troostite. However, the structure of each pawl was the same throughout.

DISTRIBUTION STATEMENT A

Approved for public release
Distribution Unlimited

DISTRIBUTION OF REPORTS

REPORT NO. 312/63 TITLE Witted Rawls
 DATE DISTRIBUTED 1/25/35 True Letter M5

	Lo- cal	Other Ord. Work	Army	Navy	Private
Author	1	1	1 ✓	1	1
Lab. File	1	1	1 ✓	1	1
Main Office File	1	1	1	1	1
Chief of Ordnance	-	-	3	2	-
Technical Staff	-	-	1	1	-
Springfield Armory	-	-	1	1	-
Watervliet Arsenal	-	-	1	1	-
Rock Island Arsenal	-	-	1	1	-
Frankford Arsenal	-	-	1	1	-
Picatinny Arsenal	-	-	1	1	-
Aberdeen Proving Ground	-	-	1	1	-
Chief, Bureau Ordnance	-	-	-	1	-
Naval Gun Factory	-	-	-	1	-
Chief, Bureau C & R	-	-	-	1	-
				welding and as directed	
Local Circulation	1	1	1	1	as directed
Available for special circulation.	2	2	3	3	1
Other Establishments requesting work.	-	2	-	-	-
Private Parties paying for work.	-	-	-	-	2

**BEST
AVAILABLE COPY**

Identification Marks

Left Hand

A 27330 (new)
A 27330 (unserviceable)
A 27274 "

Right Hand

A 27304 (new)
A 27304 (unserviceable)
A 27273 "

Discussion

The steel was clean in all six specimens submitted. The non-metallics present were small and well separated. There were no segregation of inclusions near the pits. They, therefore, were not a contributing cause of the pitting.

The microstructure of all was martensite and troostite and the grain size was small. This indicates that the forging and heat treating temperatures were satisfactory. The variations in the amounts of martensite and troostite which differ somewhat from specimen to specimen, indicates that the method of quenching varied somewhat from piece to piece. This would cause variations in hardness. (No hardness determinations were made).

The structural differences in the individual specimens were not enough to cause pitting.

The appearance of the pitted portion is of repeated cycles of corrosion and light abrasions and not primarily of wear caused by being dug or janned by something hard, as no distorted crystals were found.

Examination of the pawls in storage at Watertown Arsenal showed no rusting or pitting. Some of these pawls were in the "as forged" condition and had just been received from the makers. Another lot were finished machined, heat treated, but unpolished. Another lot in storage considerably over a year were polished and were still bright. This indicates that with reasonable care the pawls should remain in serviceable condition for a long time.

Figure 1, is a photograph showing the pitted condition of the unserviceable pawls, together with new ones.

731-215

Figure 2, at X100, is an unetched section of pawl #A 27304. This is typical of all six. The non-metallics are small and well separated. MF-18

Figure 3, at X1000, etched with 1% Nital is a section of pawl #A 27304 taken at the bottom of one of the pits. No structural cause of the pitting is visible. This is typical of all the pawls submitted, except for the variations in the amounts of martensite and troostite. (Some of the specimens contained considerably more troostite.) MF-19

Respectfully submitted,

H. G. Carter

Figure 1
Photograph showing pitted
condition of the unservice-
able pawls, together with
new ones.

731-218




Figure 2

X100 unetched pawl #A 27304
Typical of all six. Non-
metallics are small and
well separated.

MF 18

Fuse Setter
Pawl
X100 MF 18

Figure 3

X1000 1% Nital, pawl #A 27304
bottom of one of the pits.
No distortion non-structural
cause of pitting. Typical
of all six except as to the
amount of martensite and
troostite.

MF 19

