



PHOTOGRAPH THIS SHEET

AD A951267

DTIC ACCESSION NUMBER



LEVEL



INVENTORY

WATERTOWN ARSENAL

Rept NO. P316/21-1
DOCUMENT IDENTIFICATION

This document has been approved
for public release and sale; its
distribution is unlimited.

DISTRIBUTION STATEMENT

ACCESSION FOR	
NTIS	GRA&I <input checked="" type="checkbox"/>
DTIC	TAB <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION	
(6 JUNE 1935)	
BY	
DISTRIBUTION /	
AVAILABILITY CODES	
DIST	AVAIL AND/OR SPECIAL
A	

Released

DTIC
ELECT
SEP 20 1981
E

DATE ACCESSIONED

DISTRIBUTION STAMP

UNANNOUNCED

81 9 08 175

DATE RECEIVED IN DTIC

PHOTOGRAPH THIS SHEET AND RETURN TO DTIC-DDA-2

Report No. P316/21-1
Watertown Arsenal

June 6, 1935

2nd Report on Gas Welded 18/8

Object

To make a metallographic study of gas welded 18/8.

Conclusions

The welding was of poor quality, considerable carbide pick up occurring and slight porosity being found. Cracks were also present. Heat treatment at 1950°F redissolved the precipitated carbides in the heat affected zone, but did not remove the carbides from the weld metal. The carbides in the weld metal were starting to diffuse into the metal. The weld metal would be liable to corrosion.

Material

Acetylene welded 18/8 sheet similar to that supplied for test described in report P316/21 was supplied in the form of an expansion joint.

The expansion joint was annealed at 1950°C for twenty minutes, pickled first electrolytically in an alkaline bath, then in an $\text{HCl} + \text{HNO}_3$ pickle bath at room temperature.

Metallographic Study

On Figures 1 and 2 are shown the structure of the welded joint. The weld tends to be porous near the surface. Small cracks are present. Considerable carbon pick up occurred. Carbides precipitated out in the heat affected zone about 1/2 cm from the weld.

Heat treatment redissolved the precipitated carbides and caused diffusion of the carbides in the weld metal to occur. The presence of these carbides in the weld would cause the weld to be liable to corrosion. To completely dissolve the carbides in the weld metal would require considerable time or higher temperatures which would be detrimental to the metal.

Respectfully submitted,

P. R. Kosting




Figure 1. Gas welded 18/8 sheet showing porosity in weld, carbides in weld metal (upper left MP42) penetrating original sheet metal, and carbide precipitation in heat affected zone.




Fig. 2. Same as Fig. 1 after 1950°F, 20 min. water quench. Carbides in weld diffusing into grains away from boundaries. Precipitated carbides in heat affected zone redissolved. Cracks are present in weld metal (MP34).