


PHOTOGRAPH THIS SHEET


AD A951459

DTIC ACCESSION NUMBER



LEVEL

Water town Arsenal Labs,  
MA



INVENTORY

Rept. No. 342/10

DOCUMENT IDENTIFICATION

7 Dec. 39


DISTRIBUTION STATEMENT A

Approved for public release.  
Distribution Unlimited

DISTRIBUTION STATEMENT

ACCESSION FOR	
NTIS	GRA&I <input checked="" type="checkbox"/>
DTIC	TAB <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION	
(7 Dec. 1939)	
BY	
DISTRIBUTION /	
AVAILABILITY CODES	
DIST	AVAIL AND/OR SPECIAL
A	

Released



DATE ACCESSIONED

DISTRIBUTION STAMP

UNANNOUNCED

81 9 23 254

DATE RECEIVED IN DTIC

PHOTOGRAPH THIS SHEET AND RETURN TO DTIC-DDA-2

Report No. 342/10  
Watertown Arsenal

December 7, 1939

BROKEN CLAMPS - HIGH FREQUENCY

5000 Lb. FURNACE - BLDG. 421

(Ex.O. 56)

Two clamps from the above furnace were submitted to ascertain the nature of failure and the quality of the brass composing the clamps. One clamp was badly covered with greenish salts (identified by laboratory as "C"), the other had only a small amount of corrosion deposit (identified by laboratory as "X").

Conclusions

1. Embrittlement was caused by strain corrosion by some corrosive agent.
2. Intergranular cracks (many) extended nearly two-thirds through the cross section of the clamp badly covered with corrosion deposits.
3. Intergranular cracks (few in number) extended nearly two-thirds through the cross section of the clamp which was only slightly covered by the corrosion deposits.
4. The brass was apparently of satisfactory quality - fairly clean, worked and annealed, (grain size about .045-.090 mm. A.S.T.M. Standard).


DISTRIBUTION STATEMENT A

Approved for public release;  
Distribution Unlimited

5. There was considerable evidence of strain in the clamps (presence of slip lines) which might have been produced when the clamps were formed.

6. The illustration is representative of the cracks found in both clamps.

Respectfully submitted,

  
H. G. Carter,  
Associate Metallurgist.



Typical Crack (Intergranular)