

AD-A995 328

~~SECRET~~ UNCLASSIFIED

WT-384
Copy 2 A

C. 210A
TECHNICAL LIBRARY
of the
DEFENSE NUCLEAR
AGENCY

JUL 29 1971

BUSTER


NEVADA PROVING GROUNDS
OCTOBER ^{UNCLASSIFIED} ~~NOVEMBER~~ 1951

By Authority of Joint DDP/DLE Review
CN
By DNA Ref IS (M) Date 23 Oct 1985
Project 3.8 By DOE Letter to DNA Date 22 June 1989

EFFECTS OF AN ATOMIC DETONATION
ON AIRCRAFT STRUCTURES ON THE GROUND

Classification (Cancelled) (Changed to SECRET)
By Authority of Chief Security Dec 17 1985
By J. [unclear] Date 5/2/85

REPRODUCTION FOR PUBLIC RELEASE;
UNCLASSIFIED
Under E.O. 11652, Dec 17 1951



~~SECRET~~
Atomic Energy Act 1954


ARMED FORCES SPECIAL WEAPONS PROJECT
WASHINGTON, D.C.

~~SECRET~~ UNCLASSIFIED B 3835
NOT CONTROLLED

Doc 5813

FC 01520384

210A



Deleted by FCS/D/A 2 Min

~~This document consists of 97 plus 4 pages (counting preliminary pages)~~

Copy 210 of 297 copies, Series A

OPERATION BUSTER

PROJECT 3.8

EFFECTS OF AN ATOMIC DETONATION ON
AIRCRAFT STRUCTURES ON THE GROUND

By

JOHN E. GILROY
1st Lt., USAF

With Appendix


by

RALPH E. PETERS


Edited by

LLOYD J. BREIDENBACH

January 1952

THIS DOCUMENT CONSISTS OF 97 PAGE(S) 
NO. 210 OF 297 COPIES, SERIES A

Aircraft Laboratory of the Aeronautics Division, Wright-Patterson
Air Force Base, Ohio



FC/01520384



Reproduced Direct from Manuscript Copy by
AEC Technical Information Service
Oak Ridge, Tennessee

FC 01520384

~~SECRET~~
Security Information

~~CONFIDENTIAL~~

ACKNOWLEDGMENTS

The authors wish to express their appreciation for the photographic support furnished by the Los Alamos Scientific Laboratory, and for the assistance of the University of Dayton in the preparation and assembling of the final report.

~~SECRET~~
Security Information

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

CONTENTS

ACKNOWLEDGMENTS iii

ILLUSTRATIONS vii

TABLES xi

ABSTRACT xii

CHAPTER 1 INTRODUCTION 1

 1.1 General 1

 1.2 Objective 1

CHAPTER 2 PROCEDURE 2

 2.1 General 2

 2.2 Location of Aircraft Relative to Ground Zero 2

 2.2.1 Location of B-17 for Dog Shot 2

 2.2.2 Location of F-47 for Dog Shot 2

 2.2.3 Location of B-17 for Easy Shot 2

 2.2.4 Location of F-47 for Easy Shot 3

 2.3 Instrumentation 3

CHAPTER 3 TEST RESULTS 7

 3.1 Dog Shot 7

 3.1.1 Fuselage Damage on B-17 7

 3.1.2 Wing Damage on B-17 7

 3.1.3 Empennage on B-17 7

 3.1.4 Fuselage Damage on F-47 (Dog Shot) 27

 3.1.5 Wing Damage on F-47 27

 3.1.6 Empennage on F-47 27

 3.1.7 Control Surfaces on F-47 27

 3.2 Easy Shot 27

 3.2.1 Fuselage Damage on B-17 (Easy Shot) 27

 3.2.2 Wing Damage on B-17 (Easy Shot) 37

 3.2.3 Empennage Damage B-17 (Easy Shot) 37

 3.2.4 Fuselage Damage on F-47 (Easy Shot) 37

 3.2.5 Wing Damage on F-47 (Easy Shot) 37

 3.2.6 Empennage Damage on F-47 (Easy Shot) 37

CHAPTER 4	DISCUSSION	47
4.1	General	47
4.2	Dog Shot	47
4.3	Easy Shot	47
CHAPTER 5	CONCLUSIONS AND RECOMMENDATIONS	49
5.1	Conclusions	49
5.1.1	Fighter Aircraft with Tail Toward Blast	49
5.1.2	Bomber Aircraft with Side Toward Blast	49
5.1.3	Bomber Aircraft with Nose Toward Blast	49
5.2	Recommendations	49
5.2.1	More Comprehensive Program	49
5.2.2	Sufficient Aircraft	49
5.2.3	Early Assignment of Aircraft	50
APPENDIX A	INSTRUMENTATION DETAILS	51

ILLUSTRATIONS

CHAPTER 2 PROCEDURE

2.1	Method of Towing B-17 from Yucca Lake Strip to Area T-7 with Tail Wheel on Flat-Bed Trailer	4
2.2	Method of Towing B-17 Showing Tow Cable from Trailer and Attachment to Main Gear	5
2.3	Condition of F-47 Prior to Exposure to Dog Shot	6

CHAPTER 3 TEST RESULTS

3.1	Typical Failure of B-17 Fuselage in Radio Operator's Compartment	8
3.2	Permanent Set in Aft Fuselage of B-17 as a Result of Side Loading During Dog Shot	9
3.3	Severe Buckle in Right Side of Fuselage of B-17 Following Dog Shot	10
3.4	View Looking Aft Showing Critical Buckle in Fuselage and Buckle in Dorsal Fin	11
3.5	Skin Buckles on the Forward Portion of the B-17 Fuselage on the Side Toward the Blast	12
3.6	Skin Buckles and Broken Window on Nose Section of B-17 on Side Toward the Blast	13
3.7	Skin Buckles on Nose Section of B-17 on Side Toward the Blast	14
3.8	Deep Buckle in Fuselage in Radio Operator's Compartment. Frame Members were Also Buckled	15
3.9	Skin Buckles on the Aft Portion of the B-17 Fuselage on the Side Toward the Blast	16
3.10	Interior View of Bomb Bay of B-17 Showing Buckle in Door and Also the Buckles in the Upper Portion of the Bulkhead as a Result of Dog Shot	17
3.11	Damage Incurred by Bomb-Bay Doors of B-17 on Dog Shot	18
3.12	Holes in Fuselage Produced by Waist Gun Window Fragments	19
3.13	Interior View of B-17 Cockpit Illustrating Thermal Damage to Fabric, Resulting from Dog Shot	20
3.14	Interior View of B-17 Cockpit Illustrating Thermal Damage to Fabric, Resulting from Dog Shot	21
3.15	Wing-to-Fuselage Fairing of B-17 Which was Torn Loose from the Fuselage Fasteners on Dog Shot	22
3.16	Condition of Surface of Left Wing Panel after Dog Shot	23

3.17	View Showing Thermal and Blast Damage to Rudder Following Dog Shot	21
3.18	View Showing Thermal and Blast Damage to Dorsal Fin Following Dog Shot	25
3.19	View Showing Thermal and Blast Damage to Vertical Stabilizer Following Dog Shot	26
3.20	Typical F-47 Flap Hinge Bracket Broken on Dog Shot	28
3.21	F-47 After Dog Shot with Damaged Control Surfaces Removed Prior to Easy Shot	29
3.22	General Condition of F-47 Fuselage After Dog Shot	30
3.23	Overall View of B-17 Illustrating Crushing of Nose Section and General Condition of Aircraft After Easy Shot	31
3.24	General Condition of F-47 Following Easy Shot. Note the Complete Failure of the Left Wing	32
3.25	Additional Damage to B-17 Fuselage Including Crushed Superstructure Aft of Cockpit Incurred During Easy Shot	33
3.26	Exterior View of Damaged Bomb-Bay Doors of B-17 After Easy Shot	34
3.27	Interior View of Buckled Bomb-Bay Door Showing Failed Structural Member	35
3.28	Buckles in Nose Section of B-17 Following Easy Shot	36
3.29	Skin Buckles in B-17 Outer Wing Panels	38
3.30	Condition of Vertical Tail of B-17 After Easy Shot As Seen From the Left Side Previously Incident to the Blast on Dog Shot	39
3.31	Condition of Right Side of Vertical Tail and Dorsal Fin of B-17 After Easy Shot	40
3.32	Fuselage Failure Aft of Cockpit in F-47 as a Result of Easy Shot	41
3.33	Fuselage Failure Aft of Cockpit in F-47 as a Result of Easy Shot	42
3.34	Failure of Left Wing of F-47 as a Result of Easy Shot	43
3.35	Damage Sustained by Right Wing Panel of F-47 During Easy Shot. Ailerons and Flaps Were Removed Prior to This Shot	44
3.36	Damage Sustained by Right Wing Panel of F-47 During Easy Shot. Ailerons and Flaps Were Removed Prior to This Shot	45
3.37	Empennage Damage Sustained by F-47 on Easy Shot. The Rudder and Elevators had Been Removed Prior to This Shot	46

CHAPTER 4 DISCUSSION

4.1 Location of Aircraft Relative to Ground Zero for Dog and Easy Shots 48

APPENDIX I INSTRUMENTATION DETAILS

A.1 Location of Instrumentation Chest In F-47 Cockpit After Removal of Control Stick, Rudder Pedals, and Instrument Panel. Chest Contains Accelerometer, Recording Oscillograph, Bridge Balance Unit, Battery, and Automatic Controls 53

A.2 Thin Skin Thermal Sensing Plate on F-47 Seat 54

A.3 Condition of Ground Mounted Instrument Chest (Large Box) with Thin Skin Thermal Sensing Plate on Top. Small Chest Contains Photo Cell Triggering Mechanism for Starting Recording Systems 55

A.4 Pressure Sensing Orifice on F-47 Fuselage 56

A.5 Schematic Diagram Showing Location of Aircraft Instrumentation 61

A.6 Schematic Diagram of Ground Installation 62

A.7 Schematic Diagram Showing General Location of Instruments 63

A.8 Buster Tests, Aircraft Instrumentation, Pressure vs Time, Channel No. 6 64

A.9 Buster Tests, Aircraft Instrumentation, Vertical Acceleration vs Time, Channel No. 5 65

A.10 Buster Tests, Aircraft Instrumentation, Vertical Acceleration vs Time, Channel No. 5 66

A.11 Buster Tests, Aircraft Instrumentation, Vertical Acceleration vs Time, Channel No. 2 67

A.12 Buster Tests, Aircraft Instrumentation, Vertical Acceleration vs Time, Channel No. 2 68

A.13 Buster Tests, Aircraft Instrumentation, Radial Acceleration vs Time, Channel No. 4 69

A.14 Buster Tests, Aircraft Instrumentation, Radial Acceleration vs Time, Channel No. 4 70

A.15 Buster Tests, Aircraft Instrumentation, Temperature vs Time, Channel No. 1 71

A.16 Buster Tests, Ground Instrumentation, Pressure vs Time, Channel No. 6 72

A.17 Buster Tests, Ground Instrumentation, Vertical Acceleration vs Time, Channel No. 5 73

A.18 Buster Tests, Ground Instrumentation, Vertical Acceleration vs Time, Channel No. 5 74

~~TOP SECRET~~


~~Security Information~~

A.19	Buster Tests, Ground Instrumentation, Vertical Acceleration vs Time, Channel No. 2	75
A.20	Buster Tests, Ground Instrumentation, Vertical Acceleration vs Time, Channel No. 2	76
A.21	Buster Tests, Ground Instrumentation, Radial Acceleration vs Time, Channel No. 4	77
A.22	Buster Tests, Ground Instrumentation, Radial Acceleration vs Time, Channel No. 4	78
A.23	Buster Tests, Ground Instrumentation, Temperature vs Time, Channel No. 1	79

~~TOP SECRET~~

~~TOP SECRET~~
ATOMIC ENERGY ACT 1946


~~TOP SECRET~~
Security Information



TABLE

APPENDIX A INSTRUMENTATION DETAILS

A.I Tabulation of Instrumentation Results 30



ABSTRACT

The objective of Project 3.8 is to determine the effects of an atomic detonation on parked aircraft with respect to structural damage.

The two aircraft allotted to this project were flown to Yucca Lake landing strip and then moved overland to the test location.

For Dog Shot, the fighter (F-47) was positioned with tail toward the blast at a ground range of 4,250 feet from the target ground zero. The bomber (B-17) was located with the left side toward the blast at a ground range of 6,310 feet from the target ground zero. Damage to the fighter from Dog Shot was confined primarily to the control surfaces, whereas damage to the bomber included a severe fuselage buckle aft of the wing, burning of the rudder fabric, and extensive local skin damage.

The aircraft were relocated for Easy Shot. The fighter was positioned with the tail toward the blast at a ground range of 2,675 feet. The bomber was placed with the nose toward ground zero at a range of 5,847 feet. The fighter was severely damaged, one wing failing completely. The bomber sustained additional damage to skin panels, and the bomb-bay doors were buckled inward.

CHAPTER 1

INTRODUCTION

1.1 GENERAL

Prior to Operation BUSTER very little data was available on the effects of an atomic detonation on aircraft parked on the ground although aircraft structural components were exposed on Operation CROSSROADS and on Operation GREENHOUSE. Information is required on the effects on complete aircraft parked on the ground to implement vulnerability studies.

1.2 OBJECTIVE

The objective of Project 3.8 is to determine the effects of an atomic detonation on parked aircraft with respect to structural damage from thermal and blast energy, and also to demonstrate the feasibility of cross-country movement of test aircraft from the Yucca Lake landing strip to the test location.

CHAPTER 2

PROCEDURE

2.1 GENERAL

Since aircraft structures are designed to different load factors, at least two types of test vehicle are required, one in the bomber category and one in the fighter category. Whereas initially five four-engine bombers (B-17) and four single-engine fighters (three F-47 and one F-80) were requested, the project finalized with one B-17 and one F-47 assigned for test purposes. The aircraft were flown to the Yucca Lake landing strip and then were transported overland to the test positions.

2.2 LOCATION OF AIRCRAFT RELATIVE TO GROUND ZERO

The aircraft were placed at specific ranges from ground zero based on predicted overpressures for Dog Shot and then moved to new positions for Easy Shot. The method of towing the B-17 is shown in Fig. 2.1 and Fig. 2.2. The F-47 was carried on top of the flat-bed trailer with the main gear straddling the bed.

2.2.1 Location of B-17 for Dog Shot

Prior to Dog Shot, the B-17 was positioned on the natural terrain with the left side toward ground zero at a ground range of 6,310 feet on a true bearing of South $0^{\circ} 57'$ West.

2.2.2 Location of F-47 for Dog Shot

The F-47 was placed at a ground range of 4,250 feet from the target ground zero on a true bearing of North $85^{\circ} 58'$ East with the tail of the aircraft toward the blast. The condition of the F-47 as received is shown in Fig. 2.3.

2.2.3 Location of B-17 for Easy Shot

The B-17 was relocated for Easy Shot at a ground range of 5,47 feet on a true bearing of South $7^{\circ} 19'$ East and oriented with the nose toward ground zero.

2.2.4 Location of F-47 for Easy Shot

The F-47 was relocated for Easy Shot at a ground range of 2,675 feet on a true bearing of 0 East and oriented with the tail toward ground zero.

2.3 INSTRUMENTATION

Instrumentation utilized on the project consisted of two oscillograph recorders, one mounted in the fighter cockpit and the other buried in the ground beside the aircraft. These instruments were employed to determine the feasibility of similar installations for future test programs. A more detailed discussion of the instrumentation is included in Appendix A.




Fig. 2.1 Method of Towing B-17 from Yucca Lake Strip to Area T-7 with Tail Wheel on Flat-Bed Trailer

RESTRICTED DATA

ATOMIC ENERGY ACTING

Security Information




Fig. 2.2 Method of Towing B-17 Showing Tow Cable from Trailer and Attachment to Main Gear




Fig. 2.3 Condition of F-47 Prior to Exposure to Dog Shot

[REDACTED]

CHAPTER 3

TEST RESULTS

3.1 DOG SHOT

The damage incurred by the B-17 as a result of the Dog Shot exposure was quite severe, the aircraft being rendered useless prior to extensive repairs including replacement of major components. The F-47 suffered loss of all the control surfaces and their attachment fittings.

3.1.1 Fuselage Damage on B-17

Due to the side-on orientation of the B-17, the fuselage was highly stressed in bending and in torsion produced by the load on the vertical tail, with a buckling failure occurring aft of the wing, in the radio operators compartment. Fig. 3.1 shows typical failure of stringers and frame members where broken on both sides of the fuselage. Fig. 3.2 shows the permanent set (clockwise) in the fuselage aft section, and Figs. 3.3 and 3.4 show details of buckled fuselage. Many of the skin panels were dished in on the side toward the blast as shown in Figs. 3.5 through 3.9. The bomb-bay doors were buckled inward, and some of the door stiffeners were ruptured. Figs. 3.10 and 3.11 show the external and interior views of the bomb-bay doors. A majority of the windows were broken and some of the acrylic fragments from the waist gun window on the left side were blown through the fuselage skin on the opposite side producing the results shown in Fig. 3.12. Paint was blistered or scorched where exposed to the incident thermal energy. Fabric in the cockpit was burned or charred. Although the fire did not propagate or reach a serious magnitude, the hazards of thermal ignition are apparent. Figs. 3.13 and 3.14 show some results of thermal damage in cockpit fabric.

3.1.2 Wing Damage on B-17

The B-17 wing appeared relatively free of damage except for the wing-to-fuselage fairing on the left side which tore loose from the rivets, as shown in Fig. 3.15. The condition of the left outer-wing panel is portrayed in Fig. 3.16.

3.1.3 Empennage

The dorsal fin, vertical stabilizer, and the rudder were severely damaged. The rudder fabric was completely burned except for the lower two panels. Dishing of the skin on the vertical fin and the dorsal fin was extensive. Paint was scorched and blistered with the red paint appearing more severely effected than the black paint in the same region. The combined effects of thermal and blast damage are shown in Figs. 3.17 through 3.19.




Fig. 3.1 Typical Failure of B-17 Fuselage in Radio Operator's Compartment



Fig. 3.2 Permanent Set in Aft Fuselage of B-17 as a Result of Side Loading During Dog Shot

~~Security Information~~

~~Security Information~~




Fig. 3.3 Severe Buckle in Right Side of Fuselage of R-17 Following Dog Shot

~~Security Information~~

ATA
ATOMIC ENERGY ACT 1946

~~Security Information~~




Fig. 3.5 Skin Buckles on the Forward Portion of the B-17 Fuselage on the Side
Toward the Blast



PROJECT MODEL
U.S. ARMY BIRTH-1000
ALSO FORCE SP-1000-1000
C/W No 1000 1200 LBS.
1000 1000 1000 1000
1000 1000 1000 1000

LBAG99

Fig. 3.6 Skin Buckles and Broken Window on Nose Section of B-17 on the Side Toward the Blast



Fig. 3.7 Skin Buckles on Nose Section of B-17 on the Side Toward the Blast



Fig. 3.8 Deep Buckle in Fuselage in Radio Operator's Compartment. Frame members were also buckled.




Fig. 3.9 Skin Buckles on Aft Portion of the B-17 Fueslage on the Side Toward the Blast

~~CONFIDENTIAL~~




Fig. 3.10 Interior View of Bomb Bay of B-17 Showing Buckle in Door and Also the Buckles in the Upper Portion of the Bulkhead as a Result of Dog Shot

~~CONFIDENTIAL~~

~~Security Information~~

~~CONFIDENTIAL~~




Fig. 3.11 Damage Incurred by Bomb-Bay Doors of B-17 on Dog Shot




Fig. 3.12 Holes in Fuselage Produced by Waist-Gun Window Fragments




Fig. 3.13 Interior View of B-17 Cockpit Illustrating Thermal Damage to Fabric Resulting from Dog Shot




Fig. 3.14 Interior View of B-17 Cockpit Illustrating Thermal Damage to Fabric Resulting from Dog Shot



Fig. 3.15 Wing-to-Fuselage Fairing of B-17 Which Was Torn Loose from the Fuselage Fasteners on Dog Shot

APR 1946
CONFIDENTIAL



Fig. 3.16 Condition of Surface of Left Wing Panel After Dog Shot



Fig. 3.17 View Showing Thermal and Blast Damage to Rudder Following Dog Shot



Fig. 3.18 View Showing Thermal and Blast Damage to Dorsal Fin Following Dc₂ Shot



Fig. 3.19 View Showing Thermal and Blast Damage to Vertical Stabilizer Following Dog Shot

3.1.4 Fuselage Damage on F-47 (Dog Shot)

The F-47 was oriented favorably to reduce damage to the fuselage and no major damage was apparent. Only slight dishing of several skin panels was observed. The canopy was intact.

3.1.5 Wing Damage on F-47

The main-wing structure was not noticeably damaged, however, the ailerons and flaps together with their attaching brackets were rendered useless and would require replacement. See Fig. 3.20 for details of broken hinge brackets. The left aileron was found 120 feet "downwind" from the aircraft.

3.1.6 Empennage on F-47

The elevators and rudder were damaged beyond repair, however, the vertical and horizontal stabilizers were not substantially damaged.

3.1.7 Control Surfaces on F-47

The damaged control surfaces were removed from the aircraft in preparation for Easy Shot resulting in the configuration shown in Figs. 3.21 and 3.22.

3.2 EASY SHOT

Since both aircraft were damaged previously on Dog Shot, the results obtained after Easy Shot were accumulative. The orientation of the B-17 was changed to have the nose toward the blast but the F-47 was maintained with the tail toward ground zero. The damage to the B-17 included dishing in of the unsupported skin panels, caving in bomb-bay doors, and thermal and pressure damage to the "chin" radome. The damage to the F-47 was extensive, the fuselage and one wing being broken. The general condition of the B-17 is shown in Fig. 3.23, and that of the F-47 in Fig. 3.24.

3.2.1 Fuselage Damage on B-17 (Easy Shot)

The fuselage damage incurred by the B-17 during Dog Shot was made progressively worse by Easy Shot. The fuselage superstructure aft of the cockpit was crushed as may be seen in Fig. 3.25. The bomb-bay doors were blown into the bomb bay, one of the heavier structural members of the door being completely ruptured. Details of the damage are shown in Figs. 3.26 and 3.27. The wing-to-fuselage fairing received additional damage. The left side of the nose was caved in and the escape hatch buckled inward. Details of this section are shown in Fig. 3.28.



Fig. 3.20 Typical F-47 Flap Hinge Bracket Broken on Dog Shot




Fig. 3.21 F-47 After Dog Shot with Damaged Control Surfaces Removed Prior to Easy Shot

ATC



Fig. 3.22 General Condition of F-47 Fuselage After Dog Shot




Fig. 3.23 Overall View of B-17 Illustrating Crushing of Nose Section and General Condition of Aircraft After Easy Shot



Fig. 3.24 General Condition of F-47 Following Easy Shot. Note the complete failure of the left wing.




Fig. 3.25 Additional Damage to B-17 Fuselage Including Crushed Superstructure Aft of Cockpit Incurred During Easy Shot




FIG. 3.26 Exterior View of Damaged Bomb-Bay Doors of B-17 After Easy Shot

1946 G. O. ... on




Fig. 3.27 Interior View of Buckled Bomb-Bay Door Showing Failed Structural Member



Fig. 3.28 Buckles in Nose Section of B-17 Following Easy Shot

3.2.2 Wing Damage on B-17 (Easy Shot)

Large areas of the wing skin were dished in as shown in Fig. 3.29. All small access doors were found open along the lower surface of the wing.

3.2.3 Empennage Damage B-17 (Easy Shot)

The elevator fabric was ruptured at several places. The dorsal fin and vertical stabilizer were crushed to a greater extent than on Dog Shot. Figs. 3.30 and 3.31 indicate the condition of the vertical tail following Easy Shot.

3.2.4 Fuselage Damage on F-47 (Easy Shot)

The fuselage of the F-47 sustained a structural failure aft of the cockpit. A portion of this failure is shown in Figs. 3.32 and 3.33. It appeared that considerable sand blasting had damaged one side of the fuselage. The canopy was destroyed. The propeller had the blades bent, probably due to contact with the ground during the blast phase.

3.2.5 Wing Damage on F-47 (Easy Shot)

The left wing panel was completely failed. Details of the failure are shown in Fig. 3.34. Sand-blasting effects were also evident. The skin over substantial areas of the upper surface of the outer-wing sections was missing. Figs. 3.35 and 3.36 portray the general condition of the right outer-wing panel. The gun-bay door was buckled. Sand-blast effects were more severe on the right hand wing, but the structural frame was practically intact.

3.2.6 Empennage Damage on F-47 (Easy Shot)

The skin on the upper surface of the horizontal stabilizer was removed by the thermal and blast effects except for small sections of skin immediately over the structural frame. The skin on the vertical stabilizer was essentially intact but showed the effects of some sand and debris blasting, however, the vertical tail was failed at the root section. The damaged tail section is shown in Fig. 3.37.



Fig. 3.29 Skin Buckles in B-17 Outer Wing Panels




Fig. 3.30 Condition of Vertical Tail of B-17 After Easy Shot as Seen from the Left Side Previously Incident to the Blast on Dog Shot




Fig. 3.31 Condition of Right Side of Vertical Tail and Dorsal Fin
of B-17 After Easy Shot



Fig. 3.32 Fuselage Failure Aft of Cockpit in F-47 as a Result of Easy Shot




Fig. 3.33 Fuselage Failure Aft of Cockpit in F-47 as a Result of Easy Shot




Fig. 3.34 Failure of Left Wing of F-47 as a Result of Easy Shot




Fig. 3.35 Damage Sustained by Right Wing Panel of F-47 During Easy Shot. Ailerons and flaps were removed prior to this shot.



Fig. 3.36 Damage Sustained by Right Wing Panel of F-47 During Easy Shot. Ailerons and flaps were removed prior to this shot.

[REDACTED]

[REDACTED]

[REDACTED]



Fig. 3.37 Empennage Damage Sustained by F-47 on Easy Shot. The rudder and elevators had been removed prior to this shot.

CHAPTER 4

DISCUSSION

4.1 GENERAL

The aircraft were positioned at specific ranges determined by the estimated overpressures, the B-17 at 3 psi and the F-47 at 6 psi. [The data available prior to the BUSTER operation indicated that for a 25 KT bomb an overpressure of 3 psi would be realized at approximately 6,300 feet and 6 psi would be realized in the vicinity of 4,250 feet.] The aircraft were positioned accordingly, as shown in Fig. 4.1.

4.2 DOG SHOT

[Results of Project 3.8 instrumentation indicated that an overpressure of 4.9 psi was experienced by the F-47 at 4,250 feet.] Overpressure data was not obtained from other agencies for Dog Shot reportedly due to malfunction of equipment, hence no correlation is possible. Overpressures were not measured at the B-17 but it is estimated that at 6,300 feet the peak overpressure was about 3.1 psi. Details of Project 3.8 instrumentation procedures and results are included in Appendix A. Both aircraft sustained sufficient damage to prevent flight missions prior to making repairs.

4.3 EASY SHOT

[On Easy Shot, the F-47 at 2,675 feet from ground zero was subjected to about 7.7 psi and the B-17 at 5,347 feet sustained a peak overpressure of about 4.1 psi according to data supplied from other agencies.] The Project 3.8 instrumentation data was not obtained on Easy Shot due to failure of lamp filaments in the recording oscillographs. The F-47 was destroyed with complete failure of the left wing, a severe failure of the fuselage near the mid-section, and a failure at the base of the vertical stabilizer in addition to extensive local skin and frame damage. The B-17 was oriented nose in which is a favorable position to reduce damage to most of the structure with the exception of the bomb-bay doors, however, local skin buckles were produced over the entire airframe during Easy Shot. The opening of all the small inspection doors on the wing was previously experienced at a considerably lower overpressure on Operation GREENHOUSE, as was the sensitivity of bomb-bay doors to damage at low overpressure. The locations of the aircraft relative to ground zero for Dog and Easy Shots are shown in Fig. 4.1.




Fig. 4.1 Location of Aircraft Relative to Ground Zero for Dog and Easy Shots

CHAPTER 5

CONCLUSIONS AND RECOMMENDATIONS

5.1 CONCLUSIONS

The following conclusions are based upon singular data as obtained from one fighter-type and one bomber-type aircraft.

5.1.1 Fighter Aircraft with Tail Toward Blast

Fighter aircraft, as represented by the F-47, exposed directly to an atomic detonation with the tail toward the blast will be rendered unflyable in overpressure regions of 4.9 psi or higher.

5.1.2 Bomber Aircraft with Side Toward Blast

Bomber aircraft, as represented by the B-17, exposed directly to an atomic detonation with the side toward the blast will be severely damaged and rendered unsafe for flight in overpressure regions of 3.1 or higher.

5.1.3 Bomber Aircraft with Nose Toward Blast

Bomber aircraft (B-17 type) oriented with the nose toward the blast will sustain skin buckles and some frame buckles at over-pressures of 4.1 psi or higher.

5.2 RECOMMENDATIONS

5.2.1 More Comprehensive Program

It is recommended that a more comprehensive program be initiated to determine on a statistical basis the vulnerability of parked aircraft to an atomic detonation.

5.2.2 Sufficient Aircraft

It is recommended that sufficient aircraft be allocated to the parked-aircraft-vulnerability program to investigate several parameters simultaneously, these parameters to include several peak overpressures, various aircraft orientations, and the effect of passive-defense measures.

[REDACTED]

5.2.3 Early Assignment of Aircraft

It is recommended that the aircraft for any future program be assigned at the earliest possible date to permit adequate planning and instrumentation work.

[REDACTED]

APPENDIX A

OSCILLOGRAPHIC-TYPE RECORDING IN
THE PRESENCE OF ATOMIC EXPLOSIONS
(UNCLASSIFIED)

A.1 PURPOSE

To study the feasibility of using oscillographic-type recording instrumentation for obtaining data on aircraft structures and structural components in the vicinity of atomic explosions and to measure certain kinetic effects on an F-47 aircraft.

A.2 FACTUAL DATA

The information reported herein was obtained from Dog and Easy shots Operations BUSTER as part of Project 5.8. The sensing and recording of the required information was accomplished by using resistance type acceleration, pressure, and temperature transmitters, multi-channel Heiland oscillograph, Nosker bridge balance units, and appropriate connecting circuits. Variations in the quantities to be measured affected the gages and produced a proportional electrical unbalance in the bridge circuit of the gage. The amount of unbalance of each gage bridge circuit was measured by the deflection of a D'Arsonval type galvanometer connected across the output terminals of the circuit. The deflection of each galvanometer was recorded simultaneously on moving photo-sensitivie paper by the camera section of the oscillograph. Timing marks every one hundredth (0.01) second were also photographed on the edge of the paper to provide a time reference for the recorded data.

The component parts of the system were calibrated by subjecting the gages to representative values of their specific functions while the gages were properly connected through the balancing controls of the oscillograph. The oscillograph trace deflections were then compared to the corresponding applied loads to obtain a calibration factor based on the amount of applied loads required per inch of trace deflection. This was accomplished for each gage-galvanometer combination used on the test.

[REDACTED]

For the purpose of this study it was necessary to prepare instrumentation for two installations. The first, an installation in the cockpit of an F-47, was used to sense and record local pressure, temperature and accelerations, with the aircraft on the ground during the tests (See Fig. A.1, A.2, and A.3). The second, an installation in the ground, was used to sense and record similar local data (See Fig. A.4). The oscillograph, oscillograph battery and the bridge balance unit used in each installation referred to above were shock mounted in a steel box in order to prevent damage from accelerations resulting from the test explosion. In each installation two Statham accelerometers were used to measure the vertical acceleration during the test, one accelerometer was mounted on the oscillograph and a second was mounted on the steel box. A third Statham accelerometer was used to measure the horizontal radial acceleration, or acceleration which occurs along a radius through ground zero for the test.

Aluminum sheets (.020-24ST) with the upper surface finished a dull black and a transonic temperature transmitter fixed to the underside were used to measure the temperatures during the tests. Pressure transmitters which had a fifteen (15) pound per square inch range were used to measure the test pressures.

Due to the different requirements of the two installations, the location of the temperature plates and the pressure pick-ups relative to the oscillograph were different. The exact location of these sensing units are covered in paragraphs 10 and 12.

The galvanometer deflection for any given bridge unbalance is directly proportional to the bridge voltage, therefore the voltage of each bridge balance unit was recorded during the test.

In order to actuate the instrumentation at the exact time the test started two Edgerton, Germeshausen and Gier, Type A-2 Blue Boxes were used. The type A-2 Blue Box contains a 929 photo-tube (V 101) with a 4.7 megohm cathode load resistor which is coupled with a 2D21 gas-filled thyatron (V 102). The thyatron is normally non-conducting but is energized by an abrupt rising, light pulse of sufficient intensity which strikes the cathode of the 929 photo-tube. The relay closes within two (2) milliseconds after the light pulse and remains closed until after the reset button is manually pressed. The power was supplied to the Blue Box by a 115 volt, AC, four hundred (400) cycle inverter.




Fig. A.1 Location of Instrumentation Chest in F-47 Cockpit After Removal of Control Stick, Rudder Pedals, and Instrument Panel. Chest contains accelerometer, recording oscillograph, bridge balance unit, battery, and automatic controls.




FIG. A.2 Thin Skin Thermal Sensing Plate on F-47 Seat

1946




Fig. A.3 Condition of Ground Mounted Instrument Chest (Large Box) with Thin Skin Thermal Sensing Plate on Top. Small chest contains photo cell triggering mechanism for starting recording systems.





Fig. A.4 Pressure Sensing Orifice on F-47 Fuselage



It was necessary to provide a warm up period for the bridge balance units and the Blue Boxes. This was accomplished in each installation by using a 24 Volt timer switch which was operated by a standard aircraft battery. At approximately H - 12 hours the clock for the timer switch was started, and the timer switch was not to trip the Blue Box warm-up relays and turn on the bridge voltages thirty minutes before H hour. The light output of the test explosion actuated the Blue Box which started the recording mechanism.

At the Nevada test site the rudder controls, suit heater, control stick and supporting castings, instrument panel and all adjoining panels were removed from the cockpit of the F-47 Serial No. 44-2566. This was necessary for the purpose of installing the instrumentation in the aircraft. The steel box containing the oscillograph, oscillograph battery and bridge balance unit was secured immediately forward of the pilots seat on the cockpit floor Fig. A.1. It was located in such a way that the longitudinal axis or the optical axis of the oscillograph paralleled the longitudinal axis of the aircraft. Positioning the oscillograph in such a manner was necessary in order to have minimum side accelerations acting on the galvanometers during the tests. The temperature panel was located four (4) inches above the bottom of the pilots' seat, parallel to the ground. The pressure transmitter for this installation was located on the right side of the fuselage just ahead of pilots compartment, Fig. A.5. The Blue Box timing switch inverter and battery were buried in the ground next to the aircraft figure A.7, and the Blue Box window was directed at the initial point of the test or the point at which the weapon was detonated.

The connection cable from the Blue Box to the Aircraft instrumentation was long enough to allow for a thirty (30) foot movement of the aircraft. In order to prevent the insulation from burning off of the cable due to the initial radiant heat of the explosion, all lead-in wires were protected by either being buried in the ground or wrapped with aluminum foil.

The steel box, containing the oscillograph, and the component parts for the second installation was buried in the ground ten (10) feet off the right wing tip of the F-47 aircraft, figure A.7. The top of the box was exposed and at ground level with the longitudinal axis of the oscillograph along a radius through ground zero, or the ground point directly below the initial point of the test. The temperature panel was mounted on the exposed surface of the box

furthest from the ground zero, and the source for the pressure transmitter was located on the exposed surface of the box closest to ground zero. For this installation the Blue Box, timer switch, inverter and battery were placed five (5) feet from the oscillograph box with the Blue Box window directed at the initial point of the test, Figure A.6. All connecting wires in this installation were buried to prevent heat damage to the insulation.

During the test no additional precautions were taken to prevent any radiation from affecting the photo-sensitive paper used for recording. Shielding with lead sheet or concrete were purposely omitted so that the radiation effects could be studied.

Due to the operational limitations it was necessary to install all instrumentation approximately twelve (12) hours before H hour. At this time the final operational check of the instrumentation was made and a zero record was taken for the test.

The first of the two (2) atomic explosions during which measurements were taken, was a 20.9 KT weapon. For this test the aircraft and ground instrumentation were four thousand, two hundred and fifty (4250) feet from ground zero. This distance was theoretically selected to give a six (6) pound per square inch over-pressure.

The peak values recorded for this test for all measured quantities are listed below for each of the installations

Quantities	Aircraft Inst. Value	Ground Inst. Value	Response of Pick-up
Overpressure (psi)	4.92	4.82	Good
Vertical Acc.Box (G)	5.2 to-8	9 to-22.75	Fair
Vertical Acc.Osc. (G)	7.9 to-2.4	3.9 to-.85	Fair
Radial Acc. Box (G)	3.4 to-2.9	.44 to-.28	Fair
Temperatures (°F)	92°	220	Good

The figure numbers above refer to graphs on which the input and response are plotted versus time.

The ground shock had no apparent influence upon the galvanometer response; however, the air shock had a definite effect upon the galvanometer recording. The galvanometer response to air shock could not be separated from the actual accelerations encountered, and there is possibly a fourteen percent (14%) error at the peak

reading for the pressure recorded on the aircraft. From the pressure time plot, Figure A.8, it is noted that there is an abrupt change in the slope at four (4) pound per square inch and at four and two tenths (4.2) pounds per square inch on the increasing portion of the curve and a similar change at the same values on the decreasing portion. These changes of slope give evidence to the possibility that air shock could be responsible for this final peak. The ground installation does not show a similar condition for the pressure record. The reason for this is undetermined.

The temperature measurement for the ground installation showed good response and the effect of air shock could be separated from the actual temperature successfully. The temperature recorded in the aircraft was of much smaller magnitude than that of the ground installation because of shielding from the direct radiation of the weapon. The ground installation temperature record showed a lag to the first peak of one (1.0) second and a lag to the second and largest peak of two and sixty five hundredth (2.65) seconds, Figure A.25.

The radiation emanating from the test explosion was also of definite concern for its effect upon the photo-sensitive paper, caused a considerable fogging or graying. The radiation effects of the first test did not seriously impair accurate reading and interpretation of the record.

The test explosion had no physical effect upon the instrumentation itself except that the filter windows of the Blue Boxes were broken. This damage did not effect normal operation and the Blue Boxes were used successfully on the last test.

The second of the two (2) atomic test explosions during which measurements were taken was a 31.25 KT weapon and for this test the aircraft and ground instrumentation was two thousand, six hundred and seventy five (2675) feet from ground zero. This position was selected theoretically to give a fifteen (15) pound per square inch overpressure.

The galvanometer lamp in each installation burned out at some undetermined time after a zero record was taken, so no information was acquired other than radiation effects. Since there were no traces on the exposed record it is not possible to determine whether the amount of fogging obtained was severe enough to seriously impair reading and interpretation.

[REDACTED]

During this test the extreme heat melted approximately half of the temperature plate of the ground installation, other than this no other physical damage was done.

All the results of the test and some of the specific recommendations are found in tabular form in Table I.

A.3 CONCLUSIONS:

The radiation emitted from the test weapon had very definite effect on the photo-sensitive paper used in the recording oscillograph. It caused considerable fogging or graying and caused difficulty in reading and interpretation.

The galvanometers showed a noticeable response to air shock, which had a definite effect upon the acceleration readings and it could not be separated from the actual test accelerations. There is a possible error at the peak pressure readings for the aircraft instrumentation. The temperature readings could be faired through the galvanometer response and good response was obtained from the temperature pick-ups.

The radiant heat accompanying Easy Shot was sufficient to melt approximately half of the temperature plate of the ground installation.

A.4 RECOMMENDATIONS:

It is recommended that:

The oscillographic-type instrumentation as described be considered for use under conditions of the first range and KT combination or similar combinations emitting equal radiation.

Lead shielding be used, or the recording instrumentation be placed in a concrete black house when the instrumentation is operated at a shorter range.

Future tests be conducted to determine response of galvanometer to rapid pressure and temperature changes, in order to determine transient effects on the recorded data.

All recording instrumentation should be surrounded by sound proof, shock absorbing material, in a box which is securely fixed to the ground. Lead masses should be used to deaden the vibrations of flat surfaces and accelerometers.





Fig. A.5 Schematic Diagram Showing Location of Aircraft Instrumentation



NOTE: ALL CONNECTING
WIRES IN THIS INSTALLATION
WERE ROUTED BELOW GROUND
LEVEL.

Fig. A.6 Schematic Diagram of Ground Installation




Fig. A.7 Schematic Diagram Showing General Location of Instruments




Fig. A.8 Aircraft Instrumentation Pressure vs. Time




Fig. A.9 Aircraft Instrumentation Vertical Acceleration vs. Time




Fig. A.10 Aircraft Instrumentation Vertical Acceleration vs. Time




Fig. A.11 Aircraft Instrumentation Vertical Acceleration vs. Time




Fig. A.12 Aircraft Instrumentation Vertical Acceleration vs. Time




Fig. A.13 Aircraft Instrumentation Radial Acceleration vs. Time




Fig. A.14 Aircraft Instrumentation Radial Acceleration vs. Time




Fig. A.15 Aircraft Instrumentation Temperature vs Time




Fig. A.16 Ground Instrumentation Pressure vs. Time




Fig. A.17 Ground Instrumentation
Vertical Acceleration vs Time

Fig. A.17 Ground Instrumentation Vertical Acceleration vs. Time




Fig. A.18 Ground Instrumentation Vertical Acceleration vs. Time




Fig. A.19 Ground Instrumentation Vertical Acceleration vs. Time




Fig. A.20 Ground Instrumentation Vertical Acceleration vs. Time




Fig. A.21 Ground Instrumentation Radial Acceleration vs. Time




Fig. A.22 Ground Instrumentation Radial Acceleration vs. Time




Fig. A.23 Ground Instrumentation Temperature vs. Time

TABLE A.1

Tabulation of Results and Some Conclusions

	Paper Exposure	Galvanometer Response to Ground Shock	Galvanometer Response to Air Shock	Accelerometer Response	Pressure Response	Temperature Response*	Correction for Exposure	Correction for Ground Acceleration	Correction for Air Acceleration
Dog Shot 20.9 KT Ground Range 4240 Slant Range 4350	Fogged but readable	None	Noticeable, definite effect on acceleration readings, these effects could not be separated from actual accelerations. Possibly 1/4 error at peak reading of pressure on aircraft	Possibly as high as 8 G's on oscillograph in the aircraft and possibly as high as 4 G's on oscillograph in ground	Good over pressure 5 psi	Record good lag to 1st peak 1. sec. to second 2.65 sec. (Major peak)	Use under conditions of first range. Wrap installation with lead foil. Concrete block house will offer additional protection	None required	Rigid mountings of box to ground surrounding box with sound shock absorbing material deaden flat surfaces and accelerometers with lead plate Lead serves a dual purpose. Also adds protection from radiation effects
Easy Shot 31.25 Ground Range 2672 Slant Range 2980	Fogged badly. May have been readable if galvanometer light had not burned out				All other effects unknown				

*Temperature readings could be faked through galvanometer response

DISTRIBUTION

Copy No.

ARMY ACTIVITIES

Asst. Chief of Staff, G-1, Department of the Army, Washington 25, D. C.	1
Asst. Chief of Staff, G-2, Department of the Army, Washington 25, D. C.	2
Asst. Chief of Staff, G-3, Department of the Army, Washington 25, D. C.	3- 6
Asst. Chief of Staff, G-4, Department of the Army, Washington 25, D. C.	7- 11
Chief of Ordnance, Department of the Army, Washington 25, D. C.	12- 14
Chief Chemical Officer, Temp. Bldg. T-7, Room G-522, Gravelly Point, Va.	15- 18
Chief of Engineers, Temp. Bldg. T-7, Room G-425, Gravelly Point, Va.	19- 21
The Quartermaster General, Second and T Sts. SW, Room 1139A, Washington 25, D. C.	22- 26
Chief of Transportation, Temp. Bldg, T-7, Room G-816, Gravelly Point, Va.	27- 28
Chief Signal Officer, Department of the Army, Washington 25, D. C.	29- 31
The Surgeon General, Main Navy Bldg., Room 1651, Washington 25, D. C.	32- 34
Provost Marshal General, Main Navy Bldg., Room 1065, Washington 25, D. C.	35- 37
Chief, Army Field Forces, Fort Monroe, Va.	38- 41
President, Army Field Forces Board No. 1, Fort Bragg, N. C.	42
President, Army Field Forces Board No. 2, Fort Knox, Ky.	43
President, Army Field Forces Board No. 3, Fort Benning, Ga.	44
President, Army Field Forces Board No. 4, Fort Bliss, Tex.	45
Commandant, The Infantry School, Fort Benning, Ga.	46- 47
Commandant, The Armored School, Fort Knox, Ky.	48- 49
President, The Artillery School Board, Fort Sill, Okla.	50- 51
Commandant, The AA&GM Branch, The Artillery School, Fort Bliss, Tex.	52- 53
Commandant, Army War College, Carlisle Barracks, Pa.	54- 55
Commandant, Command and General Staff College, Fort Leaven- worth, Kans.	56- 57
Commandant, Army General School, Fort Riley, Kans.	58

DISTRIBUTION (Continued)

	Copy No.
Commanding General, First Army, Governor's Island, New York 4, N. Y.	59- 60
Commanding General, Second Army, Fort George G. Meade, Md.	61- 62
Commanding General, Third Army, Fort McPherson, Ga.	63- 64
Commanding General, Fourth Army, Fort Sam Houston, Tex.	65- 66
Commanding General, Fifth Army, 1660 E. Hyde Park Blvd., Chicago 15, Ill.	67- 68
Commanding General, Sixth Army, Presidio of San Francisco, Calif.	69- 70
Commander-in-Chief, European Command, APO 403, c/o Postmaster, New York, N. Y.	71- 72
Commander-in-Chief, Far East, APO 500, c/o Postmaster, San Francisco, Calif.	73- 74
Commanding General, U. S. Army, Pacific, APO 958, c/o Postmaster, San Francisco, Calif.	75- 76
Commanding General, U. S. Army, Caribbean, APO 834, c/o Postmaster, New Orleans, La.	77- 78
Commanding General, U. S. Army, Alaska, APO 942, c/o Postmaster, Seattle, Wash.	79- 80
Director, Operations Research Office, 6410 Connecticut Ave., Chevy Chase, Md.	81- 83
Commanding Officer, Ballistic Research Laboratories, Aberdeen Proving Ground, Aberdeen, Md.	84- 85
Commanding Officer, Engineer Research and Development Laboratory, Fort Belvoir, Va.	86- 87
Commanding Officer, Signal Corps Engineering Laboratories, Fort Monmouth, N. J.	88- 89
Commanding Officer, Evans Signal Laboratory, Belmar, N. J.	90- 91
Commanding General, Army Chemical Center, Md. ATTN: Chemical and Radiological Laboratory	92- 93

NAVY ACTIVITIES

Chief of Naval Operations, Department of the Navy, Washington 25, D. C. ATTN: Op-36	94- 95
Chief, Bureau of Ships, Department of the Navy, Washington 25, D. C.	96- 99
Chief, Bureau of Ordnance, Department of the Navy, Washington 25, D. C.	100
Chief, Bureau of Medicine and Surgery, Department of the Navy, Washington 25, D. C.	101-102
Chief, Bureau of Aeronautics, Department of the Navy, Washington 25, D. C.	103-104
Chief, Bureau of Supplies and Accounts, Department of the Navy, Washington 25, D. C.	105-106
Chief, Bureau of Yards and Docks, Department of the Navy, Washington 25, D. C.	107-109

[REDACTED]
DISTRIBUTION (Continued)

	Copy No.
Chief of Naval Personnel, Department of the Navy, Washington 25, D. C.	110
Commandant of the Marine Corps, Washington 25, D. C.	111-113
Commander-in-Chief, U. S. Pacific Fleet, Fleet Post Office, San Francisco, Calif.	114
Commander-in-Chief, U. S. Atlantic Fleet, Fleet Post Office, New York, N. Y.	115
President, U. S. Naval War College, Newport, R. I.	116
Commandant, Marine Corps Schools, Quantico, Va.	117-118
Chief of Naval Research, Department of the Navy, Washington 25, D. C.	119-120
Commander, U. S. Naval Ordnance Laboratory, Silver Spring 19, Md.	121
Commander, U. S. Naval Ordnance Laboratory, Silver Spring 19, Md. ATTN: Aliex	122
Director, U. S. Naval Research Laboratory, Washington 25, D. C.	123
Commanding Officer and Director, U. S. Naval Electronics Laboratory, San Diego 52, Calif.	124
Commanding Officer, U. S. Naval Radiological Defense Laboratory, San Francisco 24, Calif.	125-128
Commanding Officer and Director, David Taylor Model Basin, Washington 7, D. C.	129
Commander, Naval Material Laboratory, New York Naval Shipyard, Naval Base, New York 1, N. Y.	130
Officer-in-Charge, U. S. Naval Civil Engineering Research and Evaluation Laboratory, U. S. Naval Construction Battalion Center, Port Hueneme, Calif.	131-132
Commanding Officer, U. S. Naval Medical Research Institute, National Naval Medical Center, Bethesda 14, Md.	133
Commander, U. S. Naval Ordnance Test Station, Inyokern, China Lake, Calif.	134

AIR FORCE ACTIVITIES

Assistant for Atomic Energy, Headquarters, United States Air Force, Washington 25, D. C.	135-136
Director of Operations, Headquarters, United States Air Force, Washington 25, D. C. ATTN: Operations Analysis Division	137-138
Director of Plans, Headquarters, United States Air Force, Washington 25, D. C. ATTN: AFOPD-P1	139
Director of Requirements, Headquarters, United States Air Force, Washington 25, D. C.	140
Director of Research and Development, Headquarters, United States Air Force, Washington 25, D. C.	141-142
Director of Intelligence, Headquarters, United States Air Force, Washington 25, D. C. ATTN: Phys. Vul. Branch, Air Targets Division	143-144

1946

DISTRIBUTION (Continued)

	Copy No.
Director of Installations, Headquarters, United States Air Force, Washington 25, D. C.	145
Asst. for Development Planning, Headquarters, United States Air Force, Washington 25, D. C.	146
Asst. for Materiel Program Control, Headquarters, United States Air Force, Washington 25, D. C.	147
The Surgeon General, Headquarters, United States Air Force, Washington 25, D. C.	148
Commanding General, Strategic Air Command, Offutt Air Force Base, Nebr.	149-151
Commanding General, Air Research and Development Command, P.O. Box 1395, Baltimore 3, Md.	152-161
Commanding General, Air Materiel Command, Wright-Patterson Air Force Base, Dayton, Ohio	162-163
Commanding General, Air Materiel Command, Wright-Patterson Air Force Base, Dayton, Ohio. ATTN: Air Installations Division	164-165
Commanding General, Tactical Air Command, Langley Air Force Base, Va.	166-168
Commanding General, Air Defense Command, Ent Air Force Base, Colo.	169-171
Commanding General, Air Proving Ground, Eglin Air Force Base, Fla.	172-173
Commanding General, Air Training Command, Scott Air Force Base, Belleville, Ill.	174-176
Commanding General, Air University, Maxwell Air Force Base, Montgomery, Ala.	177-179
Commanding General, Special Weapons Center, Kirtland Air Force Base, N. Mex.	180-182
Commanding General, 1009th Special Weapons Squadron, 1712 G St. NW, Washington 25, D. C.	183
Commanding General, Wright Air Development Center, Wright-Patterson Air Force Base, Dayton, Ohio	184-187
Commanding General, Air Force Cambridge Research Center, 230 Albany St., Cambridge 39, Mass.	188-189
Commanding General, U. S. Air Forces in Europe, APO 633, c/o Postmaster, New York, N. Y.	190-191
Commanding General, Far East Air Forces, APO 925, c/o Postmaster, San Francisco, Calif.	192-193
Commanding General, Air Force Missile Center, Patrick Air Force Base, Cocoa, Fla.	194
Commandant, USAF School of Aviation Medicine, Randolph Air Force Base, Randolph Field, Tex.	195
Asst. to the Special Asst., Chief of Staff, United States Air Force, Washington 25, D. C. ATTN: David T. Griggs	196
The RAND Corporation, 1500 Fourth St., Santa Monica, Calif.	197-198

~~SECRET~~
Security

~~SECRET~~

DISTRIBUTION (Continued)

Copy No.

AFSWP ACTIVITIES

Chief, Armed Forces Special Weapons Project, P.O. Box 2610,
Washington 13, D. C. 199-207

Commanding General, Field Command, Armed Forces Special Weapons
Project, P.O. Box 5100, Albuquerque, N. Mex. 208-213

OTHER ACTIVITIES

Chairman, Research and Development Board, Department of De-
fense, Washington 25, D. C. 214

Director, Weapons System Evaluations Group, Office of the
Secretary of Defense, Washington 25, D. C. 215

Executive Director, Committee on Atomic Energy, Research and
Development Board, Department of Defense, Washington 25,
D. C. ATTN: David Beckler 216

Executive Director, Committee on Medical Sciences, Research and
Development Board, Department of Defense, Washington 25,
D. C. 217

U. S. Atomic Energy Commission, Classified Document Room, 1901
Constitution Ave., Washington 25, D. C. ATTN: Mrs. J. M.
O'Leary 218-220

Los Alamos Scientific Laboratory, Report Library, P.O. Box
1663, Los Alamos, N. Mex. ATTN: Helen Challenger 221-223

Sandia Corporation, Classified Document Division, Sandia Base,
Albuquerque, N. Mex. ATTN: Wynne K. Cox 224-243

Department of Physics, Princeton University
Princeton, N. J.
ATTN: Dr. Walker Bleakney 244

Commanding General, Wright Air Development Center,
Wright-Patterson Air Force Base, Dayton, Ohio
ATTN: WCEEI-4, Maj. H. E. Kee, Jr. 245

Massachusetts Institute of Technology, Cambridge,
Mass. ATTN: Dr. Lawrence Levy 246

Weapon Test Reports Group, TIS 247

Surplus in TISOR for AFSWP 248-297

~~SECRET~~
Security

~~SECRET~~

~~SECRET~~
ATC 1946