AD-A069 225 UNCLASSIFIED	NEW JERSEY NATIONAL DA APR 79 R J	STATE DEPT OF M SAFETY PROGR MCDERMOTT	ENVIRON	MENTAL AHAWKIN	PROTECT LAKE D	ION TR AM (NJ DACWO	RENTON 00057) 51-78-C	F/G 13 • ATE -0124 NL	5/2 ETC(U)	
1 OF 40 4069225		255		AND		AND THE REAL PROPERTY				
			And a second sec		a ti ni mlik Alahan dina	, tend			The second secon	jamen -
	Bernens Bergens Turster Bergens Turster Bergens Bergen	The second secon	CONTRACTOR 			Environment Beneralister Benera	Lauran Bauyan Bauyan Bauyan Salar Salar Salar		1000005F	
3									H. H.	E/
					A Contraction of the second se				A Distance of the second se	4. Lan
Later health shills shikle	=		and and a second se			*		-		Anna ann an Thài
		E Biologiano de Constantino de Const	END _{date} filmed 7 - 79. _{ddc}						*	
								**		. /





	REPORT DOCUMENTATION PAGE		
REPORT NUMBER 2. GOVT ACCESSION NO		BEFORE COMPLETING FORM D. 3. RECIPIENT'S CATALOG NUMBER	
100057			
TITLE (and Subtitie)		5. TYPE OF REPORT & PERIOD COVERED	
Phase I Inspection Report National Dam Safety Program Manahawkin Lake Dam Ocean County, N.J. AUTHOR(a) Richard J. McDermott, P.E.		FTNAL	
		6. PERFORMING ORG. REPORT NUMBER	
		8. CONTRACT OR GRANT NUMBER(*)	
		DACW61-78-C-0124	
PERFORMING ORGANIZATION NAME AND ADD	DRESS	10. PROGRAM ELEMENT, PROJECT, TASK	
Storch Engineering' 220 Ridgedale Ave. Florham Park, N.J. 07932			
I. CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE	
U.S. Army Engineer District, P	hiladelphia	April, 1979	
Custom House, 2d & Chestnut St	reets	13. NUMBER OF PAGES	
Philadelphia, Pennsylvania 191 4. MONITORING AGENCY NAME & ADDRESS(11 d	06 Ifferent from Controlling Office)	15. SECURITY CLASS. (of this report)	
	1	Ibalandfiel	
		SCHEDULE	
Approved for public release; d	listribution unlimite	ed.	
Approved for public release; d	listribution unlimite	ed. om Report)	
Approved for public release; d 7. DISTRIBUTION STATEMENT (of the ebetrect o 8. SUPPLEMENTARY NOTES Copies are obtainable from Nat Virginia, 22151.	istribution unlimite	ed. om Report) ormation Service, Springfield	
Approved for public release; d 7. DISTRIBUTION STATEMENT (of the ebetrect o 8. SUPPLEMENTARY NOTES Copies are obtainable from Nat Virginia, 22151. 9. KEY WORDS (Continue on reverse eide if neces	istribution unlimite ntered in Block 20, 11 different for ional Technical Info	ed. om Report) prmation Service, Springfield	
Approved for public release; d 7. DISTRIBUTION STATEMENT (of the abstract of 8. SUPPLEMENTARY NOTES Copies are obtainable from Nat Virginia, 22151. 9. KEY WORDS (Continue on reverse eide if neces Dams	istribution unlimite ntered in Block 20, 11 different fr ional Technical Info eary and identify by block number Safety	ed. om Report) prmation Service, Springfield	
Approved for public release; d 7. DISTRIBUTION STATEMENT (of the ebetrect o 8. SUPPLEMENTARY NOTES Copies are obtainable from Nat Virginia, 22151. 9. KEY WORDS (Continue on reverse eide if necee Dams Embankments	istribution unlimite ntered in Block 20, 11 different for ional Technical Info eary and identify by block number Safety Visual Inspection	ed. om Report) ormation Service, Springfield	
Approved for public release; d 7. DISTRIBUTION STATEMENT (of the ebetrect of 8. SUPPLEMENTARY NOTES Copies are obtainable from Nat Virginia, 22151. 9. KEY WORDS (Continue on reverse side if neces Dams Embankments Spillway Structural Analysis	istribution unlimite ntered in Block 20, if different in ional Technical Info eery and identify by block number Safety Visual Inspection National Dam Safety Manahawkin Lake Dam	ed. om Report) prmation Service, Springfield) Act Report	
Approved for public release; d 7. DISTRIBUTION STATEMENT (of the abstract of 8. SUPPLEMENTARY NOTES Copies are obtainable from Nat Virginia, 22151. 9. KEY WORDS (Continue on reverse elde if neces Dams Embankments Spillway Structural Analysis 4. ABSTRACT (Continue on reverse elde if neces	istribution unlimite ntered in Block 20, 11 different fr ional Technical Info eary and identify by block number Safety Visual Inspection National Dam Safety Manahawkin Lake Dam	ed. om Report) prmation Service, Springfield p Act Report	
Approved for public release; d 7. DISTRIBUTION STATEMENT (of the ebetrect of 8. SUPPLEMENTARY NOTES Copies are obtainable from Nat Virginia, 22151. 9. KEY WORDS (Continue on reverse eide if neces Dams Embankments Spillway Structural Analysis 4. ABSTRACT (Continue on reverse eide if neces Analysis 4. ABSTRACT (Continue on reverse eide if neces Analysis 4. ABSTRACT (Continue on reverse eide if neces Analysis 4. ABSTRACT (Continue on reverse eide if neces Analysis An	istribution unlimite ntered in Block 20, 11 different for ional Technical Info eary and identify by block number Safety Visual Inspection National Dam Safety Manahawkin Lake Dam may and identify by block number technical investiga luation of the dam i ublic Law 92-367. T view of available de hydraulic and hydro the dam's general co	ed. om Report) ormation Service, Springfield o Act Report tion as to the dam's ade- is as prescribed by the The technical investigation esign and construction record ologic calculations, as ondition is included in the	

Dea Shiving Terres and from a set for the set	CURITY CLASSIFICATION OF THIS PAGE
REPORT DOCUMENTATION PAGE	READ IN TRUCTIONS BEFORE CONFLETING FORM
N ROBERCIA THERE IS SENT AREAS AND AREA	A RECIPIENT'S CATALOU MUNGER
00057	
ase I Trapaction Report	TERE OF REPORT & PERIOD COVERED
tional Dan Gafety Program	FINAL
moli sita al'unita	RURAN TROUBL BED BAMARTER
.L.M . Vanco the	CONTRACTOR AND
a subsciences	CENERMON I NAMO NO ILEAN INCLA IN
chard J. McDermott, P.E.	DAGW61-78-C-0124
enforming ordanization whet and accesss sich Engineering FRidgedale ave.	10 PROSEAU ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
priss Park, N.J. 07932	
CANNOL, HO GREED AND ADDRESS	12 REPORT DATE
S. Army Englacer District, Fullade Lyhia	April, 1979
stom house, 23 & Chestingt Streets	EROAR TO RESMUN 21
1. adelphine, Fennsylventa 19100 de	CO IS SECURITY SUITS FOR DUE CERT
	Unctessalled
	124 CECLASSICATION DOWNERACING
provat for public release; distribution unlimit	rā. F. Report
provac for public release; distribution unlimit bistelaurou starsaent (armo enver mined in incered) a different	rđ. T. Papari
proved for public release; distribution unlimit bistelestan statsachter to excess entred place of a planeou	rđ. re Reputi
provac for public release; distribution unlimit bisteaution starsment (a the revail mixed o black of, i alliment bisteaution starsment (a the revail mixed o black of, i alliment bisteaution starsment (a the revail mixed of black of, i alliment bisteaution starsment (a the revail mixed of black of, i alliment bisteaution starsment (a the revail mixed of black of, i alliment bisteaution starsment (a the revised of black of, i alliment (b bisteaution starsment (b)	ьб. т. Рерон)
proved for public release; distribution unlimit bisteaution starsment (a to rever mixed withous 20, 1 allines) superexpanse to the free National Tackedes Inf pier are obtainable from National Tackedes! Inf relais, 22151.	rā. r. ^{report} ration Service, Springfield
proved for public release; distribution unlimit bistelestem statement of the estate class of refines of shee test faw borts pick are obtainable from National Tachnical Inf rsings 22151.	rd. m Report rration Service, Springfield
proved for public release; distribution unlimit bisteleyten statement of the research class of contract and level are both insole from National Technical inf of a 22151. Contains of reverse des a concert and denic free out and contains of reverse des a concert and denic free out and contains of reverse des a concert and denic free out and	rd. * ^{repond}
proved for public release; distribution unlimit bistelestantan statsment of the express entred of these of a proven shee serve to the post are obtainable from National Tachadeal inf contacts of a press also a contact of a part and also for a press also a contact of a part and disting the contact of a press also a contact of a part and disting the disting of a part of a part of a part of a part disting the part of a part of a part of a part disting the part of a part of a part of a part of a part disting the part of a part of a part of a part of a part disting the part of a part disting the part of a	rd. * ^{Reputs} tration Service, Springfield
proved for public release; distribution unlimit bernaation statsment of no essent envelop there of a dimension of the least fact hours of a set obtainable from National Fechnical Inf clais, 22151. Safe ty di him his bi him his bi him his shing y banks bi him his shing y banks	rd. m Reparty rration Service, Springfield *
proved for public release; distribution unlimit bernaatuse statement of the research decess, addiment bernaatuse statement of the research decess, addiment gen are obtainable from National Sockuteal inf con acts Containable from National Sockuteal inf con acts Containable from National Sockuteal inf da da da da da da da da da da da da da	ra. * * * * * *
proved for public releases distribution unlimit bistelessten statsment of the estrest entred place of a different bistelessten statsment of the estrest entred place of a different bistelessten statsment of the estrest entred place of a different bisteless constitues a true of a state of a different constitues a true of a second bister of the bisteless bisteless bisteless of the estrest estrest for bisteless bisteless bisteless bisteless bisteless bisteless bisteless bisteless bisteless bisteless true true of the bisteless bisteless bisteless bisteless bisteless true true of the bisteless bisteless true true bisteless bisteless bisteless true true bisteless bisteless bisteless true true bisteless bisteless bisteless bisteless true true bisteless bisteless bisteless bisteless true true bisteless bisteless bisteless bisteless bisteless bisteless true true bisteless bisteless bisteless bisteless bisteless bisteless true true bisteless bisteless bisteless bisteless bisteless bisteless bisteless true true bisteless b	ration Service, Epringfield Act Report
resonant for public release; distribution unlimit destearned statement of the sense sense sense the the formation destearned statement of the sense sense the the formation dest are obtainable from Mational Fachaical Inf dest are obtainable from Mational Fachaical Inf formas, 22151, destate the sense of the sense and the formation formation and sense of the sense and the formation inverse the sense of the sense of the sense tructural Analysis for the the pection and evaluation of the day inverse of the targeofiem, rester of available d tructural and inspection and evaluation of the day and sense the sense of the sense of available d tructural and inspection and evaluation of the day and sense the formetion, rester of available d tructural and inspection and evaluation of the day and the the sense of the sense of the day's general tructural and sense the of the day's general of tructural and sense of the day's general of tructural of the day's general of the day's general of tructural of the sense of the day's general of tructural and sense of the day's general of tructural of the day's general of the day's general of tructural of the day's general of the day's general of tructural of the day of the day's general of tructural of the day's general of the day's general of tructural of the day's general of the day's general of the day's general of the tructural of the day of the day's general of the day's genera	ration Service, Springfield the second reation Service, Springfield the as to the dar's ade- the second of the dar's ade- the second of the second the second of the second of the second of the second the second of the second of
proved for public release; distribution unlimit permanent arreast of the server entrole from a finite permanent of the server entrole from Netional Technical inf permanent of the server and a second and the server for weight along as reverse and a second of the server the second of the server and second by Sefery illyay Safe y the inspection and evaluation of the dar in the inspection and evaluation of the dar the inspection and evaluation of the dar the inspection and evaluation of the dar internet of the dar second and hydraulic and hydr internet and the second and contraction of the dar the inspection and evaluation of the dar internet and inspection and evaluation of the dar internet and the second and contraction of the dar internet and the second and contraction of the dar internet and the second and the second and the second internet and the second and the dar's general of the internet of the dar's general of the dar second of the dar's general of the second and the dar's general of the dar second of the dar's general of the second and the second and the second and the second and the the second and the secon	ration Service, Springfield Tration Service, Springfield Mor: Report Las rescribed by the Lion as to the dar's ace- tion as to the dar's ace-

NOTICE

THIS DOCUMENT HAS BEEN REPRODUCED FROM THE BEST COPY FURNISHED US BY THE SPONSORING AGENCY. ALTHOUGH IT IS RECOGNIZED THAT CERTAIN PORTIONS ARE ILLEGIBLE, IT IS BEING RELEASED IN THE INTEREST OF MAKING AVAILABLE AS MUCH INFORMATION AS POSSIBLE.



DEPARTMENT OF THE ARMY PHILADELPHIA DISTRICT. CORPS OF ENGINEERS CUSTOM HOUSE-2D & CHESTNUT STREETS PHILADELPHIA. PENNSYLVANIA 19106

REFER TO		ARCESSION IN	
NAPEN-D		-ETID_ DOG GHARROUNDED JULTIFICATION	Batta Sactiga Batta Sactiga Diri
Honorable Brendan T. B Governor of New Jersey Trenton, NJ 08621	yrne	DT	I/BYAILABILITY 1995
		A	

1 4 MAY 1979

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Manahawkin Lake Dam in Ocean County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dan's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Manahawkin Lake Dam, initially listed as a high hazard potential structure but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in good overall condition and the spillway is adequate. To insure the continued functioning of the dam and its impoundment, the following remedial actions are recommended to be undertaken within one year from the date of approval of this report:

a. Repair eroded areas on the dam embankment and provide a suitable ground cover. A protective coating should be applied to exposed steel sheet piling before placing fill.

b. Inspect and repair the concrete spillway as necessary.

c. A detailed topographic survey of the dam and vicinity should be made .

d. The owner should upgrade the operating and maintenance procedures by issuing a manual and check list for recommended procedures. Inspection and maintenance visits should be logged. Records of pond levels should be kept during routine visits and during severe storms. An annual site inspection should be conducted using a visual inspection check list similar to the one used in this report.

NAPEN-D Homorable Brendan T. Byrne

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman William J. Hughes of the Second District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dem Safety Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,

Emer Girth

1 Incl As stated

1

JAMES G. TON Colonel, Corps of Engineers District Engineer

Copies furnished: Dirk C. Hofman, P.E., Deputy Director Division of Water Resources N. J. Dept. of Environmental Protection P. O. Box CN029 Trenton, NJ 08625

John O'Dowd, Acting Chief Bureau of Flood Plain Management Division of Water Resources N. J. Dept. of Environmental Protection P. O. Box CW029 Treaton, NJ 08625

MANAHAWKIN LAKE DAM (NJ00057)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 20 December 1978 by Storch Engineers under contract to the State of New Jersey. The state, under agreement with the U. S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Manahawkin Lake Dam, initially listed as a high hazard potential structure but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in good overall condition and the spillway is adequate. To insure the continued functioning of the dam and its impoundment, the following remedial actions are recommended to be undertaken within one year from the date of approval of this report:

a. Repair eroded areas on the dam embankment and provide a suitable ground cover. A protective coating should be applied to exposed steel sheet piling before placing fill.

b. Inspect and repair the concrete spillway as necessary.

c. A detailed topographic survey of the dam and vicinity should be nade.

d. The owner should upgrade the operating and maintenance procedures by issuing a manual and check list for recommended procedures. Inspection and maintenance visits should be logged. Records of pond levels should be kept during routine visits and during severe storms. An annual site inspection should be conducted using a visual inspection check list similar to the one used in this report.

APPROVED: Kimen 4 Im SAMES G. TON

Colonel, Corps of Engineers District Engineer

DATE: 7 May 79

PHASE I REPORT NATIONAL DAM SAFETY PROGRAM

Nam of Dam: State Located: County Located: Drainage Basin: Stream: Date of Inspection:

(m

(1, 1)

Manahawkin Lake Dam, I.D. NJ00057 New Jersey Ocean Atlantic Coastal Mill Creek December 20, 1978

Assessment of General Condition of Dam

Based on visual inspection, available records, past operational performance and engineering analyses, Manahawkin Lake Dam is assessed as being in good overall condition.

The spillway is capable of passing the designated spillway design flood (100-year storm) when the water level in the lake is equal to the dam crest elevation and, therefore, is assessed as being adequate.

The concrete spillway appears to be structurally sound, although its surface appears to be slightly eroded. The spillway surface should be protected and any cracks and spalls not visible at the time of inspection should be repaired in the near future by sand blasting, grouting where needed and coating with epoxy.

The embankment is generally free of settlement and appears to be structurally sound. However, a portion of it is eroded causing the corewall and steel sheet piles to be exposed. This condition should be repaired in the near future by filling and compacting so that the dam crest is made level. A protective coating should be applied to the steel sheet piles before filling. In addition, a suitable stand of grass should be established on the bare sections of the embankment in the near future.

i

The owner should implement in the near future a program of periodic inspection and maintenance for the dam which would also include a topographic survey as required to develop as-built drawings based on the original construction plans. As part of the inspection and maintenance program, the lake would be lowered at least every five years at which time the lake should be cleaned and the submerged portions of the dam, spillway and outlet works inspected and repaired.

Richard J. McDermott, P.E.



TABLE OF CONTENTS

	Page
ASSESSMENT OF GENERAL CONDITION OF DAM	i
OVERVIEW PHOTO	iii
TABLE OF CONTENTS	iv
PREFACE	vi
SECTION 1 - PROJECT INFORMATION 1.1 General	. 1 .
1.2 Description of Project 1.3 Pertinent Data	
SECTION 2 - ENGINEERING DATA 2.1 Design 2.2 Construction	10
2.3 Operation 2.4 Evaluation	
SECTION 3 - VISUAL INSPECTION 3.1 Findings	14
SECTION 4 - OPERATIONAL PROCEDURES 4.1 Procedures	17
 4.2 Maintenance of Dam 4.3 Maintenance of Operating Facilities 4.4 Description of Warning System 4.5 Evaluation 	

TABLE OF CONTENTS (cont.)

	Page
SECTION 5 - HYDRAULIC/HYDROLOGIC	19
5.1 Evaluation of Features	
SECTION 6 - STRUCTURAL STABILITY	21
6.1 Evaluation of Structural Stability	
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS	23
7.1 Dam Assessment	
7.2 Recommendations	
PLATES	
A NEW MAD	

- 1 KEY MAP
- 2 VICINITY MAP

3 GEOLOGIC MAP

- 4 GENERAL PLAN
- 5 SPILLWAY SECTIONS
- 6 PHOTO LOCATION PLAN

APPENDICES

(Carlan

- 1 Check List Visual Inspection Check List - Engineering Data
- 2 Photographs
- 3 Engineering Data
- 4 Hydrologic Computations
- 5 Bibliography

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 30214. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that the unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

MANAHAWKIN LAKE DAM, I.D. NJ00057

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

Public Law 92-367, August 8, 1972 authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The Division of Water Resources of the New Jersey Department of Environmental Protection (NJDEP) in cooperation with the Philadelphia District of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the State of New Jersey. Storch Engineers has been retained by the NJDEP to inspect and report on a selected group of these dams. The NJDEP is under agreement with the Philadelphia District of the Corps of Engineers.

b. Purpose of Inspection

The visual inspection of Manahawkin Lake Dam was made on December 20, 1978. The purpose of the inspection was to make a general assessment of the structural integrity and operational adequacy of the dam structure and its appurtenances.

1.2 Description of Project

a. Description

Manahawkin Lake Dam is an earthfill dam with an uncontrolled concrete overflow spillway with a curved shape and two gated corrugated metal pipe outlets. The embankment is sandy and generally free of vegetation with the exception of some grass on its downstream face. Water which passes over the spillway discharges into a downstream channel with timber bulkhead sides.

The concrete spillway is formed over a curved ring of steel sheet piles. The sheet piles are connected on each side of the spillway to a timber core wall within the embankment. Timber bulkheads form the edge of the lake on each side of the spillway for distances of approximately 30 feet to the west and approximately 150 feet to the east. In addition, a buried bulkhead extends from the spillway westward along the rear edge of a beach area adjacent to the dam for a distance of approximately 660 feet.

Having an overall length of 900 feet, the embankment consists of three portions as follows: 1.) a center portion with an overall length of 110 feet and top width of 8 feet lies on either side of the spillway, 2.) a low berm approximately 2 feet high extends westward along the rear edge of the beach area adjacent to the dam for a distance of approximately 640 feet, and 3.) a 150-foot long bulkhead extends along the edge of the lake east of the spillway. The spillway crest has an overall crest length of 70.2 feet and a downstream channel which tapers

from a width of 55 feet to a width of 36 feet within 75 feet of the spillway. Designed for two staged operation, the spillway crest has a primary stage 30 feet long at elevation 23.6 and two secondary stages each of which is 20.1 feet long and at elevation 24.2. (Note: all references to the spillway crest elevation will be to the primary stage elevation of 23.6 unless otherwise noted).

The spillway crest lies 4.2 feet below the elevation of the dam crest and 8.1 feet above the elevation of the downstream channel bottom.

Each of the two outlets consists of a 30-inch corrugated metal pipe which penetrates the spillway. A manually operated slide gate is contained in a concrete manhole located approximately midway between the inlet and outlet ends of each pipe.

b. Location

Manahawkin Lake Dam is located in the Township of Stafford, Ocean County, New Jersey. Constructed across Mill Creek, it impounds Manahawkin Lake which is located in a residential area near the intersection of Routes 9 and 180. Principal access to the dam is through a parking area which is entered from Route 9.

c. Size and Hazard Classification

Size and Hazard Classification criteria presented in "Recommended Guidelines for Safety Inspection of Dams", published by the U.S. Army Corps of Engineers are as follows:

SIZE CLASSIFICATION

	Impoundment				
Category	Storage (Ac-ft)	Height (Ft)			
Small	< 1000 and ≥ 50	< 40 and ≥ 25			
Intermediate	\geq 1000 and < 50,000	\geq 40 and < 100			
Large	≥ 50,000	≥ 100			

HAZARD POTENTIAL CLASSIFICATION

Category

Low

Significant

Kigh

Loss of Life (Extent of Development) None expected (no permanent structures for human habitation) Few (No urban developments and no more than a small number of inhabitable structures) More than few Economic Loss

(Extent of Development) Minimal (Undeveloped to occasional structures or agriculture) Appreciable (Notable agriculture, industry or structures)

Excessive (Extensive community, industry or agriculture)

Manahawkin Lake Dam is classified as "Small" size and "Significant" hazard due to the following applicable data:

Structural Height = 12 feet

Maximum Impoundment = 435 acre-feet

Potential Loss of Life:

No homes in downstream flood plain as delineated by SDF outflow.

Potential Economic Loss:

Three highway bridges within 1/4 mile of dam. Route 180 bridge would be overtopped by breach outflow. Service Station 2000 feet downstream of dam would be flooded by breach outflow.

d. Ownership

Manahawkin Lake Dam is owned by the County of Ocean, Court House, Toms River, New Jersey 08753.

e. Purpose of Dam

The purpose of the dam is the impoundment of a recreational lake facility.

f. Design and Construction History

The earthfill embankment together with a timber spillway was constructed prior to 1929; it was described as being "very old" in that year. In 1960, an inspection by the State of New Jersey revealed that the dam was in poor condition and in need of immediate repair. Subsequently, the dam and lake were acquired by the Township of Stafford and then deeded to the County of Ocean. The Engineering Department of Ocean County designed a new spillway in 1964 which was constructed in 1968 by David Wright, Inc. The spillway reconstruction project included the construction of bulkheads along the edge of the lake on each side of the spillway for distances of approximately 30 feet to the west and approximately 150 feet to the east, as well as the construction of bulkheads on each side of the downstream channel for a distance of approximately 75 feet. In addition, corewalls were constructed in the embankment for a distance of approximately 50 feet on each side of the spillway and the embankments regraded. The present outlet works were also constructed as part of the project.

Plans for the present spillway and appurtenances mentioned above were prepared by Richard E. Lane, P.E., Assistant Ocean County Engineer, and dated June, 1964.

g. Normal Operational Procedures

The dam and appurtenances are maintained by the Ocean County Bridge Department. There is no fixed schedule of maintenance; rather, the Ocean County Bridge Department repairs and maintains the embankment, spillway, appurtenances and lake as needed.

The outlet pipes are used to drain the lake to facilitate repairs and sediment and debris removal. They are not used for emergency purposes during storms.

1.3 Pertinent Data

a. Drainage Area = 19.7 square miles

b. Discharge at Dam Site:

Maximum known flood at damsite
Outlet works at pool elevation
Diversion tunnel low pool outlet at
 pool elevation
Diversion tunnel outlet at pool
 elevation
Gated spillway capacity at pool
 elevation
Gated spillway capacity at
 top of dam
Ungated spillway capacity at
 top of dam

Total Spillway Capacity at top of dam

c. Elevation (Feet above MSL)

Top Dam	28.0
Maximum pool design surcharge	28.0
Full flood control pool	N.A.
Recreation pool	23.7
Spillway crest - Primary	23.6
- Secondary	24.2
Upstream portal invert diversion	
tunnel	N.A.
Stream bed at centerline of dam	16.2
Maximum tailwater	20± (Estimated)

Unknown 84 c.f.s.

N.A.

N.A.

N.A.

N.A.

1908 c.f.s.

1908 c.f.s.

d. Reservoir

Length of maximum pool Length of recreation pool Length of flood control pool

e. Storage (acre-feet)

Recreation pool Flood control pool Design surcharge Top of Dam

f. Reservoir Surface (Acres)

Top of dam Maximum pool Flood control pool Recreation pool Spillway pool

g. Dam

Туре

Length Height (Center Section 110 ft. long) Top Width (Center Section) Side Slopes (Center Section)

- Upstream
- Downstream

Zoning

Impervious Core Cut off Grout Curtain 4270 feet 3900 feet N.A.

127 acre-feet N.A. 400 acre-feet 400 acre-feet

73 acres 73 acres N.A. 54 acres 54 acres

Earthfill 900 feet 12 feet 8 feet

4 horiz to 1 vert. 1.5 horiz. to 1 vert. Unknown Timber core wall Steel Sheet Piling Unknown

h.	Diversions and Regulating Tunnel	N.A.
i.	Spillway	
	Туре	Curved overflow
	Primary Crest	
	Length	30 feet
	Elevation	23.6 feet
	Secondary Crest	
	Length	40.2 feet
	Elevation	24.2
	Gates	N.A.
	Upstream channel	N.A.
	Downstream Channel	Rectangular section
		with timber sides.

j. Regulating Outlets

2 - 30 CMP with gate in manhole

SECTION 2: ENGINEERING DATA

2.1 Design

No plans or calculations pertaining to the original construction of the dam could be obtained. However, information was generated at the time of the spillway reconstruction in 1968 and is available. As mentioned in paragraph of 1.2.f., plans were prepared in 1964 including the following:

- 1. Plan of dam and appurtenances
- 2. Plan, elevation and section of spillway
- 3. Details of spillway crest and dam appurtenances
- 4. Logs of two borings made in the spillway area
- 5. Profile and cross-sections of downstream channel
- 6. Estimate of construction quantities
- 7. Location of dam

In addition, calculations pertaining to the reconstruction were obtained. These include hydraulic analyses of the spillway and downstream channel as well as hydrologic analyses of the drainage basin.

Design of the spillway in 1964 was based on the requirement that the spillway be able to pass the design flood while maintaining a minimum freeboard of 1.5 feet. The design flood peak intensity was computed to be 1170 cfs. The capacity of the spillway was computed to be 1280 cfs with lake stage at elevation 27.0 which allows 1.5 feet of freeboard.

2.2 Construction

No records are available pertaining to the construction of the original dam which was built prior to 1929. The spillway, outlet works and bulkheads were constructed in 1968 and certified as being completed in accordance with the approved plans and specifications by Lawrence F. Wagner, Ocean County Engineer on January 21, 1969.

2.3 Operation

No records of operation of the lake or dam are available. Seven past inspection reports have been obtained and are summarized as follows:

Prior to reconstruction of spillway:

- 5-10-29: Timber sluice type spillway in poor condition; timbers rotted.
- 9-29-60: Both the control structures and those parts of the embankment adjacent thereto in need of immediate repairs.
- 3-16-67: Dam structurally unstable. Downstream face of embankment eroded and concrete walls abraded to a point of failure.

During reconstruction of spillway:

5-13-68: Construction work found to be progressing satis factorily.

Subsequent to reconstruction of spillway:

- 7-7-70: Spillway maintained according to approved plans. Spillway in good condition.
- 8-5-71: Spillway maintained according to approved plans. Spillway in good condition.
- 7-11-72: Spillway is being maintained according to the approved plans. Spillway is in good condition.

2.4 Evaluation

a. Availability

Available engineering information is limited to that which is on file at the NJDEP. The NJDEP file contains copies of plans, calculations, correspondence and photographs available for inspection at the offices of the Bureau of Flood Plain Management, 1474 Prospect Street, Trenton, N.J. Available from the Ocean County Engineering Department are plans of the spillway which duplicate those in the NJDEP file.

b. Adequacy

The available information forms a fairly complete description of the subject dam with a few exceptions which are listed in paragraph 7.1.b.

c. Validity

That information which was able to be verified was valid within a reasonable allowance for error. Data found in the NJDEP file which is at variance with the findings of this inspection and evaluation are noted in paragraph 7.1.b.

SECTION 3: VISUAL INSPECTION

3.1 Findings

a. General

The inspection of Manahawkin Lake Dam took place on December 20, 1978 by members of the staff of Storch Engineers. A copy of the visual inspection check list is contained in Appendix 1. The following procedures were employed for the inspection:

- The embankment of the dam, appurtenant structures and adjacent areas were examined.
- The embankment and accessible appurtenant structures were measured and key elevations determined by hand level.
- The embankment and appurtenant structures and adjacent areas were photographed.
- A member of the staff of the Ocean County Engineering Department was present to assist in the inspection.

b. Dam

The dam embankment is uniformly aligned horizontally.

The surface generally is sandy and bare with some areas of grass on the downstream face in the vicinity of the spillway. The embankment east of the spillway is essentially free of erosion while the embankment west of the spillway is eroded to the extent that the timber corewall and steel sheet piles are exposed and the crest elevation has been decreased by approximately 0.5 feet. The majority of the embankment west of the spillway consists of a long sandy berm approximately 2 feet high (crest elevation 28.5) and forming a crest located between a beach area and commercially developed property along Route 180. The only section of the 900-foot long dam that consists of an embankment higher than two feet is located adjacent to both ends of the spillway and has a total crest length of 110 feet (including the spillway crest length).

No evidence of cracking, settling or seepage was noted in the dam nor were any animal holes observed.

The generalized soils description of the dam site consists of shallow surface alluvial deposits of stratified silty sand with varying amounts of gravel deposited during the Quaternary Period and known as the Cape May Formation in the Geologic Map of New Jersey prepared by Lewis and Kummel. The shallow surface soils are underlain by alluvial deposits of stratified fine micaceous quartz sand with small amounts of silt with local thin layers of gravel and clay deposited during the Tertiary Period and known as the Kirkwood Sands.

Bedrock is in excess of 100 feet below the ground surface. It is assumed that the dam is founded on the silty sands of the Cape May Formation.

c. Appurtenant Structures

The crest of the spillway appeared to be uniformly aligned, although a major part of it was submerged by overflow at the time of inspection. Water was flowing over the primary (elev. 23.6) crest of the spillway and, therefore, the condition of much of the spillway surface was not clearly observed. In the sections of the spillway that were dry, some eroding of the concrete surface was observed. In general, however, all concrete appeared to be in good condition.

Reportedly, the outlet equipment is in good working condition, although its operation was not observed at the time of inspection. The 30-inch diameter CM pipes were observed at their outlet ends and appeared to be in good condition. The manholes housing the outlet gates were observed to be in good condition.

d. Reservoir Area

Manahawkin Lake, having a shape suggesting a rectangle, is approximately 3/4 mile long with an average width of 600 feet. It is located primarily in a residential area with the exception of its upstream end which lies in an undeveloped, wooded area.

Along most of its length, the lake has moderately sloping shores, while the land at its upstream end is relatively flat. A few docks are located along the edge of the lake where residential development has taken place.

e. Downstream Channel

The spillway outflows into Mill Creek which, in the proximity of the dam, is a straight channel with an earth bottom and timber bulkhead sides. It has a fairly uniform bed free of weeds, pools, obstructions and debris. A bridge crosses the stream approximately 250 feet downstream from the dam.

SECTION 4: OPERATIONAL PROCEDURES

4.1 Procedures

The level of water in Manahawkin Lake is regulated naturally by discharge over the two stage spillway of Manahawkin Lake Dam. The two staged crest has fixed elevations. Whenever necessary for maintenance and repair the lake is lowered by opening the outlet gates of the two 30-inch diameter pipes. The lake reportedly has not been drained for a period of at least five years. It is estimated that the time needed to drain the lake is approximately 1 to 2 days.

4.2 Maintenance of the Dam

There is no program of regular inspection and maintenance of the dam and appurtenant structures. One of the provisions of the permit for reconstruction of the spillway specified that "an annual report shall be submitted describing the existing conditions" of the dam embankment, spillway and appurtenances. However, only three of the required annual reports have been written. The last of these was completed in 1972. Maintenance is performed by the Ocean County Bridge Department as the need arises.

4.3 Maintenance of Operating Facilities

The slide-gates and the operating mechanisms used to open and close them are maintained by the Ocean County Bridge Department as the need arises. It could not be determined when the outlet conduits were last maintained.

4.4 Description of any Warning System in Effect

There is no warning system in service now and none was utilized in the past.

4.5 Evaluation of Operational Adequacy

The operation of the spillway, since its reconstruction in 1968 has been successful to the extent that the dam has not been overtopped since then.

The maintenance program for the dam appears to have been fairly adequate. The spillway and top of dam are in good condition. However, some areas of maintenance have not been adequately performed, such as the following:

- Erosion of embankment not adequately treated; corewall and sheet piles allowed to become exposed.
- Erosion at end of bulkhead on west side of downstream channel not adequately treated.
- 3. Bare areas on embankment not restored with grass.

SECTION 5: HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. Design Data

The intensity of storm water runoff that the spillway should be able to handle is based on the size and hazard classification of the dam. This runoff intensity, called the spillway design flood (SDF), is described in terms of return frequency or probable maximum flood (PMF) depending on the extent of the dam's size and potential hazard. According to the "Recommended Guidelines for Safety Inspection of Dams", published by the U.S. Army Corps of Engineers, the SDF for Manahawkin Lake Dam falls in a range of 100-year frequency to 1/2PMF. In this case, the low end of the range, 100-year frequency, is chosen since the factors used to select size and hazard classification are on the low side of their respective ranges.

The peak 100-year flood is 1660 cfs as calculated in accordance with analytical procedures contained in Special Report 38 published by the NJDEP.

Computations used to determine the spillway discharge capacity are contained in Appendix 4. The spillway was assumed to have outflow characteristics of a broad crested weir with breadth equal to two feet.

The spillway discharge (with water level at the dam crest) was computed to be 1908 c.f.s. The dam crest elevation was taken to be 28.0 to account for the erosion in the vicinity of the spillway. Since the computed discharge is greater than the computed SDF peak (1660 c.f.s.), the spillway is considered to be adequate according to criteria developed by the U.S. Army Corps of Engineers.

b. Experience Data

No records are available that would document the proper operation of the dam and spillway since the spillway reconstruction in 1968. No records of lake levels are maintained.

c. Visual Observations

No evidence was found at the time of inspection that would indicate that the dam had been overtopped.

d. Overtopping Potential

As indicated in paragraph 5.1.a., the dam would not be overtopped during storms equivalent to the designated SDF. Detailed hydraulic and hydrologic analyses are contained in Appendix 4.

SECTION 6: STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

140

The embankment appeared, at the time of inspection, to be structurally sound with no evidence of cracks or differential settlement.

b. Design and Construction Data

The analysis of structural stability and construction data for the embankment are not available. The only design and construction data available for the spillway are the drawings prepared by Richard E. Lane, Assistant Ocean County Engineer, prepared in 1964.

c. Operating Records

There are no operating records available for the dam. The water level of Manahawkin Lake is not monitored.

d. Post Construction Changes

Since Manahawkin Lake Dam was reconstructed in 1968, there have been very few changes to the dam or the area surrounding it that could have significant effect on its structural integrity. The following changes have occurred:

- 1. Vegetation has grown on the embankment.
- 2. The embankment has become eroded.
e. Seismic Stability

Manahawkin Lake Dam is located in Seismic Zone 1 as defined in "Recommended Guidelines for Safety Inspection of Dams" which is a zone of very low seismic activity. Experience indicates that dams in Seismic Zone 1 will have adequate stability under seismic loading conditions if they have adequate stability under static loading conditions. Manahawkin Lake Dam appeared to be stable under static loading conditions at the time of inspection.

SECTION 7: ASSESSMENT AND RECOMMENDATIONS

7.1 Dam Assessment

a. Safety

Based on hydraulic and hydrologic analyses outlined in Section 5 and Appendix 4, the spillway of Manahawkin Lake Dam is considered to be adequate according to criteria developed by the U. S. Army Corps of Engineers.

The structural integrity of the dam appears to be adequate based on visual field investigations. No report nor written evidence was found that would contradict that assessment.

Therefore, based on hydraulic and structural considerations, Manahawkin Lake Dam is assessed as being satisfactory in relation to guidelines developed by the U.S. Army Corps of Engineers.

b. Adequacy of Information

Information was gathered from several sources, including: 1.) field investigation, 2.) plans, calculations and correspondence in NJDEP files, 3.) USGS quadrangle sheet, 4.) aerial photography from Ocean County, and 5.) consultation with Ocean County Engineering Department. The information obtained is sufficient to allow a Phase I assessment as outlined in "Recommended Guidelines for Safety Inspection of Dams." Some of the absent data are as follows:

- 1. Stream and lake elevation gauging records.
- 2. Description of dam embankment fill materials.
- 3. Annual inspection reports subsequent to 1972.
- c. Necessity for Additional Data/Evaluation

Although some data pertaining to Manahawkin Lake Dam are not available, additional data are not considered imperative for this Phase I evaluation due to the size and hazard potential classifications of the dam and its general appearance of structural integrity.

7.2 Recommendations

a. Remedial Measures

Based on visual inspection of Manahawkin Lake Dam and pertinent data obtained as part of this evaluation, it is recommended that the owner undertake the following remedial measures in the near future:

- The eroded areas on the dam embankment should be properly filled and compacted in such a way that the dam crest is made uniform at elevation 28.5. A protective coating should be applied to the exposed steel sheet piling before placing fill.
- A suitable stand of grass should be established on the bare sections of the embankment.

- The concrete spillway should be thoroughly inspected and repaired as outlined below:
 - a. Drain the lake to an elevation equal to the invert of the outlet pipe.
 - b. Sand blast all concrete, pressure grout any major cracks and patch all spalls and eroded surfaces.
 - Apply an epoxy preservative coating to all surfaces.

The implementation of the above measures will require proper detailed design and the obtaining of applicable NJDEP approvals.

b. Maintenance

The owner of the dam should initiate, in the near future, a program of periodic inspection and maintenance, the complete records of which to be kept on file and made available to the public. A visual inspection of the dam and appurtenances by a qualified professional engineer should be made annually and reported on a standardized check-list form. Repairs should be made when required and the following maintenance should be performed annually: remove trees and brush from the embankment, fill and sod any eroded surfaces of the embankment and clear the downstream channel. In addition, the lake should be lowered at least every five years at which time the lake should be cleaned and submerged portions of the dam and appurtenances inspected and repaired.

c. Additional Studies

A detailed topographic survey of the dam and area around the dam based on USGS datum should be undertaken by a qualified licensed land surveyor or professional engineer in the near future. The survey map should be related to existing construction drawings and should become part of the permanent record mentioned in paragraph 7.2.b.









MANAHAWKIN LAKE Total Dam Crest Length = 900 fe Manholes Timber Bulkhead Embankment Timber Corewall (exposed) Bulkhead (buried) Beach 55 Chain Link Fence 110 Timber Bulkhead Steel Sheet Piles (exposed 36' MILL CREEK N.S. STATE HIGHMAN ROUTE NO. 180 NOTE: Information taken from plan by Richard E. Lane, P.E., June, 1964 and field inspection December 20, 1978.







O" & CMP (GO' long) 30"\$ CMP (80' long) Manhole 30" Slide Gate Manhole Concrete Crest Spillway Crest Length = 70.2 30" Slide Gate Tin Total 0 30" . CMP Downstream Spillway Face 4" Weepholes 0 0 0 0 0 0 Concre Expansion Joints 0 Apron 3"TEG Sheeting 0 0 0 0 0 0 0 0 0 AP-3 Steel She 17.+ 4" T&G Sheeth 3"x12" Treated Timber Cap Top. Elev. 8" & Minimum L 12" Treated Timber Piles +E: 10" & Untreated ter 11 Galvonized Tie 11 Downstream Channel TE-11 11 STORCH ENGINEERS 长 FLORHAM PARK, NEW JERSEY INSPECTION AND E SPILLW MANAHAWKI I.D. N.J. 00057



Primary Spillway Crest Elev. 23.6 Secondary Spi Elev. 24.2 TOP O Elev. Normal Pool Elev. 23.7 Height of Dam Fill Clay Gravel A" & Weepho MILAUXUXUXUXUXUXUXUX AP-3 Steel Sheet Piling (16' long) 4" Concrete Apron Grouted Stone 8" thick 12" Graded Select Base 10" # Untreated Piles (12' long) 3"TEG (10'10 NOTE: Information taken from plan by Richard E. Lane, P.E., June, 1964 and field inspection December 20, 1978.



3 stream Spillway Face 4" T&G Sheeting Downstream Bed Elev. 16.2 Galvanized Tie Rods 12"¢ Treated Timber Piles (16'long) PLATE 6 DIVISION OF WATER RESOURCES STORCH ENGINEERS N.J. DEPT. OF ENVIR. PROTECTION FLORHAM PARK, NEW JERSEY TRENTON, NEW JERSEY INSPECTION AND EVALUATION OF DAMS SPILLWAY SECTION MANAHAWKIN LAKE DAM I.D. N.J. 00057 SCALE: NOT TO SCALE DATE: FEBRUARY, 1979







APPENDIX 1

Check List - Visual Inspection

Check List - Engineering Data

	Check List Visual Inspection Phase 1	in Lake County Ocean State N.J. Coordinators N.J. DEP	n <u>12/20/78</u> Weather <u>Cloudy</u> Temperature 30 ⁰ F	Time of Inspection 24.1 M.S.L. Tailwater at Time of Inspection 18.1 M.S.L.	me1:	R. McDermott			J.Gribbin Recorder	ritton, Ocean County			
		Name Dam Manahawkin Lak	Date(s) Inspection 12/3	Pool Elevation at Time	Inspection Personnel:	J. Gribbin	• D. Buckelew	A. Miller	•	Present: Bill Brittor	 		「「「「「「「「」」」」」」」」」」」」」」」」」」」」」」」」」」」」」

•

REMARKS OR RECOMMENDATIONS Lowe 1-• CONCRETE/MASONRY DAMS • OBSERVATIONS N.A. N.A. N.A. N.A. N.A. VISUAL EXAMINATION OF STRUCTURE TO ABUTHENT/ENBANCHENT JUNCTIONS SEE PAGE ON LEAKAGE WATER PASSAGES . FOUNDATION DRAINS

• siic 2 REMARKS OR RECOMPENDATIONS CONCRETE/MASONRY DAMS OBERSVATIONS N.A. • N.A. N.A. N.A. N.A. VERTICAL AND HORIZONTAL ALIGNERN VISUAL EXAMINATION OF CONSTRUCTION JOINTS STRUCTURAL CRACKING SURFACE CRACKS CONCRETE SURFACES SINIOL HTIJONOM

	EMBAWOJENT	·
VISUAL EXAMINATION OF	OBSERVATICNS REMARKS OR RECOMMENDATIC	SNOI
SURFACE CRACKS	None Observed	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None Observed	
SLOUGHING OR EROSION OF ENEANWENT AND ABUTNENT SLOPES	Downstream face of embankment adjacent to west wingwall of spillway eroded; steel sheet piles exposed and rusted. Timber corewall exposed on embankment west of spillway.	rewall could be
VERTICAL AND HORIZONTAL ALINEMENT OF THE CREST	Appeared straight	
RIPRAP FAILURES	N.A.	

REMARKS OR RECOMMENDATIONS Sheet .. junction and embankment in good condition embankment eroded; junction in good condition Embankment is sandy and bare except for some grass on downstream face THE OWNERS **OBSERVATIONS** East wingwall: West wingwall: None observed N.A. N.A. STAFF CAGE AND RECORDER JUNCTION OF EMBANCOENT AND ABUTHENT, SPIILWAY AND DAM ANY NOTICEABLE SEEPAGE VISUAL EXAMINATION OF The GENERAL DRAINS

Concrete surfaces of gate manholes in good condition ` REMARKS OR RECOMPLENDATIONS Submerged except for opening in downstream face of spillway, which appeared to be in good condition. Refer to downstream channel. OBSERVATIONS OUTI,ET WORKS Submerged N.A. N.A. • CRACKING AND SPALLING OF CONCKETE SURFACES IN OUTLET CONDUIT VISUAL EXAMINATION OF INTAKE STRUCTURE OUTLET STRUCTURE EMERCENCY CATE OUTLET CHANNEL .*

REMARKS OR RECOMMENDATIONS Aligned true to plans. Surface of weir and downstream face eroded; aggregate some-what exposed. No cracks or spalls observed. 1 Refer to downstream channel OBSERVATIONS · UNCATED SPILLWAY N. A. N.A.. VISUAL EXAMINATION OF DISCHARCE CHANNEL BRIDCE AND PIERS APPROACH CHANNEL CONCRETE WEIR

REMARKS OR RECOMMENDATIONS OBSERVATIONS CATED SPILLWAY N.A. N.A. N.A. N.A. N.A. VISUAL EXAMINATION OF CATES AND OPERATION EQUIPMENT DISCHARGE CHANNEL APPROACH CHANNEL BRIDGE AND PIERS CONCRETE SILL

REMARKS OR RECOMMENDATIONS OBSERVATIONS INSTRUMENTATION • NONE NONE NONE NONE NONE . : MONUMENTATION/SURVEYS VISUAL EXAMINATION OBSERVATION WELLS PIEZONETERS OTHER WEIRS

Beach along south shore. Resi-dential development along east and west shores. Wooded area along north shore. REMARKS OR RECOMMENDATIONS Slopes range from 2% to 5% . OBSERVATIONS RESERVOIR · Not known VISUAL EXAMINATION OF SEDIMENTATION SIOPES

•	
•	DOWNSTREAM CHANNEL
VISUAL EXAMINATION OF	OBSERVATIONS REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Well formed channel with vertical sides for 75' downstream of spillway. 'Some erosion observed at end of bulkhead on west side. No West bank at end of bulkhead obstructions observed should be protected.
SLOPES	Vertical timber bulkheads; except portion of west bank: approx. 3:1 slope grass covered
APPROXIMATE NO. OF HORES AND POPULATION	None in the vicinity of the dam. Service station and automobile showroom in vicinity of dam. Not in downstream flood plain of dam as delineated by SDF outfloo
and the second sec	

	CHECK LIST ENCINEFRING DATA DESIGN, CONSTRUCTION, OPERATION
TTEM	REMARKS
FLAN OF DAM	Plans of proposed spillway by Richard E. Lane, P.E., Assistant Ocean County Engineer dated June 1964.
REGIONAL VICINITY MAP	Available
CONSTRUCTION HISTORY	Original construction: no data available Spillway reconstruction: data available
TYPICAL SECTIONS OF DAM	Not available
HYDROLOGIC/HYDRAULIC DATA	Available: NJDEP File
OUTLETS - PLAN	Available: Lane Drawings
- DETAILS -CONSTRAINTS	Available: Lane Drawings
RAINFALL/RESERVOIR RECORDS	Not available
A STATE STA	

TTELL	DEMABKS
TEM	
MONITORING SYSTEMS	None
•••	
:	•
MODIFICATIONS	
CNULLAND AND AND AND AND AND AND AND AND AND	
	· · · · · · · · · · · · · · · · · · ·
HIGH POOL RECORDS	Not available
POST CONSTRUCTION ENGINEERING	Inspection Reports available
STUDIES AND REPORTS	
PRIOR ACCIDENTS OK FAILURE OF DAM	worde reported
REPORTS	N.A.
MAINT ENANCE	Not available
OPERATION	
RECORDS	

ITEM	REMARKS	9
DESIGN REPORTS	Not available	•
GEOLOGY REPORTS	Not available	
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	Available Not available Not available	
	•	
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	Available (2 borings) Not available Not available	
POST-CONSTRUCTION SURVEYS	OF DAM Not available	
BORROW SOURCES.	Not available	

.
SPILLWAY PLAN

-

SECTIONS

DETAILS

PLANS & DETAILS

REMARKS

Available. See Lane plans referenced earlier.

••,

Available, See Lane plans referenced earlier.

0

Photographs



РНОТО 2

CONCRETE MANHOLE FOR SLIDE GATE. OUTLET PIPE IN SPILLWAY DOWNSTREAM FACE.



PHOTO 1 SPILLWAY



0

1.

0









20 DEC. 1978





BULKHEAD ALONG EDGE OF LAKE, EAST OF SPILLWAY



РНОТО 6

BULKHEAD ALONG EDGE OF LAKE, WEST OF SPILLWAY

AT 3 LITE

20 DEC. 1978





Engineering Data

0

CHECK LIST HYDROLOGIC AND HYDRAULIC DATA

ENGINEERING DATA

•

ELEVATION	AREA CHARACTERIS	TICS: Wooded with one large housing development (STORAGE CAPACITY): 23.7(127 acre-feet)
ELEVATION	TOP FLOOD CONTR	OL POOL (STORAGE CAPACITY): N.A.
ELEVATION	MAXIMUM DESIGN	POOL: 28.0
ELEVATION	TOP DAM:	-28.0
SPILLWAY	CREST:	Curved reinforced concrete
а.	Elevation	23.6 (Primary crest, length 30 feet)
b.	Туре	uncontrolled overflow
с.	Width	25 inches
d	Length	70.2 feet (total)
е.	Location Spille	over entire length of spillway
. f.	Number and Type	of Gates None
OUTLET WO	DRKS:	2 - 30" Diam. pipes
a.	Туре	Corrugated metal pipes
b.	Location	through spillway
с.	Entrance invert	s 17.88 (plans)
d.	Exit inverts	16.80 (plans)
e.	Emergency drain	down facilities: Slide gates in manholes
HYDDOMET	EOROLOGICAL GAGES	
IT DRUME I		
a.	Туре	N. A.
a. b.	Type Location	N. A. N. A.
a. b. c.	Type Location Records	N. A. N. A. N. A.
a. b. c. MAXIMUM I	Type Location Records NON-DAMAGING DISC	N. A. N. A. N. A. HARGE:

0

0

Hydrologic Computations

Sheet _ _ _ of _ 6 STORCH ENGINEERS Made By JG Date 2/8/79 Manahawkin Lake Dam _Chkd By_____Date _____ 100-year Flood (Peak Discharge) (Reference: Special Report #38) 1. Drainage Area = 19.7 sq. mi. 2. Main Channel Slope (s): Length of main channel = 6.5 mi. Elev. at 0.65 mi (10%) from lake = 34 Elev. at 5.5 mi (85%) from lake = 105 $S = \frac{105 - 34}{4.875} = 14.6 \text{ ft.}/\text{mi.}$ 3. Surface Storage Index Area of lakes and swamps as measured from uses 1.10 sq. mi. quadrangle = 6.58 % $S_t = \frac{1.10}{19.7} \times 100 + 1 =$ 4. Manmade impervious cover index I : Population of drainage area = ~ 6500 people ()Population density (D) = 6500 = 330 persons/sq.mi.

Sheet 2 of 6 **STORCH ENGINEERS** Made By JG Date 2/8/79 Project 1132 Manahawkin Lake Dam Chkd By____Date_ I = 0. 117 D 0.792 - 0.039 log D I = 6.5 % 5. 100-year flood peak discharge Q100: Q100 = 136 A 0.84 5 0.26 5, -0.51 I 0.14 = 136 (19.7) 0.84 (14.6) 0.26 (6.58) -0.51 (6.5) 0.14 = 136 (12.23) (2.01) (.383) (1.30) = 1660 cfs

Sheet _ 3 of _ 6 **STORCH ENGINEERS** Made By JG Date 2/7/79 Project ______22 Manahawkin Lake Dam Chkd By_____Date____ Spillway Discharge Ĵ₽. 2' Downstream Spillway Face (Reference: King, et.al., Handbook of Hydraulics, 1963) The spillway crest will be taken as a broad crested weir with breadth = 2! Discharge is given by

Q = CLH 3/2

where

Q = discharge in cfs C = coefficient (dependent on H) L = length of crest in ft. H = head over crest in ft. STORCH ENGINEERS

Sheet <u>4</u> of <u>6</u> _Made By <u>JG</u> Date <u>2/7/79</u>

:

Project 1132

0

_Chkd By_____Date _____

Manaha	putin	late	Dam
1 IGHAFIC	WRIT	Lanc	Dam

Primary Crest L= 30'		Secondary Crest L= 40.2'				
H (ft.)	c	Q (c.f.s.)	H (ft.)	c	Q (c.f.s.)	Total Q (c.f.s.)
0	-	0	0.	-	0	0
0.6	2.61	36	0	-	0	36
1.0	2.66	80	0.4	2.61	27	107
2.0	2.85	242	1.4	2.77	184	426
3.0	3,20	499	2.4	3.03	453	95Z
4.0	3.32	797	3,4	3.32	837	1634
4.4	3.32	919	3,8	3.32	989	1908





(Reference: Hydroulic Charts for the selection of Highway Culverts, 1965)

Pipe will function under outlet control

 $D = 2.5' \qquad TW = \frac{D+d_c}{2} H = HW - TW$ Length = 60' HW = 23.6 - 16.8 = 6.8' (Normal lake stage)

Lake Stage	HW (ft)	H (ft)	Q (cfs)	2Q (cfs)
23.6	6.8	4.5	42	84
22.6	5.8	3.5	37	74
21.6	4.8	2.6	32	64
20.6	3.8	1.7	26	52
19.6	2.8	1.0	20	40

0

0

Bibliography

- "Recommended Guidelines for Safety Inspection of Dams," Department of the Army, Office of the Chief of Engineers, Washington, D. C. 20314.
- <u>Design of Small Dams</u>, Second Edition, United States Department of the Interior, Bureau of Reclamation, United States Government Printing Office, Washintton, 1973.
- Holman, William W. and Jumikis, Alfreds R., <u>Engineering Soil</u> <u>Survey of New Jersey, Report No. 8, Ocean County</u>, Rutgers University, New Brunswick, N. J. 1953.
- "Geologic Map of New Jersey" prepared by J. Volney Lewis and Henry B. Kummel, Dated 1910 - 1912.
- Stankowski, Stephen J., <u>Magnitude and Frequency of Floods in</u> <u>New Jersey with Effects of Urbanization, Special Report 38</u>, State of New Jersey Department of Environmental Protection, Division of Water Resources, 1974.
- Herr, Lester A., <u>Hydraulic Charts for the Selection of Highway</u> <u>Culverts</u>, U. S. Department of Transportation, Federal Highway Administration, 1965.
- <u>Safety of Small Dams</u>, Proceedings of the Engineering Foundation Conference, American Society of Civil Engineers, 1974.
- King, Horace Williams and Brater, Ernest F., <u>Handbook of</u> <u>Hydraulics</u>, Fifth Edition, McGraw-Hill Book Company, 1963.
- Plans titled "Plans of Proposed Construction of Manahawkin Lake Spillway," (5 sheets) prepared by Richard E. Lane, P.E., dated June, 1964.