/	AD-	A069 4	72 KI NA JU IED	MBALL TIONAL N 78 F	L ROBEL DAM SAL J KIM	RT) AND FETY PR BALL	ASSOCI	DELTA	BENSBUR DAM (IN	G PA VENTORY D	NUMBER	F/ NY 6) 78-C-00 N	6 13/2 ,ETC	U)
		OF 2 AD A069 472		Ministration Minis			The second secon	Id Internet				1		AND
		A second											The second	A second
	-		-											
								-	A Constant of the second secon					
	1000 1000	JE.		-	nuder 			 Marine Marine Marine Marine Marine Marine		1 Internet Atomic State 1 Internet Atomic Sta				
		A.								<text><text><text><text><text></text></text></text></text></text>			2.3 μ <sup>2</sup> 3.4 μ <sup>2</sup> </td <td></td>	
						-			E STATE BARRIES					/



MOHAWK RIVER BASIN

# DELTA DAM

.

ONEIDA COUNTY, NEW YORK INVENTORY NUMBER NY 6

# PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM



APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED CONTRACT NO. DACW-51-78-C-0025

200 PM NG

JUN 6 1979

UBIVIS

BERT KIMBALL and ASSOCIATES W. Highland Ave. Ebensburg, Pa.

**Prepared** For

d by

• •

2

A069475

AD

DEPARTMENT OF THE ARMY NEW YORK DISTRICT, CORPS OF ENGINEERS NEW YORK, NEW YORK

# **DISCLAIMER NOTICE**

.

Π

Π

Π

Π

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DDC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

SECURITY &LASSINGATION OF THIS PAGE (When Data Entered) READ INSTRUCTIONS REPORT DOCUMENTATION PAGE BEFORE COMPLETING FORM ARCALSION CIPIENT'S CATALOG NUMBER . REPORT NUMBER Phase I: Inspection Report Delta Dam Mohawk River Basin, Oneida Count New No. WY 6 R. Jeffry/Kimball P.E. PERFORMING ORGANIZATION NAME AND ADDRESS L. Robert Kimball and Associates 615 W. Whghland' Avenue Ebensburg, Pennsylvania Department of the Army 26 Federal Di 5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program 6. PERFORMING ORG. REPORT NUMBER Mohawk River Basin, Oneida County, N.Y. B. CONTRACT OR GRANT NUMBER(.) DACW51-78-C-0025 10. PROGRAM ELEMENT. PROJECT, TASK AREA & WORK UNIT NUMBERS 30 Jun 78 26 Federal Plaza / New York District, CofE THEFR OF PAGES New York, New York 10007 14. MONITORING AGENCY NAME & ADDRESS(II different from Controlling Office) 15. SECURITY CLASS. (of this report) UNCLASSIFIED 15a. DECLASSIFICATION DOWNGRADING SCHEDULE 15. DISTRIBUTION STATEMENT (of the Report) Approved for public release; Distribution unlimited. National Dam Safety Program. Delta Dam (Inventory Number NY 6), Mohawk (ttor 17. DISTRIBUTIO River Basin, Oneida County, New York. Phase 1 Inspection Report. JUN 6 1979 18. SUPPLEMENTARY NOTES 9. KEY WORDS (Continue on reve Dam Safety Oneida County National Dam Safety Program Mohawk River Visual Inspection Delta Dam Hydrology, Structural Stability ABSTRACT (Cantinue an reverse eide if necessary and identity by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. Delta Dam was judged to be unsafe, non-emergency due to a seriously inadequate spillway. Additional studies and investigations were also reccommended. HIL OSY DD 1 JAN 73 1473 EDITION OF I NOV 65 IS OBSOLETE UNCLASSIFIED SECURITY CLASSIFICATION OF THIS PAGE (I hen Date Entered)

DEPARTMENT OF THE ARMY U. S. ARMY ENGINEER DISTRICT, NEW YORK 26 FEDERAL PLAZA NEW YORK, NEW YORK 10007

2 OCT 1978

· · · ·

NANEN-F

Honorable Hugh L. Carey Governor of New York Albany, New York 12224

Dear Governor Carey:

2.2

TD NO

The purpose of this letter is to inform you of a clarification of the guidelines used by this office in assessing dams under the National Program of Inspection of Dams.

Office of the Chief of Engineers has recently provided a clarification that dams with seriously inadequate spillways are to be assessed as unsafe, nonemergency, until more detailed studies prove otherwise or corrective measures are completed.

The following dams in your state have previously been assessed as having seriously inadequate spillways, with capability to pass safely only the percentage of the probable maximum flood as noted in each report. They are now to be assessed as unsafe:

NAME OF DAM

1.0. 10.	NAME OF DAM
N.Y. 59	Lower Warwick Reservoir Dam
N.Y. 4	Salisbury Mills Dam
N.Y. 45	Amawalk Dam
N.Y. 418	Jamesville Dam
N.Y. 685	Colliersville Dam
N.Y. 6	Delta Dam
N.Y. 421	Oneida City Dam
N.Y. 39	Croton Falls Dam
N.Y. 509	Chadwick Dam (Plattenkill)
N.Y. 66	Boyds Corner Dam
N.Y. 397	Cranberry Lake Dam
N.Y. 708	Seneca Falls Dam
N.Y. 332	Lake Sebago Dam
N.Y. 338	Indian Brook Dam
N.Y. 33	Lower(S) Wiccopee Dam (Lower Hudson W.S. for Peekskill)

NANEN-F Honorable Hugh L. Carey

I.D. NO.	NAME OF DAM
N.Y. 49	Pocantico Dam
N.Y. 445	Attica Dam
N.Y. 658	Cork Center Dam
N.Y. 153	Jackson Creek Dam
N.Y. 172	Lake Algonquin Dam
N.Y. 318	Sixth Lake Dam
N.Y. 13	Butlet Storage Dam
N.Y. 90	Putnam Lake (Bog Brook Dam)
N.Y. 166	Pecks Lake Dam
N.Y. 674	Bradford Dam
N.Y. 75	Sturgeon Pool Dam
N.Y. 414	Skaneateles Dam
N.Y. 155	Indian Lake Dam
N.Y. 472	Newton Falls Dam
N.Y. 362	Buckhorn Lake Dam

The classification of "unsafe" applied to a dam because of a seriously inadequate spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening, and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard to loss of life downstream from the dam.

Consequently, it is advisable to implement the recommendations previously furnished in the reports for the above-mentioned dams as soon as practicable.

It is requested that owners of these dams be furnished a copy of this letter and that copies be permanently appended to all reports previously furnished to you.

Sincerely yours,

CLARK H. BENN Colonel, Corps of Engineers District Engineer

2

MOHAWK RIVER BASIN

# DELTA DAM

ONEIDA COUNTY, NEW YORK Inventory number Ny 6

# PHASE 1 Inspection Report National Dam Safety Program



**Prepared** by

I

I

L. ROBERT KIMBALL and ASSOCIATES 615 W. Highland Ave. Ebensburg, Pa.

**Prepared** For

DEPARTMENT OF THE ARMY NEW YORK DISTRICT, CORPS OF ENGINEERS NEW YORK, NEW YORK

### Table of Contents

General	Page No. 1
Overview Photograph	
Site Location Map	2
Section 1: Project Information	3
Section 2: Engineering Data	7
Section 3: Visual Inspection	8
Section 4: Operational Proceedures	9
Section 5: Hydraulic/Hydrologic	10
Section 6: Structural Stability	16
Section 7: Assessment/Remedial Measures	17
Appendices	

A. Geology

I

I

I

I

I

I

and and a second

a court

T

----

T

I

- B. Hydrologic Computations
- C. Photographs
- D. Pertinent Correspondence and Reports

• .

- E. Construction Drawings
- F. Visual Check List
- G Engineering Data Check List

DDC TAB	1
Unannounced	
	]
Justification	
By	
Distribution/	
Availability Code:	3
Avail and/or	
Dist special	
1 7	
1125	

-..

1.1

1

1213

Service .

#### Description of Photographs Delta Dam

#### Plate

 Overall view of the dam from left abutment. Note: Seepage visible on section of dam below gate house.

#### APPENDIX C

 Left abutment portion of dam from downstream. <u>Note</u>: Deterioration of gunite facing, seepage. <u>Visible</u>: Old gate house at toe, stilling pools for principal and emergency spillway. -

e din t

- 3. Right portion of dam from downstream. <u>Note</u>: Deterioration of gunite facing, sprays in spillway apparently caused by deterioration in concrete. <u>Visible</u>: Stilling pool, rip rap protection.
- 4. View of immediate downstream area from top of dam.
- Looking at major seepage area below gate house from top of dam. Note: Vegetative growth in face, rolling and bulging of gunite facing. Amount of seepage depicted by ground saturation and puddles at toe.
- Close up view from downstream of right abutment of dam.
   Note: Vegetative growth and deterioration of gunite facing.
- 7. Close up view of downstream face of left abutment of dam.
- 8. Close up of deterioration of gunite facing on downstream face of left abutment of dam.
- 9. Upstream face and gate house from left abutment.
- Upstream face from gate house.
   Note: Erosion of concrete on upstream face at water line.

Phase I Report

Name of Dam: Delta Dam

I

State Located: New York

County Located: Oneida

Stream: Mohawk River

Date of Inspection: May 5, 1978

#### ASSESSMENT

The visual inspection and evaluation of Delta Dam did not reveal any problems which would require immediate emergency action. This is not to imply that planning and implementation of followup analyses, design and construction should be put off. As soon as practical, the following studies should be initiated by the owner.

- Flood routing completed for this structure indicated that the spillway is seriously inadequate as defined by ETL 1110 "Review of Spillway Adequacy". The dam cannot safely pass either the SPF or PMF. Either additional spillway facilities or lowering of the pool elevation to provide additional storm storage or a combination of the two should be studied and a plan implemented in the near future.
- 2. A thorough evaluation of the condition of the structure including test borings, sampling, and testing and stability analyses should be conducted. Results of the stability analyses should reflect whether the structure can withstand overtopping and used as a design parameter for spillway modifications. The condition of the concrete within the dam and the affect of seepage throughout the dam should be determined.

Approved by: Det

R. Jeffrey Kimbell, P.E. L. ROBERT KIMBALL & ASSOCIATES Registration No. PA 26275 E

Approved by:

Vience

CLARK H. BENN Colonel, Corps of Engineers District Engineer 30 Jun 75





#### PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM DELTA DAM ID# NY 6

SECTION 1: PROJECT INFORMATION

#### 1.1 General

- a. <u>Authority</u>: Authority is provided by the National Dam Inspection Act, Public Law 92-367,1972; Contract No. DACW 51-78-C-0025.
- b. <u>Purpose of Inspection</u>: Evaluation of non-Federal dams to identify dams which are a threat to life and property.

#### 1.2 Description of Project:

- a. Description of Dam and Appurtenances: Delte Dam is a cyclopean masonry gravity structure about 100' high and 1000' long. The dam was completed in 1912 and is used to supply water to the canal system. There are two large (331 and 385' long) abutment sections separated by a 300' long concrete ogee spillway. On the left abutment section is a gatehouse which controls valves for four 60" steel pipes that are used as the outlet works. The top of of the spillway crest is 550.0' and the top of dam is 558.0'.
- b. Location: Delta Dam is located approximately 3-1/2 miles north of the City of Rome, Oneida County, New York. The latitude is 43°-16.2' and the longitude is 75°-26'.
- c. <u>Size Classification</u>: The storage capacity at normal pool is approximately 63,000 ac-ft. and the height is 100 ft. On this basis the size classification is large.
- d. <u>Hazard Classification</u>: The dam is classified as high hazard because of the presence of approximately 20 homes immediately downstream and the City of Rome.
- e. <u>Ownership</u>: The dam is owned by the State of New York Department of Transportation.
- f. <u>Purpose of Dam</u>: Delta Dam was originally constructed and is currently being used to supply water for the canal system.
- g. Design and Construction History: The dam is believed to be designed by the State of New York. Construction began in 1909 and completed in 1912. The contractor was Arthur McMullin. Construction drawings are available at the Department of Transportation offices. Little information was available on the construction history of the dam.

Evaluation of seepage through the dam was completed in 1976-1978 by the New York State DOT with recommendations made for stopping the seepage.

- h. <u>Normal Operational Procedures</u>: The reservoir supplies water for the New York Canal System and water is drawn off the lake as needed. The water is regulated by opening the four 60" diameter pipes. If a large storm is expected, the caretaker may lower the lake level to store some of the runoff.
- 1.3 Pertinent Data:
  - a. <u>Drainage Areas</u>: The Delta Dam impounds waters of the Mohawk River. It has a drainage area of 150 square miles of open rolling country.
  - b. Discharge at Damsite:

Maximum Known Flood at Damsite: 4.5' over spillway: 9,000 cfs Spillway Capacity at Maximum Design Pool Elev.: Unknown Spillway Capacity at Top of Dam: 21,600 cfs Outlet works Capacity at Normal Pool: 2,900 cfs Outlet works Capacity at Top of Dam: 3,100 cfs Total Spillway Capacity at Top of Dam: Assumed 24,700 cfs

c. Elevation (Ft. above MSL):

Top of Dam: 558

Maximum Pool Design Surcharge: Unknown

Spillway Crest: 550

Streambed at Centerline of Dam: 480

Maximum Tailwater: 490

d. Reservoir:

Length of Normal Pool: 2,300'

Length of Maximum Pool: 2,600' (Top of Dam)

e. Storage (ac-ft):

Normal Pool: 63,000

Design Surcharge: Unknown

Top of Dam: 87,500

f. Reservoir Surface (acres):

Top of Dam: 3,200

Normal Pool: 2,670

Spillway Crest: 2,670

g. Dam:

Type: Cyclopean masonry gravity dam

Length: 1000'

Height: 100'

Top Width: 10.5'

Side Slopes: Upstream 1:30 Downstream 1:6.5

Zoning: N/A

Impervious Core: N/A

Cutoff: Approximately 8' wide and 8' deep into rock

Grout Curtain: Unknown - 1924 report says that grouting will be done, however no record of grouting was found.

.....

h. Diversion & Regulating Tunnel:

Type: Four 60" diameter pipes

Length: Approximately 70 feet

Closure: Opened and closed by electric motors

Access: At gatehouse on crest of dam .

Regulating Facilities: Valves with electric motors regulate the flow to the Mohawk River.

## i. Spillway:

Π

Π

-

I

1

Type: Concrete ogee Length of Weir: 300' Crest Elevation: 550' Gates: None U/S Channel: None D/S Channel: Approximately 65' drop at 1:6.7 slope j. Regulating Outlets: None

#### SECTION 2: ENGINEERING DATA

2.1 <u>Design</u>: Pre-construction drawings are available at the Department of Transportation office in Utica. No hydrologic or hydraulic design data was available. A report by Thos. H. Wiggin in 1924 summarizes stability. 1. . . .

1

- 2.2 Construction: No construction records were available for review.
- 2.3 <u>Operation</u>: No operating instructions were made available to indicate proper operation of the outlet works.
- 2.4 Evaluation: Some of the hydrologic and hydraulic data necessary to perform a detailed analysis of the structure was not available. The material that is available appears to be valid.

7

#### SECTION 3: VISUAL INSPECTION

#### 3.1 Findings:

- a. <u>General</u>: Delta Dam was inspected by personnel of L. Robert Kimball and Associates and the New York State Department of Transportation on May 5, 1978.
- b. Dam: The dam appears to conform to the construction drawings. The dam has had considerable deterioration in the past which has been repaired. Deterioration and seepage problems are continuing to progress.
- c. Appurtenant Structures: All drawdown facilities appeared to be in good working condition.
- d. <u>Reservoir Area</u>: The impoundment retains waters of the Mohawk River. The overburden in the area is relatively thin and the slopes are moderate.
- e. <u>Downstream Channel</u>: The immediate downstream channel is medium wide and open except for several bridges which are of no effect. The channel to the City of Rome is a medium wide flood plain with some development along the river.
- 3.2 Evaluation: Visual inspection revealed that the dam has seepage passing through the two abutment monoliths. These two monoliths show significant deterioration of the shotcrete and leaching of the shotcrete or concrete. Some of the leaching may be coming from the concrete, since severe deterioration was noted at an early age (1924). The dam is founded on a dark gray fissile shale which is nearly horizontally bedded. This type of rock usually exhibits significant seepage, but it is not present. The drawdown facilities appear to be in good working condition. The downstream area would be affected severly if Delta Dam were to fail.

8

#### SECTION 4: OPERATIONAL PROCEDURES

- 4.1 Procedures: The dam is operated as a water supply for the New York Barge Canal System and water is drawn off the reservoir as needed. At times, if a storm is expected, water is expelled from the reservoir so storm waters can be stored.
- 4.2 <u>Maintenance of Dam</u>: Day to day maintenance is performed on the dam as needed.

die .

- 4.3 <u>Maintenance of Operating Facilities</u>: Normal maintenance of operating facilities is performed as needed.
- 4.4 Description of Any Warning System In Effect: No warning system is present.
- 4.5 Evaluation: The dam and appurtement structures appear to be operated at regular intervals and the operational equipment is well maintained.

#### SECTION 5: HYDRAULIC/HYDROLOGIC

#### 5.1 Evaluation of Features:

a. <u>Design Data</u>: No hydrologic design data was available for the structure. The review information available included stability analysis with a maximum water level 2 feet below the top of dam at elevation 556 feet.

Delta Dam is used primarily for canal water supply. When practical the reservoir level is lowered to accommodate flood waters. The caretaker reports that principal spillway gates are opened when storms are predicted. 2.42 -1

100

Fai

b. Experience Data: Reservoir water level records are kept by the caretaker. They are not formally recorded by the owner.

A report titled "Upper Hudson and Mohawk River Basins Hydrologic Flood Routing Models" prepared by the New York District Corps of Engineers, 1976 contains information on Delta Dam.

There is a U.S.G.S. gauge downstream of the dam. The Corps report indicates a peak discharge of 21,819 cfs for their model of the Transposed Agnes event. The caretaker reports a discharge of approximately 9,000 cfs during the Agnes storm.

c. <u>Visual Observations</u>: At the time of the inspection approximately 0.4 feet (5 inches) of water was discharging over the spillway crest (water elevation 550.4').

One of the four spillway gates was open and discharging. All four gates were operated successfully during our inspection.

The downstream toe stilling pool including concrete walls and rip rap were in good condition.

The immediate downstream channel is obstructed by a canal aquaduct and a highway bridge. These structures do not present a concern to overflow capacity.

d. <u>Overtopping Potential</u>: To determine the overtopping potential of Delta Dam, flood routing was conducted.

This potential was investigated through the development of the probable maximum flood (PMF) for the watershed and the subsequent routing of the PMF through the reservoir system. The PMF is that hypothetical flow induced by the most critical combination of precipitation, minimum infiltration losses, and concentration of run-off at a specific location, that is considered reasonably possible for a particular drainage area.

The drainage area contributing to Mohowk River at Delta Reservoir is approximately 150 square miles. Snyder coefficients were developed through watershed modeling done by the Corps. An average Cp = 0.75 and tp = 12.3 were established to define the basic hydrologic working tool, the unit hydrograph. Using Hydrometeorological Report No. 23, the PMP index rainfall was determined to be 19.0 inches for a 24 hour duration, 200 square mile basin. The percentages of the index rainfall applied to other durations were interpolated from the plot of drainage area versus percent of 24 hours, 200 square miles. The computed PMF peak flow was 83,000 CFS. After routing the PMF through the impounded storage, the peak flow was reduced to 67,900 CFS. A plot of the PMF inflow and outflow hydrographs is included in the Appendix. Assumptions made concerning the discharge-storage capacity of the dam were:

- The reservoir pool was assumed to be at elevation 550.0' (spillway crest).
- 2. It was assumed that all four gated spillway pipes were closed in developing a discharge rating. This condition is possible and leads to a slightly conservative analysis.
- 3. A weir coefficient of 3.18 was calculated from available spillway capacity data. The coefficient was assumed accurate for H>4'. A total spillway length of 300' was assumed correct from construction drawings. For discharges above top of dam elevation (558') a weir length of 662' with a coefficient of 2.8 was added to the spillway discharge to allow for flow over the dam.
- Elevation Storage data was calculated using U.S.G.S. topographic maps.

The ability of the Delta Dam to discharge the standard project flood (SPF) was also evaluated. The SPF peak flow of 49,600 CFS was routed through the impounded storage and reduced to 37,400 CFS. The SPF outflow is indicative of a pool elevation of 560.2 feet above MSL. The dam is overtopped by 2.2 feet, the spillway crest by 10.2 feet. The PMF outflow of 67,900 CFS is equivalent to 5.2 feet over the dam (13.2 feet above the spillway crest).

> Summary of Flood Routing Delta Reservoir

Elevation Top of Dam = 558.0'

Elevation Crest of Spillway = 550.0'

PMF Routing

5.200

quid.

1.14

5.17 2

at to

· maria

- - - -

in the

PMF Peak - 83,000 cfs

PMF After Routing Through Reservoir - 67,900 cfs

Elevation of Routed PMF Corresponding to 67,900 cfs - 563.2'

Dam Overtop - 5.2'

Spillway Surcharge - 13.2'

#### SPF Routing

SPF Peak - 49,600 cfs

SPF After Routing Through Reservoir - 37,400 cfs

Elevation of Routed SPF Corresponding to 37,400 cfs - 560.2'

Dam Overtop - 2.2'

Spillway Surcharge - 10.2'

5.2 Hydraulic Evaluation of Flood Wave

a. General: For the dam break analysis the flood wave for both the total and partial failure were calculated. The dam is a cyclopean masonry gravity dam founded on rock. Partial failure appears to be the more probable of the two cases.

A summary of flood wave calculations follows this discussion. For both total and partial failure damage to structures 21,000 feet downstream in Colonial Park can be expected. The total failure would flood portions of the city of Rome, New York. Partial failure flooding would be limited to structures within 15 to 20 feet of river level. For partial failure structures located along Route 46 within 2 miles of the dam would be damaged.

Hydraulic Evaluation of Flood Wave: Total storage = 86,800 AF. 2 =1.558 distance As Full breach from Dam  $W_b = W_d = 950$   $D_b = Y_o = 90$  <=1Qmax = 1.36 x10 cfs Reach 1. 1= 2000 W=1200' 2000 Qmax = 1.25 × 10 (cfs) Dos = 70 Reach Z. 1= 2000, W=120> -4000 Dos= 52 Qmax = 1.13 ×10 cfs 8000 W= 3000' Reach 3. L= 4000' Dps = 34 Q max = 1.0 × 10 cfs Reach 4. L= 2000 w = 2500' 10,000 Dps=36 Qmax = 900 x10 cfs 13,000 Reach 5 L=3000' = 2500' D Ridge Mills  $D_{DS} = 33$ Q ..... = 830 × 10 cfs 13

L. ROBERT KIMBALL JOB NAME \_\_ BY\_\_\_\_ DATE SHEET NO. JOB NUMBER \_ OF Consulting Engineers Reach 6 L= 4500' W= 2500' 17,500 Dos = 31.5 Qmax = 750 x10 cts Reach 7 L=3600 W= 3000 21,100 Flort Are Br. Dos = 28 over Mohauk 1 .... River Q max = 750,000 cfs 1 : 1 - 2.1.L. Construction Activity of the second s ..... ..... ..... and the beaution of the ..... ------..... ..... ----------1 ...... \_\_\_\_\_ 1 -----. . . . . . . ...... -----to a summer and a second second . ..... ..... ...... . . . . . . . . . . . . . . . A construction in the second sec ----- Колтонски страни и продакци и прод И продакци и И продакци и п -----...... . . . . -------------........ --------------...... 1T ....... -----...... 14 .... ------ -----

b) Partial Fail A=sume Wb=50 Db=Y0 = 90  $K = \frac{950}{50} = 19$   $K^{0,28} = 2.23$ Qmax = 163,000 cfs distance fri dam Reach 1 L=2000 W= 300 2,000-Dos = 23 Qmax = 148,000 cfs Reach 2 1= 2000 W= 1200 4,000 Dos=16.5 Qmax = 135,200 cfs L = 4,000 W= 1,100' Reach 3 8,000 Dos=16.5 Qmax= 124,000 cfs Reach 4 L = 2000 N = 1000 10,000 Dos=16.3 Rmax= 110,000 cts L = 3000 W = 800 Reach 5 13,000 Dos=17.5' Qmax= 193,000 cfs L=4500' W= 900' Reach 6 17,500' Dos=15 Qmax=38,000 cfs L= 3600' W= 900' Reach 7 21,100' Dos= 14 Qmax = 79.250 cfs 15

#### SECTION 6: STRUCTURAL STABILITY

#### 6.1 Evaluation of Structural Stability:

2

1

T

- a. <u>Visual Observations</u>: No misalignment or settlement of the structure was observed. Water was flowing over the spillway and prevented a close examination of the crest slab.
- b. Design and Construction Data: Design data are not available except from the 1924 report which is presented in this report. Construction data are not available. Dam sections were reviewed by Thos. H. Wiggin in 1924 with the water surface at Elev. 556.0 (6' above spillway crest) with and without water pressure beneath the dam. The line of resistance falls within the middle third assuming no water pressure beneath the dam and falls a short distance outside of the middle third if water pressure is assumed to penetrate 2/3 of the area beneath the dam.
- c. Operating Records: No information was available on operating records pertaining to the stability of the dam.
- d. Post Construction Changes: There have been no post construction changes which should affect the stability of the structure.
- e. <u>Seismic Stability</u>: Seismic stability computations are not available. The reservoir is located on the border between seismic zones 1 and 2 and is assumed to present no hazard unless static conditions are unfavorable or marginal.

#### SECTION 7: ASSESSMENT/REMEDIAL MEASURES

#### 7.1 Dam Assessment:

- a. <u>Safety</u>: This dam does not appear to present an immediate danger to life or property. However, the cracks, seepage and leaching of the concrete may increase with time and reduce the stability of the structure. The dam does not appear to present any serious operational deficiencies. The spillway is not adequate to pass the SPF.
- b. <u>Adequacy of Information</u>: The information available is inadequate for complete analysis of the dam. The validity of the information available appears to be good. Analysis of stability for maximum highwater and actual uplift pressure is needed.
- c. <u>Urgency</u>: The condition of Delta Dam is considered to be a nonemergency situation not requiring immediate action to protect downstream development. However, due to the presence of cracking, seepage and leaching, a follow upstudy should be conducted before the situation becomes worse. The hydrologic analysis indicates that remedial action is necessary in the near future to provide adequate hydrologic controls for the PMF.

### d. Necessity for Future Analyses:

- A test boring, pressure testing, and laboratory testing program should be conducted to evaluate the internal integrity of the structure.
- 2. Piezometers should be installed to monitor the uplift pressure on the structure.
- 3. The stability of the structure should be re-evaluated using the data obtained above and consider maximum high water.
- 4. The cause of the seepage should be further investigated as suggested in the Materials Bureau report (see appendix D).

#### 7.2 Remedial Measures:

- a. <u>Alternatives</u>: The Materials Bureau report should be followed up using the alternative decided upon by the New York Department of Transportation.
- b. Remedial modifications should be made within the next two years to increase storm storage and/or spillway capacities if the structural stability of the dam at the high water level (PMF) is inadequate. Additional spillway facilities may be added at the abutments and/or the reservoir pool lowered.
- c. An adequate regulation plan and warning system should be developed for use in the event of a threatened failure.



#### DELTA RESERVOIR

The bedrock in this region is composed chiefly of Utica Shale, which is of Middle Ordovician Age. These rocks are basically horizontally bedded with only a slight dip to the south. The area is relatively stable tectonically.

During the late Cenozoic Era, this area was heavily glaciated. This produced sediments of various thicknesses and consistencies, particuarly in the valley bottoms.

Construction of the local division of the lo

11

Formation of

ll

### APPENDIX B HYDROLOGIC COMPUTATIONS

I

T

-

----

-----

A summer

-

a statement

Low real of

[]

[]

1

-

I

I



Consulting Engineers

I

in a

[]

Π

[]

Transformer of

Townson of

-

I

Ĩ

JUD MANL

SHEET NO \_\_\_\_ OF

DELTA DAM

## ELEVATION - DISCHARGE RELATIONSHIP

ELEV	OVER	FLOW	SECTION	NON -OVE	RELOW	SECTION	TOTAL
(FT)	с	H	((.3.5)	с	Н	(c. s. s.)	(C.f.s.)
550.0		0	0				0
550.5	3.18	.5	337				337
551.0	3.18	1	954			••••••••••••••••••••••••••••••••••••••	954
552.0	3.18	2	2,700				2,700
553.0	3.18	3	4,957			-	4,957
554.0	3.18	4	7,632				7,632
555.0	3.18	5	10,666	Cantorna	-		10,666
556.0	3.18	6	14,021				14,021
557.0	3.18	7	17,668				17,668
558.0	3.18	8	21,586			-	21,536
559.0	3.18	9	25,757	2.8	1	1,854	27,611
560.0	3.18	10	30,167	2.8	2	5,243	35,410
562.0	3.18	12	39,656	2.9	4	14,829	54,485
564.0	3.18	14	49,972	2.8	6	27,242	77,214
566.0	3.18	16	61,054	2.8	8	546,14	102,996

JOB NUMBER SHEET NO. Consulting Engineers OF DELTA DAM ELEVATION - STORAGE RELATION SHIP SUR FACE ELEV. A ELEY DISCHARGE TOTAL Q STORAGE (FT.) (FT.) (ACRES) (C.F.S.) (AC.FT) 550.0 2,673 0 0 0.5 550.5 2,712 1,346 337 0.5 551.0 2,751 21712 954 1.0 552.0 2,829 5,502 2,700 1.0 553.0 2,907 1,957 8,370 1.0 554.0 2,985 11, 316 4,632 1.0 3,063 555.0 14,340 10,666 1.0 556.0 3,141 17,442 14,021 1.0 557.0 3,219 20,622 17,668 1.0 3,297 558.0 23,880 21,586 1.0 559.0 27,216 3,375 27,611 1.0 560.0 3,453 30,630 35,410 2.0 562.0 3,609 37,692 54,485 2.0 564.0 3,765 45,066 77,214 2.0 566.0 3,921 52,752 102,996



		Dots par I
	essessangerseverser estern visted Jah 1472 web-1 visted Jah 1472	
	1900 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	
	restriction at the Plant Cubical Plan	
	NO WERE AND THE FORM AND THE PART AND	
	1.4.1 5 0	
HID     Numeration       HID		
	SURFACE FRANKE COMPUTATION 15130 15134 1555 1164E JACI JAPE JACE 0 0 0 0 0 0	
<ul> <li></li></ul>	There is a start with the with the start of	
True der eine alle liebe der eine der e	алт, улу ула 104.00 104.00 104.00 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.	
Jesserererererererererererererererererer	STAR DITE STAL DITE STAL STAR STAR STAR CAST ALSON WINN STAR DITE STAR STAR STAR STAR STAR CAST ALSON WINN STAR DIE 110 0.0 1100 0.07 0.02	
Approximation     *100 million     *100 million     *100 million     *100 million       Approximation     *100 million     *100 million     *100 million     *100 million       Approximation     *100 million     *100 million     *100 million     *100 million       Approximation     *100 million     *100 million     *100 million     *100 million       Approximation     *100 million     *100 million     *100 million     *200 million       Approximation     *100 million     *100 million     *100 million     *200 million       Approximation     *100 million     *100 million     *200 million     *200 million       Approximation     *100 million     *100 million     *200 million     *200 million       Approximation     *100 million     *200 million     *200 million     *200 million       Approximation     *200 million     *200 million     *200 million     *200 million       Approximation     *200 million     *200 million     *200 million     *200 million       Approximation     *200 million     *200 million     *200 million     *200 million       Approximation     *200 million     *200 million     *200 million     *200 million       Approximation     *200 million     *200 million     *200 million     *200 million	The Levis chained that a	
0017     From 0.11     From 0.74     Volue 1.00       002     1014     001     001     001     001       002     1014     001     001     001     001       003     1014     001     001     001     001       004     111     001     001     001     001       004     001     000     001     001     001       004     001     000     001     001       004     001     000     001     001       004     000     000     001     001       004     000     000     001     000       004     000     000     000       004     000     000     000       004     000     000     000       004     000     000     000       004     000     000     000       004     000     000     000       004     000     000     000       004     000     000     000       000     000     000     000       000     000     000     000       000     000     000		
	DULT HINAUSCIEN 2. SAME PARENT DISULTING TO THE PARENT CHE 0.74 YOUR 1.00	2/10
	20.25. 11-15. 1905. 1905. 1905. 1905. 242. 242. 242. 242. 242. 255.	185.
	The Pair excs done is .	
	· (*)5 (*)0 671.	
	7 0.15 1.00 77. 2 0.15 0.01 27. 2 0.10 235.	

and that are a
Ι torne a Contract of the Concernant of -AL VOLUNE 753722. 15.73 12522. [] 72-H0UR 21115-12-71 12-71 24-4004 54296 13.46 • 17+95 • 00-50+ • 00-5 and the second Π [] 0



I I I																										П	-		
		******				31092. 42000.																							
		0000000000	T JPHI INARE	5 15AME	к 75r SТОНА 0.0	41. 2004. 2756/.	0- 00T	243. 243.	242.	240.	6.5% • 14.6 • 25.0	219.		254. 247.	515. 18.	1794.		31143.	61137. 57855.	e 1446. • 1426.	5.741. 0-091.	Se Cak.	21362.	17403.	) 4630.	10484.	96.3U. 4326.	7391. 5689.	
		0.0000000000000000	<pre>x Jec.searer exuT(9): + 003 [fart, Jec. 0 0 0 # 0.01 [Ne 3418</pre>	1.055 AV.0 1.05	LAU A (200	15015. 21 19000. 17	stue avé la s late cest	1-2. C+1.	115. 225.	110. 221. 175. 221.	fro. 831.	7	7:05 2:01. 7:04 2:85. 2:95. 3:37.	812. 870. 970. 179.	1771. 34575. 1771. 34575.		1611. 170711.			1411. 55470. 107. 5374.	Pact. alone.	Intra Parta.		2324. 1.45.				1402. 1464. 1840. 1762.	
		0.000.0000	Tstag house a	0.035 C	1.1.4. 1.1.1.	and	TINE ELF						<u></u>	2.01	1.0				- 12 - 12	1 1 12	15		10	2 CE 2 TE	6	1 24	1 c.	C 1	
	4	00703000				5702465e 0.																			the second se				
	4.70		.42	·	Sit in its	15000 1	240 500	1004 2																		П			







|--|





		- *	1				1	1								1			-		1			1		*				Γ	1	
	4.																															
	П						45066. 77214.																									
	П		0000000				37692. 54485.																									
	LI LI		0 3 3				27567.																									
			8838558	47 1424E	90 0	54 ST04A	24504. 21566.																									
			9 9 9	9LT JP	.ess 150	0.0 0.0	21441.	509 0UT	.543.	243	240.	239. 236.	230. 235.	634 . 633 .	233.	229.	122	224.		363.	501.	101.	1140.	1 = 0 7 .	2344.	3448. 6122.	.173P	-62112	29246.	37363.	32056.	24046.
			0000000	apt soulling liters u	avo 0a14 avo 0.0	AM54K 0.0	15415.	AV6. 111	541.	635. 669.	214.	213.		610. 617.	216.	619. 203.	94.	140.	0.37.	1999.	673.	3550.	3529.	3524.	16.41 .	23173.	5:020.	4/574.	465.44.	40402	88614.	14593.
			000	FEDROSS FECOU	1.05% (21.05% 0.0	n hu	12752.	sus sign	12.	175.		76.34	100	144.	147.	735.	169.	714.		1231.	20.55.		3013.	4034.	5561.	10370.	14512.		65507.	31249.	·2+2+2	
124 - 124 -			******	L LCOMP	0.0	is istor	0125. 2700.	awt i		(* ± 0		- 1	* 31	1 4 1	14	r <u>t</u>	13	P C	23	2	2.2	12	5.5	e é	25	5 . I.	53	1.5	55	04		::
5 109265 = 0. 5 109265 = 0.			9.9.9	Is1.		12.11	3043. 954.																									
STORAGE = DUTFLORE =	F		000000				 																									
	I	8	0000				5108465 a 001751,0% a		and the second s																							







# APPENDIX C PHOTOGRAPHS

.

1

-

[]

-

[]

-

Π

[]

#### Description of Photographs Delta Dam

### Plate

 Overall view of the dam from left abutment. Note: Seepage visible on section of dam below gate house.

#### APPENDIX C

- Left abutment portion of dam from downstream. <u>Note</u>: Deterioration of gunite facing, seepage. <u>Visible</u>: Old gate house at toe, stilling pools for principal and emergency spillway.
- 3. Right portion of dam from downstream. <u>Note</u>: Deterioration of gunite facing, sprays in spillway apparently caused by deterioration in concrete. Visible: Stilling pool, rip rap protection.
- 4. View of immediate downstream area from top of dam.
- Looking at major seepage area below gate house from top of dam. <u>Note</u>: Vegetative growth in face, rolling and bulging of gunite facing. <u>Amount of seepage depicted by ground saturation and puddles at toe.</u>
- Close up view from downstream of right abutment of dam.
  <u>Note</u>: Vegetative growth and deterioration of gunite facing.
- 7. Close up view of downstream face of left abutment of dam.
- Close up of deterioration of gunite facing on downstream face of left abutment of dam.
- 9. Upstream face and gate house from left abutment.
- Upstream face from gate house. Note: Erosion of concrete on upstream face at water line.











PLATE 6



PLATE 7





APPENDIX D PERTINENT CORRESPONDENCE AND REPORTS

and the second

[]

[]

[]

Ш

# NEW YORK STATE DEPARTMENT OF TRANSPORTATION

Raymond T. Schuler, Commissioner

176 OCI 20

1220 Washington Avenue, State Campus, Albany, New York 12226

CONSTRUCTION NAMAGEMENT

October 26, 1976

Mr. George Koch, Supervisor Dam Safety Program NYS Department of Environmental Conservation 50 Wolf Road Albany, NY 12233

Dear Mr. Koch:

## Re: Dam #935 Delta Reservoir Mohawk River

Pursuant to your letter of August 12, 1976, an inspection of the subject dam was made by members of the New York State Department of Transportation employees from the Materials Bureau and Soil Mechanics Bureau of the Technical Services Subdivision and from the Main and Regional Offices of the Waterways Maintenance Subdivision.

The inspection group found no soils problems with the dam.

Leaking appears on the downstream face of the dam in several isolated areas beneath the gate house. The amount of water appearing at the face is sufficient to indicate that water is passing through the dam. However, since the dam is a concrete structure which is keyed into bedrock, the leaks are not considered serious enough at this time to classify the situation as an emergency.

The entire dam face including the spillway and buttresses have been repaired with shotcrete at various times. The condition of the shotcrete is poor. Many cracks and deteriorated areas exist in the shotcrete. Also we found that the shotcrete emitted a hollow sound when struck with a hammer in nearly all areas that were reachable. This indicates that the shotcrete is not bonded to the dam.

The shotcrete repairs cover all original vertical and horizontal construction joints. Water may be coming through the dam in a very few locations, most likely the joints, and spreading between the original concrete and the debonded shotcrete layer. This can account for several surface leaks on the dam face.

XXXXXXXXXX

Feter A.A. Berle.

#### August 12, 1976

Mr. Joseph R. Stellato, Director Naterways Maintenance Subdivision D.O.T. Administration & Engineering Bldg. State Compus Albany, New York

#### Re: Dam #935 Delta Reservoir Mohawk River

#### Dear Mr. Stellato:

In conformance with the Dept. of Environmental Conservation Dam Safety program, an inspection was made of the referenced dam on August 8, 1976. The inspection indicates that the concrete in the downstream slope of the dam is spalling and in need of repair. Our previous inspection of this structure was on April 5, 1973. A review of our reports and photos from the two inspections indicates that the concrete deterioration has increased to the extent that now there is a leak in the east abutment approximately two-thirds of the height above the base.

Our records indicate that a letter was sent to your office on April 16, 1903 recommending concrets repair work on the downstream slope. Your letter of April 18, 1973 to Mr. Stanford Zeccolo indicated that a contract would be let to repair the damaged concrete areas. These areas have not been repaired but have deteriorated more.

Because of the large reservoir storage (75,000 A.F.) behind the dam, we feel it is imperative that the concrete maintenance is taken care of before any serious problems develop. After your regional engineer has had an opportunity to inspect the dam, we would like to know of your intentions.

Very truly yours,

George Koch, Supervisor Dam Safety Program

DR. Marale beleer of chronice D.u.T. Motoricis people took somples. 10/13/76 GK:bt De I Phone H. Zywick 9/17/76 14 Foid Fingis from D.U.T. Hilberg will inspect den in about a wrake and he will then repaire their decision. G. Kuch it Sert cc: Henry B. Zywiak

Mr. George Koch October 26, 1976 Page 2

Materials personnel in cooperation with Regional Waterways will conduct an evaluation of the dam. This evaluation will begin by trying to locate the leaks through the dam and the first step will be the opening up of some of the drains on the downstream face which are located at the vertical construction joints. Plugged drains may be a key factor. If the evaluation of the vertical drains does not provide an answer as to where the leak(s) is located, then exploration holes will be made through the shotcrete layer at selected areas. With favorable weather conditions, it is anticipated this evaluation will be completed this fall.

Upon completion of this evaluation, the proper course of action for Waterways to follow will be decided upon.

Waterways will keep you advised on the evaluation and whatever course of action may develop from it.

Sincerely yours, Edward M. Rowan TO

JOSEPH R. STELLATO Director of Waterways Maintenance

# Bureau of Water Regulation

#### April 16, 1973

Mr. Joseph R. Stellato, Director Waterways Maintenance Subdivision D. O. T. Administration & Eng. Bldg. State Campus Albany, New York

Dear Mr. Stellato:

D.O.T.Reg. Dam No. 935 (114-A) Across Mohawk River at Felta Reservoir Town of Rome, Oneida County D. O. T. Reg. Dam No. 372 (115-K) Across Mohawk River Town of Rome Cheida County

In conformance with this Department's Dam Safety Program, an inspection was made of the above-referenced dams on April 5, 1973.

A review of our files reveals that these dams are ouned by the State of New York. I am assuming that your division is responsible for the maintenance of these structures. If I am in error, please advise.

The Felta dam was constructed in 1912 and consists of a concrete-stone structure approximately 980 feet long and 100 feet high forming an impoundment approximately two miles across at its greatest width and four miles long. The reservoir was created as an addition to the State water storage system for supplying the barge canal.

Our findings reveal that spalding of the concrete has occurred along the wall faces.

Dam No. 932 (115-K) was constructed prior to 1917 and consists of granite blocks mortared together. The structure is approximately 180 feet long and sim feet high. The dam is approximately one-quarter of a mile upstream if from the canal and is the second dam upstream from the canal. It was constructed to act as an ice breaker to protect the canal system.

...

# DEPARTMENT OF TRANSPORTATION

**Raymond T. Schuler, Commissioner** 

1220 Washington Avenue, State Campus, Albany, New York 12226

April 18, 1973

Mr. Stanford Zeccolo Sr. Hydraulic Engineer NYS Dept. of Environmental Conservation Bureau of Water Regulation 50 Wolf Road Albany, New York 12201

	- Chen
Brading	E MEI. SERV.
AP	R 2 0 1973
EUD.	WATER REG.

Dear Mr. Zeccolo:

Re: DOT Reg. Dam No. 935 (114A) DOT Reg. Dam No. 932 (115K)

We have forwarded your letter of April 16, 1973 concerning the above referenced dams to our Region 2 Office in Utica. The dams are under our maintenance.

The spalling on the concrete wall faces of Delta Dam is a condition we were aware of and monitor closely. We plan eventually to let a contract for the refacing of these areas.

The tree growth occurring at the Upper Retention Dam at Rome will be eliminated by our Section 4 Maintenance Forces.

Thank you for bringing these findings to our attention. All of our dams are scheduled for inspection this August under our Structure Inspection Procedures.

Sincerely yours,

JOSÉPH R. STELLATO Director of Waterways Maintenance

JRS: JD: dl

Our findings concerning this dam reveal that trees are growing in the gratte joints along the obutments. This growth could cause serious damage to the structure.

We suggest that your office investigate the above situations. Maintenance at this time could save more expensive repairs in the future.

. .

Very truly yours,

... N: 53.2

Stanford Zeccolo Sr. Hydraulic Engineer

SZ/Ed cc: L. Blake

DELTA DEC DAM INSPECTION REPORT 3 4 33 3 CTY YR. AP. DAM NO. INS. DATE USE TYPE BUILT INSPECTION Location of Spillway Elevations and outlet Size of Spillway Geometry of and outlet Non-overflow section GENERAL CONDITION OF NON-OVERFLOW SECTION Settlement Deflections Cracks Joints Surface of Leakage -Concrete Undermining Settlement of Crest of Dam Embankment Downstream Upstream Toe of Slope Slope Slope GENERAL CONDITION OF SPILLNAY AND OUTLET WORKS Auxiliary Service or Stilling Spillway Concrete Spillway Basin Joints Surface of Spillway 2 Concrete Toe Mechanical Plunge Drain 7 Equipment Pool Maintenance Hazard Class Evaluation Inspector Surface concrete spalling COMMENTS: 8/5/76 Add. troud spalling theakerse.

DAM INSPECTION REPORT (By Visual Inspection) Date & Inspector & Dam Number Hazard Class\* River Basin County Town 935 Uneidal Mchauk Rome Type of Construction Use Water Supply CEnal Earth w/concrete spillway Earth w/drop inlet pipe Power Earth w/stone or riprap spillway Recreation Concrete Fish and Wildlife Stone Farm Pond No Apparent Use-Abandoned Timber Estimated Height of Dam above Streambed Estimated Impoundment Size Under 10 feet 1-5 acres 10-25 feet 5-10 acres Over 25 feet 200 Over 10 acres Condition of Spillway Service satisfactory In need of repair or maintenance Explain: 4 Cap coming off Condition of Non-Overflow Section Satisfactory In need of repair or maintenance Explain: Concrete dracting Small Isakego. Condition of Mechanical Equipment 4-Satisfactory In need of repair or maintenance Explain: Evaluation (From Visual Inspection) 4 No defects observed beyond normal maintenance Repairs required beyond normal maintenance \*Explain Hazard Class, if Necessary

Boonvelle Guadraugre -NO ICE: Lint filling out one of these forms as completely as partible for each dam in your district, return it at once to the STATE OF NEW YORK CONSERVATION COMMISSION ALBANY DAM REPORT Wohaw & 6 / 15 , 191 5 CONSERVATION COMMISSION, DIVISION OF INLAND WATERS. GL STLEMEN: I have the honor to make the following report-in relation to the structure known De as the ..... Dam. This dam is situated upon the Mohowk River in the Town of Rome , Queida County, about 5 miles from the Hilles City of Roue T. . 2 distance do wh stream from the dam, to the highway bridge, (Up or down) is ibout 750 ft. The dam is now owned by M.Y. Alale as I was built in or about the year 1912, and was extensively repaired or reconstructed di ing the year ...... As it now stands, the spillway portion of this dam is built of Couchelle or timber) As nearly as I can learn, the character of the foundation bed under the spillway portion rock and under the remaining portions such of the dam is A to adation bed is solid rock

DAM INSPECTION REPORT (By Visual Inspection) Date Dam Number River Basin & Inspector Town County Hazard Class\* 9.35 Charak Inpida RAMe Type of Construction Use Earth w/concrete spillway Water Supply CGAL Earth w/drop inlet pipe Power Earth w/stone or riprap spillway Recreation Concrete Fish and Wildlife Stone Farm Pond Timber No Apparent Use-Abandoned Estimated Impoundment Size Estimated Height of Dam above Streambed 1-5 acres Under 10 feet 5-10 acres 10-25 feet Over 10 acres Over 25 feet 200 Condition of Spillway Service satisfactory Service satisfactory Auxiliary satisfactory In need of repair or maintenance Explain: 4 Cap coming off Condition of Non-Overflow Section Satisfactory Condition of Mechanical Equipment A Satisfactory In need of repair or maintenance Explain: Evaluation (From Visual Inspection) A No defects observed beyond normal maintenance Repairs required beyond normal maintenance \*Explain Hazard Class, if Necessary

The total length of this dam is 980feet. The spillway or waste-200 feet long, and the crest of the spillway is eir portion, is about. about feet below the top of the dam.

The number, size and location of discharge pipes, waste pipes or gates which may be "sed for drawing off the water from behind the dam, are as follows: 4 waste pipes in bollow at point indicated - each 5 ft. in diameter.

ate briefly, in the space below, whether, in your judgment, this dam is in good condition, or bad condition, describing particularly y leaks or cracks which you may have observed.)

This daw is in very good condition. There are no leaks -cracks in it.

Reported by CWHDouglass, 15 Staudast St.

vacuse, M.G.

SEE OTHER SIDE)

Apillivary Section a the space below, make one sketch showing the form and dimensions of a crime prover interval the spitway or waste-weir of this im, and a second sketch showing the same information for a cross section rough the ther portion of the dam. Show par-sularly the greatest height of the dam above the stream bed, its thickness at the top, and chickness at the bottom, as nearly as u can learn.) 4. screte abut we full we 2 Jo ou 1 F5 eid rock bottom In the space below, make a third sketch showing the general plan of the dam, and its approximate position in relation to buildings or ther conspicuous objects in the vicinity... sec ou 2 a) =10 Coverete 19.2 30 ou 1 batter 8 showing position of wasterpiper rock colo 3
MEL ED SGC C F FE ACLES FLAM G. V FER WORKS AL V IPAL NGINEERS IC. FOR TESTING ATTENIALS

### THOS. H. WIGGIN CONSULTING ENGINEER 50 CHURCH STREET HUDSON TERMINAL BUILDING ROOM 367 TEL. CORT. 7785 NEW YORK

REPORTS. DESIGNS. SUPER //GIGN, VALUATION WATER SUPPLY SEW/14/32 CAMAS PLOSS CONTROL TUNINELS REINFORCED CONCRETE INSPECTION OF SPECIAL MATERIAL INVESTIGATION OF SPECIAL PROCESSES

?

NEW YORK

Juno 7th. 1926.

Lessra R. H. Freder. A. P. Enight. J. D. Black.

Committee of the Chamber of Commerce. Rome. Now York.

Gentlemen:-

In accordance with a letter dated March 8th and telegram dated March 14th, 1924 from Mr. Fraser of your Committee. I have made an investigation of the Delta Dam. located on the Mohawk River about 5 miles north of Rome and forming a part of the state Barge Canal feeder system and beg to report as follows:

The Delte Dam is a cyclopeen mesonry structure about 90' high in the deeper portions and about 1000 feet long. At the center is a spillway section 300 feet long. The dam impounds approximately 20 billion gallons of water, which is used to feed the summit level of the Barge Canal. The investigation was undertaken under the suspices of the Chamber of Commerce, owing to approhension for the safety of the dam felt by citizens of Rome because the surface of the dam both upstream and downstream, but more particularly downstream, is disintegrated over considerable areas. The disintegrated concrete can be removed by pick or bar to a depth of 6" in places. The disintegration is apparently due in part to seepage of water through the dam (on the

#### Dolta Dam.

coping which also shows disintegration, moisture comes from rain or snow) and the freezing of the saturated concrete in cold weather. Even with seepage such action would not generally be nearly so-marked and the secondary cause is probably weakness and excessive perosity of the surface concrete. Many concrete structures, including a number of well-known dans show similar, though generally less marked deterioration. The attention of many prominent investigators is now focussed on Portland cement and its permanence is being questioned even where under cover of earth or water. However, important disintegration is seldem found where there is not exposure to moisture and frost.

The dam was inspected in company with all the members of your Committee on March 18th last and again on May 9th. A heavy crowber was used at many points on the downstream face that could be reached from the ground and at some other points higher up which were reached from a short ludder. One bad spot on the upstream face of the easterly bulkhead portion was examined from a hanging ladder. The worst spots were found on the downstream face on the bulkhead section east of the spillway. Some of these places were 6 feet or so long and 4 feet or so in maximum height and the disintegrated material was easily removed to a depth of about 6 inches. The downstream face of the bulkhead portions of the dam to a height of 10 or 15 feet above the ground was rather generally covered with a shell of calcareous matter from 1/2" to 1" in thickness which could be scaled off in large sheets. This material was evidently deposited by water which came through the dam and represents soluble parts of the coment. The action is akin to that by which stalagmites are formed in limestone caves.

#2.

Delta Jam

Benaath this shell the concrete was generally in fair condition. It was noted on the Eay 9th visit that flood waters which spilled over the dam between the March 18th and the later visit had washed away all the badly disintegrated concrete from the downstream face of the spillway, leaving many depressions.

200

Some of the soft material that was removed by the bar appeared to have more than the normal quantity of sand but most of it had plenty of stone and the stone seemed to be sufficiently solid. From this inspection it was concluded that the concrete would be able surely and for some years to come to carry its full empected stress out to within 6 or 8 inches of the surface and in the computations that have been made, it was assumed that the exterior 8" did not bear stress but was effective so far as weight is concerned.

The investigation has covered the following points:

- 1. Materials and workmonship in the dam and foundation conditions.
- 2. .acquacy of the design.
- 3. Damage that would be occasioned by failure.

4. Lethods of repair.

In the report following these topics will be taken up in order, using the same numbers.

#### 1. MATERIALS AND WORTHANSHIP AND FOUNDATION

The surface defects in this dam are evident to all who have examined it. By the use of the crowbar as previously doscribed, it is found that the concrete is solid except for a thickness of 3" at the bazimum and generally it is solid nearly to the surface. The solidity of the interior is indicated in the gate well which can be examined by removing iron covers west of the spillway. It is also noticeable that concrete in the upper part of the dam is generally sound except in parts of the coping and that concrete in the ornemental arches forming the cornice is particularly good, possibly owing to a greater proportion of cement in the concrete. The cornice is also too high up to be affected by leakage through the dam and is well sheltered besides.

The State Engineer's office has kindly furnished me with laboratory reports of sand and coment quoted below and several engineers who were present at times during the construction of the dam have described from memory their impressions.

	Coment: Dragon Fortland.	Tensile of 1 : 3 tes. Lbs. per	strength briquet- Sq. In.	Rati to Sto Sand	10 1. 1.	<u>Voida</u>	Loar
		7 devs	28 deys	7 days	28 de	73	
1.00	Frenchville bank send Do washed Stendard send	165 189 216	253 273 277	76 87 100	91 99 100	37.0	4.5
4. 5. 6.	Crusher dust Do with send, ratio 1:4 Standard send	289 185 195	424 271 322	147 95 100	152 84 100	50.5	:
7. 8. 9.	Westernville bank sand Do washed Standard sond	234 193 170	345 317 324	158 113 100	106 95 100	31.8	7.0

Coment & Sand Tests - From Records of State Engineer

Coarse aggregate:- Crushed limestone from quarry near Booneville, N. Y.

From such information as I have gathered, the Frenchville

Dolta Dam.

cand seems to have been used. I examined the bank with you on hey 9th and it is easy to understand references to lumps of elay which got into the send. The sand itself seems to occur in clean bands and pockets but is covered and more or less interbedded with elay. It is stated that the sand was carefully inspected for elay but was not always satisfactory and that after some time washing at the pit was required. One statement was to the effect that a proportion of crusher dust was sometimes used but no convincing ovidence of this is available and the contractor esamet recall that any was used.

I conclude that lines 1, 2 and 5 in the above table of tests represent the material probably used at various times. Two of the 7 day tests with standard sand and one of the 28 day tests are below the present requirements for strength of cement briquettes (viz 200 lbs. at 7 days and 300 lbs. at 28 days) but Portland cement of 2 or 3 decades ago was even less strong and made good masonry fully as often as the present product.

One engineer stated that the broken limestone used in the concrete was not so good as that used for the cyclopean blocks but had thinner beds and tended to make more dust. The pieces of stone found in the rotten concrete seemed hard and strong.

The dam was divided by vertical joints at right angles to the length of the dam into sections 50° long, with keys or dovetails between. These sections were filled alternately with concrete and carried up about 20° at a time. The photographs to which I have had access through the State ingincer and through

25.

2

~

5

engineers connected with the work, show this alternate concreting of sections and also show that the dam was brought to approximately one level for nearly if not all its length and then carried up again, saw tooth fushion. for another lift of about 20'. This method of construction provided for the minimum shrinkage cracks across the dam. Keys or devotable at these vortical joints tend to prevent leakage and to make the dam act as a unit. Large cyclopean stones projecting across every main horizontal joint furnish not only shearing or anti-sliding strength, but some tensile strength as well.

From an excellent descriptive article on the Delta Dam by Emile Low, one of the resident engineers on the Barge Canal, (Engineering & Contracting June 19, 1912, pp. 681-88) the following points bearing on construction methods are briefed:-

- (a) Lasonry consists of 1:22:5 concrete, rather soft, with 40,5 of large cyclopean stones imbedded. These latter were often over a cubic yard in size. They were scrubbed and washed thoroughly before being placed.
- (b) Cyclopean stones were kept back 12" from faces of forms and 6" apart horizontally from each other. Layers of stones were placed so as to break joints horizontally and vertically.
- (c) At horizontal joints cyclopean stones were left projecting so as to form a bond.
- (d) In joining new work to old, the old surfaces were freed of dirt and luitance and washed with thin mortar.
- (e) Concrete was mixed in batches containing 2% bbls. of coment, i.e. about ou yds. of concrete. The mixer was made by Thes. Carlin's Son's Co. and was a 5 ft. cube rotated on a diagonal axis. The average duily output of concrete was about 170 cu. yds.
- (f) Both concrete and cyclopean stones were placed by a double line of derricks. The stones were raised and lowered to "work up a bed in the fresh concrete".
- (g) During cold weather, heated stones were used. "with steam under canvas to prevent freezing".

#### Dolta Dim.

(h) The mixture was made "rather wet so that little tanging was required, but shovels were used to work the concrete down in marrow forms or between stones. The coarser aggregate was kept away from the forms by forgs. On rock foundation the surface was closred of all loose pieces, washed and wet coment or mortar perabbed over it with brooms".

In discussion with engineers who were present during the building of the dam, soveral difficulties in construction have been brought out. It was mentioned that the slope of the form for the too of the dam in connection with the attempt to get as many largo stones out under this form as possible, caused the exercice botween the form and the large stones to be less accessible and more likely to contain an excess of morter and laitance. The difficulty of keeping a soft bed under the large stones was also mentioned and scopage through the dam under these stones thought to be a possible result. On the other hand enother observer mentioned the concrete as being wet and the stones as being lowered into a sloppy matrix. A more permanent resident at the dam spoke of building up the stones locally because it was difficult to keep noist concrete under then if the concrete was spread out over the whole 30 foot section. This seems like a more probable condition then that of extreme sloppiness at the point of placing large stones and corresponds with the writer's observation on the large dams of the Catskill water system of New York City. Surfaces which are left for a little while become partly set and it is impracticable to embed stones unless fresh concrete is placed to cufficient depth to bury the unevennesses in the bottom of the stone. This difficulty is inherent in cyclopoun masonry but has been overcome in many dams to the extent necessary to avoid leak-

Jolts Jome

age and the probability of leakage should be loss than in the case of a rubble masenry dam where mortar has to be placed in every joint under and between stones.

On the whole it is difficult to account for the rather emossive scepage through the dam by any evidence that has been produced. The difficulty of avoiding excess of mortar and laitance in the concrete between the large stones and the sloping forms is a real one and was not encountered in most other cyclopeun dams because these in general had either stone or concrete blocks for their exposed faces and these blocks were laid shead of the concrete and took the place of wooden forms. It is possible that the quality of concrete in the downstream face may have been affected by this cause, accentuated by the use of too much water, which is now known to weeken concrete.

By investigation of eauses of weakness in the concrete halbeen necessarily superficial. However, the evidence in hand and personal acquaintance with the high character of the engineers connected with the design and supervision of the dam and with the good reputation of the contractor leave no room for a shadow of doubt in my mind that the work was done with unusual care and faithfulness and that the defects were due to unknown causes such as are all too common in cenent work. Thousands of dollars have been spent on studies of defects in concrete, frequently without disclosing convincing reasons. Investigations of the nature of Portland cement are being conducted by national and municipal agencies as well as by manufacturers' associations, foundations and technical societies. More are planned and the Delta Dam may well be included in examples to be studied.

2C.

Dolta Dama

### Post Loringa to be Made in Dan.

binge it is evident that a new face must be placed on the dam, it is perhaps not so necessary to know absolutely what is the cause of the present weakness but it is necessary to be assured that the weakness does not exist except near the outer surface and will not progress inward beneath the new faces. I have had several conferences with Col. Frederick S. Greene, Supt. of Public Works, Mr. Roy K. Fuller, Commissioner of Canals and Mr. Dwight B. La Du. State Engineer and Surveyor, with respect to these and other problems and it has been agreed that 3 core borings will be put down from top to bottom of the dam and at least 3 samples cut from the face of the dam in order to see the quality of the interior masonry and obtain some tests thereon. My present opinion is predicated on the assumption that these tests will show the interior concrete to be sufficiently sound for its purpose but until these tests have been completed, the conclusions reached in this report must be taken subject to that condition being found in the tosts.

### Foundations of Dam.

The foundations for this dam consist of level-bedded Eudson River shale and eye witnesses state that it disintegrates rapidly when uncovered. The stone which is now uncovered adjacent to the dam is very flakey and obviously unsuitable for a foundation. but I have no doubt that the rock under the dam is cufficiently solid for the moderate pressures required in this comparatively low dam. The borings previously mentioned will extend through the dam into the rock and will verify the quality of the rock as well as that of the musonry.

Assuming that the borings will show that the rock under the dam has remained sound, the most important question regarding foundation is whether the dam is adequately keyed into the rock so as to avoid danger of sliding which has figured in most of the limited number of failures of gravity dams that have occurred.

I have examined all the official and also such private photographs as were available and have also examined the official cross sections of excavation. These show that the dum is well keyed into the rock foundation in the whole of the bulkhead sections and in all but about 150 feet of the spillway section, viz. at the westerly end thereof. In this stretch of 150 feet there is practically only the roughness of the nearly level shale foundation and the cut off wall at the rear of the dam to prevent sliding. The spron which is 4 feet thick nears against only a shallow shoulder at the front. The mathematical significance of this defeet is explained further along under Adequacy of Design. At this place it will only be stated that the friction of mesonry against even the comparatively flat foundation furnishes sufficient resistance unless water pressure gets under the dam or ponetrates the horizontal seems in the rock immediatoly below the dam. Assistance from adjacent sections that are more completely bonded adds to security but improvements in the front footing of this 150 foot stretch of spillway are desirable. The section of bulkhead dam at the gate house is particularly well footed by its own depth into rock and by the walls and floor of the blow-off pool.

-10.

Dolta Dam.

The remaining question as to foundation is the permanence of the rock shoulder in front of the dam, particularly at the spillway. The apron and paving below seem to be still intest, judging from the downstream edge which is the only part projecting above the permanent water cushion pool, but no flood has occurred which has eaused a depth of more than 1'9" of water over the spillway. Some time will come a flood causing a depth of 6' or more. The condition of the paving and of the rock beneath and downstream therefrom could be carefully examined when the repairs are made. The contract for repairs should be so drawn as to permit relaying part or all of the paving and using cement grout in the joints if found desirable.

### Crouting Foundation.

This level bedded shalo foundation, while generally tight, may contain some horizontal seems between layers. Referense is made in Mr. Lowe's article above mentioned to a small quantity of leakage collected into drains which were to be grouted. The Olive Bridge Dan of the Catskill Water Works had a somewhat similar foundation and it was found comparatively easy to force grout or liquid mortar down through a vertical 2" hole into the rock and in some cases up into other drill holes as much as 50' distant. I cannot find that any grouting was done in the foundation of the Dolta Dam. The disadvartage in mmitting this grouting would be that of possible upward pressure exerted under the dam in the level seems in the rock. This matter will be discussed more fully under adequacy of Design. The best construction would call for a thorough grouting and then a system of drain-

.11.

ago beneath the dam for the downstream 2/3 or so of its width soas to remove the possibility of upward pressure. Something can still be done to repair this omission if tests show it to be important and methods are taken up later on in the section entitled Liethods of Repair.

#### 2. ADECUACY OF DESIGN

Perhaps the best way to show how the Delta Dam compares in design with other dams is by drawing several representative dens to the same scale and tracing them one over another on the same cheet. This has been done in Sheets RL and R2 attached. Sheet MI shows several typical "bulkhead" dams, that is, dams which are not used as overflows or spillways. These are all "gravity" dems, that is dems which owe their stability to weight alone without any assistance from arch section secured by building the dan on a horizontal curve or arch. It will be noticed that two of the bulkhood dans, namely #5 and #3, are materially lighter than the Delta Dam and 22 which is the so-called New Croton dam of the H. Y. City Mater Supply, while much heavier at the top, has a lighter section lower down. The Croton dam is a very high dam and becomes much heavier at lower depths. The Sodom dam, 25 was built before stresses in dams were understood as they are jow. It is in a rather nerrow valley on vory firm gneiss and while quite thin has nover shown the least sign of distress. The Austin, Pa. dan, 28. failed by sliding on its foundation. Dem 23. the Olive Bridge dem of the Catskill System and Dam 34, the Croton Falls dam of the New York City Croton system are very much heavier than the Delta Dem, particularly at the tops, which are designed for roadways

-12.

0

of liberal width and to withstand heavy ice pressure. Dan #7 which is of a design commonly used by a very large public corporation is of about the same weight as the Delta Dan. In general, it may be said that the Delta Dam has about the same section as would be round often in private or dividend-producing enterprises but is lighter than most of the large modern public dems.

Drawing R2 chows a similar comparison for spillway sections. In this case the Delta Dan down to a depth of 75' is considerably lighter than any other dam of which I have record except +2, the Furlock dam which is heavier at the top but about the same as Delta at depth 75 feet. Another engineer who recently made a similar comparison has informed no that he also was unable to find a lighter section, although there are doubtless lighter ones among the many hundreds of unrecorded dams. The spillway section of Delta dam, however, is of about the same weight as the bulkhead section and would have about the same computed stability in spite of the fact that it is customary to make spillway sections heavier than bulkhead sections. One of the spillway dams shown on R2, namely 36, at Austin, Texas, failed by sliding due to the solubility of its foundation which was limpstone.

# Computations as to Stability of Delta Dam.

I have made some computations as to stability of and stresses in the Delta dam and these are shown on Sheets R3, R4 and R5. Since making these computations I have had access to computasions made by the Barge Canal engineers and find a close agreement.

Eheet RS shows the stresses in the bulkhead section of the delte del on two assumptions, namely (a) that the water pressure

1130

2011. 2.3.

does not have access beneath the dam and (b) that the water pressure does have access beneath the dam and acts on 2/3 of the area with an effect diminishing from full head at the upstream edge or too heel of the dam to tail water head at the downstream edge or too of the den. It will be seen from this diagram that the so-called line of resistance comes within the middle third assuming no water pressure beneath the dam and it comes a short distance outside of the middle third if water pressure is assumed to penetrate beneath the dam. The vertical stresses in either case are not particularly high, namely about six tons per square foot compression at the too and less than 1 ton tension at the heel assuming water pressure beneath the dam.

Diagrams R4 and R5 give similar computations for the spillway section but in the case of R5 the investigation has been extended to cover ice pressure and shows that the dam would be evestressed if an ice pressure of 40,000 per linear foot could be exerted. This question of ice pressure is one that has never been satisfactorily settled by engineers. Adequate provision for ice pressure results in the very massive design shown for the Ashekan Dam on Sheet R1. There are probably 100 times as many dams that do not provide for ice pressure as there are dams which do provide for ice pressure. Among municipal engineers the reason for providing for ice pressure is generally that the dam impounds a very large body of water shows a populus district and that this extra insurance is justified to provent a shadow of doubt as to loss of life and of valuable property. The Dolta dam impounds a very large body of water. The effect of a break in this dam on the fity of Rome is take t

:14.

Dolta Dun

up hereinefter unler the heading "Demage that would be occasioned by Failure". In this place I will limit myself to the statement that heavy ice pressure is not likely to occur at the Delte Dam on account of the shape of the reservoir but that the policy (which public documents show was in the minds of the decigners) of draining the reservoir so that it is 40 or 50 feet below the crost of the dam through the winter is certainly a commendable one.

For the case with upward water pressure oven without ice pressure, the ratio of the resultant horizontal to vertical force resches the high value of about .65 and calls for very good slideresisting bonding at all construction joints and at the foundation. Projecting cyclopean stones seem by the photographs to afford excellent bond at construction joints. Where the foundation is excavated below the surface of the rock, the bonding with the foundation is greatly mided by a bearing against the front of the excavation. The extent to which this aid is needed in the case with upward water pressure may be estimated by assuming that the total sliding force of 221,000 lbs. per linear foot of dam is resisted by a combination of 3 forces described below:

- (a) By friction on the foundation assumed very conservatively as 50% of the not downward weight or pressure.
   50% of 273,000
- <u>137,000</u>
- (b) By bearing of rear cut-off wall against rock at front of cut-off trench. If it were assumed that water pressure against the dan for a height equal to width of cut-off trench were thus resisted the aid would be 25,000

163,000

v15.

(c) Remainder of sliding force, or 231,000 - 163,000 = 33,000 lbs. may be assumed to be resisted by betring of dam sgainst front of excavation or against interaclists shoulders in the rock. If unit compression of concrete sgainst rock is taken as 200 lbs. per sq. in. or 28,800 lb. per sq. foot, then a total depth of 2.4 feet of shoulder is needed for 68,000 lbs.

It has been proviously explained under section entitled Foundation of Dam that the rock shoulders are adequate (generally at least twice the 2.4' depth above noted) except for a stratch of 150 feet in the westerly end of spillway. In this stratch, if under pressure should exist to the extent computed on R3. R4 and R5, on increased friction factor combined with aid from adjacent better supported sections would be called into action and would doubtless provail though a greater margin of safety should be provided in so important an dam.

The necessity of preserving the rock downstream which provents the dam from sliding has been explained in the section entitled Poundations of Dam.

It may be concluded that in design the Delta dam follows usual commercial practice in its partial provision against uplift pressure and its absence of prevision against ice pressure. It is less concervative than most of the modern large municipal and national dams. The westerly 150 feet of spillway is still less conservative. The deterioration has not yet materially affected the stability of the dam but would become a factor if not checked. 3. LAAL THAT TOUCH BE OCLASIONED BY FAILURE OF THE DELTA DAM

As a matter of completeness and because engineering judgment in the design and construction of any dam must be affected by such considerations. I have made a brief investigation of the Dolta Der.

probable damage that would result from a failure of the Delta dam. The dam is constructed in sections 50' long. The least failure of importance that could be conceived as happening would be for three 20' sections to move by partial tipping followed by sliding in the nammer that occurred in the case of the Austin dam on the Colorado River in Texas and that other dam at Austin. Pennsylvania. Such an event would occur, if at all, in a time of maximum flood. There are approximately 137 square miles of water shed upstream from the Delta dem and a rainfall of 10 inches in 50 hours such as occurred in New Jersey and Southern New York in 1903 might easily cause a depth of 7° or more over the spillway in spite of the great holding back power of the Delta resorvoir. At this time the reservoir which has a full level capacity of about 2,750,000,000 cu. ft. or 20.6 billion gallons would be holding a considerably larger quantity of water, namely about 3,600,000,000 cu. It. or 27 billion gallons. 七

A rough computation made by taking cross sections from U. S. Geological Sheet of the stream below the dam, indicates that water would escape through a 90° opening in the dam at the rate of about 180,000 cu. ft. per second. A wall of water about 10° high would advance toward Rome probably at the rate of about 10 miles an hour and after the channel were entirely filled would continue to flow for/several hours with a velocity of 6 or 8 miles an hour and with a depth of 10 to 15° in the river north of Nome. The bridge opening under Dominick Street has only about 1,000 sq. ft. of opening as compared with about 15,000 sq. ft. which would be required to carry 180,000 cu. ft. per second at the velocity which it would be likely to attain. The pater would therefore back up

Dalta Jun.

North of Deminick Street until it overflowed that street for a length of half a mile or so and a depth of 5 or 8 feat. Sepography is not available to determine the exact course of the water but the lower parts of the main city, the new developments to the East and the factories couth of East Dominick Street would suffer greatly from water escaping West over the divide toward wood Greek and South and East toward the Genel. The conal section is not large enough to contain such a flood and would be submerged but the Mohawk valley would carry the flood off to the cast without excessive depth. There would probably be serious loss of life, greater or less depending on the time of day or of night at which the break eccurred.

The lesson that I would draw from this study is that the Dolta dam, impounding as it does a very large quantity of water, and located so that a failure would have such serious consequences. should be repaired thoroughly so as to make its factor of safety a little batter than it was when originally constructed. In the winter time, as has already been explained, the practice of drawing down the reservoir somewhat, which has the effect of preventing any considerable ice pressure, should be continued as an invariable policy or else reliable means adopted to keep the ice cut away "row the dam.

#### 4. METEODS OF REPAIR

The repairs to the Delta danshould be of such a nature as to accomplish the following purposes:-

- (a) The cutting off of any scepage between the layers of level-bodded shale under the dam.
- (b) The drainage of the rock foundation under the downstream portion of the dam so as to eliminate upward water pressure so far as practicable.

Dolts Dan.

- (c) Increase in the provisions for resisting sliding of the westerly 150 feet of spillway section.
- (a) Strongthening, to the extent found desirable after unwatering and inspecting. of the apron protecting the rock in front of the spillway.
- (c) The cutting off of scopege through the dam in the parts visible above ground in order both to eliminate the saturation of the surface concrete which has caused disintegration by freezing and to reduce any upward pressure that may exist within the joints. The stoppage of this scoping is particularly necessary in connection with placing repair masonry mentioned below.
- (f) The removal of unsound maconry from the emposed faces of the dam. It is assumed that very little unsound masonry emists below the ground line and below the low water level in the rear of the dam.
- (g) The placing on upstream and downstream faces of the dam of a sufficiently substantial layer of new masonry well bonded with the old mesonry to avoid future disintegration and to increase somewhat the weight and factor of sofety of the structure.

Some further explanations of the methods suggested for accomplishing the purposes above enumerated are given below under the same letters.

#### (a) Cutting Off Seepage Under Dau.

As proviously explained in the report, grouting is generally gone in the foundation of a dam to cut off the seepage under the dam and also to reduce the possible upward pressure tending to doerease the stability of the dam in the way described under Dosign. Core berings can be made from the top of the dam through which grouting of the foundation can be done. The 3 test holes will indicate whether grouting of the foundation is desirable, though if these 3 result in a negative conclusion a few more holes should be tried as a verification when the contract repair work is started. It is possible that these same holes may also be used for grouting

### Delta Dan.

joints in the dam above the foundation though grouting from the floe may be more effective. A special packer such as has been used in other cases can be employed in these borings in order to limit the grouting below any desired point. A hole every 10 feet along the dam ought to be sufficient.

### (b) Draining Rock Foundation.

To still further reduce possibility of upward pressure holes may be drilled into the foundation at a distance of about 1/3 the width of the dam from the upstream edge. These holes could be put in on a slope from the downstream face of the dom and would limit the upward pressure to the height at which the hole was started in this downstream face. Heles for relieving pressure in real have been used successfully in the Catakill water works in accordance with the writer's design.

(c) Increase in Slide-Resisting Provisions for the Westerly 150 fest (Approx.) of Spillway.

Study will be needed to determine the best method. The easiest way will be to empavate a trench in rock and put in a heavy block of concrete just downstream from the toe of the conerete apron. The surface of the new concrete would be sloped up to fit the profile of the apron paving and would replace a part of this paving.

# (a) Strengthoning Apron.

Official photos and cross sections indicate paving apperently ungrouted laid partly on earth or fill. After unwatering the pool and inspecting the rock beneath and dewnstream from the upron at enough places to be assured that the rock has not softened or become eroded in a serious way. it may be found sufficient Dolta Dan.

to relay all disturbed or undermined paving and grout the joints with ecanon mortar. A 7 foot flood should be in mind in inspecting and repairing this apron. Inspection after every flood is a particularly important duty considering the laminated nature of this shale and its tendency to go to pieces when expected. It is expected that the continued wetness of the stream bed has provented deterioration such as has taken place in the rock which has been expected to air.

#### (c) Cutting Off Scepage Through Dam.

The test holes which have been previously mentioned in the report will be used not only to test quality of masonry but also to test the possibility of grouting in such a way as to intercept the seepage which is now coming through the dam in numerous places. If this solution is found facsible, which is not at all sure, the holes already described under paragraph (a) above can also be used for this purpose. In any case it should be possible after proparing the upstream face of the dam to caulk and grout any visible joints and waterproof any porcus places that will be expesed. Making the upstream face of the dam tight is necessary, otherwise any new masonry placed downstream is likely to retain water behind it and be disturbed by freezing. Furthermore, the old missury may keep on deteriorating behind the new if it is wet and freezes.

# (f) Removing Unsound Masonry.

The unsound maconry can be removed easily by sir chicol. possibly by the aid of hose streams before and after using the chisel. The total quantity will be very considerable. There is nothing difficult however about the operation and everybedy agrees

-21.

that this rotton concrete must be removed down to sound material before placing new material for the outside surface. The cleanness of the downstream face of the spillway as observed after the spring overflow suggests that strong hose streams may be used to advantage in removing most of the rotton concrete.

### (g) New Mesonry on Upstream and Downstream Faces.

In order that there shall be no danger of a repetition of the frest action resulting in scaling off of the surface masonry I believe the new surfacing should have a substantial thickness and should be bended to the old masonry not alone by grooves but also by steel anchors grouted into drilled holes in the old masonry. I have in mind a thickness of about 2 feet though detailed study may indicate the desirability of making the new masonry thicker than 2 feet at the bottom and perhaps it may be reduced to 15" or 18" at the top. There is a problem in keeping the pleasing appearance of the dan where the new masonry terminates at the top. This is particularly true on the downstream face near the top where there is an ornsmental cornice with arches.

On the downstream face at least, except near the onds of the dam where the head is low, the new mesonry should be footed in cound rock (or mesonry in the spillway) and bonded by shoulders in order to secure the advantage in stability resulting from the increased width of the dam. Below the ground line and pool level on the downstream face of the dam and below the winter water level on the upstream face of the dam, the new mesonry can without question be of concrete and sufficient cement should be used to be sure that there will be no further disintegration. A mixture of 1: 2: 4 or

Delta Dan.

[]

perhaps 1: 20: 4; approximately would be satisfactory, the exact propertions of sand and stone to be determined so as to give the densect precticable mix. Above the levels previously mentioned, it would seem best to use stone masonry of a permanence equal to the very good stone which was used for the cyclopean blocks and also for the paving which is visible downstream from the dam and shows absolutely no disintegration of even the sharpest corners of the stone blocks.

Discussing further the kind of musonry to be used for the lower parts of the repairs, there will be an advantage in using concrete masonry below ground on the downstream face even if stone could be had for the same price because the concrete will bend more strongly with the present masonry and grooves can be cut to insure the shearing strength between new and old masonry necessary to make the two parts act together in producing stability of the structure.

Referring further to the artistic question of joining new end old masonry at the top of the dam, a thoroughly satisfactory solution can only be worked out on the drafting board which will of course be done by the engineering force under the State Engineer end Surveyor. It is the intention of the State authorities as expressed to me to prepare the designs and contract for the repair work after the test borings have been made. It will then be possible to go to the Legislature next winter and proceed with the repairs the following season.

Work Should be done in Summer if Possible.

There was some discussion between Supt. of Public Works Greene, State Engineer and Surveyor La Du and the writer as to

2230

Dolta Dun.

whether the repairs could properly be done in the winter in order that the recervoir might be used for feeding the Canal without interruption during the season of navigation. There is no question that it is physically possible to make the repairs in winter but this would add at least §75,000 I think and perhaps more to their cost since there would have to be a steam heated housing over all parts where masonry was being placed and adequate protection would have to be loft in place until the masonry was well set to avoid a repairtion of the disintegration.

I an inclined to think that a computation of the amount of water required for the canal under present traffic conditions will show that the summit level can be adequately fed from the other available sources. It may be necessary to curtail to some extent the freedom with which pleasure beats can pass the locks; that is it may be necessary to pass them in groups at certain times and not whenever they come along. It is certainly worth considerable care and planning to avoid the expense and constructional disadvantages of making these repairs during freezing weather. Acknowledgements.

In conclusion I would like to make acknowledgement of the cooperation afforded me by your Committee and by engineers formerly connected with the Barge Canal: also of the courtesies extended on all my visits by Superintendent of Public Works Frederick S. Greene. State Engineer and Surveyor Dwight B. La Du and Commissioner of Canals Roy K. Fuller.

# Romo Chamber of Commerce Should Meintain Interest.

The proposed program of Supt. Greene and State Engineer Le bu





AD-A069 472 KIMBALL (L ROBERT) AND ASSOCIATES EBENSBURG PA F/G 13/2 NATIONAL DAM SAFETY PROGRAM. DELTA DAM (INVENTORY NUMBER NY 6),ETC(U) JUN 78 R J KIMBALL DAM SAFETY PROGRAM. DELTA DAM (INVENTORY NUMBER NY 6),ETC(U) DACW51-78-C-0025 NL													
	2 OF 2 AD A069 472	<u>W</u>						<ul> <li>The second secon</li></ul>	Area Area Area Area Area Area Area Area				
					NUMBER OF	Montechnikowa Warth and the second second Martine Second second Martine Second seco	fan i sentreasen i fine Arresse sont aven Mitseparategy Mitseparategy	-		~			
						-		11. 				END date filmed 7-79 ddc	-
										c.			
				*									
1.										_	-	-	/













2 TONS (OF 2000 #) PER SQ FT

# EXPLANATION OF STRESS CURVES A TOE AT L

Horizontal distances from the vertical zero line to curves A, intensities of vertical compressive or tensile stresses as the l on torizontal planes at any level at downstream edge (Toe) . edge (heel) of dam.

Curve A shows compressive stress at the with ar without pressure under the section of dam in question

Curve B shows tensile or compressive stress at heel will water pressure.

Curve C shows tensile stress at heel with upward water Scales for Curves A, B& C are of top of curves.

Horizontal distances from the vertical zero line to Cur show ratios of herizontal (or sliding forces) to vertical ( producing) forces of any level and are the friction coe required to just produce stability.

Curve D shows ratio of horizontal to vertical press upward water pressure under the section of dam in que Curve E shows ratio of harrzontal to vertical press upmond water pressure.

STUDIES OF DELTA DAM FOR CHAMBER OF COMMERCE, ROME, N STRESSES IN BULKHEAD SECTION-NO ICE PR May 1924

THOS.H.WIGGIM, Consulting Engineer 30 OHURCH St., M.Y. CITY.

# S CURVES A TOE AT LEFT

Stand at

tical zero line to curves A, B&C show or tensile stresses as the Case may be at downstream edge (toe) or upstream

3

thess at be with er without upword webs om in question opressive stress at heel without upward

theel with upward water pressure re of top of curves. vertical zero line to Curves Ds E liding forces) to vertical (or trictian-and are the triction coefficients by. rizontal to vertical pressure with the section of dam in question. rizontal to vertical pressure without

DELTA DAM COMMERCE, ROME, N.Y. SECTION-NO ICE PRESSURE 1924

Consulting Engineer HURCH St., K. CITY.

23

0

Delta Din.

[]

to make the test boring and other tests this summer preparatory to drawing up plans and a contract for repairs to be made next season is a highly satisfactory one and one in which the people of Home and particularly your association should be interested to the extent of making their wishes felt when the matter comes up for legislative consideration next winter. The provisions to provent ice pressure against the dam might well be made a matter of permanent interest and inspection by your association.

Research Work Needod.

I have strongly urged that a committee of the American Society of Sivil Engineers or of Engineering Foundation be appointed to settle the doubtful points as to uplift water pressure and ice pressure in dans. Only lack of funds will prevent favorable Acction. Such committees give their services but cannot pay for clerical and detailed engineering assistants and apparatus; henco small endowments are necessary and the funds evailable in the societies above mentioned do not nearly suffice for work badly needed.

Yours vory truly.

THE :LAR.

No Charge

1

## PART I

Materials Bureau Trip Report on Delta Dam, Rome New York

"INSPECTING DELTA DAM FOR SOURCE(S) OF LEAKS EVIDENT ON DAM FACE"

NYS DOT Region 2 Personnel Contacted: Chester Urbanczyk Ben Sweeney Edward Sears Henry Zwyack

> DATE: 12/1/76 PIN: ML7201.70.116 FROM: E. F. DiCocco TO: R. H. Obuchowski
R. H. Obuchowski and E. F. DiCocco visited the Delta dam on 11/15/76 and 11/17/76. The purpose of the visits was to determine the source of leak(s) evident on the face of the dam. The following persons were contacted at the dam.

#### Official Capacity

Ed Sears Chet Urbanczyk Ben Sweeney Henry Zwyack

Name

Gatehouse Attendant at the dam R-2 Canals & Locks Engineer R-2 Canals & Locks Superintendent R-2 Head of Canals & Locks

The following contracts on the dam are on microfilm. They are all available from Carl Tiemann of the NYSDOT Waterways unit at telephone (518) 457-4474.

Contract	MICRO	FILM NO.	
Number	Roll	Frame	Type of Work
229	10	473	Original Construction
M56-6	22	237	Repair
M58-13	22	303	Repair

#### DELTA DAM HISTORY

19.11 - Dam Constructed

1926- 1927 - A layer of concrete was placed across the upstream face of the dam to reduce seepage. The downstream face of the dam was covered with a "weatherproof facing of gunite" to stop the disintegration of the existing downstream face. The work was done by Department forces and lapsed over at least one winter.

- 1956 Contract M56-6 issued to grout leaking areas of dam face. We (Materials Bureau) have parts of these contract plans.
- 1959 Contract M58-13 issued to "shotcrete" dam spillway and face. I don't believe we have any copies or portions of these plans.

### PROBLEM LEAK(S)

Upon initial inspection of the dam leak(s), it was evident that the flow of the leak is steady. This means that the leak(s) are fed by a constant flow and the only <u>obvious</u> source capable of supplying a constant source of water must be the reservoir behind the dam. However, it is not obvious how the water from the reservoir finds its way to the leak(s) at the face of the dam. Diagrams I and II (attached) depicts the situation. Diagram I shows the dam in general view from its downstream face. Diagram II is a closeup view of section C depicted in diagram I.

Trip of 11/15/76 (EFD & RHO) On this trip, R. Obuchowski and E. F. DiCocco took several pictures of the situation, discussed the general problems with Chet Urbanczyk and Ben Sweeney of Region 2 and took the measurements (approximate) given on diagrams I and II of this report. The drains (1& 2) at the bottom of the dam were also exposed for inspection. We retrieved a sample of a white, sedimented material that was plugging each drain. The Materials Bureau Chemistry Lab analyzed this material and reported (76LUE2476) that it was probably Calcium Hydroxide (Ca(OH)<sub>2</sub>). This is probably a product of water leaching into and through the dam slowly and carrying the Calcium Hydroxide into the drains and eventually plugging them over the lifetime of the dam. The drain intakes (1 & 2) at the top of the dam were also chipped open for examination. We found that drain 1 was filled with water and sand (apparently) up to about 5.5 feet from the top deck of the dam. The last 5.5 feet were clear. The condition of drain 2 was the same as drain 1 except that the top 4' were clear of water and sand. We do not know whether or not these drains were purposely filled with sand at the time of their construction. If they were, it was probably to keep the flow rate of water low so as to try to minimize erosion, scouring and leaching of the concrete in the dam. Drains 1 & 2 are the 2 drains closest to leak(s) 1 & 2 (See diagram II). More drains are to the right of drains 1 & 2. These were not exposed or inspected. We do not know what their condition is. All vertical drains were placed at vertical (cold) concrete construction joints at the time of dam construction. The inspected drains 1 & 2 at the bottom of the dam exhibited no water draining out. Therefore, we do not feel that the water flow rate in these two drains is sufficient to feed apparent leaks 1 & 2. During this inspection we also noted that the reservoir level was 8.4' from the top of the dam. This corresponds to an elevation of 550' from sea level. In addition, water was flowing over the main dam spillway.

2

Trip of 11/17/76 (EFD & RHO) On this trip, R. Obuchowski and E. F. DiCocco met with Chet Urbanczyk and Ed Sears. We placed Rhodamine red dye in drains 1 & 2 at the top of the dam. We expected the dye to come out at either of leaks 1 & 2 or both. However, no dye came out at either leak. This confirms that the two drains (1 & 2) are not feeding the two evident leaks (1 & 2). The dye did come out of various construction joints near the two drains tested. Dye leaked from both vertical and horizontal construction joints. To get some idea of the leaking rate of the two drains, we timed the dye and obtained the following results:

Urain I (West)		
Start Dyeing	11:14	am
Dye visible at horizontal construction		
joint 10' down from top of dam	11:45	am
Dye not visible at base drain	2:15	pm

Drain 2 (East)

Dye immediately visible (5 minutes) at vertical and horizontal construction joints 10' from top of dam.

During this dyeing process, we refilled each drain 3 times to the top in order to provide enough pressure head and water to carry the dye out. Rhodamine dye is very powerful. It should be used sparingly. A paper cupfull is enough to stain large areas (100 ft.<sup>2</sup>) of water. Rhodamine is also reported to be harmless to fish and water plant life. We have 8 pictures (yet to be developed) showing this dyeing process and resultant staining. The dyeing confirmed that the 2 vertical drains tested are not feeding the leak(s). Since the other vertical drains are even further from leaks 1 & 2 than are drains 1 & 2, we do not feel that they are connected to and feeding the leaks either.

<u>Trip of 11/23/76</u> (EFD & RAM) On this trip R. Marcucci and E. F. DiCocco met with Ed Sears and Chet Urbanczyk at the Delta dam. We tried placing dye in the reservoir at the level of leak 1 ( $30'\pm$  from dam top). The dye did not come through at leak 1, but was drawn around the valve house by the tremendous suction of water due to the outlet valve on the opposite side of the valve house.

A ladder was placed on the face of the dam and E. F. DiCocco inspected both leaks (1 & 2). Leak 2 is not a true leak. It is fed by leak 1 and the water spreads out along the shotcrete construction joint at apparent leak 2. However, the water is not leaking out at the construction joint at leak 2. Therefore the only true leak seems to be leak 1. Because we discovered that leak 2 is not a true leak, we did not try dyeing at its level (43' from top of dam) behind the dam in the reservoir.

We then tried dyeing in the westernmost intake well (closest to leak 1) in the valve house itself. We also transferred the open outlet valve draining the reservoir from the stated intake well. The dye in the intake well was well stirred and mixed with the water. No dye came out anywhere. At this point we are not able to report the source of the leak. Obviously, many possibilities exist. We suspect that the water is somehow infiltrating through construction joints to the leak.

We have left the dye with Ed Sears, the valve house attendant. He has tried dyeing various intake wells. To date, 12/1/76 we (the Materials Bureau) have received no word of results. If positive results had been obtained, the Materials Bureau would have been notified.

<u>OPINION</u>. After reviewing the M56-6 contract plans, we found that leak 1 is just about centrally located in an area of grout repair holes. It may be that the original leak(s) of the M56-6 contract were not adequately sealed and that they eventually reworked their way to the present leak. The leak is located at station 3+10 at elevation 530'. This corresponds to within 2'+ of a grout drill hole as shown on the plans.

#### OPTIONS AND FUTURE WORK:

 Ed Sears & Chet Urbanczyk will continue monitoring the situation. They will notify Materials if anything happens.

- The reservoir will be lowered to about the level of leak 1 for the winter. We plan to inspect the reservoir side face of the dam when the lake is frozen in the winter.
- 3. <u>SUGGESTION</u>. Perhaps an infrared photograph of the dam face (downstream) leak area will reveal the extent of water infiltration. This idea might be further explored.
- 4. If all else fails, exploratory chipping of the leaking area might be done by department forces next spring and summer.
- NOTE: We have various plans and photographs and slides for inspection by whoever is interested.

Trip of 1/20/77 (RHO & RCB) Ed Sears, R. C. Babyak & R. H. Obuchowski inspected the Delta Dam. The following conditions at or near the dam were noted:

a.	Top of Dam Elevation	558.4'
b.	Approximate Elevation of Leak One	529.1'
c.	Approximate Elevation Difference (a-b)	29.3'
d.	Reservoir Level on 1/20/77	534.7'
e.	About two (2') of snow on the ground.	

- f. Construction joints on the upstream face of the dam were deteriorated at the edges. Deterioration extended about 4"+ deep. This deterioration may be causing or contributing to leak one.
- g. Blocks of ice at upstream side of dam hiding water level at approximate level of leak. This made it very difficult to observe upstream face at approximate level of leak one.
- h. Approximately 10" layer of ice buildup covering leak 1. Ed Sears tried dyeing the westernmost intake well prior to 1/20/77. On that same day, no dye was visible at leak one level 4 hours after placing the Rhodamine red dye in intake well. However, red dye was possibly visible on 1/20/77 at leak one location. However, this observation was not certain.

Observations a-h address themselves to options 1 & 2 on pages 3 and 4 of this Trip Report. Referring to options 3 and 4 on page 4 of this Trip Report, we did no exploratory chipping of the concrete in the area of leak one. Neither did we pursue the infrared photograph option any further.



# PART II

1

# "DELTA DAM REPAIR ALTERNATIVES AND RECOMMENDATIONS"

DATE:	February 9, 1978
PIN:	ML 7201.70.116
FROM:	E. F. DiCocco
то:	R. H. Obuchowski

During the past year, field crews from this office inspected the Delta dam near Rome, NY several times in attempts to determine the source(s) of the dam leak on the downstream face of the eastern end of the dam. As noted in Part I of the trip report (p. 3), we have concluded that leak number one appears to be the only true leak. The approximate location of leak one is shown in the section "C" diagram on page 5 of the trip report. The report is written by E. F. DiCocco to R. H. Obuchowski and dated 12/1/76. It includes and explains the reasoning for some of our conclusions and findings. It also lists previous repair contract identifications and, where copies of the contract plans can be obtained. This 12/1/76 report should be read in order to obtain a better understanding of our findings.

No leaks or problem areas are visible at the western end or spillway of the dam. Therefore, this report only deals with the eastern end of the dam and the known leak.

The leak is flowing steadily, but does not appear likely to cause a catastrophic failure. Its flow is high enough so that, in time, additional material will be leached and washed out of the concrete in the dam causing the leak to worsen. Any increase in flow may cause: erosion problems in the soil at the base of the dam; water problems at the valve control building at the base; further washout in the concrete. The leak should be stopped and prevented from expanding beyond its present size. Repairing the leak will eliminate any need for expensive emergency repairs to it in the future.

There are several other seepage areas at the downstream eastern side of the dam (see 1977 color photos - Table B). Some of the repair alternatives will also help in remedying these seepage problems. However, we do not feel these seepage areas are very critical. The most important problem is leak number one.

The color photos in Table B also reveal that the shotcrete facing originally placed circa 1927 is very deteriorated. Although this deteriorated shotcrete is unsightly, we do not feel that it needs to be removed and replaced to maintain the structural integrity of the dam. However, since the Delta reservoir is part of Delta Lake State Park, and the general public frequently sees the "apparent condition" of the dam, you may want to replace the deteriorated shotcrete with a cosmetic facade. Cost considerations should control this option.

During our inspections, we noticed that some of the construction joints on the upstream facing were deteriorating. These deteriorating joints may be providing water with access routes to the construction joints in the main body of the dam beneath the two foot (+) facing. This 2'+ facing is shaded blue on the cross sectional view of Delta Dam on page 5/8 of the M56-6 contract drawing. The water may then be infiltrating along the main construction joints to steadily feed the observed leak. Presuming this to be the problem, we recommend the following four repair alternatives. These repairs might possibly be done with NYSDOT Maintenance forces, by scaling this work to fit their capacity and concentrating on the area of the leak. The lowest level of the reservoir encountered during our inspections was about 30 feet from the top. This left a water depth of about 50 feet. Because of this, we are not exactly certain what the condition of the dam facing is within the lower 50 feet. The facing may be deteriorated more or less extensively than now suspected. 2

From our inspections, we propose repair alternatives A, B, C and D to stop the leak. Alternatives A, B and C are listed in order of increasing effort and cost. Alternative D is our primary recommendation and the least costly.

### ALTERNATIVE A

Patch the two foot (+) thick facing on upstream eastern end of the dam. The repair should be as follows: Drain the Delta reservoir completely. Then, chip the existing concrete along all vertical and horizontal construction joints in the facing. The chipping should straddle each joint and should be continued into concrete that is not deteriorated. Clean out all deteriorated and loosely bonded existing material in and around the chipped out joints. Then, sandblast these chipped out areas until a sound, clean surface is obtained. Where large patch areas are necessary, anchor steel reinforcing mesh to the sound concrete of the dam. Then, fill in the chipped out joints with a mortar mix proportioned 1:2 (cement:sand) by volume. A stiff mortar mix can be hand-packed into the joints or wooden or metal forms can be placed to shape the plastic mortar to match the original shape of the dam's upstream facing. The freshly placed mortar should be allowed to cure at least one day prior to reimmersing it in water. This length cure should allow the fresh mix to set well enough so that, when it is reinmersed in water, its strength will not be affected due to a disruption of its water/cement (w/c) ratio.

While the reservoir is drained, it would be convenient and advantageous to inspect the full depth of all intake wells carefully. In addition, both sides of the spillway and the upstream western end of the dam should also be carefully inspected at this time.

### ALTERNATIVE B

Pressure grout the entire eastern end of the dam. This could be done with conventional methods of pressure grouting into deep vertical predrilled holes through the top of the dam. The grout holes should be drilled approximately 5 feet apart or less. Grouting should progress from the bottom upwards. The grout should be a pure cement slurry or epoxy grout without any sand. Similar pressure grouting was conducted on the Delta dam under repair contract M56-6.

During our inspections, we exposed two vertical drains (drains 1 and 2, p. 5 of the Part I report). Each of these drains was plugged with efflorescence product from about 5' from the top to the bottom of each drain. This efflorescence was caused by water leaching through cracks and seams in the concrete and depositing the residue in the drains. The configuration of these drains is shown in a xerox copy of a photograph taken in October 1909 during the original construction of the dam. This photo is labeled C-1. The drain, interlocking keyways, and cyclopean masonry are clearly marked. We are concerned that similar efflorescence product may have been deposited in cracks and joints throughout the dam during its lifetime. If this is the case, the pressurized grout material may not bond well to the efflorescence and not completely seal the joints, cracks or leak(s). We have attached an article from the 10/74 issue of Public Works magazine which describes some advantages and problems associated with epoxy grouting procedures.

## ALTERNATIVE C

Drain the reservoir fully. On the eastern upstream face of the dam, remove the existing nominal two foot thick (+) facing until original concrete is encountered that is not deteriorated. Also chip out repairs that may have been done under alternative A as necessary. Anchor suitably sized reinforcing bars into the original sound concrete that has been uncovered by removing the nominal 2' (+) facing. Place formwork to reconstruct the facing to the original configuration or thicker. Then resurface the entire eastern upstream face of the dam with suitable NYSDOT Class A concrete. This pour should progress in stages vertically upwards from the base of the dam. The fresh concrete should be properly vibrated as work progresses in each stage. New joints should be formed and sealed using waterstops. The fresh concrete should be reimmersed in water as described in alternative A.

We do not recommend shotcrete as a substitute for this procedure. We believe that if shotcrete were used, rebound losses of up to 30% of the shotcrete projected would occur. This high rebound loss, the thickness required (2'+), and the special procedures and equipment needed, would make shotcreting too expensive.

## ALTERNATIVE D

Pressure grout in the immediate vicinity of the leak until water flow is sufficiently negligible or completely stopped. Grouting should progress from leak number one and radiate outward in all directions. The grout can be either an epoxy type or cement slurry. The grout should be capable of rebonding cracks and delaminations in the concrete.

After reviewing several epoxy type grouts, we can recommend one with reasonable certainty of success. This product is "Niklepoxy concrete injection resin - product #3". It is manufactured by Rocky Hountain Chemical Company. This material's primary advantages are claimed to be:

- It is capable of rebonding cracks and delaminations in portland cement concrete in the presence of water and at temperatures as low as 0°C (32°F).
- 2. On frost free dry surfaces, the system can be applied and can develop strength at temperatures as low as  $-23^{\circ}C$  ( $-10^{\circ}F$ ).
- 3. The resin can be injected at relatively low pressures (10 to 25 psi) above the counteracting water pressures. Counteracting pressures should

be less than 20 psi for adequate performance.

For the reader's convenience, we have included a copy of the information sheet on this product.

Other epoxy grouts are available from various other manufacturers and distributors. Based on their product literature, we do not feel they will perform as well. However, these other products should be carefully examined to determine their suitability. This Bureau is presently engaged in evaluating these other epoxy materials via consultations with their distributors.

Alternative D is our primary alternative. We feel it is the cheapest method of stopping the leak. It should be tried first. Alternatives A, B, and C should be considered if D fails.

#### CAUTIONS CONCERNING EPOXY GROUT

Some epoxy mortar grout compounds are very toxic. Others are less toxic. If epoxy grout is used in repairing the Delta dam, care should be exercised to ensure that the Delta Lake reservoir is not contaminated with toxic compounds. This problem may be particularly important in this case because the Delta reservoir is connected with the barge canal system and the Mohawk River. The river is used as a water supply by some municipalities. However, the Delta reservoir itself is not a city water supply. Epoxy grouts can be used safely if placed in accordance with manufacturer's directions.

## SUGGESTIONS

During our 2/22/77 inspection of the dam, we inspected the westernmost intake well in the gatehouse. The water level in the well was dropped about 30' from the top. Substantial concrete cracking on the interior walls of the intake well was observed. We believe this observed cracking may be contributing to the downstream face leak and seepage areas. Therefore, any repair of the dam should consider an examination of all intake wells for possible necessary repairs. The intake wells should be repaired where warranted. Photographs B-7, B-8 and B-9 in Table B are typical examples of the intake well deterioration we observed.

We also recommend that all vertical drains plugged with efflorescence be cleaned out. This can probably be accomplished by jetting water, under high pressure, into the drains. Fire hoses might be suitable for this. Water jetting should proceed from the bottom of each drain upwards. This procedure allows loosened materials to wash back out through the bottom of the drains. Once the drains are cleaned out, they will probably be working. Therefore, an interceptor pipe should be placed at the base of the drains to carry seepage water to a suitable drainage area. A possible drainage area outlet for the interceptor pipe is onto the rip-rap near the dam spillway. We do not recommend placing a waterproof membrane between the chipped and new facings of alternative C for two reasons:

- 1. The chipped face would have to be smoothed over with mortar so that the rough chipped concrete could not puncture the membrane. This smoothing process requires very careful time consuming and costly repairs.
- 2. Even if it were feasible to place the membrane in the suggested manner, the membrane would act as a "bond breaker" between the new facing and the old concrete. Obviously, this is not desirable because the new surfacing would likely peel away from the membrane and the dam.

We also do not recommend placing a waterproof membrane <u>over</u> the new upstream face resurfacing. Although this seems a good idea, we strongly believe that repeated winter icing action on the membrane would seriously damage it. This is undesirable because a torn or damaged membrane cannot perform as the intended water barrier.

Since the leak and seepage occurs on the eastern side of the dam, we do not recommend any repairs on the downstream face of the spillway or western end of the dam at this time.

Interesting insight into this dam's construction history can be found in this report dated 6/7/24:

"Report on Delta Dam to the Chamber of Commerce Committee of Rome, NY" by Thomas H. Wiggin, Consulting Engineer, 50 Church Street, NYC, NY

The report gives background information on prior Delta dam repairs as well as on original construction methods including "cyclopean masonry" and block construction in stages. Five (5) black and white photographs showing original construction operations from 1909 to 1911 are included in the 6/7/24 report. We have included xerox copies of two of these 5 photographs. The xerox copies of the photos are labeled C-1 and C-2. They show the cyclopean masonry, block construction, interlocking keyways and vertical drains. The 1924 report should be studied prior to developing specific repair plans.

To aid the reader of this transmittal in understanding the present situation more fully, we have attached Tables A and B with a total of 17 photographs showing the problem features of the dam. Each photograph is numbered and short descriptions are provided.

Table A includes 8 black and white photographs circa 1956-1959. These pictures show various stages of repair during the M56-6 contract period. The present leak (number 1) is in the chipped out area shown on pictures A-6, A-7, and A-8. The general condition of the dam in 1959 is also evident from these pictures.

Table B displays color photographs of our most current investigations. Phodamine red dye is evident in pictures B-1, B-2, and B-3. Its location is circled in each of these 3 photos. Close-up photos of leak one are shown in photos B-2 and B-4. In each of these photos, leak one is designated by a hexagon.

.

6

Sheet 5/8 of the M56-6 contact plans is included for your reference. It shows various views of the dam. We have located leak number 1 on this drawing. All dimensions shown in red pencil are approximate.

To reiterate, we feel that the cheapest repair alternative is D. Alternatives A, B, and C follow with increasing cost if D fails. In addition, any alternatives chosen should consider intake well repairs as well as an examination of the entire dam when the reservoir is drained.

## APPENDIX E CONSTRUCTION DRAWINGS

- A

[]

Π

1

·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·
 ·

[]



## APPENDIX F VISUAL CHECK LIST

Π

1

Γ

Γ

	CHECK LIST VISUAL INSPECTION PHASE 1
	NAME DAM Delta COUNTY Oneida STATE New York 10# NY 6
	TYPE OF DAM Cyclopean masonry gravity structure HAZARD CATEGORY High DATE(s) INSPECTION May 5, 1978 WEATHER Rain-cloudy TEMPERATURE 50°
۴.	POOL ELEVATION AT TIME OF INSPECTION 550.4 M.S.L. TAILWATER AT TIME OF INSPECTION 482.0 M.S.L.
	INSPECTION PERSONNEL:
	R. Jeffrey Kimball, P.F. Ed Sears - Caretaker Jim Kaulfman, NYDOT
	James T. Hockensmith Ed Warner, New York Department of Tran.
	John C. Pierchoski, P.E.
1000 M	John C. Pierchoski, P.E. RECORDER
-Sig	
thursday.	

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	Many small and medium cracks on both mono- liths adj. to the spillway. Much of the shotcrete has spalled or has not bonded to the dam. Some spalling and cavitation at the water level on the upstream face.	
STRUCTURAL CRACKING	No structural cracks observed, however shotcrete covers face.	
VERTICAL AND HORIZONTAL ALIGNMENT	Good, no movement noted.	
MONOLITH JOINTS	Joints have been heavily shotcreted (looks like severe deterioration in past)	
CONSTRUCTION JOINTS	Considerable patchwork on vertical joints. Looks like they were eroded badly and patched.	
STAFF GAGE OF RECORDER:	Staff gage on side of intake gate house, is read daily.	

The second s

	CONCRETE/MASONRY DAMS	
VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
ANY NOTICEABLE SEEPAGE	Considerable minor cracking downstream left face. Considerable evidence of previous seepage now dried up. Fairly high seepage in left Monolith section. Considerable seepage at elevation 527,5 near spillway, and at 19 down from top (elevation	539). Horizontal eroding and spalling at water level (550.5) Right front face showing evidence of extensive past seepage that is now stopped. Spillway wing walls both sides are spider webbed with
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	Left abutment set deeply into thin bedded, black, gray shale. No seepage noticable.	cracks.
DRAINS	Small drains may be plugged.	
WATER PASSAGES	None known	
FOUNDATION	Abutments and base appears to be notched into dark gray fissile shale. Appears sound all around.	

		Investigation in the second in
terms terms terms terms terms	OUTLET WORKS	
VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Four - 60" Diameter steel pipes One pipe was opened 14 inches.	
INTAKE STRUCTURE	Good condition - one minor crack on gate house. Equipment well maintained and operable. Electric motors on all valves.	
OUTLET STRUCTURE	No major damage apparent. Very minor cracking along walls	329 cfs. being discharged according to Mr. Sears.
OUTLET CHANNEL	Potrom not visible, full of water, sides looked good.	
EMERGENCY GATE	All discharge gates and pipes operate smoothly.	

States and the second states and the

	UNGATED SPILLWAY	
VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	No distress noted - Ogee spillway, water flowing over spillway did not permit close examination	
APPROACH CHANNEL	None	
DISCHARGE CHANNEL	About 12 places where shotcrete has spalled and is causing water to splash away from spillway. Water flowing over spillway did not permit close examination.	
BRIDGE AND PIERS	Abandoned canal bridge immediately downstream. It will not have a restrictin effect.	

	CATED SPILLWAY	
VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	N/A	
APPROACH CHANNEL	N/A	
DI SCHARGE CHANNEL	N/A	
BRIDGE AND PIERS	N/A	
GATES AND OPERATION EQUIPMENT	N/A	

AL EXAMINATION OF	OBSERVAT I ONS	REMARKS OR RECOMMENDATIONS
TTION SSTRUCTIONS, EBRIS, ETC. )	Good condition, riprap is large and not displaced. Canal bridge downstream is not an obstruction.	
8	3 or 4 to 1 and brush and tree covered, stable.	
OXIMATE NO. OMES AND LATION	At least 20 homes.	

the second second

Christian					
	REMARKS OR RECOMMENDATIONS				
RESERVOIR	OBSERVATIONS	Apparently stable.	Very little - will have no affect on storage capacity		
	VISUAL EXAMINATION OF	SLOPES	SEDIMENTATION		

	HER None known	EZOMETERS None known	IRS None known	SSERVATION WELLS None known	NUMENTATION/SURVEYS None known	SUAL EXAMINATION BSERVATIONS REMARKS OR RECOMMENDATIONS REMARKS OR RECOMMENDATIONS		OBSERVATIONS None known None known None known None known None known None known	VISUAL EXAMINATION MONUMENTATION/SURVEYS OBSERVATION WELLS WEIRS PIEZOMETERS OTHER
ATION ADDR ATION	ATION     DISTRUMENTATION       ATION     REMARKS CR RECOMMENDATIONS       ATION     OBSERVATIONS       ATION     BAREMARKS CR RECOMMENDATIONS       /SURVEYS     None known       /ELLS     None known       /SURVEY     None known       /SURVEY     None known       /SURVEY     None known       /SURVEY     None known       None known     None known	ATION OBSERVATION ATION OBSERVATIONS REMARKS OR RECOMMENDATIONS /SURVEYS None known fells None known None known None known	ATION INSTRUMENTATION ATION OBSERVATIONS REMARKS OR RECOMMENDATIONS /SURVEYS None known /ELLS None known	ATION OBSERVATIONS REMARKS OR RECOMMENDATIONS REMARKS OR RECOMMENDATIONS VOILE Known	ATION OBSERVATIONS REMARKS OR RECOMMENDATIONS		REMARKS OR RECOMMENDATIONS		

## APPENDIX G ENGINEERING DATA CHECK LIST

A straight of

I

NAME OF DAM Delta Dam ID# NY 6									ords by New York State Department
CHECK LIST ENGINEERING DATA DESIGN, CONSTRUCTION, OPERATION PHASE 1	REMARKS	New York State Department of Transportation Utica, New York	•	New York State Department of Transportation Utica, New York		New York State Department of Transportation Utica, New York	New York State Department of Transportation Utica, New York		New York State Department of Transportation Utica, New York U.S.G.S. gaging station downstream - pool rec of Transportation
	ITEM	AS-BUILT DRAWINGS		REGIONAL VICINITY MAP	•	CONSTRUCTION HISTORY	TYPICAL SECTIONS OF DAM	OUTLETS - PLAN	<ul> <li>DETAILS</li> <li>DUSTRAINTS</li> <li>CONSTRAINTS</li> <li>DISCHANCE RATINGS</li> <li>RAINFALL/RESERVOIR RECORDS</li> </ul>

ITEM	REMARKS
 DESIGN REPORTS	New York State Department of Transportation Utica, New York
GEOLOGY REPORTS	New York State Department of Transporation Thomas H. Wiggin Report.
 DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	Unknown Thomas H. Wiggin Report - New York State Department of Transportation Unknown
MATERIALS INVESTIGATIONS BORING RECORDS LANUKATURY FILLD	New York State Department of Transportation Unknown Unknown
POST-CONSTRUCTION SURVEYS OF DAM	None known
BORROW SOURCES	Unknown

I I I	
EM	REMARKS
NITORING SYSTEMS	Staff gage at dam by caretaker and U.S.G.S. gaging station downstream
DIFICATIONS	None known
GH POOL RECORDS	caretaker's office at dam - Hurricane Agnes June 1972 W.E. 554.2
DST CONSTRUCTION ENGINEERING FUDIES AND REPORTS	New York State Department of Transportation - Materials Bureau 1976 Thomas II. Wiggin Report - 1924.
RIOR ACCIDENTS OR FAILURE OF DAM Escription Eports	None Known
A I NT ENANCE PERATION ECORDS	New York State Department of Transportation Utica, New York

and an and and

|--|

## CHECK LIST HYDROLOGIC AND HYDRAULIC ENGINEERING DATA

DRAIN	AGE	AREA CHARACTERISTICS: 15	0 square miles rolling woodland
ELEV	TIO	N TOP NORMAL POOL (STORAG	E CAPACITY): 550.0 (63,000 acre feet)
ELEVA	AT 10	N TOP FLOOD CONTROL POOL	(STORAGE CAPACITY): N/A
ELEV	ATIO	N MAXIMUM DESIGN POOL:	Unknown
ELEV	ATIO	N TOP DAM:	558.0
CRES	r:		
	a.	Elevation	550.0
	ь.	Туре	concrete ogee
	c.	Width	
	d.	Length	300.0
	e.	Location Spillover	center of structure
	f.	Number and Type of Gates	None

OUTLET WORKS:

in the second

-

[]

[]

[]

a.	Type	4-60"	steel	pipes	
			Contraction and a state of the second		

ь.	Location	East of	center of	dam
c.	Entrance inverts	487.5		
d.	Exit inverts	479.0		
e.	Emergency draindown	facilities	Above pipe	S .

## HYDROMETEOROLOGICAL GAGES:

a.	Туре	Staff gage	Stream gage - U.S.G.S.
ь.	Location	Dam Upstream	Downstream
c.	Records	Daily by care taker	U.S.G.S.

MAXIMUM NON-DAMAGING DISCHARGE Hurricane Agnes - June 1972 - 4.2' over spillway