

AD-A072 234

O'BRIEN AND GERE ENGINEERS INC PHILADELPHIA PA JUSTIN--ETC F/G 13/2
NATIONAL DAM INSPECTION PROGRAM. LOWER LAKE DAM (NDI-PA 00306, --ETC(U)
MAY 79

DACW31-79-C-0010


NL

UNCLASSIFIED

OF
AD
A07223



END
DATE
FILED
9-79
DDC



DELAWARE RIVER BASIN
EAST BRANCH WALLENPAUPACK CREEK, PIKE COUNTY

11

DA072234

LOWER LAKE DAM


NDI - PA 00306

PA DER 52-144

LEVEL

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM



Distribution Unlimited
Approved for Public Release
Contract No. DACW31-79-C-0010

FILE COPY

Prepared By
O'BRIEN & GERE
Justin & Courtney Division
PHILADELPHIA, PENNSYLVANIA
19103

FOR
DEPARTMENT OF THE ARMY
BALTIMORE DISTRICT CORPS OF ENGINEERS
BALTIMORE, MARYLAND

DDC
REF ID: A

MAY 1979

~~790806055~~

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DDC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

(12)

94P

(11)

May 79

DELAWARE RIVER BASIN

Name of Dam: Lower Lake Dam

County and State: Pike County, Pennsylvania

Inventory Number: PA 00306

(15)

DACW31-79-C-0010

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

(6)

National Dam Inspection Program.
Lower Lake Dam (NDI-PA 00306, PA
DER 52-144), Delaware River Basin,
East Branch Wallenpaupack Creek, Pike
County, Pennsylvania. Phase I Inspection Report.

Prepared by:

O'BRIEN & GERE ENGINEERS, INC.
JUSTIN & COURTNEY DIVISION

For:

DEPARTMENT OF THE ARMY
Baltimore District, Corps of Engineers
Baltimore, Maryland 21203

Accession For	
NTIS GRA&I	
DDC TAB	
Unannounced	
Justification	
By _____	
Distribution/	
Availability Codes	
Dist.	Avail and/or special
A	23 CP

410760 Gen

79 08 06 055

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected, and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I REPORT
NATIONAL DAM INSPECTION PROGRAMS

Name of Dam: Lower Lake Dam ID # PA 00306
State Located: Pennsylvania
County Located: Pike
Stream: East Branch Wauhallaupack Creek
Coordinates: Latitude 41° 19.1', Longitude 75° 12.6'
Date of Inspection: December 6, 1978

ASSESSMENT

Lower Lake Dam is an earth embankment with a concrete gravity spillway. The embankment is approximately 340 feet in length with a maximum height of 22.5 feet. The spillway is a broad crested weir, 140 feet in length, divided into three sections. The reservoir drain system consists of two 72" x 44" corrugated metal pipes controlled by means of 36-inch diameter sluice gates. The dam impounds a 250 acre reservoir for recreation within the Promised Land State Park.

Examination of the results of the hydrologic and hydraulic analyses indicates that the spillway is capable of passing the 0.5 PMF, therefore, the spillway is classified as adequate.

Based on visual observations made on the date of the inspection, the dam and its appurtenant structures are considered to be in good condition. Riprap on the upstream side of the embankment is missing or covered by grass and earth. Minor settlement has occurred in an area adjacent to the downstream side of the right wingwall. A crack and movement of the left wingwall at the tie-in with the upstream slope of the embankment has occurred. Erosion has created depressions on the upstream side of the embankment, particularly the lower half of the right side of the embankment and along both wingwalls.

Recommendations and remedial measures are as follows:

a. Facilities

1. Eroded areas on the upstream face of the embankment should be filled; graded filter and riprap should be provided where wave protection is inadequate.
2. The area of settlement adjacent to the right wingwall on the downstream side should be excavated several feet and the backfill

material compacted. Monthly observations should be made to check for settlement.

3. The crack in the upstream side of the left wingwall and the adjacent construction joint should be monitored for further movement.

b. Operation and Maintenance Procedures

1. A warning system should be developed. During periods of heavy rainfall or rapid snowmelt, the dam should be monitored and downstream residents alerted in the event of an impending failure.

O'BRIEN & GERE ENGINEERS, INC.
JUSTIN & COURTNEY DIVISION

Will M. Heiser

Will M. Heiser, P.E.
Vice-President
Pennsylvania Registration #006926-E



June 8, 1979

James W. Peck

Approved By
JAMES W. PECK
Colonel, Corps of Engineers
District Engineer

Date: 16 Jy 1979

OVERVIEW
LOWER LAKE DAM, PIKE COUNTY, PENNSYLVANIA




TABLE OF CONTENTS

	<u>PAGE</u>
SECTION 1 - PROJECT INFORMATION	
1.1 General	1
1.2 Description of Project	1
1.3 Pertinent Data	3
SECTION 2 - ENGINEERING DATA	
2.1 Design	5
2.2 Construction	5
2.3 Operation	5
2.4 Evaluation	6
SECTION 3 - VISUAL INSPECTION	
3.1 Findings	7
SECTION 4 - OPERATIONAL FEATURES	
4.1 Procedures	8
4.2 Maintenance of the Dam	8
4.3 Maintenance of Operating Facilities	8
4.4 Warning System in Effect	8
4.5 Evaluation of Operational Adequacy	8
SECTION 5 - HYDRAULICS AND HYDROLOGY	
5.1 Evaluation of Features	9
SECTION 6 - STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability	10
SECTION 7 - ASSESSMENT, RECOMMENDATIONS AND PROPOSED REMEDIAL MEASURES	
7.1 Dam Assessment	11
7.2 Recommendations and Proposed Remedial Measures	11

TABLE OF CONTENTS
(Continued)

- | | |
|--------------|---|
| APPENDIX A - | CHECKLIST, ENGINEERING DATA, DESIGN
CONSTRUCTION, OPERATION, PHASE I |
| APPENDIX B - | CHECKLIST, VISUAL INSPECTION, PHASE I |
| APPENDIX C - | HYDROLOGIC & HYDRAULIC DATA |
| APPENDIX D - | PHOTOGRAPHS |
| APPENDIX E - | DRAWINGS |
| APPENDIX F - | SITE GEOLOGY |

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
LOWER LAKE DAM
NDI ID NO. PA-00306
DER # 52-144

SECTION 1
PROJECT INFORMATION

1.1 General

- a. Authority. The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.
- b. Purpose of Inspection. The purpose of this inspection is to evaluate the structural and hydraulic conditions of the Lower Lake Dam and appurtenant structures, and to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project

- a. Dam and Appurtenances. (Supplemented by information obtained from the Pennsylvania Department of Environmental Resources (DER), Division of Dam Safety.)

Lower Lake Dam is an earth embankment with a concrete gravity spillway. The embankment is approximately 340 feet in length with a maximum height of 22.5 feet. The dam impounds a reservoir with a surface area of 250 acres and a storage capacity of 1,085 acre-feet at normal pool level. The top of the dam is 20 feet wide; the upstream and downstream side slopes are approximately 2.5 horizontal to 1.0 vertical (2.5H:1V). No information is available concerning the properties of the embankment materials. Within the embankment is a tapered reinforced concrete cutoff wall that extends from bedrock to 3.5 feet below the top of the embankment.

The reinforced concrete spillway, which has a maximum height of 13 feet from base to crest, consists of 3 sections separated by bridge piers. Each section is a broad-crested weir with a vertical upstream face and a flat, sloping downstream face. The crest of the center section is 48.5 feet long and the crest of each of the two end sections is 45.75 feet long. The crest of the center section, which is 3 feet wide, is 0.5 feet below the crest of the end sections; each of the end sections is 2.5 feet wide. At the base of the weir is a stilling basin with baffle blocks. The stilling basin slab, which has six 3-inch weep holes, overlays a 6-inch layer of

stone. Approximately 26 feet downstream of the toe of the spillway is a 2 foot high weir or end sill with six 3"x6" semicircular drains. The stilling basin floor extends an additional 3 feet downstream from the toe of the end sill. This additional section is cantilevered above an apron located 4 feet below the overhang. Seven 4-inch pipes pass through the end wall supporting the stilling basin slab to provide drainage for the 6-inch layer of stone that is under the stilling basin slab.

The reservoir drain system consists of two 72"x44" corrugated metal pipes located near the base of the two bridge piers. Flow through the pipes discharges on the apron. The flow is controlled by means of 36 inch diameter sluice gates located at the upstream end of the pipes. The sluice gates are operated from the bridge deck.

The underside of the concrete bridge structure is located approximately 7 feet above the crest of the spillway and has an 18-foot wide asphalt roadway.

- b. Location. Lower Lake Dam is located on the East Branch of Wauallen-paupack Creek at a point about 1 mile west of Promised Land, in Green Township, Pike County, Pennsylvania. The dam site is shown on the USGS Quadrangle entitled "Promised Land, Pennsylvania" at coordinates N 41° 19.1', W 75° 12.6'. A regional location plan of Lower Lake Dam is included as Plate 1, Appendix E.
- c. Size Classification. Lower Lake Dam has a maximum capacity of 1,347 million gallons (4,140 acre-feet) and a maximum height of 22.5 feet. The structure is in the intermediate size category.
- d. Hazard Classification. There are approximately 40 private residences on Lake Paupack, which is located 1.5 miles downstream of Lower Lake Dam. The topography downstream of the dam is such that flood waters would not be directed toward these homes. Therefore, the structure is in the "Significant" hazard category.
- e. Ownership. The dam is owned and operated by the Commonwealth of Pennsylvania, Department of Environmental Resources. Correspondence should be addressed to the Commonwealth of Pennsylvania, Department of Environmental Resources, P.O. Box 1467, Harrisburg, Pennsylvania, 17120.
- f. Purpose of the Dam. The dam was built to provide a reservoir for recreation in the Promised Land State Park.
- g. Design and Construction History. The dam was designed by L. Robert Kimball, a consulting engineer, and was constructed by the Pocono Mountains Construction Company, Inc. between 1958 and 1959. Repairs to the abutment wingwalls to correct structural deficiencies and drainage problems were made in 1963 and 1964.

- h. Normal Operating Procedures. According to the Park Foreman, the lake is normally maintained at Elevation 1707.0 which is the elevation of the center spillway crest. Operating procedures are limited to the operation of the two sluice gates, which are normally in a partially open position. A minimum release of 1.6 cfs. is required by DER.

1.3 Pertinent Data

a. Drainage Area.

Square Miles	10.6
--------------	------

b. Discharge at Dam Site (cfs.).

Total Spillway Capacity at top of dam Elev. 1717.0	14,620
---	--------

c. Elevation (Feet above MSL).

Spillway Crest, Center Section (Normal, Recreation Pool)	1707.0
Spillway Crest, Outer Sections	1707.5
Top of Dam (at low point of top of dam)	1717.0
Reservoir Drain Invert	1694.5
Streambed at Centerline of Dam	1694.5

d. Reservoir (Miles).

Length of Normal, Recreation Pool	1.2
Length at Maximum Non-overtopping Pool	1.4
Fetch at Normal Pool	0.5

e. Storage (acre-foot).

Normal, recreation pool, Elev. 1707.0	1,085
Top of Dam at Low Point, Elev. 1717.0	4,140

f. Reservoir Surface Area (acres).

Normal, Recreation Pool, Elev. 1707.0	250
Top of Dam at Low Point, Elev. 1717.0	365

g. Dam Data.

Type	Earth
Length	340 feet
Height	22.5 feet (maximum)
Top Width	20 feet
Side Slopes	2.5H:1V (upstream and downstream)
Zoning	No
Impervious Core	No
Cutoff	Yes
Grout Curtain	No

h. Spillway.

Type	Broad-crested weir
Length	48.5 feet (center sections)
Width	45.75 feet (outer sections)
Crest Elevation	3.0 feet (center section)
Gates	2.5 feet (outer sections)
Upstream Channel	1707.0 (center section)
Downstream Channel	1707.5 (outer sections)
	None
	Lower Lake
	Follows a natural draw through a heavily wooded region.

i. Outlet Works.

Type	Two 72"x44" CMP's
Length	50 feet
Closure	Two 36-inch diameter sluice gates at upstream end.
Access	Intake is submerged; Hand- operated mechanism for sluice gate on deck of bridge.
Regulating Facilities	Hand operated sluice gates

SECTION 2
ENGINEERING DATA

2.1 Design

- a. Data Available. The information available for review of Lower Lake Dam includes the following (all information obtained from the Pennsylvania DER main office files in Harrisburg, Pennsylvania):
 - 1. Dam inspection reports beginning in 1962 and through the intervening years.
 - 2. Photographs beginning in 1958 and through the intervening years.
 - 3. Application, Report Upon the Application and Permit for construction of Lower Lake Dam.
 - 4. Seven design drawings - L. Robert Kimball, consulting Engineer.
 - 5. Miscellaneous correspondence.
- b. Design Features. The design features are discussed in Section 1.2.a and shown on Plates 2, 3, 4 and 5 of Appendix E.

2.2 Construction

The construction data available in the Pennsylvania DER offices in Harrisburg, Pennsylvania, are several photographs, construction reports and correspondence. The dam was constructed by the Pocono Mountains Construction Company, Inc. between 1958 and 1959. Repairs to the downstream wingwalls were made in 1963 or 1964 to correct structural deficiencies. Saturated earth loads on the wingwalls had caused deflections of the walls, openings in joints, and fracturing in the south abutment wingwall. The repairs to the wingwalls were made, additional weepholes were drilled in the walls, and a drainage system constructed to carry the runoff below the wingwalls.

2.3 Operation

Operation procedures appear to be limited to those necessary to maintain a minimum flow of 1.6 cfs. or to draw the lake down by means of the sluice gates, which are operated from the bridge deck. There is no evidence that operating procedures have been written for this structure.

2.4 Evaluation

- a. Availability. All information made available was obtained from DER.
- b. Adequacy. Information supplied by DER, observations made during the field inspection, and discussions with the park foreman provided sufficient material to perform a Phase I evaluation.
- c. Validity. There appears to be no reason to question the validity of the information available.

SECTION 3
VISUAL INSPECTION

3.1 Findings

- a. General. The field inspection of the Lower Lake Dam took place on December 6, 1978. The reservoir water surface elevation was approximately an inch above the spillway crest of the center section during the inspection. No underwater areas were inspected. The observations and comments of the field inspection team are in the checklist which is Appendix B of this report. The appearance of the facility indicates that the dam and its appurtenances are well maintained.
- b. Dam. The riprap on the upstream side of the embankment is missing or covered by grass and earth. There is an area of minor settlement of up to 3 inches in the embankment adjacent to the downstream right wingwall tie-in. This area is approximately 3 feet wide and 30 feet long. Erosion has created depressions up to 12 inches deep along both upstream wingwalls and depressions up to 3 inches deep on the lower half of the upstream slope on the right side of the embankment. The depressions along the wingwalls cover a 2 to 3 feet wide strip from the top of the dam to the waterline. The eroded area of the embankment covers a 7 foot wide strip starting at the wingwall and extending approximately 40 feet.
- c. Appurtenant Structures. A crack at the upstream end of the left wingwall at the tie-in was observed as well as a differential movement of approximately 1/4 inch of an adjacent construction joint. Occasional hairline cracking and spalling of the wingwalls were noted.

The park foreman, Carl Rose, opened both sluice gates further to demonstrate that they were fully operational.

- d. Reservoir. Area reconnaissance of the reservoir disclosed no evidence of excessive siltation, slope instability, or other features that would significantly affect the storage capacity of the reservoir. The slopes along the perimeter are heavily vegetated and on gradients of less than 15 percent. Promised Land Dam is located immediately upstream of the reservoir.
- e. Downstream Channel. Below Lower Lake Dam, the East Branch of Wauhallaupack Creek flows through heavily wooded areas for 1.5 miles before reaching Lake Paupack. The channel gradient averages about 1.1% for this section of the creek.

SECTION 4
OPERATIONAL PROCEDURES

4.1 Procedures

Operational procedures have been covered in section 1.2.h. According to the owner's representative, written operating procedures are not available. Normal operating procedures for this structure do not require a dam tender.

4.2 Maintenance of the Dam

The dam appears to be well maintained by the Promised Land State Park personnel. Maintenance inspections are reported to be conducted on a regular basis by both the Park Superintendent and personnel from the Division of Completed Projects, DER. Records and photographs of these inspections are available. Regular maintenance performed has consisted of minor concrete repairs and debris removal.

4.3 Maintenance of Operating Facilities

According to the maintenance records, the sluice gates are checked, lubricated, and operated on a regular basis by Promised Land State Park personnel.

4.4 Warning System in Effect

According to the Park Superintendent, no formal warning systems or procedures have been established for periods of high lake levels.

4.5 Evaluation of Operational Adequacy

The current operating and maintenance procedures for the Lower Lake Dam appear to be adequate, even though there are no formal operating procedures.

A warning system should be developed. During periods of heavy rainfall or rapid snowmelt, the dam should be monitored and downstream residents alerted in the event of an impending failure.

The dam is accessible under all weather conditions for inspection and emergency action.

SECTION 5
HYDRAULICS AND HYDROLOGY

5.1 Evaluation of Features

- a. Design Data. No original design data is available. The drainage area contributing to Lower Lake Dam is about 5.0 miles long and averages about 2.1 miles wide. Ground elevations range from 2012 to 1707. The slopes of the watershed adjacent to the reservoir are all less than 15 percent. The watershed is nearly 100 percent wooded.

For further information, refer to the computations, data, and printouts included in Appendix C.

- b. Experience Data. According to the owner's representative, no regular records of reservoir water levels are maintained. However, during Hurricane Agnes in June, 1972, the stage in the reservoir was observed to be 18 inches above the crest of the spillway. Rainfall records for Promised Land State Park are maintained at the Park Office.

- c. Visual Observations. On the date of the inspection, no adverse conditions were observed that would indicate that the spillway capacity would be reduced during a flood. Further observations are given in Appendix B.

- d. Overtopping Potential. The spillway is capable of handling a discharge of 11,700 cfs. The SDF for this "Intermediate" size dam, with a "Significant" hazard classification, is the 0.5 PMF which has a peak inflow of 4,570 cfs. and a peak outflow of 3,190 cfs. The 0.5 PMF hydrograph for the Promised Land Dam drainage area was routed through that reservoir with a starting water surface elevation at 1726.3, 0.2 above the crest of the spillway, and into Lower Lake. At this point, the routed Promised Land Dam hydrograph was combined with the 0.5 PMF hydrograph for the Lower Lake drainage area and routed through Lower Lake with a starting water surface elevation of 1707.3, 0.3 feet above the crest of the center section of the spillway. The maximum water surface elevation in the Lower Lake Reservoir resulting from this routing is 4.0 feet above the spillway crest of the center section and 6.0 feet below the lowest point of the top of the dam.

Examination of the results of the hydrologic and hydraulic analyses indicates that the spillway is capable of passing the 0.5 PMF without overtopping the embankment (See Appendix C for computations).

- e. Spillway Adequacy. The Lower Lake Dam spillway is classified as adequate.

SECTION 6

STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

- a. Visual Observations. Riprap facing on the upstream slope of the embankment is missing or covered by grass and earth. Minor settlement of up to 3 inches of the embankment adjacent to the downstream right wingwall tie-in could be due to poor compaction of earth adjacent to wingwall.

A crack at the upstream end of the left wingwall at the tie-in and movement of an adjacent construction joint of approximately 1/4 inch were observed. However, this should have minor effect on the overall stability of the structure. Occasional hairline cracking and spalling of the wingwalls were noted.

Based on the available information and field observations, the embankment and spillway appear to be in good condition with no visible signs of structural instability.

- b. Design and Construction Data. A partial set of design drawings is available. No design calculations or soil data are available. Lists of the design and construction data reviewed are given in Section 2.1.a and 2.2.
- c. Operating Records. There is no evidence that operating records are maintained for the Lower Lake Dam.
- d. Post-Construction Changes. The available information indicates that the only major modifications to the original structure were made in 1963 or 1964 on the wingwalls to correct deflections of the walls, openings in joints, and fracturing of concrete in the south abutment wingwall. The wingwalls were repaired, additional weepholes drilled in the walls, and a drainage system constructed to carry the runoff below the wingwalls. Information is available in the DER files on maintenance work done on the dam through the years.
- e. Seismic Stability. Lower Lake Dam is located within Seismic Risk Zone I of the "Seismic Zone Map of Contiguous States". Normally, it can be considered that if a dam in this zone is stable under static loading conditions, it can be assumed safe for any expected Zone 1 earthquake conditions.

SECTION 7

ASSESSMENT, RECOMMENDATIONS, AND PROPOSED REMEDIAL MEASURES

7.1 Dam Assessment

- a. Evaluation. Based on visual observations made on the date of the inspection, the dam and its appurtenant structures are considered to be in good condition. Riprap on the upstream side of the embankment is missing or covered by grass and earth. Minor settlement has occurred in an area adjacent to the downstream side of the right wingwall. A crack and movement of the left wingwall at the tie-in with the upstream slope of the embankment has occurred. Erosion has created depressions on the upstream side of the embankment, particularly the lower half of the right side of the embankment and along both wingwalls.

The SDF is the 0.5 PMF. Examination of the results of the hydrologic and hydraulic analysis indicates that the spillway is capable of passing the 0.5 PMF and, therefore, is adequate.

- b. Adequacy of Information. A Phase I evaluation is considered reasonable based on observations made during the field inspection, information supplied by DER, and conversations with the owner's representative.
- c. Urgency. The remedial measures recommended in Section 7.2 should be effected as soon as possible.
- d. Necessity for Further Evaluation. No further investigations are recommended at this time.

7.2 Recommendations and Proposed Remedial Measures

a. Facilities

1. Eroded areas on the upstream face of the embankment should be filled; graded filter and riprap should be provided where wave protection is inadequate.
2. The area of settlement adjacent to the right wingwall on the downstream side should be excavated several feet and the backfill material compacted. Monthly observations should be made to check for settlement.
3. The crack in the upstream side of the left wingwall and the adjacent construction joint should be monitored for further movement.

b. Operation and Maintenance Procedures

1. A warning system should be developed. During periods of heavy rainfall or rapid snowmelt, the dam should be monitored and downstream residents alerted in the event of an impending failure.

APPENDIX

A

**Check List Engineering Data
Design, Construction, Operation**

Phase I

APPENDIX

A

Check List Engineering Data

Design, Construction, Operation

Phase I

CHECK LIST NAME OF DAM Lower Lake Dam
ENGINEERING DATA ID # PA - 00306
DESIGN, CONSTRUCTION, OPERATION
PHASE I

NAME OF DAM Lower Lake Dam
ID # PA - 00306

Sheet 1 of 4

REMARKS

AS-BUILT DRAWINGS

There are no "As-Built" drawings available. There are 7 Design drawings in DE12 file. See Plates 2, 3, 4, and 5 in Appendix E.

REGIONAL VICINITY MAP

Refer to Appendix E, Plate 1

The dam was built in 1958-1959 by the General State Authority of Pennsylvania for the purpose of creating a recreation pool. The structure was designed by L. Robert Kimball, P.E. & constructed by Pocono Mountain Construction Co., Inc.. Repairs to the abutment wingwalls to correct fracture and drainage problem were made in 1961 or 1962.

CONSTRUCTION HISTORY

TYPICAL SECTIONS OF DAM

OUTLETS - PLAIN DETAILS CONSTRAINTS

RAINEAU / RESERVOIR RECORDS

ITEM	REMARKS
DESIGN REPORTS	"Report Upon the Application of the Department of Forests and Waters" for Lower Lake Dam available in DER files.

GEOLOGY REPORTS	None provided in DER files. Refer to Appendix F of this report
-----------------	--

DESIGN COMPUTATIONS	No data available
HYDROLOGY & HYDRAULICS	No data available
DAM STABILITY	No data available
SEEPAGE STUDIES	No data available

MATERIALS INVESTIGATIONS	Brief descriptions of boring logs and excavation in "Report Upon the Application of the Department of Forests and Waters" for Lower Lake Dam and in construction reports.
BORING RECORDS LABORATORY } FIELD }	

POST-CONSTRUCTION SURVEYS OF DAM	May, 1961 inspection of dam by G.S.A. engineer
----------------------------------	--

BORROW SOURCES	There is no record of the source of the borrow material.
----------------	--

Sheet 3 of 4

ITEM	REMARKS
MONITORING SYSTEMS	None
MODIFICATIONS	Additional weep hole added to downstream retaining walls.
HIGH POOL RECORDS	June, 1971 - Hurricane Agnes - 18 inches of water on top of wall
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	Fracturing, deflection, and separation of retaining walls on downstream side - noted May, 1961 - repaired walls and weep holes added.
MAINTENANCE OPERATION RECORDS	Regular maintenance inspections from June, 1962 to present date. Maintenance performed noted in reports. Information available in DEER files.

ITEM	REMARKS
SPILLWAY PLAN	
SECTIONS	{ Refer to Appendix E
DETAILS	

OPERATING EQUIPMENT
PLANS & DETAILS

No information available.

MISCELLANEOUS

Material in DER files:

1. Engineering Drawings
2. Construction Reports
3. Dam inspection reports through the years.
4. Photographs taken during dam inspections.
5. Miscellaneous correspondence.
6. Application, Report upon the Application, and Permit for construction of Lower Lake Dam

APPENDIX

B

Check List

Visual Inspection

Phase I

CHECK LIST
VISUAL INSPECTION
PHASE I

Sheet 1 of 11

Name Dam	<u>Lion's Gap Lake Dam</u>	County	<u>Pike</u>	State	<u>Pennsylvania</u>	National ID #	<u>PA - 000006</u>
Type of Dam	<u>Earth Fill / Cong. Gravity</u>	Hazard Category	<u>High</u>				
Date(s) Inspection	<u>Dec. 10, 1970</u>	Weather	<u>Clear, cold</u>	Temperature	<u>≈ 32°</u>		

Pool Elevation at Time of Inspection 1707.1 M.S.L. Tailwater at Time of Inspection 1694 M.S.L.

Inspection Personnel:

<u>George C. Ellis</u>	<u>Dawn R. Pizarro</u>
<u>David B. Campbell</u>	
<u>Thomas G. Ahn</u>	<u>David B. Campbell</u>
	Recorder

Remarks:

Carl Rose, promised land State Park foreman, accompanied inspection personnel.

CONCRETE/MASONRY DAMS

Sheet 2 of 11		
<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
ANY NOTICEABLE SEEPAGE	None Observed	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	No separation observed	
DRAINS	Draains for 6" stone layer under stalling basin slab are working. Deep holes in stalling basin slab drain into 6" stone layer	
WATER PASSAGES	N/A	
FOUNDATION	Not Observed	

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF		OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	CONCRETE SURFACES	Occasional hairline cracking of wing walls, some minor spalling.	Patch cracks & spalls
STRUCTURAL CRACKING		Slight cracking at upstream end or left wing wall at tie-in,	Continue to observe, no problem now.
VERTICAL AND HORIZONTAL ALIGNMENT		No alignment problems observed.	-
MONOLITH JOINTS		No problems observed	-
CONSTRUCTION JOINTS		small differential movement at construction joint on upstream side of left wingwall separation between left and center unit and south wingwall	Continue to observe

ENBANKMENT

Sheet 4 of 11

REMARKS OR RECOMMENDATIONS

VISUAL EXAMINATION OF		REMARKS OR RECOMMENDATIONS
OBSERVATIONS		
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed	-
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Erosion along upstream side of left wingwall, Erosion has created depression about 1.5' deep along upstream side of right wingwall. General erosion of lower left of upstream slope on right side.	Fill eroded areas and reseed
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	No misalignment observed	-
RIPRAP FAILURES	Upstream slope supposed to have 1 foot thick riprap layer. Riprap is missing or uneven across and over.	Restore riprap to upstream slope

EMBANKMENT

Sheet 5 of 11

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
DRAINS	Warp holes on both waterways, drain portion of embankment, warp holes on discharge, some discharging water (up to 10 cm)	-
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Some minor settlement adjacent to right abutment tie-in, low elevation and discharge.	-
ANY NOTICEABLE SEEPAGE	None observed	-
STAFF GAGE AND RECORDER	None	-

OUTLET WORKS

Sheet 6 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	N/F	
INTAKE STRUCTURE	Not observed under water Rmk foreman opened both sluice gates	
OUTLET STRUCTURE	72" x 44" CMP, couldn't observe exterior (CMP controlled by 36" clam. sluice gates)	
OUTLET CHANNEL	CMP's empty onto concrete apart + than to natural channel which contains heavily washed about 50% fine sand	
EMERGENCY GATE	2 - 36" clam. sluice gate controlling 2 - 72" x 44" CMP's	
BRIDGE	Steel bridge with 2 - 1'-6" piers (cone.) on spillway, bridge 7'-3" above center section of spillway, bridge has asphalt roadway.	

UNGATED SPILLWAY

Sheet 7 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	breakwater weirs (2'-6" wide), 3 sections, first 6' long at Outer section about 6" higher than center section, weir has vertical upstream face and flat sloping downstream face	-
APPROACH CHANNEL	lower lake	-
DISCHARGE CHANNEL	water flows over weirs into stilling basin with baffle blocks water from stilling basin discharged through, and over embankment wall and drops to concrete apron, then to natural channel	see sheet 6/11
BRIDGE AND PIERS		

GATED SPILLWAY

Sheet 8 of 11

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
CONCRETE SILL	N/A	
APPROACH CHANNEL	N/A	
DISCHARGE CHANNEL	N/A	
BRIDGE AND PIERS	N/A	
GATES AND OPERATION EQUIPMENT	N/A	

INSTRUMENTATION		
	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
VISUAL EXAMINATION	None	
MONUMENTATION/SURVEYS		
OBSERVATION WELLS	None	
WEIRS	None	
PIEZOMETERS	None	
OTHER	N/A	

RESERVOIRVISUAL EXAMINATION OF
OBSERVATIONS

	<u>REMARKS OR RECOMMENDATIONS</u>
SLOPES	All slopes less than 15% Shoreline generally (mainly) unobstructed, park facility areas also partially cleared
SEDIMENTATION	None obstructed

DOWNSTREAM CHANNEL

Sheet 11 of 11

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
<u>CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)</u>	Channel flows through heavily wooded areas for 1.5 miles to Lake Pauline. No bridges or man-made obstructions.	
<u>SLOPES</u>	The channel gradient averages about 1.1% for the 1.5 miles from Lower Lake Dam to Lake Pauline.	
<u>APPROXIMATE NO. OF HOMES AND POPULATION</u>	There are approximately 40 homes on Lake Pauline with an estimated population of 200.	A formal warning system should be developed and implemented. Procedures for evacuating people within the potential flood area should be implemented.

APPENDIX

C

Hydrologic & Hydraulic Data

SUBJECT	SHEET	BY	DATE	JOB NO
---------	-------	----	------	--------

TABLE OF CONTENTS APPENDIX C

Hydraulics & Hydrologic Data

Promised Land Dam

Hydrograph Coefficients & PMP Calculations	shts. 1&1
Stage-Area, Stage-Storage Calculations	shts. 2, 2a, 2b
Spillway & Embankment Discharge Comp.	shts. 3 & 4
Route 350 Cutout Discharge Computations	shts. 5-9
channel Erosion Below Dam	sht. 9a

Lower Lake Dam

Hydrograph Coefficients & PMP Calculations	shts. 10&11
Stage-Area, Stage-Storage Calculations	shts. 11&12
Spillway & Embankment Discharge Computations	shts. 13-15

HEC - I Dam Safety Version Computer Output shts. 19-28

SUBJECT	Upper Promised Land Dam	SHEET	1	BY	DRP	DATE	12/14/75	JOB NO	1841-010
---------	-------------------------	-------	---	----	-----	------	----------	--------	----------

D.A. = Area I + Area II

$$\text{Area I} = 1.015 \text{ in}^2/\text{unit} \times 27.7 \text{ units} \times 4 \times 10^6 \frac{\text{ft}^2}{\text{in}^2} \times 3.587 \times 10^{-8} \frac{\text{mi}^2}{\text{ft}^2}$$

$$= 4.04 \text{ mi}^2$$

$$\text{Area II} = 1.015 \text{ in}^2/\text{unit} \times 19.53 \text{ units} \times 4 \times 10^6 \frac{\text{ft}^2}{\text{in}^2} \times 3.587 \times 10^{-8} \frac{\text{mi}^2}{\text{ft}^2}$$

$$= 2.84 \text{ mi}^2$$

$$\text{D.A.} = 6.88 \text{ mi}^2 \approx 6.9 \text{ mi}^2 \text{ by planimeter}$$

6.57 mi² by reports use 6.57 mi²

Hydrograph Parameters (Snyder method)

$$\epsilon_p = C_t (L L_c)^{0.3}$$

$$C_t = 1.23 \quad \left. \begin{array}{l} \text{supplied by COE} \\ C_p = 0.45 \end{array} \right\} \text{Zone 1}$$

$$L = 4.1 \text{ miles}$$

$$L_c = 1.9 \text{ miles}$$

$$\epsilon_p = 1.23 ((4.1)(1.9))^{0.3} = 2.3 \text{ hr.}$$

$$\epsilon_r = \frac{2.3 \text{ hr.}}{5.5} = 0.4 \text{ hr.}$$

Probable Maximum Storm (PMS) (Hydromet 33)

Zone 1 (Fig. 1)

Probable Max. Precip (PMP) = 22.2 in. (200 mi², 24 hr)

Depth-Area-Duration Relationships

Maximum 6 hr = 111% PMP

Maximum 12 hr = 123% PMP

Maximum 24 hr = 133% PMP

Loss Rate

initial loss = 1"

uniform loss = 0.05 in./hr

SUBJECT

Upper Promised Land Dam

SHEET

1

BY

DRP

DATE

12/15/73

JOB NO

1841-010

Base flow

$$1.5 \text{ cfs}/\text{mi}^2 \times 6.57 \text{ mi}^2 = 9.9 \text{ cfs}$$

Elevation - Area - Capacity Data

Elev.

1725.6

1727

1740

1760

1720.4

1715.1 (Streambed elev.)

Area (mi²)

0.71

1.27

1.90

Area (Acres)

422.0 - data

460.8]

812.8 } planimeter

1216.0]

287

0

extension of data
see next page



O'BRIEN & GERE

SUBJECT

PLD

SHEET

BY

2a DRP

DATE

1/18/79

JOB NO

1841-010

Extend Elevation-Area-Capacity Data below spillway crest
using conic method:

$$V = 765,000,000 \text{ gallons at Elav 1725.6} \quad A = 422 \text{ acre-ft}$$

$$(h = 1725.6 - 1715.1 \text{ (streambed elev)} = 10.5 \text{ ft}) \quad A = 18,382,320 \text{ ft}^2$$

$$\rightarrow V = 102,172,727 \text{ cu ft} = 2347 \text{ acre-ft}$$

$$r = \sqrt{\frac{A}{\pi}} = \sqrt{\frac{18,382,320 \text{ ft}^2}{\pi}} = 2418.9 \text{ ft}$$

$$V = \pi (2418.9)^2 \frac{(105)}{3} = 64,335,954 \text{ cu ft} \quad (\text{single cone})$$

too low

break into 2 cones

① assume area at $h/2$ is $1/2$ area at h

$$\begin{aligned} \text{Upper Cone Volume} &= \left(\frac{5.25}{3}\right)(422 + 211 + \sqrt{(422)(211)}) \\ &= 1629.9 \text{ acre-ft} \approx 71,000,000 \text{ cu ft} \end{aligned}$$

$$\begin{aligned} \text{Bottom Cone Volume} &= \pi r^2 \frac{h}{3} = A \frac{h}{3} = 211 \left(\frac{5.25}{3}\right) = 369.3 \text{ acre-ft} \\ &= 16,000,000 \text{ cu ft} \end{aligned}$$

$$\begin{aligned} \text{Total} &= 87,000,000 \text{ cu ft} \\ &\text{too low} \end{aligned}$$

② assume area at $h/2$ is 55% area at h

$$\begin{aligned} \text{Upper Cone Volume} &= \left(\frac{5.25}{3}\right)(422 + 232 + \sqrt{(422)(232)}) \\ &= 1692 \text{ ac-ft} = 73,700,000 \text{ cu ft} \end{aligned}$$

$$\begin{aligned} \text{Bottom Cone Volume} &= \pi r^2 \frac{h}{3} = (232) \left(\frac{5.25}{3}\right) = 406 \text{ ac-ft} \\ &= 17,700,000 \text{ cu ft} \end{aligned}$$

$$\text{Total} = 91,400,000 \text{ too low}$$



O'BRIEN & GERE

SUBJECT

PLD

SHEET

2b

BY

DRP

DATE

1/13/79

JOB NO

1841-010

- ③ assume area at $h/2$ is 65% area at h

$$\text{Upper Cone Volume} = \left(\frac{5.25}{3}\right)(422 + 274 + \sqrt{(422)(274)})$$

$$= 1813 \text{ ac-ft} = 79,000,000 \text{ cu ft}$$

$$\text{Bottom Cone Volume} = \left(\frac{5.25}{3}\right)(274) = 479.5 \text{ ac-ft}$$

$$= 20,900,000 \text{ cu ft}$$

$$\text{Total} = 99,900,000 \text{ cu ft}$$

- ④ assume area at $h/2$ is 68% area at h

$$\text{Volume} = \left(\frac{5.23}{3}\right)(422 + 2(287) + \sqrt{(422)(287)})$$

$$= 2343 \text{ ac-ft} = 102,064,000 \text{ cu ft} \quad \underline{\text{good}}$$



O'BRIEN & GERE

SUBJECT

Upper Promised Land Dam

SHEET

3

BY

DRP

DATE

12/18/79

JOB NO

1841-010

Rev. 4/15/79

Spillway Discharge Rating

$$Q = CLH^{3/2}$$

broadcrested weir (trapezoidal section)

$$B = 14 \text{ ft} \quad (\text{width of weir})$$

$$C = 3.1 \quad (\text{Brater \& King})$$

Reduce L for abutment effects, no piers

$$L = L' - 1(NK_p + K_a)H_a \quad (\text{Design of Small Dams, 1977})$$

$$N=0 \quad (\text{no piers})$$

$$K_a = 0.2$$

$$H_a \approx H$$

$$L = 33 - 0.4 H$$

weir elev = 1726.1

embankment elev = 1731.1

$$Q = 3.1 LH^{3/2}$$

H (ft)	L (ft)	Q (cfs)	WSEL
0.7	32.7	59	1726.8
1.5	32.4	185	1727.6
3.0	31.8	512	1729.1
4.5	31.2	923	1730.6
5.0	31.0	1074	1731.1

Embankment Discharge Rating

$$Q = CLH^{3/2}$$

broadcrested weir (trapezoidal)

$$B = 12 \rightarrow 14 \text{ ft}$$

$$C = 3.1$$

$$\text{Elev } 1731 \quad L = 140 - 33 = 107 \text{ ft}$$

$$1731.6 \quad L = 160 - 33 = 127$$

$$1740 \quad L = 560$$



O'BRIEN & GERE

SUBJECT

Upper Promised Land Dam

SHEET

BY

DRP

DATE

12/20/78

JOB NO.

4/15/79

<u>Hair</u>	<u>Lhair</u>	<u>Qhair</u>	<u>Hemb</u>	<u>Lamb</u>	<u>Qemb</u>	<u>Qhair + Qemb</u>	<u>Elev.</u>
5	31	1074	0	0	0	1074	1731.1
6.5	31	1593	1.5	116	661	2254	1732.6
8	31	2174	3.0	124	1997	4171	1734.1
9.5	31	2614	4.5	170	5030	7844	1735.6

SUBJECT

Upper Promised Land Dam

sheet

BY

DRP

DATE

12/19/78

JOB NO

1841-010

Rte 390 Bridge

located downstream of dam


could act as a control structure

top of road approx 1733, bottom of culvert approx 1714.

semicircular opening $r = 12'$

crown elev = 1726

Headwater Below Crown (Open Channel flow)



θ	$D_c(\text{ft})$	$A_c(\text{ft}^2)$
$22\frac{1}{2}^\circ$	4.6	$57 + 51 = 108$
45°	8.5	$113 + 72 = 185$
$67\frac{1}{2}^\circ$	11.1	$170 + 51 = 221$

assume critical depth occurs in channel
 $d_c = \frac{2}{3}H$

$$Q_c = A_c \sqrt{g D_c}$$

$$A_c = A_1 + A_2 \therefore A_1 = \frac{\pi r^2}{2} = 57 \text{ ft}^2$$

$$A_2 = \frac{B}{2} (\sqrt{r^2 - D_c^2}) D_c = 51 \text{ ft}^2$$

$$Q_c(\text{cfs}) \quad Elav*$$

	$Elav^*$	centroid = $0.576 R + c$
1314	1720.9	= 6.9
3061	1726.6	
4178	1730.6	

$$+ 1714 + H = Elav$$

Headwater Above Crown, $H/D < 0.75$

assume well rounded inlet $C_C = 1$, $K_i = 0$ (Morris & Wiggett)

$$Q = A \sqrt{2g(H + \frac{V_a^2}{2g})}$$

$$A = 126.1 \text{ ft}^2$$

$$\text{Assume } \frac{V_a^2}{2g} \approx 0$$

H_p	H/D	$Q(\text{cfs})$	$Elav$
6.9	0.575	4765	1726
7.9	0.67	5102	1727
8.9	0.75	5415	1728

SUBJECT

Upper Promised Lord Dam

SHEET

BY

DRP

DATE

12/19/78

JOB NO

Rev. 4/13/79

Headwater Above crown, $H/D > 1^+$

- * For $0.75 \leq H/D \leq 1$ oscillating heads occur, producing slug flow the curve will be interpolated in this region.

$$Q = A \sqrt{\frac{2g(H + \frac{V_o^2}{2g} + S_b L)}{1 + f(\frac{L}{D})}}$$

$$R^{4/3} = \left(\frac{1/2 \pi R^2}{\pi r + 2r} \right)^{4/3} = 5.65$$

$$f(\frac{L}{D}) \approx \frac{29.1 n^2 L}{R^{4/3}} = \frac{29.1 (0.025)^2 (36)}{5.65} = 0.12$$

$$\frac{V_o^2}{2g} \approx 0 \quad S_b L \approx 0$$

$$Q = A \sqrt{\frac{2gH}{1.12}}$$

H_p	H/D	$Q (\text{cfs})$	Elav
11.9	0.99	59.6	1731
12.9	>1	6160	1732
13.9	>1	6395	1733

When $H_p \geq 13.9$ a combination of weir & pressure flow occurs, see following page for computations

weir length is assumed to be 50' at 1733

" " is approx. 200' at 1740

" " " " 800' at 1760



O'BRIEN & GERE

SUBJECT

Upper Promised Land Dam

SHEET

7

BY

DRP

DATE

12/20/75

JOB NO.

1841-010

Rev 4/13/79

$$H_p > 13.9$$

		Pressurflow	$H_w = H_p - 13.9$	L	Qweir	$Q_p + Q_w$	Elav
15.4	6731		1.5	82	467	7198	1734.5
16.9	7051		3.0	114	1836	8887	1736.0

* assumes reservoir level over orifice

Combined Discharge Rating Curve for Route 390 Bridge

Elav.	Q(cfs)
1714.0	0
1720.9	1314
1726.0	4765
1727.0	5102
1728.0	5415
1731.0	5916
1732.0	6160
1733.0	6395
1734.5	7198
1736.0	8887

SUBJECT

Upper Promised Land Dam.

SHEET

8

BY

DRP


DATE

1/2/78

JOB NO

1341-010

Rev 3/15/79





O'BRIEN & GERE

SUBJECT

Upper Promised Land Dam

SHEET

9

BY


DRP

DATE

5/15/79

JOB NO.

1841-010




SUBJECT

Lower Promised Land Dam

SHEET
9aBY
DRPDATE
6/5/79JOB NO.
1841-010
Cross-Section at Downstream Residence

Streambed elevation estimated at 1713.7, 100 ft downstream
 at Route 320 Bridge, streambed slope 0.3%
 250 ft downstream of dam

Channel $n = 0.040$ Overbank $n = 0.170$

PROJECT	NAME	SHEET	BY	DATE	JOB NO
Lower Promised Land Dam		10	DRP	12/14/73	1841-01C

$$D.A. = \text{Area I} + \text{Area II} + \text{Area III}$$

$$= 4.04 \text{ m}^2 + 2.84 \text{ m}^2 + [1.015 \text{ cm}^2/\text{unit} \times 22.52 \text{ units} \times 4 \times 10^{10} \frac{\text{g}}{\text{cm}^2} \times 3.567 \times 10^{-5} \text{ m}^3/\text{g}^2]$$

$$= 4.04 + 2.84 + 3.28$$

$$= 10.2 \text{ m}^2 \quad \text{below Upper Promised Land Dam } 3.3 \text{ m}^2 \\ 10.56 \text{ m}^2 \text{ (by report)} \quad " \quad " \quad " \quad " \quad " \quad 3.99 \text{ m}^2$$

Hydrograph Parameters (Snyder method)

$$\tau_p = C_f (L L_c)^{0.3}$$

$$L = 3.0 \text{ miles}$$

$$L_c = 1.2 \text{ miles}$$

$C_f = 1.23$ supplied by COE
 $C_p = 0.45$ Zone 1

$$\tau_p = 1.23 (3)(1.2)^{0.3} = 1.8 \text{ hr.}$$

$$\tau_r = \frac{\tau_p}{5.5} = \frac{1.8}{5.5} = 0.3 \text{ hr.}$$

Probable Maximum Storm (PMS) (Hydromet 33)

Zone 1 (Fig. 1)

Probable Max. Precip. (PMP) = 22.2 in. ($200 \text{ m}^2, 24 \text{ hr}$)

Depth - Area - Duration Relationships

Maximum 6 hr = 111% PMP

Maximum 12 hr = 123% PMP

Maximum 24 hr = 133% PMP

Loss Rate

initial loss = 1"

uniform loss = 0.05 in/hr

SUBJECT

Lower Promised Land Dam

SHEET

BY

D12P

DATE

12/15/7

JOB NO

1841-010

Base flows

$$1.5 \text{ cfs/mi}^2 \times 3.99 \text{ mi}^2 = 6.0 \text{ cfs}$$

Elevation - Area - Capacity Data

Elev.	Area (mi ²)	Area (acres)
1715	0.19	185.6 **
1720	0.63	403.2
1740	1.11	710.4
1707		250*
1700	-	51 } see next page
1693	0	

* from Inventory

** do not use conflicts with
Inventory



O'BRIEN & GERE

SUBJECT	SHELF	BY	DATE	JOB NO
LPLD	12	DRP	1/18/79	

Extend Elevation-Area-Capacity Data below spillway crest using conic method

$$\text{Elev} = 1707.0 \quad A = 250 \text{ acres} \quad V = 353,500,000 \text{ gal} = 47,192,513 \text{ cu ft}$$

+ from rough engineer's calc on file
in insurance

Top of Embankment = 1717
Base = 1693

Single Conic

$$h = 1707 - 1693 = 14 \text{ ft}$$

$$V = \pi r^2 \frac{h}{3} = \frac{Ah}{3} = 250 \text{ acres} \cdot \frac{(14)}{3} = 1167 \text{ acre-ft}$$

$$= 50,850,000 \text{ cu ft}$$

close break into
2 cones

Conics assume areas at $\frac{h}{2}$ $A = \alpha \text{ area at } h \quad p = \%$

$$V = \frac{h/2}{3} (A + pA + \sqrt{pA(A)}) + \frac{h}{3} (pA)$$

$$= \frac{h/2}{3} (A + 2pA + \sqrt{pA^2})$$

$$47,192,513 = \frac{7}{3} (250)(43,560)(1 + 2p + \sqrt{p})$$

$$1.86 = 1 + 2p + \sqrt{p}$$

$$2p + \sqrt{p} = 0.86$$

$$p = 0.2$$

$$p = 0.21$$

$$2(0.2) + (0.44) = 0.84$$

$$2(0.21) + 0.46 = 0.88$$

$$p = 0.205$$

$$A_{at \text{ base}} + 0.205(250) = 51.3 \text{ acres}$$

Check

$$V = \frac{7}{3} (250 + 102.6 + \sqrt{250(51.3)}) = 1087 \text{ ac-ft}$$

$$= 47,348,740 \text{ cu ft} \checkmark$$

good

SUBJECT

Lower Promised Land Dam

SHEET

BY

DRP

DATE

12/19/78

JOB NO

1841-010

5/15/79

Spillway Discharge Rating

$$Q = C_1 H^{3/2}$$

broad crested weir $B = 2.54$
 (flat upstream, slope 1/6, $C = 3.2$
 avg value between broad
 crested and triangular)

Reduce L for pier & abutment effects.
 3 weirs, 2 at same elevation

$$L = L' - 2(NK_p + K_a)H_a$$

center weir elev = 1707.0

1 pointed piers, no abutment, $L' = 48.5'$

$$L = 48.5 - 2(0) = 48.5"$$

H (ft)	C	<u>$Q_1 (cfs)$</u>	Elev.	Upper chord elev ≈ 1717.0
0.3	3.2	26	1707.3	Lower chord elev ≈ 1714.0
0.8		110	1707.8	
1.5		285	1708.5	
3.0		806	1710.0	
4.5		1482	1711.5	
6.0		2281	1713.0	
7.0	↓	2874	1714.0	



O'BRIEN & GERE

SUBJECT

Lower Promised Land Dam.

SHEET

BY

DRP

DATE

12/19/78

JOB NO

1841-010

Rev 5/15/78

1:1 weirs, elev 1707.5

1 pointed pier, abutment 4' off approach, L = 45.75'

$$L = 45.75' - 2(O+D)H_a = 45.75'$$

<u>H (ft)</u>	<u>C</u>	<u>Q_2 (cfs)*</u>	<u>Elev</u>
0	3.2	0	1707.5
0.3		24	1707.8
1.0		146	1708.5
2.5		579	1710.5
4.0		1171	1711.5
5.5		1888	1713.0
6.5		2426	1714.0

* values for
single weir

combined spillway Discharge Rating - Weir flows

<u>Elev.</u>	<u>Q_1</u>	<u>Q_2</u>	<u>$2Q_2$</u>	<u>$2Q_2 + Q_1$ (cfs)</u>
1707.0	0	0	0	0
1707.3	26	0	0	26
1707.8	110	24	48	158
1708.5	285	146	292	577
1710.0	806	579	1158	1964
1711.5	1482	1171	2342	3824
1713.0	2281	1888	3776	6057
1714.0	2874	2426	4852	7726

SUBJECT

Lower Promised Land Dam

SHEET

15

BY

DRP

DATE

1/2/79

JOB NO

1841-010

Water surface level between 1714 and 1717

Free flow occurs with WSEL between 1714 & 1717

$$Q = CA \sqrt{2gH}$$

(Design at small dams)

$$C = 0.62$$

A = Area

H = Head on orifice

$$\text{Area (center opening)} = 45.5(7) = 319.5 \text{ ft}^2$$

$$\text{Area (end opening)} = 45.75(6.7) = 307.4 \text{ ft}^2$$

$$Q_1 = 0.62(319.5) \sqrt{2(32.2)} + 1 \\ = 1,892 \sqrt{H}$$

$$Q_2 = 0.62(307.4) \sqrt{2(32.2)} H \\ = 1479.7 \sqrt{H}$$

WSEL	center opening		End opening		Total Q
	H ₁	Q ₁	H ₂	Q ₂	
1714	3.5	3160	3.25	2668	5835
1715	4.5	3583	4.25	3050	6100
1716	5.5	3962	5.25	3390	6780
1717	6.5	4307	6.25	3699	7398

* assumes maximum level over orifice

Water surface level above 1717

Combination of primary and free flow

Orifice

$$Q = CLH^{3/2} \quad \text{bi-radical law} \quad B \approx 15^4$$

$$C = 3.1$$

L values

See next page

SUBJECT

Lower Promised Land Dam

SHEET

16 BY DRP

DATE

1/2/79

JOB NO


1841-010

5/15/79

WSEL	Pressure flow				Weir flow				Q _{total}	
	H	Q ₁	H ₂	Q ₂	H _w	L _w	C	Q _w	Q ₁ +Q ₂ +Q _w	
1718	7.5	4624	7.5	4052	1	280	3.1	863	13,598	
1719	8.5	4922	8.5	4811	2	325	3.1	1850	16403	

* assumed reservoir level over溢出

Weir shape





OBRIEN & GERE

SUBJECT

Lower Promised Land Dam

SHEET

BY

17 DRP

DATE

1/13/79

JOB NO.

1841-010

5/13/79

Combined Discharge RatingFlow:Q (cfs)

1707.0	0
1707.3	26
1707.8	158
1708.5	577
1710.0	1964
1711.5	3824
1713.0	6057
1714.0	7726
1715.0	9,683
1716.0	10,742
1717.0	11,705
1718.0	13,598
1719.0	16,402



O'BRIEN & GERE

SUBJECT

Lower Promised Land Damz

SHEET

BY

DRP

DATE


1/3/79

JOB NO.

1541-010

2015/5/5/T

Discharge Rating Curve
for Lower Promised Land
Dam



FLOOD HYDROGRAPH PACKAGE (MEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 25 SEP 78

Sh. 19

NATIONAL DAM INSPECTION PROGRAM

LOWER LAKE DAM PROMISED LAND, PA.
PWF HYDROGRAPH

		A1	A2	A3	0	10	0	0	0	-4	0
1											
2		A1									
3		A2									
4		A3									
5		R	150	0							
6		Y1	5	0							
7		Y2	1	9	1						
8		Y3	0.2	0.3	0.4						
9		K1	0	A1							
10											
11											
12											
13											
14											
15											
16		K1	0	22.2	111	123	133	0			
17											
18		Y1	1	1726.8	1727.6	1729.1	1730.6	1731.1	-1726.3	-1	
19		Y6	1726.1	0	185	512	923	1074	1730.6	1734.1	1735.6
20		Y5	0	59	185	512	923	1074	2254	4171	7844
21		SA	0	287	422	460.8	812.8	1216			
22		SE1715.1	1720.4	1725.6	1727	1740	1760				
23		SS1726.1									
24		SD1731.1									
25		K1	1	A3	CHANNEL ROUTING	1	1	1			
26											
27		K1	Y								
28		Y2	1								
29		Y6	0.12	0.04	0.12	1713.7	1740	1750	0.003		
30		Y7	0	1740	100	1720	200	1742	201	1713.7	249
31		Y7	250	1714.2	300	1720	450	1740			1713.7
32		K1	0	B1							
33											
34											
35		K1	1								
36		P	0	22.2	111	123	133	0			
37		T	1.8	0.45	2						
38		X	-1.5	-0.05	2						
39		K2	B2								
40		K1	1	COMBINE INFLOW AND RUNOFF HYDROGRAPHS FOR LOWER PROMISED LAND LAKE	1						
41		K1	B3	ROUTING THROUGH LOWER PROMISED LAND LAKE	1						
42											
43											
44		Y1	1								
45		Y6	1707.0	1707.3	1707.8	1708.5	1710.0	1711.5	-1707.3	-1	
46		Y6	1717.0	1716.0	1719.0	1719.0	1720.0	1723.0	1714.0	1715.0	1716.0
47		Y5	0	26	158	577	1964	3824	6057	7726	9663
48		Y5	11705	13598	16003	250	403.2	710.4			10742
49		SA	0	51							
50		SE	1693	1760	1707	1720	1740				

5h.20

551707.0
40 1717
99

51
52
53

FLOOD HYDROGRAPH PACKAGE (IMEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 25 SEP 78

RUN DATE 06/06/79.
 TIME 09.10.25.

Sh. 21

NATIONAL DAM INSPECTION PROGRAM
 LOWER LAKE DAM-PROMISED LAND, P.P.

PMF HYDROGRAPH	
NO	NH2
150	0
	NWIN
	30
	TDAY
	0
	JHR
	0
	JOPR
	5
	NWT
	0
	LROF
	0
	TRACE
	0

MULTI-PLAN ANALYSES TO BE PERFORMED

NPLAN= 1 NRTIO= 9 LRATIO= 1	
RTIOS=	.20
	.30
	.40
	.50
	.60
	.70

NRTIO= .80	
------------	--

NRTIO= .90	
------------	--

NRTIO= 1.00	
-------------	--

 SUB-AREA RUNOFF COMPUTATION

RUNOFF TO UPPER PROMISED LAND LAKE

ISTA0		TCOMP		TECON		ITAPP		JPLT		JPRT		INAME		ISNOW		ISTAGE		IAUTO	
A1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	

IMYDG		IUMG		TAREA		SNAP		HYDROGRAPH DATA		RATIO		ISNOW		ISAME		LOCAL	
1	1	6.57	0.00	10.56	0.00	0.000	0.000	0.000	0.000	0.000	0	0	0	0	0	0	

SPFE		PHS		R6		R12		R24		R48		R72		R96	
0.00	22.20	111.00	123.00	133.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	

TASPC COMPUTED BY THE PROGRAM IS .602

LRF OPT		STARTR		DLTKR		RTIO1		ERAIN		STAKS		RTIOK		STRTL		CNSTL		ALSMX		RTTHDP	
0	0.00	0.00	0.00	1.00	0.00	0.00	0.00	0.00	0.00	1.00	0.00	1.00	0.00	0.00	0.00	0.00	0.00	0.00			

TP= 2.30		CP= .45		NTA= 0	
----------	--	---------	--	--------	--

STRTOQ= -1.50		RECEDSION DATA		RTIOR= 2.00	
---------------	--	----------------	--	-------------	--

ORCSW= -.05	
-------------	--

UNIT HYDROGRAPH 4.3 END-OF-PERIOD ORDINATES. LAG=		2.30 HOURS. CP=		.45 VOL= 1.00	
72..	523.	736.	813.	664.	581.
389..	300.	296.	229.	199.	153.
102..	89.	78.	68.	52.	40.
27..	83.	21.	18.	16.	12.
7..	6.	5.	5.	4.	3.

0	MODA	MR.MN	PERIOD	END-OF-PERIOD FLOW	COMP 0	LOSS	EXCS	RAIN	PERIOD	RAIN	EXCS	LOSS	COMP 0
500	601	554	11	21.82	1.46	189142.	47.1	5355.90					

55. 12

HYDROGRAPHIC ROUTING

THE JOURNAL OF BUSINESS ETHICS

PEAK OUTLET 15 121.01 TIME 26.00 HOURS

PEAK OUTFLOW IS 684. AT TIME 26:00 HOURS

PEAK OUTLOAD IS 956. AT TIME 25.50 MUNARS

PEAK OUTFLOW IS 1432: AT TIME 25:00 HOURS

PEAK OUTFLOW IS 1986: AT TIME 24.50 HOURS

PEAK OUTLET 15 26340 AI TIME 24:00 MONG

PEAK QUOTE: ON 15 NOVEMBER 1953: AT TIME 21.50 MOWAS

PEAK OUTFLOW IS 4042. AT TIME 23.00 HOURS

HYDROGRAPH ROUTING

INSTAO	ICOMP	IECON	ITAPF	JPLT	JPPT	I NAME	INSTAE	IAUTO
A3	1	0	0	0	0	1	0	0
		ROUTING DATA						
GLOSS	CLOSS	Avg	IRES	ISAM	IOP	IPMP	LSTR	
0.0	0.000	0.00	1	1	0	0	0	
NSTPS	NSTDL	LAG	AMSKK	X	TSK	STORA	ISPRAT	
1	0	0	0.000	0.000	0.000	0.000	0.	

NORMAL DEPTH CHANNEL ROUTING

END SECTION COORDINATES--STA.ELEV,STA.ELEV--ETC

	STORAGE	15.00	17.41	19.95	1.17	2.18	3.47	5.03	6.75	8.60	10.60	12.73
	OUTFLC#	0.00	176.72	600.84	1261.56	2169.00	3358.19	4833.72	6563.99	8548.27	10787.74	14012.03
	STAGE	13284.87	16042.86	19065.51	22357.00	25921.76	29764.46	33889.89	38302.97	43008.66	48012.03	53017.03
	FLC#	0.00	176.72	600.84	1261.56	2169.00	3358.19	4833.72	6563.99	8548.27	10787.74	14012.03
		13284.87	16042.86	19065.51	22357.00	25921.76	29764.46	33889.89	38302.97	43008.66	48012.03	53017.03

MAXIMUM STAGE IS 1720.6
 MAXIMUM STAGE IS 1721.3
 MAXIMUM STAGE IS 1722.5

5V7. - +

MAXIMUM STAGE IS 1720.6
 MAXIMUM STAGE IS 1721.3
 MAXIMUM STAGE IS 1722.5

SUR-AREA RUNOFF COMPUTATION

RUNOFF TO LOWER PROMISED LAND LAKE

1STAO R1	1C0MP 0	1ECON 0	1TAPE 0	HYDROGRAPH DATA TRSDA TRSPC	JPLT 0	JPRT 0	INAME 0	ISTAGE 0	IAUTO 0
IHYDG 1	IUNG 1	TAREA 3.99	SNAP 0.00	10.56	0.00	0.000	ISNOW 0	ISAMF 1	LOCAL 0
				PRECIP DATA					
				R6 R12 R24		R48	R72	R96	
SPFE 0.00	PMS 22.20	PMS 111.00	PMS 123.00	133.00	0.00	0.00	0.00	0.00	
TRSPC COMPUTED BY THE PROGRAM IS .802									

LRCPT	STRKR	DLTKR	RTOL	ERAIN	LOSS DATA STKRS RTOK	STRTL	CNSTL	ALSMX	ATIMP
0	0.00	0.00	1.00	0.00	0.00 1.00	1.00	0.05	0.00	0.00

UNIT HYDROGRAPH DATA

TP=	1.80	CP= .45	NTAS= 0

RECSSION DATA

START=	-1.50	END=	-.05	RTIOR= 2.00

UNIT HYDROGRAPH 34 END-OF-PERIOD ORDINATES, LAG=	1.82 HOURS. CP= .45	VOL= 1.00
81. 296. 527. 619. 566. 47A. 104. 340.	340. 76. 62.	287. 52. 44.
204. 172. 145. 123. 104. 87. 76. 13.	13. 11.	10.
37. 32. 27. 22. 19. 4.		
7. 6. 5.		

MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	END-OF-PERIOD FLOW MO.DA	HR.MN	PFRIOD	RAIN	EXCS	LOSS	COMP Q
0												

SUM	23.68	?1.R42	1.R46	11590.
(601.) (554.) (47.1)	3762.12)			

COMBINE HYDRORAPHS

COMBINE INFLOW AND RUNOFF HYDROGRAPHS FOR LOWER PROMISED LAND LAKE

1STAO B2	1C0MP 2	1ECON 0	1TAPE 0	JPRT 0	INAME 0	ISTAGE 1	IAUTO 0
-------------	------------	------------	------------	-----------	------------	-------------	------------

5h 25

***** HYDROGRAPH ROUTING

ROUTING THROUGH LOWER PROMISED LAND LAKE

	ISTAO 83	ICOMP 1	IECON 0	ITAPE ROUTING DATA	JPLT 0	JPRF 0	I NAME INPT	I STAGE IPMP	I AUTO LSTR
GLOSS	CLOSS 0.0	Avg 0.000	IRFS ISAWF	LAG 1	AMSKR X	TSK 0	STOPA 0.000	-1707. -1707.	-1
	NSTPS 1	NSTDL 0		0.000	0.000	0.000			
STAGE	1707.00 1717.00	1707.30 1718.00	1707.80 1719.00	1708.50	1710.00	1711.50	1713.00	1714.00	1715.00
FLOW	8.00 11705.00	26.00 13598.00	158.00 16403.00	577.00	1964.00	3826.00	6057.00	7726.00	9663.00
SURFACE AREA=	0.	51.	250.	403.	710.				
CAPACITY=	0.	119.	1085.	5291.	16233.				
ELEVATION=	1693.	1700.	1707.	1720.	1740.				
	CREL 1707.0	SPWID 0.0	COOW 0.0	EXPN 0.0	ELEV 0.0	COOL 0.0	CAREA 0.0	EXPL 0.0	DAM DATA
PEAK OUTFLOW IS	1097.	AT TIME	21.00	HOURS	TOPFL 1717.0	COQD 0.0	EXPO 0.0	DAMWID 0.	
PEAK OUTFLOW IS	1740.	AT TIME	21.00	HOURS					
PEAK OUTFLOW IS	2458.	AT TIME	21.00	HOURS					
PEAK OUTFLOW IS	3189.	AT TIME	20.50	HOURS					
PEAK OUTFLOW IS	3945.	AT TIME	21.00	HOURS					
PEAK OUTFLOW IS	4846.	AT TIME	21.00	HOURS					
PEAK OUTFLOW IS	5766.	AT TIME	21.50	HOURS					
PEAK OUTFLOW IS	6637.	AT TIME	21.50	HOURS					
PEAK OUTFLOW IS	8254.	AT TIME	22.00	HOURS					

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLANT-RATIO ECONOMIC COMPUTATIONS
FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
AREA IN SQUARE MILES (SQUARE KILOMETERS)

517. 66

OPERATION	STATION	AREA	PLAN	RATIO 1 .20	RATIO 2 .30	RATIO 3 .40	RATIO 4 .50	RATIO 5 .60	RATIOS APPLIED TO FLOWS		RATIO 6 .70	RATIO 7 .80	RATIO 8 .90	RATIO 9 1.00
									RATIO 1 .20	RATIO 2 .30				
HYDROGRAPH AT	A1	6.57	1	2386.	3579.	4772.	5966.	7153.	8352.	9545.	10738.	11931.		
	(17.02)	(67.57)	(101.36)	(135.14)	(168.93)	(202.71)	(235.50)	(270.28)	(304.07)	(337.85)				
ROUTED TO	A2	6.57	1	421.	684.	956.	1432.	1966.	2636.	3353.	4042.	4647.		
	(17.02)	(11.91)	(19.36)	(27.06)	(40.56)	(56.22)	(74.65)	(94.95)	(114.47)	(156.94)				
ROUTED TO	A3	6.57	1	421.	684.	956.	1431.	1965.	2637.	3355.	4040.	4648.		
	(17.02)	(11.91)	(19.38)	(27.07)	(40.53)	(56.19)	(74.66)	(94.99)	(114.41)	(155.67)				
HYDROGRAPH AT	B1	3.99	1	1662.	2493.	3324.	4155.	4986.	5817.	6648.	7479.	8309.		
	(10.33)	(47.06)	(70.59)	(94.12)	(117.65)	(141.19)	(164.71)	(188.24)	(211.77)	(235.30)				
? COMBINED	B2	10.56	1	1788.	2709.	3640.	4568.	5509.	6458.	7405.	8351.	9487.		
	(27.35)	(50.62)	(76.70)	(103.08)	(129.35)	(155.99)	(182.87)	(209.61)	(236.47)	(268.63)				
ROUTED TO	B3	10.56	1	1097.	1749.	2458.	3189.	3945.	4846.	5786.	6837.	8256.		
	(27.35)	(31.05)	(49.28)	(69.61)	(90.30)	(111.71)	(137.22)	(163.83)	(193.62)	(233.74)				

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

ELEVATION
STORAGE
OUTFLOW
INITIAL VALUE
1726.30
2641.
17.SPILLWAY CREST
1726.10
2554.
n.TOP OF DAM
1731.10
5048.
1074.

RATIO OF RESERVOIR W.S.ELEV P.M.F	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILSAFE HOURS
.20	1728.68	0.00	3765.	421.	0.00	26.00
.30	1729.73	0.00	4303.	686.	0.00	26.00
.40	1730.71	0.00	4431.	956.	0.00	25.50
.50	1731.56	.46	5307.	1432.	9.50	25.00
.60	1732.26	1.16	5716.	1986.	14.50	24.50
.70	1733.90	1.80	6100.	2636.	17.00	24.00
.80	1733.46	2.36	6446.	3353.	19.00	23.50
.90	1734.00	2.90	6786.	4042.	20.50	23.00
1.00	1734.33	3.23	6996.	5472.	21.50	22.00

PLAN 1 STATION A3

RATIO	MAXIMUM FLOW.CFS	MAXIMUM STAGE.FT	TIME HOURS
.20	421.	1715.9	26.00
.30	686.	1716.6	26.00
.40	956.	1717.2	26.00
.50	1431.	1718.1	25.00
.60	1955.	1719.0	24.50
.70	2637.	1719.8	24.00
.80	3355.	1720.6	23.50
.90	4040.	1721.3	23.00
1.00	5476.	1722.5	22.50

Slo. 2'

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

ELEVATION	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
STORAGE	1707.30	1707.00	1717.00
OUTFLOW	1160.	1085.	4140.
	26.	0.	11705.


37.25

RATIO OF RESERVOIR W.S.ELEV PMF	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-T	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.20	1709.06	0.00	1623.	1097.	0.00	21.00
.30	1709.76	0.00	1615.	1740.	0.00	21.00
.40	1710.40	0.00	1996.	2650.	0.00	21.00
.50	1710.99	0.00	2167.	3180.	0.00	20.50
.60	1711.58	0.00	2333.	3945.	0.00	21.00
.70	1712.19	0.00	2526.	4886.	0.00	21.00
.80	1712.82	0.00	2722.	5786.	0.00	21.50
.90	1713.47	0.00	2929.	6837.	0.00	21.50
1.00	1714.27	0.00	3130.	8254.	0.00	22.00


APPENDIX

D

Photographs




**VIEW OF THE SPILLWAY, STILLING BASIN
AND BRIDGE STRUCTURE**



**VIEW OF THE SPILLWAY AND BRIDGE
FROM THE UPSTREAM SIDE**

D-1



THE UPSTREAM SIDE OF THE DAM SHOWING THE SPILLWAY STRUCTURE, BRIDGE, AND THE EMBANKMENT




VIEW OF LOWER LAKE FROM THE LOWER LAKE DAM BRIDGE


D-2



VIEW OF THE UPSTREAM SLOPE OF THE RIGHT ABUTMENT SHOWING EROSION ALONG THE WINGWALL



APRON AND ENDSILL OF THE STILLING BASIN



**OUTLET CONDUIT
EMBEDDED IN THE ENDSILL**



**WALLENPAUPACK CREEK
DOWNSTREAM OF THE DAM**

D-4



APRON AND ENDSILL OF
THE STILLING BASIN

APPENDIX

E

Drawings



O'BRIEN & GERE
ENGINEERS, INC.

SUBJECT

Lower Lake Dam

SHEET


BY

DATE


JOB NO

TABLE OF CONTENTS APPENDIX E


Regional Vicinity Map	Plate 1
Spillway Plan & Details	Plate 2
Cross-Sections	Plates 3 & 4
Plan & Sketch of Anchor Rods	Plate 5
Problem Areas	Plate 6



**WATERSTOP
DETAIL**
NO SCALE




SECTION A-A
SCALE 1/8"=1'-0"



**SPILLWAY SECTION
AT EXPANSION JOINT**
SCALE 1/8"=1'-0"


CRETE SHEET
DETAIL SHEET NO. 2
AND SHEET NO. 3

EXPANSION JOINT-
DETAIL SHEET NO. 3



**SECTION
1-105.5**
SEE SHEET 4

SPILLWAY PLAN
SCALE 1/8"=1'-0"



BENDS NOT LESS THAN 30° IN

**SLAB EXPANSION
JOINT DETAIL**
SCALE 1/8"=1'-0"

**WATERSTOP
DETAIL**
NO SCALE


**SLAB C
JO**

20 OZ COPPER WATERSTOP
SEE DETAIL

2" WIDE FORM EXPANSION
JOINT PLATE


SECTION B-B
SCALE 1/2'-0"

BENDS NOT LESS
THAN 30° IN





WATERSTOP
DETAIL
NO SCALE

SECTION A-A
SCALE 1/2'-0"




SECTION 1-1
SCALE 1/2'-0"



SECTION 2-2
SCALE 1/2'-0"

SECTION THROUGH
WING WALL
SCALE 1/2'-0"



SECTION 3-3
SCALE 1/2'-0"

Plate 2

REVISED

SUBMITTED:	ARCHITECT			
SUBMITTED:	ENGINEER			
ADDRESS:				
DEPARTMENT OF FORESTS & WATER-BUREAU OF RECREATION				
ADDRESS:				
STRUCTURING ENGINEER				
STRUCTURING ENGINEER				
CHECKED BY THE GENERAL STATE AUTHORITY				
MECH	STRUCT	HEAT	PLUMB	ELECT.






PROJECT NO.-G.S.A.-121-1

PROMISED LAND PARK

PINE COUNTY

SPILLWAY PLAN & DETAILS

DATE: 10/10/1968
SCALE: 1/2'-0"



KEY







Plate 3

PROJECT NO. - G.S.A. - 121 - 1

PROMISED LAND PARK

PINE COUNTY, PENNSYLVANIA

CROSS SECTIONS






STATION 0+00 TO 1+60

L. ROBERT KIRKMAN,
CONSULTING ENGINEER

REvised	SUBMITTED SUBMITTED APPROVED: APPROVED:	ARCHITECT ENGINEER DEPARTMENT OF FORESTS & WATERS-BUREAU OF RECREATION SUPERVISING ENGINEER ARCHITECTURAL - ENGINEERING UNIT G.S.A.	THE GENERAL STATE AUTHORITY GEORGE H. LEADER A.J. CARLUO, EXECUTIVE DIRECTOR HARRISBURG
		CHECKED BY THE GENERAL STATE AUTHORITY ARCH. STRUCT. MEAT. PLUM. ELECT.	
			DATE: 10/67 SCALE: 1/6400

KEY

- BACKFILL
- CRUSHED STONE FILL
- CONCRETE
- RIP RAP
- EXISTING GRADE - SOIL
- FINISHED GRADE OR EXCAVATION LINE
- SELECT BACK FILL



KEY









Plate 4

REVISED		SUBMITTED: ARCHITECT /		PROJECT NO.-G.S.A.- 121-1			
		SUBMITTED: ENGINEER		PROMISED LAND PARK			
		APPROVED:		PIKE COUNTY PENNSYLVANIA			
		DEPARTMENT OF RECREATION & WATERS - BUREAU OF RECREATION		CROSS SECTIONS			
		APPROVED:		STATION 1+80 TO 3+40			
		SUPERVISING ENGINEER ARCHITECTURAL - ENGINEERING UNIT G.S.A.		L. ROBERT KIMBALL CONTRACTING ENGINEER			
		CHECKED BY THE GENERAL STATE AUTHORITY		GENERAL STATE AUTHORITY			
		ARCH	STRUCT.	HEAT	PLUMB	ELECT	DATE
							GEORGE M. LEADER
							A. J. CARUSO - EXECUTIVE DIRECTOR
							HARRISBURG PENNSYLVANIA
							NO. 9
							2


BACK FILL
CRUSHED STONE FILL
CONCRETE
RIP RAP
EXISTING GRADE SOIL
EXISTING GRADE ROCK
FINISHED GRADE OR
EXCAVATION LINE
SELECT BACK FILL

46'-6"

42'-6"

2'-0" 5'-6" 5'-6" 5'-6" 5'-6" 5'-6" 5'-6" 2'-0"

1'-9" 5'-6" 5'-



— SECT. 10
SCALE

3" DIA.

50'-0"

46'-6"

42'-0"

42'-6"

5'-6" 5'-6" 5'-6" 5'-6" 5'-6" 4' 6"

2'-0" 5'-6" 5'-6" 5'-6" 5'-6" 5'-6" 5'-6"

PLAN

SCALE $\frac{1}{8}'' = 1'-0''$

NOTE:

*9 BARS TO BE GROUTED WITH
NON-SHRINKING GROUT.

ROCK LINE

Plate

PLAN

SHOWING

ANCHOR

POSITION

PROJECT


L. RQBI

CONSULT

N—
 $\frac{1}{8}'' = 1'-0''$

OLE

2



late 5

SKETCH
LOCATION OF
WDR RODS.

FOLAND DAM
FT NO G.S.A. 121-1

BERT KIMBALL
LTING ENGINEER

LOWER LAKE




Plate 6
Lower Lake Dam
NOT TO SCALE

APPENDIX

F

Site Geology

SITE GEOLOGY

LOWER LAKE DAM

Lower Lake Dam is situated in Pike County and within the limits of the Eastern Glaciated section of the Appalachian Plateau physiographic province. Thick deposits of glacially derived debris and till cover the nearly horizontally bedded, red, gray and green shale and sandstone units of the Devonian Catskill group of marine and continental sediments. The dam and lake both rest on glacial till and ground moraine deposits which are dense, compact and relatively impermeable. Prior to construction of the lake the area was covered with high valley swamps and bogs, attesting somewhat to the compactness and impervious nature of the dense, glacial till mantle.

No known faults or major structural defects occur in the bedrock in the vicinity of the dam and lake.




PLATE 1
REGIONAL
GEOLOGY MAP
SCALE 1:24000