

AD-A072 253

BAKER (MICHAEL) JR INC BEAVER PA  
NATIONAL DAM INSPECTION PROGRAM. (PA-474 (PA NO NAME NUMBER 35)--ETC(U)  
JUL 79 C Y CHEN


F/G 13/2

DACW31-79-C-0011


NL

UNCLASSIFIED

1 OF 1  
AD  
A072. 53



END  
DATE  
FILMED  
9-79  
DDC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A



ADA072253

Distribution Unlimited  
Approved for Public Release  
Contract No. DACW31-79-C-0011 ✓

OHIO RIVER BASIN

PA 474  
(PA NO NAME No. 35)  
MERCER COUNTY, COMMONWEALTH OF PENNSYLVANIA  
NDI No. PA 00249  
PennDER No. 43-50  
SCS No. PA 474

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

6 National Dam Inspection Program.  
(PA-474 (PA No Name Number 35), NDI Num-  
ber PA-00249, PennDER Number 43-50,  
SCS Number PA-474), Ohio River Basin, Saw  
Mill Run, Mercer County, Pennsylvania.  
Phase I Inspection Report.

Prepared for: DEPARTMENT OF THE ARMY  
Baltimore District, Corps of Engineers  
Baltimore, Maryland 21203

Prepared by: MICHAEL BAKER, JR., INC.  
Consulting Engineers  
4301 Dutch Ridge Road  
Beaver, Pennsylvania 15009

10 Chuan Yuan / Chen  
11 Ju / 79 12 82 p.  
15 DACW 31-79-C-0011

410795 . 9 08 06 07.1.

JOB

## PREFACE

This report was prepared under guidance contained in the "Recommended Guidelines for Safety Inspection of Dams," for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I Inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Accession For	NTIS GADAI	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	DOC TAB			
	Unannounced			
	Justification			
By				
Distribution				
Availability Codes				
Available for				
Special				
Dist				



**PHASE I REPORT  
NATIONAL DAM INSPECTION PROGRAM**

PA 474 (PA No Name No. 35), Mercer County, Pennsylvania  
NDI No. PA 00249, PennDER No. 43-50, SCS No. PA 474  
Saw Mill Run  
Inspected 9 May 1979

**ASSESSMENT OF  
GENERAL CONDITIONS**

PA 474 (also known as PA No Name No. 35) is a zoned earth floodwater retarding dam designed by the U.S. Department of Agriculture, Soil Conservation Service (SCS). The dam consists of a main embankment, a vegetated earth emergency spillway, an intake riser and outlet conduit (principal spillway) and a saddle dike. The dam is a "High" hazard-"Small" size dam and is owned and operated by the Mercer County Commissioners. The main embankment has a crest length of 1640 feet and a maximum height of 30 feet.

Hydraulic/hydrologic evaluations, performed in accordance with procedures established by the Baltimore District, Corps of Engineers, for Phase I Inspection Reports, revealed that the spillway will pass the Probable Maximum Flood (PMF) without overtopping the dam. The spillway is therefore considered "adequate."


The dam was found to be in good overall condition at the time of inspection on 9 May 1979. However, the owner should perform the following several minor items of remedial work as soon as practicable:

- 1) Periodically inspect the seepage area to the left of the outlet structure to identify a change in quantity of seepage or the exiting of muddy water from this area and, if necessary, study the situation in detail and take appropriate remedial measures.
- 2) Remove the sedimentation and vegetation above the inlet and outlet of the spring drain in the dike and clean the pipe out, if necessary. The downstream channel may need to be reshaped to provide sufficient drainage away from the toe of the dike.
- 3) Remove the stockpiled brush from the emergency spillway channel.
- 4) Fill the animal burrows in the embankment and establish a rodent control program.

- 5) Replace the joint filler between the outlet conduit and the impact basin head wall.
- 6) Periodically inspect and maintain the filter drain outlets.
- 7) Clear the debris from the trash rack of the riser and periodically inspect and maintain the trash rack in the future.


In addition, the following operational measures are recommended to be undertaken by the owner:

- 1) Develop a detailed emergency operation and warning system.
- 2) During periods of unusually heavy rain, provide around-the-clock surveillance of the dam.
- 3) When warning of a storm of major proportions is given by the National Weather Service, the owner should activate the emergency operation and warning system.



Submitted by:


MICHAEL BAKER, JR., INC.

  
C. Y. Chen, Ph.D., P.E.  
Engineering Manager-Geotechnical

Date: 6 July 1979

Approved by:

DEPARTMENT OF THE ARMY  
BALTIMORE DISTRICT, CORPS OF ENGINEERS

  
JAMES W. PECK  
Colonel, Corps of Engineers  
District Engineer

Date: 21 July 1979



PA 474



Overall View of Dam from Left Abutment



Overall View of Dike from Knoll located between Dam and Dike

## TABLE OF CONTENTS

	<u>Page</u>
Section 1 - Project Information	1
Section 2 - Engineering Data	7
Section 3 - Visual Inspection	9
Section 4 - Operational Procedures	11
Section 5 - Hydraulic/Hydrologic	12
Section 6 - Structural Stability	13
Section 7 - Assessment, Recommendations/Remedial Measures	15

## PLATES

Plate 1 - Location Plan
Plate 2 - Watershed Map
Plate 3 - Plan of Storage Area
Plate 4 - Dam Site
Plate 5 - Profile of Dam and Emergency Spillway
Plate 6 - Foundation Drain Details
Plate 7 - Spring Drain Details
Plate 8 - Plan and Profile of Principal Spillway

## APPENDICES

Appendix A - Check List - Visual Inspection and Field Sketch
Appendix B - Check List - Engineering Data
Appendix C - Photographs
Appendix D - Hydrologic and Hydraulic Computations
Appendix E - Regional Geology



PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM  
PA 474 (PA NO NAME No. 35)  
NDI No. PA 00249, PennDER No. 43-50, SCS No. PA 474

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

- a. Authority - The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.
- b. Purpose of Inspection - The purpose of the inspection is to determine if the dam constitutes a hazard to human life or property.

1.2 DESCRIPTION OF PROJECT

- a. Description of Dam and Appurtenances - PA 474 (also referred to as PA No Name No. 35) was designed by the U.S. Department of Agriculture, Soil Conservation Service (SCS) for floodwater detention. The dam consists of a zoned earth embankment, a vegetated earth emergency spillway channel, a riser intake with a 36-inch diameter outlet conduit, and a saddle dike located to the right of the main embankment.

→ The crest length of the main embankment is 1640 feet. The maximum height of the dam at the original streambed is 30 feet. The dam crest is at El. 1264.3 feet and the top width is 14 feet. The inclination of the upstream face is 2.5H:1V (Horizontal to Vertical) with a 10-foot wide berm at El. 1242 feet. The downstream slope is 2.5H:1V. A filter trench was installed in the downstream prism of the embankment from original Station 4+92 to 9+77. A portion of the filter trench is provided with 6-inch diameter filter drainpipe. The two outlets of the filter drainpipes exit into the impact basin approximately 1 foot downstream of the baffle wall. To the right of the main embankment is a small knoll which separates the saddle dike from the main embankment. This knoll consists primarily of sandy silt (ML) soils and is approximately 540-feet long between the two embankments. The crest length of the dike is —————→

CONT' →



CONT

670 feet and the maximum height is 9 feet. The crest width of the homogeneous embankment (dike) is 14 feet. The inclination of both the upstream and downstream slopes of the dike is 2.5H:1V.

The outlet works (principal spillway in SCS terminology) consists of a two-stage reinforced concrete riser connected to a 36-inch diameter reinforced concrete pipe. The riser unit consists of a low flow orifice 2 feet by 1.33 feet with a crest El. 1241.8 (sediment pool). Two 9-foot long overflow weirs (one on each side of the riser) with a crest El. 1249.2 feet form the second stage of the riser. The weirs have a 1.5-foot vertical clearance below the soffit of the concrete slab on the top of the riser. The riser unit has a 24-inch diameter pond drainpipe extending 26 feet upstream to a vertical section of 30-inch pipe. This pond drain served as diversion during construction. The end of the pipe (where it exits into the riser) is presently bolted shut with a 1/4-inch steel plate. The outlet conduit for the riser is 144.3-feet long and rests on a concrete cradle. Five reinforced concrete anti-seep collars are spaced on approximately 20-foot centers along the first 100 feet of the conduit. The conduit exits into a reinforced concrete impact basin.

ABSTRACT

A 450-foot long vegetated earth emergency spillway channel is located at the left abutment of the dam. The control section for the channel is at El. 1257.0 feet and is 100-feet wide at the base. The side slopes are 4H:1V on the left and 2H:1V on the right. A wrap around dike, approximately 160-feet long, was built to protect the toe of the main embankment from scour during flood flows. The toe of the dike is protected with riprap from the control section to the downstream end of the dike.

- b. Location - PA 474 (PA No Name No. 35) is located on Saw Mill Run about 1.0 mile southwest of the Borough of Sandy Lake and 0.5 mile east of the Borough of Stoneboro. Portions of the dam are located in both the Borough of Stoneboro and Sandy Lake Township in Mercer County, Pennsylvania. Located approximately 600 feet downstream from the dam is U.S. Route 62, which runs in a northeast-southwest direction. Access to the dam is via a township road (located to the southwest of the dam) from U.S. Route 62. A dirt path from the township road then provides the nearest access to the dam and reservoir. The coordinates of the dam are Latitude N 41°-20.1' and Longitude W 80°-05.7'.

- c. Size Classification - The maximum height of the dam is 30 feet and the reservoir volume to the top of dam (El. 1264.3 feet) is 814 acre-feet. The dam is therefore in the "Small" size category.
- d. Hazard Classification - This dam is in the "High" hazard category because it is likely that more than a few lives would be lost and economic losses would be excessive in the event of a failure of this dam under flood pool conditions.
- e. Ownership - The dam is owned by the Mercer County Commissioners, Mercer County Courthouse, Mercer, Pennsylvania 16137.
- f. Purpose of Dam - The dam is used for floodwater detention.
- g. Design and Construction History - The dam was designed by the SCS under the authority of the Watershed Protection and Flood Prevention Act, Public Law 566, as amended. The dam was constructed by Kane Brothers Company, 975 Bears Den Road, Youngstown, Ohio from April 1965 to September 1966 (with an appropriate winter shut-down period).
- h. Normal Operational Procedures - The principal and emergency spillways are uncontrolled. The pool is normally at the level of the low inlet of the riser structure, El. 1241.8 feet. No major flood has occurred since construction of the dam in 1965-66 and the pool level has not reached the crest elevation (El. 1257.0 feet) of the emergency spillway. The dam does not have any operating equipment and is only occasionally visited by Mercer County or SCS personnel. Mercer County and SCS personnel inspect the dam each year according to procedures for annual inspection of SCS dams of this type. Copies of annual inspection reports are available in the Mercer County Conservation District office and in the Pennsylvania Department of Environmental Resources' (PennDER) file for this dam. Routine maintenance is performed by Mercer County personnel when it is necessary.



### 1.3 PERTINENT DATA

a.	<u>Drainage Area (square miles) -</u>	1.56
b.	<u>Discharge at Dam Site (c.f.s.) -</u>	
	Maximum Flood -	Unknown
	Total Spillway Capacity	
	(At Pool El. 1264.3 ft.) -	6892
c.	<u>Elevation (feet above Mean Sea Level [M.S.L.]) -</u>	
	Design Top of Dam -	1264.3
	Minimum Top of Dam -	1264.5
	Sediment Pool -	1241.8
	Maximum Pool (Design) -	1261.1
	Maximum Pool (Phase I Analysis*) -	1261.2
	Emergency Spillway Crest -	1257.0
	Streambed at Centerline of Dam -	1234
	Maximum Tailwater -	Unknown
d.	<u>Reservoir (feet) -</u>	
	Length of Maximum Pool -	2900
	Length of Flood Control Pool -	1400
	Length of Sediment Pool -	800
e.	<u>Storage (acre-feet) -</u>	
	Sediment Pool (El. 1241.8 ft.) -	14
	Flood Control Pool (El. 1257.0 ft.) -	366
	Top of Dam (El. 1264.3 ft.) -	814
f.	<u>Reservoir Surface (acres) -</u>	
	Sediment Pool (El. 1241.8 ft.) -	2.5
	Flood Control Pool (El. 1257.0 ft.) -	46
	Top of Dam (El. 1264.3 ft.) -	79
g.	<u>Dam -</u>	
	Type -	Zoned earthfill
	Length (feet) -	1640
	Height (feet) -	30
	Top Width (feet) -	14
	Side Slopes - Upstream -	2.5H:1V
	(with 10-foot wide	
	berm at El. 1242 ft.)	
	Downstream -	2.5H:1V

\* See Appendix D.

- Zoning** - Three zones and two different types of materials were used to zone the main embankment. A typical section of the dam is shown on Plate 3. Also, the type of material used for each zone is given on Plate 3.
- Cutoff** - A 12-foot base width cutoff trench was installed below the main embankment varying from 2 to 6 feet below original ground level. The "as built" depths of the cutoff trench are shown on Plate 5.
- Drains** - A filter trench was provided in the main embankment from original Station 4+92 to 9+77. The fine aggregate (ASTM fine concrete aggregate) was installed an average depth of 3 feet below the stripping line. From Station 5+88 to 8+97 the filter trench was provided with a 6-inch diameter filter drainpipe surrounded by a coarse filter. The two outlets for the drainpipe exit into the impact basin just downstream of the baffle wall. (See Plate 6.)

**h. Saddle Dike -**

<b>Type</b> -	Homogeneous earthfill
<b>Length (feet)</b> -	670
<b>Height (feet)</b> -	9
<b>Top Width (feet)</b> -	14
<b>Side Slopes</b> - Upstream -	2.5H:1V
Downstream -	2.5H:1V

**i. Diversion and Regulating Tunnel -** None

**j. Spillway (Emergency Spillway in SCS Terminology) -**

<b>Type</b> -	Vegetated earth channel located at left abutment of main dam
<b>Length (feet)</b> -	450
<b>Base Width (feet)</b> -	100
<b>Side Slopes</b> - Left -	4H:1V
Right -	2H:1V
<b>Crest Elevation (feet M.S.L.)</b> -	1257.0
<b>Gates</b> -	None
<b>Downstream Channel</b> -	Flows would pass through a well vegetated area (grass) for approximately 200 feet, then through a wooded area, and into the original stream channel.



k. Regulating Outlets (Principal Spillway in SCS Terminology) -

Type - Two-stage inlet riser and 36-inch reinforced concrete outlet pipe

First Stage Orifice -

Crest Elevation (feet M.S.L.) -	1241.8
Width (feet) -	2.0
Height (feet) -	1.33 (1'-4")

Second Stage Overflow Weir -

Crest Elevation (feet M.S.L.) -	1249.2
Length (feet)* -	9.0
Vertical Clearance (feet) -	1.5

Outlet Pipe - A 36-inch I.D. reinforced concrete pipe supported on a concrete cradle. The concrete cradle was installed on the bottom of the outlet conduit excavation (in situ soils). Five reinforced concrete anti-seep collars were provided on approximately 20-foot centers. The pipe was installed in 16-foot long sections for a total length of 144.3 feet (including the wall section at the intake riser).

Riser Floor Invert Elevation

(feet M.S.L.) -	1230.0
-----------------	--------

Outlet Conduit Exit Invert Elevation

(feet M.S.L.) -	1228.56
-----------------	---------

Impact Basin

Length (feet) -	15.75
Base Width (feet) -	11.8 (11'-10")
Invert Elevation (feet M.S.L.) -	1226.56

Tailwater Sill Elevation

(feet M.S.L.) -	1228.56
-----------------	---------

Downstream Channel - A 20-foot rock riprap-lined section, then an approximately 190-foot long earth lined section before exiting into the original channel.

---

\* 9-foot length on each of two sides of the riser.

## SECTION 2 - ENGINEERING DATA

### 2.1 DESIGN

Floodwater Retarding Dam PA 474 (PA No Name No. 35) was designed by the SCS according to its standard practice for structures of this type, circa 1964. Design data reviewed included:

- 1) SCS Drawings No. PA-474-P, "Sandy Creek Watershed Project, Floodwater Retarding Dam PA-474, Crawford and Mercer Counties, Pennsylvania." Design drawings are available in PennDER's files. "As built" drawings are available in the SCS Harrisburg office and the Mercer County Conservation District office.
- 2) "Sandy Creek Watershed Work Plan," report prepared by the Mercer County Commissioners, et. al., March 1962. (A copy is available in the Mercer County Conservation District office in Mercer.)
- 3) Dam Permit Application Report prepared by the Pennsylvania Department of Forests and Waters (predecessor of PennDER) on 11 May 1965.
- 4) Design information including laboratory soil data, slope stability calculation summaries, hydrologic and hydraulic design calculations, and structural design calculations are available in the SCS Harrisburg office files.
- 5) Various post-construction inspection reports by the SCS and the Mercer County Conservation District personnel. (Copies are available in PennDER's files.)

### 2.2 CONSTRUCTION

Readily available information on the construction of this dam was reviewed in connection with this Phase I Investigation. This information consisted of PennDER File No. 43-50 for this dam.

Many design and construction modifications recorded were incorporated into the "as built" drawings. Most of these drawings have been included in this report; however, all additional drawings are available in the files of the SCS Harrisburg office or the Mercer County Conservation District office.



### 2.3 OPERATION

The "Sandy Creek Watershed Work Plan" and a subsequent agreement between the Mercer County Commissioners and the SCS, dated 9 June 1965, detail the provisions for operation and maintenance of this structure. This agreement is available in the files of the Mercer County Conservation District office.

### 2.4 EVALUATION

- a. Availability - The PennDER File No. 43-50, the Mercer County Conservation District office file, and the file contained in SCS Harrisburg office are readily available for review.
- b. Adequacy - The information available is adequate for a Phase I Inspection of this dam.
- c. Validity - Observations and measurements performed during the visual inspection did not indicate any deviations from the "as built" drawings for this dam.

### SECTION 3 - VISUAL INSPECTION

#### 3.1 FINDINGS

a. General - The inspection was performed on 9 May 1979. No unusual weather conditions were experienced and the lake was at sediment pool. A subsequent site visit was performed on 5 June 1979. The dam and appurtenant structures were found to be in good overall condition at the time of the inspection. Noteworthy deficiencies observed are described briefly in the following paragraphs. The complete visual inspection check list and field sketch are given in Appendix A.

b. Dam - Clear seepage was observed exiting at an estimated rate of 0.5 g.p.m. to the left of the outlet structure. The two filter drain outlets which exit into the impact basin were flowing with clear water. The left outlet was flowing at an estimated rate of 5 g.p.m. The right drain outlet was clogged with material. After removal of the material the drain outlet flowed partially full then tapered to a trickle. This drain was stained orange. This orange staining could possibly be from two sources: 1) iron staining; 2) algae growth.

Several rodent/animal burrows were observed in the embankment. The locations of these holes are shown on the field sketch.

c. Dike - A 6-inch diameter corrugated metal pipe which passes through the dike was designed to carry flow from a natural groundwater spring located just upstream from the dike. Both the inlet and the outlet of this drain are covered with sedimentation and vegetation.

d. Appurtenant Structures - Overall, the concrete of the riser intake, outlet conduit and impact basin was observed to be in good condition. However, the joint filler between the outlet conduit and the head wall of the outlet structure was deteriorated and missing in some spots. The trash rack of the low level inlet was partially clogged with debris at the time of inspection. Several small trees (1 to 2 inch diameter) were cut from and stockpiled in the discharge channel of the emergency



spillway. Also, at the end of the discharge channel of the emergency spillway, a fence crosses the channel.

- e. Reservoir Area - The sediment pool reservoir is small (approximately 14 acre-feet) and has shallow water areas conducive to the growth of cattails. The Mercer County Conservation District uses the reservoir for protection of wildlife and has installed a number of floating duck nests in the reservoir. No unusual sedimentation in the reservoir was observed. The reservoir area for the flood control pool is protected.
- f. Downstream Channel - The original stream channel of Saw Mill Run forms the outlet discharge channel. Approximately 600 feet downstream from the dam is U.S. Route 62. Two mobile homes are located approximately 400 feet downstream of the dam and may be affected by flood discharges from the dam. Additionally, approximately 20 homes are located in low lying areas below the dam which could be affected by large discharges from the reservoir. These homes are located in the Borough of Stoneboro. The center of Stoneboro is approximately 3000 feet downstream of the dam. Saw Mill Run passes through Stoneboro and outlets into the downstream channel from Sandy Lake. This channel then flows into Sandy Creek.

## **SECTION 4 - OPERATIONAL PROCEDURES**

### **4.1 PROCEDURES**

Operational procedures are summarized in paragraph 1.2.h.

There are no formal emergency procedures in the event of impending catastrophe for the dam. The condition of the dam is checked by Mercer County personnel some time subsequent to each occurrence of heavy precipitation. The emergency spillway and riser intake are uncontrolled and the pond drainpipe has a steel plate bolted on its inlet to the riser structure. The reservoir under normal conditions remains at approximate El. 1241.8 feet and has 15.2 feet of additional storage to the crest of the emergency spillway.

It is recommended that formal emergency procedures and evacuation plans be prepared and prominently displayed, and furnished to all personnel.

### **4.2 MAINTENANCE OF DAM AND APPURTENANCES**

Maintenance of the dam and appurtenant structure is the responsibility of Mercer County. Maintenance is performed by Mercer County personnel when necessary. The dam and appurtenant structures are formally inspected annually by personnel from the Mercer County Conservation District office and the SCS. During these inspections, the condition of the dam is reviewed and recommendations for repairs, when necessary, are made. There is no operating equipment for this dam.

### **4.3 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT**

At the present time, there is no warning system or evacuation plan in the event of a dam failure. An emergency warning procedure should be developed.

### **4.4 EVALUATION OF OPERATIONAL ADEQUACY**

The present operational and maintenance procedures are considered adequate.



## SECTION 5 - HYDRAULIC/HYDROLOGIC

### 5.1 EVALUATION OF FEATURES

- a. Design Data - Hydrologic and hydraulic design calculations for PA 474 were obtained from the SCS "Design Report" on file at PennDER. According to SCS criteria, circa 1964, the emergency spillway and freeboard hydrographs were developed and routed through the reservoir to establish the elevations of the design high water and crest of dam, respectively. The emergency spillway hydrograph was developed using a 6-hour rainfall of 9.6 inches resulting in a peak discharge of 4929 c.f.s. The freeboard hydrograph was developed using a 6-hour rainfall of 19.1 inches with a corresponding peak discharge of 9500 c.f.s.
- b. Experience Data - No reservoir stage or rainfall records are maintained at the dam site. According to the Mercer County Conservation District Representative the emergency spillway has never been activated.
- c. Visual Observations - At the time of the inspection, no condition was observed that could seriously affect the discharge capabilities of the spillway and outlet works.
- d. Overtopping Potential - PA 474 is classified as a "High" hazard-"Small" size dam requiring evaluation for a spillway design flood (SDF) in the range of 1/2 Probable Maximum Flood (1/2 PMF) to the Probable Maximum Flood (PMF). Since the reservoir has a maximum storage capability nearly equal to that of an "Intermediate" size dam, the PMF was chosen as the SDF.

The hydrologic and hydraulic capabilities of the dam were evaluated by routing the PMF through the reservoir with the aid of the U.S. Army Corps of Engineers' Flood Hydrograph Package, HEC-1. The PMF hydrograph developed as part of this analysis had a peak discharge of 2710 c.f.s. using a 6-hour Probable Maximum Precipitation (PMP) of 21.8 inches. The results of this routing indicate that the reservoir is capable of passing the PMF with a maximum reservoir level of El. 1261.2 feet, which is 3.3 feet below the minimum crest of the dam. The maximum discharge from the reservoir, as indicated by this analysis, is 2473 c.f.s.

- e. Spillway Adequacy - The dam, as outlined in the above analysis, is capable of passing the PMF without overtopping. Therefore, the spillway is adequate according to the recommended criteria.

## SECTION 6 - STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

- a. Visual Observations - The seepage area noted to the left of the outlet structure during the visual inspection should be periodically examined in the future to verify that the quantity of seepage is not increasing and transportation of fine material is not occurring. Should the extent of the seepage area or turbidity of the seepage increase with time, the condition should be studied in detail and appropriate remedial measures taken.
- b. Design and Construction Data - Calculations of embankment slope and foundation stability were not available for review. However, a summary report from the SCS Soil Mechanics Laboratory at Lincoln, Nebraska dated 8 December 1964 presented the results of the laboratory soil testing program and slope stability analysis performed. Shear strength properties obtained and used in the slope stability analysis were reported as follows:

#### Foundation Materials -

Soil Type -	Sandy Silt (ML)
Type of Test Performed -	Consolidated Undrained Triaxial Shear Test
Angle of Internal Friction ( $\phi$ ) -	26.5°
Cohesion (c) -	200 p.s.f.
Sample Type -	Undisturbed Sample

#### Embankment Materials -

Soil Type -	Silty Clay (CL-ML)
Type of Test Performed -	Consolidated Undrained Triaxial Shear Test
Angle of Internal Friction ( $\phi$ ) -	26°
Cohesion (c) -	725 p.s.f.
Sample Type -	Remolded and compacted at 95% Standard Proctor

The results of three stability analyses (using the Swedish Circle Method) was presented, however, their analysis used a 3H:1V upstream slope and 2H:1V downstream slope. The SCS results indicated the slopes to be stable under their assumed geometry and the report concluded that the slopes would also be stable under 2.5H:1V slopes upstream and downstream. It should be pointed out that the foundation drain recommended by the SCS to prevent piping and relieve uplift at the toe was installed. Also, the selective placement (zoning) of the embankment was installed as recommended.



Based upon the above information, coupled with the visual inspection, it is concluded that no further stability assessments are deemed necessary.

- c. Operating Records - No operating records are maintained. The operation procedures do not indicate any cause for concern relative to the structural stability of the dam.
- d. Post-Construction Changes - The post-construction changes to the dam do not adversely affect the structural stability.
- e. Seismic Stability - The dam is located in Zone 1 on the "Seismic Zone Map of the Contiguous United States," Figure 1, page D-30, "Recommended Guidelines for Safety Inspection of Dams." This is an area of very low seismic activity. Experience indicates that dams in Seismic Zone 1 will have adequate stability under seismic loading conditions if they have adequate stability under static loading conditions. As indicated in paragraph 6.1.b., this dam could be shown to meet the stability requirements of the "Recommended Guidelines for Safety Inspection of Dams." Therefore, further consideration of the seismic stability is not warranted for this Phase I Inspection Report.

## SECTION 7 - ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES

### 7.1 DAM ASSESSMENT

- a. Safety - The dam was in good overall condition at the time of inspection. The seepage observed during the visual inspection does not constitute a hazard to the safety of the structure according to the conditions present at the time of the inspection. PA 474 is a "High" hazard-"Small" size dam and should have a hydraulic capability sufficient to pass the PMF. As presented in Section 5, the spillways and reservoir were determined adequate to pass the PMF without overtopping the dam.
- b. Adequacy of Information - The information available combined with the visual observations and measurements made during the field inspection are considered sufficient for this Phase I Inspection Report.
- c. Urgency - The owner should initiate the action discussed in paragraph 7.2 as soon as practicable.
- d. Necessity for Additional Data/Evaluation - No further investigation is necessary, unless future inspections of the seepage area indicate changing conditions.

### 7.2 RECOMMENDATIONS/REMEDIAL MEASURES

The inspection revealed a few items of remedial work which should be performed as soon as practicable by the owner. These include:

- 1) Periodically inspect the seepage area to the left of the outlet structure to identify a change in quantity of seepage or the exiting of muddy water from this area and, if necessary, study the situation in detail and take appropriate remedial measures.
- 2) Remove the sedimentation and vegetation above the inlet and outlet of the spring drain in the dike and clean the pipe out, if necessary. The downstream channel may need to be reshaped to provide sufficient drainage away from the toe of the dike.
- 3) Remove the stockpiled brush from the emergency spillway channel.



- 4) Fill the animal burrows in the embankment and establish a rodent control program.
- 5) Replace the joint filler between the outlet conduit and the impact basin head wall.
- 6) Periodically inspect and maintain the filter drain outlets.
- 7) Clear the debris from the trash rack of the riser and periodically inspect and maintain the trash rack in the future.

In addition, the following operational measures are recommended to be undertaken by the owner:

- 1) Develop a detailed emergency operation and warning system.
- 2) During periods of unusually heavy rain, provide around-the-clock surveillance of the dam.
- 3) When warning of a storm of major proportions is given by the National Weather Service, the owner should activate the emergency operation and warning system.

**PLATES**







PLATE I LOCATION PLAN  
PA 474





PLATE 2 WATERSHED MAP  
PA 474







AREA TO BE SEED - 1.000000 64 ACRES  
 AREA TO BE CLEANED - 1.000000 64 ACRES

NOTE:  
 AREAS TO BE SEED INCLUDE ONLY DAM, ONE  
 EMERGENCY SPILLWAY, CULVERT AREA AND  
 DISTURBED AREAS IN VICINITY OF DAM.  
 SOME DISTURBED AREAS LIMITS TO BE SET IN FIELD.

THIS PAGE IS BEST QUALITY PRACTICABLE  
 FROM COPY FURNISHED TO DDC

—X— EXISTING FENCE  
 [—X—] SECTION TO BE FENCED  
 —I— FENCE TO BE INSTALLED  
 FOR FENCE DETAILS SEE SHEET 11

PLATE 3  
 AS BUILT PLANS

SCALE 0 50 100 200 400 FEET

SANDY CREEK WATERSHED  
 FLOODWATER RETARDING DAM PA-474  
 MERCER COUNTY, PENNSYLVANIA  
 PLAN OF STORAGE AREA


U. S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE

Designed <i>James H. Riddington &amp; Co.</i>	Date	Approved by
Drawn <i>R. A. STALTER</i>	FEB. 65	Title
Traced	Sheet	Drawing No.
Checked <i>By Lloyd Thomas</i>	No. 2	PA-474-P



# **EMERGENCY SPILLWAY & CURVE DATA**

STATION	DEFLECTION	CHORD
PC 1+74.87	15° 00'	15.00
1+79.88	4° 18'	15.26
1+84.89	8° 36'	15.52
1+89.90	12° 54'	15.78
1+94.91	17° 12'	16.04
1+99.92	21° 30'	16.30
2+04.93	25° 48'	16.56
2+09.94	30° 06'	16.82
2+14.95	34° 24'	17.08
2+19.96	38° 42'	17.34
2+24.97	43° 00'	17.60
2+29.98	47° 18'	17.86
2+34.99	51° 36'	18.12
2+39.00	55° 54'	18.38
2+44.01	60° 12'	18.64
2+49.02	64° 30'	18.90
2+54.03	68° 48'	19.16
2+59.04	73° 06'	19.42
2+64.05	77° 24'	19.68
2+69.06	81° 42'	19.94
2+74.07	86° 00'	20.20
2+79.08	90° 18'	20.46
2+84.09	94° 36'	20.72
2+89.10	98° 54'	20.98
2+94.11	103° 12'	21.24
2+99.12	107° 30'	21.50
3+04.13	111° 48'	21.76
3+09.14	116° 06'	22.02
3+14.15	120° 24'	22.28
3+19.16	124° 42'	22.54
3+24.17	129° 00'	22.80
3+29.18	133° 18'	23.06
3+34.19	137° 36'	23.32
3+39.20	141° 54'	23.58
3+44.21	146° 12'	23.84
3+49.22	150° 30'	24.10
3+54.23	154° 48'	24.36
3+59.24	159° 06'	24.62
4+04.25	163° 24'	24.88
4+09.26	167° 42'	25.14
4+14.27	172° 00'	25.40
4+19.28	176° 18'	25.66
4+24.29	180° 36'	25.92
4+29.30	184° 54'	26.18
4+34.31	189° 12'	26.44
4+39.32	193° 30'	26.70
4+44.33	197° 48'	26.96
4+49.34	202° 06'	27.22
4+54.35	206° 24'	27.48
4+59.36	210° 42'	27.74
5+04.37	215° 00'	28.00
5+09.38	219° 18'	28.26
5+14.39	223° 36'	28.52
5+19.40	227° 54'	28.78
5+24.41	232° 12'	29.04
5+29.42	236° 30'	29.30
5+34.43	240° 48'	29.56
5+39.44	245° 06'	29.82
5+44.45	249° 24'	30.08
5+49.46	253° 42'	30.34
5+54.47	258° 00'	30.60
5+59.48	262° 18'	30.86
6+04.49	266° 36'	31.12
6+09.50	270° 54'	31.38
6+14.51	275° 12'	31.64
6+19.52	279° 30'	31.90
6+24.53	283° 48'	32.16
6+29.54	288° 06'	32.42
6+34.55	292° 24'	32.68
6+39.56	296° 42'	32.94
6+44.57	301° 00'	33.20
6+49.58	305° 18'	33.46
6+54.59	309° 36'	33.72
6+59.60	313° 54'	33.98
7+04.61	318° 12'	34.24
7+09.62	322° 30'	34.50
7+14.63	326° 48'	34.76
7+19.64	331° 06'	35.02
7+24.65	335° 24'	35.28
7+29.66	339° 42'	35.54
7+34.67	344° 00'	35.80
7+39.68	348° 18'	36.06
7+44.69	352° 36'	36.32
7+49.70	356° 54'	36.58
7+54.71	361° 12'	36.84
7+59.72	365° 30'	37.10
8+04.73	369° 48'	37.36
8+09.74	374° 06'	37.62
8+14.75	378° 24'	37.88
8+19.76	382° 42'	38.14
8+24.77	387° 00'	38.40
8+29.78	391° 18'	38.66
8+34.79	395° 36'	38.92
8+39.80	399° 54'	39.18
8+44.81	404° 12'	39.44
8+49.82	408° 30'	39.70
8+54.83	412° 48'	39.96
8+59.84	417° 06'	40.22
9+04.85	421° 24'	40.48
9+09.86	425° 42'	40.74
9+14.87	429° 60'	41.00
9+19.88	433° 78'	41.26
9+24.89	437° 96'	41.52
9+29.90	442° 14'	41.78
9+34.91	446° 32'	42.04
9+39.92	450° 50'	42.30
9+44.93	455° 08'	42.56
9+49.94	459° 26'	42.82
9+54.95	463° 44'	43.08
9+59.96	468° 02'	43.34
10+04.97	472° 20'	43.60
10+09.98	476° 38'	43.86
10+14.99	480° 56'	44.12
10+19.00	485° 14'	44.38
10+24.01	489° 32'	44.64
10+29.02	493° 50'	44.90
10+34.03	498° 08'	45.16
10+39.04	502° 26'	45.42
10+44.05	506° 44'	45.68
10+49.06	511° 02'	45.94
10+54.07	515° 20'	46.20
10+59.08	519° 38'	46.46
11+04.09	523° 56'	46.72
11+09.10	528° 14'	46.98
11+14.11	532° 32'	47.24
11+19.12	536° 50'	47.50
11+24.13	541° 08'	47.76
11+29.14	545° 26'	48.02
11+34.15	549° 44'	48.28
11+39.16	554° 02'	48.54
11+44.17	558° 20'	48.80
11+49.18	562° 38'	49.06
11+54.19	566° 56'	49.32
11+59.20	571° 14'	49.58
12+04.21	575° 32'	49.84
12+09.22	579° 50'	50.10
12+14.23	584° 08'	50.36
12+19.24	588° 26'	50.62
12+24.25	592° 44'	50.88
12+29.26	597° 02'	51.14
12+34.27	601° 20'	51.40
12+39.28	605° 38'	51.66
12+44.29	609° 56'	51.92
12+49.30	614° 14'	52.18
12+54.31	618° 32'	52.44
12+59.32	622° 50'	52.70
13+04.33	627° 08'	52.96
13+09.34	631° 26'	53.22
13+14.35	635° 44'	53.48
13+19.36	639° 62'	53.74
13+24.37	643° 80'	54.00
13+29.38	647° 98'	54.26
13+34.39	652° 16'	54.52
13+39.40	656° 34'	54.78
13+44.41	660° 52'	55.04
13+49.42	665° 10'	55.30
13+54.43	669° 28'	55.56
13+59.44	673° 46'	55.82
14+04.45	678° 04'	56.08
14+09.46	682° 22'	56.34
14+14.47	686° 40'	56.60
14+19.48	690° 58'	56.86
14+24.49	695° 16'	57.12
14+29.50	699° 34'	57.38
14+34.51	703° 52'	57.64
14+39.52	708° 10'	57.90
14+44.53	712° 28'	58.16
14+49.54	716° 46'	58.42
14+54.55	721° 04'	58.68
14+59.56	725° 22'	58.94
15+04.57	729° 40'	59.20
15+09.58	733° 58'	59.46
15+14.59	738° 16'	59.72
15+19.60	742° 34'	59.98
15+24.61	746° 52'	60.24
15+29.62	751° 10'	60.50
15+34.63	755° 28'	60.76
15+39.64	759° 46'	61.02
15+44.65	764° 04'	61.28
15+49.66	768° 22'	61.54
15+54.67	772° 40'	61.80
15+59.68	776° 58'	62.06
16+04.69	781° 16'	62.32
16+09.70	785° 34'	62.58
16+14.71	789° 52'	62.84
16+19.72	794° 10'	63.10
16+24.73	798° 28'	63.36
16+29.74	802° 46'	63.62
16+34.75	807° 04'	63.88
16+39.76	811° 22'	64.14
16+44.77	815° 40'	64.40
16+49.78	819° 58'	64.66
16+54.79	824° 16'	64.92
16+59.80	828° 34'	65.18
17+04.81	832° 52'	65.44
17+09.82	837° 10'	65.70
17+14.83	841° 28'	65.96
17+19.84	845° 46'	66.22
17+24.85	849° 64'	66.48
17+29.86	853° 82'	66.74
17+34.87	858° 00'	67.00
17+39.88	862° 18'	67.26
17+44.89	866° 36'	67.52
17+49.90	870° 54'	67.78
17+54.91	875° 12'	68.04
17+59.92	879° 30'	68.30
18+04.93	883° 48'	68.56
18+09.94	888° 06'	68.82
18+14.95	892° 24'	69.08
18+19.96	896° 42'	69.34
18+24.97	900° 60'	69.60
18+29.98	904° 78'	69.86
18+34.99	908° 96'	70.12
18+39.00	913° 14'	70.38
18+44.01	917° 32'	70.64
18+49.02	921° 50'	70.90
18+54.03	926° 08'	71.16
18+59.04	930° 26'	71.42
19+04.05	934° 44'	71.68
19+09.06	938° 62'	71.94
19+14.07	942° 80'	72.20
19+19.08	946° 98'	72.46
19+24.09	951° 16'	72.72
19+29.10	955° 34'	72.98
19+34.11	959° 52'	73.24
19+39.12	964° 10'	73.50
19+44.13	968° 28'	73.76
19+49.14	972° 46'	74.02
19+54.15	977° 04'	74.28
19+59.16	981° 22'	74.54
20+04.17	985° 40'	74.80
20+09.18	989° 58'	75.06
20+14.19	994° 16'	75.32
20+19.20	998° 34'	75.58
20+24.21	1002° 52'	75.84
20+29.22	1007° 10'	76.10
20+34.23	1011° 28'	76.36
20+39.24	1015° 46'	76.62
20+44.25	1019° 64'	76.88
20+49.26	1023° 82'	77.14
20+54.27	1028° 00'	77.40
20+59.28	1032° 18'	77.66
21+04.29	1036° 36'	77.92
21+09.30	1040° 54'	78.18
21+14.31	1045° 12'	78.44
21+19.32	1049° 30'	78.70
21+24.33	1053° 48'	78.96
21+29.34	1058° 06'	79.22
21+34.35	1062° 24'	79.48
21+39.36	1066° 42'	79.74
21+44.37	1070° 60'	80.00
21+49.38	1074° 78'	80.26
21+54.39	1078° 96'	80.52
21+59.40	1083° 14'	80.78
22+04.41	1087° 32'	81.04
22+09.42	1091° 50'	81.30
22+14.43	1096° 08'	81.56
22+19.44	1100° 26'	81.82
22+24.45	1104° 44'	82.08
22+29.46	1108° 62'	82.34
22+34.47	1112° 80'	82.60
22+39.48	1116° 98'	82.86
22+44.49	1121° 16'	83.12
22+49.50	1125° 34'	83.38
22+54.51	1129° 52'	83.64
22+59.52	1134° 10'	83.90
23+04.53	1138° 28'	84.16
23+09.54	1142° 46'	84.42
23+14.55	1146° 64'	84.68
23+19.56	1150° 82'	84.94
23+24.57	1155° 00'	85.20
23+29.58	1159° 18'	85.46
23+34.59	1163° 36'	85.72
23+39.60	1167° 54'	85.98
23+44.61	1172° 12'	86.24
23+49.62	1176° 30'	86.50
23+54.63	1180° 48'	86.76
23+59.64	1185° 06'	87.02
24+04.65	1189° 24'	87.28
24+09.66	1193° 42'	87.54
24+14.67	1197° 60'	87.80
24+19.68	1201° 78'	88.06
24+24.69	1205° 96'	88.32
24+29.70	1210° 14'	88.58
24+34.71	1214° 32'	88.84
24+39.72	1218° 50'	89.10
24+44.73	1223° 08'	89.36
24+49.74	1227° 26'	89.62
24+54.75	1231° 44'	89.88
24+59.76	1236° 02'	90.14
25+04.77	1240° 20'	90.40
25+09.78	1244° 38'	90.66
25+14.79	1248° 56'	90.92
25+19.80	1253° 14'	91.18
25+24.81	1257° 32'	91.44
25+29.82	1261° 50'	91.70
25+34.83	1266° 08'	91.96
25+39.84	1270° 26'	92.22
25+44.85	1274° 44'	92.48
25+49.86	1279° 02'	92.74
25+54.87	1283° 20'	93.0



THIS PAGE IS BEST QUALITY PRACTICABLE  
 FROM COPY FURNISHED TO DOD

# PLATE 4 AS BUILT PLANS


0 50 100 150 FEET  
 SCALE


SANDY CREEK WATERSHED  
 FLOODWATER RETARDING DAM PA-474  
 MERCER COUNTY, PENNSYLVANIA  
 DAMSITE

U. S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE

Designer James A. Riddle 2-65	Approved by R. A. STALTER 2-65
Title Floodwater Retarding Dam	Drawing No. PA-474-P







THIS PAGE IS BEST QUALITY PRACTICE  
FROM COPY FURNISHED TO DDC

SEE SHEETS 2, 3, 14, AND 15 FOR  
LINES OF SPILLWAYS AND TEST PITS.

2  
PLATE 5

As Built

AS BUILT PLANS

SANDY CREEK WATERSHED FLOODWATER RETARDING DAM PA-474 MERCER COUNTY, PENNSYLVANIA PROFILE OF DAM & EMERGENCY SPILLWAY			
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE			
Designed <i>James H. Kelly</i>	Date 8-65	Approved by Title	
Drawn R. J. MAYE	FEB 65	Title	
Checked <i>Alfred A. Snyder</i>	2-65	Sheet No. 4 of 6	Drawing No. PA-474-P




3 20' SECTIONS  
1 6" SECTION PERFORATED  
1 5'-6" SECTION  
1 6'-10" SECTION  
1 90° ELBOW (121)  
2 90° ELBOWS (122)  
1 90° ELBOW (122B)  
1 METAL END CAP  
1 SMALL ANNUAL LEAK (122-122-122-122)  
129'-10" TOTAL (USE STANDARD COUPLING BARS)

12 20" SECTIONS }  
1 12" SECTION } PERFORATED  
1 7" SECTION }  
1 5'-6" SECTION }  
1 6'-10" SECTION }  
1 22"-30" ELBOW (1X1)  
1 90° ELBOW (1X1)  
2 90° ELBOWS (1X2)  
1 90° ELBOW (1X2½)  
1 MINOR: NO CAP  
1 SMALL ANIMAL LEAD (12" x 12" x 10")  
249'-10" TOTAL (USE STANDARD COUPLING BANDS)

**NOTE:**  
ALL FILTER DRAIN PIPE TO BE IRON OR STEEL  
GRADE 1, CLASS III, COATING TYPE A, 1/2" DIA

FOUNDATION DRAWN & BUILT  
INSTALLED AS DESIGNED



ASIM

SECTION  
SAME AS  
WITH DRUG  
DRUG CASE



DRAIN PIPE

PERFORATED

(12)  
(12)  
(12)


STANDARD (ADDITIONAL BANDS)

FOUNDATION DRAIN SYSTEM  
INSTALLED AS DESIGNED



DISPOSAL AREA FOR ROCK  
FORCED FROM FILL  
SEE SHEET 6

ISOMETRIC OF FOUNDATION DRAIN DETAIL




70' 0" 8+75 8+97


20' 0" 9+77

40' 0" - STATIONING ALONG E OF FILL  
- STATIONING ALONG E OF DRAIN

PIPE DIA.	SPACING
4"	100'
6"	50'-100'
8"	30'-100'
10"	20'-50'
12"	10'-20'
14"	5'-10'
16"	0'-5'
18"	0'-5'
20"	0'-5'



FOUNDATION DRAIN SYSTEM FOR ALL DRAIN TUBES



SECTION 6-8




PLATE 6

FOUNDATION DRAIN DETAIL - INSTALLED AS DESIGNED  
**AS BUILT PLANS**

As Built  
2

SANDY CREEK WATERSHED FLOODWATER RETARDING DAM PA-474 MERCER COUNTY, PENNSYLVANIA FOUNDATION DRAIN DETAILS	
U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE	
Designed by <i>James A. Rothberger</i>	Drawn by <i>C. CRIS</i>
Checked by <i>Robert L. Thomas</i>	Approved by <i>PA-474-P</i>
Date FEB 65	Sheet 3 of 15

THIS PAGE IS BEST QUALITY PRACTICE  
FROM COPY FURNISHED TO DDC





# 6" Dia. Filter Drain Pipe (Perforated)

- 8 15'-6" Sections
- 4 1"x2" Elbows
- 1 1"x1' Tee
- 1 Metal End Cap

Use Standard Coupling Sands


Material Spec. 110  
Construction Spec. 12

 R.S.T.M. fine concrete aggregate  
 R.S.T.M. #70 Road Gravel


Approx volume of d

## Note:

For gradation limits for all drain fill and additional filter drain pipe installation data see sheet #5 of const'g plans.




SECTION B-B



RELIEF WELL DETAIL

Dimensions of relief well installation to be determined by the Engineer to fit field conditions. Dimensions shown are suggested values.



\* Collar no.'s refer to those shown on the const'g plans; sheet #6.

PLAN VIEW  
Not to Scale

PROFILE OF 6" DIA SPRING DRAIN


SCALE: Noted  
Noted

Drain Pipe (Perforated)  
 Sections  
 Shows  
 Top  
 End Cap  
 Standard Coupling Bands


Material Spec. 110  
 Construction Spec. 12

[Symbol] A.S.T.M. Fine concrete aggregate } Approx volume of drain fill required = 30 Cu Yds  
 [Symbol] A.S.T.M. #70 Road Gravel


See limits for all drain fill and additional  
 pipe installation data see sheet "5" of const'n plans.




**PLAN VIEW**  
 Not to Scale



**PROFILE OF 6" DIA SPRING DRAIN**  
 SCALE: HORIZ. 1" = 10'-0" VERT. 1" = 1'-0"



**SECTION A-A**



**SECTION C-C**

THIS PAGE IS BEST QUALITY FRAGMENTED  
 FROM COPY FURNISHED TO DGC

**AS BUILT PLANS**

**PLATE 7**


As D<sup>n</sup>

MODIFICATION

SANDY CREEK WATERSHED FLOODWATER RETARDING DAM PA-474 MERCER COUNTY, PENNSYLVANIA SPRING DRAIN DETAILS	
U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE	
Date: <u>12 MAY 66</u> Drawn: <u>RJM</u> Title: <u>Spring Drain Details</u> Checked: <u>St. Louis, Engineer</u>	Approved by: <u>St. Louis, Engineer</u> Title: <u>St. Louis, Engineer</u> Sheet: <u>PA-474-P</u> Drawing No.: <u>PA-474-P</u>

2





DIMENSIONS OF PIPE ARE BASED ON 0.2% YIELD  
STRESS AND DO NOT INCLUDE CREEP

ANTI-SEEP COLLAR DATA		
COLLAR	WINDING FEET OVER WALL	WATER EL ON 12-10 DRAIN PWT
1	0	129.9
2	30	129.01
3	50	129.7
4	70	129.00
5	90	128.86


NOTE: DIFFERENTIAL SETTLEMENTS AND  
FROM A GRADE SURVEY  
TO BE DETERMINED BY THE ENGINEER

EXIT CHANNEL


SLABE BASE  
LENGTH 20' APPROX.

FOUNDATION SPREAD  
BETWEEN SHEET PILES

PLAN VIEW OF PRINCIPAL SPILLWAY




ANTI-SEEP COLLAR



IMPACT BASIN



EXIT CHANNEL



TRANSITION SECTION

EXIT CHANNEL


TYPICAL SECTIONS  
PROV. LIMITS FOR EXCAVATION BETWEEN MEAT LINES

# AS BUILT PLANS

## PLATE 8

15'-0" GRAD 2

OUTLET END OF PIPE TO BE  
FINISHED SO THAT NO METAL  
IS EXPOSED



PROFILE OF PRINCIPAL SPILLWAY

PROPOSED ROAD 16'  
AND 12' 0" 101 PER LINE FT. BASED ON 6.0 IN. 42"  
AND 5' 0" 101 PER LINE FT. BASED ON 6.0 IN. 42"  
0.01" CRACK NON-POSTSTRESSED PIPE = 0.050 101 PER LINE FT.  
0.01" CRACK PRESTRESSED PIPE = 0.350 101 PER LINE FT.  
16" 1.0 REINFORCED CONCRETE WATER PIPE  
9 - 16" SECTIONS  
1 - WALL PIECE FOR 12" WALL  
105.33' TOTAL

NOT TO SCALE

*As Built*

SANDY CREEK WATERSHED			
FLOODWATER RETARDING DAM PA-474			
MERCER COUNTY, PENNSYLVANIA			
PLAN-PROFILE OF PRINCIPAL SPILLWAY			
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE			
Designed by <i>John R. Mays</i>	DATE <i>2-65</i>	Approved by	
Drawn by <i>R. J. MAYS</i>	FEB 65	Checked by	
Traced		Drawing No.	PA-474-P
Checked by <i>Alfred A. Smyth</i>	2-65		

THIS PAGE IS BEST QUALITY FRAGMENTS  
FROM COPY FURNISHED TO DDC

2



**APPENDIX A**

**CHECK LIST - VISUAL INSPECTION  
AND FIELD SKETCH**

Check List  
Visual Inspection  
Phase 1

A-1

Name of Dam PA 474 County Mercer State PA Coordinates Lat. N 41° 20.1'  
NDI # PA 00249 Long. W 80° 05.7'  
PennDER # 43-50  
SCS # PA 474  
Date of Inspection 9 May 1979 Weather Sunny Temperature 90°F.

Pool Elevation at Time of Inspection 1242.5 ft.\* M.S.L. Tailwater at Time of Inspection 1229.0 ft.\* M.S.L.

\*All elevations are referenced to the crest of the riser orifice (El. 1241.8 ft.)

Inspection Personnel:

Michael Baker, Jr., Inc.

Rodney E. Holderbaum  
James G. Ullinski

Site Visit (5 June 1979)

Dr. C. Y. Chen  
James G. Ullinski

James G. Ullinski Recorder



CONCRETE/MASONRY DAMS - Not Applicable

A-2

Name of Dam: PA 474  
NDI # PA 00249

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

LEAKAGE

STRUCTURE TO  
ABUTMENT/EMBANKMENT  
JUNCTIONS

DRAINS

WATER PASSAGES

FOUNDATION

CONCRETE/MASONRY DAMS - Not Applicable

A-3

Name of Dam: PA 474  
NDI # PA 00249

VISUAL EXAMINATION OF OBSERVATIONS REMARKS OR RECOMMENDATIONS

SURFACE CRACKS  
CONCRETE SURFACES

STRUCTURAL CRACKING

VERTICAL AND HORIZONTAL  
ALIGNMENT

MONOLITH JOINTS

CONSTRUCTION JOINTS



Name of Dam: PA 474  
DOI # PA 00249

EMBANKMENT

A-4

VISUAL EXAMINATION OF OBSERVATIONS REMARKS OR RECOMMENDATIONS

SURFACE CRACKS

None

UNUSUAL MOVEMENT OR  
CRACKING AT OR BEYOND  
THE TOE

None

SLOUGHING OR EROSION OF  
EMBANKMENT AND ABUTMENT  
SLOPES

None

VERTICAL AND HORIZONTAL  
ALIGNMENT OF THE CREST

No problems observed

RIPRAP FAILURES

None

**EMBANKMENT**

**A-5**

Name of Dam: PA 474

NDI # PA 00249

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
RODENT/ANIMAL BURROWS	Several rodent/animal burrows were observed in the embankment. The approximate location of these holes are shown on the field sketch.	The holes should be repaired.
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	No problems observed	
ANY NOTICEABLE SEEPAGE	Minor seepage was observed to the left of the outlet structure (impact basin) wall. Clear flow of approximately 0.5 g.p.m. at the time of inspection.	This area should be observed periodically in the future to identify any changes in characteristics.
STAFF GAGE AND RECORDER	None installed	
DRAINS	Two 6-in. corrugated metal drainpipes enter the impact basin (one on each side). The left drain was flowing with clear water, approximately 1.5 in. deep in the invert (approximately 15 g.p.m.). The right drain was clogged. After unclogging, the drain flowed full for approximately five minutes and eventually tapered off to a slow trickle.	These drains shall be inspected periodically for turbidity, volume of flow and blockage.



# OUTLET WORKS

A-6

Name of Dam: PA 474  
NDI # PA 00249

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	The outlet conduit, at its exit, was in good condition. The remainder of the conduit was unobservable.	
INTAKE STRUCTURE	Very good condition. The interior and exterior surfaces show no sign of deterioration. Some debris has accumulated around the trash rack.	Debris should be removed periodically.
OUTLET STRUCTURE	Joint filler between the outlet conduit and concrete outlet structure has deteriorated. No other deterioration was observed.	Joint filler should be replaced and inspected periodically.
OUTLET CHANNEL	The outlet channel is in fairly good condition. A small road crossing is located several hundred ft. downstream from the dam.	The road crossing could become clogged with debris but would not significantly affect discharges from the reservoir.
EMERGENCY GATE	The 24-in. diameter pond drain outlet has a steel plate bolted in front of it.	
SPRING DRAIN IN DIKE	A 6-in. C.M.P. provides drainage for a groundwater spring located upstream of the dike. This drain has an inlet on the upstream side of the dike and outlets downstream of the dike. Both the inlet and outlet were covered with sedimentation and vegetation.	The inlet and outlet should be uncovered and the drain and pipe made functional according to design intent.

Name of Dam: PA 474  
DOI # PA 00249

UNGATED SPILLWAY  
(EMERGENCY SPILLWAY  
IN SCS TERMINOLOGY)

A-7

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

CONCRETE WEIR

No concrete weir was installed. The spillway is a well vegetated side channel spillway.

APPROACH CHANNEL

The approach channel is well vegetated and free of debris.

DISCHARGE CHANNEL

Several small trees (1-2 in. diameter) were cut from and stockpiled in the discharge channel. A fence is located at the end of the emergency spillway discharge channel.

All brush and debris should be removed from the channel.

BRIDGE AND PIERS

Not Applicable



**GATED SPILLWAY - Not Applicable**

**A-8**

Name of Dam: PA 474

NDI # PA 00249

<b>VISUAL EXAMINATION OF</b>	<b>OBSERVATIONS</b>	<b>REMARKS OR RECOMMENDATIONS</b>
------------------------------	---------------------	-----------------------------------

**CONCRETE SILL**

**APPROACH CHANNEL**

**DISCHARGE CHANNEL**

**BRIDGE AND PIERS**

**GATES AND OPERATION  
EQUIPMENT**

A-9

INSTRUMENTATION - None

Name of Dam: PA 474

NDI # PA 00249

VISUAL EXAMINATION      OBSERVATIONS      REMARKS OR RECOMMENDATIONS

MONUMENTATION/SURVEYS

OBSERVATION WELLS

WEIRS

PIEZOMETERS

OTHER



**RESERVOIR**

**A-10**

Name of Dam: PA 474

NDI # PA 00249

<b>VISUAL EXAMINATION OF</b>	<b>OBSERVATIONS</b>	<b>REMARKS OR RECOMMENDATIONS</b>
------------------------------	---------------------	-----------------------------------

**SLOPES**

The areas adjacent to the reservoir are generally mildly sloping farmland. The slopes are stable from a soil mechanics point of view.

**SEDIMENTATION**

Considering the age of the structure and the watershed characteristics, sedimentation should not be significant at this time.

The reservoir was designed by the SCS with allowance for 50 years of sediment accumulation.

## DOWNSTREAM CHANNEL

Name of Dam: PA 474

MDI # PA 00249

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

## CONDITION

(OBSTRUCTIONS,  
DEBRIS, ETC.)

No major obstructions are located in the downstream channel. Several small bridges span the stream which could become blocked with debris during a large flood.


## SLOPES

The slopes adjacent to the downstream channel are mild to flat and are stable from a soil mechanics point of view. The downstream channel slope is mild, averaging 2.5% below the dam.

APPROXIMATE NO.  
OF HOMES AND  
POPULATION

Saw Mill Run flows into the Borough of Stoneboro approximately 3000 ft. downstream from the dam. Approximately 20 homes are located in low lying areas and could be affected by large discharges from the reservoir.





Clear Seepage Observed To The Left Of The Outlet Structure In The Riprap

Normal Pool  
Elev. 1241.8

Principal Spillway

Intake Suiser

Cattails

Maximum Pool  
El. 1261.2 Ft.

Marshy, Ground Water Spring Area

Dike

Drainage Ditch

Access Gate

Control Section of Emergency Spillway Channel  
El. 1237.0 Ft.

Cut Brush Stockpiled In The Emergency Spillway

Dike

Exit Channel Eroded Drainage Ditch

Joint Filler Left Side of Conduit is Missing

Minor Erosion

Farm Pond (Constructed Prior To Dam)

Gate

Legend

● Rodent / Animal Burrow  
I-I Fence

FIELD SKETCH

PA 474

(PA No Name No. 35)

NDI No. PA 00249

Penn DER No. 43-50

(Not to Scale)

**APPENDIX B**

**CHECK LIST - ENGINEERING DATA**



CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION

B-1

Name of Dam: PA 474  
NDI # PA 00249

ITEM	REMARKS
PLAN OF DAM	Reference Drawings: "Sandy Creek Watershed, Floodwater Retarding Dam PA-474, Mercer County, Pennsylvania," U.S. Department of Agriculture, Soil Conservation Service (SCS), October 1964 (16 sheets of "as built" drawings available in SCS Harrisburg office and Mercer County Conservation District office; prints of the design drawings are available in PennDER's files). Plan of Dam - Reference Drawings Sheets 2 and 3 included in this report as Plates 3 and 4.
REGIONAL VICINITY MAP	A portion of a USGS 7.5 minute topographic quadrangle, Sandy Lake, Pennsylvania, was used to prepare the vicinity map which is enclosed in this report as the Location Plan (Plate 1).
CONSTRUCTION HISTORY	The dam was designed by the SCS and constructed by Kane Brothers Co. of Youngstown, Ohio. The construction occurred from April 1965 to September 1966 with an appropriate winter shutdown period. Inspection was provided by the SCS during the construction.
TYPICAL SECTIONS OF DAM	See Plates 3 and 5 (Reference Drawings Sheets 2 and 4).
HYDROLOGIC/HYDRAULIC DATA	Some hydrologic/hydraulic data are included in the "Sandy Creek Watershed Work Plan" report prepared by the Mercer County Commissioners, et. al., March 1962. Other information is included in the Dam Permit Application Report (11 May 1965) available in PennDER's files. Additional hydrologic/hydraulic data are available in the files of the SCS Harrisburg office.
OUTLETS	- PLAN Reference Drawings - Sheets 3, 5, and 6. (Included in this report as Plated 3, 7, and 5, respectively.
	- DETAILS Reference Drawings - Sheets 5, 6, 7, 8, 9, and 10.
	- CONSTRAINTS None
	- DISCHARGE RATINGS are available in the SCS design files.
RAINFALL/RESERVOIR RECORDS	None available

Name of Dam: PA 474  
NDI # PA 00249

B-2

ITEM	REMARKS
DESIGN REPORTS	No complete design report is readily available, but design report components are available in the files of the SCS Harrisburg office. Additional design information is included in the "Sandy Creek Watershed Work Plan" and in the PennDER Dam Permit Application Report.
GEOLOGY REPORTS	No geology report is readily available. Some geologic information is included in the "Sandy Creek Watershed Work Plan," the files of the SCS Harrisburg office, and various Pennsylvania Geological Survey publications.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	Design computations are available in the files of the SCS Harrisburg office.
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	See Reference Drawings Sheets 2, 3, 4, 13, 14, 15, and 16. Additional information is available in the SCS Harrisburg office files.
POST-CONSTRUCTION SURVEYS OF DAM	The post-construction survey was used to prepare the "as built" drawings, most of which are presented as plates of this report.
BORROW SOURCES	Reference Drawing Sheet 2 (Plate 3 of this report) shows the extent of the borrow area. Additionally, if suitable material was encountered in the emergency spillway excavation, this material was used before the borrow area was opened up.



Name of Dam: PA 474  
NDI # PA 00249

B-3

ITEM	REMARKS
------	---------

MONITORING SYSTEMS      None

**MODIFICATIONS**      Modifications (design changes) during construction were incorporated into the "as built" drawings.  
No additional modifications have been performed.

**HIGH POOL RECORDS**      No records are kept.

**POST-CONSTRUCTION ENGINEERING STUDIES AND REPORTS**      The dam is inspected annually by personnel from the SCS and the Mercer County Conservation District. In 1969 a detailed inspection of the riser unit was performed.

**PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS**      None

**MAINTENANCE OPERATION RECORDS**      Maintenance and operation are reviewed as a part of the annual inspections and recommendations for corrective action are given, if necessary.

Name of Dam: PA 474  
DOI # PA 00249

B-4

ITEM	REMARKS
------	---------

SPIILLWAY PLAN.

SECTIONS,  
and  
DETAILS See Plates 3, 4, and 5.

OPERATING EQUIPMENT None  
PLANS & DETAILS



CHECK LIST  
HYDROLOGIC AND HYDRAULIC DATA  
ENGINEERING DATA

B-5

DRAINAGE AREA CHARACTERISTICS: 1.56 sq. mi. (primarily farmland and woods)

ELEVATION TOP SEDIMENT POOL (STORAGE CAPACITY): 1241.8 ft. (14 ac.-ft.)  
1257.0 ft.

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): (366 ac.-ft.)

ELEVATION MAXIMUM DESIGN POOL: 1261.1 ft.

ELEVATION TOP DAM: 1264.3 ft.

CREST: (SCS Terminology - Emergency Spillway)

- a. Elevation 1257.0 ft. (control section)
- b. Type Vegetated earth channel
- c. Width 100 ft.
- d. Length Approximately 450 ft.
- e. Location Spillover At left end of dam
- f. Number and Type of Gates None

OUTLET WORKS: (SCS Terminology - Principal Spillway)

- a. Type Concrete riser
- b. Location At edge normal pool approximately 400 ft. from left abutment.
- c. Entrance inverts El. 1241.8 ft. (orifice)  
El. 1249.2 ft. (high stage intake)
- d. Exit inverts El. 1228.6 ft.
- e. Emergency draindown facilities 24-in drainpipe  
(bolted shut at present time)

HYDROMETEOROLOGICAL GAGES: None

- a. Type
- b. Location
- c. Records

MAXIMUM NON-DAMAGING DISCHARGE: Unknown

**APPENDIX C**

**PHOTOGRAPHS**



## DETAILED PHOTOGRAPH DESCRIPTIONS

### Overall Views of Dam

Upper Photo - Overall View of Dam from Left Abutment

Lower Photo - Overall View of Dike from Knoll  
Located Between Dam and Dike

- Photo 1 - Upstream Slope of Dam, Intake Riser and Reservoir
- Photo 2 - Close-up View of Intake Riser (Principal Spillway)
- Photo 3 - Downstream Slope of Dam,  
Outlet Structure and Outlet Channel
- Photo 4 - Close-up View of Outlet Structure  
(Note flow exiting toe drain outlet  
in right-center of photo.)
- Photo 5 - View of Upstream Portion of Emergency  
Spillway from Edge of Reservoir
- Photo 6 - View of Downstream Portion of Emergency Spillway Channel
- Photo 7 - View of Crest of Dam from Original Station 16+07  
(corner) Looking Towards Left Abutment of Dam
- Photo 8 - View of Right Wing of Dam from Original Station 16+07  
(corner)  
(Knoll located between dam and dike begins at approxi-  
mate location of fence gate shown in photo.)
- Photo 9 - View of Outlet Channel from Head Wall of Outlet Structure  
(Note two mobile homes located in right-center of photo.)
- Photo 10 - View of Roadway Culvert Downstream of Dam

Note: Photographs were taken on 9 May 1979.

PA 474




**PHOTO 1. Upstream Slope of Dam, Intake Riser and Reservoir**




**PHOTO 2. Close-up View of Intake Riser (Principal Spillway)**






**PHOTO 3. Downstream Slope of Dam, Outlet Structure and Outlet Channel**



**PHOTO 4. Close-up View of Outlet Structure**  
(Note flow exiting the drain outlet in right-center of photo.)

PA 474




**PHOTO 5. View of Upstream Portion of Emergency Spillway,  
from Edge of Reservoir**




**PHOTO 6. Downstream Portion of Emergency Spillway Channel**



PA 474




**PHOTO 7. View of Crest of Dam from Original Station 16 + 07 (corner)  
Looking Towards Left Abutment of Dam**



**PHOTO 8. View of Right Wing of Dam from Original Station 16 + 07 (corner)  
(Knoll located between dam and dike begins at approximate  
location of the fence gate shown in photo.)**

**PA 474**



**PHOTO 9. View of Outlet Channel from Head Wall of Outlet Structure  
(Note two mobile homes located in the right-center of the photo.)**



**PHOTO 10. Roadway Culvert Downstream of Dam**



**APPENDIX D**

**HYDROLOGIC AND HYDRAULIC COMPUTATIONS**

MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009

Subject PA-474 Dam S.O. No. \_\_\_\_\_  
(Pa rd name #33) Sheet No. \_\_\_\_\_ of \_\_\_\_\_  
Drawing No. \_\_\_\_\_  
Computed by \_\_\_\_\_ Checked by \_\_\_\_\_ Date \_\_\_\_\_

## TABLE OF CONTENTS

	<u>Page</u>
PREFACE	<u>L</u>
RAINFALL & HYDROGRAPH DATA	1
WATERSHED MAP	2
STAGE vs DISCHARGE CURVE	3
STAGE vs STORAGE CURVE	4
TOP OF DAM PROFILE	5
MAP OF DOWNSTREAM DAMAGE AREA	6
COMPUTER ANALYSIS	7-11



## PREFACE

### HYDROLOGIC AND HYDRAULIC COMPUTATIONS

The hydrologic determinations presented in this Phase I Inspection Report are based on the use of a Snyder's unit hydrograph developed by the U.S. Army Corps of Engineers. Due to the limited number of gaging stations available in this hydrologic region and the wide variation of watershed slopes, the Snyder's coefficients may yield results of limited accuracy for this watershed. As directed however, a further refinement of these coefficients is beyond the scope of this Phase I Investigation.

In addition, the conclusions presented pertain to present conditions, and the effect of future development on the hydrology has not been considered.

MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009

Subject PA-474 Dam

RAINFALL & HYDROGRAPH DATA

S.O. No. \_\_\_\_\_

Sheet No. 1 of 11

Drawing No. \_\_\_\_\_

Computed by G.O.S.

Checked by REH

Date 2-16-79

RAINFALL

FROM HMR 33, DRAINAGE AREA IS LOCATED IN ZONE 2

PMP 24 hr - 200 mi. = 23.3 inches

$$\left. \begin{array}{l} P_{24hr} = 117\% \\ P_{12hr} = 127\% \\ P_{24hr} = 141\% \\ P_{48hr} = 151\% \end{array} \right\} \begin{array}{l} \text{Rainfall ratios for} \\ D.A. = 1.56 \text{ mi.}^2 \end{array}$$

HYDROGRAPH

DAM IS LOCATED IN ZONE 23,  $C_t \rightarrow$  plate L  $C_p = 0.55$


$$\begin{aligned} t_p &= 3.3(L L_{ca})^{0.3} \\ &= 3.3(2.12 \times 0.8)^{0.3} \\ &= 3.87 \text{ hrs} \end{aligned}$$

$$\begin{aligned} L &= 2.12 \text{ mi} \\ L_{ca} &= 0.80 \text{ mi} \\ t_R &= .33 \text{ hrs} \end{aligned}$$

$$\begin{aligned} t_r &= t_p / 5.5 \\ &= 3.87 / 5.5 \\ &= 0.70 \text{ hr.} \end{aligned}$$

$$\begin{aligned} t_{pR} &= t_p + 0.25(t_R - t_r) \\ &= 3.87 + 0.25(0.33 - 0.70) \\ &= 3.78 \text{ hrs} \end{aligned}$$





QUADS  
A. JACKSON CENTER  
B. SANDY LAKE  
DRAINAGE AREA = 1.36 sq. mi.  
L = 2.12 mi  
Lca = 0.80 mi

SCALE  
0 2000 4000

PA-474  
WATERSHED MAP

MICHAEL BAKER JR. INC.  
Consulting Engineers & Surveyors

MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009

Subject PA-474 Dam

S.O. No. \_\_\_\_\_

Sheet No. 3 of 11

STAGE VS DISCHARGE

Drawing No. \_\_\_\_\_

Computed by G.A.S.


Checked by PEH

Date 2-21-79

STAGE    DISCHARGE

1241.8	0
1243	11
1245	24
1247	32
1249.2	39
1251.2	131
1253.2	138
1255.2	145
1257	151
1258.73	669
1259.62	1202
1260.34	1746
1260.98	2302
1262.09	3440
1263.10	4613
1264	5816
1264.8	7045

NOTE  
THIS DISCHARGE DATA WAS TAKEN  
FROM THE S.C.S. DESIGN REPORT  
FOR DAM PA 474.





MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009

Subject PA-474 Dam

S.O. No. \_\_\_\_\_

Sheet No. 4 of 11

STAGE vs STORAGE


Drawing No. \_\_\_\_\_

Computed by g.s. Checked by REH Date 2-21-79

<u>STAGE</u>	<u>STORAGE</u>
1235	0
1240	3.75
1245	31.25
1250	119.25
1255	266.75
1260	509.75
1265	863.25

NOTE

THIS STORAGE DATA WAS  
TAKEN FROM THE S.C.S.  
DESIGN REPORT FOR  
DAM PA 474.



MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009

Subject PA-474 Dam


S.O. No. \_\_\_\_\_

Sheet No. 5 of 11

TOP OF DAM PROFILE

Drawing No. \_\_\_\_\_

Computed by G.A.S. Checked by REH Date 6-4-79






MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009

Subject PA-474 Dam S.O. No. \_\_\_\_\_  
Map of Downstream Area Sheet No. 6 of 11  
Drawing No. \_\_\_\_\_  
Computed by \_\_\_\_\_ Checked by \_\_\_\_\_ Date \_\_\_\_\_



\*\*\*\*\*  
FLOOD HYDROGRAPH PACKAGE (HEC-1)  
DAM SAFETY VERSION JULY 1978  
LAST MODIFICATION 26 FEB 79  
NOJ UPDATE 04 JUN 79  
\*\*\*\*\*

1	A1	NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS							
2	A2	HYDROLOGIC AND HYDRAULIC ANALYSIS OF PA 474 NOJ 12							
3	A3	PROBABLE MAXIMUM FLOOD PHF/UNIT GRAPH BY SNYDERS METHOD							
4	B	200	0	20	0	0	0	0	0
5	B1	5	1	1					
6	J	1							
7	J1	1.0							
8	K	0							
9	K1	1							
10	M	1							
11	P	23.3	117	127	141	151			
12	T						1.0	0.05	
13	h	3.78							
14	X	-1.5							
15	K	1							
16	K1								
17	V								
18	V1	1							
19	V41241.8	1243	1245	1247	1249.2	1251.2	-1241.8	-1	
20	V41259.6	1260.34	1260.98	1262.09	1263.10	1264	1253.2	1255.2	1257 1250.73
21	V5	0	11	24	32	39	130	145	151 649
22	V5	1202	1746	2302	3440	4613	5816	7015	
23	S5	0	3.75	31.25	115.25	264.75	509.75	843.25	
24	SE	1235	1240	1245	1250	1255	1260	1265	
25	S11241.8								
26	S01264.3	2.65	1.5	2000 <sup>0</sup>					
27	K	99							

THIS IS A ROUTING AT DAM PA. 474

\* See note - page 5



\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79  
 MBJ UPDATE 04 JUN 79  
 \*\*\*\*\*

RUN DATE 06/15/79  
 TIME 12.56

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
 HYDROLOGIC AND HYDRAULIC ANALYSIS OF PA 474 MBJ 12  
 PROBABLE MAXIMUM FLOOD PHF/UNIT GRAPH BY SNYDERS METHOD

JOB SPECIFICATION									
NQ	MR	MMIN	IDAY	IMR	IMIN	METRC	IPLT	IPRT	NSTAN
200	0	20	0	0	0	0	0	-4	0
			JOPER	MMI	LROPT	TRACE			
			5	0	0	0	0		

MULTI-PLAN ANALYSES TO BE PERFORMED  
 APLAN= 1 NRTIO= 1 LRTIO= 1

PTIOS= 1.00

SUB-AREA RUNOFF COMPUTATION

SNYDER UNIT HYDROGRAPH

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRY	INAME	ISTAGE	IAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

IHYDC	IUNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	1	1.56	0.0	1.56	0.0	0.0	0	1	0

PRECIP DATA

SPFF	PMS	R6	R12	R24	R48	R72	R96
0.0	23.30	117.00	127.00	141.00	151.00	0.0	0.0

TRSPC COMPUTED BY THE PROGRAM IS 0.800

LOSS DATA

LROPT	STKR	OLTKR	RTIOL	ERAIN	STKRS	RTIOK	STATL	CMSTL	ALSMX	RTIMP
0	0.0	0.0	1.00	0.0	0.0	1.00	1.00	0.05	0.0	0.0

UNIT HYDROGRAPH DATA

TP= 3.78 CP=0.55 NTA= 0

RECESSION DATA

STRTD= -1.50 QNC5H= -0.05 RTIUR= 2.00

UNIT HYDROGRAPH 77 END-OF-PERIOD CRDINATES, LAG= 3.81 HOURS, CP= 0.55 VOL= 1.00

4.	13.	27.	44.	62.	81.	101.	118.	132.	142.
148.	150.	145.	135.	125.	116.	108.	100.	93.	86.
80.	74.	68.	63.	59.	54.	51.	47.	43.	40.

0		END-OF-PERIOD FLOW										0	
MO.DA	HR.MN	PERIOD	RAIN	EYCS	LOSS	COMP Q	MO.DA	HR.MN	PERIOD	RAIN	EYCS	LOSS	COMP Q
16.	17.	12.	16.	15.	14.	30.	16.	17.	12.	16.	15.	14.	30.
17.	18.	16.	17.	16.	15.	13.	17.	18.	16.	17.	16.	15.	13.
18.	19.	17.	18.	17.	16.	12.	18.	19.	17.	18.	17.	16.	12.
19.	20.	18.	19.	18.	17.	11.	19.	20.	18.	19.	18.	17.	11.
20.	21.	19.	20.	19.	18.	10.	20.	21.	19.	20.	19.	18.	10.
21.	22.	20.	21.	20.	19.	9.	21.	22.	20.	21.	20.	19.	9.
22.	23.	21.	22.	21.	20.	8.	22.	23.	21.	22.	21.	20.	8.
23.	24.	22.	23.	22.	21.	7.	23.	24.	22.	23.	22.	21.	7.
24.	25.	23.	24.	23.	22.	6.	24.	25.	23.	24.	23.	22.	6.
25.	26.	24.	25.	24.	23.	5.	25.	26.	24.	25.	24.	23.	5.
26.	27.	25.	26.	25.	24.	4.	26.	27.	25.	26.	25.	24.	4.
27.	28.	26.	27.	26.	25.	3.	27.	28.	26.	27.	26.	25.	3.
28.	29.	27.	28.	27.	26.	2.	28.	29.	27.	28.	27.	26.	2.
29.	30.	28.	29.	28.	27.	1.	29.	30.	28.	29.	28.	27.	1.
30.	31.	29.	30.	29.	28.	0.	30.	31.	29.	30.	29.	28.	0.
SUM 28.15 25.71 2.46 77432.													
( 715.11 653.11 62.11 2192.63)													

## HYDROGRAPH ROUTING

THIS IS A ROUTING AT DAM PA. 474

	I	JCOMP	IECON	ITYPE	JPLT	JPRY	INAME	ISTAGE	IAUTO
	C	1		O	O	O	O	O	O
		AUG	IRFS	ISAME	IOPT	IPMP	LSTR		
	QLOSS	CROSS	LAG	AMSKK	X	TSK	STORA	ISPRTAY	-I
	0.0	0.0	0	0.0	0.0	0.0	-1242.		
	NSTPS	MSTDCL							
	1	C							
STAGE	1241.80	1245.00	1247.00	1249.20	1251.20	1253.20	1255.2		
	1259.60	1260.98	1262.09	1263.10	1264.00	1264.80			
FLOW	0.0	24.00	32.00	39.00	131.00	138.00	145.0		
	1202.00	2302.00	3440.00	4613.00	5816.00	7045.00			
CAPACITY=	0.	31.	119.	267.	510.	863.			
ELEVATION=	1235.	1245.	1250.	1255.	1260.	1265.			
	CREL	SPEEDID	COOM	EXPW	ELEVEL	COQL	CAREA	EXPL	
	1241.8	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
DAM DATA									
TOTEL	COOD	EXPD	DAMIWD						
1264.3	2.6	1.5	2000.						

PEAK OUTFLOW IS 2473. AT TIME 44.33 HOURS



PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION	STATION	AREA	PLAN	RATIO	1
					1.00
HYDROGRAPH AT	1	1.56	1	2710.	
	(	4.04)	(	76.73)	
ROUTED TO	DAM	1.56	1	2473.	
	(	4.04)	(	70.03)	

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 1261.00 14. 0.	SPILLWAY CREST 1261.00 14. 0.	TOP OF DAM 1264.30 814. 6277.	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
RATIO OF PMF	MAXIMUM RESERVOIR M.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS	
1.00	1261.15	0.0	591.	2473.	0.0	44.33	0.0	



**APPENDIX E**

**REGIONAL GEOLOGY**

PA 474 (PA NO NAME No. 35) DAM  
NDI No. PA 00249, PennDER No. 43-50, SCS No. PA 474


#### REGIONAL GEOLOGY

PA 474 Dam has been constructed across the shallow valley of Saw Mill Run, which is in the Glaciated Section of the Appalachian Plateaus Physiographic Province.

Foundation soils beneath the dam vary in thickness from 14 to 18 feet according to design test borings. Beneath a thin 4 to 5-foot thick mantle of recent alluvium is a layer of glacial till about 10 to 18 feet thick. The glacial material, as described on the boring logs, is largely ML, SM silts and sands with some GM-GP gravel. The water table was high throughout the site.

According to the geologic map on the following page, bedrock units beneath the soil cover are members of the Connoquenessing formation, Pottsville group, Pennsylvania system. The bedrock dips to the southeast (generally upstream) at a rate of approximately 100 feet per mile. The boring logs describe the bedrock as sandstone with some thin shale interbeds.





# LEGEND


PENNSYLVANIAN

Pottsville Group



## MERCER FORMATION

*Mostly dark-gray shale, but contains thin beds of coal and limestone and lenses of sandstone. Generally unimportant as an aquifer, but locally yields may be sufficient for domestic and stock use.*




## CONNOQUENESSING FORMATION

*Medium- to fine-grained gray sandstone containing lenses of dark-gray shale and discontinuous beds of Quakertown coal. Yields moderate quantities of water that is locally high in iron content.*



## SHENANGO FORMATION

*The upper member ( Msu ) is composed of soft medium- to dark-gray shale with interbeds of siltstone and lenses of fine-grained sandstone. Unimportant as an aquifer. The lower member ( MSI ) is composed of medium- to fine-grained light-gray sandstone and medium- to dark-gray shale and siltstone. Yields moderate to large quantities of water that is locally high in iron content at shallow depths.*



## POTTSVILLE UNDIFFERENTIATED

*Sandstones, possibly containing some relatively thick beds of shale; correlation with Connoquenessing, Mercer, and Homewood Formations uncertain. Unimportant as an aquifer.*

MISSISSIPPIAN