

AD-A073 169


NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/G 13/2  
NATIONAL DAM SAFETY PROGRAM. MIDDLE BRANCH DAM (NY 00034), HUFS--ETC(U)  
SEP 78 J J WILLIAMS

DACW51-78-C-0035


NL

UNCLASSIFIED

| OF |  
AD  
A073169



END  
DATE  
FILED  
9-79  
DDC



ADAC73169

HUDSON RIVER BASIN

MIDDLE BRANCH OF CROTON RIVER, PUTNAM COUNTY

NEW YORK

# MIDDLE BRANCH DAM

## PHASE I INSPECTION REPORT

## NATIONAL DAM SAFETY PROGRAM

NY 00034

APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED  
CONTRACT NO. DACW 51-78-C-0035



DEPARTMENT OF THE ARMY  
NEW YORK DISTRICT, CORPS OF ENGINEERS  
26 FEDERAL PLAZA  
NEW YORK, NEW YORK 10007  
AUGUST 1978

79 08 27 028

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DDC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report Middle Branch Dam Hudson River Basin, Putnam County, New York Inventory No. N.Y. 34		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR(s) <b>P</b> John J. Williams P.E.		6. PERFORMING ORG. REPORT NUMBER
8. CONTRACT OR GRANT NUMBER(s) <b>P</b> DACW-51-78-C-0035		9. PERFORMING ORGANIZATION NAME AND ADDRESS O'Brien and Gere Engineers 1301 Buckley Road Syracuse, New York 13221
11. CONTROLLING OFFICE NAME AND ADDRESS New York State Department of Environmental Conservation/ 50 Wolf Road Albany, New York 12233		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza/ New York District, Coff New York, New York 10007		12. REPORT DATE 21 Sept 1978
		13. NUMBER OF PAGES <b>12 160P</b>
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		16. DECLASSIFICATION/DOWNGRADING SCHEDULE <b>D D C REFILED 29 AUG 1979 BULLETP C</b>
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 2c if different from Report) <b>LEVEL</b>		
18. SUPPLEMENTARY INFORMATION 6 National Dam Safety Program. Middle Branch Dam (NY 00034), Hudson River Basin, Middle Branch of Croton River, Putnam County, New York. Phase I Inspection Report		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety Middle Branch Dam National Dam Safety Program Putnam County Visual Inspection Middle Branch of Croton River Hydrology, Structural Stability		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. Middle Branch Dam was judged to be unsafe, non-emergency due to seepage and saturated ground at junction of west abutment and downstream slope of the earth embankment.		

393 970 *Gm*



HUDSON RIVER BASIN

Name of Dam: Middle Branch Dam  
County and State: Putnam County, New York  
Inventory Number: NY 00034

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Prepared by: O'Brien & Gere Engineers, Inc.

For: New York State  
Department of Environmental Conservation

Date: August 17, 1978

79 08 27 028

PHASE I REPORT  
NATIONAL DAM INSPECTION PROGRAM

Name of Dam: Middle Branch Dam

State Located: New York

County Located: Putnam County

Stream: Middle Branch of the Croton River

Date of Inspection: July 17, 1978

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification _____	
By _____	
Distribution/	
Availability Codes	
Dist	Available or special
A	23 CP


ASSESSMENT OF  
GENERAL CONDITIONS


Middle Branch Dam is an earth embankment with a masonry corewall, about 615 feet long and 94 feet high at its maximum section. An ungated spillway and outlet channel, excavated in bedrock, are located west of the structure.

Significant seepage and saturated ground were noted at the junction of the west abutment and the downstream slope of the earth embankment. This condition should be monitored on a regular basis to determine if the flow increases or if discoloration and fines migration develop. The trees and brush growing on the downstream slope near the west abutment have a deleterious effect on the compacted earth embankment. This vegetation should be cut near the ground surface so that conditions of the abutment can be assessed, and the root systems of the trees investigated to determine if they should be removed.

Examination of the results of the hydrologic/hydraulic analysis indicates that the dam would be overtopped by all floods exceeding approximately 58 per cent of the Probable Maximum Flood.

O'BRIEN & GERE ENGINEERS, INC.


  
John J. Williams, P.E.  
Vice President

Approved by:   
Clark H. Benn  
Colonel, Corps of Engineers  
District Engineer

Date: 21 September 1978



OVERALL VIEW OF UPSTREAM SLOPE



OVERALL VIEW OF DOWNSTREAM SLOPE

## TABLE OF CONTENTS

<u>TEXT</u>	<u>PAGE</u>
Section 1 - Project Information	1-4
Section 2 - Visual Inspection	5-6
Section 3 - Hydrology/Hydraulics	7
Section 4 - Structural Stability	8
Section 5 - Assessment, Recommendations/Remedial Measures	9

## FIGURES

- Figure 1 - Regional Vicinity Map
- Figure 2 - Data Table - New York City Reservoirs
- Figure 3 - Flow Diagram for Croton System
- Figure 4 - Geologic Map
- Figure 5 - Plan and Section Drawings of Dam, Spillway and Outlet Works

## PHOTOGRAPHS

## APPENDIX

Field Inspection Report	A1-A7
Hydrologic/Hydraulic Calculations	A8-A20
Previous Inspection Reports	A21-A27

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
NAME OF DAM MIDDLE BRANCH DAM ID# 00034

SECTION I - PROJECT INFORMATION

**1.1      GENERAL**

a. Authority - This report is authorized by the Dam Inspection Act, Public Law 92-367, and has been prepared in accordance with Contract #1467.021 between O'Brien and Gere Engineers, Inc. and the New York State Department of Environmental Conservation.

b. Purpose of Inspection - The purpose of this inspection is to evaluate the structural and hydraulic conditions of Middle Branch Dam and appurtenant structures, and to determine if the Dam constitutes a hazard to human life or property.

**1.2      PROJECT DESCRIPTION (from information supplied by the New York City Department of Environmental Protection)**

a. Description of Dam and Appurtenances - Middle Branch Reservoir is located in southeastern Putnam County and is about  $1\frac{1}{2}$  miles west of the Village of Brewster, New York. The dam is constructed across the Middle Branch of the Croton River which is also blocked by the Croton Falls Dam located about  $2\frac{1}{4}$  miles downstream and to the southwest. The upper reaches of the Croton Falls impoundment extends to the downstream toe of the Middle Branch Dam and forms the stilling pond for outlet works.

Middle Branch Dam is a homogeneous, earth embankment with a masonry corewall. The structure has a maximum height of about 94 feet, is approximately 615 feet long and has a top width of about 50 feet. The upstream face of the dam is about 4.5 horizontal to 1 vertical; the downstream slope is about 3 horizontal to 1 vertical.

The spillway, located west of the embankment, consists of a 100 feet wide ungated flat crested, cut stone weir and an outlet channel.

Discharge from the reservoir is accomplished through two uncontrolled inlets located in a stone masonry intake tower upstream of the embankment. The flow passes through a brick lined, horseshoe shaped tunnel (8 feet by 8 feet) to a vault which houses two 36 inch gate valves. Two conduits, housed in a similarly constructed tunnel, continue downstream and, after passing through a stone masonry gatehouse adjacent to the downstream toe of slope, the two pipes bifurcate to four 20 inch diameter pipes. These pipes continue about 120 feet to the stilling basin where each one terminates as a vertical fountain-type orifice. Refer to Figure 5 for a plan and section drawing of the outlet works.

Middle Branch Reservoir is part of the Croton Water Supply System; the Dam and Appurtenance Structures are owned by the City of New York and operated by the Department of Environmental Protection.

The Middle Branch Dam, originally called Tilly Foster, was designed by The Aqueduct Commissioners, City of New York and was completed in 1878.

b. Size Classification - Middle Branch Reservoir was designed for a storage volume of 4.005 billion gallons (12,300 acre-feet) at the maximum operating pool elevation of 371.55 feet mean sea level (MSL). The dam has a maximum height of 94 feet. Both of these criteria place the structure in the intermediate size category as defined by the Recommended Guidelines for Safety Inspection of Dams.

c. Hazard Classification - Middle Branch Dam is located about  $2\frac{1}{4}$  miles upstream of the Croton Falls Dam. A failure or overtopping of the Middle Branch structure would allow flood waters to discharge into the downstream reservoir. This might cause failure or overtopping of the Croton Falls Dam and result in the possible loss of many lives and extensive property damage. Therefore, the structure is in the high hazard category as defined by the Recommended Guidelines for Safety Inspection of Dams.

### 1.3 PERTINENT DATA (from information supplied by the City of New York, Department of Environmental Protection)

a. Drainage Area - The drainage area of Middle Branch Reservoir is 21.31 square miles. Lake Carmel is included within the drainage area and is located on the Middle Branch of the Croton River about 5 miles upstream of the Middle Branch Dam. The surface area of the reservoir at maximum operating pool (Elevation 371.55) is about 428.2 acres.

b. Discharges - Discharge from the reservoir is accomplished by means of two 36 inch manually operated gate valves located in the outlet gatehouse. Invert elevation of the outlet tunnel at the intake tower is 306.0 feet MSL. The maximum pool elevation of 375.55 feet MSL was recorded on October 16, 1955 and corresponds to a discharge of 2,640 cfs over the spillway.

c. Reservoir Data

Maximum Operating Pool (Reservoir at El. 371.55)

Length - 11,000 feet  
Area - 428 acres  
Volume - 12,300 acre-feet

Top of Dam (El. 380)

Length - 11,050 feet  
Area - 429 acres  
Volume - 16,150 acre-feet

Maximum Pool (PMF El. 382.75)

Length - 11,100 feet  
Area - 430 acres  
Volume - 17,100 acre-feet

d. Dam Data

Type - earth embankment  
Top Elevation - 380 feet  
Height - 94 feet (maximum)  
Streambed elevation at centerline of dam - 303 feet  
Length - 615 feet  
Top Width - 50 feet  
Side Slopes - upstream slope 4.5:1 (horizontal: vertical), downstream slope (3:1)  
Zoning - none  
Impervious Core - 8 feet thick masonry corewall  
Cutoff - none  
Grout Curtain - none

e. Outlet Works - See Section 1.2.a.

f. Engineering Data - The information available for review of Middle Branch Reservoir included the following:

- 1) Data Table - New York City Reservoirs,
- 2) Profile of Flow Diagram for Croton System,
- 3) Plan and Section Drawings of Dam, Spillway and Outlet Works,
- 4) Dam Report by the Conservation Commission, State of New York, dated August 6, 1915,
- 5) "Report of a Structure Impounding Water", State of New York, Department of State Engineer and Surveyor (undated).

#### 1.4 OPERATING AND MAINTENANCE PROCEDURES

a. Operation - Two 36 inch diameter drain pipes, used for drawdown are controlled by means of gate valves located in the gatehouse at the downstream toe. According to Mr. John Birrell, Section Engineer, New York City Department of Environmental Conservation, the valves are exercised every six months. Reservoir elevation readings are taken daily.

b. Maintenance of Dam and Operating Facilities  
According to Mr. Birrell, maintenance is performed on a "most needed" basis.

c. Flood Warning System - According to Mr. Birrell, inspection crews are placed on round the clock duty during periods of high runoff. Reservoir levels or unusual observations are reported to Mr. Birrell and the Deputy Chief Engineer. Mr. Birrell would contact local police and the Civil Defense for evacuation of downstream areas in the event of impending failure or overtopping.

## SECTION 2 - VISUAL INSPECTION

### 2.1 FINDINGS

a. General - The field inspection of the Middle Branch Dam took place on July 17, 1978. The reservoir water surface elevation was about 370 feet MSL during the inspection. No underwater areas were inspected.

b. Dam - The riprap protecting the upstream slope is composed of subangular stone ranging from 6 inches to 2 feet in diameter. A number of shallow depressions exist in the upstream slope protection giving the surface a gently undulating character. A copse of small trees and brush, on an otherwise clear slope, is growing at the junction of the riprap and grass near the west abutments.

The grass covering the upper portion of the upstream slope, crest of embankment and downstream slope is mowed a few times a year according to Mr. John Birrell, Section Engineer, New York City, Department of Environmental Protection. No misalignments were observed on the downstream slope. However, a large area of saturated ground and several springs discharging rust-colored water were noted along the west abutment. This wet condition extends from about 20 feet below the crest of the dam to the toe of the downstream slope and is characterized by a lush growth of trees and brush. The seepage has cut a channel which conducts the flow down the intersection between the downstream slope and natural valley abutment. The total visible discharge at the toe of slope was estimated to be about 0.5 cubic feet per second (cfs) at time of inspection. The eastern end of the downstream slope and abutment area is also covered with trees and underbrush but there is no evidence of seepage or wet ground conditions. The outlet gatehouse is constructed within the downstream slope at the east abutment. The riprap protecting the downstream toe consists of large, flat stones (1 to 3 feet in diameter). Some grass and bushes are growing between the stones.

c. Intake Tower and Appurtenances - The stone masonry of the intake tower is in very good condition. According to Mr. Birrell, there are stoplog slots for each of the two inlets in the tower; the access hatch to the interior of the tower was bolted down at time of inspection. Mr. Birrell stated that the valves in the vault have not been operable for twenty years and that an attempt to operate them a few years ago was unsuccessful. The

downstream outlet gatehouse appeared to be in good condition; however, one of the two valves housed in the structure was discharging water in a fountain-like fashion from its stuffing box. Mr. Birrell stated that attempts to repack the valve have been unsuccessful and that it is scheduled for further repairs.

The cut stone blocks forming the spillway crest appear in good condition, but have been slightly undermined. Although the reservoir level was about six inches below the spillway crest at time of inspection, the joints were allowing some discharge into the outlet channel. The upper reach of the discharge channel has a very mild slope and supports a heavy growth of brush. The bedrock, which forms the base of the outlet channel, provides a non-uniform surface for energy dissipation at the exit of the spillway channel.

d. Reservoir Area - The natural ground surrounding the reservoir has a moderate to steep slope and is well covered with trees and brush.

### SECTION 3 - HYDROLOGY/HYDRAULICS

According to the Recommended Guidelines for Safety Inspection of Dams, the Spillway Design Flood is the Probable Maximum Flood (PMF). The PMF was calculated from the 6 hour Probable Maximum Precipitation (PMP), using a loss rate of 0.1 inches per hour. The flood hydrograph was constructed from the Snyder unit hydrograph using average coefficients. Flood routing through the reservoir was performed assuming the gated outlets to be closed and the initial water surface elevation equal to the crest of the spillway. The peak inflow and outflow rates were calculated as 18,900 cfs and 18,200 cfs respectively. The peak outflow corresponds to a stage of 11.2 feet above the spillway crest (2.2 feet above the top of dam). Inflow and outflow peak rates for one-half of the PMF were calculated as 9,490 cfs and 7,300 cfs respectively. The spillway capacity was determined to be 8,910 cfs. Although the spillway capacity is insufficient to pass the PMF, it will safely discharge at least  $\frac{1}{2}$  PMF.

A drawdown analysis was performed assuming discharge from the two 36 inch diameter pipes and the starting water surface at the spillway crest, and 2 cfs per square mile inflow (42.6 cfs). According to the calculations, complete drawdown of the reservoir would take 55 days.

## SECTION 4 - STRUCTURAL STABILITY

### 4.1 VISUAL OBSERVATIONS AND DATA REVIEW

Visual inspection of the Middle Branch embankment did not reveal evidence of misalignments or settlement in the crest and slopes of the dam. However, the discolored seepage and saturated ground observed at the west abutment indicate the existence of uncontrolled seepage and possible fines migration which could lead to an unstable condition.

No design data was made available for Middle Branch Dam.

### 4.2 GEOLOGY AND SEISMIC STABILITY

Middle Branch Reservoir is located in the New England Uplands physiographic province. The rocks in this province are either metamorphic or igneous, and the land forms show a close relationship to the relative durability of these rocks. The embankment was constructed across the Middle Branch of the Croton River and is founded upon Precambrian metamorphic biotite and granitic gneiss. The spillway and discharge channel were constructed in the bedrock forming the north valley slope and are separated from the west dam abutment by an outcrop of the same formation.

No fault zones or lineaments are known to exist in the vicinity of the reservoir. The structure is located in Seismic Risk Zone 1 of the Seismic Zone Map of Contiguous States and it appears that static stability conditions are adequate for earthquakes.

## SECTION 5 - ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES

### 5.1 ASSESSMENT

Visual inspection and analysis of the available information reveals that the embankment has a potential piping problem.

The uncontrolled seepage and saturated ground along the downstream slope near the west abutment is indicative of possible fines migration through the embankment or along the contact between the structure and natural valley abutment. It is also possible that the rust colored seepage is from discharge channels which may have formed through joints in the bedrock abutment. The discoloration may be attributable to iron oxides resulting from chemical weathering of ferromagnesian minerals contained within the local bedrock formation.

The root systems of the trees and brush growing on the downstream face near the west abutment have a deleterious effect upon the compacted materials in the embankment and provide seepage paths which may lead to future piping and failure of the structure.

### 5.2 RECOMMENDATIONS/REMEDIAL MEASURES


The uncontrolled seepage on the downstream slope of the west abutment should be monitored on a regular basis to see if flow increases or if fines migration can be detected. If either of these conditions develop, a subsurface investigation program should be initiated at several sections of the embankment with emphasis in the west abutment areas. The investigation should include, but not be limited to, the determination of the composition and in situ properties of the embankment, corewall and foundation materials, and to detect possible fines migration. Results of this program should be used to establish if the materials are satisfactory as designed and constructed; and to perform seepage and stability analyses of the embankment.

The trees and brush growing on the western portion of the downstream slope should be cut near the ground surface so that conditions at this location can be further assessed and monitored on a regular basis. A further investigation should be made to determine the extent of the root systems before remedial measures can be recommended.

The inoperable valves in the vault and the leaking gate valve in the gatehouse should be repaired.

**FIGURES**

P



# **FIGURE 1**

## **REGIONAL VICINITY MAP**

## CROTON SYSTEM

DATA

Name of Reservoir	Location		Drainage Area		Date Rec'd.	KIND
	Town	County	Sq Mi	Includes Items	Sec Co	
1 BOYD CORNERS	KENT	PENN.	23.46	1	3/3	MASONRY, EARTH
2 BARRETT'S POND			25	2	3/3	EARTH
3 LAKE OLENE DA	CARMEL		0.60	3	6/0	EARTH
4 WEST BRANCH (Carmel)	"		42.87	1, 104	3/3	EARTH, MASONRY
5 WEST BRANCH	"					
6 MIDDLE BRANCH	SOUTHEAST		21.31	3	1/0	EARTH, MASONRY
7 BOO BROOK	"		3.67	6	1/0	
8 EAST BRANCH (3000M)	"		80.20	6, 67	1/0	MASONRY, EARTH
9 CROTON FALLS (DYEING)	"		87.50	6, 10	1/1	EARTH, CONCRETE
10 LAKE O'LEAD	CARMEL		0.02	9	1/0	EARTH
11 CROTON FALLS	"		188.64	4, 5, 8, 9, 10	1/1	CYCLOPEAN MASONRY
12 LAKE K.R.C	"		204	11	1/0	EARTH
13 AMANWALK	SOMERS - WESTCHESTER		14.15	10, 10, 2	1/0	EARTH, MASONRY
14 TITICUS	NORTH SALEM		29.33	13	1/0	MASONRY, EARTH
15 CROSS RIVER	BEDFORD		29.00	14	1/0	CYCLOPEAN MASONRY
16 MUSCOOT	SOMERS & BEDFORD		315.73	10, 10, 15	1/0	MASONRY
17 NEW CROTON	CORTLAND		375.00	1, 10, 16	1/0	MASONRY

X Controlled Lakes

CROTON TOTALS

## CATSKILL SYSTEM

1 ASHOKAN	OLIVE BRIDGE - ULSTER	29.00	1	2.5	MASONRY
2 SCHOHARIE	31.804 - GREENE	34.00	2	12.6	MASONRY
CATSKILL TOTALS					

## DELAWARE SYSTEM

1 NEVERSINK	NEVERSINK	SULLIVAN	0.90	1	1.95	EARTH, CONCRETE
2 PEPACTON	COLCHESTER MOUNTAINS & MIDDLETON	DELAWARE	372.0	2	1.95	"
3 CANNONVILLE	DEPOS, TOWNS, & WALTON	DELAWARE	4500	3	1.95	"
4 RONDOUT	WAWARSING, NEVERSINK	ULSTER	35.00	1, 10, 4	1.95	CONCRETE
DELAWARE TOTALS						

## KENSICO RESERVOIR

KENSICO	NO. 2 CISTERNS - WESTCHESTER	13.33	1.95	1.95	MASONRY
---------	------------------------------	-------	------	------	---------

PERTAINING TO N.Y. CITY RESERVOIRS

THE IMPOUNDING RESERVOIRS BELONG TO THE  
OPERATING LEVEL & 560.0 BILL GAL. (AVAILABLE)

NAME OF CEM	Capacity (Bil. Gal.)	Area of Water Surface in Sq. Miles	Length of Storage M. & S.	Elev. of Spillway M.S.L. Sandy Hook Foot	Elev. of Top of Max Depth Min. Open Land Foot	Elev. of Sill or Outlet Min. Depth Outfall Foot	Depth to Spillway 10 Outfall Feet
WATER	1.696	0.464	296.9	62	500.05	536.7	43.4
	0.170	0.100	87.1	..4	778.55	768.6	10.0
CORE & SILL	0.163	0.264	160.9	22	504.55	449.6	5.0
WATER	10.070	1.092	1002.0	156	503.2	455.0	47.0
CORE	4.005	0.609	428.2	602	571.55	466.1	51.1
"	4.800	0.620	399.0	49	418.55	363.1	51.5
WATER	5.243	0.698	596.0	105	410.55	351.0	65.0
WATER	0.006	0.240	153.6	42	309.55	279.0	30.0
MASONRY	0.360	0.191	122.2	21	496.55	400.6	16.0
CORE	14.192	1.600	1002.4	180	504.4	214.0	95.0
"	0.365	0.158	101.1	31	502.55	364.0	10.0
CORE	6.692	0.947	606.1	85	399.55	354.6	65.0
WATER	7.167	1.046	669.4	81	324.5	249.0	75.0
MASONRY, CONCRETE FACES	10.300	1.202	760.2	124	329.55	234.6	100.0
"	4.914	1.022	1166.1	350	190.55	164.6	90.0
	25.702	5.350	2259.2	380	193.55	194.6	360
	94.637	06.6	15.531	9911.0	177.52		

127.050	122.0	12.99	6915.2	40.2	840.00	UNKNOWN	308.88	37.78
19.503	17.0	1.70	145.0	16.5	1130.0	"	1050.0	00.00
147.441	140.5	14.73	9460.2	56.5				

CONCRETE CORE	35.466	34.9	2.9	1470	16.5	1440.00	1319.00	13.400	126.00
"	143.701	140.2	0.9	5700	53.5	1230.00	1152.00	1143.00	137.00
SOIL FILL	96.726	95.7	7.5	4600	53.5	01150.00	1090.00	1035.00	0115.00
CONCRETE CORE	50.040	49.6	3.25	2030	17.0	840.00	723.00	720.00	120.00
"	325.941	320.4	21.95	4050	143.5	0.00 HEIR HIGH "			

4 SAFETY OR INTERIM STORAGE PES FOR ALL OF THE CUNY & DELAWARE SUPPLIES

30573	1440.00	347	2210.3	330	357.00	1130.00	1295.92	67.63
-------	---------	-----	--------	-----	--------	---------	---------	-------

THE CROTON, CATSKILL & DELAWARE SYSTEMS TOTALLING 547.5 B/L GAL. ABOVE MIN.  
AVAILABLE ABOVE SILL. AN ADDITIONAL 30.6 BILL. GAL. IS STORED IN A SAFETY STORAGE RESERVOIR.

Wk #	Total Storage in Billion Gallons	Length of S.C. Way Feet	Max Depth Below Spillway Feet	Max Hgt of Main Dm		Width of Dam Feet	Length of Dam Feet			
				Above Lowest Foundation Feet	Above N.R.C. Surface Feet		Top	Bottom	Total	Masonry Portion
4		1350		700	57.0	6.60	5360	6700	6700	
0										
0		2600		660	620	15.00	307.50	1794.5	2600.0	
1		AC 52.00		65.0	500	25.00	240.00	741.0		
1		1000		99.0		50.00	600.00	615.0	1000.0	
3	0			116.88	53.8	32.88	793.88	1338.8		
0	x	5000		98.0	70.0	12.00	53.00	1100.0	500.0	
0	2	10000		51.0	45.0	15.00	240.00	2190.0	1000.0	
0	3	7000		179.0	113.0	23.00	118.00	1300.0	1100.0	
0		500			82.0	55.00	656.00	1270.0	50.0	
0		2300		135.0	107.0	25.70	75.21	1312.5	237.0	
0		2400		170.0	126.0	23.00	118.50	1080.0	670.0	
0		9500		58.0		4.00	40.00	1150.0	1130.0	
0	1	10000		247.0	174.0	10.00	208.00	2165.0	2160.0	

REMA  
Most of the Cr  
carried by the  
Aqueduct

3	4.197	950.0	72.00	252.0	210.0	26.55	200.00	4650.0	1000.0
00		1324.0	150.0	102.0	155.0	15.00	130.00	2200.0	2000.0

Schoharie Water  
Tunnel to P... to  
enter the Catskill

.00	1.600	600.0	.75.00	345.0	195.0	60.00	1392.00	2020.0	NONE
00	6.000	000.0	100.00	304.0	204.0	60.00	1460.00	2450.0	"
00	1.092	3240.0	76.00	196.0	179.0	45.00	1312.00	2000.0	"
00	1.092	1560.0	95.70	196.0	179.0	45.00	1312.00	2000.0	"
00	2.387	600.0	175.00	375.0	195.0	60.00	1392.00	2400.0	"

Neversink, Pepe  
are conveyed to  
& W. Delaware  
Thence all Fou

63 UNKNOWN	50.0	155.50	307.0	163.0	23.00	235.00	1693.0	1643.0
------------	------	--------	-------	-------	-------	--------	--------	--------

of the Croton S  
plus pumpage  
Falls flows in

2 1'

3

SICO  
SICO

Comp J.J.O  
CROTON J.P.D.  
Crown J.P.D.

Marks

Croton Supply is  
the New Croton

The New Croton

is conveyed by the Shandaken  
Reservoir. Thence both supplies  
enter the Aqueduct. Hence both supplies  
enter the Aqueduct.


Racoon & Cannonsville supplies  
via the Neversink, East Delaware  
Channels to the Neversink Reservoir  
or supplies enter the Del. Aqueduct,  
or supplies enter the Del. Aqueduct.

## FIGURE 2

Supply, all of the West Branch  
Upper Cross River & Croton  
to service the  
West Branch & Service Croton

Acc NS

H




#### LEGEND

- = NATURAL WATER COURSE.
- - - = TUNNEL AQUEDUCT.
- = GRADE AQUEDUCT.

#### NOTE

ELEVATIONS OF RESERVOIRS ARE AT MASONRY CREST OF SPILLWAY.  
 FIGURES SHOWN IN RESERVOIRS ARE CAPACITIES IN BILLION GALLONS.


ELEVATIONS REFER TO M.S.L. SANDY HOOK.



CITY OF NEW YORK  
BUREAU OF WATER SUPPLY

## PROFILE OF FLOW DIAGRAM FOR CROTON SYSTEM


FIGURE 3



Scale: 1 inch = 1.7 miles

- |  |                                     |  |             |
|--|-------------------------------------|--|-------------|
|  | bqpc - biotite, quartz, plagioclase |  | Xi - marble |
|  | Am - Amphibolite                    |  |             |
|  | bg - biotite, granitic gneiss       |  |             |
|  | qtcs - quartz, feldspar, gneiss     |  |             |
|  | Xm - schistose gneiss               |  |             |
|  | Xgb - gabbro, hornblende, gneiss    |  |             |

**Figure 4**  
Geologic Map






FIGURE 5

2

APPENDIX

**PHOTOGRAPHS**



SOUTHEAST ABUTMENT AND DOWNSTREAM SLOPE



TOE OF DOWNSTREAM SLOPE



WATER DISCHARGING FROM  
36 INCH GATE VALVE



HEAVY OVERGROWTH AT NORTHWEST ABUTMENT

**FIELD INSPECTION  
REPORT**

Check List  
Visual Inspection  
Phase 1

Name Dam	Middle Branch Dam	County	Putnam	State	New York	Coordinator	-----
Date (s) Inspection	July 17, 1978	Weather	Overcast	Temperature	75°		
Pool Elevation at Time of Inspection	370	M.S.L.	Tailwater at Time of Inspection	-----	M.S.L.		

Inspection Personnel:  
A-1  
Mr. George Elias  
Mr. David Campbell  
Mr. Steve Snider

Recorder  
Mr. Steve Snider

Accompanied by:

Mr. John Birrell - Section Engineer, New York City Department of Environmental Protection  
Mr. Edward Stoorza - Section Foreman, New York City Department of Environmental Protection

**EMBANKMENT**

<b>VISUAL EXAMINATION OF</b>	<b>OBSERVATIONS</b>	<b>REMARKS OR RECOMMENDATIONS</b>
SURFACE CRACKS	None noted.	None.
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None noted.	None.
SLoughing or Erosion of embankment and abutment slopes	None noted.	None.
Vertical and horizontal alignment of the crest	None noted.	None.
RIPRAP FAILURES	None noted.	None.

EMBANKMENT

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

JUNCTION OF EMBANKMENT  
AND ABUTMENT, SPILLWAY  
AND DAM

Some seepage noted at the west  
abutment. Ground surface was  
moist and saturated in some  
locations.

A study should be undertaken  
to determine the cause and  
source of seepage.

ANY NOTICEABLE SEEPAGE

A-3

See above.

STAFF GAGE AND RECORDER

N/A

DRAINS

N/A

OUTLET WORKS	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
VISUAL EXAMINATION OF CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	N/A	None.
INTAKE STRUCTURE	Stone deck of intake tower prohibits access to interior of structure.	Repair gate valve.
OUTLET STRUCTURE	One of the gate valves was discharging water from its stuffing box.	A-4
OUTLET CHANNEL	Discharge from the outlet conduits flows directly into the Croton Falls Reservoir.	None.
EMERGENCY GATE		See "Outlet Structure"

RESERVOIR

VISUAL EXAMINATION OF

SLOPES

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

No problems noted.

None.

SEDIMENTATION

None noted.

None.

VISUAL EXAMINATION OF		UNCATED SPILLWAY	REMARKS OR RECOMMENDATIONS
	OBSERVATIONS		
CONCRETE WEIR	The cut stone blocks forming the spillway crest have been slightly undermined.	None.	
APPROACH CHANNEL	No problems noted.	None.	
DISCHARGE CHANNEL	A-6	Heavy growth of brush on upper reach of channel.	
BRIDGE AND PIERS		N/A	

ITEM	REMARKS
MONITORING SYSTEMS	Personnel from the New York City Department of Environmental Protection operate and monitor operation of the reservoir.
MODIFICATIONS	None.
HIGH POOL RECORDS	Maximum pool of record was 375.55 feet MSL recorded on October 16, 1955.
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None available. A-7
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None available.
Maintenance OPERATION RECORDS	None available.

**HYDROLOGIC/HYDRAULIC CALCULATIONS**

JUSTIN & COURTNEY, INC.  
 Division of O'Brien & Gere Engineers, Inc.  
 PHILADELPHIA, PA

NAME OF CLIENT NYSDEC

PROJECT MIDDLE BRANCH RESERVOIR

SHEET NO. 1 OF 8

DATE 7/19/78

COMP. BY LW

CHECKED BY DBC

PMP east of the  $105^{\circ}$  meridian for an area of 10 sq. miles and 6 hour duration is 24" according to Design of Small Dams, SCS, Fig. 15

$$\text{Drainage Area} = 21.31 \text{ sq. miles}$$

Reduction in order to provide for imperfect "fit" of storm isohyetal patterns to the shape of a particular basin.

$$\text{Reduction Factor} = 18.6\%$$

$$6\text{-hr. PMP} = 24 \text{ inches} * 0.819 = 19.536$$

Figure 16, Zone 1:

$$6 \text{ hr. PMP} = 19.536 * 0.92 = 18.0 \text{ inches}$$

$$12 \text{ hr. PMP} = 19.536 * 1.04 = 20.3 \text{ inches} \rightarrow -18.0 = 2.3$$

$$24 \text{ hr. PMP} = 19.536 * 1.13 = 22.0 \text{ inches} \rightarrow -20.3 = 1.7"$$

$$\begin{aligned} t_p &= C_t (L + L_{ca})^{0.3} \\ &= 2.0 (15 * 7)^{0.3} = 8.08 \text{ hr.} \end{aligned}$$

$$t_r = t_p / 5.5 = 1.47 \text{ hrs.} \quad \text{Use: } t_R = 1.5 \text{ hrs.}$$

$$t_{pr} = t_p + 0.25(t_R - t_r) = 8.08 + 0.25(1.5 - 1.47) = 8.09 \text{ hrs.}$$

JUSTIN & COURTNEY, INC.  
 Division of O'Brien & Gere Engineers, Inc.  
 PHILADELPHIA, PA

SHEET NO. 2 OF 8

DATE 7/19/78

COMP. BY LW

CHECKED BY DBC

NAME OF CLIENT NYSDEC

PROJECT MIDDLE BRANCH RESERVOIR

6 HR. - 18 inch PMP Distribution

<u>Time (hrs)</u>	<u>Fig.18 (Zone C) % of 6 hr. PMP</u>	<u>Accumulate PMP</u>	<u>Increment</u>
0-1.5	57.0	10.3	10.3
1.5-3.0	76.0	13.7	3.4
3.0-4.5	88.0	15.9	2.2
4.5-6.0	100.0	18.0	2.1
6.0-7.5			0.6
7.5-9.0			0.6
9.0-10.5			0.6
10.5-12.0			0.5
12.0-13.5			0.3
13.5-15.0			0.2
15.0-16.5			0.2
16.5-18.0			0.2
18.0-19.5			0.2
19.5-21.0			0.2
21.0-22.5			0.2
22.5-24.0			0.2

JUSTIN &amp; COURTNEY, INC.

Division of O'Brien &amp; Gere Engineers, Inc.

PHILADELPHIA, PA

SHEET NO. 3 OF 8NAME OF CLIENT NYSDECDATE 7/19/78PROJECT MIDDLE BRANCH RESERVOIRCOMP. BY LWCHECKED BY DBC

## THIRD QUARTILE DISTRIBUTION

<u>Time (hrs.)</u>	<u>Adjusted PMP Increments</u>	<u><math>\leq</math> PMP</u>
0-1.5	0.2	0.2
1.5-3.0	0.2	0.4
3.0-4.5	0.2	0.6
4.5-6.0	0.2	0.8
6.0-7.5	0.2	1.0
7.5-9.0	0.3	1.3
9.0-10.5	0.6	1.9
10.5-12.0	0.6	2.5
12.0-13.5	2.1	4.6
13.5-15.0	3.4	8.0
15.0-16.5	10.3	18.3
16.5-18.0	2.2	20.5
18.0-19.5	0.6	21.1
19.5-21.0	0.5	21.6
21.0-22.5	0.2	21.8
22.5-24.0	0.2	22.0

JUSTIN & COURTNEY, INC.  
 Division of O'Brien & Gere Engineers, Inc.  
 PHILADELPHIA, PA

NAME OF CLIENT NYSDEC

SHEET NO. 4 OF 8

PROJECT MIDDLE BRANCH RESERVOIR

DATE 7/20/78

COMP. BY LW

CHECKED BY DBC

Discharge capacity for outlet pipes:

$$H = \frac{V^2}{2g} + K_e \frac{V^2}{2g} + K_b \frac{V^2}{2g} + K_v \frac{V^2}{2g} + h_f$$

$H$  = available head

$K_e$  = entrance loss coefficient

$K_b$  = bend loss coefficient

$K_v$  = valve loss coefficient

$$h_f = 2.87 n^2 \frac{LV^2}{d^{4/3}} \quad (6-262) \text{ Brater}$$

$$= 2.87 (0.013)^2 \frac{500 (2g)}{\left(\frac{30}{72}\right)^{4/3}} \cdot \frac{V^2}{2g} = 4.6 \frac{V^2}{2g}$$

$$K_e = 0.5 \quad K_b = 0.08 \quad K_v = 0.07$$

$$\begin{aligned} H &= 6.25 \frac{V^2}{2g} \\ &= 6.25 \cdot \frac{Q^2}{27g \left(\frac{30}{72}\right)^2} = 0.0049427 Q^2 \end{aligned}$$

$$Q = 14.1 H^{1/2}$$

JUSTIN & COURTNEY, INC.  
 Division of O'Brien & Gere Engineers, Inc.  
 PHILADELPHIA, PA

SHEET NO. 5 OF 8

NAME OF CLIENT NYSDEC

DATE 7/20/78

PROJECT MIDDLE BRANCH RESERVOIR

COMP. BY LW

CHECKED BY DBC

Area of water surface at Spillway Crest is 428.2 acres

$\Delta H$ (ft.) Above spillway crest	$Q_{\text{spillway}}$ $(3.3)/100 H^{3/2}$	STORAGE (A-F) Above spillway crest	$Q = (3.3) 615 (H - q)^{3/2}$	$\Sigma Q$
0	0	0	0	0
1	330	428.2	0	330
2	933	856.4	0	933
3	1715	1284.6	0	1715
4	2640	1712.8	0	2640
5	3690	2141.0	0	3690
6	4850	2569.2	0	4850
7	6112	2997.4	0	6112
8	7467	3425.6	0	7467
9	8910	3853.8	0	8910
10	10436	4282.0	2030	12466
11	12039	4710.2	5740	17779
12	13718	5138.4	10546	24264

JUSTIN & COURTNEY, INC.  
Division of O'Brien & Gere Engineers, Inc.  
PHILADELPHIA, PA

SHEET NO. 6 OF 8


NAME OF CLIENT NYSDEC

DATE 8/16/78

PROJECT MIDDLE BRANCH RESERVOIR

COMP. BY SHS

CHECKED BY DBC



JUSTIN & COURTNEY, INC.  
Division of O'Brien & Gere Engineers, Inc.  
PHILADELPHIA, PA

SHEET NO. 7 OF 8

DATE 7/20/78

COMP. BY LW

CHECKED BY ASPC

NAME OF CLIENT NYSDEC

PROJECT MIDDLE BRANCH RESERVOIR

$$\begin{aligned} \text{Capacity} &= 4.005 \text{ Billion gallons} \\ &= 4005 \text{ Million gallons} \\ &= 4005 (3.0689) \text{ Acre-Feet} \\ &= 12,291 \text{ A-F} \end{aligned}$$

Size Classification - Intermediate

Storage :  $1000 \leq 12,291 < 50,000$  A-F

HEIGHT :  $40 \leq 94 < 100$  Feet

Maximum spillway capacity without overtop the Dam is  
8910 cfs; about 74% of PMF. Outflow Peak Discharge

JUSTIN & COURTNEY, INC.  
 Division of O'Brien & Gere Engineers, Inc.  
 PHILADELPHIA, PA

SHEET NO. 8 OF 8

DATE 8/1/78

COMP. BY DBC

CHECKED BY REH


NAME OF CLIENT NYSDEC

PROJECT MIDDLE BRANCH RESERVOIR

Depth - spillway to outlet = 61 feet

Volume of reservoir = 12,291 acre-feet

$$Q = 2(14.1) H^{0.5} \quad Q_B (\text{base flow}) = 2(\text{cfs/sq.mile}) 21.3 (\text{sq.mile}) \\ = 42.6 \text{ CFS}$$



$$V = 12291 = (428.2 + A_2)/2(20) + A_2/2(41)$$

$$A_2 = 262.6 \text{ acres}$$

<u>(ft.)</u> <u><math>\Delta H</math></u>	<u>(ft.)</u> <u><math>H_{Avg.}</math></u>	<u>(cfs)</u> <u><math>Q_{Avg.}</math></u>	<u>(cfs)</u> <u><math>Q_{Net}</math></u>	<u>(acres)</u> <u>Avg. Area</u>	<u>(hrs.)</u> <u><math>\Delta t</math></u>	<u>(hrs.)</u> <u><math>\Sigma \Delta t</math></u>
10	56	211	168	386.8	278	278
10	46	191	148	304.0	249	527
10	36	169	126	231.0	222	749
10	26	144	101	167.0	200	949
10	16	113	70	102.0	176	1125
11	5.5	66	23	35.0	203	1328

$\therefore$  TIME OF DRAWDOWN =  $1328/24 \approx 55$  Days  
 A-15

\*\*\*  
MDC-1 VERSION DATED JAN 1973  
UPDATED AUG 74  
CHANGE NO. 01  
\*\*\*

NATIONAL DAM INSPECTION PROGRAM  
MIDDLE BRANCH RESERVOIR  
PMF HYDROGRAPH

	N2	NMR	NMIN	DAY	THR	TMIN	MTRC	IPLT	IPRT	NSTAN
50	1	30	1	0	0	0	0	0	2	0
		JOPER	NMT							
		5	0							

MULTI-PLAN ANALYSES TO BE PERFORMED  
NPLAN= 1 NRTD= 5 LRTD= 1  
RITOS= .20 .60 .80 1.00

A-16

SUB-AREA RUNOFF COMPUTATION									
ISIA#	ICOMP	IECON	ITAPE	JPLT	JPR	ITNAME			
1	0	0	0	0	0				
HYDROGRAPH DATA									
IHYDG	IJNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
0	1	21.31	0.00	0.00	0.00	0.000	0	0	0
PRECIP DATA									
	NP	STORM	DAJ	DAK					
	16	0.00	0.00	0.00					
		PRECIP PATTERN							
10.30	.20	.20	.20	.20	.30	.60	.60	2.10	3.40
	2.20	.60	.50	.20	.20				
LOSS DATA									
STRKR	DLTR	RTOFR	ERAIN	STRKS	RTOK	STRTL	CNSTL	ALSMX	RTIMP
0.00	0.00	1.00	0.00	0.00	1.00	0.00	0.10	0.00	0.00
UNIT HYDROGRAPH DATA									
TP=	8.09	CP=	.63	NTA=	0				
RECEDITION DATA									
STRTD=	0.00	QRCSD=	0.00	QTDR=	1.00				
APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE IC= 6.30 AND R= 4.69 INTERVALS									
UNIT HYDROGRAPH 30 END-OF-PERIOD ORDINATES. LAG= 9.07 HOURS. CP= .63 VOL= 1.00									
76.	277.	545.	614.	1006.	1072.	985.	815.	663.	540.
40.	358.	292.	238.	193.	158.	128.	104.	85.	69.
56.	46.	37.	30.	25.	20.	16.	13.	11.	9.
END-OF-PERIOD FLOW									
TIME	RAIN	EXCS	COMP	0					
1	1.30	.20	.05	4.					

1	7 30	.20	.05	136.
1	8 60	.30	.15	197.
1	10 30	.60	.45	297.
1	11 60	.60	.45	475.
1	13 30	2.10	1.95	868.
1	14 60	3.40	3.25	1756.
1	16 30	10.30	10.15	3693.
1	17 60	2.20	2.05	7553.
1	19 30	.60	.45	11906..
1	20 60	.50	.35	15894.
1	22 30	.20	.05	10450.
1	23 60	.20	.05	18976.
2	1 30	0.00	0.00	17464.
2	2 60	0.00	0.00	14846.
2	4 30	0.00	0.00	12270.
2	5 60	0.00	0.00	10082.
2	7 30	0.00	0.00	8233.
2	8 60	0.00	0.00	6710.
2	10 30	0.00	0.00	5465.
2	11 60	0.00	0.00	4450.
2	13 30	0.00	0.00	3624.
2	14 60	0.00	0.00	2951.
2	16 30	0.00	0.00	2403.
2	17 60	0.00	0.00	1957.
2	19 30	0.00	0.00	1593.
2	20 60	0.00	0.00	1297.
2	22 30	0.00	0.00	1056..
2	23 60	0.00	0.00	860.
3	1 30	0.00	0.00	700.
3	2 60	0.00	0.00	569.
3	4 30	0.00	0.00	463.
3	5 60	0.00	0.00	376.
3	7 30	0.00	0.00	303.
3	8 60	0.00	0.00	244.
3	10 30	0.00	0.00	186.
3	11 60	0.00	0.00	126.
3	13 30	0.00	0.00	30..
3	14 60	0.00	0.00	9.
3	16 30	0.00	0.00	6.
3	17 60	0.00	0.00	1.
3	19 30	0.00	0.00	0.
3	20 60	0.00	0.00	0.
3	22 30	0.00	0.00	0.
3	23 60	0.00	0.00	0.
4	1 30	0.00	0.00	0.
4	2 60	0.00	0.00	0.

SUM 22.00 19.60 178038.

2FS INCHES AC+FI	PEAK 10976.	6-HOUR 17696.	24-HOUR 10174.	72-HOUR 3726.	TOTAL 178036.	VOLUME
						1 FOR PLAN 1. R110 1
1.	6.	9.	17.	39.	95.	174.
778.	1511.	2381.	3179.	3690.	3493.	351.
1647.	1342.	1093.	890.	725.	491.	2016.
211.	172.	140.	114.	93.	61.	259.
6.	2.	1.	0.	0.	0.	0.

A-17

HYDROGRAPH AT STA 1 FOR PLAN 1, RT10 2					
2.	7.	18.	34.	54.	119.
1555.	3021.	4762.	6350.	7380.	7590.
3293.	2684.	2186.	1780.	1449.	1180.
422.	364.	210.	228.	165.	150.
12.	6.	2.	0.	0.	0.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

2ES	7590.	7076.	4070.	1490.	71535.
INCHES					
AC-FT					

HYDROGRAPH AT STA 1 FOR PLAN 1, RT10 3

2.	11.	27.	51.	82.	116.	178.	205.	521.	1053.
2333.	4532.	7199.	3537.	11070.	11385.	10679.	8908.	7374.	6049.
4940.	4026.	3279.	2670.	2176.	1770.	1442.	1174.	956.	775.
634.	516.	420.	342.	278.	226.	162.	146.	111.	76.
13.	6.	3.	1.	0.	0.	0.	0.	0.	0.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

2ES	11345.	10618.	6104.	2235.	107303.
INCHES					
AC-FT					

HYDROGRAPH AT STA 1 FOR PLAN 1, RT10 4

3.	14.	36.	69.	109.	158.	238.	380.	694.	1404.
3111.	6043.	9525.	12716.	14760.	15180.	13971.	11877.	9832.	8065.
6586.	5368.	4372.	3560.	2899.	2361.	1922.	1565.	1275.	1038.
845.	688.	560.	455.	371.	301.	242.	195.	147.	101.
24.	7.	3.	1.	0.	0.	0.	0.	0.	0.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

2ES	15160.	14157.	8139.	2981.	143070.
INCHES					
AC-FT					

HYDROGRAPH AT STA 1 FOR PLAN 1, RT10 5

6.	16.	45.	86.	136.	197.	297.	475.	868.	1756.
3089.	7553.	11906.	15894.	18450.	18976.	17464.	14846.	12290.	10082.
6233.	6710.	5465.	4650.	3624.	2951.	2403.	1957.	1593.	1297.
1056.	860.	700.	569.	463.	376.	303.	246.	184.	126.
30.	9.	4.	1.	0.	0.	0.	0.	0.	0.

A-18

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

2ES	19976.	17696.	10174.	3726.	178838.
INCHES					
AC-FT					

HYDROGRAPH ROUTING

I1IAQ	I1COMP	I1CON	I1GEON	I1TAPE	JPLT	JPT1	JPT2	INAME	0
-------	--------	-------	--------	--------	------	------	------	-------	---

ROUTING DATA

ALOSS	CLOSS	AVG	IRES	ISAME	1	1	0	0
-------	-------	-----	------	-------	---	---	---	---

NSTPS NSTOL LAG AMSKK TSK STORA

0	0	0.000	0.000	0.000	-1.	-1.	0	0
---	---	-------	-------	-------	-----	-----	---	---

STORAGE= 0. 426. 156. 1286. 2141. 2569. 3626. 4282. 5136.

0	1	0	0	0	0	0	0	0
---	---	---	---	---	---	---	---	---

1.	1.	1.	2.	4.	7.	11.	17.	28.	49.
96.	192.	368.	756.	1252.	1764.	2209.	2451.	2513.	2448.
2302.	2111.	1999.	1689.	1510.	1337.	1175.	1025.	898.	801.
710.	627.	551.	483.	422.	368.	326.	299.	276.	254.
232.	211.	192.	175.	159.	146.	131.	119.	107.	96.

STOR

1.	1.	2.	3.	6.	9.	16.	22.	36.	63.
124.	248.	455.	730.	1031.	1308.	1514.	1626.	1654.	1624.
1557.	1469.	1371.	1272.	1173.	1078.	959.	907.	831.	762.
698.	638.	585.	536.	493.	455.	420.	389.	356.	329.
301.	274.	249.	226.	206.	187.	170.	154.	140.	128.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

JFS	2513.	2428.	1711.	725.	34796.
INCHES	1.06	2.99	3.80	3.80	
AC-FT	1205.	3396.	4316.	4316.	

STATION 2. PLAN 1, RTIO 2

2.	2.	3.	5.	8.	14.	22.	34.	55.	98.
192.	424.	993.	1953.	3172.	4366.	5246.	5632.	5567.	5219.
4736.	4233.	3716.	3256.	2823.	2647.	2121.	1825.	1583.	1380.
1196.	1031.	895.	792.	698.	613.	536.	468.	405.	351.
313.	285.	259.	236.	214.	195.	177.	161.	146.	133.

STOR

2.	2.	4.	6.	11.	18.	28.	44.	71.	127.
249.	494.	889.	1396.	1930.	2390.	2698.	2825.	2804.	2690.
2527.	2361.	2151.	1964.	1768.	1624.	1474.	1337.	1214.	1102.
5000.	910.	829.	756.	689.	629.	574.	526.	482.	443.
406.	370.	336.	306.	278.	252.	229.	209.	189.	172.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

JFS	5632.	5416.	3518.	1463.	70228.
INCHES	2.36	2.36	6.32	7.66	7.66
AC-FT	2687.	2687.	7181.	8710.	8710.

STATION 2. PLAN 1, RTIO 3

2.	3.	4.	7.	13.	21.	32.	51.	83.	147.
288.	761.	1250.	3387.	5403.	7257.	9069.	9401.	8731.	7658.
6693.	6126.	5338.	4611.	3982.	3627.	2946.	2527.	2161.	1670.
1612.	1402.	1212.	1044.	903.	798.	703.	616.	538.	466.
399.	337.	304.	276.	251.	228.	207.	188.	171.	156.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

JFS	9401.	8715.	5558.	2206.	105777.
INCHES	3.80	9.71	11.54	11.54	
AC-FT	4324.	11031.	13113.	13120.	

\*QV4\*

		STATION						2. PLAN 1, RTIO 4		
		3.	4.	5.	6.	7.	8.	17.	23.	43.
		4275.	1133.	2610.	4959.	7056.	11684.	13775.	12991.	11633.
		8675.	7332.	6548.	5726.	6931.	9261.	3655.	3150.	2694.
		1397.	1707.	1487.	1289.	1111.	954.	840.	740.	649.
		684.	409.	344.	307.	279.	253.	230.	203.	190.
										173.

		STOR								
		4.	5.	6.	7.	8.	9.	22.	36.	56.
		495.	966.	1699.	2606.	3510.	4148.	4377.	4320.	4139.
		3633.	3382.	3125.	2856.	2596.	2352.	2127.	1921.	1735.
		1916.	1281.	1161.	1052.	954.	868.	790.	719.	1567.
		537.	484.	438.	398.	352.	329.	299.	271.	654.
										595.

		PEAK						6-HOUR		24-HOUR		72-HOUR		TOTAL VOLUME	
		2FS	13775.	12521.	7512.	2965.	141380.								
		TNC-ES		5.47	13.12	15.43									
		AC-FI		6212.	14907.	17535.									

\*QV4\*

		STATION						2. PLAN 1, RTIO 5		
		5.	6.	7.	8.	9.	10.	21.	34.	54.
		594.	1544.	3547.	6689.	11740.	17633.	18174.	16314.	1386.
		10417.	8851.	7416.	6633.	5807.	5005.	4320.	3704.	13784.
A-20		2355.	2024.	1729.	1505.	1305.	1126.	966.	868.	3194.
		559.	473.	338.	336.	302.	274.	249.	227.	273.

		STOR								
		5.	6.	7.	8.	9.	10.	28.	45.	70.
		615.	1192.	2043.	3171.	4158.	4657.	4696.	4561.	4176.
		3931.	3663.	3409.	3153.	2982.	2620.	2374.	2146.	1939.
		1531.	1429.	1293.	1171.	1061.	962.	874.	796.	1751.
		591.	529.	476.	431.	392.	356.	324.	294.	656.
										595.

		PEAK						6-HOUR		24-HOUR		72-HOUR		TOTAL VOLUME	
		2FS	18174.	16476.	9492.	3688.									
		TNC-ES		7.19	16.57	19.32									
		AC-FI		8174.	16838.	21955.									

## PEAK FLOW SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS

OPERATION	STATION	PLAN	.20	.40	.60	.80	1.00	RATIOS APPLIED TO FLOWS
HYDROGRAPH AT		1	1	3735.	7590.	11385.	15180.	18976.
ROUTE 13	2	1	2	0.	0.	0.	0.	0.

PREVIOUS INSPECTION REPORTS

NOTICE: After filling out one of these forms as completely as possible for each dam in your district, return it at once to the  
Conservation Commission, Albany.

STATE OF NEW YORK  
CONSERVATION COMMISSION  
ALBANY

DAM REPORT

*Aug. 6th, 1913 -*

CONSERVATION COMMISSION,

DIVISION OF INLAND WATERS.

GENTLEMEN:

I have the honor to make the following report in relation to the structure known as  
the *Middle Branch or Tilly Foster River* Dam.


This dam is situated upon the *Middle Branch of Foster River* in the Town of *South East*, *Putnam* County, about *2 1/4 miles* from the Village ~~City~~ of *Wassaic*. The distance *Up* stream from the dam, to the *Tilly Foster Railroad*, ~~on~~ *Post Office*, is about *2 miles*.

The dam is now owned by *New York City* and was built in or about the year *1877* and was extensively repaired or reconstructed during the year *1890*.

As it now stands, the spillway portion of this dam is built of *Concrete* and the other portions are built of *Gravel*.


As nearly as I can learn, the character of the foundation bed under the spillway portion of the dam is *Bedrock* and under the remaining portions such foundation bed is *Bedrock*.

(In the space below, make a third sketch showing the general plan of the dam, and its approximate position in relation to buildings or other conspicuous objects in the vicinity.)




(On the reverse side, make a sketch showing the form and dimensions of a cross section through the roadway or waste-well of this dam, and copy and sketch also, the same information for a cross section through the other portion of the dam. Show particularly the profile, width of the dam above the surface of the water at the top, and thickness of the bottom, as nearly as you can learn.)

### SPILLWAY SECTION



### OTHER SECTION



The total length of the dam is about 600 feet. The spillway or waste portion, is about 100 feet long, and the crest of the spillway is about 10 feet below the top of the dam.

The number, size and location of discharge pipes, waste pipes or gates which may be used for drawing off the water from behind the dam, are as follows: Two

30" pipes leading into 4 20" pipes at powerhouse

At the time of this inspection the water level above the dam was 3 ft. 0 in.  
~~about~~ below the crest of the spillway.

(State briefly, in the space below, whether, in your judgment, this dam is in good condition, or bad condition, describing particularly any leaks or cracks which you may have observed.)

This dam seemed to be in good condition and except that when water over it would probably float into the bottom of the base causing the known result to damage and wash away the heavy timber that is in place.

Reported by John C. Johnson

## STATE OF NEW YORK

DEPARTMENT OF

## State Engineer and Surveyor

ALBANY

## Report of a Structure Impounding Water

To assist in carrying out the provisions of Section 22 of the Conservation Law, being Chapter LXV of the Consolidated Laws of New York State, relating to safeguarding life and property and the erection, reconstruction or maintenance of structures for impounding water, owners of such structures are requested to fill out as completely as possible this report form for each such dam or reservoir owned within the State of New York for which no plans or reports relative thereto are on file in this Department, and to return this report form, together with prints or photographs explanatory thereof to this department, Branch Reservoir.

1. The structure is on the Middle Branch flowing into the Croton River in the Town of Carmel, County of Putnam, N.Y. New York, about a mile west from Brewster's Station on the Harlem Division of the N.Y.C.R.R.  
(Give exact distance and direction from a well-known bridge, dam, village main cross-roads or mouth of a stream)
2. Is any part of the structure built upon or does its pond flood any State lands? No
3. The name and address of the owner is The City of New York
4. The structure is used for impounding water for water supply
5. The material of the right bank, in the direction with the current, is.....; at the spillway crest elevation this material has a top slope of.....inches vertical to a foot horizontal on the center line of the structure, a vertical thickness at this elevation of.....feet, and the top surface extends for a vertical height of.....feet above the spillway crest.
6. The material of the left bank is.....; has a top slope of.....inches to a foot horizontal, a thickness of.....feet and a height of.....feet.
7. The natural material of the bed on which the structure rests is (clay, sand, gravel, boulders, granite, shale, slate, limestone, etc.).....
8. State the character of the bed and the banks in respect to the hardness, perviousness, water bearing, effect of exposure to air and to water, erodability, etc.

9. If the bed is in layers, are the layers horizontal or inclined? ..... If inclined what is the direction of the horizontal outcropping relative to the axis of the main structure and the inclination and direction of the layers in a plane perpendicular to the horizontal outcropping? .....

10. What is the thickness of the layers? .....

11. Are there any porous seams or fissures? .....

12. The watershed at the above structure and draining into the pond formed thereby is 21.31 square mile

13. The pond area at the spillway crest elevation is 430 acres and the pond impounds 535.4 cubic feet of water.

14. The maximum known flow of the stream at the structure was ..... cubic feet per second c

(Date)

15. Has the spillway capacity ever been exceeded by a high flow? ..... No .....

Can any possible flood flow from the pond otherwise than through the wastes noted under 17 and 18 of this report? ..... No .. If so, give the location, the length and the elevation relative to the spillway crest and the character and slopes of the ground of such possible wastes.....

16. State if any damage to life or to any buildings, roads or other property could be caused by any possible failure of the above structure. Describe the location, the character and the use of buildings below the structure which might be damaged by any failure of the structure; of roads adjacent to or crossing the stream below the structure, giving the lowest elevation of the roadway above the stream bed and giving the shape, the height and the width of stream openings; and of any embankments or steep slopes that any flood could pass over. Also indicate the character and use made of the ground below the structure.....

The failure of this dam could cause no great loss of life or damages as it is only about 100 feet up-stream from the Croton Falls Reservoir

100

17. WASTES. The spillway of the above structure is ..... feet long in the clear; the waters are held at the right end by a ..... the top of which is ..... feet above the spillway crest, and has a top width of ..... feet; and at the left end by a ..... the top of which is ..... feet above the spillway crest, and has a top width of ..... feet.

2                   30

18. There is also for flood discharge a pipe 2 ..... inches in I.D. diameter and the bottom is ..... feet below the spillway crest; and a (sluice, gate outlet) ..... wide in the clear by ..... feet high, and the bottom is ..... feet below the spillway crest.

no

19. APRON. Below the spillway there is an apron ~~XXXXXX~~.....  
(Material)

~~xxxxxxxxxxxxxx for which the maximum width of the apron is about thickness of xxxxxxxx feet  
xxxxx width xx xxxxxxxxxx feet~~

20. Has the structure any weaknesses which are liable to cause its failure in high flows? .....

21. SKETCHES. On the back of this report make a sketch to scale for each different cross-section of the above structure at the greatest depth; giving the height and the depth from the surface of the foundation, the bottom width, the top width (for a concrete or masonry spillway at two feet below the crest), the elevation of the top in reference to the spillway crest, the length of the section, and the material of which the section is constructed; on the spillway section show a cross section of the apron, giving its width, thickness and material, and show the abutment or wash wall at the end of the spillway, giving its heights and thickness. Mark each section with a capital letter. Also sketch a plan; show the above sections by their top lines, giving the mark and the length of each; the openings by their horizontal dimensions; the abutments by their top width and top lengths from the upstream face of the spillway section; and outline the apron. Also sketch an elevation of each end of the structure with a cross section of the banks, giving the depth and width excavated into the banks.

22. WATER SUPPLY. The waters impounded by the above structure have (not) been used for a public water supply since 1878 by City of New York .....

7  
53541