

AD-A079 001

GAI CONSULTANTS INC MONROEVILLE PA
NATIONAL DAM INSPECTION PROGRAM. VALLEY-HI EAGLE LAKE DAM (NDS --ETC(U)
SEP 79 B M MIHALCIN

F/G 13/13

DACW31-79-C-0013


NL

UNCLASSIFIED

1 OF 2
AD
A079001

EEC





ADA079001

SUSQUEHANNA RIVER BASIN
OREGON CREEK, FULTON COUNTY


PENNSYLVANIA
VALLEY-HI EAGLE LAKE DAM

LEVEL
FF

NDS I.D. No. PA - 00186
PENNADER I.D. No. 29 - 33

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

ORIGINAL CONTAINS COLOR PLATES: ALL DOCUMENTS
REPRODUCTIONS WILL BE IN BLACK AND WHITE




Distribution Unlimited
Approved for Public Release
Contract No. DACW31-79-C-0013

PREPARED FOR

DEPARTMENT OF THE ARMY
Baltimore District, Corps of Engineers
Baltimore, Maryland 21203

DDC FILE COPY

PREPARED BY
GAI CONSULTANTS, INC.
570 BEATTY ROAD
MONROEVILLE, PENNSYLVANIA 15146
SEPTEMBER 1979



80-7 1 077

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DDC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

(11/Sep 79) (12/10/79)

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition, and the downstream damage potential.

⑥ National Dam Inspection Program,
Valley-Hi Eagle Lake Dam (NDS I.D.
Number PA-00186, PennDer I.D. Number
29-33), Susquehanna River Basin,
Oregon Creek, Fulton County, Pennsylvania.
Phase I Inspection Report,

⑩ Bernard M. Mihalein i

4/11 00 2

45 DACW31-79-C-0013

See A

Accession For	
NTIS GRA&I	
DDC TAB	
Unannounced	
Justification	
By	
Distribution	
Availability Codes	
Avail and/or special	

PHASE I REPORT
NATIONAL DAM INSPECTION PROGRAM

ABSTRACT

Valley-Hi Eagle Lake Dam: NDI I.D. No. PA-00186

<u>Owner:</u>	Valley-Hi Development Association, Inc.
<u>State Located:</u>	Pennsylvania (PennDER I. D. No. 29-32)
<u>County Located:</u>	Fulton
<u>Stream:</u>	Oregon Creek
<u>Inspection Date:</u>	9 August 1979
<u>Inspection Team:</u>	GAI Consultants, Inc. 570 Beatty Road Monroeville, Pennsylvania 15146

Based on a visual inspection and hydrologic/hydraulic analysis the overall condition of the facility is considered to be fair.

The size classification of the facility is small and the hazard classification is considered to be high. In accordance with the recommended guidelines, the Spillway Design Flood (SDF) ranges between the 1/2 PMF (Probable Maximum Flood) and the PMF. Results of the hydrologic/hydraulic analysis indicate the facility will discharge and/or store only 24 percent of the PMF prior to overtopping of the embankment. Overtopping is expected to cause embankment failure, with the breaching analysis indicating that failure will probably result in an increase to potential for loss of life downstream of the facility. Therefore, the spillway system is considered to be seriously inadequate, and the facility unsafe, non-emergency.

Deficiencies noted by the inspection team included seepage and swamp-like conditions immediately downstream of the embankment toe and around the outlet conduit, heavily overgrown outlet and spillway discharge channels, an erosion ditch extending from the right abutment hillside to the downstream embankment toe along the embankment-abutment contact, deteriorated spillway concrete, several unvegetated areas along the embankment and adjoining spillway dike, and a submerged outlet conduit riser and control valve.

Due to the seriously inadequate spillway classification, it is recommended that the owner immediately develop and implement a warning system for the notification of downstream residents should emergency conditions develop. Included in the plan should be provisions for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.

In addition, it is recommended that the owner:

- a. Have the facility studied by a registered professional engineer, experienced in the hydraulics and hydrology of dams, and implement measures necessary to make the facility hydraulically adequate.
- b. Remove the logs from the spillway approach and clear the downstream discharge channel of all obstructions to permit unimpeded flow.
- c. Take positive measures to collect and channel the seepage from the area immediately downstream of the embankment toe into the outlet discharge channel, and clear the channel to eliminate ponding.
- d. Visually assess the seepage during future inspections to ensure that it is not encroaching on the embankment toe.
- e. Seed those areas of the embankment and spillway dike which are unprotected and subject to erosion.
- f. Provide protection for the erosion ditch being developed along the right abutment-embankment contact.
- g. Provide a more durable roadway surface along the crest (particularly near the right abutment) to curtail rutting of the crest by vehicular traffic.
- h. Develop manuals of maintenance and operation to ensure continued care and proper maintenance of the facility. Included in the manuals should be provisions for operating the drawdown mechanism.

GAI Consultants, Inc.

Approved by:

Bernard M. Mihalcin

Bernard M. Mihalcin, P.E.

Janet Rock



Date 17 Sept. 1979

Date 25 Sep 79



OVERVIEW PHOTOGRAPH

TABLE OF CONTENTS

	<u>Page</u>
PREFACE	i
ABSTRACT.	ii
OVERVIEW PHOTOGRAPH	v
TABLE OF CONTENTS	vi
SECTION 1 - GENERAL INFORMATION	1
1.0 Authority	1
1.1 Purpose	1
1.2 Description of Project.	1
1.3 Pertinent Data.	2
SECTION 2 - ENGINEERING DATA.	6
2.1 Design.	6
2.2 Construction Records.	6
2.3 Operating Records	6
2.4 Other Investigations.	6
2.5 Evaluation.	6
SECTION 3 - VISUAL INSPECTION	8
3.1 Observations.	8
3.2 Evaluation.	9
SECTION 4 - OPERATIONAL PROCEDURES.	10
4.1 Normal Operating Procedure.	10
4.2 Maintenance of Dam.	10
4.3 Maintenance of Operating Facilities	10
4.4 Warning System.	10
4.5 Evaluation.	10
SECTION 5 - HYDROLOGIC/HYDRAULIC EVALUATION	12
5.1 Design Data	12
5.2 Experience Data	12
5.3 Visual Observations	12
5.4 Method of Analysis.	12
5.5 Summary of Analysis	13
5.6 Spillway Adequacy	15
SECTION 6 - EVALUATION OF STRUCTURAL INTEGRITY.	16
6.1 Visual Observations	16
6.2 Design and Construction Techniques.	16
6.3 Past Performance.	17
6.4 Seismic Stability	17
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES	18
7.1 Dam Assessment.	18
7.2 Recommendations/Remedial Measures	19

TABLE OF CONTENTS

- APPENDIX A - CHECK LIST - ENGINEERING DATA
- APPENDIX B - CHECK LIST - VISUAL INSPECTION
- APPENDIX C - HYDROLOGY AND HYDRAULICS
- APPENDIX D - PHOTOGRAPHS
- APPENDIX E - GEOLOGY
- APPENDIX F - FIGURES
- APPENDIX G - REGIONAL VICINITY AND WATERSHED BOUNDARY MAP

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
VALLEY-HI EAGLE LAKE DAM
NDI# PA-186, PENNADER# 29-33

SECTION 1
GENERAL INFORMATION

1.0 Authority.

The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

1.1 Purpose.

The purpose is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. Valley-Hi Eagle Lake Dam is a zoned earth embankment approximately 25 feet high and 450 feet long (including spillway). The facility is provided with a trapezoidal-shaped spillway cut in rock and located at the left abutment. The spillway is equipped with a concrete trapezoidal-shaped overflow weir situated along the dam centerline. The outlet works consists of a 15-inch diameter steel pond drain that discharges at the downstream embankment toe. Flow through the pond drain is regulated via a 15-inch diameter gate valve located at the inlet.

b. Location. Valley-Hi Eagle Lake Dam is located on Oregon Creek in Brush Creek and Wells Townships, Fulton County, Pennsylvania about 1-mile north of U. S. Route 30 and about 5 miles northeast of Pennsylvania Turnpike Interchange 12 at Breezewood, Pennsylvania. The dam, reservoir, and watershed are contained within the Wells Tannery, Pennsylvania, 7.5 minute U.S.G.S. topographic quadrangle. The coordinates of the dam are N 40° 2.1' and W 78° 11.0' (see Appendix G).

c. Size Classification. Small (25 feet high; 555 acre-feet storage capacity at top of dam).

d. Hazard Classification. High (see Section 3.1.e).

e. Ownership. Valley-Hi Development Association, Inc.

P. O. Box 42
Breezewood, PA 15533
Jack Gothie - President

f. Purpose. Private recreation.

g. Historical Data. Application to construct Valley-Hi Eagle Lake Dam was originally made by Jack F. Gothie in June 1962 and subsequently approved by the State of Pennsylvania in September 1962. The facility was designed by Albert M. Larsen of McConnellsburg, Pennsylvania. Construction did not begin until September 1963 and was completed in August 1964. Construction of the facility was performed by K. G. Richards of McConnellsburg, Pennsylvania. Records of construction progress are limited to several memoranda prepared by state inspectors subsequent to periodic inspections. No monthly construction progress reports were prepared as required. Engineering supervision and control of construction appears to have been minimal; however, available correspondence indicates the facility was inspected by the state upon completion and all construction was approved. No major modifications have been made to the structure since its completion.

Valley-Hi Eagle Lake Dam is now an integral part of a private real estate development under the direction of the Valley-Hi Development Association, Inc. Jack Gothie serves as president of the Association which consists of private investors who either own or lease tracts of land in the area surrounding Valley-Hi Eagle Lake.

1.3 Pertinent Data.

a. Drainage Area (square miles). 2.2

b. Discharge at Dam Site. No records of reservoir levels or spillway discharges are kept. Discussions with the owner's representative indicated that the highest flow to date occurred during the flood of June 1972, when flow over the weir was estimated at approximately 8 inches.

Discharge Capacity of the Outlet Conduit - Discharge curves are not available.

Discharge Capacity of Spillway at Maximum Pool ≈ 1050 (see Appendix C, Sheet 9).

c. Elevations (feet above mean sea level). The following elevations were obtained from field measurements that were based on the elevation of the normal pool at 1327

feet (as per U.S.G.S.).

Top of Dam	1332.2 (design)
	1331.9 (field)
Maximum Design Pool	Not known
Maximum Pool of Record	1327.7 (estimated)
Normal Pool	1327
Spillway Crest	1327
Upstream Inlet Invert	1312.5
Downstream Outlet Invert	1307.2
Streambed at Dam Centerline	1309
Maximum Tailwater	Not known

d. Reservoir Length (feet).

Top of Dam	3300
Normal Pool	2900

e. Storage (acre-feet).

Top of Dam	555
Normal Pool	296
Design Surcharge	Unknown

f. Reservoir Surface (acres).

Top of Dam	62
Normal Pool	44
Maximum Design Pool	Not known

g. Dam.

Type Zoned earth.

Length 450 feet (including
spillway).

Height 25 feet (field
measured: crest to
invert of outlet
conduit).

Top Width 11 feet

Upstream Slope 2H:1V

Downstream Slope 2-1/2H:1V

Zoning Impervious clay core
flanked by semi-
impervious zones com-

		prised of a mixture of clay and shale (see Figure 3).
Impervious Core		See "Zoning" above.
Cutoff		Core trench 10 feet wide at the base with 1H:1V side slopes is reportedly provided along the embankment centerline (see Figure 3).
Grout Curtain		None indicated.
h. <u>Diversion Canal and Regulating Tunnels.</u>		None.
i. <u>Spillway.</u>		
Type		Trapezoidal-shaped channel cut in rock at the left abutment and equipped with a concrete trapezoidal- shaped overflow weir (See Appendix C, Sheet 5).
Crest Elevation		1327 feet
Crest Length		30 feet
j. <u>Outlet Conduit.</u>		
Type		15-inch diameter steel pipe placed on a con- crete cradle.
Conduit Length		130 feet (inlet to outlet).
Closure and/or Regulat- ing Facilities		Flow through the con- duit is reportedly controlled via a 15- inch diameter gate valve located at the inlet end.
Access		Under normal pool conditions, the gate

valve control mechanism
is submerged under
several feet of water
and accessible only
by boat

SECTION 2
ENGINEERING DATA

2.1 Design.

a. Design Data Availability and Sources. No design data, calculations, or reports are available concerning any aspect of this facility. Design features, presented below, are derived from information and correspondence contained in PennDER files. Included in the files are design drawings, dated photographs, and state inspection memoranda and reports.

b. Design Features.

1. Embankment. Details of the design features are based on available correspondence and the field inspection. The actual as-built configuration of the facility is shown on Figure 1. Figures 2 through 4 are design drawings, but have not been revised to show as-built conditions.

The embankment is a zoned earth structure comprised of an impervious clay core flanked by semi-impervious zones composed of a mixture of clay and shale on both the upstream and downstream slopes. The upstream slope is set at 2H:1V and is protected by a layer of sandstone riprap that projects about 3 feet above normal pool. A 5-foot wide berm is reportedly provided along the upstream face at elevation 1292. The downstream slope is set at 2-1/2H:1V while the crest is 11 feet wide.

Available design drawings indicate that a 10-foot wide cutoff is provided along the embankment centerline (see Figure 2). Contract specifications state that all fill was to be placed in 8-inch loose layers and compacted with a sheep's foot roller to a density of 95 percent of maximum dry weight.

2. Appurtenant Structures.

a) Spillway. The spillway is a trapezoidal-shaped channel cut in rock at the left abutment. It is equipped with a trapezoidal-shaped overflow weir positioned along the embankment centerline within a portion of the channel that is lined with concrete. Figures 3 and 4 detail several different spillways in plan and cross-section, none of which accurately depict the one observed by the field team. A plan and cross-section of the actual spillway, based on field measurements, are shown on sheet 5, Appendix C. The presence of a cutoff beneath the spillway is not known.

b. Outlet Conduit. The outlet conduit consists of a 15-inch diameter steel pipe placed on a concrete cradle. Flow through the conduit is controlled via a 15-inch diameter solid brass gate valve located at the inlet. The control mechanism for the gate valve is submerged, by design, by several feet of water under normal pool conditions and is accessible only by boat. Concrete anti-seep collars are reportedly provided at 20-foot intervals along the conduit. A small concrete headwall supports and protects the discharge end.

c. Specific Design Data and Criteria. No specific design data are available for any aspect of the facility.

2.2 Construction Records.

Construction data is limited to PennDER memoranda and several construction photographs obtained during periodic state inspections. The lack of information and reliable as-built drawings suggests limited engineering supervision or control during construction. State inspectors, however, found the construction acceptable and eventually recommended the approval of the project.

2.3 Operating Records.

No records of operation are available.

2.4 Other Investigations.

No formal investigations have been performed on this facility subsequent to its completion.

2.5 Evaluation.

Engineering data are limited to design drawings (not as-built), PennDER correspondence, and a few construction photographs. No formal design calculations are available; however, the available data are considered sufficient to make a reasonable Phase I assessment of the facility.

SECTION 3
VISUAL INSPECTION

3.1 Observations.

a. General. The general appearance of the dam and its appurtenances suggests that they are currently in fair condition.

b. Embankment. Observations made during the visual inspection reveal the embankment to be in fair condition. Seepage was observed immediately below the downstream embankment toe to the left and right of the outlet conduit. Both areas were draining freely into the outlet conduit discharge channel at rates estimated at less than 1 gpm for the area to the right of the conduit and between 3 to 4 gpm for the area to the left of the conduit (see Photograph 10). Some wet areas were observed along the lower portion of the downstream embankment face, particularly around the outlet conduit; however, no measurable seepage was noted. A small erosion ditch was observed along the embankment-right abutment contact that extends from the crest to the downstream toe. The ditch apparently carries drainage from the adjacent hillside and is not a design feature. The embankment, for the most part, appears reasonably maintained. Both the upstream and downstream slopes are covered with grass and high weeds; however, care appears to be taken to cut trees which have taken root. The embankment crest and adjacent spillway dike are completely void of any protective vegetation (see Photographs 1, 2 and 8). This has resulted in local areas of minor erosion and some rutting of the crest from vehicular use.

c. Appurtenant Structures.

1. Spillway. The spillway, as observed during the visual inspection, appears to be in fair condition. A log bridge has been placed across the approach channel (see Photograph 4) and serves as a potential obstruction to unimpeded spillway discharge as does heavy overgrowth and boulders observed within the discharge channel (see Photograph 6). The concrete overflow weir and sidewalls show signs of cracking, scaling, and overall minor deterioration (see Photograph 4). Water was observed seeping through a crack located near the middle of the left side of the overflow weir (see Photograph 5).

2. Outlet Conduit. The only visible portion of the outlet conduit is its discharge end shown in Photograph 9. It is impossible to visually assess the overall condition of the conduit; however, discussions with representatives of

the owner indicate it was last operated in the fall of 1978, and, at that time, was considered to be in good condition.

d. Reservoir Area. The general area surrounding the reservoir is characterized by steep slopes that are heavily forested (see Photographs 1 and 3). Valley-Hi Eagle Lake Dam is part of a private real estate development known as Valley-Hi Eagle Lake. Thus, the complexion of the surrounding area is subject to change although the present owners contend they have no plans for mass development of the area.

e. Downstream Channel. The channel downstream of Valley-Hi Eagle Lake Dam is characterized as a narrow, heavily wooded valley with generally steep confining slopes (see Photograph 11). Oregon Creek merges with Sideling Hill Creek approximately 4 miles downstream of the dam. Within the next mile, in the vicinity of PA Route 915, the creek passes 5 residences which are considered sufficiently close to the stream to be potentially affected by a breach of the embankment (estimated population: 15-20). Thus, the hazard classification of the facility is considered to be high.

3.2 Evaluation.

The overall condition of the facility is considered fair. Positive steps should be taken to identify the origin of the seepage causing ponding at the downstream toe and subsequently monitor their respective flow rates. The remaining deficiencies are considered, for the most part, maintenance related and can be alleviated with proper remedial measures.

SECTION 4 OPERATIONAL PROCEDURES

4.1 Normal Operating Procedure.

Valley-Hi Eagle Lake Dam is essentially a self-regulating facility. Excess inflow passes through the spillway and is discharged into the stream below. The 15-inch diameter steel outlet conduit has historically been used only for the purpose of drawing down the reservoir and is operated via a 15-inch diameter gate valve located at the inlet end of the conduit. Under normal pool conditions, the gate valve is submerged and accessible by boat only. There are no formal operating procedures associated with the facility and no operating manual is available.

4.2 Maintenance of Dam.

Maintenance of the facility is currently performed on an informal basis. No formal maintenance procedures are adhered to and no maintenance manual is available.

4.3 Maintenance of Operating Facilities

The only operating mechanism associated with the facility is the 15-inch diameter gate valve located on inlet end of the outlet conduit. The valve was last operated in the fall of 1978 when the reservoir was partially drawn down. The valve was reported to have opened and closed very easily. Nevertheless, no formal maintenance procedures are adhered to and no maintenance manual is available.

4.4 Warning System.

There are no formal warning systems in effect.

4.5 Evaluation.

The facility is designed to be essentially self-regulating. The dam is equipped with only one operable mechanism, that being a 15-inch diameter gate valve controlling flow through the outlet conduit. Procedures for operating the mechanism are not formalized.

Maintenance of the facility is performed on an as-needed basis. No formal maintenance procedures are adhered

to and no maintenance manual is available. In addition, there are no formal warning systems in effect.

SECTION 5
HYDROLOGIC/HYDRAULIC EVALUATION

5.1 Design Data.

No design data, calculations or formal reports are available. Available data is limited to design drawings and correspondence contained in PennDER files.

5.2 Experience Data.

No records of spillway discharge are available. Discussions with representatives of the owner, present during the inspection, indicated that, to date, the highest flow through the spillway was approximately 8 inches over the weir during the flood of June 1972.

5.3 Visual Observations.

The visual inspection revealed several conditions which are considered to be potential impediments to the unrestricted and efficient discharge of the spillway. The log bridge at the entrance to the approach channel is an obstruction prior to flow reaching the weir while the heavy overgrowth and boulders observed within the spillway channel may serve to increase the discharge retarding effects of tailwater. In addition, the concrete portion of the spillway, including the overflow weir, shows signs of deterioration. The observed structural cracking may be sufficiently extensive to make the concrete vulnerable to the high pressures developed under large flows. However, due to the fact that the spillway is cut in rock at the left abutment, removal of the concrete portion will likely serve only to further obstruct flow, but, is not considered a major structural hazard.

5.4 Method of Analysis.

The facility has been analyzed in accordance with procedures and guidelines established by the U. S. Army, Corps of Engineers, Baltimore District, for Phase I hydrologic and hydraulic evaluations. The analysis has been performed utilizing a modified version of the HEC-1 program developed by the U. S. Army, Corps of Engineers, Hydrologic Engineering Center, Davis, California. Analytical capabilities of the program are briefly outlined in the preface contained in Appendix C.

5.5 Summary of Analysis.

a. Spillway Design Flood (SDF). In accordance with the procedures and guidelines contained in the National Guidelines for Safety Inspection of Dams for Phase I Investigations, the Spillway Design Flood (SDF) for Valley-Hi Eagle Lake Dam ranges between the 1/2 PMF (Probable Maximum Flood) and the PMF. This classification is based on the relative size (small), and the potential hazard of dam failure to downstream developments (high). Due to the high potential for downstream damage, and to the rather large storage volume behind the dam at maximum pool (\approx 555 acre-feet), the SDF for this facility is considered to be the PMF.

b. Results of Analysis. Valley-Hi Eagle Lake Dam was evaluated under normal operating conditions. That is, the reservoir was initially at its assumed normal pool or spillway elevation of 1327 feet (MSL), with the low level blowoff line closed, and the spillway discharging freely. The spillway is a free overfall, concrete, trapezoidal-shaped weir structure which discharges into a gently sloped open channel. Since the weir is only about 4 feet above the discharge channel invert, and due to the gentle channel slope, a backwater curve was computed via the HEC-2 computer program so that the effects of tailwater on the weir outflows could be ascertained. Finally, the necessary downstream channel routing was done under the assumption that the stream was dry prior to the inflow of the dam outflow. All pertinent engineering calculations relative to the evaluation of this facility are provided in Appendix C.

Overtopping analysis (using the Modified HEC-1 Computer Program) indicated that the discharge/storage capacity of Valley-Hi Eagle Lake Dam can accommodate only about 24 percent of the PMF (SDF) prior to the overtopping of the embankment (Appendix C, Summary Input/Output Sheets, Sheet E). The low top of dam was inundated by depths of water of 1.6 and 3.0 feet under the 1/2 PMF and PMF events, respectively (Summary Input/Output Sheets, Sheet I). Therefore, since the SDF for this facility is the PMF, Valley-Hi Eagle Lake Dam has a high potential for overtopping, and thus, for breaching under floods of less than PMF magnitude.

Since Valley-Hi Eagle Lake Dam cannot safely handle a flood of at least 1/2 PMF magnitude, the possibility of embankment failure under floods of 1/2 PMF intensity or less was investigated (in accordance with ETL-1110-2-234). Several feasible alternatives were analyzed since it is difficult, if not impossible, to determine exactly how or if a specific dam will fail. The major concern of the breaching evaluations is with the impact of the various breach discharges on increasing downstream water surface elevations above those to be expected if breaching did not occur.

The Modified HEC-1 Computer Program was used for the breaching analysis with the assumption that the breaching of an earth dam would begin once its reservoir's water level reached the low top of dam elevation.

Two sets of breach geometry were evaluated for the Valley-Hi Eagle Lake Dam for each of two failure times, a rapid time (0.5 hrs.) and a prolonged time (4.0 hrs.), (total time for each breach section to reach its final dimensions) so that a range of this most sensitive variable might be examined. In addition, an average or more probable set of breach conditions was analyzed, with a failure time of 2.0 hours.

The peak breach outflows (resulting from a 0.26 PMF overtopping) ranged from about 2,190 cfs for the minimum section--maximum fail time scheme to about 20,210 cfs for the maximum section--minimum fail time scheme (Appendix C, Sheet 23). The outflow from the average breach scheme was about 6,920 cfs, compared to the non-breath 0.26 PMF peak outflow of about 1200 cfs (Summary Input/Output Sheets, Sheets L and E). The water surface elevation corresponding to the non-breath 0.26 PMF peak discharge at a section (Section 4) located about 13,700 feet downstream from the dam was approximately 1,165.8 feet (MSL); and approximately 1,063.0 feet (MSL) at a section (Section 6) located about 23,500 feet downstream from the dam (Summary Output/Input Sheets, Sheet J). The water surface elevations corresponding to the average condition peak breach outflows at the two above-mentioned downstream sections were 1,171.3 feet (MSL) and 1,070.3 feet (MSL), respectively (Appendix C, Sheet 24). The approximate elevation of the structures (forest ranger offices) located at Section 4 is about 1,186 feet (MSL); while the approximate elevations of the four residences located at Section 6 are 1,067 feet (MSL), 1,070 feet (MSL); 1,071 feet (MSL), and 1,072 feet (MSL). Therefore, the increase in the water surface at Section 4, caused by the failure of Valley-Hi Eagle Lake Dam, was about 5.5 feet; however, the breach water surface is well below the damage level of the office structures. The increase in the water surface at Section 6, caused by the failure of the dam, was about 7.3 feet, with the breach water surface at about the damage levels of two of the residences, and just below the damage level of another. It can further be surmised that embankment failure under somewhat larger base flood conditions could possibly damage all four residences at Section 6.

The consequences of dam failure can be better envisioned if not only the increase in the height of the flood-wave is considered, but also the great increase in the momentum of the larger and probably swifter moving volume of water. Therefore, the failure of Valley-Hi Eagle Lake Dam

is quite possible, and will most probably lead to increased property damage and possibly to increased loss of life in the downstream regions.

5.6 Spillway Adequacy.

As presented previously, under existing conditions Valley-Hi Eagle Lake Dam can accommodate only about 24 percent of the PMF (the SDF) prior to embankment overtopping. Should a 0.26 PMF or larger event occur, the dam could be overtopped and could possibly fail, endangering the residences in the downstream regions. Therefore, the spillway of Valley-Hi Eagle Lake Dam is considered to be seriously inadequate.

SECTION 6
EVALUATION OF STRUCTURAL INTEGRITY

6.1 Visual Observations.

a. Embankment. The conditions observed at the time of the inspection indicate the embankment is in fair condition. Two large wet areas are located immediately below the downstream embankment toe to the left and right of the outlet conduit. Drainage from the area left of the conduit was estimated at 3 to 4 gpm while drainage from the area to the right was minimal and estimated at less than 1 gpm. The origin of the seepage in these areas could not be ascertained; however, no seepage was observed through the downstream embankment face except for a minor area around the outlet conduit headwall. Presently, the seepage is not considered a threat to the stability of the embankment; however, measures should be taken to identify its source and monitor it if necessary.

The erosion ditch observed at the interface of the downstream slope and right abutment has begun to cut into the embankment. Since the ditch is an apparent frequent drainage path for runoff from the adjoining hillside, positive measures should be taken to protect it from further erosion by possibly lining it with rock or concrete.

Both the embankment crest and right spillway dike lack adequate protective vegetation. As a result, several areas of minor erosion were noted. The embankment crest is not restricted to vehicular use and some minor rutting was also observed.

b. Appurtenant Structures.

1. Spillway. The spillway channel is cut in a formation of sandstone located at the left abutment. For the most part, its structural condition appears stable although the exposed rock surfaces exhibit extensive fracturing and/or jointing. The concrete portion is in a deteriorated condition that includes some spalling, scaling, and structural cracking. Failure of the concrete, if it were to occur under high flows, would likely not affect the structural stability of the spillway due to the fact that it is cut in rock.

2. Outlet Conduit. Based on design drawings and discussions pertaining to its past performance, the outlet conduit is considered to be in good condition.

6.2 Design and Construction Techniques.

No data are available relative to the design of the facility. Detailed construction data are not available; however, inspection memoranda and photographs contained in PennDER files imply that the embankment was reasonably well constructed despite the inference that engineering supervision and control was minimal.

6.3 Past Performance.

Discussions during the inspection, with representatives of the owner, indicated the facility has functioned adequately since its completion. No formal investigations or state inspections have been performed.

6.4 Seismic Stability.

The dam is located within Seismic Zone No. 1 and may be subject to minor earthquake induced dynamic forces. It is believed that the static stability of the embankment is sufficient to withstand such forces although no calculations or investigations were performed to confirm this opinion.

SECTION 7
ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety. Visual observations indicate the structure to be in fair condition. The most significant deficiencies noted were the seepage and ponding at the downstream embankment toe and the obstructions within the spillway channel. None of the observed deficiencies are considered an immediate threat to the safety of the facility. Other minor deficiencies included an erosion ditch along the right abutment-embankment contact, minor deterioration of the spillway concrete, several unprotected areas along the embankment and spillway dike and a submerged outlet conduit valve control.

The size classification of the facility is small and the hazard classification is considered to be high. In accordance with the recommended guidelines, the Spillway Design Flood (SDF) ranges between the 1/2 PMF (Probable Maximum Flood) and the PMF. Results of the hydrologic/hydraulic analysis indicate the facility will discharge and/or store only 24 percent of the PMF prior to overtopping of the embankment. Overtopping is expected to cause embankment failure, with the breaching analysis indicating that failure will result in an increase to potential for loss of life downstream of the facility. Therefore, the spillway system is considered to be seriously inadequate, and the facility unsafe, non-emergency.

b. Adequacy of Information. The available information is considered sufficient to make a reasonable Phase I assessment of the facility.

c. Urgency. Due to the seriously inadequate spillway system, it is recommended that the owner immediately develop and implement a warning system for the notification of downstream residents in the event emergency conditions develop. Included in the plan should be provisions for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.

Other remedial measures recommended below should be undertaken as soon as possible.

d. Necessity for Additional Investigation. Additional investigations to more accurately assess the hydraulic adequacy of the facility are considered necessary.

7.2 Recommendations/Remedial Measures.

Due to the seriously inadequate spillway classification, it is recommended that the owner immediately develop and implement a warning system for the notification of downstream residents should emergency conditions develop. Included in the plan should be provisions for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.

In addition, it is recommended that the owner:

- a. Have the facility studied by a registered professional engineer, experienced in the hydraulics and hydrology of dams, and implement measures necessary to make the facility hydraulically adequate.
- b. Remove the logs from the spillway approach and clear the downstream discharge channel of all obstructions to permit unimpeded flow.
- c. Take positive measures to collect and channel the seepage from the area immediately downstream of the embankment toe into the outlet discharge channel, and clear the channel to eliminate ponding.
- d. Visually assess the seepage during future inspections to ensure that it is not encroaching on the embankment toe.
- e. Seed those areas of the embankment and spillway dike which are unprotected and subject to erosion.
- f. Provide protection for the erosion ditch being developed along the right abutment-embankment contact.
- g. Provide a more durable roadway surface along the crest (particularly near the right abutment) to curtail rutting of the crest by vehicular traffic.
- h. Develop manuals of maintenance and operation to ensure continued care and proper maintenance of the facility. Included in the manuals should be provisions for operating the drawdown mechanism.

APPENDIX A
CHECK LIST - ENGINEERING DATA

NAME OF DAM: Valley-Hi Eagle Lake Dam ENG INEERING DATA
NDI #: PA-186 PENNDER# : 29-33

CHECK LIST
ENGINEERING DATA
PHASE I

PAGE 1 OF 5

ITEM	REMARKS	NDI # PA - 186
PERSONS INTERVIEWED AND TITLE	Jack Gothie (President) - Valley-Hi Development Association, Inc. Nelson Gothie (Secretary-Treasurer) - Valley-Hi Development Association, Inc.	
REGIONAL VICINITY MAP	See Appendix G (U.S.G.S. 7.5 minute topographic quadrangle, Wells Tannery, Pennsylvania)	
CONSTRUCTION HISTORY	Designed by Albert M. Larsen, P. E. - McConnellsburg, Pennsylvania. Constructed by K. G. Richards (1963-1964), McConnellsburg, Pennsylvania.	
AVAILABLE DRAWINGS	Design drawings available from PennDER (not as-built). Owner has no drawings. Field inspection indicates available drawings do not accurately reflect as-built conditions.	
TYPICAL DAM SECTIONS	See Appendix F, Figure 3.	
OUTLETS: PLAN DETAILS DISCHARGE RATINGS	See Appendix F, Figure 3. (Figure 3 does not accurately represent as-built conditions). Discharge rating curves are not available.	

ENGINEERING DATA (CONTINUED)

PAGE 2 OF 5

ITEM	REMARKS	NDI# PA - 186
SPILLWAY: PLAN SECTION DETAILS	See Appendix F, Figure 3 and 4. (Figures 3 and 4 do not accurately represent as-built conditions).	
OPERATING EQUIPMENT PLANS AND DETAILS	None available.	
DESIGN REPORTS	None available.	
GEOLOGY REPORTS	None available.	
DESIGN COMPUTATIONS: HYDROLOGY AND HYDRAULICS STABILITY ANALYSES SEEPAGE ANALYSES	None available.	
MATERIAL INVESTIGATIONS: BORING RECORDS LABORATORY TESTING FIELD TESTING	See Appendix F, Figure 2.	

ENGINEERING DATA (CONTINUED)

PAGE 3 OF 5

ITEM	REMARKS	NDI# PA - 186
BORROW SOURCES	See Appendix F, Figure 2.	
POST CONSTRUCTION DAM SURVEYS	None since construction.	
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None.	
HIGH POOL RECORDS	No formal records. Highest pool to date reportedly occurred during flood of June 1972 when flow over the spillway weir was estimated at 8 inches.	
MONITORING SYSTEMS	None.	
MODIFICATIONS	None. Available drawings do not accurately represent as-built conditions.	

ENGINEERING DATA (CONTINUED)

PAGE 4 OF 5

ITEM	REMARKS	NDT# PA-186
PRIOR ACCIDENTS OR FAILURES	None.	
MAINTENANCE: RECORDS MANUAL	No formal records or manual. Maintenance is performed on an as-needed basis.	
OPERATION: RECORDS MANUAL	No formal records or manual. Nelson Gothie is familiar with the operation of the outlet conduit gate valve. Valve was last operated in the fall of 1978 and was reported to be in good condition.	
OPERATIONAL PROCEDURES	See "Operation" above.	
WARNING SYSTEM AND/OR COMMUNICATION FACILITIES	None.	
MISCELLANEOUS		

CHECK LIST
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

NDI ID # PA-186
PENN DER ID # 29-33
PAGE 5 OF 5

SIZE OF DRAINAGE AREA: 2.2 square miles

ELEVATION TOP NORMAL POOL: 1327 STORAGE CAPACITY: 296 acre-feet

ELEVATION TOP FLOOD CONTROL POOL: -- STORAGE CAPACITY: --

ELEVATION MAXIMUM DESIGN POOL: -- STORAGE CAPACITY: --

ELEVATION TOP DAM: 1331.9 STORAGE CAPACITY: 555 acre-feet

SPILLWAY DATA

CREST ELEVATION: 1327

TYPE: Trapezoidal-shaped concrete spillway with trapezoidal-shaped weir.

CREST LENGTH: 30 feet

CHANNEL LENGTH: approximately 450 feet

SPILLOVER LOCATION: left abutment

NUMBER AND TYPE OF GATES: none

OUTLET WORKS

TYPE: 15-inch diameter steel pipe

LOCATION: near center of dam

ENTRANCE INVERTS: 1312.5 (estimated)

EXIT INVERTS: 1307.2

EMERGENCY DRAWDOWN FACILITIES: 15-inch diameter gate valve at inlet end of outlet conduit.

HYDROMETEOROLOGICAL GAGES

TYPE: None

LOCATION: --

RECORDS: --

MAXIMUM NON-DAMAGING DISCHARGE: About 8-inches of flow over weir during flood of June 1972.

APPENDIX B
CHECK LIST - VISUAL INSPECTION

CHECK LIST
VISUAL INSPECTION
PHASE 1

PAGE 1 OF 8

NAME OF DAM Valley-Hi Eagle Lake Dam STATE Pennsylvania COUNTY Fulton
NDI# PA - 186 PENNDR# 29-33
TYPE OF DAM zoned earth SIZE small
DATE(S) INSPECTION 9 & 10 August 1979 WEATHER partly cloudy
POOL ELEVATION AT TIME OF INSPECTION approximately 1327 M.S.L.
TAILWATER AT TIME OF INSPECTION N/A M.S.L.

INSPECTION PERSONNEL

B. Mihalcin (9/10/79)
W. Veon (8/9&10/79)
D. Bonk (8/9&10/79)

OWNER REPRESENTATIVES

Valley-Hi Development Assoc., Inc.
Jack Gothie - President
Nelson Gothie - Secretary-Treasurer

OTHERS

RECORDED BY D. L. Bonk

EMBANKMENT

ITEM	OBSERVATIONS AND/OR REMARKS	NDI# PA -186
SURFACE CRACKS	None observed.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed.	
SLoughing or Erosion of Embankment and Abutment Slopes	Erosion ditch observed along the embankment-right abutment contact extending from the crest to the downstream toe. The left abutment is an unprotected earth and rock cut displaying evidence of minor erosion. Spillway dike between the spillway channel and embankment is void of vegetative cover and subject to erosion as is embankment crest.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Vertical - good condition. Horizontal - good condition.	
RIPRAP FAILURES	None observed. Sandstone riprap extends about 2 to 3 feet above normal pool and was reportedly handplaced.	
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Good.	

EMBANKMENT

ITEM	OBSERVATIONS AND/OR REMARKS	NDI# PA - 186
DAMP AREAS IRREGULAR VEGETATION (DUSH OR DEAD PLANTS)	Two large damp or wet areas extend across the downstream embankment toe to both the left and right of the outlet conduit. Some ponding of water is evident and the area is generally covered with hydrophilic type vegetation.	
ANY NOTICEABLE SEEPAGE	Minor seepage observed around the outlet conduit. Saturated area at and locally above toe (not critical, but should be observed). Drainage from area left of the outlet conduit estimated at 3 to 4 gpm. Source appears to be through spillway dike at left abutment and probably not through embankment (should be controlled and monitored).	
STAFF GAGE AND RECORDER	None.	
DRAINS	None.	

ITEM	OUTLET WORKS OBSERVATIONS AND/OR REMARKS	NDT# PA - 186
INTAKE STRUCTURE	Submerged, not observed.	
OUTLET CONDUIT (CRACKING AND SPALL- ING OF CONCRETE SURFACES)	15-inch diameter steel outlet conduit. Concrete headwall at the downstream toe in good condition.	
OUTLET STRUCTURE	N/A	
OUTLET CHANNEL	Unlined trapezoidal-shaped channel. The outlet conduit discharge channel merges with the spillway discharge channel approximately 300 feet downstream of the embankment toe. In between, the channel is set on a gentle slope which has resulted in some ponding as well as the partial submergence of the conduit.	
GATE(S) AND OPERA- TIONAL EQUIPMENT	The outlet conduit control valve is submerged below normal pool by design. It is unmarked and could not be observed by the inspection team. Valve last operated in autumn of 1978 and was reported to be in good condition.	

EMERGENCY SPILLWAY

OBSERVATIONS AND/OR REMARKS

NDI # PA - 186

ITEM

TYPE AND CONDITION

Free overfall, trapezoidal-shaped concrete weir structure. Concrete in poor condition exhibiting structural cracking and extensive scaling.

APPROACH CHANNEL

About a 70-foot long trapezoidal-shaped channel appears founded on rock. Channel opening is obstructed at its entrance by the presence of large logs used to provide access to the embankment crest.

SPILLWAY CHANNEL
AND SIDEWALLS

The downstream face of the weir exhibits some concrete scaling and has a large horizontal structural crack located on the left side about half way down the slope. Water is seeping up through the crack. Left sidewall also exhibits some structural cracking. The right sidewall has some surface cracking and has experienced some erosion at its contact with the downstream face of the weir structure.

STILLING BASIN
PLUNGE POOL

None observed.

DISCHARGE CHANNEL

Trapezoidal-shaped channel apparently founded on rock. Channel bottom is relatively flat for about 250 feet downstream from the weir. The channel is obstructed by vegetation, as well as rock and soil which has eroded from the sidewalls.

BRIDGE AND PIERS

None.

EMERGENCY GATES

None.

SERVICE SPILLWAY

ITEM	OBSERVATIONS AND/OR REMARKS	NDI# PA - 186
TYPE AND CONDITION	N/A	
APPROACH CHANNEL	N/A	
OUTLET STRUCTURE	N/A	
DISCHARGE CHANNEL	N/A	

INSTRUMENTATION

ITEM	OBSERVATIONS AND/OR REMARKS	NDI# PA - 186
MONUMENTATION SURVEYS	None.	
OBSERVATION WELLS	None.	
WEIRS	None.	
PIEZOMETERS	None.	
OTHERS	N/A	

RESERVOIR AREA AND DOWNSTREAM CHANNEL			PAGE JF 8
ITEM	OBSERVATIONS AND/OR REMARKS	NDI# PA - 186	
SLOPES: RESERVOIR	Steep and heavily forested. No evidence of slope instability.		
SEDIMENTATION	None observed.		
DOWNTSTREAM CHANNEL (OBSTRUCTIONS, DEBRIS, ETC.)	Pennsylvania Route 915 crosses stream at a distance of approximately 4.5 miles downstream.		
SLOPES: CHANNEL VALLEY	Steep and heavily forested.		
APPROXIMATE NUMBER OF HOMES AND POPULATION	In the vicinity of Pennsylvania Route 915, the creek passes 5 residences which are considered sufficiently close to the stream to be potentially affected by a breach of the embankment. (Estimated population: 15-20)		

APPENDIX C
HYDROLOGY AND HYDRAULICS

PREFACE

The modified HEC-1 program is capable of performing two basic types of hydrologic analyses: 1) the evaluation of the overtopping potential of the dam; and 2) the estimation of the downstream hydrologic-hydraulic consequences resulting from assumed structural failures of the dam. Briefly, the computational procedures typically used in the dam over-topping analysis are as follows:

- a. Development of an inflow hydrograph(s) to the reservoir.
 - b. Routing of the inflow hydrograph(s) through the reservoir to determine if the event(s) analyzed would over-top the dam.
 - c. Routing of the outflow hydrograph(s) from the reservoir to desired downstream locations. The results provide the peak discharge(s), time(s) of the peak discharge(s), and the maximum stage(s) of each routed hydrograph at the downstream end of each reach.
- The evaluation of the hydrologic-hydraulic consequences resulting from an assumed structural failure (breach) of the dam is typically performed as shown below.
- a. Development of an inflow hydrograph(s) to the reservoir.
 - b. Routing of the inflow hydrograph(s) through the reservoir.
 - c. Development of a failure hydrograph(s) based on specified breach criteria and normal reservoir outflow.
 - d. Routing of the failure hydrograph(s) to desired downstream locations. The results provide estimates of the peak discharge(s), time(s) to peak and maximum water surface elevations of failure hydrographs for each location.

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 8/21/79 PROJ. NO. 79-617-186
CHKD. BY DJS DATE 8-27-79 SHEET NO. 1 OF 24



DAM STATISTICS

HEIGHT OF DAM \approx 25 FT (FIELD MEASURED)
(MEASURED FROM OUTLET INVERT EL 1307.2
TO LOW TOP OF DAM EL 1331.9)

MAXIMUM POOL STORAGE CAPACITY \approx 555 AC-FT (FROM HEC-1)
@ TOP OF DAM

NORMAL POOL STORAGE CAPACITY \approx 126 AC-FT (DESIGN; SEE NOTE 1)
 \approx 296 AC-FT (ACTUAL; SEE SHEET 3
AND HEC-1 OUTPUT)

DRAINAGE AREA \approx 2.2 SQ MI

[PLANIMETERED OFF USGS
7.5 MINUTE MAPS
TANNERY, PA QUAD]

NOTE 1: NORMAL POOL STORAGE VALUE OBTAINED FROM "REPORT
UPON THE APPLICATION OF JACK GOTHE", DATED
JULY 26, 1962, AS FOUND IN PENN DER FILES. THE
ACTUAL REPORTED VALUE WAS 41 MILLION GALLONS.

DAM CLASSIFICATION

DAM SIZE - SMALL (REF 1, TABLE 1)

HAZARD CLASSIFICATION - HIGH (FIELD OBSERVATION)

REQUIRED SDF - $1/2$ PMF TO PMF (REF 1, TABLE 3)

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 8/21/79 PROJ. NO. 79-617-196
CHKD. BY DSE DATE 8-27-79 SHEET NO. 2 OF 24



HYDROGRAPH PARAMETERS

LENGTH OF LONGEST WATERCOURSE \approx 1.8 MI

$L_{CA} \approx 0.4$ MI (MEASURED ALONG THE LONGEST WATERCOURSE
FROM THE DAM TO THE CENTROID OF THE BASIN)

LENGTH OF RESERVOIR @ NORMAL POOL \approx 0.5 MI

NOTE 2: VALUES OF L , L_{CA} AND RESERVOIR LENGTH ARE
MEASURED FROM THE 7.5 MINUTE USGS WELLS
TANNERY, PA. QUAD. ALL VARIABLES ARE DEFINED
IN REF 2, IN THE SECTION ENTITLED "SNYDER
SYNTHETIC UNIT HYDROGRAPH".

$$C_+ \approx 1.5 \\ C_p \approx 0.55$$

[SUPPLIED BY COE; ZONE 21]
[SUSQUEHANNA RIVER BASIN]

SINCE RESERVOIR LENGTH $> L_{CA}$

$$* t_p = \text{SNYDER'S STANDARD LAG} = 1.5 (L')^{0.6}$$

WHERE $L' = \text{LENGTH ALONG LONGEST WATERCOURSE}$
 $\text{FROM THE RESERVOIR INLET TO THE}$
 DRAINAGE DIVIDE

$$\therefore t_p \approx 1.5 (1.8 - 0.5)^{0.6} \approx 1.76 \text{ HR}$$

* AS PER BALTIMORE DISTRICT COUNCIL OF ENGINEERS FOR
CASES WHEN THE LENGTH OF RESERVOIR $\geq L_{CA}$

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 8-21-79 PROJ. NO. 78-617-186
CHKD. BY DTS DATE 8-27-79 SHEET NO. 3 OF 24



RESERVOIR SURFACE AREAS

SURFACE AREA (SA) @ DESIGN NORMAL POOL EL 1322 \approx 25 AC

SA @ ACTUAL ASSUMED NORMAL POOL EL 1327 \approx 44 AC

NOTE 3: ACTUAL ASSUMED NORMAL POOL EL 1327 OBTAINED FROM USGS 7.5 MINUTE WELLS TANNERY, PA QUAD. LAKE AREA @ EL 1327 MEASURED FROM SAME QUAD. ELEVATIONS GIVEN ON DESIGN DRAWINGS (APPENDIX F) MAY BE IN ERROR BY AS MUCH AS 27 FT \Rightarrow DESIGN NORMAL POOL ELEVATION OF 1295 FT (FIG 3) \approx 1322 FT. RESERVOIR SA @ EL 1322 FT (1295FT) MEASURED FROM FIG 2.

SA @ EL 1340 \approx 92 AC

(PLANIMETERED FROM USGS 7.5 MINUTE WELLS TANNERY, PA QUAD)

LOW TOP OF DAM ELEVATION \approx 1331.9 FT (FIELD MEASURED)

RATE OF SA INCREASE PER FOOT OF RESERVOIR RISE:

$$\Delta \text{SA} / \Delta H \approx (92 - 44) \text{ AC} / (1340 - 1327) \text{ FT} \approx 3.7 \text{ AC/FT}$$

$$\therefore \text{SA} @ \text{EL } 1331.9 \text{ FT} \approx 44 \text{ AC} + [3.7 \text{ AC/FT}] \times (1331.9 - 1327) \text{ FT} \approx 62 \text{ AC}$$

RESERVOIR ELEVATION @ "O" STORAGE

DESIGN NORMAL POOL VOLUME \approx $\frac{1}{3}$ HA \approx 126 AC-FT (CONC METHOD)

SA @ DESIGN NORMAL POOL EL 1322 \approx 25 AC

$$\therefore H \approx \frac{3(126 \text{ AC-FT})}{(25 \text{ AC})} \approx 15.1 \text{ FT}$$

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 8-21-79 PROJ. NO. 78-617-196
CHKD. BY DJS DATE 8-27-79 SHEET NO. 4 OF 24



ZERO VOLUME ELEVATION \approx 1322 FT - 15.1 FT \approx 1306.9 FT

NOTE 4: THE ABOVE COMPUTED "0" VOLUME ELEVATION IS PROBABLY LOWER THAN THE ACTUAL MINIMUM RESERVOIR ELEVATION; HOWEVER, IN ORDER TO COMPUTE AN ELEVATION-STORAGE RELATIONSHIP AND STILL MAINTAIN A SA \approx 25 AC @ EL 1322, THE COMPUTED ZERO VOLUME ELEVATION MUST BE INPUT INTO THE HEC-1 PROGRAM.

RESERVOIR ELEVATION-STORAGE RELATIONSHIP

COMPUTED INTERNALLY BY THE HEC-1 PROGRAM, BASED ON THE GIVEN ELEVATION VS SURFACE AREA INFORMATION AS GIVEN ABOVE (SEE SUMMARY INPUT/OUTPUT SHEETS)

PMP CALCULATIONS

- STANDARD RAINFALL INDEX = 22.2 IN. (REF 9, FIG 2)
(CORRESPONDING TO A DURATION OF 24 HRS
AND AN AREA OF 200 SQ MI)
- GEOLOGIC ADJUSTMENT FACTOR \approx 105% (REF 9, FIG 1)
(CORRESPONDING TO A LONGITUDE OF $79^{\circ} 11'$ AND
A LATITUDE OF $40^{\circ} 2'$)
- CORRECTED RAINFALL INDEX = $(22.2 \text{ IN}) \times (1.05) \approx 23.3 \text{ IN}$
- DRAINAGE AREA \approx 2.2 SQ.MI. \Rightarrow ASSUME DATA CORRESPONDING TO A 10 SQ MI AREA IS REPRESENTATIVE OF THIS BASIN:

SUBJECT DAM SAFETY INSPECTION
VALLY HI EAGLE LAKE DAM
BY WJV DATE 8-22-79 PROJ. NO. 73-617-186
CHKD. BY DJC DATE 8-37-79 SHEET NO. 5 OF 24




DURATION (HR)	PERCENT OF INDEX RAINFALL (%)	
6	117.5	FROM CCE
12	127.0	DURATION VS INDEX
24	136.0	CURVES
48	142.5	
72	145.0	


- HOP BROOK FACTOR (ADJUSTMENT FOR BASIN SHAPE AS WELL AS Fc) THE LESSER LIKELIHOOD OF A SEVERE STORM CENTERING OVER A SMALLER BASIN) CORRESPONDING TO A DA ≈ 2.2 SQ MI (< 10 SQ MI) $\Rightarrow 0.80$ (REF 4, PG 48)

SPILLWAY CAPACITY

- PROFILE OF SPILLWAY : (NOT TO SCALE)
(PRIMARILY BASED ON FIELD MEASUREMENTS AND OBSERVATIONS)



- CROSS-SECTION OF SPILLWAY : (NOT TO SCALE)
(PRIMARILY BASED ON FIELD MEASUREMENTS AND OBSERVATIONS)



SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 8-23-79 PROJ. NO. 73-617-196
CHKD. BY DJS DATE 8-27-79 SHEET NO. 6 OF 24



- SPILLWAY IS A FREE OVERFALL, CONCRETE, TRAPEZOIDAL-SHAPED WEIR STRUCTURE WHICH DISCHARGES INTO A RELATIVELY FLAT OPEN CHANNEL. THE DISCHARGE CHANNEL IS PRESENTLY CLOGGED WITH FALLEN ROCK AND SOIL FROM THE UNPROTECTED SIDEWALLS, AND BY DENSE VEGETATION GROWING WITHIN THE CHANNEL. THUS, THE CHANNEL HAS LESS OF A CONVEYANCE CAPACITY, WHICH WHEN COUPLED WITH THE RELATIVELY FLAT CHANNEL SLOPE CAN LEAD TO ADVERSE TAILWATER CONDITIONS ON THE WEIR OUTFLOWS. WEIR DISCHARGES CAN BE DEFINED BY THE RELATIONSHIP:

$$Q_w = CLH^{3/2} \quad (\text{REF 5, PG 5-3})$$

WHERE Q = DISCHARGE, IN CFS;
 L = LENGTH OF WEIR CREST \approx 30 FT;
 H = HEIGHT OF RESERVOIR ABOVE WEIR CREST
 \approx 4.7 FT (CONSIDERING THE UNEVEN CREST) PRIOR
TO EMBANKMENT OVERTOPPING; AND
 C = DISCHARGE COEFFICIENT \approx 3.1 @ $H \approx$ 4.7 FT
(@ ASSUMED DESIGN HEAD) ACCORDING TO
INFORMATION CONTAINED ON PGS 5-41 TO 5-44 OF
REF 5.

NOTE 5: THE ABOVE RELATIONSHIP IS REPRESENTATIVE FOR WEIRS WITH RECTANGULAR OPENINGS. THEREFORE, IT WILL BE APPLICABLE TO A 30FT WIDE RECTANGULAR OPENING ABOVE THE WEIR. FLOW ALONG THE INCLINE PORTIONS OF THE WEIR SECTION WILL BE ASSUMED TO OCCUR AT THE SAME VELOCITY AS THE DISCHARGE OVER THE WEIR. \Rightarrow WINGWALL FLOW WILL BE DEFINED BY THE CONTINUITY EQUATION:

$$Q_{ww} = v_w A_{ww} = (Q_w / A_w) \times A_{ww} \quad (\text{REF 5, PG 3-4})$$

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 8-23-79 PROJ. NO. 78-617-136
CHKD. BY DTS DATE 8-27-79 SHEET NO. 7 OF 24



WHERE Q_{ww} = DISCHARGE OVER THE INCLINED
WINGWALL, IN CFS;
 v_w = VELOCITY OF WEIR DISCHARGE, IN
FPS;
 A_{ww} = FLOW AREA ABOVE BOTH WINGWALLS, IN
 FT^2 ; AND
 A_w = FLOW AREA ABOVE WEIR, IN FT^2 .

- APPROACH CHANNEL LOSSES @ DESIGN FLOW :

a) APPROXIMATE APPROACH CHANNEL WIDTH \approx 30 FT;
RIGHT SIDE OF APPROACH CHANNEL VARIES FROM 0 FT HEIGHT @
ENTRANCE OF CHANNEL TO ABOUT 7.6 FT @ THE WEIR, w/
ABOUT A 1 TO 1 SIDESLOPE;
LEFT SIDE OF APPROACH CHANNEL VARIES FROM 0 FT HEIGHT @
ENTRANCE OF CHANNEL TO ABOUT 13 FT @ THE WEIR, w/ ABOUT
A 1 TO 1 SIDESLOPE.

∴ @ RESERVOIR EL 1331.9 (LOW TOP OF DAM) THE MAXIMUM
APPROACH CHANNEL DEPTH = FOREBAY DEPTH + HEAD OVER
WEIR CREST \approx 2.6 FT + 4.7 FT \approx 7.3 FT

⇒ APPROACH CHANNEL FLOW AREA = A_a

$$A_a \approx (30 \text{ ft} \times 7.3 \text{ ft}) + 2[\frac{1}{2}(7.3 \text{ ft} \times 7.3 \text{ ft})]$$

$$A_a \approx 272 \text{ ft}^2$$

b) INITIAL ESTIMATE OF DISCHARGE @ EL 1331.9 FT

$$Q_w \approx (3.1)(30 \text{ ft})(4.7 \text{ ft})^{\frac{3}{2}} \approx 950 \text{ cfs}$$

$$A_w \approx 4.7 \text{ ft} \times 30 \text{ ft} \approx 141 \text{ ft}^2$$

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 8-23-79 PROJ. NO. 78-617-186
CHKD. BY DJS DATE 8-27-79 SHEET NO. 8 OF 24



$$\therefore Q_{ww} \approx \left(\frac{950 \text{ cfs}}{141 \text{ ft}^2} \right) \times 2 \left[\frac{1}{2} (4.7 \text{ ft} \times 4.7 \text{ ft}) \right]$$

$$Q_{ww} \approx 150 \text{ cfs}$$

$$\Rightarrow Q_{\text{TOTAL}} \approx 950 \text{ cfs} + 150 \text{ cfs} \approx 1100 \text{ cfs}$$

c) AVERAGE APPROACH CHANNEL VELOCITY $\approx \frac{Q_{\text{TOTAL}}}{A_a}$

$$v_a \approx \frac{1100 \text{ cfs}}{272 \text{ ft}^2} \approx 4.0 \text{ fps}$$

$$\Rightarrow \text{AVERAGE APPROACH VELOCITY HEAD} = h_a \approx \frac{v_a^2}{2g}$$

$$h_a \approx \frac{(4.0)^2}{2g} \approx 0.25$$

ASSUMING THAT THE APPROACH CHANNEL ENTRANCE LOSS $\approx 0.1 h_a$ (REF 4, PG 379) $\Rightarrow 0.03 \text{ ft}$

d) APPROACH CHANNEL FRICTION LOSS $= h_f \approx \left[\frac{v_a^n}{1.49 R_h^{1/4}} \right]^2 \times L$

WHERE L_c = AVERAGE APPROACH CHANNEL LENGTH $\approx 70 \text{ ft}$
(FIELD ESTIMATED);

n = MANNINGS ROUGHNESS COEFFICIENT ≈ 0.05
(REF 7, PG 112; EXCAVATED CHANNEL, COBBLE BOTTOM
AND BRUSH ON SLOPES);

R_h = HYDRAULIC RADIUS = $\frac{\text{FLOW AREA}}{\text{WETTED PERIMETER}}$
FLOW AREA = $A_a \approx 272 \text{ ft}^2$, RIGHT APPROACH
WALL AVERAGES ABOUT 3.3 FT IN HEIGHT ON A
1 TO 1 SLOPE (SHEET 7) \Rightarrow PARTIAL WETTED PERIMETER
 $\approx 5.4 \text{ ft}$, LEFT APPROACH WALL HAS ABOUT A
5.3 FT REPRESENTATIVE HEIGHT @ EL 1331.9 ON A
1 TO 1 SLOPE (SHEET 7) \Rightarrow PARTIAL WETTED PERIMETER
 $\approx 7.5 \text{ ft}$ \Rightarrow TOTAL WETTED PERIMETER $\approx 30 \text{ ft} + 5.4 \approx 35.4 \text{ ft}$
 $+ 7.5 \text{ ft} \approx 42.9 \text{ ft} \Rightarrow R_h \approx \frac{272 \text{ ft}^2}{42.9 \text{ ft}} \approx 6.3 \text{ ft}$

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 8-23-79 PROJ. NO. 79-617-196
CHKD. BY DSS DATE 8-27-79 SHEET NO. 9 OF 24



$$\therefore h_f \approx (70 \text{ FT}) \left[\frac{(4.0)(0.05)}{(1.49)(6.3)} \right]^2 \approx 0.11 \text{ FT}$$

$$\therefore \text{TOTAL APPROACH CHANNEL LOSS} \approx 0.03 + 0.11 \approx 0.14 \text{ FT}$$

$$\Rightarrow \text{ACTUAL EFFECTIVE HEAD} \approx 4.7 \text{ FT} - 0.14 \text{ FT} \approx 4.56 \text{ FT}$$

- SUBMERGENCE EFFECTS :

$$\begin{aligned} \text{DISCHARGE W/O SUBMERGENCE} \Rightarrow Q_w &\approx (3.1)(30 \text{ FT})(4.56 \text{ FT})^{3/2} \approx 910 \text{ CFS} \\ Q_{ww} &\approx \left[\frac{(910 \text{ CFS})}{(45 \text{ FT} \times 30 \text{ FT})} \right] \times (4.56 \text{ FT}) \\ &\approx 140 \end{aligned}$$

$$\Rightarrow Q_{\text{TOTAL}} \approx 910 \text{ CFS} + 140 \text{ CFS} \approx 1050 \text{ CFS}$$

\therefore TAILWATER ON SPILLWAY @ $Q \approx 1050 \text{ CFS}$ IS APPROXIMATELY
@ EL 1328.7 FT (SHEET 10)

SINCE THE RESERVOIR LEVEL @ $Q \approx 1050 \text{ CFS}$ IS APPROXIMATELY
@ EL 1331.9 FT $\Rightarrow h_d \approx 1331.9 - 1328.7 \approx 3.2 \text{ FT}$
(h_d = DIFFERENCE BETWEEN RESERVOIR AND TAILWATER LEVELS)

$\therefore h_d/H_e \approx \frac{3.2}{4.56} \approx 0.70 \Rightarrow$ NO ADVERSE EFFECTS
(ASSUMING THE SUBMERGENCE RELATIONSHIP FOR AN Ogee-SHAPED
WEIR IS REPRESENTATIVE FOR THIS TRAPEZOIDAL-SHAPED
WEIR; REF 4, PG 392)

\Rightarrow SPILLWAY CAPACITY PRIOR TO EMBANKMENT
OVERTOPPING $\approx 1050 \text{ CFS}$

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 8-24-79 PROJ. NO. 78-617-196
CHKD. BY DJS DATE 8-27-79 SHEET NO. 10 OF 24



TAILWATER RATING CURVE


DUE TO THE HEIGHT OF THE SPILLWAY CEEST ABOVE THE DISCHARGE CHANNEL (ONLY \approx 4 FT), AND TO THE VERY FLAT GRADIENT OF THE DISCHARGE CHANNEL (\approx 0.7%), A BACKWATER CURVE WAS COMPUTED TO ASCERTAIN THE EFFECTS OF TAILWATER ON SPILLWAY DISCHARGES. THE BACKWATER CURVE WAS CALCULATED VIA THE HEC-2 WATER SURFACE PROFILE COMPUTER PROGRAM*. HEC-2 COMPUTES BACKWATER BY THE STANDARD STEP METHOD (REF 7, PG 274-280), BASED ON CHANNEL CROSS-SECTION INFORMATION. THE SPECIFIC CROSS-SECTION DATA USED IS GIVEN ON SHEET II. THE COMPUTATIONS WERE INITIATED AT AN APPARENT CONTROL SECTION, LOCATED ABOUT 300 FT DOWNSTREAM FROM THE SPILLWAY, BY THE ASSUMPTION OF CRITICAL DEPTH. (THE CONTROL SECTION INCLUDED THE PROFILE ALONG THE SPILLWAY DIKE; SEE FIGURE 1, APPENDIX F.) CALCULATIONS PROCEEDED UPSTREAM TO THE TOE OF THE SPILLWAY IN ONE STEP. THE RATING TABLE BELOW CORRESPONDS TO THE HEC-2 OUTPUT FOR SECTION 0.1 @ THE TOE OF THE SPILLWA (SEE SUMMARY INPUT/OUTPUT SHEETS, SHEET)

ELEVATION (FT)	Q (CFS)	ELEVATION (FT)	Q (CFS)
1323.0	0	1329.6	1700
1324.7	100	1329.9	2000
1326.0	300	1330.1	2300
1327.0	500	1330.5	2600
1327.9	700	1330.9	3000
1329.5	900	1331.4	3500
1329.7	1100	1331.9	4000
1329.2	1400		

* HEC-2 WATER SURFACE PROFILES (USER'S MANUAL), HYDROLOGIC ENGINEERING CENTER, U.S. ARMY CORPS OF ENGINEERS, DAVIS, CALIFORNIA, Nov. 1976

SPILLWAY TAILWATER SECTION S

SHEET 11 OF 24



SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 8-24-79 PROJ. NO. 78-617-186
CHKD. BY DJS DATE 8-27-79 SHEET NO. 12 OF 24



SPILLWAY RATING CURVE

AS THE HEAD ABOVE THE WEIR BECOMES SMALL, THE ROUGHNESS OF THE CREST AND THE CONTACT PRESSURE BETWEEN THE WATER AND THE CREST EXERT A LARGER INFLUENCE ON DISCHARGES. THAT IS, THE C-VALUES DECREASE WITH DECREASING HEAD. THE OPPOSITE TREND OCCURS FOR HIGHER HEADS. THEREFORE, ASSUME THAT THE DISCHARGE COEFFICIENT - HEAD RELATIONSHIP FOR THE TRAPEZOIDAL-SHAPED WEIR CAN BE REPRESENTED BY THAT FOR AN OGEE-SHAPED WEIR (REF 4, PG 379, FIG 250). THE MAXIMUM HEAD PRIOR TO OVERTOPPING OF THE EMBANKMENT IS ABOUT 4.7 FT, WHICH WILL BE ASSUMED TO BE THE DESIGN HEAD (H_0). THE DESIGN DISCHARGE COEFFICIENT (C_0) WILL BE ASSUMED TO EQUAL 3.1 (SHEET 6).

ALL DISCHARGES OVER THE WEIR ARE DEFINED BY THE $Q_w = CLH^{3/2}$ RELATIONSHIP, AND ALL DISCHARGES OVER THE INCLINED WINGWALL ARE DEFINED BY THE $Q_{ww} = (Q_w/A_w) \times A_{ww}$ RELATIONSHIP AS GIVEN ON SHEET 6. THE HEAD OVER THE WEIR WILL BE ADJUSTED TO ACCOUNT FOR APPROACH CHANNEL LOSSES BY PROPORTIONING THE COMPUTED LOSS OF 0.14 FT AT EL 1331.9 FT. ALSO, SUBMERGENCE EFFECTS WILL BE CONSIDERED ACCORDING TO THE TAILWATER RATING TABLE ON SHEET 10.

SPILLWAY RATING CURVE IS GIVEN ON SHEETS 13 AND 14.

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM

BY WJV DATE 8-24-79 PROJ. NO. 78-617-136

CHKD. BY DS DATE 8-27-79 SHEET NO. 13 OF 24



- SPILLWAY RATING TABLE : (TABLE CONTINUED ON SHEET 14)

RESERVOIR ELEVATION (FT)	① H (ft)	② H/H_e (Ft/Ft)	③ C/C_o	④ ESTIMATED LOSS (FT)	⑤ EFFECTIVE HEAD: H_e (FT)	INITIAL ESTIMATES		
						⑥ Q_w (CFS)	⑦ A_w (FT ²)	⑧ A_{ww} (FT ²)
1327	0	—	—	—	0	0	—	0
1328	0.8	0.17	0.84	2.60	0.02	0.78	50	23
1329	1.6	0.38	0.90	2.79	0.05	1.75	190	53
1330	2.8	0.60	0.94	2.91	0.08	2.72	390	82
1331	3.8	0.81	0.97	3.01	0.11	3.69	640	111
1331.9	4.7	1.0	1.0	3.10	0.14	4.56	910	137
1332	4.8	1.02	1.0	3.10	0.14	4.66	940	140
1333	5.8	1.23	1.03	3.19	0.17	5.63	1280	169
1334	6.9	1.45	1.05	3.26	0.20	6.60	1660	198
1335	7.6	1.66	1.07	3.32	0.23	7.57	2070	227
1336	8.8	1.87	1.08	3.35	0.26	8.54	2510	256
1327	9.9	2.09	1.09	3.38	0.29	9.51	2970	295

- ① Although the low spillway crest elevation is 1327 ft, the high crest elevation is 1327.5 ft, due to reservoir fluctuation - 1327.2 ft $\Rightarrow H = \text{RESERVOIR FLFL} - 1327.2 \text{ FT}$
- ② Ref 4, pg 373, Fig 250, based on H/H_e ; ③ $C \approx 3.1 \times C/C_o$; ④ Estimated loss $\approx H/H_e \times 0.14 \text{ FT}$
- ⑤ Effective Head = $H_e \approx H - \text{Approach Loss}$; ⑥ $A_{ww} \approx H_e^2$
- ⑦ $Q_w \approx C \times (30 \text{ ft}) \times H_e^{3/2}$; ⑧ $A_w \approx 30 \text{ ft} \times H_e$; ⑨ $A_{ww} \approx H_e - 5.2 \text{ ft}$
- ⑩ $1332.2 = \left(\frac{Q_w}{30 \text{ ft}} \right) \times A_{ww}$

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 8-24-79 PROJ. NO. 78-617-186
CHKD. BY DJS DATE 8-27-79 SHEET NO. 14 OF 24



- SPILLWAY RATING TABLE : (CONTINUED FROM SHEET 13)

(1) INITIAL ESTIMATE Q _T (CF ₁)	(11) TW ELEVATION (FT)	W ₀ /H ₀ (11/FR)	C _s /C (11/FR)	C _s	FINAL VALUES				RESERVOIR ELEVATION (FT)	
					(12) C _{s/c}	(13) Q _w (CF ₁)	A _w (FT ²)	A _{ww} (CF ₁)	Q _T (CF ₁)	
0	-	-	-	-	0	-	-	0	0	1327
50	1323.8	5.4	1.0	2.60	50	23	0.6	0	50	1328
200	1325.4	2.1	1.0	2.79	190	53	3.1	10	200	1329
420	1326.7	1.2	1.0	2.91	390	82	7.4	40	420	1330
720	1327.9	0.84	1.0	3.01	640	111	13.6	80	720	1331
1050	1328.7	0.70	1.0	3.10	910	137	20.9	140	1050	1331.9
1090	1328.7	0.71	1.0	3.10	940	140	21.7	150	1090	1332
1520	1329.4	0.64	0.99	3.16	1270	169	31.6	240	1510	1333
2020	1329.9	0.62	0.99	3.23	1640	199	42.6	350	1990	1334
2570	1330.5	0.59	0.99	3.29	2060	227	54.5	490	2550	1335
3170	1331.1	0.57	0.98	3.28	2460	256	67.4	650	3110	1336
3820	1331.7	0.56	0.98	3.31	2910	295	81.2	830	3740	1337

- (12) Q_T = Q_w + Q_{ww} ;
- (11) TW ELEVATION INTERPOLATED FROM SHEET 10 , BASED ON Q_T ;
- C_{s/c} FROM REF 4, PG 382, FIG 254 , BASED ON W₀/H₀ ;
- (13) C_s = C × C_{s/c}
- (14) Q_w = C_s (30 FT) H_c^{3/2} ; A_w , A_{ww} , Q_{ww} , Q_T ARE DEFINED AS ON SHEET 13

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 8-24-79 PROJ. NO. 78-617-186
CHKD. BY DTS DATE 8-27-79 SHEET NO. 15 OF 24



EMBANKMENT RATING CURVE

- LENGTH OF EMBANKMENT SUBMERGED VS RESERVOIR ELEVATION (BASED ON FIELD MEASUREMENTS)

RESERVOIR ELEVATION (FT)	EMBANKMENT LENGTH (FT)
1331.9	0
1332.0	70
1332.2	220
1332.3	310
1332.4	380
1335.7	430
1336.0	440
1337.0	450

} BASED PARTIALLY ON 10 H TO IV
SIDESLOPE OF RIGHT ABUTMENT
AS MEASURED FROM USGS TOPO MAP

- ASSUME THE EMBANKMENT ACTS LIKE A BROAD-CRESTED WEIR WHEN OVERTOPPED, w/ DISCHARGE DEFINED BY:

$$Q = CLH^{3/2} \quad (\text{SHEET } 6)$$

WHERE L = LENGTH OF EMBANKMENT INUNDATED, IN FT;
 C = DISCHARGE COEFFICIENT FOR EMBANKMENTS
 $= f(\frac{H}{L})^4/l$ WHERE l = BREADTH OF CREST ≈ 11 FT,
AND REF 12, PG 46); AND
 H = AVERAGE "FLOW-AREA WEIGHTED" HEAD ABOVE
THE LOW TOP OF DAM EL 1331.9 FT. THE CREST
PROFILE IS ROUGHLY TRIANGULAR, WITH THE
LEFT SIDE OF THE TRIANGLE TERMINATING AT
EL 1332.2 (AT THE SPILLWAY WINGWALL). THE RIGHT
SIDE OF THE TRIANGLE CONTINUES TO EL 1337.0 AND
ABOVE. THE LEFT SIDE IS ABOUT 110 FT LONG,

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 9-25-79 PROJ. NO. 79-617-196
CHKD. BY DJS DATE 8-27-79 SHEET NO. 16 OF 24



WITH A TRIANGULAR FLOW AREA UP TO EL 1332.
AND A TRAPEZOIDAL FLOW AREA ABOVE THIS
ELEVATION. THE RIGHT SIDE HAS A MAXIMUM
LENGTH OF ABOUT 340 FT, WITH A TRIANGULAR
FLOW AREA AT ALL ELEVATIONS.

RESERVOIR ELEVATION (FT)	LEFT SIDE			RIGHT SIDE			⑤ WEIGHTED H (FT)	⑥ H/l (FT/FT)
	① H ₁ (FT)	② A ₁ (FT ²)	H ₁ × A ₁ (FT ³)	③ H ₂ (FT)	④ A ₂ (FT ²)	H ₂ × A ₂ (FT ³)		
1331.9	0	-	-	0	-	-	0	-
1332.0	0.05	1.8	0.09	0.05	1.8	0.09	0.05	≈ 0.01
1332.2	0.15	16.5	2.48	0.15	16.5	2.48	0.15	0.01
1332.3	0.25	27.5	6.88	0.20	40.0	8.00	0.22	0.02
1332.4	0.35	39.5	13.5	0.25	67.5	16.9	0.29	0.03
1335.7	3.7	407	1506	1.9	608	1155	2.6	0.24
1336.0	4.0	440	1760	2.1	693	1455	2.8	0.25
1337.0	5.0	550	2750	2.6	984	2298	3.5	0.32

RESERVOIR ELEVATION (FT)	⑦ C	⑧ L (FT)	EMBANKMENT Q (CFS)
1331.9	-	0	0
1332.0	2.90	70	≈ 0
1332.2	2.95	220	40
1332.3	2.98	310	100
1332.4	2.99	330	180
1335.7	3.08	430	5550
1336.0	3.08	440	6350
1337.0	3.09	450	9100

- ① $H_1 = (\text{RESERVOIR ELEV} - 1331.9 \text{ FT})/2$ BT.
EL 1332.2, AND ABOVE EL 1331.9 ≈
 $A_1 = \frac{(\text{RESERVOIR ELEV} - 1331.9) + (\text{RESERVOIR ELEV} - 1332.2)}{2}$
 $A_1 = H_1 \times L_1$, w/ $L_1 = \frac{1}{2} L$ BELOW
EL 1332.2 FT, AND $L_1 = 110$ FT ABOVE;
② $A_2 = H_2 \times L_2$, w/ $L_2 = \frac{1}{2} L$ BELOW
EL 1332.2, AND $L_2 = L - 110$ FT ABOVE;
③ $H = [(H_1 \times A_1) + (H_2 \times A_2)] / (A_1 + A_2)$
④ REF 12, PG 46;
⑤ FROM SHEET 15;
⑥ $Q = CLH^{3/2}$

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 8-25-79 PROJ. NO. 79-617-106
CHKD. BY DJS DATE 8-31-79 SHEET NO. 17 OF 24




TOTAL FACILITY RATING CURVE

$$\text{TOTAL DISCHARGE} = \text{SPILLWAY } Q + \text{EMBANKMENT } Q$$


RESERVOIR ELEVATION (FT)	① SPILLWAY Q (CFS)	② EMBANKMENT Q (CFS)	TOTAL Q (CFS)
1327.0	0	-	0
1328.0	50	-	50
1329.0	200	-	200
1330.0	430	-	430
1331.0	720	-	720
1331.9	1050	0	1050
1332.0	1090	0	1090
1332.2	③ 1170	40	1210
1332.3	③ 1220	100	1320
1332.4	③ 1260	180	1440
1333.0	1510	④ 500	2010
1334.0	1990	④ 1570	3560
1335.0	2550	④ 3550	6100
1335.7	③ 2940	5550	8490
1336.0	3110	6350	9460
1337.0	3740	9100	12940

- ① FROM SHEET 14
- ② FROM SHEET 16
- ③ STRAIGHT-LINE INTERPOLATION
- ④ LOG-LOG INTERPOLATION




DOMESTICATED CULTIVATED SECTION

SHEET 19 CIF 24



DOWNSTREAM RIVER SECTION

SHEET 20 OF 24




SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 9-4-79 PROJ. NO. 78-617-186
CHKD. BY _____ DATE _____ SHEET NO. 21 OF 24



BREACH ASSUMPTIONS

- TYPICAL BREACH SECTION :



- HEC-1-DAM BREACHING ANALYSIS INPUTS :

(BREACHING WILL COMMENCE WHEN THE RESERVOIR LEVEL REACHES THE TOP OF DAM ELEVATION)

PLAN NUMBER AND COMMENT	BREACH BOTTOM WIDTH (FT)	MAX BREACH DEPTH (FT)	SECTION SIDESLOPES	* BREACH TIME (HRS)	NSEL @ START OF FAILURE (FT)
① MIN BREACH SECT; MIN FAIL TIME	0	25	1/2 H TO IV	0.5	1331.9
② MAX BREACH SECT; MIN FAIL TIME	200	25	4 H TO IV	0.5	1331.9
③ MIN BREACH SECT; MAX FAIL TIME	0	25	1/2 H TO IV	4.0	1331.9
④ MAX BREACH SECT; MAX FAIL TIME	200	25	4 H TO IV	4.0	1331.9
⑤ AVERAGE POSSIBLE CONDITIONS	100	25	1 H TO IV	2.0	1331.9

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 9-4-79 PROJ. NO. 78-G17-196
CHKD. BY _____ DATE _____ SHEET NO. 22 OF 24



- THE BREACH ASSUMPTIONS LISTED ON SHEET 22 ARE BASED SOMEWHAT ON INFORMATION CONCERNING EARTH DAM BREACHING PROVIDED BY THE COE, BALTIMORE DISTRICT ; AND ALSO ON THE PHYSICAL CONSTRAINTS OF THE DAM AND SURROUNDING TERRAIN :

CONSTRAINT	VALUE
HEIGHT OF DAM	≈ 25 FT (^{FIELD} _{MEASURED})
EMBANKMENT CREST LENGTH	≈ 430 FT (^{FIELD} _{MEASURED})
VALLEY BOTTOM WIDTH	≈ 200 FT (FIG 3)
VALLEY SIDESLOPES ADJACENT TO DAM :	
RIGHT WALL	} ≈ 4H TO 1V (FIG. 3)
LEFT WALL	

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY WJV DATE 9-4-79 PROJ. NO. 73-617-186
CHKD. BY _____ DATE _____ SHEET NO. 23 OF 24



HEC-1 - DAM BREACHING ANALYSIS OUTPUT :

RESERVOIR DATA

UNDER O.26 PMF CONDITIONS -

* PLAN NUMBER	VARIABLE BREACH BOTTOM WIDTH (FT)	ACTUAL MAX FLOW DURING FAULT TIME (CFS)	CORRESPONDING TIME OF FLOW (HR)	IMPERMITELED OR HECK Routed MAX Flow DURING FAIL TIME (CFS)	CORRESPONDING TIME OF FLOW (CFS)	ACTUAL PEAK FLOW THROUGH DAM (CFS)	CORRESPONDING TIME OF PEAK FLOW THROUGH DAM (CFS)	TIME OF INIITAL BREAK (HR)
①	0	4448	43.00	4448	43.00	4448	43.00	42.50
②	200	23206	42.84	20068	42.75	23206	42.94	42.50
③	0	2191	46.50	2191	46.50	2191	46.50	42.50
④	200	4393	43.58	4371	43.50	4393	43.58	42.50
⑤	100	6917	43.58	6820	43.50	6917	43.58	42.50

* SEE TABLE ON SHEET 21

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EARLF LAKE DAM
BY WJV DATE 9-4-79 PROJ. NO. 73-G17-196
CHKD. BY _____ DATE _____ SHEET NO. 24 OF 24



HEC-1 - DAM BREACHING ANALYSIS OUTPUT :

Downstream Routing Data

Under 0.26 PMF Base Flow Conditions -

PLAN NUMBER	VARIABLE BREACH POSITION WSEL (FT)	OUTPUT @ PEAK FLOW (CFS)	SECTION 4 Located 13700 FT DS FROM DAM		CORRESPONDING WSEL 2. (FT)	PEAK FLOW (CFS)	OUTPUT @ SECTION 6 Located 23500 FT DS FROM DAM		WSEL 3. (FT)	WSEL 4. (FT)	Δ ELEV (FT)
			CORRESPONDING WSEL (FT)	WSEL w/o BREACH (FT)			CORRESPONDING WSEL 2. (FT)	WSEL w/o BREACH (FT)			
①	0	3067	1168.9	1165.8	+3.1	2933	1068.0	1063.0	1063.0	1063.0	+5.0
②	200	7110	1172.5	1165.8	+6.7	5004	1070.7	1063.0	1063.0	1063.0	+7.7
③	0	1986	1167.3	1165.8	+1.5	1961	1065.6	1063.0	1063.0	1063.0	+2.6
④	200	3905	1169.8	1165.8	+4.0	3613	1069.0	1063.0	1063.0	1063.0	+6.0
⑤	100	5439	1171.3	1165.8	+5.5	4619	1070.3	1063.0	1063.0	1063.0	+7.3

1. SEE TABLE ON SHEET 21;
2. WATER SURFACE ELEVATIONS CORRESPONDING TO BREACH FLOWS (SUMMARY INPUT / OUTPUT SHEETS, SHEETS AND);
3. BASE FLOW ELEVATIONS CORRESPONDING TO THE PEAK 0.26 PMF AS INTERPOLATED FROM SHEETS AND); AND
4. Δ ELEV = CORRESPONDING WSEL - WSEL w/o BREACH

SUBJECT

DAM SAFETY INSPECTIONVALLEY-HI EAGLE LAKE DAMBY DLBDATE 9-6-79PROJ. NO. 78-617-1B6CHKD. BY WJVDATE 9-13-79SHEET NO. A OF O

BACKWATER
 CURVE COMPUTATIONS
 FOR TAILWATER
 ON SPILLWAY
 WEIR

J1	LOCN	1000	1010	SIFT	METRIC	HVINS	Q	WSEL	FO
J2	NPNTF	NPNTL	PREVS	ASFCV	XSTCH	FN	ALLDC	10W	CHAN
1.	0.000	0.0	0.0	0.0	0.0	0.0	0.0	1322.000	0.0
J3 VARIOUS CODES FOR SUMMARY PRINTOUT									
J4	0.000	39.000	42.000	43.000	1.000	2.000	3.000	26.000	0.0
J5	L.P.D.F	NUMBER	***** REQUESTED SECTION NUMBERS *****						
HC	-10.000	-10.000	0.0	0.0	0.0	0.0	0.0	0.0	0.0
0F	0.000	0.000	0.000	0.000	0.100	0.300	0.0	0.0	0.0
0T	14.000	100.000	300.000	500.000	700.000	900.000	1100.000	1400.000	1700.000
GT	2300.000	2600.000	3000.000	3500.000	4000.000	0.0	0.0	0.0	0.0
X1	0.000	9.000	40.000	75.000	0.0	0.0	0.0	0.0	0.0
GR	1351.000	0.0	1324.000	40.000	1321.000	43.000	1321.000	72.000	1324.000
GR	1376.000	225.000	1327.000	275.000	1324.000	325.000	1331.000	355.000	0.0
X1	0.100	4.000	0.0	50.000	300.000	300.000	300.000	300.000	300.000
GR	1352.000	0.0	1323.000	12.000	1323.000	42.000	1331.000	50.000	0.0
FJ	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

SUBJECT

DAM SAFETY INSPECTION

VALLEY-HI EAGLE LAKE DAM

BY DLB

DATE 9-6-79

PROJ. NO. 78-617-1A6

CHKD. BY WJV

DATE 9-13-79

SHEET NO. B OF 0



VALLEY-HI EAGLE LAKE DAM
SUMMARY PRINTOUT

SECID	ALCH	ENDIN	U	CASED.	CR14S	EG	VCH
0.200	0.0	1321.00	100.00	1321.71	1321.71	1322.06	4.75
0.200	0.0	1321.00	300.00	1322.46	1322.46	1323.17	6.74
0.200	0.0	1321.00	500.00	1323.04	1323.04	1324.01	7.88
0.200	0.0	1321.00	700.00	1323.53	1323.53	1324.73	8.76
0.200	0.0	1321.00	500.00	1323.98	1323.98	1325.36	9.43
0.200	0.0	1321.00	1100.00	1324.84	1324.84	1325.86	9.31
0.200	0.0	1321.00	1400.00	1325.41	1325.41	1326.31	9.19
0.200	0.0	1321.00	1700.00	1325.75	1325.75	1326.65	8.47
0.200	0.0	1321.00	2000.00	1326.16	1326.16	1326.92	8.12
0.200	0.0	1321.00	2300.00	1326.40	1326.40	1327.15	8.23
0.200	0.0	1321.00	2600.00	1326.55	1326.55	1327.35	8.63
0.200	0.0	1321.00	3000.00	1326.73	1326.73	1327.60	9.12
0.200	0.0	1321.00	3500.00	1326.94	1326.94	1327.89	9.67
0.200	0.0	1321.00	4000.00	1327.09	1327.09	1328.15	10.31
0.100	0.0	1323.00	100.00	1324.87	0.0	1324.73	1.89
0.100	0.0	1323.00	300.00	1326.04	0.0	1326.18	2.99
0.100	0.0	1323.00	500.00	1327.00	0.0	1327.21	3.68
0.100	0.0	1323.00	700.00	1327.79	0.0	1328.06	4.20
0.100	0.0	1323.00	900.00	1328.47	0.0	1328.81	4.64
0.100	0.0	1323.00	1100.00	1328.74	0.0	1329.19	5.36
0.100	0.0	1323.00	1400.00	1329.19	0.0	1329.90	6.24
0.100	0.0	1323.00	1700.00	1329.64	0.0	1330.40	6.99
0.100	0.0	1323.00	2000.00	1329.95	0.0	1330.83	7.93
0.100	0.0	1323.00	2300.00	1330.14	0.0	1331.31	8.67
0.100	0.0	1323.00	2600.00	1330.50	0.0	1331.63	9.24
0.100	0.0	1323.00	3000.00	1330.94	0.0	1332.48	9.95
0.100	0.0	1323.00	3500.00	1331.32	0.0	1333.24	10.83
0.100	0.0	1323.00	4000.00	1331.50	0.0	1333.98	11.58

SUBJECT DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM
BY DLB DATE 9-5-79 PROJ. NO. 78-617-186
CHKD. BY NJV DATE 9-13-79 SHEET NO. C OF 0



OVERTOPPING

DAM SAFETY INSPECTION
VALLEY HI EAGLE LAKE DAM ***** OVERTOPPING ANALYSIS *****
15-MINUTE TIME STEP AND 72-HOUR STORM DURATION

JOB SPECIFICATION							
JO	MHR	MIN	IDAY	IMIN	METRC	IPRT	NSTAN
208	0	15	0	0	0	0	0
					BRUPT	TRACE	
					0	0	
					5	0	

MULTI-PLAN ANALYSES TO BE PERFORMED
NPLAN= 1 NKTC= 6 LRTG= 1
RFLGS= .10 .20 .30 .40 .50 1.00

SUB-AREA RUNOFF COMPUTATION

INFLOW INTO VALLEY HI EAGLE LAKE

1STAO	ICOMP	IECON	ITAPE	JPLT	JPRT	I NAME	I STAGE	I AUTO
1	0	0	0	0	0	1	0	0

1HYOG	LUNG	TAREA	SNAP	HYDROGRAPH DATA	ISNOW	I NAME	LOCAL
1	1	2.20	0.00	TRSPC TRSPC RATIO	0	1	0
				0.00 0.00 0.000			

SPFT	PMS	R6	R12	R24	R48	R72	R96
0.00	23.30	117.50	127.00	136.00	142.50	145.00	0.00

TRSPC COMPUTED AT THE PROGRAM IS .800
INITIAL AND CONSTANT RAINFALL LOSSES AS PER COE

BRUPT	STKTH	ULTRK	RTOL	ERAIN	STKRS	RTION	LOSS DATA	STRUL	CNSTL	AUSMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	1.00	.05	0.00	0.00

UNIT HYDROGRAPH DATA
TP= 1.76 CP= .55 NTA= 0

BASE FLOW PARAMETERS
AS PER COE

SINU=	-1.50	ORIGIN=	-0.05	RTUR= 2.00
UNL HYDROGRAPH 4H END-OF-PERIOD ORDINATES, LAG= 1.71 HOURS, CP= .55 VOL= 1.00				
71. 19. 160. 252. 340. 408. 445. 446.				
7H1. 2H1. 250. 221. 195. 173. 152. 135.				
84. 82. 73. 64. 57. 50. 44. 39.				
27. 24. 21. 18. 17. 15. 13. 11.				

APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SHYDER CP AND TP ARE TC= 7.81 AND RE= 8.11 INTERVALS

SUBJECT DAM SAFETY INSPECTION
VALLEY - HI EAGLE LAKE DAM
BY DLB DATE 9-5-79 PROJ. NO. 78-617-186
CHKD. BY WJV DATE 9-13-79 SHEET NO. D OF 0



**Engineers • Geologists • Planners
Environmental Specialists**

ROCKS THROUGH HISTORY

	LSTAO	LCUMP	LECON	LIAPE	JPLT	JPT	INAME	IStage	IAUTO
LOSS	101	1	0	0	0	0	0	1	0
			ROUTING DATA						
LOSS	CLOSS	Avg	TRES	ISAME	IUPT	IPMP			
	0.0	0.000	0.00	1	1	0			
SURFACE AREA=	0.	25.	44.	62.	92.				
CAPACITY=	0.	126.	296.	555.	1174.				
ELEVATION=	1307.	1322.	1327.	1332.	1340.				
	CREL	SPWID	COOW	EXPW	ELEV	COOL	CAREA	EXPL	
	1327.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	DAM DATA								
	TOPEL	CUDD	EXPD	DAMWID					
	1331.9	0.0	0.0	0.0					

SUBJECT DAM SAFETY INSPECTION
VALLEY - HI EAGLE LAKE DAM
BY DLB DATE 9-5-79 PROJ. NO. 78-617-186
CHKD. BY BMM DATE 9-13-79 SHEET NO. E OF 0



PEAK DURATION 60		PEAK AT TIME 43.25 HOURS		PEAK DURATION 15		PEAK AT TIME 42.75 HOURS		PEAK DURATION 15		PEAK AT TIME 41.75 HOURS	
CFS	PEAK 821.	0-1 HOUR	24-HOUR	72-HOUR	TOTAL VOLUME	CFS	PEAK 867.	0-1 HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CMS	23.	19.	H.	3.	27359.	CFS	067.	268.	95.	95.	27359.
Inches		2.62	4.54	4.82	775.	CMS		H.	3.	3.	775.
		21.59	115.34	122.43	4.82					4.82	4.82
MM	AC-FI	331.	533.	565.	565.	MM	AC-FI	122.43	122.43	122.43	122.43
		408.	657.	691.	697.					565.	565.
PEAK DURATION 15		PEAK AT TIME 42.75 HOURS		PEAK DURATION 15		PEAK AT TIME 42.75 HOURS		PEAK DURATION 15		PEAK AT TIME 41.75 HOURS	
CFS	PEAK 1441.	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME	CFS	PEAK 1054.	409.	143.	143.	41246.
CMS	41.	30.	12.	4.	1168.	CMS					1168.
Inches		4.46	6.91	7.27	7.27						7.27
	MM	113.16	175.62	184.58	184.58						184.58
	AC-FI	522.	811.	852.	852.						852.
		644.	1000.	1051.	1051.						1051.
PEAK DURATION 15		PEAK AT TIME 41.75 HOURS		PEAK DURATION 15		PEAK AT TIME 41.75 HOURS		PEAK DURATION 15		PEAK AT TIME 41.75 HOURS	
CFS	PEAK 5805.	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME	CFS	PEAK 4031.	1400.	482.	482.	138731.
CMS	100.	114.	40.	14.	3928.	CMS					3928.
Inches		17.04	23.68	24.44	24.44						24.44
	MM	432.08	601.53	620.92	620.92						620.92
	AC-FI	199.	217.	2866.	2866.						2866.
											3530.
											3530.
RESERVOIR CUTS LOW		WATERFALLS		RESERVOIR CUTS LOW		WATERFALLS		RESERVOIR CUTS LOW		WATERFALLS	

OVERTAPPING OCCURS @ ≈ 0.24 PMF

SUBJECT DAM SAFETY INSPECTION
VALLEY-HI EAGLE LAKE DAM

BY JLB DATE 9-5-79 PROJ. NO. 78-617-186

CHKD. BY DMM DATE 9-13-79 SHEET NO. F OF 0



Engineers • Geologists • Planners
Environmental Specialists

ADJUSTED DEPTH CHANNEL ROUTING

IN (1)	OUT (2)	IN (3)	ELMAX	ELMIN	MLNTH	SEL
0.00	1300.00	100.00	1280.00	245.00	1262.00	250.00
215.00	1202.00	450.00	1260.00	500.00	1300.00	

STATION	IN (1)	OUT (2)	IN (3)	ELMAX	ELMIN	MLNTH	SEL
0.00	1300.00	100.00	1280.00	245.00	1262.00	250.00	1258.00
215.00	1202.00	450.00	1260.00	500.00	1300.00		
STATION	0.00	3.50	7.50	15.79	29.79	49.49	74.89
	231.53	285.63	340.17	397.10	456.43	518.17	582.32
ROUTE DATA	0.00	390.50	1337.28	2998.59	5435.57	8774.80	13130.35
	54542.00	67668.64	82190.43	98105.80	115416.47	134135.94	154268.56
STAGE	1256.00	1260.24	1262.42	1264.64	1266.84	1269.05	1271.26
	1261.11	1262.32	1264.53	1266.74	1268.95	1270.16	1293.37
ROUTE	0.00	390.50	1337.28	2998.59	5435.57	8774.80	13130.35
	54542.00	67668.64	82190.43	98105.80	115416.47	134135.94	154268.56

HYDROGRAPH ROUTING

ROUTE FROM SECTION 2 TO SECTION 3 + 10460 FT DS FROM DAM

STAG	ICOMP	LEGUN	ITAPE	JPTR	INAME	ISTAGE	IAUTO
203	1	0	0	0	1	0	0
0.0	0.000	0.00	1	1	0	0	0
0.0	0.000	0.00	1	0	0	0	0
0.0	0.000	0.00	1	0	0	0	0
0.0	0.000	0.00	1	0	0	0	0
0.0	0.000	0.00	1	0	0	0	0
0.0	0.000	0.00	1	0	0	0	0

ROUTED DEPTH CHANNEL ROUTING

IN (1)	OUT (2)	IN (3)	ELMAX	ELMIN	MLNTH	SEL
0.00	1220.00	300.00	1200.00	1000.00	1180.00	1000.00
1030.00	1160.00	1400.00	1200.00	2100.00	1220.00	
STORAGE	0.00	242.61	73.42	174.28	325.20	526.18
	1610.00	22d1.2d	2178.69	4323.28	3914.46	4552.41
WATERFALL	0.00	271.40	940.29	2270.39	4665.66	8450.21
	17500.53	19210.01	120606.23	146396.86	179739.69	214939.30

CROSS SECTION COORDINATES--STA.ELEV STA.ELEV--EIC
0.00 1220.00 300.00 1200.00 1000.00 1180.00 1000.00 1176.00 1176.00
1030.00 1160.00 1400.00 1200.00 2100.00 1220.00
STORAGE
WATERFALL

SUBJECT DAM SAFETY INSPECTION
VALLEY-HI EAGLE LAKE DAM
BY DLB DATE 9-5-79 PROJ. NO. 78-617-186
CHKD. BY BMM DATE 9-13-79 SHEET NO. G OF 0



ԱՅՆԿՐԱՔԻ ԽՈՎՏԼԱՆ

THE JOURNAL OF CLIMATE

ISTAG	LCOMP	LECON	LTAPE	JPLT	JPT	LNAME	LSTAGE	LAUTO
304	1	0	0	0	0	1	0	0
		ROUTING DATA						
CLASS	Avg	ARES	ISAME	10PT	1PAP			LASTR
0.0	0.000	0.00	1	0	0			0
ASTRS	NSFDL	LAG	AMSK	X		TSK	STUKA	ISPRAT
1	0	0	0.000	0.000	0.000			0

VOL. 4, NO. 1, DECEMBER 1951 COUNCIL OF THE AMERICAN RAILROADS

CROSS SECTION COORDINATES--STA., ELEV.--ETC

STURGE	0.00	4.45	11.25	28.59	58.12	99.86	153.41	219.95	294.25
STURGE	490.75	604.93	731.00	869.15	1019.20	1181.20	1355.16	1541.07	1736.94
outflow	0.00	352.00	1242.18	2881.71	5455.70	9158.00	14162.71	20631.50	28730.84
outflow	30300.00	6134.18	80084.23	98279.01	141932.57	167619.96	196029.60	227270.19	
STAGE	1101.00	1103.58	1106.16	1168.74	1171.32	1173.89	1176.47	1179.05	1181.63
STAGE	1180.79	1189.37	1191.95	1194.53	1197.11	1199.68	1202.26	1204.84	1207.42
FLOW	0.00	352.00	1242.18	2881.71	5455.70	9158.00	14162.71	20631.50	28730.84
FLOW	50400.00	6134.18	80084.23	98279.01	141932.57	167619.96	196029.60	227270.19	

HYDROGRAPH ROUTING

ROUTE FROM SECTION A TO SECTION B AT 17940 FT DS EMIN DAM

ISNAME	ICOMM	SECIN	IYATE	JPLT	JPKT	INAME	1STAGE	IAUTO
405	1	0	0	0	0	0	0	0
CLASS	Avg	RES	ROUTING DATA					
0.000	0.000	1	1	1	1	0		
NSIPS	NSIDL	LAG	AMSK	X	X	TSK	SIUR	ISPRAT
1	0	0	0.000	0.000	0.000	0.000	-1	0

ՀԱՅԱՍՏԱՆԻ ՀԱՆՐԱՊԵՏՈՒԹՅԱՆ ԿՈՎԻԴ-19

SUBJECT

DAM SAFETY INSPECTION
VALLEY-HI EAGLE LAKE DAM

BY DLBDATE 9-5-79PROJ. NO. 78-617-186CHKD. BY BrownDATE 9-13-79SHEET NO. 14 OF 0

NURKEL depth channel routing

dist (ft)	val (ft)	val (ft)	ELNVL	ELMAX	ELMIN	SEL
0.00	1150.00	100.00	1120.00	200.00	1104.00	205.00
4250	* 0.350	1250	1100.0	1150.0	4240.	.01800

CROSS SECTION COORDINATES--STA, ELEV, STA, ELEV--ETC

0.00	1150.00	100.00	1120.00	200.00	1104.00	205.00	1100.00
250.00	1104.00	300.00	1120.00	400.00	1150.00		

STURGE	0.00	5.97	14.25	26.95	50.82	79.84	116.03	159.38	209.69
	344.73	388.99	457.75	531.00	608.74	690.98	777.71	868.93	964.65
OUTLINE	0.00	584.22	2001.16	4560.62	8105.15	12797.23	18736.97	26021.97	34875.98
STAGE	1100.00	1102.04	1105.26	1107.89	1110.53	1113.16	1115.79	1118.42	1121.05
	1120.32	1128.95	1131.58	1134.21	1136.84	1139.47	1142.11	1144.74	1147.37
END	0.00	584.22	2001.16	4560.62	8105.15	12797.23	18736.97	26021.97	34875.98
	51329.37	70764.94	85714.31	102212.27	120295.33	140001.06	161367.71	184433.91	209238.50

HYDROGRAPH ROUTING

ROUTE FROM SECTION 5 TO SECTION 6 * 23500 FT DS FROM DAM (* RT 915 BRIDGE)

1STAQ	1CURL	1ECON	1TAPE	1PLT	1PRT	1NAME	1STAGE	1NAME	1AUTU
SUB	1	0	0	0	0	1	0	0	0
0.00	CLOSS	Avg	ROUTING DATA						
0.0	0.000	0.00	ARES	ISAME	IPRT	1EMP	LSTR	LSTR	
				1	0	0			
NATL'S	MBFL	LAG	ASMK	X	WTK	SIUWA	ISPRAT		
1	0	0	0.000	0,000	0.000	-1.	0		

NURKEL depth channel routing

dist (ft)	val (ft)	ELNVL	ELMAX	ELMIN	SEL
0.00	1150.00	1057.0	1100.0	5560.	.00300

0.00	1150.00	200.00	1050.00	1067.00	1051.00	1057.00	1081.00	1057.00
1002.00	1007.00	1700.00	1080.00	1900.00	1100.00			

STURGE	0.00	5.97	14.25	26.95	50.82	79.84	116.03	159.38	209.69
	1241.05	1677.95	2126.75	2592.61	3069.55	3559.56	4062.65	4578.82	5108.05
OUTLINE	0.00	254.51	744.49	1376.70	2107.11	3064.65	4870.70	8143.56	13401.18
	516.57.94	47161.36	60097.36	87867.93	112397.35	139619.21	169487.41	201970.35	237047.19



Engineers • Geologists • Planners
Environmental Specialists

SUBJECT

DAM SAFETY INSPECTION

VALLEY-HI EAGLE LAKE DAM

BY DLB DATE 9-5-79

PROJ. NO. 78-617-186

CHKD. BY BMM DATE 9-13-79

SHEET NO. I OF 0



SUMMARY OF DAM SAFETY ANALYSIS					
ELEVATION	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM		
STORAGE	1327.00	1327.00	1331.90		
OUTFLOW	296.	296.	555.		
	0.	0.	1050.		

RATIO	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.10	1329.09	0.00	427.	359.	0.00	43.75
.20	1331.29	0.00	518.	827.	0.00	43.25
.30	1332.40	.50	580.	1441.	3.00	42.75
.40	1333.05	1.15	628.	2082.	4.50	42.50
.50	1333.98	1.28	657.	2755.	5.50	42.25
1.00	1334.91	3.01	751.	3865.	8.25	41.75

PLAN 1 STATION 102					
RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS		
.10	360.	1260.0	43.75		
.20	827.	1261.2	43.25		
.30	1437.	1262.6	42.75		
.40	2080.	1263.4	42.50		
.50	2758.	1264.3	42.25		
1.00	5847.	1267.4	41.75		

PLAN 1 STATION 203					
RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS		
.10	358.	1178.6	44.00		
.20	822.	1180.3	43.50		
.30	1304.	1181.4	43.25		
.40	2002.	1182.5	43.00		
.50	2634.	1183.3	42.75		
1.00	5595.	1185.8	42.50		

PLAN 1 STATION 304					
RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS		
.10	458.	1163.0	44.00		
.20	821.	1164.9	43.75		
.30	1301.	1166.4	43.50		
.40	1996.	1167.4	43.25		
.50	2627.	1168.3	43.00		
1.00	5582.	1171.4	42.50		

SUBJECT DAM SAFETY INSPECTION
VALLEY-HI EAGLE LAKE DAM

Y DLB DATE 9-5-79 PROJ. NO. 78-617-186

CHKD. BY BMM DATE 9-13-79 SHEET NO. 5 OF 0



PLAN 1		STATION 405	
RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.10	357.	1101.6	44.25
.20	621.	1103.1	43.75
.30	1381.	1104.1	43.50
.40	1997.	1105.1	43.25
.50	2626.	1105.9	43.00
1.00	5572.	1108.6	42.75

PLAN 1		STATION 506	
RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.10	456.	1059.7	44.50
.20	819.	1061.8	44.00
.30	1373.	1063.8	43.75
.40	1988.	1065.7	43.50
.50	2596.	1067.2	43.25
1.00	5317.	1070.9	43.00

SUBJECT

DAM SAFETY INSPECTIONVALLEY-HI EAGLE LAKE DAMBY DLRDATE 9-6-79PROJ. NO. 78-617-186CHKD. BY BMMDATE 9-13-79SHEET NO. K OF 0BREACHING

BREACHING ANALYSIS
 CONSISTS OF SAME INPUT
 DATA AS FOR THE
 OVERTOPPING ANALYSIS
 W/ THE ADDITION OF THE
 BREACH DATA GIVEN
 HERE.

DAM SAFETY INSPECTION
 VALLEY-HI EAGLE LAKE DAM ***** BREACHING ANALYSIS *****
 15-minute TIME STEP AND 12-HOUR STORM DURATION

ITEM	MIN	MIN	DAY	JHR	MIN	METRIC	IPRT	IPRT	NSFAN
2nd	0	15	0	0	0	0	0	0	0
				JOPEK	0	0	0	0	0
				WAT	0	0	0	0	0
				DRPT	0	0	0	0	0
				TRACE	0	0	0	0	0
					5	0	0	0	0

MULTI-PLAN ANALYSIS TO BE PERFORMED
 MELIAN= 5 MELIO= 1 LRTIO= 1

REF ID: .26HYDROGRAPH ROUTINGROUTE LENGTH THROUGH RESERVOIR

PLAN
 ①

DAM DATA		DAM DATA	
TYPEID	CODID	EXPD	DAMWID
1331.9	0.0	0.0	0.

DAM BREACH DATA		DAM BREACH DATA	
BRECID	Z	LBM	TRAIL
0.	.50	1307.00	.50 1327.00 1331.90

BEGIN DAM FAILURE AT 42.50 HOURS
 PEAK OUTFLOW IS .9440. AT TIME 43.00 minutes

BEGIN DAM FAILURE AT 42.50 HOURS
 PEAK OUTFLOW IS 2.3200. AT TIME 43.84 HOURS

②

DAM BREACH DATA		DAM BREACH DATA	
BRECID	Z	LBM	TRAIL
200.	4.00	1307.00	.50 1327.00 1331.90

BEGIN DAM FAILURE AT 42.50 HOURS
 PEAK OUTFLOW IS 2.191. AT TIME 46.50 hours

③

DAM BREACH DATA		DAM BREACH DATA	
BRECID	Z	LBM	TRAIL
0.	.50	1307.00	4.00 1327.00 1331.90

BEGIN DAM FAILURE AT 42.50 HOURS
 PEAK OUTFLOW IS 2.191. AT TIME 46.50 hours

④

SUBJECT DAM SAFETY INSPECTION
VALLEY-HI EAGLE LAKE DAM

DLB DATE 9-5-79 PROJ. NO. 78-617-186

CHKD. BY BMM DATE 9-13-79 SHEET NO. L OF 0



DAM BREACH DATA					
	Z	R.E.L.B.W.	T.F.A.I.L.	W.S.E.L.	F.A.I.L.T.
W.H.W.D.	2	4.00	1307.00	4.00	1327.00
W.H.W.D.	100.	4.00	1307.00	4.00	1327.00

REGUL DAM FAILURE AT 42.50 HOURS

PLAK DURFTION IS 4393. AT TIME 43.58 HOURS

REGUL DAM FAILURE AT 42.50 HOURS

PLAK DURFTION IS 6911. AT TIME 43.58 HOURS

(4)

(5)


SUBJECT DAM SAFETY INSPECTION
VALLEY-HI EAGLE LAKE DAM
BY DLB DATE 9-5-79 PROJ. NO. 78-617-186
CHKD. BY Bromy DATE 9-13-79 SHEET NO. M OF O



THE DIA BREACH HYDROGRAPH WAS DERIVED USING A TIME INTERVAL OF .042 HOURS DURING BREACH FORMATION.
DOWNSTREAM CALCULATIONS WILL USE A TIME INTERVAL OF .250 HOURS.
THIS TABLE COMPARES THE HYDROGRAPH FOR DOWNSTREAM CALCULATIONS WITH THE COMPUTED BREACH HYDROGRAPH.
INTERMEDIATE FLOWS ARE INTERPOLATED FROM END-OF-PERIOD VALUES.

TIME FROM BEGINNING OF BREACH (HOURS)	INTERPOLATED BREACH HYDROGRAPH (CFS)	COMPUTED BREACH HYDROGRAPH (CFS)		ERROR (CFS)	ACCUMULATED ERROR (AC-FT)
		CUMULATED	BREACH		
42.200	0.000	1076.	1076.	0.	0.
42.242	.042	1341.	1215.	-126.	126.
42.283	.083	1606.	1436.	-170.	296.
42.325	.125	1871.	1706.	-165.	461.
42.367	.167	2136.	2008.	-128.	589.
42.408	.208	2401.	2330.	-70.	659.
42.450	.250	2666.	2666.	0.	659.
42.492	.292	2990.	3006.	-16.	643.
42.533	.333	3313.	3345.	-32.	611.
42.575	.375	3631.	3678.	-41.	570.
42.617	.417	3961.	4002.	-41.	530.
42.659	.458	4285.	4312.	-27.	503.
43.000	.500	4609.	4609.	0.	503.
43.042	.542	4850.	4900.	-51.	452.
43.083	.583	5090.	5171.	-81.	371.
43.125	.625	5331.	5419.	-89.	283.
43.167	.667	5571.	5646.	-74.	209.
43.208	.708	5811.	5861.	-50.	159.
43.250	.750	6052.	6052.	0.	159.
43.292	.792	6180.	6215.	-35.	123.
43.333	.833	6308.	6376.	-68.	56.
43.375	.875	6416.	6510.	-74.	18.
43.417	.917	6561.	6624.	-60.	-78.
43.458	.958	6692.	6738.	-46.	-124.
43.500	1.000	6820.	6820.	0.	-124.
43.542	1.042	6786.	6888.	-102.	-226.
43.583	1.083	6752.	6917.	-164.	-390.
43.625	1.125	6719.	6905.	-186.	-571.
43.667	1.167	6865.	6851.	-166.	-743.
43.708	1.208	6651.	6755.	-104.	-847.
43.750	1.250	6618.	6618.	0.	-847.
43.792	1.292	6338.	6439.	-100.	-947.
43.833	1.333	6058.	6217.	-159.	-1506.
43.875	1.375	5719.	5956.	-171.	-1283.
43.917	1.417	5499.	5655.	-156.	-1439.
43.958	1.458	5220.	5316.	-96.	-1535.
44.000	1.500	4940.	4940.	0.	-1535.
44.042	1.542	4487.	4532.	-45.	-1580.
44.083	1.583	4033.	4095.	-62.	-1642.
44.125	1.625	3580.	3636.	-56.	-1698.
44.167	1.667	3127.	3163.	-36.	-1735.
44.208	1.708	2613.	2686.	-73.	-1748.
44.250	1.750	2220.	2220.	0.	-1748.
44.292	1.792	1965.	1783.	181.	-1566.
44.333	1.833	1709.	1400.	309.	-1257.
44.375	1.875	1454.	1095.	359.	-898.
44.417	1.917	1196.	884.	315.	-583.
44.458	1.958	945.	759.	184.	-399.
44.500	2.000	687.	687.	0.	-399.

SUBJECT DAM SAFETY INSPECTION
VALLEY-HI EAGLE LAKE DAM
BY DLB DATE 9-5-79 PROJ. NO. 78-617-186
CHKD. BY BMM DATE 9-13-79 SHEET NO. N OF O



SUBJECT DEM SAFETY INSPECTION
VALLEY-HI EAGLE LAKE DAM
BY DLB DATE 9-5-79 PROJ. NO. 78-617-186
CHKD. BY BMM DATE 9-13-79 SHEET NO. 0 OF 0



SUMMARY OF DAM SAFETY ANALYSIS

PLAN	ELEVATION OVER DAK	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	TIME OF FAILURE HOURS	
PLAN	MAXIMUM REACHING HEAD	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF FAILURE HOURS
1	1331.99	.09	500.	4440.	.56	42.50
2	1331.96	.06	598.	23206.	.30	42.84
3	1332.06	.16	564.	2191.	1.42	46.50
4	1331.97	.07	559.	4393.	.42	44.50
5	1331.97	.07	559.	6917.	.42	43.50

PLAN	STATION	STATION	SECTION @
	506		PA ROUTE 915
①			(1ST HOUSES)
②			
③			
④			
⑤			

MAX OUTFLOW
HOURS

(1ST HOUSES)

PLAN	RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
①	.26	2933.	1068.0	44.25
②	.26	5004.	1070.7	43.75
③	.26	1961.	1065.6	47.25
④	.26	3611.	1069.0	44.75
⑤	.26	4619.	1070.3	44.50

LIST OF REFERENCES


1. "Recommended Guidelines for Safety Inspection of Dams," prepared by Department of the Army Office of the Chief of Engineers, Washington, D. C. (Appendix D).
2. "Unit Hydrograph Concepts and Calculations," by Corps of Engineers, Baltimore District (L-519).
3. "Seasonal Variation of Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Duration of 6, 12, 24, and 48 Hours," Hydrometeorological Report No. 33, prepared by J. T. Riedel, J. F. Appleby and R. W. Schloemer Hydrologic Service Division Hydrometeorological Section, U. S. Department of the Army, Corps of Engineers, Washington, D. C., April 1956.
4. Design of Small Dams, U. S. Department of the Interior, Bureau of Reclamation, Washington, D. C., 1973.
5. Handbook of Hydraulic, H. W. King and E. F. Brater, McGraw-Hill, Inc., New York, 1963.
6. Standard Handbook for Civil Engineers, F. S. Merritt McGraw-Hill, Inc., New York, 1968.
7. Open-Channel Hydraulics, V. T. Chow, McGraw-Hill, Inc., New York, 1959.
8. Weir Experiments, Coefficients, and Formulas, R. E. Horton, Water Supply and Irrigation Paper No. 200, Department of the Interior, United States Geological Survey, Washington, D. C., 1907.
9. "Probable Maximum Precipitation Susquehanna River Drainage Above Harrisburg, Pennsylvania," Hydrometeorological Report 40, prepared by H. V. Goodyear and J. T. Riedel, Hydrometeorological Branch Office of Hydrology, U. S. Weather Bureau, U. S. Department of Commerce, Washington, D. C., May 1965.
10. Flood Hydrograph Package (HEC-1) Dam Safety Version, Hydrologic Engineering Center, U. S. Army Corps of Engineers, Davis, California, July 1978.
11. "Simulation of Flow Through Broad Crest Navigation Dams with Radial Gates," R. W. Schmitt, U. S. Army Corps of Engineers, Pittsburgh District.

12. "Hydraulics of Bridge Waterways," BPR, 1970, Discharge Coefficient Based on Criteria for Embankment Shaped Weirs, Figure 24, page 46.
13. Applied Hydraulics in Engineering, Morris, Henry M. and Wiggert, James N., Virginia Polytechnic Institute and State University, 2nd Edition, The Ronald Press Company, New York, 1972.
14. Standard Mathematical Tables, 21st Edition, The Chemical Rubber Company, 1973, page 15.
15. Engineering Field Manual, U. S. Department of Agriculture, Soil Conservation Service, 2nd Edition, Washington, D. C. 1969.

APPENDIX D
PHOTOGRAPHS



古
董



2



1



6

PHOTOGRAPH 5 Close-up view of concrete deterioration associated with the spillway overflow weir and sidewalls.

PHOTOGRAPH 6 View, looking downstream, of the spillway discharge channel.

PHOTOGRAPH 7 View of the downstream end of the spillway discharge channel approximately 250 feet from the overflow weir which is located along the centerline of the embankment.

PHOTOGRAPH 8 View, looking upstream, of the earth and rock dike which forms the right sidewall of the spillway channel. Note the lack of protective vegetation.



PHOTOGRAPH 9 View of the concrete headwall and unlined channel at the discharge end of the outlet conduit located at the downstream embankment toe.

PHOTOGRAPH 10 Close-up view of water draining from the area at the base of the downstream embankment toe to the left of the outlet conduit.

PHOTOGRAPH 11 View of the area immediately downstream of the dam as seen from the embankment crest.

PHOTOGRAPH 12 View of one residence located near the stream along PA Route 915 approximately 4.5 miles downstream of the embankment.



10



12



9



11


APPENDIX E
GEOLOGY

Geology

Valley Hi-Eagle Lake Dam is located in the Appalachian Mountain Section of the Valley and Ridge Province of south-central Pennsylvania. This section lies immediately east of the Allegheny Front and is a region of sharp contrast with the plateau country west of the Front. The Appalachian Mountain Section is composed of a broad band of long narrow mountain ridges and intermountane valleys which cross the state from the south-central border nearly to the northeast corner. Intense lateral compression from the southeast produced a series of high amplitude anticlines and synclines whose axes generally trend in a southwest-northeast direction. Folding was followed by uplift and, subsequent erosion cut valleys in the soft nonresistant beds and left the hard, resistant strata as ridges.

The dam and reservoir are located on Oregon Creek on the north side of an abandoned stretch of Pennsylvania Turnpike between the Rays Hill and Sideling Hill Tunnels. The area between Rays and Sideling Hill is in a gentle syncline, complicated by a minor anticline just downstream of the dam. Both structures strike northeast-southwest with the dominant syncline merging into the much larger Broad Top synclinorium to the north. Plunge along the strike of the syncline between Rays and Sideling Hills is northward so that progressively younger strata outcrop north of the site. Mississippian age strata compose the near surface bedrock in

the immediate vicinity of the dam and reservoir. Patchy remnants of the lower portion of the Mauch Chunk Formation lie along the axial trace of syncline east of the site. Portions of the reservoir are underlain by red shales and sandstones of the Mauch Chunk Formation. The more resistant, massive Pocono sandstone generally occurs along the flank of the syncline east and west of the site and also along the crest of the minor anticline just east of the dam.



AD-A079 001


GAI CONSULTANTS INC MONROEVILLE PA
NATIONAL DAM INSPECTION PROGRAM. VALLEY-HI EAGLE LAKE DAM (NDS --ETC(U)
SEP 79 B M MIHALCIN

F/G 13/13
DACP31-79-C-0013


NL

UNCLASSIFIED

2 OF 2
AD
A079001



END
DATE FILMED
2-80
DDC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-1

APPENDIX F

FIGURES

LIST OF FIGURES

<u>Figure</u>	<u>Description/Title</u>
1	General Plan (field inspection notes)
2	Location and General Layout
3	Typical Embankment Sections
4	Spillway Sections

Note: The design drawings presented herein do not represent "as-built" conditions. Elevations contained on the drawings are considered to be inaccurate.





FIGURE 1 - VALLEY-HI EAGLE LAKE
GENERAL PLAN
FIELD INSPECTION NOTES










FIGURE 2



LONGITUDINAL
SCOLECOPHY







APPENDIX G
REGIONAL VICINITY AND WATERSHED BOUNDARY MAP

