OF ADA DEISE	4°							
	×,			H. I.	1 A L	HNU		
- م ج	1			END PATE FILMER 10 - 81 DTIC				

MISSOURI

MISSOURI-GRAND-CHARITON BASIN

ADA105155

LAKE PAHO DAM MERCER COUNTY, MISSOURI MO 10108

PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM



JULY, 1978





DEPARTMENT OF THE ARMY ST. LOUIS DISTRICT, CORPS OF ENGINEERS 210 NORTH 12TH STREET ST. LOUIS, MISSOURI 63101

LMSED-FI

6 October 1978

SUBJECT: National Program of Inspection of Dams

THRU: Division Engineer, Lower Mississippi Valley, ATTN: LMVED-G

TO: HQDA (DAEN-CWE-DS), WASH DC 20314

REFER TO

1. Reference letter DAEN-CWE-DS, your office, 16 February 1978, subject as above.

2. As requested in referenced letter, inclosed are the correspondence file and final inspection report for Lake Paho Dam (Mo. 10108), which has been classified as unsafe.

FOR THE DISTRICT ENGINEER:

2 Incl as JACK R. NIEMI Chief, Engineering Division

Storen .

6 October 1978

۰.

1.1.1

· · 1

ţ

LMSED-FI

SUBJECT: Phase I Inspection Report

District Engineer Department of the Army Kansas City District, Corps of Engineers 700 Federal Building Kansas City, Missouri 64106

Lake Paho Dam (Mo. 10108), which is within the boundaries of your district, was recently inspected under the provisions of the National Program of Inspection of Non-Federal Dams. Inclosed for your information and retention is a copy of the final inspection report.

FOR THE DISTRICT ENGINEER:

SIGNED Jack R. Niemi

l Incl as JACK R. NIEMI Chief, Engineering Division

Copy furnished: LMVD, ATTN: LMVED-G DEPARTMENT OF THE ARMY U.S. ARMY ENGINEER DISTRICT, ST.LOUIS CORPS OF ENGINEERS 210 NORTH 12th ST. ST. LOUIS, MISSOURI 63101

LMSED-FI

29 September 1978

MUD OF ice LANDED

· · ·

Honorable Joseph P. Teasdale Governor of Missouri State Capitol Jefferson City, Missouri 65101

Dear Governor Teasdalet

Inclosed is a copy of the final inspection report for Lake Paho Dam (No 10106). As you realize, this dam has been classified in the unsafe, non-emergency category in accordance with criteris set forth in the National Program of Inspection of non-Federal Dams. The report on the dam's condition is presented to you for appropriate state use in assuring a safe dam. I ask that you keep me informed of the actions taken on implementing the recommendations in the dam inspection report. This follow-up action is a vitally important phase of this program.

A copy of the report has also been furnished the owner, the Missouri Department of Conservation, per your request.

As you realize, under the provisions of the Freedom of Information Act, this document will be subject to release, upon request, to interested parties, as soon as this letter arrives in your office.

At your request, we are furnishing copies of the Lake Paho Dam Inspection Report to Mr. Robert S. Townsend, Acting Director of the Missouri Department of Natural Resources, and to Dr. Wallace B. Howe, State Geologist. LNSED-TI Honorable Joseph P. Teasdala

29 September 1978

<u>.</u>

1 : 5

.....

÷.,

. .

Copies of the report are also being furnished to MG R. C. Marshall, Division Engineer, U. S. Army Engineer Division, Lower Mississippi Valley, P. O. Box 80, Vicksburg, Hississippi 39180, and to the Office of the Chief of Engineers, Washington, D.C. 20314.

2

and the second second second

Anna Landar

.

...

Sincerely yours,

• •

1 Incl As stated LEON E. MCRINNEY Colonal, CE District Engineer DEPARTMENT OF THE ARMY U.S. ARMY ENGINEER DISTRICT, ST.LOUIS CORPS OF ENGINEERS 210 NORTH 12th ST. ST. LOUIS, MISSOURI 63101

LMSED-FI

29 September 1978

い

MUD atta LMVE

Mr. Carl R. Noren, Director Missouri Department of Conservation 2901 North Ten Mile Drive Jefferson City, Missouri 63101

Dear Mr. Norent

Inclosed is a copy of the final inspection report for Lake Paho Dam (Mo. 10108). As you realize, this dam has been classified in the unsafe, non-emergency category in accordance with criteria set forth in the National Program of Inspection of non-Federal Dams. I have inclosed a copy of "Statement by The President" that explains the program.

Copies of the report have also been sent to Governor Teasdale; MG R. C. Marshall, Division Engineer, U. S. Army Engineer Division, Lower Mississippi Valley, P. O. Box 80, Vicksburg, Mississippi 39180; the Office of the Chief of Engineers, Washington, D.C. 20314; Mr. Robert S. Townsend, Acting Director of the Missouri Department of Natural Resources; and to Dr. Wallace B. Howe, State Geologist.

As you realize, under the provisions of the Freedom of Information Act, this document will be subject to release, upon request, to interested parties after receipt by Governor Teasdale or his representatives.

I would like to thank you for your cooperation in the program.

Sincerely yours,

2 Incl As stated LEON E. McKINNEY Colonel, CE District Engineer

	PAGE	READ INSTRUCTIONS
REPORT DOCUMENTATION		BEFORE COMPLETING FORM 3. RECIPIENT'S CATALOG NUMBER
	AD-A1051	1
. TITLE (and Subtitie)	1.14 11200 4	5. TYPE OF REPORT & PERIOD COVERE
Phase I Dam Inspection Report	, محمد ر ر هر	
National Dam Safety Program		Final Report.
Lake Paho Dam (MO 10108)		C. PERFORMING ORG. REPORT NUMBER
Mercer County, Missouri		
· Author(•) Hoskins-Western-Sonderegger, Inc.		8. CONTRACT OR GRANT NUMBER(*)
IL Harris P. Hese 15	- 175	DACW43-78-C-0155
PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK
U.S. Army Engineer District, St. Lo	ouis	AREA & WORK UNIT NUMBERS
Dam Inventory and Inspection Sectio		1-, 146
210 Tucker Blvd., North, St. Louis,	Mo. 63101	11101
1. CONTROLLING OFFICE NAME AND ADDRESS	. 71	12. REPORT DATE
U.S. Army Engineer District, St. Lo	,	Jul 1978
Dam Inventory and Inspection Section	-	19. NUMBER OF PAGES
210 Tucker Blvd., North, St. Louis, MONITORING AGENCY NAME & ADDRESS(11 different		Approximately 40
MURIUNING AGENUT RAME & AUDRESAM DIMENT		
National Dam Safety Program	n. Lake	UNCLASSIFIED
Paho Dam (MO 10108), Missou		154. DECLASSIFICATION/DOWNGRADING SCHEDULE
Chariton Basin, Mercer Cour		SCHEDULE
6. DISTE Missouri. Phase I Inspecti	ion Report.	<u> </u>
IS. SUPPLEMENTARY NOTES		
18. SUPPLEMENTARY NOTES 19. KEY WORDS (Continue on reverse side if necessary m	nd identify by block number)
9. KEY WORDS (Continue on reverse side if necessary #)
9. KEY WORDS (Continue on reverse side if necessary a Dam Safety, Lake, Dam Inspection, F	Private Dams	
9. KEY WORDS (Continue on reverse elde if necessary and Dam Safety, Lake, Dam Inspection, F RA ABSTRACT (Continue on reverse elde N necessary and This report was prepared under the Non-Federal Dams. This report asse respect to safety, based on availab	Private Dams and Identify by block number) National Program esses the general ple data and on v	of Inspection of condition of the dam with isual inspection, to
9. KEY WORDS (Continue on reverse elde if necessary and Dam Safety, Lake, Dam Inspection, F RA ABSTRACT (Continue on reverse elde N necessary and This report was prepared under the Non-Federal Dams. This report asse respect to safety, based on availab	Private Dams and Identify by block number) National Program esses the general ple data and on v	of Inspection of condition of the dam with isual inspection, to
	Private Dams and Identify by block number) National Program esses the general ple data and on v	of Inspection of condition of the dam with isual inspection, to
19. KEY WORDS (Continue on reverse side if necessary and Dam Safety, Lake, Dam Inspection, F 10. ABSTRACT (Continue on reverse side M necessary and This report was prepared under the Non-Federal Dams. This report asse respect to safety, based on availab	Private Dams Microsoft by block number) National Program esses the general ble data and on v to human life or	of Inspection of condition of the dam with isual inspection, to

ż

Ī

. R

> . .

ing constants and the second secon

SECURITY CLASSIFICATION OF THIS PAGE(When Date Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Date Entered)

المراجع ومحاد المراجع والمراجع

and the second second

.



DEPARTMENT OF THE ARMY ST. LOUIS DISTRICT, CORPS OF ENGINEERS 210 NORTH 12TH STREET ST. LOUIS, MISSOURI 63101

SUBJECT: Lake Paho Dam Phase 1 Inspection Report

This report presents the results of field inspection and evaluation of the Lake Paho Dam:

It was prepared under the National Program of Inspection of Non-Federal Dams

This dam has been classified as unsafe, non-emergency by the St. Louis District as a result of the application of the following criteria:

- 1) Spillway will not pass 50 percent of the Probable Maximum Flood
- 2) Overtopping could result in dom tailure
- 3) Dam failure significantly increases the hazard to loss of life downstream

SIGNED SUBMITTED BY: Chief, Engineering Division 29 SEP 1978 APPROVED BY :_____ Colonel, CE, District Engineer





29 SEP 1970

Date

Date

PHASE I REPORT

NATIONAL DAM SAFETY PROGRAM

Name of DamLake Paho DamState LocatedMissouriCounty LocatedMercer CountyStreamWest Muddy CreekDate ofJuly 13, 1978InspectionInspection

Lake Paho Dam was inspected by an interdisciplinary team of engineers from Hoskins-Western-Sonderegger, Inc. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

The guidelines used in the assessment were furnished by the Department of the Army, Office of the Chief of Engineers and developed with the help of several Federal and State agencies, professional engineering organizations, and private engineers. Based on these guidelines, this dam is classified as an intermediate size dam with a high downstream hazard potential. Failure would threaten the life and property at three homes. The estimated damage zone extends five miles downstream of the dam. Within the damage zone are one fish hatchery, three homes and four improved road crossings. The floodplain is farmed.

-Our inspection and evaluation indicates that the spillway does not meet the criteria set forth in the guidelines for a dam having the above size and hazard potential. The spillway will pass 46% of the Probable Maximum Flood without overtopping the dam. The Probable Maximum Flood (PMF) is defined as the flood that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. An additional deficiency, in accordance with the guidelines, is the lack of seepage analysis. These analyses should be obtained in the future.

Other deficiencies visually observed by the inspection team were spalling of spillway concrete, open joints in the spillway, some deterioration of riprap, bank erosion at the end of the spillway stilling basin and erosion in a few small areas on the upstream slope.

Several items of preventive maintenance need to be initiated by the owner. These are described in detail in the body of the report. Copies of the report have been furnished the dam owner and the Governor of Missouri.

E8694 tokup

29 SEP 1310

Date 29 SEP 19/0

Date

Harold P. Hoskins, P.E. Hoskins-Western-Sonderegger, Inc. Lincoln, Nebraska

APPROVED	ΒY	

SUBMITTED BY

Colonel, CE, District Engineer

Chief, Engineering Division

SIGNED



PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM LAKE PAHO DAM - ID NO. MO. 10103

TABLE OF CONTENTS

Paragraph No.	<u>Title</u>	Page No.
	SECTION 1 - PROJECT INFORMATION	
1.1 1.2 1.3	General Description of Project Pertinent Data	1 1 2
	SECTION 2 - ENGINEERING DATA	
2.1 2.2 2.3 2.4	Design Construction Operation Evaluation	5 5 5 5
	SECTION 3 - VISUAL INSPECTION	
3.1 3.2	Findings Evaluation	6 8
	SECTION 4 - OPERATIONAL PROCEDURES	
4.1 4.2 4.3 4.4 4.5	Procedures Maintenance of Dam Maintenance of Operating Facilities Description of Any Warning System in Effect Evaluation	9 9 9 9 9
	SECTION 5 - HYDRAULIC/HYDROLOGIC	
5.1	Evaluation of Features	10
	SECTION 6 - STRUCTURAL STABILITY	
6.1	Evaluation of Structural Stability	12
	SECTION 7 - ASSESSMENT/REMEDIAL MEASURES	
7.1 7.2	Dam Assessment Remedial Measures	13 14

APPENDIX A - MAPS

Plate 1 Plate 2 Plate 3 Vicinity Topography Location Map Orthophotograph

APPENDIX B - PHOTOGRAPHS

Photographs of Dam and Lake (No. 2 through No. 22)

APPENDIX C - PLANS AND REPORTS

Mo. Cons. Comm. Mo. Cons. Comm. Mo. Cons. Comm. Phase I Lake Paho Topographic Map Plan and Cross-Section Spillway Plan and Elevation Sections and Profile

APPENDIX D - HYDROLOGIC COMPUTATIONS

Plate D1

Inflow Hydrographs

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. <u>Authority</u>. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, District Engineer directed that a safety inspection of the <u>Lake</u> <u>Paho Dam be made</u>.

b. <u>Purpose of Inspection</u>. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

C. <u>Evaluation Criteria</u>. Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams." These guidelines were developed with the help of several Federal agencies and many State agencies, professional engineering organizations, and private engineers.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances.

(1) The dam is an earth fill approximately 1075 feet in length with a maximum height of approximately 40 feet. Topography adjacent to the dam is gently rolling. Soils on the lower slopes/abutments are apparently derived from fine grained glacial till.

(2) The uncontrolled spillway consists of a reinforced concrete chute over the right (west) abutment.

(3) A controlled discharge system is located toward the left (east) end of the dam.

(4) Nine catfish rearing ponds are located immediately downstream from the toe of the dam. The water levels in these ponds is maintained by means of the controlled discharge system.

b. Location. The dam is located in the west central portion of Mercer County, Missouri, as shown on Plate 2. The lake formed by the dam is shown on Plate 1 in the SE 1/4 and the N 1/2 of Section 25, T65N, R25W and the S 1/2 of Section 24, T65N, R25W with fingers extending into the NW 1/4 of Section 24, T65N, R25W, the E 1/2 of Section 23N, T65N, R25W and the W 1/2 of Section 30, T65N, R24W. The lake is also shown on the Princeton NW Orthophotograph (Plate 3). c. <u>Size Classification</u>. Criteria for determining the size classification of dams and impoundments are presented in the guidelines referenced in paragraph 1.1c above. Based on these criteria, this dam and impoundment is in the intermediate size category.

d. <u>Hazard Classification</u>. Guidelines for determining hazard classification are presented in the same guidelines as referenced in paragraph c above. Based on referenced guidelines, this dam is in the High Hazard Classification. The estimated damage zone extends five miles downstream of the dam. Within the damage zone are one fish hatchery, three homes and four improved road crossings. The floodplain is formed.

e. <u>Ownership</u>. The dam is owned by the Missouri Department of Conservation.

f. <u>Purpose of Dam.</u> The dam forms a recreational lake covering about 275 acres.

g. <u>Design and Construction History</u>. It was reported that construction of the dam began in 1949 and the lake was opened to the public in 1951. Construction plans for the dam were prepared by the Missouri Department of Conservation. Portions of these plans are included with this report as Appendix "C". The quality of reproduction is the best attainable from copy furnished.

h. <u>Normal Operating Procedure.</u> The reservoir level is relatively stable. It was reported that the maximum flow over the spillway was about 1 foot in depth in 1978. It was also reported that the lake level reached its lowest elevation in 1967 when it was 6 to 8 feet below spillway elevation.

1.3 PERTINENT DATA

a. <u>Drainage Area</u> - 2950⁺ acres.

b. Discharge at Damsite.

(1) All discharge at the damsite is through an ungated concrete weir and chute spillway and a 10" ductile iron pipe which is used to supply water to downstream fish rearing ponds. The pipe is controlled by a hinged section which is raised and lowered by cable at its intake in the reservoir and a valve at its outlet box. [here is a 36" corrugated metal pipe which was formerly used as a spillway. This pipe was plugged with concrete after the pipe collapsed in 1963.

(2) Estimated experienced maximum flood at damsite - 174 cfs which occurred in early 1978.

(3) Estimated ungated spillway capacity at maximum pool elevation (948.69) - 2026 cfs.

- c. Elevation (Feet Above M.S.L.).
- (1) Top of dam 950^+ .
- (2) Spillway crest 944^+ .
- (3) Streambed at centerline of dam 910^+ .
- (4) Maximum tailwater unknown.
- d. <u>Reservoir</u>. Length of maximum pool 9600 feet ⁺.

e. <u>Storage (Acre-feet)</u>. Top of dam - 5750 (from computed storage elevation curve).

- f. Reservoir Surface (Acres).
- (1) Top of dam 375.
- (2) Spillway crest 275.
- g. <u>Dam.</u>
- (1) Type earth embankment.
- (2) Length 1075 feet ⁺.
- (3) Height 40 feet ⁺.
- (4) Top width 20 feet.
- (5) Side Slopes -

(a) Upstream - Plans show 2.5H on 1V down to 5 foot wide berm with 3H on 1V below the berm.

(b) Downstream - Plans show 2.5H on 1V down to 5 foot wide berm and 3H on 1V below the berm.

(6) Zoning - none shown on plans.

(7) Impervious core - none shown on plans.

(8) Cutoff - Plans show a relatively shallow cutoff along the centerline with 12 foot bottom width and side slopes of 1H on 1V.

(9) Grout curtain - none shown on plans.

(10) Drains - unknown.

11) Riprap - none shown on plans but the upstream slope is covered from near the crest of the dam down to an unknown elevation with a 5 to 6 foot horizontal thickness of limestone riprap. The exposed riprap is on a slope of approximately 1.5H on 1V (determined with hand level).

h. Diversion and Regulating Tunnel. None.

i. Spillway.

(1) Type - concrete chute with modified S.A.F. stilling basin.

(2) Length of weir - 60 feet.

(3) Crest elevation - 943.69 feet m.s.l.

j. Regulating Outlets.

A 10" ductile iron pipe with hinged section at intake structure and valve at the outlet box. This outlet is used specifically to supply water to downstream fish rearing ponds. This outlet is not considered in the hydrologic analysis of the dam.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

A set of plans for constructing the dam was supplied by the Missouri Department of Conservation. Portions of these plans are shown in Appendix C.

2.2 CONSTRUCTION

It was reported that construction started in 1949 and the lake was opened to the public in 1951. No construction data were available.

2.3 OPERATION

The maximum loading on the dam was reported to be in 1978 when about 1 foot of water passed over the uncontrolled spillway.

The controlled discharge system on the left end of the dam supplies water, as needed, to the fish rearing ponds. The discharge flows through the control tower and into a 10 inch diameter ductile iron pipe which passes through the embankment to a controlled distribution box downstream from the toe of the dam.

2.4 EVALUATION

a. <u>Availability</u>. The only engineering data readily available were the construction plans shown in Appendix C.

b. <u>Adequacy</u>. The available engineering data were inadequate to make a detailed assessment of the design and construction of the dam.

c. <u>Validity</u>. Engineering data that were available were prepared by the Missouri Department of Conservation.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. <u>General</u>. A visual inspection of Lake Paho dam and appurtenances was made on July 13, 1978 by the following engineers from Hoskins-Western-Sonderegger, Inc., Lincoln, Nebraska: Garold Ulmer, Civil Engineer, Richard Walker, Hydrologist, Rey Decker, Geology and Soil Mechanics. The following Missouri Department of Conservation personnel were contacted at the dam site: Jim King and Marvin Quindorff.

Results of the observations are disucssed below.

b. <u>Dam.</u> Materials on the surface of the dam consist of plastic clays and sandy clays. The crest and downstream slope is well vegetated with grasses and legumes. They had been recently mowed and appeared to be well maintained. Rough measurements indicate that the crest of the dam slopes downward to the inlet section of the spillway from a point about 60 feet left (east) of the spillway. There is approximately 3.5 feet difference in elevation between the top of the spillway wall and the crest of the dam 60 feet eastward. (See Appendix C).

The exposed upstream slope is covered with moderately durable limestone riprap. The riprapped zone has a horizontal thickness of 5 to 6 feet and extends to the crest of the dam. It is relatively well graded with individual stones up to an estimated size of 400 lbs. The exposed riprap has a slope of about 1.5H on 1V. This upstream protection must have been added after the initial construction. There is no significant erosion on the upstream slope except in a few spots between centerline stations 1+00 and 2+00. (Stationing according to plans).

Rough measurements of the embankment section near centerline station 6+00 indicates downstream slopes of 2.5H on 1V from the crest down to the berm and 3H on 1V below the berm. A plot of the section measured during the inspection is shown in Appendix C. There was no indication of emergence of the phreatic line on the downstream slope.

There were no indications of cracks, slides, sinkholes, or abnormal deformations on the embankment.

The area adjacent to the downstream toe is very seepy from about centerline station 3+50 to 7+00 (Stationing according to plans). No boils were observed in the seepy area. The seepage water is clear and seems to be ponded in the shallow ditch that extends along the toe. Outlets from the tile lines shown on the plans were not evident. Rough measurements indicate that the water surface in the first fish rearing pond, some 25 to 30 feet downstream from the toe of the dam, is approximately 0.6 foot below the elevation of the seepage water ponded along the toe.

The abutments apparently consist of fine grained glacial till (CL or CH) containing some gravel. Such material is exposed in the right abutment immediately downstream from the spillway stilling basin. No slips or slides were observed in the abutments.

A small seepy area was noted in the left abutment along the toe of the dam at about centerline station 9+50. This is very near the location of the outlet pipe from the controlled discharge tower. A very small seepy area was also noted on the right abutment upslope from about the midpoint of the spillway chute. This area was dry at the time of inspection but it was supporting water-loving vegetation.

An old farm pond, approximately 20×20 feet, is located in a side drainage on the left abutment about 250 feet downstream from the dam. There was water in the pond at the time of inspection but it was reported that it is empty during dry periods of the year. There is no apparent connection with water in the farm pond and the reservoir.

c. Appurtenant Structures.

(1) Spillway - Rough measurements of the spillway indicate that it was built according to plans shown in Appendix C.

The 10 inch wide concrete sill along the upstream lip of the spillway is absent for about 15 feet on the left side of the spillway.

The concrete floor of the spillway adjacent and upstream from point No. 1 (J-1) shown on the plans is spalled and deteriorating. (See photo 2). A hole about 6 x 6 inches was observed at the bottom of the right (looking downstream) side wall at J-1. The expansion joint in the right side wall at J-2 was open for a width of 0.5 to 0.75 inches. Expansion joints at J-3 and J-4 were open about 0.5 inches with a hole about 3 x 3 inches at the bottom of the right side at wall joint J-3.

The weep holes in the floor of the spillway were discharging a small flow of clear effluent. However, most of the iron pipe outlets for the weep holes are corroded to the point where much of the pipe is missing.

An area approximately 5 feet wide by 30 feet long is eroded into the channel bank adjacent to and downstream from the right wing wall of the S.A.F. energy dissipator.

Water about 1 inch in depth was flowing over about a 5 foot width of right side of the spillway on the day of the inspection.

(2) The plans show a gated discharge system consisting of a 36 inch corrugated metal pipe passing under the embankment at about centerline station 2+25.(Stationing according to plans). It was reported that the corrugated metal inlet structure for this system collapsed about 1963. At that time, this discharge system was "plugged with old mattresses and other materials and the inlet pumped full of concrete". No seepage was observed at the outlet of the discharge pipe for this system.

(3) The present controlled discharge system on the left end of the dam was constructed to supply the catfish bearing ponds after the failure of the initial system. This system consists of a gate tower with an inlet pipe attached to a swivel joint. The inlet end of the pipe is raised or lowered by means of a winch and cable mounted on the control tower. The discharge flows through the control tower and into a 10 inch diameter ductile iron pipe about 125 feet in length which passes through the embankment to a controlled distribution box about 70 feet downstream from the centerline and 13 feet \pm below the reservoir surface of the dam. There is a shutoff valve in the discharge pipe located near the downstream toe of the dam, about 48 feet downstream from the centerline of the dam. The valve and the swiveled inlet were reported to be operable. The 10 inch discharge pipe was flowing full at the inspection.

The control or inlet tower for this system is tilted about 10 degrees off of vertical towards the left (east) and downstream (south) as shown in photo No. 13. It was reported that this vertical deformation was caused by ice the first year after installation. A plan view and cross section of this system is shown in Appendix C.

It was reported that this system is to be replaced in the near future. Asbestos/concrete pipe was on-site for the new system at the time of the inspection.

d. <u>Reservoir Area</u>. The reservoir area is bounded by rolling grassland and tree covered ridges. No significant erosion was noted around the shore line nor were any slips or slides evident.

e. <u>Downstream Channel</u>. The outlet channel for the spillway has a 20 foot \pm bottom width, 5 foot \pm depth with side slopes of approximately 3H on 1V from the channel banks to the flood plain. The channel is open, grassed and well maintained with no evidence of slides or erosion.

The outlet channel passes under U.S. Highway 36 about 1400 feet downstream from the dam. A house and 10 stall trailer court are located on the right (west) side of the channel just upstream from the highway bridge.

3.2 EVALUATION

None of the conditions observed are significant enough to indicate a need for immediate remedial action or a serious failure potential. Deterioration of the concrete and the open joints in the spillway channel bank erosion at the end of the spillway and erosion under and around the upstream riprap toward the right (west) end of the dam could lead to potential problems if left uncontrolled or uncorrected.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

The controlled discharge system is operated whenever water is needed for the fish rearing ponds. This system is well above the bottom of the reservoir and could not lower the normal level of the lake more than a few feet if allowed to flow uncontrolled.

4.2 MAINTENANCE OF DAM

The dam is well maintained. The spillway and riprap have suffered some deterioration.

4.3 MAINTENANCE OF OPERATING FACILITIES

The inlet tower of the controlled discharge system has been tilted for many years. This has had no apparent adverse effects on the operation of the facility. However, it was reported that this system is to be replaced.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

The inspection team is not aware of any warning system for this dam.

4.5 EVALUATION

1

If the observed deterioration of the spillway, erosion of the outlet channel and upstream riprap are allowed to continue, danger of failure of the structure could develop.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

a. <u>Design Data</u>. No original hydrologic design data were received from the owner.

b. <u>Experience Data</u>. The drainage area is developed from USGS <u>Princeton, Mo</u>. (15') Quadrangle. The reservoir water surface areas and volumes were developed from a topographic sheet furnished by the Missouri Department of Conservation. The hydraulic computations for the spillway and dam overtopping discharge ratings were made from a set of as-built plans furnished also by the Missouri Department of Conservation. These plans were checked from surveys made during the inspection.

c. Visual Observations.

(1) Approximately 15 feet of the 10" sill on the left bank of the spillway crest is broken. The spillway has some spalling near its throat. There is also some spall near the bottom of the chute.

(2) There is some erosion at the right bank at the end of the spillway stilling basin.

(3) The gate tower for the discharge pipe to the spawning ponds is leaning approximately 10° out of plumb.

(4) There are no drawdown facilities for evacuating the reservoir at present. The original low level spillway has been plugged, and the 10" diameter discharge line to the fish rearing ponds is not feasible for this purpose. However, there is pipe on the site to rebuild the discharge system to the fish rearing ponds.

(5) The spillway and exit channel are located at the immediate right abutment of the dam.

d. <u>Overtopping Potential</u>. The spillway is too small to pass the probable maximum flood without overtopping. One-half the PMF will overtop the dam by 0.3' for a period of 3.5 hours. The spillway will pass the 46% of PMF without overtopping. The existing spillway will pass the 100- year frequency flood without overtopping. The results of the routings through the dam are tabulated in regard to the following conditions.

Frequency	Inflow Discharge c.f.s.	Outflow Discharge _c.f.s.	Maximum Pool Elevation	Freeboard Top of Dam Min. Elev. 350.1	Time Dam Overtopping <u>Hr.</u>
100 Yr.	3800	900	946.7	+ 3.4	0
1/2 PMF	9500	4100	950.5	- 0.4	2.0
PMF	19200	15200	952.8	- 2.7	6.0
0.47 PMF	8800	3400	950.1	0	0

According to the recommended guidelines from the Department of the Army, Office of the Chief of Engineers, this dam is classified as intermediate size by height and storage and has a high hazard classification. Therefore, the PMF is the test for the adequacy of the dam and its spillway.

The estimated damage zone extends five miles downstream of the dam. Within the damage zone are one fish hatchery, three homes and four improved road crossings. The floodplain is farmed. This information was furnished by the St. Louis District, Corps of Engineers, in a letter dated 13 July, 1978.

I

Ι

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. <u>Visual Observations</u>. Visual observations which adversely affect the structural stability of this dam are discussed in Sections 3 and 4.

The seepage along the toe of the dam has apparently been present for many years without apparent adverse affects on the structural stability of the dam.

b. <u>Design and Construction Data</u>. No design or construction data were available relative to the structural stability of the dam.

c. <u>Operating Records</u>. No operating records were available other than as reported in Section 4.

d. <u>Post Construction Changes</u>. Post construction changes include the plugging of the initial discharge system, installation of the present discharge system and the addition of riprap on the upstream face. None of these have any apparent adverse affect upon the structural stability of the structure.

e. <u>Seismic Stability</u>. This dam is in seismic Zone 1. An earthquake of this magnitude is not expected to cause structural failure of this dam. However, such an earthquake might cause damage to the present controlled outlet system and to the abandoned (plugged) system. Displacement of rupture of these systems could cause serious danger of failure of the dam.

12

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Safety. Several items noted during the visual inspection should be corrected. These items include spalling of the concrete and open joints in the spillway, bank erosion at the end of the spillway stilling basin, some deterioration of the riprap and erosion in a few small areas on the upstream slope. Seepage along the downstream toe does not appear to have an adverse affect upon the structural stability of the dam. The 2.5/3H on IV downstream slopes on this dam will generally provide adequate factors of safety against shear failures for a dam of this height. Additional studies by an engineer experiences in earth dam design to determine seepage pressures in the downstream section and along the toe of the dam and subsequent seepage and uplift analyses would bee required to assess the affects of increasing the pool level to the top of the dam. The source of the downstream seepage near the controlled outlet structure (\pounds Sta. 9+50±) should also be investigated. The inlet tower for the controlled outlet should be repaired or replaced and control valves(s) for the system installed at or near the upstream crest of the dam.

The maximum design flood (PMF) will overtop the dam, however, the spillway will pass the flood that would result from one-half the probable maximum precipitation.

b. <u>Adequacy of Information</u>. Due to the lack of engineering design and construction data, the conclusions in this report are based upon performance history and visual observations. Seepage analyses were not found which is a deficiency that should be corrected in the future. The inspection team considers these data sufficient to support the conclusions herein.

c. <u>Urgency</u>. There does not appear to be an immediate urgency to correct the deficiencies noted in paragraph "a". These deficiencies could ultimately lead to structural failure if not corrected.

d. <u>Necessity for Phase II</u>. Based on results of the Phase I inspection, no Phase II investigation is recommended.

e. <u>Seismic Stability</u>. This dam is located in Seismic Zone 1. An earthquake of this magnitude is not expected to be hazardous to this dam. Detailed studies of historical seismic activity in the area and related analyses would be required to evaluate the potential damage to the present controlled outlet system and to the abandoned (plugged) outlet that might result from an earthquake of this magnitude.

7.2 REMEDIAL MEASURES

a. <u>Alternatives</u>. An auxiliary spillway on the left abutment would alleviate the hazards of overtopping by the probable maximum flood.

b. O&M Maintenance and Procedures.

(1) The observed deficiencies in maintaining the spillway and the upstream slope of the dam should be corrected and regular maintenance procedures should be initiated. Seepage pressures and quantities should be monitored. Periodic inspections should be made of the dam and appurtenances, with special attention to the condition of the controlled outlet and the abandoned outlet systems. APPENDIX A MAPS

ĺ

÷.,

1



and the second state of th

and the second second



a section of sectors in the sector



The strength of the state of the second state of the second state of the second state of the second state of the

1.5 1 - ----

APPENDIX B PHOTOGRAPHS



PHOTO NO. 2 SPALLING OF CONCRETE IN SPILLWAY INLET



PHOTO NO. 3 SPILLWAY LOOKING DOWN-STREAM. NOTE SPALLING OF CONCRETE AND DOWNSTREAM BANK EROSION



1

PHOTO NO. 4 LOOKING UPSTREAM IN SPILLWAY



PHOTO NO. 5 EXPANSION JOINT J-4 (LOWEST JOINT) JOINT OPEN APPROX. 1/2 INCH



PHOTO NO. 6 EXPANSION JOINT J-3 (RIGHT SIDE) JOINT OPEN APPROX. 1/2 INCH. 3" X 3" HOLE AT BOTTOM OF JOINT



PHOTO NO. 7 EXPANSION JOINT J-2 (RIGHT SIDE) JOINT OPEN APPROX. 1/2 TO 3/4 INCH



PHOTO NO. 8 EXPANSION JOINT J-2 (LEFT SIDE)



PHOTO NO. 9 EXPANSION JOINT J-1 (RIGHT SIDE) NOTE APPROX. 6" X 6" HOLE AT BOTTOM OF JOINT



PHOTO NO. 10 LOOKING EAST ALONG CREST


PHOTO NO. 11 FISH REARING PONDS DOWN-STREAM



PHOTO NO. 12 UPSTREAM FACE AND OUTLET TOWER FROM WEST



PHOTO NO. 13 OUTLET TOWER FROM SOUTH

PHOTO NO. 14 UPSTREAM SLOPE FROM EAST END





PHOTO NO. 15 DISCHARGE CONTROL BOX DOWNSTREAM FROM STA. 14+15



PHOTO NO. 16 SEEPS ALONG TOE OF DAM LOOKING WEST FROM EAST END



PHOTO NO. 17 SEEP AT TOE NEAR CENTER OF DAM. FISH REARING PONDS WATER LEVEL IS 0.6' LOWER THAN SEEP



PHOTO NO. 18 ORIGINAL SPILLWAY THAT HAS BEEN PLUGGED



PHOTO NO. 19 SPILLWAY CHUTE OUTLET CHANNEL AND FISH REARING PONDS



PHOTO NO. 20 OUTLET CHANNEL



PHOTO NO. 21 EROSION AT RIGHT SIDE OF SPILLWAY STILL-ING BASIN



PHOTO NO. 22 LOOKING UPSTREAM ACROSS FISH REARING PONDS TO DAM. PHOTO TAKEN FROM HIGHWAY 136. APPENDIX C PLANS AND REPORTS









.

and the second second

APPENDIX D HYDROLOGIC COMPUTATIONS

1 i

HYDROLOGIC COMPUTATIONS

1. The Mockes dimensionless standard curvalinear unit hydrograph and the SCS TR-20 program were used to develop the inflow hydrographs (see Plate D1).

a. Twenty-four hour, 100-year rainfall for the dam location was taken from NOAA Technical Paper 40. The 24-hour probable maximum precipitation was taken from the curves of Hydrometeorological Report No. 33 and current OCE directives furnished 3 August 1978.

b. Drainage area = 4.61 square miles.

c. Time of concentration of runoff = 1.79 hours.

d. The antecedent storm conditions were heavy rainfall and low temperatures which occurred on the previous 5 days, i.e. greater than 2.1 inches, (SCS AMCIII). The initial pool elevation was assumed at the crest of the spillway.

e. The total 24-hour storm duration losses for the 100-year storm were 1.06 inches (SCS) which is a 0.22 PMF storm. The total losses for the 24-hour duration 1/2 PMF storm were 1.1 inches. The total losses for the PMF storm were 1.2 inches. These data are based on SCS runoff curve No. 90 for 100 year storm and No. 91 for 1/2 PMF and PMF. Antecedent moisture conditions were from SCS AMCIII.

f. Average soil loss rates = 0.05 inch per hour approximately.

2. The dam outflow rates are based on the broad-crested weir equation (Q=CLH1.5) for both components; that is, the flow through the concrete chute spillway and the component of flow going over the dam top or over low elevation abutment areas H is the head on the spillway weir crest or the dam crest, L is the effective length acting as a weir, and C is an appropriate weir coefficient which varies with head and is based on U.S. Geological Survey criteria. The discharge through the 10" diameter pipe which supplies the fish rearing ponds was assumed not to contribute to the combined rating curve for the dam.

3. The Probable Maximum Flood and fractions of it were routed through the dam to determine that percentage of PMF which just overtops the dam. This result was obtained by interpolating between the 0.4 and 0.5 PMF routings respectively. The routings were made using SCS TR-20 computer program. The 100 year flood was also routed through the dam. The input PMP rainfall distributions, reservoir inflow hydrographs, and outflow hydrographs are shown on Plate D1 for the PMF and 1/2 PMF.

