

AD-A109 799

STETSON-DALE UTICA NY

F/6 13/13

NATIONAL DAM SAFETY PROGRAM. HAWKINSVILLE DAM (INVENTORY NUMBER--ETC(U)


SEP 81 J B STETSON

DACW51-81-C-0009

NL

UNCLASSIFIED

1 of 2
AD A
09799





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

AD A109799

LEVEL II

②

BLACK RIVER BASIN

HAWKINSVILLE DAM

NEW YORK

INVENTORY No. NY 895

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM


APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED

DTIC

JAN 20 1982

E

DTIC FILE COPY



NEW YORK DISTRICT CORPS OF ENGINEERS

AUGUST 1981

01 19 82 061

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM	
1. REPORT NUMBER		2. GOVT ACCESSION NO. AD-1104744	
3. TITLE (and Subtitle) Phase I Inspection Report Hawkinsville Dam Black River Basin, Oneida County, NY Inventory No. 895		4. RECIPIENT'S CATALOG NUMBER	
5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program		6. PERFORMING ORG. REPORT NUMBER	
7. AUTHOR(s) JOHN B. STETSON		8. CONTRACT OR GRANT NUMBER(s) DACW51-81-C-0009	
9. PERFORMING ORGANIZATION NAME AND ADDRESS Stetson-Dale 185 Genesee Street Utica, New York 13501		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
11. CONTROLLING OFFICE NAME AND ADDRESS Department of the Army 26 Federal Plaza New York District, CofE New York, New York 10287		12. REPORT DATE 10 September 1981	
13. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza New York District, CofE New York, NY 10287		14. NUMBER OF PAGES	
15. DISTRIBUTION STATEMENT (of this Report) Approved for public release; Distribution unlimited.		16. SECURITY CLASS. (of this report) UNCLASSIFIED	
17. DECLASSIFICATION/DOWNGRADING SCHEDULE		18. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)	
19. SUPPLEMENTARY NOTES			
20. SUBJECT TERMS (Continue on reverse side if necessary and identify by block number) Dam Safety National Dam Safety Program Visual Inspection Technology, Structural Stability Hawksville Dam Black River Basin Oneida County			
21. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. The examination of documents and visual inspection of the Hawkinsville Dam did not reveal conditions which constitute an immediate hazard to human life or property. The dam, however, has a number of problem areas which require further investigation and remedial work.			

The structural stability analysis indicates unsatisfactory stability would result from loadings which could occur under ice loading conditions and the Probable Maximum Flood (PMF) and 1/2 PMF events. A structural stability investigation should be commenced within 3 months to determine the characteristics of the uplift forces acting on the dam, the properties of the existing dam and foundation, and the effect of these conditions on the stability of the dam. Remedial work should be undertaken depending on the results of this investigation and completed within 18 months.

The hydrologic/hydraulic analysis indicates that the spillway will pass only 11% of the Probable Maximum Flood (PMF). The dam will be overtopped by 19 feet and 10 feet by the PMF and 1/2 PMF respectively. Failure of the dam during the 1/2 PMF event would significantly increase the downstream hazard from that which would exist just prior to failure of the dam. The spillway capacity, therefore, is assessed as "seriously inadequate" and the dam is assessed as unsafe, non-emergency.

The classification of "unsafe" applied to a dam because of a "seriously inadequate spillway" is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening, and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard to loss of life downstream from the dam.

It is, therefore, recommended that within 3 months of notification to the Owner, a detailed hydrologic/hydraulic investigation of the structure should be undertaken to more accurately determine the site specific characteristics of the watershed and their effect upon the overtopping potential of the dam. The results of these investigations will determine the appropriate remedial measures necessary to provide adequate spillway capacity. This remedial work should be completed within 18 months. In the interim, a detailed emergency action plan must be developed and implemented during periods of unusually heavy precipitation. Also, around-the-clock surveillance of the structure must be provided during these periods.

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Accession For	
NTIS	<input checked="" type="checkbox"/>
DTIC	<input type="checkbox"/>
Unann	<input type="checkbox"/>
JO	<input type="checkbox"/>
By	
Dist	
Avail	
Date	
A	

TABLE OF CONTENTS

	<u>Page</u>
Preface	
Assessment of General Conditions	i-ii
Overview Photograph	
Section 1 - Project Information	1-4
Section 2 - Engineering Data	5
Section 3 - Visual Inspection	6-7
Section 4 - Operation and Maintenance Procedures	8
Section 5 - Hydrologic/Hydraulic	9-11
Section 6 - Structural Stability	12-15
Section 7 - Assessment/Remedial Measures	16-17

APPENDIX

Photographs	A
Visual Inspection Checklist	B
Hydrologic/Hydraulic, Engineering Data and Computations	C
References	D
Stability Analysis	E
Previous Inspection Reports/Available Documents	F
Drawings:	G
Figure 1 - Location Map	
Figure 2 - Typical Section of Spillway	

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam:	Hawkinsville Dam I.D. No. NY 895
State Located:	New York
County:	Oneida
Watershed:	Black River Basin
Stream:	Black River
Date of Inspection:	May 22, 1981

ASSESSMENT OF GENERAL CONDITIONS

The examination of documents and visual inspection of the Hawkinsville Dam did not reveal conditions which constitute an immediate hazard to human life or property. The dam, however, has a number of problem areas which require further investigation and remedial work.

The structural stability analysis indicates unsatisfactory stability would result from loadings which could occur under ice loading conditions and the Probable Maximum Flood (PMF) and 1/2 PMF events. A structural stability investigation should be commenced within 3 months to determine the characteristics of the uplift forces acting on the dam, the properties of the existing dam and foundation, and the effect of these conditions on the stability of the dam. Remedial work should be undertaken depending on the results of this investigation and completed within 18 months.

The hydrologic/hydraulic analysis indicates that the spillway will pass only 11% of the Probable Maximum Flood (PMF). The dam will be overtopped by 19 feet and 10 feet by the PMF and 1/2 PMF respectively. Failure of the dam during the 1/2 PMF event would significantly increase the downstream hazard from that which would exist just prior to failure of the dam. The spillway capacity, therefore, is assessed as "seriously inadequate" and the dam is assessed as unsafe, non-emergency.


The classification of "unsafe" applied to a dam because of a "seriously inadequate spillway" is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening, and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard to loss of life downstream from the dam.

It is, therefore, recommended that within 3 months of notification to the Owner, a detailed hydrologic/hydraulic investigation of the structure should be undertaken to more accurately determine the site specific characteristics of the watershed and their effect upon the overtopping potential of the dam. The results of these investigations will determine the appropriate remedial measures necessary to provide adequate spillway capacity. This remedial work should be completed within 18 months. In the interim, a detailed emergency action plan must be developed and implemented during periods of unusually heavy precipitation. Also, around-the-clock surveillance of the structure must be provided during these periods.

The following remedial work should be undertaken within one year:

1. Trees and brush should be removed from the earthfilled portion of the right abutment of the dam.
2. The crest elevation of the earthfilled portion should be raised to meet the elevation of the top of concrete at the right abutment of the spillway.
3. The area where seepage occurs near the center of the earthfilled portion should be cleared of brush and the surface graded so that observations can be made of the extent and quantity of the seepage which occurs.
4. The reservoir drain should be placed in operating condition by the installation of a sluice gate operator.
5. Repairs should be made to the concrete surfaces at the left abutment to prevent further deterioration.
6. A formalized inspection system should be initiated to develop data on the conditions and maintenance operations at the facility.
7. A flood warning and emergency evacuation system should be implemented to alert the public in the event conditions occur which could result in failure of the dam.

Dale Engineering Company


John B. Stetson, President

Approved By:
Date:


for Col. W. M. Smith, Jr.
New York District Engineer

10 SEP 1981



1. OVERVIEW OF HAWKINSVILLE DAM AS VIEWED FROM
DOWNSTREAM BRIDGE.

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
HAWKINSVILLE DAM I.D. NO. NY 895
BLACK RIVER BASIN
ONEIDA COUNTY, NY

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

a. Authority

Authority for this report is provided by the National Dam Inspection Act, Public Law 92-367 of 1972. It has been prepared in accordance with a contract for professional services between Dale Engineering Company and the U.S. Army Corps of Engineers.

b. Purpose of Inspection

The purpose of this inspection is to evaluate the existing condition of the Hawkinsville Dam and appurtenant structures owned by the Hudson River-Black River Regulating District, and to determine if the dam constitutes a hazard to human life or property and to transmit findings to the U.S. Army Corps of Engineers.

This Phase I inspection report does not relieve an Owner or Operator of a dam of the legal duties, obligations or liabilities associated with the ownership or operation of the dam. In addition, due to the limited scope of services for these Phase I investigations, the investigators had to rely upon the data furnished to them. Therefore, this investigation is limited to visual inspection, review of data prepared by others, and simplified hydrologic, hydraulic and structural stability evaluations where appropriate. The investigators do not assume responsibility for defects or deficiencies in the dam or in the data provided.

1.2 DESCRIPTION

a. Description of Dam and Appurtenances

The Hawkinsville Dam is a run-of-river concrete gravity dam. The structure is approximately 300 feet long, with a maximum height of approximately 18 feet. A short embankment section is located at the right abutment of the dam. This embankment section is poorly defined and hardly discernible as a man-made embankment. An abandoned Excelsior manufacturing plant is situated downstream from the left abutment of the dam. A 5-1/2 foot diameter penstock was used to conduct flow from the impoundment to operate the machinery in the plant. Flow into the penstock is controlled by a sluice gate situated at the waterbox in the left abutment. A 4 foot high by 3 foot wide sluice gate serves as a reservoir drain and is situated in the left abutment of the dam.

b. Location

The reservoir is located in the hamlet of Hawkinsville, Town of Boonville, Oneida County, New York.

c. Size Classification

The maximum height of the dam is approximately 18 feet. The volume of the impoundment is approximately 1230 acre feet to the top of dam. Therefore, the dam is in the intermediate size classification as defined by the Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification

A residential property is located along the bank of the Black River just downstream from the dam. Several summer homes are located on the banks of the river further downstream. Therefore, the dam is in the high hazard category as defined by the Recommended Guidelines for Safety Inspection of Dams.

e. Ownership

The dam is owned by the Hudson River-Black River Regulating District.

Contact: Hudson River-Black River Regulating District
491 Eastern Boulevard
Watertown, NY 13601

Attention: Kenneth H. Mayhew

Telephone: (315) 788-5440

f. Purpose of the Dam

The dam was originally constructed to provide power for an Excelsior manufacturing plant located just below the left abutment of the dam. This use has been abandoned for several years and the facility now serves only to provide a recreational pool on the Black River.

g. Design and Construction History

The Hawkinsville Dam was constructed in 1915. There are no plans available for this structure. No information is available regarding the design or construction history of the facility.

h. Normal Operational Procedures

The sluice gate to the penstock which serves the abandoned Excelsior plant is operated annually. Representatives of the Hudson River-Black River Regulating District also provide surveillance of the facility. During normal operations, the water level in the impoundment fluctuates with run-off conditions and provides a recreational pool in the Black River. This pool is approximately 1.2 miles long with numerous summer cottages developed along its banks.

1.3 PERTINENT DATA

a. Drainage area

The drainage area of the Hawkinsville Dam is 270 square miles.

b. Discharge at Dam Site

The maximum recorded discharge at USGS gage number 04252500 was 12,400 cfs on March 28, 1913. This gage is 3-3/4 miles downstream of the dam.

Computed discharges:

Ungated spillway, top of dam	14,990 cfs
Gated drawdown *	195 cfs

c. Elevation (feet above MSL)

Top of dam	1,056
Spillway crest	1,050
Stream bed at centerline of dam	1,038 ±

d. Reservoir

Length of normal pool	6,340 ft.
-----------------------	-----------

e. Storage

Top of dam	1,230 acre ft.
Normal pool	130 acre ft.

f. Reservoir Area

Top of dam	270 acres
Spillway pool	40 acres

g. Dam

Type - concrete gravity
Length of abutments - 60 ft.
Height - 18 ft.
Freeboard between normal reservoir and top of dam - 6 ft.
Side slopes - N/A
Zoning - none
Impervious core - concrete
Grout Curtain - None

* Flow through 3 foot x 4 foot gated outlet, with reservoir at top of dam elevation.

h. Spillway

Type - Uncontrolled, inclined crest with rounded downstream corner and inclined downstream face.

Length - 300 ft.

Crest elevation - 1050

Gates - None

U/S Channel - Reservoir

D/S Channel - Natural

i. Reservoir Drain

5-1/2 ft. diameter, sluice gated penstock.

3 ft. wide x 4 ft. high, gated.

SECTION 2: ENGINEERING DATA

2.1 GEOTECHNICAL DATA

a. Geology

The Hawkinsville Dam is located on the southwest margin of the Adirondack Province which is a part of the Appalachian Highlands, the major physiographic division. The area had been subjected to glacial activity, scouring and deposition.

Bedrock, in the immediate vicinity of the dam, is of Precambrian rock, mainly granitic and syenitic gneisses. Layers of amphibolite are present in places. The gneisses have considerable strength and bearing capacity and is generally considered to be relatively impervious. Amphibolite, on the other hand, is readily susceptible to weathering and may yield rotted zones which could permit seepage. Such weathered zones are present and visible near the right bank of the channel downstream of the dam.

Outcroppings of bedrock are present, immediately below the dam, in the downstream channel from approximately the middle of the dam to the right bank. No outcrops were observed from the center of the dam to the left bank. Further downstream, and upstream of the bridge, outcrops are present bank to bank.

b. Subsurface Investigations

The 1915 report indicates that both the spillway and the dam foundation were to be set on rock. There is no indication as to whether the rock was to be treated or if the foundation was to be keyed.

2.2 DESIGN RECORDS

No records were available from the original design of the dam.

2.3 CONSTRUCTION RECORDS

No information was available concerning the original construction.

2.4 OPERATIONAL RECORDS

There are no operational records available for this dam.

2.5 EVALUATION OF DATA

The data presented in this report was obtained from the New York State Department of Conservation, Dam Safety Section. The information available appears to be reliable and adequate for a Phase I inspection report.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General

The Hawkinsville Dam was inspected on May 22, 1981. The Dale Engineering Company inspection team was accompanied on the inspection by Kenneth H. Mayhew of the Hudson River-Black River Regulating District. The water level in the impoundment was approximately 1050.3 feet. Water was cresting the spillway to the depth of approximately 4 inches. The weather during the inspection was fair.

b. Dam

The concrete gravity section of the dam was found to be generally in good condition. The section maintains alignment with no evidence detected of structural instability or displacement of the concrete section. Some surface deterioration of the concrete on the face of the spillway was evident as viewed through the cascading water. However, this deterioration was not observed to be of a severe extent. The left abutment of the spillway section suffers from some degree of concrete deterioration, however, the deterioration does not presently affect the structural integrity of the facility.

c. Abutments

The right abutment of the dam consists of an earthfill section which is heavily overgrown with trees and brush. This earthfill portion of the facility is irregular with respect to its section and the elevation of the crest. These irregularities make it hardly discernible as a man-made portion of the facility. Seepage is occurring at the toe of this embankment near the center of the earthfill portion. This area was repaired in 1973. At that time, seepage was repaired by the excavation of a cut-off trench parallel to the dike at the point of seepage near the middle of the dike. After excavation, clay was compacted in layers in the excavation from a depth well below the leak to a point well above. It is evident that this repair has not been completely successful.

d. Appurtenant Structures

The gate controlling the reservoir drain and the gate controlling flow into the penstock are completely submerged and the operating mechanism has been removed. Manipulation of the gates can only be performed through the use of portable hoisting equipment. The penstock appears to be in satisfactory structural condition when viewed from the outside. No access to the interior of the penstock is provided.

3.2 EVALUATION

The visual inspection revealed several deficiencies on this structure. No evidence of misalignment or settlement were detected in the field. The following specific items were noted:

1. The earthfilled portion of the dam at the right abutment is heavily overgrown with trees and brush;
2. The crest elevation of the earthfilled portion of the dam is depressed below the elevation of the top of the concrete at the right abutment of the spillway;
3. Minor seepage occurs near the center of the earthfilled portion at the right abutment.
4. The concrete surfaces at the left abutment of the spillway section are deteriorated.

SECTION 4 - OPERATION AND MAINTENANCE PROCEDURES

4.1 PROCEDURES

Since its abandonment as a source of power for the Excelsior plant, this facility has served only to maintain a recreational pool in the Black River. Periodic visits are made to the facility to check on the conditions at the site. The gates serving the penstock are opened annually.

4.2 MAINTENANCE OF THE DAM

Maintenance and operation of the dam is controlled by the Hudson River-Black River Regulating District. The concrete portions of the facility have not deteriorated due to lack of maintenance. The earth embankment at the right abutment suffers from lack of maintenance. No formalized inspection system is in effect at the facility.

4.3 MAINTENANCE OF OPERATING FACILITIES

The gates serving the penstock are exercised annually. The sluice gate operating mechanism has been removed to avoid vandalism.

4.4 DESCRIPTION OF WARNING SYSTEM

No warning system is in effect at present.

4.5 EVALUATION

1. A flood warning and emergency evacuation system should be implemented to warn the public should conditions occur which could result in failure of the dam.
2. A formal inspection procedure should be implemented and records maintained so that changing conditions can be readily identified.

SECTION 5: HYDROLOGIC/HYDRAULIC

5.1 DRAINAGE AREA CHARACTERISTICS

The Hawkinsville Dam is located in the northeast portion of Oneida County on the Black River in Hawkinsville, New York. Upstream of the dam site, the Black River has a drainage area of approximately 270 square miles which is characterized by mostly wooded areas. The surface area at the spillway elevation is approximately 39 acres.

5.2 ANALYSIS CRITERIA

The purpose of this investigation is to evaluate the dam and spillway with respect to their flood control potential and adequacy. This has been assessed through the evaluation of the Probable Maximum Flood (PMF) for the watershed and the subsequent routing of the flood through the reservoir and the dam's spillway system. The PMF event is that hypothetical flow induced by the most critical combination of precipitation, minimum infiltration loss and concentration of run-off of a specific location that is considered reasonably possible for a particular drainage area.

The hydrologic analysis was performed using the unit hydrograph method to develop the flood hydrograph. Due to the limited scope of this Phase I investigation, certain assumptions based on experience and existing data, were used in this analysis and in the determination of the dam's spillway capacity to pass the PMF. In the event that the dam could not pass 1/2 the Probable Maximum Flood without overtopping, additional analyses are to be performed on potential dam failures if the dam is designated as a High Hazard Classification. This process was done with the concept that if the dam was unable to satisfy this criteria, further refined hydrologic investigations would be required.

The U.S. Army Corps of Engineers' Hydrologic Engineering Center's Computer Program HEC-1 DB using the Modified Puls Method of flood routing was used to evaluate the dam, spillway capacity and downstream hazard.

Unit hydrographs were defined by Snyder coefficients, C_t and C_p . Snyder's C_t was estimated to be 2.0 for the drainage area and C_p was estimated to be 0.625. The drainage area was divided into sub-areas to model the variability in hydrologic characteristics within the drainage basin. Run-off, routing and flood hydrograph combining was then performed to obtain the flow into the reservoir. In this analysis, the reservoir pool was assumed to be at the spillway crest elevation at the start of the storm and outflow through the low level outlet was assumed to be zero.

The Probable Maximum Precipitation (PMP) was 18.7 inches according to Hydrometeorological Report (HMR #33) for a 24-hour duration storm, 200 square mile basin, while loss rates were set at 1.0 inches initial abstraction and 0.1 inches/hour continuous loss rate. The loss rate function yielded 79 percent run-off from the PMF. The peak for the PMF inflow hydrograph was 141,429 cfs and the 1/2 PMF inflow peak was 70,484 cfs. The storage capacity of the reservoir reduced these peak flows to 137,430 cfs for the PMF and 69,174 cfs for the 1/2 PMF.

5.3 SPILLWAY CAPACITY

The spillway is an uncontrolled weir with an inclined crest and rounded downstream corner. The discharge capacity of the spillway at the top of dam elevation is 14,990 cfs.

SPILLWAY CAPACITY

<u>FLOOD</u>	<u>PEAK DISCHARGE</u>	<u>CAPACITY AS % OF FLOOD DISCHARGE</u>
PMF	137,430 cfs	11%
1/2 PMF	69,174 cfs	22%

5.4 RESERVOIR CAPACITY

The reservoir storage capacity was estimated from USGS mapping and available riverbed information at Hawkinsville Dam. The resulting estimates of the reservoir storage capacity are shown below:

Top of Dam	1,230 acre feet
Spillway Crest	130 acre feet

5.5 FLOODS OF RECORD

The nearest USGS gaging station (number 04252500) is located approximately 3-3/4 miles downstream of the dam. It is located on the Black River near Boonville, New York, and has a drainage area of 295 square miles as compared to the 270 square mile drainage area at the dam. The maximum discharge for this gage was 12,400 on March 28, 1913. The period of record is from 1911 through present.

5.6 OVERTOPPING POTENTIAL

The HEC-1 DB analysis indicates that the dam will be overtopped as follows:

<u>FLOOD</u>	<u>MAXIMUM DEPTH OVER DAM</u>
PMF	18.6 feet
1/2 PMF	9.8 feet

A dam break analysis was performed to determine the significance of various dam failures on the downstream hazard. This analysis was performed with the 1/2 PMF assuming the dam to fail at the maximum elevation resulting from the 1/2 PMF. The flood elevations, due to various dam failures and the flood elevations that would exist just before the corresponding dam break induced flood wave are shown on the following page. These flood elevations are compared approximately 1100 feet downstream of the dam, which is one of the downstream hazard areas.

Flood Elevations
1100 Feet Downstream of Dam

	<u>Just Prior to Dam Break</u>	<u>Due to Dam Break</u>
Failure Time = 0.1 hrs.	1130.3	1136.5
Failure Time = 0.3 hrs.	1130.3	1136.0
Failure Time = 0.5 hrs.	1130.3	1135.4

The above elevations were estimated from USGS quad sheets. These elevations are not exact and their significance is in the difference between the elevations for the flood levels with and without the dam failure. The worst of these three cases indicates that the flood depth would increase from 10 feet to 16.5 feet due to a dam failure. The structures in this area are located about 10 to 15 feet above the stream level. Therefore, this flood depth increase of 6.5 feet indicates that the downstream hazard would be significantly increased by a dam failure under this condition.

5.7 EVALUATION

The hydrologic/hydraulic analysis establishes the spillway capacity as 11% of the Probable Maximum Flood (PMF) and 22% of the 1/2 PMF. The dam will be overtopped by 19 feet by the PMF and 10 feet under the 1/2 PMF. The stability analysis indicates unsatisfactory stability for the dam under the 1/2 PMF loading condition and the dam break analysis indicates that failure of the dam under the 1/2 PMF will increase the downstream flood levels on the order of 6.5 feet. Therefore, the spillway is assessed as seriously inadequate according to the Corps of Engineers' screening criteria.

SECTION 6: STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations

This concrete dam functions as a spillway for virtually its entire length across the Black River. A penstock controlling intake to a steel pipe flume is incorporated into the left (west) abutment structure. The flume passes into a not-in-service mill/manufacturing building situated on the west shore of the river, a short distance downstream from the dam.

The dam appears to be founded on rock as evidenced by the rock outcroppings that rise to above the river level in various areas immediately downstream of the toe. Topographically, in the vicinity of the dam, the land surface comprising the westerly shore area rises steeply, while, in contrast, the land surface adjacent to the easterly river bank is flat with some areas slightly below the river surface. A county bridge is located a few hundred feet downstream of the dam.

The spillway was cresting at the time of the inspection. This spillway, as viewed from the abutments, appears to be in relatively good condition with no indication of structural movement or other distress evident. The exposed concrete surface appears to be in relatively good condition.

Various areas of the concrete surface zones in the left abutment-intake structure suffer from spalling and surface deterioration. Noticeable erosion of concrete has occurred at about the waterline.

Visually, the right abutment is in good structural condition with the concrete surface experiencing little deterioration.

Some areas of the land surface adjacent to the east river bank, slightly upstream from the dam, are below the level of the river and the constructed dike/bank which establishes the river boundary. The surface across parts of the low areas is damp and spongy, with isolated locations of ponded water. Slight flow was noted, indicating the probability that the noted surface water is seepage from the river.

b. Design and Construction Data

No design or "as-built" drawings relating to the construction of the dam have been found. Information about the dam cross section and the river bed foundation apparently are not on record. Dimensions used to develop a cross section necessary for the stability analysis which is part of the present study were compiled from field measurements obtained during the inspection visit, and from discussions and correspondence with Kenneth Mayhew, Chief Engineer, Board of Hudson River-Black River Regulating District (see Appendix F). This latter source could obtain only information to indicate that the dam is 300 feet long and 12 feet high.

c. Operating Records

No operating records are available.

d. Post Construction Changes

The correspondence included in Appendix F indicates that the original dam at this site was constructed in 1824, and rebuilt in 1915, but no records of these construction endeavors have been made available. Mr. Mayhew indicates that some reconstruction of the earthen embankment adjacent to the east abutment was undertaken in 1973 to help correct a seepage condition.

e. Seismic Stability

Rock foliation appears to generally trend N60°E and dip about 50°SE. Joint trends and their spacing are as follows:

<u>Strike</u>	<u>Dip</u>	<u>Spacing</u>
N45E	about 90°	2 feet
N40W	80°SW	6-8 inches

A branching fracture system, with a spacing of about 1-3 feet, has a general trend of about N65°W. One of two widened joint or foliation plane openings, about 6 inches, follows a less resistant amphibolite layer.

No known faults exist in the immediate vicinity of the dam. Several small lineaments, which may represent faults, are indicated on the Brittle Structures Map. These are located about one mile to the northeast of the dam and trend northeastward.

The area is located within Zone 2 of the Seismic Probability Map. Earthquakes recorded in the area are tabulated below:

<u>Date</u>	<u>Intensity</u> <u>Modified Mercalli</u>	<u>Location</u> <u>Relative to Dam</u>
1853	VI	18 miles NW
1963	V	1 mile E
1979	IV-V	8 miles WSW
1980	VI	4 miles ENE
1980	IV-V	12 miles NE
1980	V-VI	6 miles NE

6.2 STRUCTURAL STABILITY ANALYSIS

No reports or plans have been made available to provide information on the dam design, alignment, and cross section. As part of this study, stability evaluations have been performed for the dam's spillway section. The structural cross section utilized in the analysis has been developed from field measurements obtained by the inspection team (see Appendix G). Actual properties of the dam's construction materials and river bed foundation were not determined as part of this study; where information on properties were necessary for computations but lacking, assumptions felt to be practical were made.

The studied loading conditions for the stability analysis include: a normal summer pool elevation at the spillway, the 1/2 PMF, and the PMF level, the normal spillway pool with an ice loading, and a normal spillway pool with seismic effects.

The analysis indicates adequate stability for the normal summer operations condition and normal pool with seismic effects. Calculations indicate unsatisfactory stability against overturning for the dam when subjected to forces possible during normal winter operations which include ice loading, and for the 1/2 PMF and the PMF conditions, according to criteria established by the U.S. Army Corps of Engineers' Recommended Guidelines for Safety Inspection of Dams (i.e., unsatisfactory stability is indicated where the resultant of forces acting on the dam is located outside the middle third of the dam base; tensile stresses would develop in the dam section, a condition which is structurally undesirable because of the low tensile strength of concrete). A summary of the stability analysis is presented in the table following this page. The stability computations are included in Appendix E.

Critical to the analysis and resulting indication of stability are the items of uplift water pressure acting on the base of the dam and the relative permeability of the site's foundation rock. For the "normal summer operating conditions" case, the analysis uplift force was based on a full headwater hydrostatic pressure acting on the dam's upstream corner and a zero tailwater hydrostatic pressure acting on the dam's downstream corner. Uplift pressures were assumed to vary linearly between the dam's upstream and downstream corners, and to act upon 100 percent of the dam base. Uplift as computed for the normal operating condition was also assigned to the flood conditions studied, assuming that uplift pressures would not increase significantly over a relatively short flood stage time period because of an expected low foundation rock permeability.

Because of the indications of structural instability indicated by the evaluations performed for the present study, further investigation is recommended to ascertain the as-built properties of the dam and the foundation, including determination of underdam uplift pressures. Final stability studies can be conducted on the basis of conditions revealed. The need to develop methods for improving the stability of this dam should be anticipated.

Measures to repair the zones of deteriorated concrete noted in the left abutment-intake structures should also be planned.

The suspected seepage condition existing over the land surface adjacent to the right abutment/east bank of the river does not appear to be having a significant effect on the dam structure. Planned periodic inspections of the general area should be undertaken, however, with observations documented to detect a worsening condition or other occurrence requiring corrective measures.

RESULTS OF STABILITY COMPUTATIONS

	<u>Loading Condition</u>	<u>Factor of Safety*</u>		<u>Location of Resultant Passing through Base***</u>
		<u>Overturning</u>	<u>Sliding**</u>	
(1)	Water level at spillway elevation, uplift on base (no ice)	2.0	21.4	0.54b
(2)	Water level at spillway elevation, uplift on base plus 5 kips per lineal foot ice load	1.03	10.1	0.03b
(3)	Water levels against upstream face and downstream face based on 1/2 PMF elevations, uplift same as Case 1	0.99	5.8	Outside Base F.S. < 1.0
(4)	Water level against upstream face and downstream face based on PMF elevations, uplift same as Case 1	0.91	4.3	Outside Base F.S. < 1.0
(5)	Water level at spillway elevation, uplift on base, seismic effects applicable to Zone 2	1.79	17.5	0.49b

* These factors of safety indicate the ratio of moments resisting overturning to those moments causing overturning, and the ratio of forces resisting sliding to those causing sliding. Upstream and downstream water levels were obtained from hydrologic/hydraulic analysis.

** As determined applying the shear-friction method.

*** Indicated in terms of dam's base dimension, b, measured from the toe of the dam.

SECTION 7: ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Safety

The Phase I inspection of the Hawkinsville Dam did not indicate conditions which would constitute an immediate hazard to human life or property.

The stability analysis indicates unsatisfactory stability during loadings which would occur under ice loading conditions and during the Probable Maximum Flood (PMF) and 1/2 PMF events.

The hydrologic/hydraulic analysis indicates that the spillway will pass only 11% of the PMF and 22% of the 1/2 PMF. The dam will be overtopped by 19 feet and 10 feet by the PMF and 1/2 PMF, respectively. Failure of the dam under the 1/2 PMF will increase the downstream hazard from that which would exist just prior to failure of the dam. The spillway capacity, therefore, is assessed as seriously inadequate.

The following specific safety assessment is based on the Phase I visual examination, analysis of hydrology/hydraulics and structural stability analysis.

1. The earthfilled portion of the dam at the right abutment is heavily overgrown with trees and brush.
2. The crest elevation of the earthfilled portion of the dam is depressed below the elevation of the top of concrete at the right abutment of the spillway.
3. Minor seepage occurs near the center of the earthfilled portion at the right abutment.
4. The concrete surfaces at the left abutment of the spillway section are deteriorated.
5. No formal inspection procedure is now in effect at the structure.
6. No warning system is presently in effect to alert the public should conditions occur which could result in failure of the dam.

b. Adequacy of Information

The information available is adequate for this Phase I investigation.

c. Urgency

The Owner should immediately implement a program of surveillance during heavy run-off conditions. Within three months, a flood warning and emergency evacuation plan should be implemented.

The recommended investigations should begin within 3 months. The remaining items set forth in the safety assesement should be addressed by the Owner within one year. Appropriate repairs as determined by the investigations should be performed within 18 months of notification.

d. Need for Additional Investigations

Further investigations relative to the stability of the structure should be performed to determine appropriate measures necessary to provide stability under all conditions. A detailed hydrologic/hydraulic analysis to more accurately determine the site specific characteristics of the watershed should be undertaken to determine the necessary measures to provide adequate spillway capacity. The remedial work necessary to provide this capacity should be undertaken depending on the results of this investigation.

7.2 RECOMMENDED MEASURES


The following is a list of recommended measures to be undertaken to insure safety of the facility.

1. Trees and brush should be removed from the earthfilled portion of the right abutment of the dam.
2. The crest elevation of the earthfilled portion should be raised to meet the elevation of the top of the concrete at the right abutment of the spillway.
3. The area where seepage occurs near the center of the earthfilled portion should be cleared of brush and the surface graded so that observations can be made of the extent and quantity of the seepage which occurs.
4. The reservoir drain should be placed in an operating condition by the installation of a sluice gate operator.
5. Repairs should be made to the concrete surfaces at the left abutment to prevent further deterioration.
6. A formalized inspection system should be initiated to develop data on the conditions and maintenance operations at the facility.
7. A flood warning and emergency evacuation system should be implemented to alert the public in the event conditions occur which could result in failure of the dam.

APPENDIX A
PHOTOGRAPHS



2. VIEW ALONG CREST OF
DAM FROM RIGHT
ABUTMENT.
NOTE: PENSTOCK IN
BACKGROUND EXTENDING
FROM THE DAM TO OLD
MILL DOWNSTREAM.




3. DOWNSTREAM FACE OF
DAM AS VIEWED FROM
LEFT ABUTMENT.



4. RIGHT ABUTMENT AS
VIEWED FROM DOWNSTREAM
NOTE: EMBANKMENT
ADJACENT TO ABUTMENT
IS LOWER ELEVATION
THAN ABUTMENT.
DRAINAGE COURSE IN
FOREGROUND DRAINS
SEEPAGE AREA SHOWN
IN PHOTO #9.




5. LEFT ABUTMENT AS VIEWED FROM DOWNSTREAM. LOW LEVEL OUTLET IN LOWER LEFT OF PHOTO.
NOTE: CONCRETE DETERIORATION OF ABUTMENT AT DOWNSTREAM WATER LEVEL AND AT CREST ELEVATION



6. GUIDE RAILS FOR LOW LEVEL OUTLET GATE.



7. DOWNSTREAM VIEW FROM LEFT ABUTMENT SHOWING PENSTOCK AND OLD MILL IN BACKGROUND AND STUB OF PENSTOCK GATE STEM IN FOREGROUND.



8. TRASHRACK AT DAM
WATERBOX FOR PUMP
AT LEFT ABUTMENT.



9. AREA OF SEEPAGE IN
EMBANKMENT EXTENDING
FROM RIGHT ABUTMENT.



10. DOWNSTREAM HAZARD ON
RIGHT BANK OF RIVER.

APPENDIX B

VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST1) Basic Data

a. General

Name of Dam HAWKINSVILLE DAM
Fed. I.D. # N.Y. 895 DEC Dam No. _____
River Basin BLACK RIVER
Location: Town BOONVILLE County ONEIDA
Stream Name BLACK RIVER
Tributary of LAKE ONTARIO
Latitude (N) 43-29.6 Longitude (W) 75-16.5
Type of Dam GRAVITY
Hazard Category HIGH
Date(s) of Inspection MAY 22, 1981
Weather Conditions FAIR 60
Reservoir Level at Time of Inspection 1050.3±

b. Inspection Personnel F.W. BYSZEWSKI, J.A. GOMEZ, D.F. MCCARTHY
H. MUSKATT - DALE ENGINEERING COMPANY K. MAYHEW H.B.R.C.

c. Persons Contacted (Including Address & Phone No.) _____
HUDSON RIVER - BLACK RIVER REGULATING DISTRICT
491 EASTERN BLVD.
WATERTOWN N.Y. 13601 TELEPHONE 315-789-5440
ATTN: KENNETH H. MAYHEW

d. History:

Date Constructed 1915 Date(s) Reconstructed _____
Designer W.G. STONE & SON - UTICA N.Y.
Constructed By L.C. CLEVELAND - WATERTOWN N.Y.
Owner BRANT EXCELSIOR COMPANY.

2) Embankment

a. Characteristics

- (1) Embankment Material EARTH FILL
(NO SOIL CHARACTERISTICS RECORDED)
- (2) Cutoff Type NONE
- (3) Impervious Core UNKNOWN
- (4) Internal Drainage System NONE
- (5) Miscellaneous ~

b. Crest

- (1) Vertical Alignment POOR, LOCAL SUBSIDENCE/
EROSION AT CREST ALONG RIGHT EMBANKMENT
- (2) Horizontal Alignment POORLY DEFINED
OVERGROWN W/ TREES & BRUSH.
- (3) Surface Cracks NONE OBSERVED.
- (4) Miscellaneous _____

c. Upstream Slope

- (1) Slope (Estimate) (V:H) VARIES - IRREGULAR
- (2) Undesirable Growth or Debris, Animal Burrows _____
OVER GROWN
- (3) Sloughing, Subsidence or Depressions NO DEFINED
SLOPE, LOCALIZED IRREGULARITIES. PREVAIL.

(4) Slope Protection NONE

(5) Surface Cracks or Movement at Toe NOT OBSERVED
DUE TO WATER LEVEL IN IMPOUNDMENT.

d. Downstream Slope

(1) Slope (Estimate - V:H) POORLY DEFINED VARIES.

(2) Undesirable Growth or Debris, Animal Burrows NONE
NO BURROWS HEAVILY OVERGROWN.

(3) Sloughing, Subsidence or Depressions NO WELL
DEFINED SLOPE TO USE AS A STANDARD.

(4) Surface Cracks or Movement at Toe NONE OBSERVED

(5) Seepage YES. NEAR CENTER OF EIGHT
EMBANKMENT. REPAIRS ATTEMPTED
1973

(6) External Drainage System (Ditches, Trenches; Blanket) NONE

(7) Condition Around Outlet Structure N/A

(8) Seepage Beyond Toe SEE (5) above

e. Abutments - Embankment Contact

OK ALTHOUGH POORLY DEFINED

93-15-3(9/80)

(1) Erosion at Contact NONE OBSERVED

(2) Seepage Along Contact NONE OBSERVED

3) Drainage System

a. Description of System NONE

b. Condition of System ~

c. Discharge from Drainage System ~

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs, Piezometers, Etc.)

NONE

5) Reservoir

- a. Slopes MODERATE SLOPE - RIVER BANK
- b. Sedimentation SUBSTANTIAL SEDIMENTATION AT
UPSTREAM FACE OF STRUCTURE.
- c. Unusual Conditions Which Affect Dam _____

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) RESIDENCES
5-600 ft DOWNSTREAM.
- b. Seepage, Unusual Growth NONE OBSERVED - FLOW
CRESTING DAM.
- c. Evidence of Movement Beyond Toe of Dam NONE OBSERVED
- d. Condition of Downstream Channel NO RECENT EROSION.

7) Spillway(s) (Including Discharge Conveyance Channel)

- OGEE SHAPED
- a. General GOOD ALIGNMENT NO SERIOUS
DETERIORATION AS VIEWED THROUGH FLOW
CRESTING SPILLWAY
- b. Condition of Service Spillway SOME DETERIORATED
CONCRETE ON ABUTMENT WALLS

c. Condition of Auxiliary Spillway NO AUX SPILLWAYd. Condition of Discharge Conveyance Channel N/A.8) Reservoir Drain/OutletType: Pipe ☒ Conduit _____ Other _____Material: Concrete _____ Metal ☒ Other _____Size: 5 1/2 FT DIA Length 120 ± FT.Invert Elevations: Entrance 104.31 Exit UNKNOWNPhysical Condition (Describe): 4' high x 3' wide SLUICE 104.1 Unobservable ☒Material: STEELJoints: NO FLOW THROUGH
PENSTOCK AT TIME Alignment GOOD
OF INSPECTIONStructural Integrity: NO APPARENT STRUCTURALPROBLEMS.Hydraulic Capability: COMPUTEDMeans of Control: Gate ☒ Valve _____ Uncontrolled _____Operation: Operable ☒ Inoperable _____ Other _____Present Condition (Describe): EXERCIZED ANNUALLY

9) Structural

- a. Concrete Surfaces MINOR EROSION OF CONCRETE OBSERVED
THROUGH FLOWING WATER
- b. Structural Cracking NONE OBSERVED
- c. Movement - Horizontal & Vertical Alignment (Settlement) NONE OBSERVED
- d. Junctions with Abutments or Embankments OK
- e. Drains - Foundation, Joint, Face NONE
- f. Water Passages, Conduits, Sluices NONE
- g. Seepage or Leakage NONE OBSERVED.

- h. Joints - Construction, etc. NONE OBSERVED THROUGH
FLAWING WATER.
- i. Foundation NO PROBLEMS OBSERVED
- j. Abutments SURFACE SPALLING OF CONCRETE.
- k. Control Gates SEE 8
- l. Approach & Outlet Channels RUN OF RIVER
- m. Energy Dissipators (Plunge Pool, etc.) NONE
- n. Intake Structures SEE 8
- o. Stability NO SIGNS OF INSTABILITY OBSERVED.
- p. Miscellaneous NONE

10) Appurtenant Structures (Power House, Lock, Gatehouse, Other)

a. Description and Condition _____

NONE.


ABANDONED EXCELSIOR PLANT DOWNSTREAM
AT

11) Operation Procedures (Lake Level Regulation):

GATE TO PENSTOCK OPERATED ANNUALLY

APPENDIX C

HYDROLOGIC/HYDRAULIC, ENGINEERING DATA AND COMPUTATIONS



SCALE 1 : 250,000

LEGEND

--- WATERSHED AREA
--- SUB AREA

DRAINAGE BASIN

**STETSON • DALE**BANKERS TRUST BUILDING
UTICA • NEW YORK • 13501

TEL 315-797-5800

DESIGN BRIEF

PROJECT NAME N.Y.S. Dam Inspections 1981 DATE _____

SUBJECT Hawkinsville Dam ID # 895 PROJECT NO. 2530

Subarea Hydrologic Parameters DRAWN BY FDM

<u>Subarea</u>	<u>Area</u>	<u>C_T</u>	<u>L</u>	<u>LCA</u>	<u>$t_1 = C_T(L \times LCA)^{0.3}$</u>
1	67.9 mi ²	2.0	14.2 mi.	7.5 mi	$8.11 + 0.31^* = 8.33$ HR
2	80.8	2.0	18.9	9.1	$9.37 + 0.37^* = 9.64$
3	96.6	2.0	17.8	13.2	$10.05 + 0.03^* = 10.08$
4	27.4	2.0	9.9	2.6	5.29

* Adjustment for travel time through reservoir.

$$* = \frac{\text{travel distance}}{V_{wr}}$$

$$V_{wr} = \sqrt{g D_m}$$

$$g = 32.2 \text{ FT/SEC}^2$$

$$D_m = \text{avg. depth of reservoir}$$

<u>Subarea</u>	<u>D_m</u>	<u>distance</u>	<u>V_{wr}</u>	<u>*</u>
1	15 FT	16,667 FT	22.0	0.31 HR
2	20	35,000	25.4	0.37
3	20	2600	25.4	0.03

**STETSON • DALE**BANKERS TRUST BUILDING
UTICA • NEW YORK • 13501

TEL 315-797-5800

DESIGN BRIEF

PROJECT NAME N.Y.S. Dam Inspections 1981 DATE _____
SUBJECT Hawkinsville Dam PROJECT NO. 230
Depth - Area - Duration DRAWN BY F.C.M.

PMP From HMR #33
for Lat. $\sim 43^{\circ}30'$ Long. $\sim 75^{\circ}16'$
Index Rainfall = 18.7 in. for 200 mi², 24 hr.
Zone 1

<u>Duration</u>	<u>Ze Index*</u>	<u>Depth</u>
6 HRS	72	13.5 in
12 HRS	86	16.1
24 HRS	97	18.1
48 HRS	107	20.0

* Adjusted for site area, Drainage Area = 270 mi²

**STETSON • DALE**BANKERS TRUST BUILDING
UTICA • NEW YORK • 13501
TEL 315-797-5800**DESIGN BRIEF**

PROJECT NAME N.Y.S. Dam Inspections 1981 DATE _____
SUBJECT Hawkinsville Dam PROJECT NO. 2-10
Spillway Rating DRAWN BY FDH

Length 300 FT.

Assume constant "C" of 3.40 - from King & Brater,
"Handbook of Hydraulics" based
on spillway geometry.

Elevation	H	Q (cfs)
1050	0	0
1051	1	1020
1053	2	2855
1055	3	5300
1057	4	8160
1058	5	11,405
1059	6	14,990
1060	8	23,080
1062	10	32,255
1064	12	42,400
1066	14	53,130
1068	16	65,280
1070	18	77,895
1072	20	91,230
1074	22	105,255
1076	24	119,925
1078	26	135,225
1080	28	151,125
1082	30	167,605
1084	32	184,640



STETSON • DALE

BANKERS TRUST BUILDING
UTICA • NEW YORK • 13501


TEL 315-797-5800

DESIGN BRIEF

PROJECT NAME N.Y.S. Dam Inspections 1981 DATE _____

SUBJECT Hawkinsville Dam PROJECT NO. 35-20

Area Capacity Curve DRAWN BY EDM





STETSON • DALE

BANKERS TRUST BUILDING
UTICA • NEW YORK • 13501
TEL 315-797-5800


DESIGN BRIEF

PROJECT NAME N.Y.S. Dam Inspections 1961 DATE _____

SUBJECT Ho K noville Dam PROJECT NO. 2530

Reservoir Drain Discharge Rating DRAWN BY _____

sluice gate entrance



Field measurements (approximate)

Elevation 1041

Flows from nomograph on p. 569 of "Design of Small Dams" by the U.S. Bureau of Reclamation. Scale 4

Spillway elevation = 1050

Top of dam elevation = 1056

$W = 3 \text{ FT}$

$D = 4 \text{ FT.}$

Elevation	H	H/D	D/W	$Q(CFS)$
Spillway	7	1.75	42	126
Top of Dam	13	3.25	65	195

CHECK LIST FOR DAMS
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

1

AREA-CAPACITY DATA:

	<u>Elevation</u> (ft.)	<u>Surface Area</u> (acres)	<u>Storage Capacity</u> (acre-ft.)
1) Top of Dam	<u>1056</u>	<u>270</u>	<u>1230</u>
2) Design High Water (Max. Design Pool)	<u>N/A</u>	<u>—</u>	<u>—</u>
3) Auxiliary Spillway Crest	<u>N/A</u>	<u>—</u>	<u>—</u>
4) Pool Level with Flashboards	<u> </u>	<u> </u>	<u> </u>
5) Service Spillway Crest	<u>1050</u>	<u>40</u>	<u>130</u>

DISCHARGES

	<u>Volume</u> (cfs)
1) Average Daily	<u>N/A</u>
2) Spillway @ Maximum High Water (Top of Dam)	<u>14,990</u>
3) Spillway @ Design High Water	<u>N/A</u>
4) Spillway @ Auxiliary Spillway Crest Elevation	<u>N/A</u>
5) Low Level Outlet w/ water level at top of dam.	<u>195</u>
6) Total (of all facilities) @ Maximum High Water	<u>15,185</u>
7) Maximum Known Flood	<u>unknown</u>
8) At Time of Inspection	<u>125 ±</u>

CREST:

ELEVATION: 1056Type: concrete gravity

Width: _____

Length: 60 FT (abutments)Spillover Uncontrolled weir

Location

center of dam, comprises majority of
dam length - spanning width of river

SPILLWAY:

PRINCIPAL

EMERGENCY

N/AElevation 1050

Type

Inclined crest, rounded downstream corner,

Width

300 FT.

Type of Control

Uncontrolled

✓

Controlled:

Type

(Flashboards; gate)

Number

Size/Length

Invert Material

Anticipated Length
of operating serviceN/A

Chute Length

N/AHeight Between Spillway Crest
& Approach Channel Invert
(Weir Flow)12' ±

HYDROMETEROLOGICAL GAGES:

Type : None at present

Location: _____

Records:

Date - _____

Max. Reading - _____

FLOOD WATER CONTROL SYSTEM:

Warning System: None at present

Method of Controlled Releases (mechanisms):

5½ FT. diameter, sluice-gated penstock. and
4'x3' gated low level outlet

4

DRAINAGE AREA: 270 SQ. Mi.

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: Predominantly Forested

Terrain - Relief: Moderate to steeply sloped hills

Surface - Soil: Not known

Runoff Potential (existing or planned extensive alterations to existing
(surface or subsurface conditions)

No extensive alterations to drainage area
known to be planned

Potential Sedimentation problem areas (natural or man-made; present or future)

Reservoir appears to be heavily silted on the
upstream face of dam up to the crest,

Potential Backwater problem areas for levels at maximum storage capacity
including surcharge storage:

None known

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the
Reservoir perimeter:

Location: Earthen embankment adjacent to right abutment

Elevation: 1052 ±

Reservoir:

Length @ Maximum Pool 5.7 ± (Miles)
(1/2 RMP)

Length of Shoreline (@ Spillway Crest) 2.42 ± (Miles)

(0001)	A1	HAWKINSVILLE DAM	FILE IS ACAN
(0002)	A2	HEC-1DB (SNYDER PARAMETERS)	
(0003)	A3	PMF - DAM OVERTOPPING ANALYSIS	
(0004)	B	9) 1 0 0 0	0
(0005)	B1	5 0 0 0	0
(0006)	J	1 7 1 0	0
(0007)	J1	0.2 0.3 0.4 0.5	0.6
(0008)	K	100 0 0 0	0
(0009)	K1	RUNOFF SUBAREA 1	
(0010)	M	1 1 67.9	0 272.7
(0011)	P	0 18.7 72	86 97
(0012)	T	0 0 0 0	0 0 0 0
(0013)	W	8.32 0.625 0	0 0 0 0
(0014)	X	-2.0 -0.10 1.6	0 0 0 0
(0015)	K	1 -200 0	0 0 0 0
(0016)	K1	ROUTE TO SUBAREA 2	
(0017)	Y	0 0 0 0	1 1 0 0
(0018)	Y1	1 0 0 0	0 0 0 0
(0019)	Y6	0.07 0.035 0.07	1406 1440 47920
(0020)	Y7	100 1440 180	1420 280 1410
(0021)	Y7	336 1440 410	1420 470 1440
(0022)	K	0 200 0	0 0 0 0
(0023)	K1	RUNOFF SUBAREA 2	
(0024)	M	1 1 80.08	0 272.7 0
(0025)	P	0 18.7 72	86 97 107
(0026)	T	0 0 0 0	0 0 0 0
(0027)	W	9.64 0.625 0	0 0 0 0
(0028)	X	-2.0 -0.10 1.6	0 0 0 0
(0029)	K	0 300 0	0 0 0 0
(0030)	K1	RUNOFF SUBAREA 3	
(0031)	M	1 1 96.6	0 272.7 0
(0032)	P	0 18.7 72	86 97 107
(0033)	T	0 0 0 0	0 0 0 0
(0034)	W	10.08 0.625 0	0 0 0 0
(0035)	X	-2.0 -0.10 1.6	0 0 0 0
(0036)	K	3 300 0	0 0 0 0
(0037)	K1	COMBINE 3 HYDROGRAPHS 1+2+3=3	
(0038)	K	1 302 0	0 0 0 0

[illegible]

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT	100
ROUTE HYDROGRAPH TO	200
RUNOFF HYDROGRAPH AT	200
RUNOFF HYDROGRAPH AT	300
COMBINE 3 HYDROGRAPHS AT	300
ROUTE HYDROGRAPH TO	302
RUNOFF HYDROGRAPH AT	400
COMBINE 2 HYDROGRAPHS AT	400
ROUTE HYDROGRAPH TO	402
END OF METHOD	

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1976
 LAST MODIFICATION 26 FEB 79

HVN DATE?WED, AUG 26 1981
 TIME?12:01:15

HAWKINSVILLE DAM FILE IS ACAN
 HEC-1DB (SNYDER PARAMETERS)
 PMF - DAM OVERTOPPING ANALYSIS

JOB SPECIFICATION									
NO	NHR	NMIN	IDAY	IMR	IMIN	METRC	IPLT	IPRT	NSTAN
90	1	0	0	0	0	0	0	4	0
		JOPER	NWT	LROPT	TRACE				
		5	0	0	0				

MULTI-PLAN ANALYSES TO BE PERFORMED

RTIOS= 0.20 0.30 0.40 0.50 0.60 0.80 1.00
 MPLAN= 1 RTIO= 7 LRTIO= 1

SUB-AREA RUNOFF COMPUTATION

RUNOFF SUBAREA 1
 ISTAQ 100 ICOMP 0 IECON 0 ITAPE 0 JPLT 0 JPRT 0 INAME 1 ISTAGE 0 IAUTO 0

HYDROGRAPH DATA									
INVDG	IUHG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	1	67.90	0.00	272.70	0.00	0.000	0	1	0

PRECIP DATA			
SPFE	PMS	R0	R24
0.00	18.70	72.00	97.00
		86.00	107.00
		R72	R96
		0.00	0.00

TRSPC COMPUT. BY THE PROGRAM IS 0.809

LOSS DATA						
LROPT	STRKR	DLTKR	FTIOL	ERAIN	STRSK	RTIOK
0.00	0.00	0.00	1.00	0.00	0.00	1.00
						STATL
						1.00
						CNSTL
						0.10
						ALSMX
						0.00
						RTIMP
						0.02

UNIT HYDROGRAPH DATA
 TF= 0.10 CP=0.63 NTA= 1

STRID= -2.00 RECESION DATA RTIOR= 1.60
 QRCN= -0.10
 UNIT HYDROGRAPH 45 END-OF-PERIOD ORDINATES, LAG= 8.25 HOURS, CP= 0.63 VOL= 1.00
 133. 494. 993. 1560. 2160. 2708. 3108. 3338. 3387. 5189.
 2827. 2475. 2167. 1898. 1662. 1455. 1274. 1116. 977. 855.
 749. 656. 574. 503. 440. 385. 337. 295. 227. 60.
 198. 174. 152. 133. 117. 102. 89. 78. 49.
 53. 46. 35. 31.

MO-DA HR-MN PERIOD RAIN EXCS LOSS MO-DA HR-MN PERIOD RAIN EXCS LOSS COMP @
 SUM 17.78 14.09 3.69 647087.
 (452.)(358.)(94.)(18323.45)

HYDROGRAPH ROUTING

ROUTE TO SUBAREA 2

ISTAQ	ICOPP	IECON	ITAE	JPLT	JPRT	INAME	ISTAGE	IAUTO
200	1	0	0	0	0	0	0	0

QLOSS	CLOSS	AVG	IRCS	ISAME	IOPT	IPMP	LSTR
0.0	0.000	0.00	1	1	0	0	0

NSTPS	NSTDLL	LAG	AMSXK	X	TSK	STORA	ISPRAT
1	0	0	0.000	0.000	-1.	0	0

NORMAL DEPTH CHANNEL ROUTING

QM(1) QM(2) QM(3) ELMVT ELMAX RLNTH SEL
 3.0700 0.0350 0.0700 1406.0 1440.0 47920. 0.00800

CROSS SECTION COORDINATES--STA/ELEV/STA/ELEV--ETC
 100.00 1440.00 180.00 1420.00 260.00 1410.00 290.00 1406.00 320.00 1406.00
 330.00 1410.00 410.00 1420.00 470.00 1440.00

STORAGE	1.00	67.86	153.32	269.78	448.37	690.35	995.73	1364.51	1796.09
	2759.53	3278.23	3821.58	4389.59	4982.26	5599.58	6241.55	6908.18	7599.46

GUTFLOW	1.00	315.42	1761.46	2371.05	4301.90	6417.26	10307.04	14550.75	19786.32
	33644.90	41955.66	51127.24	61225.27	72232.52	84156.08	97011.69	110802.33	125547.75

STAGE	1410.00	1417.79	1409.58	1411.17	1413.16	1414.95	1416.74	1418.53	1420.31
	1423.89	1425.86	1427.47	1429.26	1431.05	1432.84	1434.63	1436.42	1438.21
FLOW	3.00	315.42	1061.46	2371.05	4300.90	6917.26	10307.04	14550.75	19786.32
	33644.98	41935.66	51128.24	61225.27	72232.52	84158.08	97011.69	110804.33	125547.75

MAXIMUM STAGE IS 1415.4
 MAXIMUM STAGE IS 1417.3
 MAXIMUM STAGE IS 1416.9
 MAXIMUM STAGE IS 1420.2
 MAXIMUM STAGE IS 1421.4
 MAXIMUM STAGE IS 1423.4
 MAXIMUM STAGE IS 1425.2

SUB-AREA RUNOFF COMPUTATION

RUNOFF SUBAREA 2
 ISYAG 200
 ICOMP 0
 ISECON 0
 ITAPE 0
 JPLY 0
 JPRY 0
 INAME 1
 ISTAGE 0
 IAUTO 0

INYDG 1
 IUNG 1
 TAREA 80.08
 SNAP 0.00
 TRSDA 272.70
 RATIO 0.00
 ISNOM 0
 ISAME 1
 LOCAL 0

PRECIP DATA

SPFE C.00
 PMS 18.70
 R6 72.00
 R12 86.00
 R24 97.00
 R48 107.00
 R72 0.00
 R96 0.00

TRSPC COMPUTED BY THE PROGRAM IS 0.889

LOSS DATA

LROPT 3.00
 STRKR 0.00
 DLTKR 0.00
 RTIOL 1.00
 ERAIM 0.00
 STRKS 0.00
 HTIOL 1.00
 STRTL 1.00
 CMSTL 0.10
 ALSPX 0.00
 RTIMP 0.01

UNIT HYDROGRAPH DATA

TP= 9.64
 CP=0.63
 NTA= 0

RECESSION DATA

STRTG= -2.00
 QRCSEN= -0.10
 RTIOL= 1.00

UNIT HYDROGRAPH 53 END-OF-PERIOD COORDINATES, I.A.E. 9.64 HOURS, CP= 0.63, NTA= 0

109.	406.	823.	1296.	1809.	2334.	2798.	3141.	3356.	3439.
3350.	3080.	2751.	2456.	2194.	1959.	1749.	1562.	1395.	1246.
1113.	994.	887.	792.	708.	632.	564.	504.	450.	402.
359.	321.	286.	256.	228.	204.	182.	163.	145.	130.
116.	103.	92.	82.	74.	66.	59.	52.	47.	42.
37.	33.	30.							

MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP Q	MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP Q
END-OF-PERIOD FLOW													
SUM 17.78 14.05 3.73 745386. (452.) (357.) (95.) (21106.96)													

SUB-AREA RUNOFF COMPUTATION

RUNOFF SUBAREA 3									
INSTAG	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	LAUTO	
330	0	0	0	0	0	1	0	0	

HYDROGRAPH DATA									
INVDG	JUNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	1	96.60	3.00	272.70	0.00	0.005	0	1	

PRECIP DATA									
SPEE	PMS	R6	R12	R24	R48	R72	R96		
C.00	-18.70	72.00	-86.00	97.00	107.00	0.00	C.00		

LOSS DATA									
LROPT	STRKR	DLTKR	RTIOL	ERAIN	STRES	RTIOK	STRTL	CNSTL	ALSMX
0.00	0.00	1.00	1.00	0.00	0.00	1.00	1.00	0.10	C.00

UNIT HYDROGRAPH DATA									
TP	10.08	CP	0.63	NTA	0				
UNIT HYDROGRAPH DATA									
RECESSION DATA									
STRTG	-2.00	GRCSN	-0.10	RTIOR	1.60				

END-OF-PERIOD FLOW

UNIT HYDROGRAPH 56 END-OF-PERIOD ORDINATES, LAG= 10.10 HOURS, CP= C.63 VOL= 1.00									
120.	448.	908.	1438.	2012.	2606.	3147.	3560.	3836.	3970.
3939.	3687.	3319.	2981.	2678.	2406.	2161.	1941.	1744.	1567.
1407.	1264.	1136.	1020.	916.	823.	739.	664.	597.	536.
481.	433.	389.	349.	314.	282.	253.	227.	204.	183.
165.	146.	133.	119.	107.	96.	87.	78.	70.	63.
56.	51.	45.	41.	37.	33.				

END-OF-PERIOD FLOW

	936.31	936.95	941.58	944.21	946.84	949.47	952.10	956.73	957.37
FLOW	0.00	526.15	1684.41	3353.50	5570.30	8617.27	12347.90	16828.73	22118.20
	35328.89	43372.50	52302.77	62283.48	73472.95	85936.25	99737.34	114959.39	131632.97
MAXIMUM STAGE IS	932.5								
MAXIMUM STAGE IS	937.3								
MAXIMUM STAGE IS	941.3								
MAXIMUM STAGE IS	944.6								
MAXIMUM STAGE IS	947.6								
MAXIMUM STAGE IS	952.6								
MAXIMUM STAGE IS	956.9								

SUB-AREA RUNOFF COMPUTATION

RUNOFF SUBAREA 4
 ISTAG 400 ICOMP 0 IECON 0 ITAPE 0 JPLT 0 JPRT 0 INAME 1 ISTAGE 0 IAUTO 0

HYDROGRAPH DATA

INIDE	IUNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	1	27.40	0.00	272.70	0.00	0.000	0	1	1

PRECIP DATA

SPFE	PMS	R6	R12	R24	R48	R72	R96
0.00	18.76	72.00	86.00	97.00	107.00	0.00	0.00

TRSPC COMPUTED BY THE PROGRAM IS 0.889

LOSS DATA

LROPT	STKR	DLTKR	RTIOL	ERAIN	STKRS	RTIOK	STRTL	CNSTL	ALSPX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	0.10	0.00	1.00

UNIT HYDROGRAPH DATA

TP= 5.29 CP=C.63 NTA= C

RECESSION DATA

STRTO= -2.00 QRCSN= -0.10 RTIOR= 1.00

UNIT HYDROGRAPH 24 END-OF-PERIOD ORIGINATES, LAGE 5.32 HOURS, CP= 0.63 VCL= 1.00

150.	547.	1074.	1601.	1966.	2066.	1956.	1507.	1272.	1033.
639.	581.	553.	449.	365.	266.	241.	195.	159.	129.

105. 85. 69. 56. 46. 37. 30. 24. 23.
 MO.DA HR.MN PERIOD RAIN EXCS LOSS COMP Q MO.DA HR.MN PERIOD RAIN EXCS LOSS COMP Q
 END-OF-PERIOD FLOW
 SUM 17.78 14.02 3.76 275463.
 (452.)(356.)(96.)(7800.26)

COMBINE HYDROGRAPHS

COMBINE 2 HYDROGRAPHS 3+4=4 TOTAL INFLOW

1STAG ICOMP IRECON ITAPE JPLT JPRT INAME ISTAGE IAUTO
 400 2 0 0 0 0 0 0 0

HYDROGRAPH ROUTING

ROUTE OVER HAWKINSVILLE DAM

1STAG ICOMP IRECON ITAPE JPLT JPRT INAME ISTAGE IAUTO
 402 1 0 0 0 0 0 0 0

QLOSS CLOSS AVG IRES ISAME IOPT IPMP LSTR
 0.0 0.000 0.00 1 1 0 0 0

NSTPS NSTDL LAG AMSKK X TSK STORA ISPRAT
 1 0 0 0.000 0.000 -1

STAGE 1050.00 1051.00 1052.00 1053.00 1054.00 1055.00 1056.00 1058.00 1060.00
 1064.00 1066.00 1068.00 1070.00 1072.00 1074.00 1076.00 1078.00 1080.00

FLOW 0.00 1020.00 2890.00 5300.00 8160.00 11400.00 14990.00 23080.00 32260.00
 53430.00 65280.00 77900.00 91230.00 105250.00 119930.00 135230.00 151130.00 167600.00

CAPACITY= 0. 65. 130. 430. 830. 1230. 1730. 2430. 3280. 4130.
 5430. 6830. 8230. 10130. 12130. 14330. 16380. 18630.

ELEVATION= 138. 1045. 1050. 1052. 1054. 1056. 1058. 1060. 1062. 1064.
 1066. 1068. 1070. 1072. 1074. 1076. 1078. 1080.

CREL SPLDID CQCN EAPW ELEV CQCL CAREA EXPL
 1050.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA
 TOFFI CQGD EXFD DAM-ID

1056.0 2.6 1.5 60.

PEAK OUTFLOW IS 27790. AT TIME 50.00 HOURS
PEAK OUTFLOW IS 41657. AT TIME 50.00 HOURS
PEAK OUTFLOW IS 55675. AT TIME 50.00 HOURS
PEAK OUTFLOW IS 69174. AT TIME 50.00 HOURS
PEAK OUTFLOW IS 83024. AT TIME 50.00 HOURS
PEAK OUTFLOW IS 110266. AT TIME 50.00 HOURS
PEAK OUTFLOW IS 137430. AT TIME 50.00 HOURS

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS						
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7
				0.20	0.30	0.40	0.50	0.60	0.80	1.00
HYDROGRAPH AT	100	67.50 (175.86)	1	7996. (226.41)	11993. (339.61)	15991. (452.82)	19989. (566.02)	23987. (679.23)	31982. (905.64)	39978. (1132.06)
ROUTED TO	200	67.50 (175.86)	1	7781. (220.35)	11697. (331.23)	15631. (442.63)	19561. (553.91)	23600. (668.26)	31573. (894.65)	39550. (1119.93)
HYDROGRAPH AT	200	80.28 (207.40)	1	8303. (235.10)	12454. (352.65)	16605. (470.21)	20756. (587.76)	24908. (705.31)	33210. (940.41)	41513. (1175.51)
HYDROGRAPH AT	300	96.60 (250.19)	1	9733. (275.61)	14600. (413.42)	19466. (551.23)	24333. (689.03)	29200. (826.84)	38933. (1102.45)	48666. (1378.06)
3 COMBINED	300	244.56 (633.45)	1	25782. (730.35)	38630. (1095.29)	51561. (1460.62)	64464. (1825.98)	77398. (2191.67)	103263. (2924.07)	129162. (3657.45)
ROUTED TO	302	244.56 (633.45)	1	25589. (724.61)	38436. (1088.38)	51278. (1452.03)	64129. (1815.94)	77064. (2182.22)	102893. (2913.61)	128719. (3644.91)
HYDROGRAPH AT	400	27.40 (70.97)	1	4472. (124.63)	6708. (189.94)	8944. (253.25)	11179. (316.57)	13415. (379.88)	17887. (506.50)	22359. (633.13)
2 COMBINED	400	271.98 (704.42)	1	26331. (796.59)	42249. (1196.35)	56362. (1596.00)	70484. (1995.90)	84691. (2398.17)	113062. (3201.55)	141429. (4004.82)
ROUTED TO	402	271.98 (704.42)	1	27790. (786.91)	41657. (1179.59)	55675. (1576.53)	69174. (1958.78)	83024. (2350.98)	110266. (3122.39)	137430. (3891.88)

PLAN 1		STATION 200	
RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.20	7781.	1415.4	48.00
0.30	11697.	1417.3	48.00
0.40	15631.	1418.9	48.00
0.50	19561.	1421.2	48.00
0.60	23600.	1421.4	48.00

0.80	31573.	1423.4	48.00
1.00	39550.	1425.2	48.00

PLAN 1 STATION 3C2

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.20	25589.	932.5	49.00
0.30	38436.	937.3	49.00
0.40	51278.	941.3	49.00
0.50	64129.	944.6	49.00
0.60	77064.	947.6	49.00
0.80	102893.	952.6	49.00
1.00	128719.	956.9	49.00

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 1050.00 130. 0.	SPILLWAY CREST 1050.00 130. C.	TOF OF DAM 1056.00 1230. 14990.	TIME OF FAILURE HOURS
RATIO OF PRF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS
0.20	1058.86	2031.	27790.	14.00	50.00
0.30	1061.51	3071.	41657.	18.00	50.00
0.40	1063.79	4060.	55675.	22.00	50.00
0.50	1065.83	5320.	69174.	25.00	50.00
0.60	1067.79	6684.	83024.	26.00	50.00
0.80	1071.35	9514.	110266.	30.00	50.00
1.00	1074.62	12810.	137430.	34.00	50.00

HAWKINSVILLE DAM FILE IS ACAN-1

HEC-1DB (SNYDER PARAMETERS)
1/2 PMF - DAM BREAK ANALYSIS

(0001)	A1	3.00	C	12	0	C	C	C	0	4	0
(0002)	A2	5	0	C	0	0	0	0	0	0	0
(0003)	A3	3	1	1	0	C	0	0	0	0	0
(0004)	B	0.5	100	0	0	0	1	0	0	0	0
(0005)	K	0	0	0	0	0	0	0	0	0	0
(0006)	K1	0	0	0	0	0	0	0	0	0	0
(0007)	M	1	1	67.9	0	272.7	0	0	0	1	0
(0008)	P	0	18.7	72	86	97	107	0	0	0	0
(0009)	T	0	0	0	0	0	0	0	0.1	0	0.02
(0010)	W	8.32	0.625	0	0	0	0	0	0	0	0
(0011)	X	-2.0	-0.10	1.6	0	0	0	0	C	0	0
(0012)	K	1	200	0	0	0	0	C	C	0	0
(0013)	K1	0	0	0	1	1	0	0	0	0	0
(0014)	Y	0	0	0	0	0	0	0	0	0	0
(0015)	Y1	1	0	0	0	0	0	0	0	0	0
(0016)	Y6	0.07	0.035	0.07	1406	1440	47920	0.008	0	0	0
(0017)	Y7	100	1440	180	1420	280	1410	290	0	0	0
(0018)	Y7	333	1410	410	1420	470	1440	C	1406	320	1406
(0019)	K	0	200	0	0	0	0	1	0	0	0
(0020)	K1	0	0	0	0	0	0	0	0	0	0
(0021)	M	1	1	80.08	0	272.7	0	0	0	1	0
(0022)	P	0	18.7	72	86	97	107	0	0	0	0
(0023)	T	0	0	0	0	0	0	1.0	0.1	0	0.01
(0024)	W	9.64	0.625	0	0	0	0	0	C	0	0
(0025)	X	-2.0	-0.10	1.6	0	0	0	0	C	0	0
(0026)	K	0	300	0	0	0	0	1	0	0	0
(0027)	K1	0	0	0	0	0	0	0	0	0	0
(0028)	M	1	1	96.6	0	272.7	0	0	0	1	0
(0029)	P	0	18.7	72	86	97	107	0	C	0	0
(0030)	T	0	0	0	0	0	0	1.0	0.1	0	0.04
(0031)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0032)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0033)	K	3	300	0	0	0	0	1	0	0	0
(0034)	K1	0	0	0	0	0	0	0	0	0	0
(0035)	M	1	1	302	0	0	0	1	0	0	0
(0036)	P	0	0	0	0	0	0	0	0	0	0
(0037)	T	0	0	0	0	0	0	0	0	0	0
(0038)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0039)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0040)	K	3	300	0	0	0	0	1	0	0	0
(0041)	K1	0	0	0	0	0	0	0	0	0	0
(0042)	M	1	1	302	0	0	0	1	0	0	0
(0043)	P	0	0	0	0	0	0	0	0	0	0
(0044)	T	0	0	0	0	0	0	0	0	0	0
(0045)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0046)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0047)	K	3	300	0	0	0	0	1	0	0	0
(0048)	K1	0	0	0	0	0	0	0	0	0	0
(0049)	M	1	1	302	0	0	0	1	0	0	0
(0050)	P	0	0	0	0	0	0	0	0	0	0
(0051)	T	0	0	0	0	0	0	0	0	0	0
(0052)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0053)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0054)	K	3	300	0	0	0	0	1	0	0	0
(0055)	K1	0	0	0	0	0	0	0	0	0	0
(0056)	M	1	1	302	0	0	0	1	0	0	0
(0057)	P	0	0	0	0	0	0	0	0	0	0
(0058)	T	0	0	0	0	0	0	0	0	0	0
(0059)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0060)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0061)	K	3	300	0	0	0	0	1	0	0	0
(0062)	K1	0	0	0	0	0	0	0	0	0	0
(0063)	M	1	1	302	0	0	0	1	0	0	0
(0064)	P	0	0	0	0	0	0	0	0	0	0
(0065)	T	0	0	0	0	0	0	0	0	0	0
(0066)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0067)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0068)	K	3	300	0	0	0	0	1	0	0	0
(0069)	K1	0	0	0	0	0	0	0	0	0	0
(0070)	M	1	1	302	0	0	0	1	0	0	0
(0071)	P	0	0	0	0	0	0	0	0	0	0
(0072)	T	0	0	0	0	0	0	0	0	0	0
(0073)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0074)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0075)	K	3	300	0	0	0	0	1	0	0	0
(0076)	K1	0	0	0	0	0	0	0	0	0	0
(0077)	M	1	1	302	0	0	0	1	0	0	0
(0078)	P	0	0	0	0	0	0	0	0	0	0
(0079)	T	0	0	0	0	0	0	0	0	0	0
(0080)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0081)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0082)	K	3	300	0	0	0	0	1	0	0	0
(0083)	K1	0	0	0	0	0	0	0	0	0	0
(0084)	M	1	1	302	0	0	0	1	0	0	0
(0085)	P	0	0	0	0	0	0	0	0	0	0
(0086)	T	0	0	0	0	0	0	0	0	0	0
(0087)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0088)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0089)	K	3	300	0	0	0	0	1	0	0	0
(0090)	K1	0	0	0	0	0	0	0	0	0	0
(0091)	M	1	1	302	0	0	0	1	0	0	0
(0092)	P	0	0	0	0	0	0	0	0	0	0
(0093)	T	0	0	0	0	0	0	0	0	0	0
(0094)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0095)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0096)	K	3	300	0	0	0	0	1	0	0	0
(0097)	K1	0	0	0	0	0	0	0	0	0	0
(0098)	M	1	1	302	0	0	0	1	0	0	0
(0099)	P	0	0	0	0	0	0	0	0	0	0
(0100)	T	0	0	0	0	0	0	0	0	0	0
(0101)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0102)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0103)	K	3	300	0	0	0	0	1	0	0	0
(0104)	K1	0	0	0	0	0	0	0	0	0	0
(0105)	M	1	1	302	0	0	0	1	0	0	0
(0106)	P	0	0	0	0	0	0	0	0	0	0
(0107)	T	0	0	0	0	0	0	0	0	0	0
(0108)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0109)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0110)	K	3	300	0	0	0	0	1	0	0	0
(0111)	K1	0	0	0	0	0	0	0	0	0	0
(0112)	M	1	1	302	0	0	0	1	0	0	0
(0113)	P	0	0	0	0	0	0	0	0	0	0
(0114)	T	0	0	0	0	0	0	0	0	0	0
(0115)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0116)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0117)	K	3	300	0	0	0	0	1	0	0	0
(0118)	K1	0	0	0	0	0	0	0	0	0	0
(0119)	M	1	1	302	0	0	0	1	0	0	0
(0120)	P	0	0	0	0	0	0	0	0	0	0
(0121)	T	0	0	0	0	0	0	0	0	0	0
(0122)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0123)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0124)	K	3	300	0	0	0	0	1	0	0	0
(0125)	K1	0	0	0	0	0	0	0	0	0	0
(0126)	M	1	1	302	0	0	0	1	0	0	0
(0127)	P	0	0	0	0	0	0	0	0	0	0
(0128)	T	0	0	0	0	0	0	0	0	0	0
(0129)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0130)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0131)	K	3	300	0	0	0	0	1	0	0	0
(0132)	K1	0	0	0	0	0	0	0	0	0	0
(0133)	M	1	1	302	0	0	0	1	0	0	0
(0134)	P	0	0	0	0	0	0	0	0	0	0
(0135)	T	0	0	0	0	0	0	0	0	0	0
(0136)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0137)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0138)	K	3	300	0	0	0	0	1	0	0	0
(0139)	K1	0	0	0	0	0	0	0	0	0	0
(0140)	M	1	1	302	0	0	0	1	0	0	0
(0141)	P	0	0	0	0	0	0	0	0	0	0
(0142)	T	0	0	0	0	0	0	0	0	0	0
(0143)	W	10.08	0.625	0	0	0	0	0	0	0	0
(0144)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0145)	K	3	300	0	0	0	0	1			

(0039)	K1	ROUTE TO SUBAREA 4									
(0040)	Y	0	0	0	1	1	0	0	0	0	0
(0041)	Y1	1	0	0	0	0	0	0	0	0	0
(0042)	Y6	0.07	0.035	0.07	910	960	29170	0.002	0	0	0
(0043)	Y7	100	960	220	940	300	920	512.5	910	367.5	910
(0044)	Y7	380	920	500	940	640	960	0	0	0	0
(0045)	K	0	400	0	0	0	0	1	0	0	0
(0046)	K1	RUNOFF SUBAREA 4									
(0047)	M	1	1	27.4	0	272.7	0	0	0	1	0
(0048)	P	0	18.7	72	86	97	107	0	0	0	0
(0049)	T	0	0	0	0	0	0	1.0	0.1	0	0
(0050)	W	5.29	0.625	0	0	0	0	0	0	0	0
(0051)	X	-2.0	-0.10	1.6	0	0	0	0	0	0	0
(0052)	K	2	400	0	0	0	0	1	0	0	0
(0053)	K1	COMBINE 2 HYDROGRAPHS 3+4=4 TOTAL INFLOW									
(0054)	K	1	402	0	0	0	0	1	0	0	0
(0055)	K1	ROUTE OVER HAWKINSVILLE DAM									
(0056)	Y	0	0	0	1	1	0	0	0	0	0
(0057)	Y1	1	0	0	0	0	0	-1050	1	0	0
(0058)	Y4	1050	1051	1052	1053	1054	1055	1056	1058	1060	1062
(0059)	Y4	1064	1066	1068	1070	1072	1074	1076	1078	1080	1082
(0060)	Y5	0	1020	2890	5300	8160	11490	14990	23080	32260	42000
(0061)	Y5	53430	65280	77900	91230	105250	119930	135230	151130	167600	184640
(0062)	SS	0	65	130	430	830	1230	1730	2430	3280	4130
(0063)	SS	5430	6830	8230	10130	12130	14330	16380	18630	21060	23490
(0064)	SE	1038	1045	1050	1052	1054	1056	1058	1060	1062	1064
(0065)	SE	1066	1068	1070	1072	1074	1076	1078	1080	1082	1084
(0066)	SS	1050	2.65	1.5	60	0	0	0	0	0	0
(0067)	S0	1056	0	1038	0.1	1050	1065.82	1065.82	1065.82	1065.82	1065.82
(0068)	S8	300	0	1038	0.3	1050	1065.82	1065.82	1065.82	1065.82	1065.82
(0069)	S8	300	0	1038	0.5	1050	1065.82	1065.82	1065.82	1065.82	1065.82
(0070)	S8	300	0	1038	0.5	1050	1065.82	1065.82	1065.82	1065.82	1065.82
(0071)	K	1	1500	0	0	0	0	1	0	0	0
(0072)	K1	CHANNEL ROUTE TO FIRST DOWNSTREAM HAZARD									
(0073)	Y	1	1	1	1	1	1	1	1	1	1
(0074)	Y1	1	0.07	0.07	1120	1160	1190	-1	0.015	614	1120
(0075)	Y6	0.07	0.035	0.07	1120	1160	1190	0.015	0.015	614	1120
(0076)	Y7	1.0	1160	200	1140	360	1123	360	1120	614	1120

	Y7	620	1123	820	1140	1020	1160
(0077)	Y7	620	1123	820	1140	1020	1160
(0078)	K	1	5100				
(0079)	K1		CHANNEL ROUTE TO SECOND DOWNSTREAM HAZARD				
(0080)	Y		1				
(0081)	Y1	1					
(0082)	Y6	0.07	0.035	0.07	1012	1050	3600
(0083)	Y7	100	1050	101	1030	1100	1015
(0084)	Y7	1260	1015	1300	1030	1340	1050
(0085)	K	1	9900				0
(0086)	K1		CHANNEL ROUTE TO THIRD DOWNSTREAM HAZARD				
(0087)	Y		1				
(0088)	Y1	1					
(0089)	Y6	0.07	0.035	0.07	1007	1050	8800
(0090)	Y7	100	1050	660	1030	1500	1010
(0091)	Y7	1660	1010	1760	1030	1820	1050
(0092)	K	1	12500				0
(0093)	K1		CHANNEL ROUTE TO FOURTH DOWNSTREAM HAZARD				
(0094)	Y		1				
(0095)	Y1	1					
(0096)	Y6	0.07	0.035	0.07	992	1030	2600
(0097)	Y7	100	1030	160	1010	240	995
(0098)	Y7	420	995	570	1010	810	1030
(0099)	K	99	0	0	0	0	0
(0100)	A						
(0101)	A						
(0102)	A						
(0103)	A						
(0104)	A						

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT	100
ROUTE HYDROGRAPH TO	200
RUNOFF HYDROGRAPH AT	200
RUNOFF HYDROGRAPH AT	300
COMBINE 3 HYDROGRAPHS AT	300
ROUTE HYDROGRAPH TO	302
RUNOFF HYDROGRAPH AT	400
COMBINE 2 HYDROGRAPHS AT	400
ROUTE HYDROGRAPH TO	402
ROUTE HYDROGRAPH TO	1500
ROUTE HYDROGRAPH TO	5100
ROUTE HYDROGRAPH TO	9900
ROUTE HYDROGRAPH TO	12500
END OF NETWORK	

RUN DATE? FRI, AUG 28 1981
 TIME? 14:17:59

HAWKINSVILLE DAM FILE IS ACAN-1
HEC-1DB (SNYDER PARAMETERS)
1/2 PMF - DAM BREAK ANALYSIS

	NHR	NMIN	IDAY	JMR	IKIN	METRC	IPLT	IPRT	NSTAN
SCD	0	12	0	0	0	0	3	4	0
			JOPER	NWT	LROPT	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED
NPLAN= 3 NRTIO= 1 LRTIO= 1

RTIUS= 0.50

Question	Answer
1. What is the main purpose of the study?	To investigate the effect of the new curriculum on the learning outcomes of the students.
2. What are the research objectives?	To compare the learning outcomes of the students who were taught using the new curriculum with those who were taught using the old curriculum.
3. What is the research hypothesis?	The students who were taught using the new curriculum will have higher learning outcomes than those who were taught using the old curriculum.
4. What is the significance of the study?	The study is significant because it will provide information about the effectiveness of the new curriculum and help to make decisions about whether to implement it on a larger scale.
5. What are the limitations of the study?	The study is limited by the fact that it only looked at one subject and one grade level. It also only looked at learning outcomes and did not look at other factors such as student attitudes or teacher satisfaction.
6. What are the conclusions of the study?	The study concluded that the new curriculum had a positive effect on the learning outcomes of the students. The students who were taught using the new curriculum had higher learning outcomes than those who were taught using the old curriculum.
7. What are the recommendations of the study?	The study recommends that the new curriculum be implemented on a larger scale. It also recommends that further research be done to look at other factors such as student attitudes and teacher satisfaction.

SUB-AREA RUNOFF COMPUTATION

RUNOFF SUBAREA 1										
INHYD6	IUNG	TAREA	SNAP	TRSDA	TRSPC	HYDROGRAPH DATA				
						RATIO	ISNOW	ISAME	ISTAGE	IAUTO
1	1	67.90	0.00	272.70	0.00	0.000	0	1	0	0
		100								

HYDROGRAPH DATA

PRECIP DATA

SPE	PMS	RO
5.00	18.70	72.00
IS	3.889	

TRSPC COMPUTED BY THE PROGRAM IS 1.889

LOSS DATA

RGFT	STKR	DLTK	RTIO	ERIN	STKS	RTIO	STRT	CNST	ALSW	RTIME
-	0.00	0.05	1.00	0.00	0.00	1.00	1.00	0.10	0.00	0.00

UNIT HYDROGRAPH DATA

IF= 0.02 LP=1.00 NIA= U

RECESSION DATA
STARTU= -2.00 QNCN= -0.10 RTIOR= 1.60

UNIT HYDROGRAPH		END-OF-PERIOD ORIGINATES		LAG= 8.31 HOURS, CP= 0.63		VOL= 0.86	
13.	50.	171.	246.	417.	511.	611.	714.
822.	932.	1046.	1163.	1281.	1403.	1526.	1640.
2135.	2163.	2293.	2420.	2539.	2651.	2756.	2853.
3100.	3169.	3230.	3283.	3330.	3369.	3401.	3424.
3446.	3435.	3414.	3374.	3325.	3250.	3166.	3085.
2853.	2780.	2708.	2639.	2571.	2505.	2440.	2378.
2199.	2142.	2087.	2034.	1981.	1931.	1881.	1833.
1695.	1651.	1609.	1568.	1527.	1488.	1450.	1412.
1306.	1273.	1240.	1208.	1177.	1147.	1117.	1089.
1007.	981.	956.	931.	907.	884.	861.	839.

MO-DA	HR-MN	PERIOD	RAIN	EXCS	LOSS	COMP Q	MO-DA	HR-MN	PERIOD	RAIN	EXCS	LOSS	COMP Q
SUM 17.88 14.19 3.69 2658278.													
(454.) (360.) (94.) (75273.98)													

HYDROGRAPH ROUTING

ROUTE TO SUBAREA 2

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
2:0	1	0	0	0	0	0	0	0

ALL PLANS HAVE SAME ROUTING DATA

GLSS	CLOSS	AVG	IRIS	ISAME	IOFT	IPMP	LSIR
0.0	0.000	0.00	1	1	0	0	0

NSTPS 1

LAG	AMSK	K	TSK	STORA	ISPRAT
0	0.000	0.000	0.000	-1.	0

NORMAL DEPTH CHANNEL ROUTING

UN(1)	UN(2)	UN(3)	ELNVT	ELMAX	RLMTH	SEL
0.000	0.000	0.000	14.00	14.00	0.00800	

CROSS SECTION COORDINATES--STA/ELEV/STA/ELEV--ETC

100.00	144.00	180.00	160.00	220.00	140.00	290.00	140.00	320.00	140.00
330.00	141.00	410.00	1420.00	470.00	1440.00				

STORAGE	0.00	67.86	153.32	269.78	448.37	690.35	995.73	1364.51	1796.09
	2759.53	3278.23	3821.56	4389.59	4982.26	5599.58	6241.55	6908.18	7599.46

OUTFLOW	0.00	315.42	1061.46	2371.05	4300.90	6917.26	10307.04	14550.75	19786.32
	33644.98	41935.66	51128.24	61225.27	72232.52	84158.08	97011.69	110804.33	125547.75

STAGE	1406.00	1407.75	1409.58	1411.37	1413.16	1414.95	1416.74	1418.53	1420.31
	1423.89	1425.68	1427.47	1429.26	1431.05	1432.84	1434.63	1436.42	1438.21

FLOW	0.00	315.42	1061.46	2371.05	4300.90	6917.26	10307.04	14550.75	19786.32
	33644.98	41935.66	51128.24	61225.27	72232.52	84158.08	97011.69	110804.33	125547.75

MAXIMUM STAGE IS 1420.3

MAXIMUM STAGE IS 1420.3

MAXIMUM STAGE IS 1420.3

SUB-AREA RUNOFF COMPUTATION

RUNOFF SUBAREA 2

ISTAQ	200	ICOMP	0	IECOM	0	ITAPE	0	JPLT	0	JPRT	0	INAME	1	ISTAGE	0	IAUTO	0
-------	-----	-------	---	-------	---	-------	---	------	---	------	---	-------	---	--------	---	-------	---

HYDROGRAPH DATA

INHYD	1	IUNG	1	TAREA	80.08	SNAP	0.00	TRSDA	272.70	TRSPC	0.00	RATIO	0.000	ISNOW	0	ISAME	1	LOCAL	0
-------	---	------	---	-------	-------	------	------	-------	--------	-------	------	-------	-------	-------	---	-------	---	-------	---

PRECIP DATA

SPFE	0.00	PMS	18.70	R6	72.00	R12	86.00	R24	97.00	R48	107.00	R72	0.00	R96	0.00
------	------	-----	-------	----	-------	-----	-------	-----	-------	-----	--------	-----	------	-----	------

TRSPC COMPUTED BY THE PROGRAM IS 0.889

LOSS DATA

LROPT	STKR	DLTKR	RTIOL	ERAIN	STKRS	RTIOK	STRTL	CNSTL	ALSMX	RTIMP
0.00	0.00	0.00	1.00	0.00	0.00	1.00	1.00	0.10	0.00	0.01

UNIT HYDROGRAPH DATA

TP= 9.64 CP=0.63 NTA= 0

RECESSION DATA

STRTO= -2.00 ORCSN= -0.10 RTIOR= 1.60

UNIT HYDROGRAPH DATA, END-OF-PERIOD COORDINATES, LAGE 9.64 HOURS, CP=0.63, NTA=0.00

UNIT	HYDROGRAPHIC	100	END-OF-PERIOD	ORDINATES	LAG	10.03 HOURS	CP	0.63	VOL	0.78
12	45	93	152	219	293	373	458	548	642	
739	945	1052	1161	1273	1387	1502	1620	1739	1858	
1861	1981	2105	2229	2354	2480	2607	2733	2855	2971	
3	3165	3283	3375	3462	3542	3617	3686	3749	3806	

MO.DA	MR.MN	PERIOD	RAIN	EXCS	LOSS	END-OF-PERIOD FLOW	MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP 0
4030.	3704.	3943.	3917.	4003.	4020.	4041.	4059.	4030.	4044.				
4330.	4106.	3972.	3923.	3854.	3773.	3693.	3615.	3536.	3463.				
3329.	3317.	3247.	3178.	3111.	3045.	2980.	2917.	2855.	2794.				
2735.	2677.	2620.	2565.	2510.	2457.	2405.	2354.	2304.	2255.				
2207.	2160.	2114.	2069.	2026.	1983.	1940.	1899.	1859.	1820.				
1781.	1743.	1716.	1670.	1635.	1600.	1566.	1533.	1500.	1468.				

SUM 17.68 14.27 3.61 3438824.
(454.)(362.)(92.)(97376.56)

COMBINE HYDROGRAPHS

COMBINE 3 HYDROGRAPHS 1+2+3=3
 ISTAG ICCPP IECON ITAPE JPLT JPRT INAME ISTAGE IAUTO
 300 3 0 0 0 0 0 0 0

HYDROGRAPH ROUTING

ROUTE TO SUBAREA 4
 ISTAG ICCMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUTO
 302 1 0 0 0 0 0 0 0

ALL PLANS HAVE SAME

ROUTING DATA

QLOSS	CLOSS	AVG	IRIS	ISAME	IOPT	IPMP	LSTR
0.0	0.000	0.00	1	1	0	0	C

NSTPS	NSTD	LAG	AMSK	X	TSK	STORA	ISPRAT
1	0	0	0.000	0.000	0.000	-1.	0

NORMAL DEPTH CHANNEL ROUTING

QN(1) QN(2) QN(3) ELNVT ELMAX RLNTH SEL
 0.0700 0.0350 0.0700 910.0 960.0 29170. 0.00200

CROSS SECTION COORDINATES--STA/ELEV/STA/ELEV--ETC

	940.00	920.00	420.00	940.00	500.00	920.00	512.50	567.50	910.00
STORAGE	2217.23	2668.88	112.72	217.02	342.92	481.11	654.54	874.33	1147.50
OUTFLOW	35338.89	43372.56	526.15	1684.41	3353.50	5570.30	8617.27	12347.90	16828.73
STAGE	930.31	938.95	912.63	915.26	917.89	920.53	923.16	925.79	928.42
FLOW	35338.89	43372.56	526.15	1684.41	3353.50	5570.30	8617.27	12347.90	16828.73
MAXIMUM STAGE IS	944.8								
MAXIMUM STAGE IS	944.8								
MAXIMUM STAGE IS	944.8								

***** SUB-AREA RUNOFF COMPUTATION *****

SUB-AREA RUNOFF COMPUTATION

RUNOFF SUBAREA 4
 ISTAQ 400
 ICOMP 0
 IECON 0
 ITAPE 0
 JPLT 0
 JFRT 0
 INAME 1
 ISTAGE 0
 IAUTO 0

HYDROGRAPH DATA
 INYOG 1
 IUNG 1
 IAREA 27.40
 IAREA 18.70
 SNAP 0.00
 TRSDA 272.70
 TRSPC 0.00
 RATIO 0.000
 ISNOW 0
 ISAME 1
 LOCAL 0

PRECIP DATA
 SPTS 0.00
 PMS 18.70
 R6 72.00
 R12 86.00
 R24 97.00
 R48 107.00
 R72 0.00
 R96 0.00

LOSS DATA

LROPT STRKR OLTKR RTIOL RTIOL CRAIN STRKS RTIOL STRTL CNSTL ALSPX RTJMP
 0.00 0.00 0.00 1.90 0.00 0.00 0.00 1.00 0.10 0.00 0.00

UNIT HYDROGRAPH DATA
 TPR 5.29 CP=0.63 NTA= 0

RECESSION DATA

SIRTE= -2.00 QRESN= -0.10 RTIOR= 1.60

UNIT HYDROGRAPH100 END-OF-PERIOD ORDINATES, LAGE 5.27 HOURS, CP= 0.62 VOL= 1.47

TRSPC COMPUTED BY THE PROGRAM IS 0.889

MO.DA	MR.MN	PERIOD	RAIN	EXCS	LOSS	END-OF-PERIOD FLOW	MO.DA	MR.MN	PERIOD	RAIN	EXCS	LOSS	COMP Q
10.	955.	1079.	01.	127.	1332.	420.	376.	473.	004.	117.	032.		
218.	272.	2115.	2172.	2115.	2146.	2165.	1581.	1691.	1789.	1877.	1953.		
1933.	1856.	1782.	1711.	1782.	1711.	1643.	1578.	2104.	2139.	2066.	2013.		
1286.	1237.	1188.	1140.	1188.	1140.	1095.	1052.	1515.	1455.	1397.	1341.		
858.	824.	792.	760.	792.	760.	730.	701.	1010.	970.	931.	894.		
572.	549.	528.	507.	528.	507.	486.	467.	673.	646.	621.	596.		
381.	366.	352.	338.	352.	338.	324.	311.	449.	431.	414.	397.		
254.	244.	234.	225.	234.	225.	216.	207.	299.	287.	276.	265.		
169.	163.	156.	150.	156.	150.	144.	138.	199.	191.	184.	176.		
								133.	128.	122.	118.		

SUM 17.88 14.12 3.76 1207460.
(454.)(359.)(96.)(34191.43)

COMBINE HYDROGRAPHS

COMBINE 2 HYDROGRAPHS 3+4=4 TOTAL INFLOW												
ISTAG	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO				
4.0	2	0	0	0	0	1	0	0				

HYDROGRAPH ROUTING

ROUTE OVER HAWKINSVILLE DAM												
ISTAG	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO				
4.02	1	0	0	0	0	1	0	0				

ALL PLANS HAVE SAME ROUTING DATA

QLOSS	CLOSS	AVG	IRIS	ISAME	IOPT	IPMP	LSTR					
0.0	0.000	0.00	1	1	0	0	0					
NSTPS	NSTD1	LAG	ANSKK	X	TSK	STORA	ISPRAT					
1	2	0	0.000	0.000	0.000	-1050.	-1					

STAGE	1051.00	1052.00	1053.00	1054.00	1055.00	1056.00	1058.00	1060.00				
FLO.	1064.00	1065.00	1070.00	1072.00	1074.00	1076.00	1078.00	1080.00				
	1027.0	2890.00	5301.00	8161.00	11400.00	14990.00	23081.90	32260.00				
	6526.0	7790.00	91231.00	115250.00	119930.00	135230.00	151130.00	167600.00				

UNPAVED= 5430. 02. 6830. 120. 8230. 430. 10130. 630. 12130. 14330. 1730. 16380. 2430. 18630. 3280. 4130.
 ELEVATION= 1038. 1045. 1062. 1050. 1070. 1052. 1072. 1054. 1074. 1056. 1076. 1358. 1378. 1065. 1080. 1062. 1064.

CREL SPWD COB EXPW ELEV COOL CAREA EXPL
 1050.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA
 TOPEL COB EXPD DAMWID
 1056.0 2.6 1.5 60.

BEGIN DAM FAILURE AT 48.20 HOURS
 PEAK OUTFLOW IS 192508. AT TIME 48.90 HOURS

BRWD 300.
 DAM BREACH DATA
 Z ELBM TFAIL WSEL FAILEL
 0.00 1038.00 0.10 1050.00 1065.82

BEGIN DAM FAILURE AT 48.80 HOURS
 PEAK OUTFLOW IS 167783. AT TIME 49.10 HOURS

BRWD 300.
 DAM BREACH DATA
 Z ELBM TFAIL WSEL FAILEL
 0.00 1038.00 0.50 1050.00 1065.82

BEGIN DAM FAILURE AT 48.87 HOURS
 PEAK OUTFLOW IS 146754. AT TIME 49.30 HOURS

HYDROGRAPH ROUTING

CHANNEL ROUTE TO FIRST DOWNSTREAM HAZARD
 ISTAT ICOMP IRECON IYAPE JPLT JPRT INAME ISTAGE IAUTO
 1500 1 0 0 0 0 2 0

ALL PLANS HAVE SAME
 ROUTING DATA
 QLOSS CLOSS AVG IPES ISAME ICFT IPMP LSTR
 0.00 0.00 0.00 1 1 0 0 0

NORMAL DEPTH CHANNEL ROUTING

CROSS SECTION COORDINATES--STA,ELEV,STA,ELEV--ETC				
100.00	1160.00	200.00	1143.00	560.00 1123.00
620.00	1123.00	825.00	1140.00	1020.00 1160.00
				366.00 1120.00
				614.00 1120.00

	OUTFLOW	3.0U	4485.83	14453.67	29040.41	48007.84	71312.36	98972.77	131041.98	167593.13
		-25487C.53	306838.00	361823.31	42232.44	487360.50	557189.00	631784.75	711197.75	795481.88

FLO ₂	1.3.	4485.83	14433.e7	29046.41	48007.84	71312.36	98972.77	131041.98	167593.13
	c5487c.53	306038.00	361823.31	422852.44	487360.50	557189.00	63178.75	711997.75	795389.88

STATION 1550, PLAN 1, RTIO 1

OUTFLOW		
27.	45.	71.
171.	176.	181.
188.	186.	184.
163.	156.	152.
122.	119.	115.
85.	87.	85.
67.	65.	63.
52.	51.	50.
49.	51.	54.
135.	155.	176.
402.	437.	471.
667.	667.	616.
1417.	1461.	1512.
756.	1774.	1727.
670.	1793.	1784.
695.	1684.	1674.
1712.	1712.	1741.
659.	659.	657.
31.	391.	412.
107.	122.	135.
187.	189.	190.
179.	176.	173.
145.	141.	137.
109.	105.	102.
80.	77.	75.
60.	58.	57.
49.	48.	47.
65.	72.	81.
223.	249.	277.
545.	585.	629.
1014.	1089.	1171.
1592.	1627.	1659.
1817.	1812.	1813.
1764.	1753.	1742.
1659.	1654.	1653.
1777.	1821.	1931.
2657.	2952.	3111.
4406.	4896.	5157.
156.	146.	135.
190.	190.	190.
167.	170.	173.
130.	134.	137.
58.	99.	102.
69.	77.	75.
53.	56.	57.
48.	47.	47.
119.	92.	81.
369.	337.	277.
770.	722.	629.
1363.	1304.	1171.
1736.	1713.	1688.
1806.	1810.	1813.
1707.	1718.	1730.
1673.	1661.	1655.
2180.	2086.	1931.
3621.	3447.	3111.
6100.	5797.	5157.

02420.	04300.	06770.	08474.	09010.	09034.	10320.	11044.	11002.
12787.	13776.	14852.	14852.	14852.	14852.	14852.	14852.	14852.
25633.	27177.	28796.	30524.	34035.	35682.	37388.	39138.	40920.
42721.	44560.	46575.	48558.	52252.	53976.	55624.	57118.	58199.
59223.	60297.	61313.	62335.	64226.	65089.	65908.	66659.	67333.
67938.	68474.	68923.	69303.	70948.	72931.	73885.	74654.	75385.
67169.	71707.	65544.	68461.	65723.	62644.	63180.	60717.	60610.
58378.	58109.	56389.	54089.	53180.	51771.	50677.	49231.	48143.
46908.	45858.	44715.	43749.	41767.	40757.	39791.	38814.	36762.
35503.	34764.	33630.	31658.	30711.	29650.	28681.	27656.	26669.
25654.	24652.	22616.	21609.	20600.	19544.	18235.	16560.	14879.

02420.	04300.	06770.	08474.	09010.	09034.	10320.	11044.	11002.
12787.	13776.	14852.	14852.	14852.	14852.	14852.	14852.	14852.
25633.	27177.	28796.	30524.	34035.	35682.	37388.	39138.	40920.
42721.	44560.	46575.	48558.	52252.	53976.	55624.	57118.	58199.
59223.	60297.	61313.	62335.	64226.	65089.	65908.	66659.	67333.
67938.	68474.	68923.	69303.	70948.	72931.	73885.	74654.	75385.
67169.	71707.	65544.	68461.	65723.	62644.	63180.	60717.	60610.
58378.	58109.	56389.	54089.	53180.	51771.	50677.	49231.	48143.
46908.	45858.	44715.	43749.	41767.	40757.	39791.	38814.	36762.
35503.	34764.	33630.	31658.	30711.	29650.	28681.	27656.	26669.
25654.	24652.	22616.	21609.	20600.	19544.	18235.	16560.	14879.

02420.	04300.	06770.	08474.	09010.	09034.	10320.	11044.	11002.
12787.	13776.	14852.	14852.	14852.	14852.	14852.	14852.	14852.
25633.	27177.	28796.	30524.	34035.	35682.	37388.	39138.	40920.
42721.	44560.	46575.	48558.	52252.	53976.	55624.	57118.	58199.
59223.	60297.	61313.	62335.	64226.	65089.	65908.	66659.	67333.
67938.	68474.	68923.	69303.	70948.	72931.	73885.	74654.	75385.
67169.	71707.	65544.	68461.	65723.	62644.	63180.	60717.	60610.
58378.	58109.	56389.	54089.	53180.	51771.	50677.	49231.	48143.
46908.	45858.	44715.	43749.	41767.	40757.	39791.	38814.	36762.
35503.	34764.	33630.	31658.	30711.	29650.	28681.	27656.	26669.
25654.	24652.	22616.	21609.	20600.	19544.	18235.	16560.	14879.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	160948.	73562.	43323.	16606.	4981696.
CMS	4558.	2063.	1142.	470.	141066.
INCHES		2.52	5.52	5.68	5.68
MM		63.91	140.12	144.26	144.26
AC-FT		36477.	79979.	82342.	82342.
CUM		44994.	98652.	101567.	101567.

MAXIMUM STORAGE = 156.

MAXIMUM STAGE IS 1136.5

STATION 1500, PLAN 2, RTIO 1

[illegible]

MAXIMUM STORAGE = 143.

MAXIMUM STAGE IS 1135.4

HYDROGRAPH ROUTING

CHANNEL ROUTE TO SECOND DOWNSTREAM HAZARD
ISTAG ICOMP IRECON ITAPE JPLY JPRI INAME ISTAGE IAUTO
5100 1 0 0 0 0 0 0 0 0

ALL PLANS HAVE SAME

ROUTING DATA
GROSS CLOSS AVG IRES ISAME IOPT IPMP LSTR
0.0 0.00 0.00 1 1 0 0
NSTPS NSTOL LAG AMSKK X TSK STORA ISPRAT
1 0 0 0.00 0.000 -1. 0

NORMAL DEPTH CHANNEL ROUTING

GN(1) GN(2) GN(3) ELMVT ELMAX RLNTH SEL
0.0700 0.0350 0.0700 1012.0 1050.0 3600. 0.00130

CROSS SECTION COORDINATES--STA=ELEV,STA=ELEV--ETC

100.00 1050.00 101.00 1030.00 1100.00 1015.00 1106.00 1112.00 1254.00 1012.00
1260.00 1015.00 1300.00 1030.00 1340.00 1050.00

STORAGE	0.00	25.12	54.27	103.61	175.85	270.99	389.03	529.97	693.80
	1079.06	1278.26	1478.13	1678.69	1879.92	2081.83	2284.41	2487.68	2691.62
OUTFLOW	0.00	725.07	2363.33	4999.72	8852.46	14117.94	20975.52	29593.62	40132.41
	69459.53	88220.19	108912.27	131443.81	155738.63	181732.34	209369.06	238599.88	269381.36
STAGE	1012.00	1014.00	1016.00	1018.00	1020.00	1022.00	1024.00	1026.00	1028.00
	1032.00	1034.00	1036.00	1038.00	1040.00	1042.00	1044.00	1046.00	1048.00
FLOW	1.00	725.07	2363.33	4999.72	8852.46	14117.94	20975.52	29593.62	40132.41
	69459.53	88220.19	108912.27	131443.81	155738.63	181732.34	209369.06	238599.88	269381.36

MAXIMUM STAGE IS 1135.4

MAXIMUM STAGE IS 1135.1

HYDROGRAPH ROUTING

CHANNEL ROUTE TO FOURTH DOWNSTREAM HAZARD
 ISTAR ICOMP 1 ISTAR ICOMP 1
 12500 12500

ALL PLANS HAVE SAME
 ROUTING DATA
 IRES ISAME 1 IRES ISAME 1
 NSTFS NSTBL 1 NSTFS NSTBL 1
 LAG 0 LAG 0
 AMSKK 0 AMSKK 0
 X 0 X 0
 STORA ISPRAT -1.0 STORA ISPRAT -1.0
 JPRY INAME ISTAR ISTAR
 0 0 0 0

NORMAL DEPTH CHANNEL ROUTING

LN(1) LN(2) LN(3) FLNVT ELMAX RLNTH SEL
 0.0700 0.0350 0.0700 992.00 1030.0 2600.0 0.03500

CROSS SECTION COORDINATES--STA,ELEV,STA,ELEV--ETC
 100.00 1030.00 160.00 1010.00 240.00 995.00
 420.00 995.00 570.00 1010.00 810.00 1030.00

STORAGE	0.00	20.53	42.36	67.51	96.32	126.79	164.92	204.71	248.16
	346.01	400.33	438.22	519.70	584.76	653.43	725.62	801.43	880.81
OUTFLOW	0.00	1613.03	5215.73	10519.11	17418.95	25898.96	35965.65	47637.97	60942.30
	92590.84	111007.50	131191.22	153175.91	176997.31	202692.00	230297.22	259850.81	291390.63
STAGE	992.00	994.03	996.00	998.00	1000.00	1002.00	1004.00	1006.00	1008.00
	1012.00	1014.00	1016.00	1018.00	1020.00	1022.00	1024.00	1026.00	1028.00
FLOW	0.00	1613.03	5215.73	10519.11	17418.95	25898.96	35965.65	47637.97	60942.30
	92590.84	111007.50	131191.22	153175.91	176997.31	202692.00	230297.22	259850.81	291390.63

MAXIMUM STAGE IS 1014.6

MAXIMUM STAGE IS 1014.9

MAXIMUM STAGE IS 1014.8

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION	STATION	AREA	PLAN	RATIO	1
					C.50
HYDROGRAPH AT	100	67.90	1	20281.	
		(175.86)	2	(574.28)	(
			3	20281.	(
ROUTED TO	200	67.90	1	19827.	
		(175.86)	2	(561.43)	(
			3	19827.	(
HYDROGRAPH AT	200	60.08	1	21170.	
		(207.40)	2	(599.46)	(
			3	21170.	(
HYDROGRAPH AT	300	96.60	1	24667.	
		(250.19)	2	(698.50)	(
			3	24667.	(
S COMBINED	300	244.58	1	65586.	
		(633.45)	2	(1857.19)	(
			3	65586.	(
ROUTED TO	300	244.58	1	65586.	
		(633.45)	2	(1857.19)	(
			3	65586.	(

4 05009.
(1840.85)(
3 65009.
(1840.85)(

HYDROGRAPH AT 400 271.98
(704.42)

1 11513.
(326.03)(
2 11513.
(326.03)(
3 11513.
(326.03)(

2 COMBINED 400 271.98
(704.42)

1 71399.
(2021.79)(
2 71399.
(2021.79)(
3 71399.
(2021.79)(

ROUTED TO 402 271.98
(704.42)

1 169914.
(4811.41)(
2 146947.
(4161.06)(
3 141032.
(3993.57)(

ROUTED TO 1500 271.98
(704.42)

1 160948.
(4557.54)(
2 152533.
(4319.25)(
3 143410.
(4060.92)(

ROUTED TO 5100 271.98
(704.42)

1 150509.
(4263.64)(
2 144671.
(4096.61)(
3 136449.
(3863.80)(

ROUTED TO 9900 271.98
(704.42)

1 119065.
(3371.55)(
2 119289.
(3377.90)(
3 119185.
(3374.93)(

ROUTED TO 12500 271.98
(704.42)

1 117458.
(3326.02)(
2 120380.
(3408.77)(

5 118601.
(5360.12) (

PLAN 1	STATION 260
RATIO	MAXIMUM
0.50	FLOW, CFS
	19827.
	STAGE, FT
	1420.3
	TIME
	HOURS
	48.00

PLAN 2	STATION 260
RATIO	MAXIMUM
0.50	FLOW, CFS
	19827.
	STAGE, FT
	1420.3
	TIME
	HOURS
	48.00

PLAN 3	STATION 200
RATIO	MAXIMUM
0.50	FLOW, CFS
	19827.
	STAGE, FT
	1420.3
	TIME
	HOURS
	48.00

PLAN 1	STATION 362
RATIO	MAXIMUM
0.50	FLOW, CFS
	65009.
	STAGE, FT
	944.8
	TIME
	HOURS
	49.00

PLAN 2	STATION 302
RATIO	MAXIMUM
0.50	FLOW, CFS
	65009.
	STAGE, FT
	944.8
	TIME
	HOURS
	49.00

PLAN 3	STATION 362
RATIO	MAXIMUM
0.50	FLOW, CFS
	65009.
	STAGE, FT
	944.8
	TIME
	HOURS
	49.00

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1									
ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS	RATIO OF PMF 0.50	MAXIMUM RESERVOIR W.S.-ELEV 1065.05
ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS	RATIO OF PMF 0.50	MAXIMUM RESERVOIR W.S.-ELEV 1065.05
ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS	RATIO OF PMF 0.50	MAXIMUM RESERVOIR W.S.-ELEV 1065.05
ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS	RATIO OF PMF 0.50	MAXIMUM RESERVOIR W.S.-ELEV 1065.05

PLAN 1 STATION 1500			
RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.50	163948.	1136.5	49.30

PLAN 2 STATION 1500			
RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.50	163948.	1136.5	49.30

RATIO 0.50 FLOW/CFS 152533. STAGE/FT 1136.0 TIME HOURS 49.20

PLAN 3 STATION 1500

RATIO 0.50 MAXIMUM FLOW/CFS 143410. MAXIMUM STAGE/FT 1135.4 TIME HOURS 49.20

PLAN 1 STATION 5100

RATIO 0.50 MAXIMUM FLOW/CFS 150569. MAXIMUM STAGE/FT 1039.6 TIME HOURS 49.20

PLAN 2 STATION 5100

RATIO 0.50 MAXIMUM FLOW/CFS 144671. MAXIMUM STAGE/FT 1039.1 TIME HOURS 49.20

PLAN 3 STATION 5100

RATIO 0.50 MAXIMUM FLOW/CFS 136449. MAXIMUM STAGE/FT 1038.4 TIME HOURS 49.40

PLAN 1 STATION 9900

RATIO 0.50 MAXIMUM FLOW/CFS 119365. MAXIMUM STAGE/FT 1034.4 TIME HOURS 49.40

PLAN 2 STATION 9900

RATIO 0.50 MAXIMUM FLOW/CFS 119289. MAXIMUM STAGE/FT 1034.5 TIME HOURS 49.60

PLAN 3 STATION 9900

RATIO 0.50 MAXIMUM FLOW/CFS 119185. MAXIMUM STAGE/FT 1034.4 TIME HOURS 49.60

PLAN 1 STATION 12500

RATIO	MAXIMUM	MAXIMUM	TIME
0.50	FLOW/CFS	STAGE/FT	HOURS
	117458.	1014.6	49.40

PLAN 2 STATION 12500

RATIO	MAXIMUM	MAXIMUM	TIME
0.50	FLOW/CFS	STAGE/FT	HOURS
	120380.	1014.9	49.60

PLAN 3 STATION 12500

RATIO	MAXIMUM	MAXIMUM	TIME
0.50	FLOW/CFS	STAGE/FT	HOURS
	118661.	1014.8	49.60

APPENDIX D

REFERENCES

APPENDIX D

REFERENCES

1. Department of the Army, Office of the Chief of Engineers. National Program of Investigation of Dams; Appendix D: Recommended Guidelines for Safety Inspection of Dams, 1976.
2. U.S. Nuclear Regulatory Commission: Design Basis Floods for Nuclear Power Plants, Regulating Guide 1.59, Revision 2, August 1977.
3. Linsley and Franzini: Water Resources Engineering, Second Edition, McGraw-Hill (1972).
4. W. Viessman, Jr., J. Knapp, G. Lewis, 1977, 2nd Edition, Introduction to Hydrology.
5. Ven Te Chow: Handbook of Applied Hydrology, McGraw-Hill, 1964.
6. The Hydrologic Engineering Center: Computer Program 723-X6-L2010, HEC-1 Flood Hydrograph Package, User's Manual, Corps of Engineers, U.S. Army, 609 Second Street, Davis, California 95616, January 1973.
7. The Hydrologic Engineering Center, Computer Program: Flood Hydrograph Package (HEC-1) Users Manual For Dam Safety.
8. Soil Conservation Service (Engineering Division): Urban Hydrology for Small Watersheds, Technical Release No. 55, U.S. Department of Agriculture, January 1975.
9. H.W. King, E.F. Brater: Handbook of Hydraulics, McGraw-Hill, 5th Edition, 1963.
10. Ven Te Chow: Open Channel Hydraulics, McGraw-Hill, 1959.
11. Bureau of Reclamation, United States Department of the Interior, Design of Small Dams: A Water Resources Technical Publication, Third Printing, 1965.
12. J.T. Riedel, J.F. Appleby and R.W. Schloemer: Hydrometeorological Report No. 33, U.S. Department of Commerce, U.S. Department of Army, Corps of Engineers, Washington, D.C., April 1956. Available from Superintendent of Documents, U.S. Government Printing Office, Washington, D.C.
13. North Atlantic Regional Water Resources Study Coordinating Committee: Appendix C, Climate, Meteorology and Hydrology, February 1972.

14. Sherard, Woodward, Gizienski, Clevenger: Earth and Earth-Rock Dams, John Wiley and Sons, Inc., 1963.
15. U.S. Soil Conservation Service, Stillwater Outdoor Hydraulic Laboratory: Handbook of Channel Design for Soil and Water Conservation, SCS-TP-61, March 1974; revised June 1954.
16. The University of the State of New York - The State Education Department, State Museum and Science Service, Geological Survey: Geologic Map of New York, 1970.
17. Y.W. Isachsen and W.G. McKendree, 1977, Preliminary Brittle Structures Map of New York, New York State Museum Map and Chart Series No. 31.
18. U.S. Geological Survey, Water Resources Division: U.S. Geological Survey Water-Data Report NY-78-1, Water Year 1978, Vol. 1.
19. U.S. Department of the Interior, Geological Survey, Maximum Known Stages and Discharges of New York Streams Through 1973, by Irving R. Leonard and Bernard Dunn, 1976.

APPENDIX E
STABILITY ANALYSIS

STETSON-DALE UTICA NY

F/G 13/13

DACW51-81-C-0009

NL

2 of 2


DOI: 10.1002/anie

END

DATE _____

02-82

DTIC



M. J. Griffin, School of Mechanical Engineering, Newcastle University, Newcastle, UK



STETSON • DALE


BANKERS TRUST BUILDING
UTICA • NEW YORK • 13501
TEL 315-797-5800

DESIGN BRIEF

PROJECT NAME N.Y.S. Dam Inspections 1981 DATE _____

SUBJECT Hawkinsville Dam PROJECT NO. 2000

Stability DRAWN BY JA



Wt. of Dam

- ① $1' \times 1' \times 4' \times \frac{1}{2} (0.15 \text{ Kcf}) = 0.3 \text{ K}$
- ② $1' \times 11' \times 4' (0.15 \text{ Kcf}) = 6.6 \text{ K}$
- ③ $1' \times 12' \times 8.5' \times \frac{1}{2} (0.15 \text{ Kcf}) = 7.65 \text{ K}$

$$\Sigma = 14.55 \text{ K}$$

Resisting Moment due to wt. of dam

$$M_R = 0.3 \text{ K} (8.5' + 4'/3) + 6.6 \text{ K} (8.5' + 2') + 7.65 \text{ K} (\frac{2}{3} + 8.5')$$

$$= 2.95 \text{ K-ft} + 69.3 \text{ K-ft} + 43.35 \text{ K-ft}$$

$$M_R = 115.6 \text{ K-ft}$$



STETSON • DALE

BANKERS TRUST BUILDING
UTICA • NEW YORK • 13501
TEL 315-797-5800

DESIGN BRIEF

PROJECT NAME N.Y.S. Dam Inspections 1981 DATE _____
 SUBJECT Hawkinsville Dam PROJECT NO. _____
 DRAWN BY JAG

UPLIFT PRESSURE

$$\text{Uplift} = 3.51^k + 2.34^k = 5.85^k$$

$$\begin{aligned} \text{Overturning Moment} &= 2.34^k \left(\frac{12.5'}{2} \right) + 3.51^k \left(\frac{3'}{3} + 5.5' \right) \\ &= 14.6^k + 29.3^k = 43.88^k \end{aligned}$$

Case I - Normal Pool (@ Spillway Crest)1. Overturning

$$\begin{aligned} \text{Overturning moment due to } 4\frac{1}{2} \text{ water pressure} \\ = 4.493^k \left(\frac{12\frac{1}{3}'}{3} \right) = 13.48^k \end{aligned}$$

$$\text{Total Overturning moment} = 13.88^k + 13.48^k = 57.36^k$$

Resisting moment due to Tailwater

$$\begin{aligned} 0.28^k (1') &= 0.28^k + \text{wt. of water} \\ 1' \times (0.0' 24 \text{ kcf}) \frac{3' (2.125') (2.125')}{2} &= 0.14^k \end{aligned}$$

$$\text{Total resistance due to T.W.} = 0.42^k$$

$$\text{Total resisting moment} = 45.6 + 0.4 = 116^k$$

$$F.S. = \frac{M_R}{M_O} = \frac{116^k}{57.36^k} = 2.02$$

Position of Resultant

$$d = \frac{\sum M}{\sum V} = \frac{116^k - 58.4^k}{14.55^k - 5.85^k} = \frac{58.6^k}{8.7^k} = 6.74'$$

$$= \frac{6.74'}{12.5'} = 0.546 \text{ from toe (Inside middle third, O.K.)}$$



STETSON • DALE

BANKERS TRUST BUILDING
UTICA • NEW YORK • 13501
TEL 315-797-5800

DESIGN BRIEF

16

PROJECT NAME

N.Y.S. Dam Inspections 1981

DATE

SUBJECT

Hawkinsville

PROJECT NO.

DRAWN BY

M.G.

i.i) Sliding

$$F.S. = \frac{N + CA + T.W. \text{ Force}}{\text{driving Force}}$$

$$N = \Sigma V = 8.7^k$$

$$F.S. = \frac{0.65(8.7^k) + (0.05 \text{ ksi})(144 \text{ in}^2)(1')(12.5') + 0.28^k}{4.493^k} = \frac{95.94}{4.493}$$

$$= 21.4$$

Case II Normal Pool w/ Ice

$$\text{Ice Force} = 5^{\text{ft}} \text{ of dam @ elev. } 104.9$$

$$M_{\text{ice}} = 5^k(11') = 55^{\text{ft-k}}$$

i) Overturning

$$F.S. = \frac{116^{\text{ft-k}}}{57.36 + 55^{\text{ft-k}}} = \frac{116}{112.36} = 1.03$$

$$\therefore \text{Resultant Pos: } \frac{116 - 112.4}{8.7} = 0.4' = 0.036$$

i.i) Sliding

$$F.S. = \frac{95.94^k}{4.493^k} = 10.1$$



STETSON • DALE

BANKERS TRUST BUILDING
UTICA • NEW YORK • 13501
TEL 315-797-5800

DESIGN BRIEF

7/6

PROJECT NAME N. Y. S. Dam Inspections 1981 DATE _____
 SUBJECT Hawkinsville PROJECT NO. _____
 DRAWN BY AJ

CASE III 1/2 PMF (Assuming Uplift same as Case II)

1) Overturning

Add'l. Overturning moment due to H.W.

$$12.954^k \left(72\frac{1}{2} \right) = 77.72^k$$

$$\text{Total } M_o = 57.36^k + 77.72^k = 135.1^k$$

Resistance due to Tailwater

$$3.44^k \left(10.5\frac{1}{3} \right) = 12.04^k$$

$$+ \frac{1}{2} (10.5') (7.44') (0.624^k/ft) \left(7.44\frac{1}{3} \right) = 6.04^k = 3.44^k (2.18')$$

$$\text{T.W. Resisting Moment} = 18.08^k$$

$$\text{Total Resisting Moment} = 115.6^k + 18^k = 133.6^k$$

$$F.S. = \frac{134^k}{135^k} = 0.99 < 1.0 \therefore \text{Resultant out from base}$$

2) Sliding

$$\sum V = 14.55^k + 2.44^k - 5.85^k = 11.14^k$$

$$\sum H_{\text{sliding}} = 12.954^k + 4.493^k = 17.447^k$$

$$F.S. = \frac{0.65 (11.14^k) + 90^k + 3.44^k}{17.447^k} = 5.8$$



STETSON • DALE

BANKERS TRUST BUILDING
UTICA • NEW YORK • 13501

TEL 315-797-5800

DESIGN BRIEF

5/6

PROJECT NAME N.Y.S. Dam Inspections 1981

DATE

SUBJECT Hawkinsville

PROJECT NO.

DRAWN BY ACCase IV PMF (Assuming Uplift same as Case I)1) OverturningAdd'l moment due to H₁₀

$$20.143^k(6') = 120.9^k\text{'}$$

$$\text{Total Overturning moment} = 120.9 + 57.4 = 178.2^k\text{'}$$

Resistance due to Tailwater

$$= 13.48^k + 2.62^k(6') = 29.2^k\text{'}$$

$$+ \frac{1'(3.5')(8.5')(0.0624^k\text{'})}{1.85^k} + \frac{1/2(12')(0.5')(1')(0.0624^k\text{'})}{3.1824^k}$$

$$= 29.2^k + 16.9^k = 46.1^k$$

$$\text{Total } M_R = 46.1 + 115.6^k = 162^k$$

$$F.S. = \frac{162}{178} = 0.91 < 1.0 \text{ in resultant above base}$$

2) Sliding

$$\Sigma V = 14.55^k + 1.856^k + 3.02^k - 5.85^k = 13.7^k$$

$$\Sigma H_{\text{sliding}} = 20.143^k + 4.493^k = 24.64^k$$

$$F.S. = \frac{0.65(13.7^k) + 90^k + 2.62^k + 4.493^k}{24.64^k} = 4.3$$



STETSON • DALE

BANKERS TRUST BUILDING
UTICA • NEW YORK • 13501
TEL 315-797-5800

DESIGN BRIEF

7/6

PROJECT NAME N.Y.S. Dam Inspections 1981 DATE _____
 SUBJECT Hawkinsville PROJECT NO. _____
 DRAWN BY SAI

Case V. Seismic Load

Zone 2; Horiz E.Q. Coeff = 0.05, Vert. Coeff = 0.025

- a) Add'l overturning moment due to dead gravity loads

$$0.05 \{ 0.3 \times (11' + 1\frac{1}{3}') + 6.6 \times (1\frac{1}{2}') + 7.65 \times (1\frac{1}{3} \times 12') \} = 3.52 \text{ K}$$

$$0.025 \{ 0.3 \times (8.5' + \frac{4}{3}') + 6.6 \times (10.5') + 7.65 \times (\frac{2}{3} \times 8.5') \} = 2.9 \text{ K}$$

$$\text{Effective Vertical loads} = 8.7 \text{ K} - 0.025(14.55 \text{ K}) = 8.34 \text{ K}$$

- b) Add'l. moment due to hydrodynamic effect
-
- Reservoir (Ref. "Design of Dams", Ch. 10)

$$P_e = C \lambda w h = 0.73(0.05)(0.027 \times 10^6)(12') = 116 \text{ K}$$

$$V_e = 0.726 P_e = 0.726(116 \text{ K}) = 84.96 \text{ K}$$

$$M_e = V_e \bar{y} = 84.96 \text{ K} (0.4118 \times 12') = 42.18 \text{ K}$$

1.) Overturning

$$F.S. = \frac{116 \text{ K}}{57.34 + 3.52 + 2.9 + 1.18} = \frac{116}{64.96} = 1.79$$

Position of Resultant

$$\bar{x} = \frac{E.M.}{E.V.} = \frac{116 - 42.18 \text{ K}}{84.96 \text{ K}} = \frac{73.82 \text{ K}}{84.96 \text{ K}} = 8.7' = 0.490$$

2.) Sliding

$$F.S. = \frac{0.65(8.34 \text{ K}) + 90 \text{ K} + 0.28}{4.93 \text{ K} + 0.05(14.55 \text{ K}) + 0.24 \text{ K}} = \frac{95.7}{5.46} = 17.5$$

APPENDIX F

PREVIOUS INSPECTION REPORTS/AVAILABLE DOCUMENTS

DEC DAM INSPECTION REPORT

<input type="checkbox"/> 16	<input type="checkbox"/> 33	<input type="checkbox"/> 15	<input type="checkbox"/> 000521	<input type="checkbox"/> 5223	<input type="checkbox"/> 6	<input type="checkbox"/> 4
RB	CTY	YR. AP.	DAM NO.	INS. DATE	USE	TYPE

AS BUILT INSPECTION

☐ 1 Location of Spillway and outlet

☐ 1 Elevations

☐ 1 Size of Spillway and outlet

☐ 1 Geometry of Non-overflow section

☐ 1 GENERAL CONDITION OF NON-OVERFLOW SECTION

☐ 1 Settlement

☐ 2 Cracks

☐ 1 Deflections

☐ 2 Joints

☐ 2 Surface of Concrete

☐ 2 Leakage

☐ 1 Undermining

☐ 1 Settlement of Embankment

☐ 1 Crest of Dam

☐ 2 Downstream Slope

☐ 2 Upstream Slope

☐ 2 Toe of Slope *Tree*

☐ 1 GENERAL CONDITION OF SPILLWAY AND OUTLET WORKS

☐ 4 Auxiliary Spillway

☐ 2 Service or Concrete Spillway

☐ 4 Stilling Basin

☐ 2 Joints

☐ 2 Surface of Concrete

☐ 2 Spillway Toe

☐ 2 Mechanical Equipment

☐ 4 Plunge Pool

☐ 4 Drain

☐ 1 Maintenance

☐ 8 Hazard Class

☐ 3 Evaluation

☐ 5 Inspector

COMMENTS:

Right Bank Look





188

521 Black

BRANT EXCELSIOR COMPANY

MANUFACTURERS OF

HIGH-CLASS WOOD EXCELSIOR

HAWKINSVILLE, NEW YORK

1. The first group of people who are interested in the study of the history of the United States are the people who are interested in the history of the United States.

[illegible]

It is not possible to consider the fact that the
of the present day, it is not the point.

the Board of Directors, as hereinafter more fully approved of this plan.

1944

Dam No. 101 Black River Watershed.

Owner - Brand Excelsior Works, Port Jervis, N. Y.

Plans on file in Map Filing Cabinet.

GEORGE E. VAN KENNEN,
CHAIRMAN

JAMES W. FLEMING,

JOHN D. MOORE,
COMMISSIONERS

ALBERT E. HOYT,
SECRETARY

JOHN J. FARRELL,
ASST. SECRETARY

1884
STATE OF NEW YORK



5213
FILE

DIVISION OF INLAND WATERS

JOHN D. MOORE, COMMISSIONER

JAMES J. FOX, DEPUTY COMMISSIONER

RICHARD W. SHERMAN, CHIEF ENGINEER

ALEX. RICE MCKIM, INSPECTOR OF DOCKS
AND DAMS

IN REPLYING PLEASE REFER
TO FILE NUMBER

CONSERVATION COMMISSION

ALBANY

March 8, 1915.

Brant Exoelsior Co.,

Hawkinsville, N. Y.

Gentlemen:-

Receipt is acknowledged of your letter of February 27,
1915, together with application and plans in duplicate for the
proposed concrete dam on the Black River. This Commission will
take action on this application in the near future.

No contracts should be let or construction started on this
project until the formal approval thereof by this Commission has
been received.

Very truly yours,

Conservation Commission,

By *John*

Commissioner.

McK/C.

March 9, 1915.

Mr. W. C. Brant,
Hawkinsville, N. Y.

Dear Sir:-

Under separate cover you will find blue print of plans and duplicate application for dam known in our records as Serial #188, Dam #521, Black River Watershed.

Upon the plan you will find a certificate signed by the Secretary to the Commission stating that by a duly adopted resolution your plans and specifications have been approved in accordance with the provisions of Section 22 of the Conservation Law.

You will also find enclosed copy of the resolution, which please read carefully and acknowledge receipt.

Yours truly,

CONSERVATION COMMISSION,

By

Secretary to Commission.

RWB/H.

ORIGINAL

Form No. 1W66 31-1-18-1000 (10-751)

GEORGE E. VAN KENNEN
CHAIRMAN
JAMES W. FLEMING
JOHN D. MOORE
COMMISSIONERS
ALBERT E. HOYT
SECRETARY
JOHN J. FARRELL
ASST. SECRETARY

STATE OF NEW YORK



CONSERVATION COMMISSION
ALBANY

Black
Dam No. *521*
DIVISION OF INLAND WATERS
JOHN D. MOORE
COMMISSIONER
JAMES J. FOX
DEPUTY COMMISSIONER
RICHARD W. SHERMAN
CHIEF ENGINEER
ALEX. RICE MCKIN
INSPECTOR OF DOCKS
AND DAMS

Serial No. *188*
Application filed *March 5-15*
Approved by Commission *March 9-15*
Material Tag No. *29*
Foundations inspected
Final inspection

APPLICATION FOR CONSTRUCTION OR RECONSTRUCTION OF A DAM

Hamkinsville, N.Y.

(Address of Applicant)

Application is hereby made to the Conservation Commission of the State of New York, in compliance with the provisions of Chap. LXV of the Consolidated Laws, the Conservation Law, for approval of the detailed specifications and plans, marked

Concrete Dam for Brant Excelsior Works, Hamkinsville, N.Y. on Black River

herewith submitted, for the { construction
~~reconstruction~~ } of the dam herein described. All provisions of law will be complied with in the erection of the said dam, whether specified herein or not.

.....
(Date)

{ Signature of
Applicant }

Mr McKim

March 16, 1915.

In re Dam #521 Black River
Watershed.

Brant Excelsior Co.,

Hartfordville, N. Y.

Gentlemen:-

Please give us at least a week's notice of the time when the foundation bed for this dam will be ready for inspection, so that our Inspector, Mr. McKim, will be able to make arrangements to be there. At the same time give us the name and address of the contractors for the work.

Very truly yours,

Conservation Commission,

By

Commissioner.

FCK/C.
Ans

100
JCH
RNS

JCH 4/9/15
JCH

WHEREAS, the Brant Excelsior Works of Hawkinsville, N. Y., did on the 5th day of March, 1915, submit plans and specifications for the construction of a dam on the Black River within the limits of the town of Boonville, ^{Outside County} said dam being known in Conservation Commission records as Dam #521 Black River watershed; and did by Conservation Commission Serial #188 make application for the approval of said plans and specifications under the provisions of the Conservation Law, and

WHEREAS, said plans and specifications have been approved by the Chief Engineer and the Inspector of Docks and Dams, and said plans signed by them respectively, Now, Therefore, Be it

RESOLVED, that said plans and specifications be and hereby are approved, provided however that this resolution shall not be deemed to authorize any invasion of any property rights, public or private, by any person in carrying out the requirements of this resolution, nor to create any claim or demand against the State of New York.

188 *De C. C. C. C.*
March 8-1914

adoption
1/2
RMS

WHEREAS, the Brant Excelsior Works of Hawkinsville,
N. Y., did on the 5th day of March, 1915, submit plans and
specifications for the construction of a dam on the Black
River within the limits of the town of Boonville, ^{*Onida County*} said dam
being known in Conservation Commission records as Dam #521
Black River watershed; and did by Conservation Commission
Serial #188 make application for the approval of said plans
and specifications under the provisions of the Conservation
Law, and

WHEREAS, said plans and specifications have been
approved by the Chief Engineer and the Inspector of Docks
and Dams, and said plans signed by them respectively, Now,
Therefore, Be it

RESOLVED, that said plans and specifications be and
hereby are approved, provided however that this resolution
shall not be deemed to authorize any invasion of any property
rights, public or private, by any person in carrying out the
requirements of this resolution, nor to create any claim or
demand against the State of New York.

LOCATION AND GENERAL DATA

Site of dam is on Black River
(Name of stream)
a branch of _____, within the
(Name of stream)
limits of the town of Beaverville, County of Oneida.
about 500 feet south of Bridge in village.
(Give approximate distance from well-known bridge, dam, village or mouth of stream, so that work can be located on map of state)

Purpose of dam Power

Reasons for making changes in existing structure Decay of old timber Dam

DATA AND DIMENSIONS

General:

Materials of which dam is to be constructed _____
Concrete proportioned 1:2:5. Will probably be constructed by owner.

Area of watershed above dam not in excess of 400 square miles.

Area of water surface of pond at level of spillway crest not in excess of 40 acres.

Capacity of reservoir (at above level) not in excess of 5,000,000 cubic feet.

Length of spillway crest 300 feet.

Maximum depth of water on spillway crest at highest known flood - 4 feet.

Maximum discharging capacity of spillway _____ cubic feet per second.

Maximum discharging capacity of spillway per square mile of drainage area _____
_____ cubic feet per second.

Masonry ~~or timber~~ portion:

Length on top... *about* *357* feet.
Length in stream bed... *about* *300* feet.
Maximum height above stream bed *12.02* feet.
Maximum height above foundation bed *14.02* feet.
Maximum width of base *12.75* feet.
Maximum width of top *4.00* feet.
Elevation of top above maximum water level in pond *8.* feet.
Elevation of top above spillway crest *6* feet.
Nature of foundations *Solid Granite.*

Earth portion:

Embankment:

Length on top feet.
Length in stream bed feet.
Maximum height above stream bed feet.
Maximum width of base feet.
Maximum width of top feet.
Elevation of top above maximum water level in pond feet.
Elevation of top above spillway crest feet.
Slope, upstream face
Slope, downstream face

Core wall:

Material
Elevation of top above spillway crest feet.
Width of top feet.
Batter of faces
Maximum height above foundations feet.
Maximum width of base feet.

Sheeting or other cut-off.....

Is fishway provided? Yes.

General description of regulating works, gate houses, outlet pipes, penstocks, forebays, canals, flashboards, gates, log chutes, etc.

See detail plans.

Names of owners of property which will be submerged by construction of dam, with approximate submerged area owned by each.

W.C. Brant - owner.

It is intended to complete work covered by this application by during 1915

(Date)

REPORT UPON APPLICATION

CONSERVATION COMMISSION — DIVISION OF INLAND WATERS

Albany.....

March 5-15

I have carefully examined the plans of the above dam, and find that if the work is constructed in accordance with the plans, filed March 5-15 with good workmanship and the specified materials that it will be safe.

Approved:

R. S. Sumner
Chief Engineer.

Alb. R. McLean
Inspector of Docks and Dams.

(NOTICE: After filling out one of these forms as completely as possible for each dam in your district, return it at once to the Conservation Commission, Albany.)

STATE OF NEW YORK
CONSERVATION COMMISSION
ALBANY

DAM REPORT

6/21/1915
(Date)

CONSERVATION COMMISSION,

DIVISION OF INLAND WATERS.

GENTLEMEN:

I have the honor to make the following report in relation to the structure known as the Hawkinsville Dam.

This dam ^{will be} situated upon the Black River in the Town of Boonville Oswego County, ~~in~~ ^{down} the Village ~~City~~ of Hawkinsville.


The distance ^{will be} ~~about~~ 300 ft ^{down} stream from the dam, to the highway bridge.

The dam is now owned by W.C. Brant, Hawkinsville, N.Y. ^{is to be} built in ~~the~~ year 1915 and ~~was~~ ^{is to be} ~~extensively repaired or reconstructed~~ during the year 1915.

As it now stands, the spillway portion of this dam is ^{to be} built of concrete and the other portions are ^{to be} built of concrete also.

As nearly as I can learn, the character of the foundation bed under the spillway portion of the dam is solid rock and under the remaining portions such foundation bed is solid rock.

521 Black



The total length of this dam is 360 feet. The spillway or waste-weir portion, is about 250 feet long, and the crest of the spillway is about 6 feet below the top of the dam.

The number, size and location of discharge pipes, waste pipes or gates which may be used for drawing off the water from behind the dam, are as follows: One waste gate to be built - not incorporated in present plans.

State briefly, in the space below, whether, in your judgment, this dam is in good condition, or bad condition, describing particularly any leaks or cracks which you may have observed.)

This dam is just about to be started - plans have been approved by Conservation Commission.

Reported by C. W. H. Douglass,
(Signature)


115 Standard St.,
(Address—Street and number, P. O. Box or R. F. D. route)

Syracuse, N. Y.
(Name of place)

(SEE OTHER SIDE)


(In the space below, make one sketch showing the form and dimensions of a cross section through the spillway or waste-weir of this dam, and a second sketch showing the same information for a cross section through the other portion of the dam. Show particularly the greatest height of the dam above the stream bed, its thickness at the top, and thickness at the bottom, as nearly as you can learn.)

Spillway -




(In the space below, make a third sketch showing the general plan of the dam, and its approximate position in relation to buildings or other conspicuous objects in the vicinity.)

Abutment wall
at left bank



Wing wall at right
bank



CLASS OF SERVICE	SYMBOL
Day Message	
Day Letter	Dis
Night Message	Nite
Night Letter	N L
If none of these three symbols appears after the check (number of words) this is a day message. Otherwise its character is indicated by the symbol appearing after the check.	

WESTERN UNION TELEGRAM

NEWCOMB CARLTON, PRESIDENT

GEORGE W. E. ATKINS, VICE-PRESIDENT

BELVIDERE BROOKS, VICE-PRESIDENT

CLASS OF SERVICE	SYMBOL
Day Message	
Day Letter	Dis
Night Message	Nite
Night Letter	N L
If none of these three symbols appears after the check (number of words) this is a day message. Otherwise its character is indicated by the symbol appearing after the check.	

RECEIVED AT 53 & 55 STATE ST., ALBANY, N. Y.

B713NY EG 26NL

0765

WATERTOWN NY JULY 7

A R MCKIM

CONSERVATION COMMISSION ALBANY NY

ON ACCT OF HIGH WATER IT HAS BEEN IMPOSSIBLE TO
 DRY OUT FOUNDATION FOR DAM AT HAWKINSVILLE CAN YOU POSTPONE
 YOUR TRIP UNTIL SATURDAY OR MONDAY

L B CLEVELAND

1255AM

WESTERN UNION TELEGRAM

Form 280

GEORGE W. E. ATKINS, VICE-PRESIDENT

NEWCOMB CARLTON, PRESIDENT

BELVIDERE BROOKS, VICE-PRESIDENT

RECEIVER'S No.	TIME FILED	CHECK
----------------	------------	-------

SEND the following Telegram, subject to the terms
on back hereof, which are hereby agreed to

July 8, 1915.

Mr. A. P. McKim,
Conservation Commission,
Albany, N. Y.

On account of high water it has been impossible to
dry out foundation for dam at Hawkinsville. Can
you postpone your trip until Saturday or Monday.

Lou B. Cleveland.

LBC.

(Confirmation)

APPROVAL BY COMMISSION

STATE OF NEW YORK

CONSERVATION COMMISSION

ALBANY

On March 9/15 the Conservation Commission, by resolution duly adopted, approved of the above application for the { construction } of dam 521 Black on Black River and hereby gives permission for the { reconstruction } of said dam within 12 months from date in accordance with the specifications and plans, and subject before erection to the approval by the Inspector of the materials of construction and of the foundation bed when stripped and prepared, and subject to the inspection of the work during and after construction. This approval may be amended if deemed necessary to secure a safe structure.

(Seal)

John J. Farrell
Secretary to Commission.

REPORT ON INSPECTION OF FOUNDATION

CONSERVATION COMMISSION — DIVISION OF INLAND WATERS

Albany.....

Work on the above dam was started....., contracts for the same having been awarded to.....

On

Approved:

Inspector of Docks and Dams.

Chief Engineer.

REPORT ON COMPLETION OF WORK

CONSERVATION COMMISSION — DIVISION OF INLAND WATERS

Albany Sept 28 - 15

On Sept 23 - 15 I inspected the above work and found that it had been completed in a satisfactory manner.

Approved:

Alfred R. McKinney
Inspector of Docks and Dams.

Chief Engineer.

INSTRUCTIONS TO APPLICANTS

Requirements for Plans.—Before beginning the construction, reconstruction, alteration or extension of a structure for impounding water, the owner of the proposed structure shall submit, in duplicate, to the Conservation Commission complete drawings showing the location of the dam, the flow line of the impounded water, the boundary lines and the ownership of the property affected, the nature of the foundation bed, the character of the materials to be employed, the size and the location of the discharge and control gates, the general and special features of the dam, and such dimensions as are necessary for the calculation of the stresses and the erection of the structure.

Drawings shall be on sheets of uniform size 24 inches wide by 36 inches long. Each sheet shall have a white space $2\frac{1}{2}$ inches high by $5\frac{1}{2}$ inches long below the title to receive the stamp of approval. On each sheet of every set of drawings there shall be clearly printed a conspicuous title in which shall appear the name of the county, the name of the city, village or town, and the name of the stream in which the dam is located, and the name of the owner thereof. The scale of the drawings shall be stated under the title. When the designs have been approved by the Commission, one set will be returned to the owner, with such approval endorsed thereon. Copies in duplicate of the specifications under which the dam is to be constructed shall accompany the plans.

Inspection.—The name of the inspector and a statement of his experience in such work must be sent to the Commission. There must also be sent a sample of at least one-half a cubic foot of sand and of cement, and twenty cubic inches of the stone for concrete or masonry to be used in the structure, and of the natural materials in the foundation bed. The foundation bed, after it has been cleared and prepared, must be inspected subject to approval by the Inspector of the Commission. The inspection of materials takes about ten days in the laboratory. On request tags will be sent for labeling the materials.

July 8-15. Excavation for West Wing ^{runway} tigan. Stones; boulders & clay & gravel.
Rain and high water.

July 25-15. Same Condition. No work done. A R M Y Lin

Aug 5-15. Bed prepared for 40' at West end. Blue hard clay & boulders.
Down 2 ft down & cut off 2 ft further.

Aug 27-15. West abut and. 50 ft spill finished. Concrete good. Forms
for 700 ft at East abut nearly ready for concrete. Recommend cut-off for
East abut. A R M Y Lin

Sept 22-15. Work completed. Concrete good. A R M Y Lin

Sept 8-17. Good Condition A R M Y Lin

150
Brant Excelsior Co

NATIONAL PRESS
 NEW YORK CITY
 719 WEST 40th STREET
INTELLIGENCE CO

Thursday, October 14, 1915.

NUMBER THIRTY-THREE



NEW DAM AT HAWKINSVILLE

Recently Completed for the Brant Excelsior Company

During the past months a new concrete dam has been constructed on the River at Hawkinsville for W. F. Brant of the Brant Excelsior Company. A picture of the dam in process of building appears in this connection. The length of the dam is 359 feet, with a spillway 298½ feet long. The dam is four feet at the crest, the width at the base varying according to the height. It is 14½ feet high at the highest point and 4½ feet at the lowest. It contains nearly 1,000 cubic yards of concrete and 1,200 barrels of cement were used. This dam replaces the old log dam which was destroyed by fire at Hawkinsville.

The work was designed by the well known engineering firm of W. G. Stone & Son, Utica, the work of building being in the hands of L. C. Cleveland, contractor and engineer of Watertown.

The new dam will give Brant Excelsior Company much more water for manufacturing purposes than before and will insure steady power for the operation of this plant. Mr. Brant has made a success of the business which gives employment to quite a number of hands and is an industry which is of much benefit to Hawkinsville. It is hoped that by 1916 another dam will be constructed at this place.

Bureau of Water Regulation

May 11, 1973

**Hudson - Black River Regulating District
90 State Street
Albany, New York 12210**

Gentlemen:

**Dam No. 521
Black River
Hawkinsville, Oneida County**

In conformance with the Department's Dam Safety Program, an inspection was made of the above-referenced dam on May 2, 1973.

A review of our files reveals that this dam was constructed in 1915 and consists of a concrete structure approximately 360 feet long and up to 12 feet high, forming an impoundment of approximately 8 million cubic feet. The dam is located 300 feet upstream from the bridge on County Route 61 in Boonville at Hawkinsville.

Our findings reveal that water is going through the right bank approximately 80 feet upstream of the dam. This is creating a stream which is flowing around the right concrete abutment and enters the river a short distance downstream of the abutment.

We suggest that your office examine the situation and take remedial action. Maintenance at this time will prevent future problems.

Very truly yours,

**Stanford Zeccolo
Senior Hydraulic Engineer**

SZ:KH;ls

cc: Mr. Leigh Blake



BOARD OF HUDSON RIVER-BLACK RIVER REGULATING DISTRICT

90 STATE STREET, ALBANY, N. Y. 12207

Phone 465-3491

CARL O. BACHMAN, PRESIDENT

JAMES P. LEWIS

DONALD C. BOWES

F. JAMES WILLIAMS JR.

EDWARD M. GALVIN

MEMBERS OF THE BOARD

FRANCIS J. TIERNEY

SECRETARY-TREASURER

JOHN W. TABNER

COUNSEL

ROBERT FORREST

CHIEF ENGINEER

KENNETH H. MAYHEW

ASSISTANT CHIEF ENGINEER

May 11, 1973

Mr. Stanford Zeccolo, Sr. Hydraulic Engineer
N. Y. S. Dept. of Environmental Conservation
Bureau of Water Regulation
Albany, N. Y. 12201

Re: Dam No. 521, Black River
Hawkinsville, Oneida Co.

Dear Mr. Zeccolo:

Receipt is acknowledged of your letter of May 11, 1973, in which you draw our attention to the leakage occurring through the right bank and around the right concrete abutment of the above mentioned dam.

I have already notified Assistant Chief Kenneth H. Mayhew of this situation as a result of your recent telephone notification. You may rest assured that whatever remedial work is necessary will be performed as soon as arrangements to do so have been made.

Thank you for your prompt action in this matter.


Very truly yours,

Robert Forrest

CHIEF ENGINEER

RF:sh

cc: Mr. Tabner
Mr. Mayhew





BOARD OF HUDSON RIVER-BLACK RIVER REGULATING DISTRICT

AL O. BACHMAN, PRESIDENT

JAMES P. LEWIS

RONALD C. BOWES

JAMES WILLIAMS, JR.

EDWARD M. GALVIN

MEMBERS OF THE BOARD

BLACK RIVER AREA OFFICE

491 EASTERN BOULEVARD

WATERTOWN, NEW YORK 13601

PHONE 768-8440 A. C. 315

FRANCIS J. TIERNEY

SECRETARY-TREASURER

JOHN W. TABNER

COUNSEL

ROBERT FORREST

CHIEF ENGINEER

KENNETH H. MAYHEW

ASSISTANT CHIEF ENGINEER

May 17, 1973

Mr. Stanford Zeccolo, Sr. Hydraulic Engineer
N.Y.S. Department of Environmental Conservation
Bureau of Water Regulation
Albany, New York 12201

Dear Mr. Zeccolo:

Dam No. 521, Black River
Hawkinsville, Oneida County
Your Letter of May 11, 1973

Mr. Forrest, Chief Engineer, of our Albany office telephoned the writer relative to flow through the east bank of the Black River southerly and upstream of our dam at Hawkinsville, New York.

An examination of this break was made on May 14th by the writer with the determination that although this leak is not serious at the moment, it should be repaired as soon as possible.


Our difficulty is that this repair must be made on property with an absentee owner and considerable time has been spent trying to contact this party for permission.

You will be notified when repairs have been completed.

Very truly yours,

K. H. Mayhew
Assistant Chief Engineer

KHM:FG
Enc. Map 3M5-1





BOARD OF HUDSON RIVER-BLACK RIVER REGULATING DISTRICT

CARL O. BACHMAN, PRESIDENT

JAMES P. LEWIS

DONALD C. BOWES

F. JAMES WILLIAMS, JR.

EDWARD M. GALVIN

MEMBERS OF THE BOARD

BLACK RIVER AREA OFFICE

481 EASTERN BOULEVARD

WATERTOWN, NEW YORK 13601

PHONE 766-8440 A. C. 818

FRANCIS J. TIERNEY

SECRETARY-TREASURER

JOHN W. TABNER

COUNSEL

ROBERT FORREST

CHIEF ENGINEER

KENNETH H. MAYHEW

ASSISTANT CHIEF ENGINEER

September 13, 1973

Mr. Stanford Zeccolo, Sr. Hydraulic Engineer
NYS Department of Environmental Conservation
Bureau of Water Regulation
Albany, New York 12201

Dear Mr. Zeccolo:

Dam No. 521, Black River
Hawkinsville, Oneida County

This is notification that remedial action has been taken to arrest the infiltration of water through the east bank of the river above the dam, as reported in your letter of May 11, 1973.

As this repair work was on the property of an absentee owner, permission to accomplish this work, as well as funds for same, presented unusual problems.

In mid August, a contractor completed the excavation of a cut-off trench parallel to and midway of the dike on this east bank at the point of water seepage. After excavation, heavy impervious clay was compacted in layers in this excavation from a depth well below the leak to well above. Topsoil was then placed to original dike level.

No shoreline alteration was affected other than brush cutting for machine clearance purposes. Excess spoil and brush was placed on the east side of the excavation resulting in no disturbance of the bed or shoreline of the river.

Very truly yours,

K. H. Mayhew
Assistant Chief Engineer

RESOURCE MGT. SERV.


SEP 18 1973

KHM:FG

cc: Mr. Forest
Mr. Blake

SCALE 1" = 100'

NORTH-BLACK RIVER REG. DISTRICT, WATERBURY, N.Y.



STATE OF NEW YORK



BOARD OF HUDSON RIVER-BLACK RIVER REGULATING DISTRICT

BLACK RIVER AREA OFFICE

LOUIS ANTHONY, JR.
CHAIRMAN
J. LOWELL FITZSIMMONS
1st VICE-CHAIRMAN
EDWIN B. HAVERLY
2nd VICE-CHAIRMAN
FRANK S. WOZNAK
BOARD MEMBER
ALLYN J. TURCK
BOARD MEMBER

491 Eastern Boulevard
Watertown, New York 13601
Phone (315) 788-5440

ROBERT A. BOUCHARD
SECRETARY-TREASURER
DONALD C. BOWES
COUNSEL
KENNETH H. MAYHEW
CHIEF ENGINEER
PHILIP A. MEIER
OPERATIONS ENGINEER
THOMAS E. BREWER
ADMINISTRATIVE ENGINEER

May 12, 1981

Stetson-Dale
185 Genesee Street
Utica, New York 13501

Att: Mr. Jerry A. Gomez, Civil Engineer

Dear Jerry:

Relative to our meeting at the Hawkinsville Dam last Thursday morning, May 7th, I have researched some of our records for information on this property and Dam.

My memory was incorrect on the size of the steel flume and the height of the Dam according to these enclosed notes. The flume is 6 ft. in diameter and the Dam is approximately 12 ft. high. We received no information on the physical dimensions of the Dam other than what are listed here.

If there are any further questions, call me at your convenience.

Sincerely,

K. H. Mayhew
Chief Engineer

KHM:FTM
Enc.

RECEIVED

MAY 13 1981

STETSON-DALE

BY _____

November 27, 1967

PRESENT DAM AND ADJACENT AREA AT HAWKINSVILLE

ONEIDA COUNTY, N. Y.

Owner: Stanley A. Presta,
formerly Brant Excelsior Co.

Location: 200' South or upstream from present Boonville-Woodgate Highway Bridge, County Route #61 crossing Black River at Hamlet of Hawkinsville.
Lot No. 18 of Adgates Western Tract, Town of Boonville, County of Oneida, State of New York

Land Area: Approximately .5+ Acres each side of present dam:
West Bank - 100' x 300' - Mill property and dam works
Assessment '66 \$5,000, '67 \$4,000
East Bank - .5 Acres adjacent to dam abutment
Assessment \$100
Also 3 Acres upstream from Dam (Trailer Area - Presta)
Assessment \$450

Exceptions: N.Y.S.C.D. fishing rights, 30' each side and Right of Way from road to water

Dam: 300' long x 12' high
Concrete spillway, abutments and gate works
Constructed 1915, abutment repairs '45 - fair condition
2 gates in West abutment 1 - 3'x3' w/o guard racks
1 - flume gate w/8' wide guard racks
Gate adjustments by means of lever pry on spindle
Flume to mill - 6' diameter x 100' - good condition
Original dam constructed 1824, rebuilt 1915
No flash boards or pins

Mill: Wood frame construction 5400 sq. ft. with 100 HP water wheel.
Good condition. No heat or machinery. Formerly used to make excelsior, 1900 to 1966. Ceased operations in 1966, mill rented for boat storage at present.

Pond: Bed of river only
Estimated volume at dam crest 8 m.c.f. or 2% size of Sixth Lake Reservoir. Approximately 50 camp sites, assessed \$300 - \$400 each.

Flow: Average over 55 year period 670 cfs
Maximum 12,400 cfs, Minimum 5 cfs


4 W. 44 Dam, 700 } 444 215
W. 44 No. 125 }
L. 7 700
At 9280000's 21 4444

PURCHASED 1961
DEED REC'D SEPT 3, 69
CHECK FOR \$5,000 PRESENTED TO
MR. PRESTA ON 9/13/69

EXTENSION, DISTRICT
BRANT APPELSIDE PLANT BUILDING
HAWKINSVILLE, N. Y.


FILE NO. 13498
ACCORD

SHEET
REV.



APPENDIX G

DRAWINGS



LOCATION PLAN

FIGURE 1



STETSON • DALE

BANKERS TRUST BUILDING
UTICA • NEW YORK • 13501
TEL 315-797-5800


DESIGN BRIEF

PROJECT NAME HAWKINSVILLE DAM, TOWN OF BOONVILLE DATE 6/1/81

SUBJECT DAM SECTION - BASED ON FIELD MEASUREMENTS PROJECT NO. _____

DRAWN BY D.F.M.

SCALE: 1" = 3'-0"



NOTE: DAM SECTION SHOWN IS BASED UPON
FIELD MEASUREMENTS AT THE TIME
OF A FIELD INSPECTION, 5/8/81.
HEIGHT OF DAM APPEARS TO VARY,
AS INFLUENCED BY ELEVATION OF
FOUNDATION ROCK. SECTION SHOWN
REPRESENTS MAXIMUM HEIGHT. ENTIRE
DAM FUNCTIONS AS A SPILLWAY.

FIGURE 2

02