ſ	AD-81	56 454	NAT	TONAL	PROGR	AN FOR	INSPE	CTION	OF NO	N-FEDE NGINEE	RAL DI RS MAI	ans Than	17	1
	UNCLAS	SSIFIE	D	NEW EF	IGLAND	014	JUN SE	,			F/G :	13/13	NL	
			ш.v											
	E.	1*												
												en a Brit	i i	
					E									
									₿N9) 					



MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A

t	GOFFSTOWN, NEW HAMPSHIRE
ţ.	
	UNCANOONUC LAKE DAM #2
5	NH 00021
A	NHWRB NO. 93.04
	PHASE I INSPECTION REPORT
1	NATIONAL DAM INSPECTION PROGRAM
	Gopy available to DTIC does not permit fully legible reproduction
	DTIC SUL 0 5 1985 B G
	DEPARTMENT OF THE ARMY NEW ENGLAND DIVISION, CORPS OF ENGINEERS WALTHAM, MASS. 02154
	JUNE 1980

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

REPORT DOCUMEN	ITATION PAGE	READ INSTRUCTIONS REFORE COMPLETING FORM
REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
NH 00021		
TITLE (and Sublitie)		5. TYPE OF REPORT & PERIOD COVERED
Uncanconuc Lake Dam #2		INSPECTION REPORT
IATIONAL PROGRAM FOR INSPEC	TION OF NON-FEDERAL	6. PERFORMING ORG. REPORT NUMBER
AUTHOR(s)		8. CONTRACT OR GRANT NUMBER(*)
J.S. ARMY CORPS OF ENGINEER HEW ENGLAND DIVISION	S	•
PERFORMING ORGANIZATION NAME AN	ID ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
CONTROLLING OFFICE NAME AND AD	DRESS	12. REPORT DATE
EPT. OF THE ARMY, CORPS OF	ENGINEERS	June 1980
24 TRAPELO ROAD. WALTHAM.	MA. 02254	13. NUMBER OF PAGES
MONITORING AGENCY NAME & ADDRE	SS(II dillerent from Centrolling Office)	15. SECURITY CLASS. (of this report)
DISTRIBUTION STATEMENT (of this Re PPROVAL FOR PUBLIC RELEASE	: DISTRIBUTION UNLIMITED	UNCLASSIFIED 18. DECLASSIFICATION/DOWNGRADING SCHEDULE
DISTRIBUTION STATEMENT (of this Re APPROVAL FOR PUBLIC RELEASE DISTRIBUTION STATEMENT (of the abo	port) : DISTRIBUTION UNLIMITED Tract antered in Black 20, 11 different fre	UNCLASSIFIED
DISTRIBUTION STATEMENT (of this Re APPROVAL FOR PUBLIC RELEASE DISTRIBUTION STATEMENT (of the abo	port) : DISTRIBUTION UNLIMITED tract universed in Black 20, 18 different fre	UNCLASSIFIED
APPROVAL FOR PUBLIC RELEASE OF DISTRIBUTION STATEMENT (of the obs Supplementary notes Cover program reads: Phase however, the official title Non-Federal Dams; use cove	Forry : DISTRIBUTION UNLIMITED tract entered in Block 30, 11 different fre I Inspection Report, Nation of the program is: Nation r date for date of report	UNCLASSIFIED Isa. DECLASSIFICATION/DOWNGRADING SCHEDULE an Report) Tonal Dam Inspection Program; onal Program for Inspection o
DISTRIBUTION STATEMENT (of this Re APPROVAL FOR PUBLIC RELEASE DISTRIBUTION STATEMENT (of the obs Cover program reads: Phase nowever, the official title Non-Federal Dams; use cove KEY WORDS (Continue on reverse elde II DAMS, INSPECTION, DAM SAF	port) : DISTRIBUTION UNLIMITED tract entered in Block 30, 11 different fre I Inspection Report, Nation of the program is: Nation r date for date of report necessary and identify by block number) ETY,	UNCLASSIFIED Is. DECLASSIFICATION/DOWNGRADING SCHEDULE a Report) Tonal Dam Inspection Program; onal Program for Inspection o
DISTRIBUTION STATEMENT (of this Re APPROVAL FOR PUBLIC RELEASE DISTRIBUTION STATEMENT (of the ebo OUSTRIBUTION STATEMENT (of the ebo Over program reads: Phase lowever, the official title ion-Federal Dams; use cove KEY WORDS (Continue on reverse elde if DAMS, INSPECTION, DAM SAF Merrimack River Basin Goffstown, New Hampshire Dan Little Brook	peri) : DISTRIBUTION UNLIMITED tract universed in Disck 20, 11 different fre I Inspection Report, Nation of the program is: Nation r date for date of report necessary and identify by block number; ETY,	UNCLASSIFIED Is. DECLASSIFICATION/DOWNGRADING SCHEDULE an Report) Tonal Dam Inspection Program; onal Program for Inspection of:
DISTRIBUTION STATEMENT (of this Re APPROVAL FOR PUBLIC RELEASE DISTRIBUTION STATEMENT (of the abo SUPPLEMENTARY NOTES Cover program reads: Phase nowever, the official title Non-Federal Dams; use cove KEY WORDS (Continue on revorce elde if DAMS, INSPECTION, DAM SAF Mertimack River Basin Goffstown, New Hampshire Dan Little Brook	peri) : DISTRIBUTION UNLIMITED tract univered in Block 20, 11 different fre I Inspection Report, Nation of the program is: Nation r date for date of report necessary and identify by block number) ETY,	UNCLASSIFIED Is. DECLASSIFICATION/DOWNGRADING SCHEDULE m Report) Tonal Dam Inspection Program; onal Program for Inspection o

ala da una desta de la ferrar de la constante

. . . .



DEPARTMENT OF THE ARMY NEW ENGLAND DIVISION CORPS OF ENGINEERS 424 TRAPELO ROAD WALTHAM. MASSACHUSETTS 02154

REPLY TO ATTENTION OF NEDED

JUL 2 2 1980

Honorable Hugh J. Gallen Governor of the State of New Hampshire State House Concord, New Hampshire 03301

Dear Governor Gallen:

Inclosed is a copy of the Uncanoonuc Lake Dam No. 2 Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Water Resources Board, the cooperating agency for the State of New Hampshire. In addition, a copy of the report has also been furnished the owner, Goffstown Conservation Commission, Town Hall, 16 Main Street, Goffstown, New Hampshire.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Water Resources Board for your cooperation in carrying out this program.

Sincerely,

MÁX B.

Colonel, Corps of Engineers Division Engineer

Incl As stated

UNCANOONUC LAKE DAM #2 NH 00021 NHWRB 93.04

È

-

D

.

.

. .

•

Į.

MERRIMACK RIVER BASIN GOFFSTOWN, NEW HAMPSHIRE

PHASE I INSPECTION REPORT





NATIONAL DAM INSPECTION PROGRAM PHASE I - INSPECTION REPORT BRIEF ASSESSMENT

Identification No: NH 00021

1

.

)

4

Name of Dam: Uncanoonuc Lake Dam #2

Town: Goffstown

County and State: Hillsborough, New Hampshire

Stream: Dan Little Brook

Date of Inspection: December 13, 1979

Uncanoonuc Lake Dam #2 is an earthen embankment structure with a central concrete core wall about 147 feet in overall length and 9 feet high from crest of dam to downstream toe. Located approximately in the center of the dam is the principal spillway which consists of a 16.1 feet long by 1.6 feet deep stoplog bay cast into the top of the concrete core wall.

The dam impounds Uncanoonuc Lake and the discharge flows through Dan Little Brook in a northeasterly, then northerly direction approximately 2.0 miles to the Piscataquog River. The dam was originally constructed for, and still serves, recreational purposes. The lake is 0.32 miles in length with a surface area of about 23.9 acres. The maximum storage capacity is about 161 acre feet.

As a result of the visual inspection of this facility, the dam is considered to be in FAIR condition. Major concerns are: downstream tilt of the concrete core wall with large vertical cracks and spalling; lack of erosion protection on the embankment and the right abutment; trees which are partially buried in the earthfill on the downstream slope; seepage at the downstream toe of the dam; and lack of a low level regulating outlet that would allow drawdown of the lake in an emergency.

The dam is classified as SMALL in size and a SIGNIFICANT hazard structure in accordance with the recommended guidelines established by the Corps of Engineers. The test flood for this dam therefore, ranges from a 100-year flood to one-half the Probable Maximum Flood (1/2 PMF). Since the dam falls on the lower end of the small size range, the 100-year flood was utilized for this hydrologic analysis. The test flood inflow was estimated to be 215 cfs and resulted in a routed test flood outflow equal to 86 cfs which would not overtop the dam crest. The maximum spillway discharge capacity with the reservoir surface at the dam crest was estimated to be 85 cfs which is nearly 100 percent of the routed test flood outflow. An assumed breach with the reservoir surface at the dam crest could damage the permanent residence located directly behind the dam and would overtop two town roads located downstream of the dam.

It is recommended that the owner engage a qualified registered professional engineer to: investigate the structural stability of the tilted and cracked concrete core wall; design and specify erosion protection for the upstream and downstream slopes of the embankment and the right abutment; specify and oversee procedures for the removal of trees and their root systems from the downstream slope of the dam and the left abutment; investigate the seepage at the downstream toe of the dam; and assess the need for and means to provide a low level regulating outlet that would allow drawdown of the pond in an emergency.

The recommendations and remedial measures are described in Section 7 and should be addressed by the owner within one year after receipt of this Phase I inspection Report.



5

Kenneth M. Stewart

Kenneth M. Stewart Project Manager N.H.P.E. 3531

S E A Consultants Inc. Rochester, New Hampshire This Phase I Inspection Report on Uncanoonuc Lake Dam No. 2 has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the <u>Recommended Guidelines for Safety Inspection of</u> <u>Dams</u>, and with good engineering judgment and practice, and is hereby submitted for approval.

hard Di Burno

RICHARD DIBUONO, MEMBER Water Control Branch Engineering Division

È

.

.

)

-

them he

ARAMAST MAHTESIAN, MEMBER Geotechnical Engineering Branch Engineering Division

140 A

CARNEY M. TERZIAN, CHAIRMAN Design Branch Engineering Division

APPROVAL RECOMMENDED:

DE B. FRYAR

Chief, Engineering Division

- X.

PREFACE

K

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

È

D

The Phase I investigation does <u>not</u> include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespassing and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

TABLE OF CONTENTS

r

<u>، ``</u>

ľ

•

.

-

• -

Section	Page
Letter of Transmittal	i
Brief Assessment	ii
Review Board Page	iv
Preface	v
Table of Contents	vii
Overview Photo	ix
Location Map	x
1. PROJECT INFORMATION	1-1
1.1 General	1-1
1.2 Description of Project	1-1
1.3 Pertinent Data	1-3
2. ENGINEERING DATA	2-1
2.1 Design	2-1
2.2 Construction	2-1
2.3 Operation	2-1
2.4 Evaluation	2-1
3. VISUAL INSPECTION	3-1
3.1 Findings	3-1
3.2 Evaluation	3-2
4. OPERATIONAL AND MAINTENANCE PROCEDURES	4-1
4.1 Operational Procedures	4-1
4.2 Maintenance Procedures	4-1
4.3 Evaluation	4-1

vii

Sec	tion		Page
5.	EVA	LUATION OF HYDROLOGIC/HYDRAULIC FEATURES	5-1
	5.1	General	5-1
	5.2	Design Data	5-1
	5.3	Experience Data	5-1
	5.4	Test Flood Analysis	5-1
	5.5	Dam Failure Analysis	5-2
6.	EVA	LUATION OF STRUCTURAL STABILITY	6-1
	6.1	Visual Observations	6-1
	6.2	Design and Construction Data	6-1
	6.3	Post-Construction Changes	6-1
	6.4	Seismic Stability	6-1
7.	ASS	ESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	7-1
	7.1	Dam Assessment	7-1
	7.2	Recommendations	7-1
	7.3	Remedial Measures	7-2
	7.4	Alternatives	7-2
		APPENDICES	
AP	PENDI	X A - INSPECTION CHECKLIST	A-1
AP	PENDI	X B - ENGINEERING DATA	B-1
AP	PENDI	X C - SELECTED PHOTOGRAPHS	C-1
AP	PENDI	X D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1

ŕ

(

ŝ

•

8

•----

.

• •

viii



Ē

C

K

į

OVERVIEW PHOTO - UNCANOONUC LAKE DAM #2



٠

E

۲...

_

X

NATIONAL DAM INSPECTION PROGRAM PHASE I INSPECTION REPORT UNCANOONUC LAKE DAM #2

SECTION 1 PROJECT INFORMATION

1.1 General

a. <u>Authority.</u> Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. S E A Consultants Inc. has been retained by the New England Division to inspect and report on selected dams in the State of New Hampshire. Authorization and notice to proceed were issued to S E A Consultants Inc. under a letter of November 5, 1979 from William Hodgson, Jr., Colonel, Corps of Engineers. Contract No. DACW33-80-C-0008 has been assigned by the Corps of Engineers for this work.

b. Purpose

(1) To perform technical inspection and evaluation of non-federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-federal interests.

(2) To encourage and prepare the states to initiate quickly effective dam safety programs for non-federal dams.

(3) To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

D

a. Location. Uncanoonuc Lake Dam #2 is located in the Town of Goffstown, New Hampshire, at the east end of Uncanoonuc Lake. The dam impounds water from Uncanoonuc Lake and the spillway discharge flows in a northeasterly, then northerly direction through Dan Little Brook for about 2.0 miles until it discharges into the Piscataquog River. The dam is shown on U.S.G.S. Quadrangle, Pinardville, New Hampshire, with coordinates approximately at N42⁵⁹19", W71³⁴41", Hillsborough County, New Hampshire (see Location Plan).

b. <u>Description of Dam and Appurtenances</u>. Uncanoonuc Lake Dam #2 is an earthen embankment structure with a central concrete core wall about 147 feet in overall length and 9 feet high from crest of dam to downstream toe. The upstream face consists of a sand and gravel fill which extends from the top of

1-1

the core wall down approximately 1 foot vertical to 10 feet horizontal (1:10) to wood logs at the edge of the lake. The downstream slope consists of a sand and gravel fill that crests about 1.5 feet lower than the top of the core wall and slopes downward approximately 1 foot vertical to 9 feet horizontal (1:9) for about nine feet and then slopes one foot vertical to 2.5 feet horizontal (1:2.5) to old ground. The crest of the core wall is about 22 inches wide.

Located approximately in the center of the dam is the principal spillway which consists of a 16.1 feet long by 1.6 feet deep stoplog bay cast into the top of the concrete core wall. A concrete apron equal to the width of the spillway extends downstream from the stoplog bay about 11.0 feet to a riprap slope which extends about 12 feet at a slope of approximately 1 foot vertical to 2 feet horizontal (1:2) to the existing stream channel.

Located at the opposite end of the lake from Uncanoonuc Lake Dam #2 is a second dam (Uncanoonuc Lake Dam #1, NH 00489). Uncanoonuc Lake Dam #1 functions as a dike as there is no apparent point of discharge. Uncanoonuc Lake Dam #1 has been classified low hazard by the New Hampshire Water Resource Board.

c. <u>Size Classification</u>. Small (height - 9 feet, storage 161 acre-feet) based on storage (less than 1,000 acre-feet and greater than or equal to 50 acre-feet) as given in the Recommended Guidelines for Safety Inspection of Dams.

d. <u>Hazard Classification</u>. Significant hazard. An assumed breach in Uncanoonuc Lake Dam #2 could result in damage to the permanent residence located directly behind the dam. The discharge emanating from the failed dam would be at the sill level and could undermine the foundation, which is exposed along the stream channel, causing appreciable damage to the structure. The potential for the loss of less than a few lives of residents inhabiting this structure exists. The water surface in the small pond immediately below the dam would rise approximately 9 feet, and the town roads adjacent to this pond would be overtopped. The first roadway below the dam would be overtopped by about 6 feet, and the second by approximately 4 feet.

e. <u>Ownership</u>. The earliest structure of the dam was built in 1921 and owned by the Uncanoonuc Mountain Incline Railway Company. The core wall and upstream face of the dam is presently owned by the town of Goffstown, Conservation Commission, Town Hall, 16 Main Street, Goffstown, New Hampshire 03045. Telephone No. (603) 497-3613. The downstream slope is owned by Fran Blazon, Mountain Base Road, Goffstown, New Hampshire 03045. Telephone No. (603) 497-3681. Also, the town of Goffstown owns a 20 foot wide right-of-way centered on the dam.

f. <u>Operator</u>. The dam is maintained and operated by the town of Goffstown, Town Hall, 16 Main Street, Goffstown, New Hampshire 03045. Telephone No. (603) 497-3613. g. <u>Purpose of Dam.</u> The dam was originally constructed for, and still serves, recreational purposes.

h. <u>Design and Construction History</u>. A plan dated 1921 showing plan and profiles for dams to be constructed on the lake, prepared by H. W. Sawyer, Professional Engineer, Goffstown, New Hampshire, is on file at the State of New Hampshire Water Resources Board. This plan indicates that the original dam was built of stone with a wood plank apron on the upstream slope. It is not known when the present concrete core wall dam was built to replace the stone dam, but plans on file at the State of New Hampshire Water Resources Board, dated 1936 and prepared by L. H. Shattuck, Inc., Manchester, New Hampshire 03101, for repairs to another dam on the lake use the core wall as a datum and indicate it to be constructed of concrete. Photos on file at the State of New Hampshire Water Resources Board verify the concrete core wall dam to be in existence by 1936.

Records at the State of New Hampshire Water Resources Board indicate that fill around the concrete core wall was washed out during the 1936 flood, and repairs were made shortly thereafter. There are no records of any further construction or repair to the dam since that time.

i. <u>Normal Operating Procedure</u>. Uncanoonuc Lake Dam #2 is used primarily to retain the waters of Uncanoonuc Lake for recreational purposes. There is no written operating procedure for this dam. However, the condition of the stop log slots (See Photo No. 6) shows that installation of stop logs is not part of the normal operating procedure.

1.3 Pertinent Data

a. <u>Drainage Area.</u> The drainage area above Uncanoonuc Lake Dam #2 covers nearly 0.26 square miles (approximately 166 acres), consisting of steeply sloping terrain surrounding Uncanoonuc Lake. The topography in the drainage basin ranges from over 1310 feet (NGVD) on top of South Mountain to approximately 648 feet at the base of the dam. The majority of the basin is heavily wooded and undeveloped. The development which does exist is predominantly located near the lake and consists of a combination of year-round and summer housing.

b. <u>Discharge at Damsite</u>. Discharge at the dam occurs over the 16.1 feet long spillway. Other than the spillway, there are no regulating outlets which would allow the surface of the lake to be lowered below the level of the spillway crest.

- (1) Outlet Works N/A
- (2) Maximum known flood at damsite unknown

(3) The ungated spillway capacity with the water surface elevation at the top of the dam (elevation 656.6 feet) was estimated to be 85 cfs.

(4) The ungated spillway capacity with the water surface elevation at the test flood elevation (elevation 656.6 feet) was estimated to be 85 cfs.

(5) Gated spillway capacity at normal pool elevation - N/A

(6) Gated spillway capacity at test flood elevation - N/A

(7) The total spillway capacity at the test flood elevation (elevation 656.6 feet) was estimated to be 85 cfs.

(8) The total project discharge at the top of the dam (elevation 656.6 feet) was estimated to be 85 cfs.

(9) The total project discharge at the test flood elevation (elevation 656.6 feet) was estimated to be 85 cfs.

c. <u>Elevation</u>. (feet, NGVD) based on an elevation of 655.0 feet, extrapolated from U.S.G.S. quadrangle sheet and assumed to be the pool elevation at the spillway crest.

- (1) Streambed at toe of dam 647.6
- (2) Bottom of cutoff Unknown
- (3) Maximum tailwater Unknown
- (4) Normal pool 655.0

1

- (5) Full flood control pool N/A
- (6) Spillway crest 655.0 (stoplogs removed) 656.6 (stoplogs in place)
- (7) Design surcharge (Original Design) Unknown
- (8) Top of dam Elevation varies 656.6 minimum
- (9) Test flood surcharge 656.6
- d. Reservoir (Length in feet)
 - (1) Normal pool 1680
 - (2) Flood control pool N/A
 - (3) Spillway crest pool 1680
 - (4) Top of dam 1680
 - (5) Test flood pool 1680

e. <u>Storage</u> (acre-feet)

۲

.

•

٠.,

Į

-

۰. -

- (1) Normal pool 120
- (2) Flood control pool N/A
- (3) Spillway crest pool 120
- (4) Top of dam 161
- (5) Test flood pool 161
- f. Reservoir Surface (acres)
 - (1) Normal pool 23.9
 - (2) Flood-control pool N/A
 - (3) Spillway crest pool 23.9
 - (4) Top of dam 26.8
 - (5) Test flood pool 26.8
- g. Dam
 - (1) Type earth embankment with central concrete core wall
 - (2) Length 147 feet overall
 - (3) Height 9 feet (maximum)
 - (4) Top width core wall 22 inches wide at crest
 - (5) Side slopes Upstream 1V to 10H to edge of lake downstream 1V to 9H and 1V to 2.5H.
 - (6) Zoning Unknown
 - (7) Impervious core concrete wall
 - (8) Cutoff Unknown
 - (9) Grout curtain None
 - (10) Other None

h. Diversion and Regulating Tunnel Not applicable (See Section j)

i. Spillway

-

2

• •,

(1) Type - Concrete stoplog bay

(2) Length of weir - 16.1 feet

(3) Crest elevation - 655.0 (stoplogs removed) 656.6 (stoplogs in place)

(4) Gates - None

(5) U/S Channel - The upstream approach channel to the spillway is wide and unobstructed. The channel slopes are tree covered and appear to be stable.

(6) D/S Channel - The spillway discharges into a natural stream channel at the toe of the dam. Approximately 115 feet downstream from the dam this discharge passes through a roadway culvert into a small pond. This pond is created by a roadway located approximately 530 feet below the dam. A few small trees overhang the portion of the channel between the dam and the first roadway culvert.

j. <u>Regulating Outlets</u>. There is no low level regulating outlet incorporated into the dam that would allow drawdown of the lake in an emergency.

1-6

SECTION 2 ENGINEERING DATA

2.1 Design

F

Ð

.

No design data were found for the existing structure of Uncanoonuc Lake Dam #2.

2.2 Construction

No construction records were found.

2.3 Operation

No engineering operational data were found.

2.4 Evaluation

a. <u>Availability</u>. No engineering data were available for Uncanoonuc Lake Dam #2. A search of the files of the New Hampshire Water Resources Board and direct contact with the owners revealed a limited amount of recorded information.

b. <u>Adequacy</u>. The final assessments and recommendations of this investigation are based on the visual inspection and the hydrologic and hydraulic calculations.

c. Validity. No engineering data were found to validate.

SECTION 3 VISUAL INSPECTION

3.1 Findings

r

R

.

هبه المراجع

.

a. <u>General.</u> Uncanoonuc Lake Dam #2 impounds a lake of small size. The drainage area above the dam consists of steeply sloped terrain. The majority of the basin is heavily wooded and generally undeveloped. The development which does exist is predominantly located near the lake. The immediate downstream channel is predominantly undeveloped.

The field inspection of Uncanoonuc Lake Dam #2 was made on December 13, 1979. The inspection team consisted of personnel from S E A Consultants Inc. and Geotechnical Engineers, Inc. Inspection checklists, completed during the visual inspection, are included in Appendix A. At the time of inspection, no stop logs were in place and water was passing approximately 1-1/4 inches deep over the 16.1 foot wide spillway. The pool elevation was at approximately 655.1 NGVD. The upstream face of the dam could only be inspected above this water level.

b. <u>Dam.</u> Uncanoonuc Lake Dam #2 is an earthen embankment structure with a central concrete core wall about 147 feet in overall length and 9 feet high from crest of dam to downstream toe.

The concrete core wall is tilted downstream on a batter of about 1 foot horizontal to 4 feet vertical (1H:4V) and has three large vertical cracks along its length and is spalled at several locations. From the visual examination alone, it is not possible to determine the cause of the tilting.

The earthfill on the upstream side of the core wall is sand and gravel and its crest is at the same elevation as the top of the concrete core wall. Some logs have been placed along the waterline on the upstream slope at approximately the elevation of the spillway crest, apparently for the purpose of retaining the earthfill above that elevation or providing erosion protection. The logs are not in a regular alignment and do not effectively serve either of these purposes today. One bush is growing on the upstream slope of the earthfill. There is no grassy vegetation, riprap, or other erosion protection on the upstream slope.

The earthfill on the downstream side of the core wall is sand and gravel and its crest is about 1.5 feet lower than the top of the concrete core wall. Most of the downstream slope is bare of vegetation. Some trees are partially buried in the earthfill on the downstream slope. The downstream slope is retained by timbers, supported by trees for a distance of about 15 feet to the left of the edge of the spillway discharge channel. There is a small seepage at the downstream toe of the dam near the left abutment.

3-1

There is a home within a few feet of the downstream toe between the spillway and the left abutment. There is evidence of significant trespassing on the dam and the area at the downstream toe.

Both abutments of the dam appear to be soil. The left abutment is covered with trees and brush at the elevation of the crest of the dam. The right abutment is bare of vegetation.

c. <u>Appurtement Structures</u>. Located approximately in the center of the dam is the principal spillway which consists of a 16.1 feet long by 1.6 feet deep stoplog bay cast into the top of the concrete core wall. At the time of the inspection, no stoplogs were in place. A concrete apron equal to the width of the spillway extends downstream from the stoplog bay about 11.0 feet to a riprap slope which extends about 12 feet to an existing stream channel. Soil has eroded from beneath the downstream edge of this concrete apron.

d. <u>Reservoir Area</u>. The slopes of the reservoir appear stable. No evidence of significant sedimentation was observed. The approach channel to the spillway is wide and unobstructed.

e. <u>Downstream Channel</u>. A few small trees overhang the discharge channel between the dam and the road culvert which is about 115 feet downstream from the dam.

3.2 Evaluation

(

On the basis of the visual inspection, Uncanoonuc Dam #2 is considered to be in fair condition.

The downstream tilt of the concrete core wall with large vertical cracks and spalling indicates that it has been unstable at one time. On the basis of the visual inspection alone, it is not possible to determine if the remedial measures taken in the past are adequate to ensure the present stability of the wall.

The lack of erosion protection on the upstream and downstream slopes of the embankment and the right abutment leaves the embankment susceptible to erosion by rainfall runoff or, if the dam should be overtopped, by overflowing water.

Trees which are partially buried in the downstream slope and trees growing on the left abutment could cause seepage and erosion problems if a tree blows over and pulls out its roots, or if a tree dies, or is cut and its roots rot.

Seepage at the downstream toe of the dam near the left abutment, if not controlled, could result in long-term instability.

The construction of the house which is located close to the downstream toe and continuing trespassing on the embankment may result in long-term seepage or erosion problems.

3-2

SECTION 4 OPERATIONAL AND MAINTENANCE PROCEDURES

4.1 Operational Procedures

a. <u>General.</u> Uncanoonuc Lake Dam #2 is used primarily to create Uncanoonuc Lake. There are no written or routine operational procedures.

b. <u>Description of any Warning Systems in Effect</u>. No written warning system exists for the dam.

4.2 Maintenance Procedures

a. <u>General.</u> The part owner, the town of Goffstown, is responsible for the maintenance of the dam. No formal maintenance plan exists.

b. <u>Operating Facilities</u>. No formal plan for maintenance of operating facilities exists.

4.3 Evaluation

•]

.

The current operation and maintenance procedures for Uncanoonuc Lake Dam #2 are inadequate to ensure that all problems encountered can be remedied within a reasonable period of time. The owners should establish a written operation and maintenance procedure, as well as establish a warning system to follow in event of flood flow conditions or imminent dam failure.

SECTION 5 EVALUATION OF HYDROLOGIC/HYDRAULIC FEATURES

5.1 <u>General.</u> Uncanoonuc Lake Dam #2 consists of an earthen embankment structure with a central concrete core wall. The dam is approximately 9 feet high from the crest of the dam to the downstream toe, with an overall length of 147 feet. Discharge from the dam occurs through the spillway located near the center of the dam. Other than this spillway, no other outlets exist. Located at the opposite end of the lake from Uncanoonuc Lake Dam #2 is a second dam (Uncanoonuc Lake Dam #1, NH00489). The crest of Uncanoonuc Lake Dam #1 is approximately 4 feet higher than the crest of Uncanoonuc Lake Dam #2. There is no apparent discharge from Uncanoonuc Lake Dam #1.

The drainage area above the dam consists of steeply sloped terrain which is heavily wooded. No other impoundments, which would delay the arrival of runoff to Uncanoonuc Lake are located in the drainage area. The dam impounds a lake which functions as a recreational facility. The dam is classified as small in size, having a maximum storage of approximately 161 acre-feet.

5.2 Design Data. No hydrological or hydraulic design data were disclosed.

5.3 Experience Data. No experience data were disclosed. Maximum flood flows or elevations are unknown.

5.4 <u>Test Flood Analysis</u>. Due to the absence of detailed design and operational information, the hydrologic evaluation was performed utilizing data gathered during field inspection, watershed size and an estimated test flood determined from the Corps of Engineers guide curves. For this dam (small size and significant hazard) the test flood ranges from the 100-year flood to one-half the Probable Maximum Flood (1/2 PMF). Since the dam falls on the lower end of the small size range, the 100-year flood was utilized for this hydrologic analysis. The drainage area consists of steeply sloping terrain, so the "mountainous" curve, from the Corps of Engineers set of guide curves, was used to estimate the maximum probable flood peak flow rate.

Based on an estimated maximum probable flood peak flow rate of 3,300 cfs per square mile and a drainage area of 0.26 square miles, the test flood inflow was estimated to be 215 cfs. The test flood was routed through the reservoir in accordance with the Corps of Engineers procedure for Estimating Effect of Surcharge Storage on Maximum Probable Discharge. The reservoir water surface was assumed to be at elevation 655.0 prior to the flood routing. The routed test flood outflow was estimated to be 86 cfs. This analysis indicated that the dam crest would not be overtopped. The maximum spillway discharge capacity with the water level at the dam crest was estimated to be 85 cfs, which is nearly 100 percent of the routed test flood outflow.

5-1

5.5 <u>Dam Failure Analysis</u>. The impact of dam failure was assessed utilizing the "Rule of Thumb" Guidance for Estimating Downstream Dam Failure Hydrographs published by the Corps of Engineers. The analysis covered a reach extending approximately 0.7 miles downstream to beyond Wallace Road. The prefailure flow is negligible (about 3 percent of the peak failure outflow from an assumed breach), so prefailure tailwater conditions were not included in the calculations and the dam failure analysis was conducted with the water surface at the dam crest. Based on this analysis, Uncanoonuc Lake Dam #2 has been classified as a significant hazard.

6

K

An assumed breach in Uncanoonuc Lake Dam #2 with the water surface at the dam crest would increase the stage of the immediate downstream channel to nearly 9 feet and could result in damage to the permanent residence located directly behind the dam. The discharge emanating from the failed dam would be at the sill level and could undermine the foundation, which is exposed along the stream channel, causing appreciable damage to the structure. The potential for the loss of less than a few lives of residents inhabiting this structure exists. The water surface in the small pond immediately below the dam would be overtopped. The first roadway below the dam would be overtopped by about 6 feet, and the second roadway by about 4 feet. Further downstream, the stage would be considerably reduced, to 3 to 4 feet, and additional damage to town roads is not likely. There are no other structures in the reach that would be impacted.

SECTION 6 EVALUATION OF STRUCTURAL STABILITY

6.1 Visual Examination

E

D

The visual examination indicates the following potential structural problems:

- (1) The downstream tilt of the concrete core wall with large vertical cracks and spalling indicates that it has been unstable at one time. On the basis of the visual inspection alone, it is not possible to determine if the remedial measures taken in the past are adequate to ensure the present stability of the wall.
- (2) The lack of erosion protection on the upstream and downstream slopes of the embankment and the right abutment leaves the embankment susceptible to erosion by rainfall runoff or, if the dam should be overtopped, by overflowing water.
- (3) Trees which are partially buried in the downstream slope and trees growing on the left abutment could cause seepage and erosion problems if a tree blows over and pulls out its roots, or if a tree dies or is cut and its roots rot.
- (4) Seepage at the downstream toe of the dam, if not controlled, could result in long-term instability.

6.2 <u>Design and Construction Data</u>. The original stone dam was designed by H.W. Sawyer, Professional Engineer, Goffstown, New Hampshire and was built by the Uncanoonuc Mountain Incline Railway Company in 1921.

6.3 <u>Post-Construction Changes.</u> It is not known when the present concrete core wall dam was built to replace the original stone dam, but records indicate it to be in existence by 1936, and the last known repairs were made to the dam in the same year.

6.4 <u>Seismic Stability</u>. This dam is located in Seismic Zone 2 and, in accordance with the Phase I guidelines, does not warrant seismic analysis.

; k

SECTION 7

ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES

7.1 Dam Assessment

T

D

a. <u>Condition</u>. The visual inspection indicates that Uncanoonuc Dam #2 is in fair condition. The major concerns with respect to the integrity of the dam are:

(1) Downstream tilt of the concrete core wall with large vertical cracks and spalling

•

•

- (2) Lack of erosion protection on the embankment and the right abutment
- (3) Trees which are partially buried in the earthfill on the downstream slope
- (4) Seepage at the downstream toe of the dam
- (5) Presence of a house close to the downstream toe of the dam and extensive trespassing on the embankment.
- (6) Lack of a low level regulating outlet that would allow drawdown of the lake in an emergency

b. <u>Adequacy of Information</u>. The information available from the visual inspection and hydraulic computations is adequate to identify the problems listed in 7.2. These problems will require the attention of a qualified registered professional engineer who will have to make additional engineering studies to design or specify remedial measures. No additional information is needed for the purposes of this Phase I investigation.

c. <u>Urgency</u>. The owners should implement the recommendations in 7.2 and 7.3 within one year after receipt of this Phase I report.

7.2 Recommendations

The owners should retain a registered professional engineer who is qualified in the design and construction of dams to:

(1) Investigate the structural stability of the tilted and cracked concrete core wall and design remedial measures if needed.

- (2) Design and specify erosion protection for the upstream and downstream slopes of the embankment, the right abutment and the spillway apron.
- (3) Specify and oversee procedures for the removal of trees and their root systems from the downstream slope of the dam and the left abutment.
- (4) Investigate the seepage at the downstream toe of the dam and design remedial measures if needed.
- (5) Assess the need for and means to provide a low level regulating outlet that would allow drawdown of the pond in an emergency.

The owner should implement the recommendations made by the engineer.

7.3 Remedial Measures

(

- a. Operating and Maintenance Procedures. The owners should:
 - (1) Visually inspect the dam and appurtenant structures once each month.
 - (2) Establish written maintenance and operating procedures, especially stipulating that stoplogs not be installed in the spillway.
 - (3) Engage a registered professional engineer qualified in the design and construction of dams to make a comprehensive technical inspection of the dam once every year.

- (4) Establish a surveillance program for use during and immediately after periods of heavy rainfall and also a warning program to follow in case of emergency conditions.
- (5) Ideally, there should be no structures located within the immediate vicinity of the dam, such as the existing house near the left abutment. Although it is not reasonable to recommend that the house be removed, the residents should be made aware of the effects that trespassing (vandalism and restricting vegetation growth) and landscaping (planting and digging up trees and shrubs) have on the structural integrity of the dam. The residents should take measures to restrict these activities.

7.4 Alternatives

There are no practical alternatives to the recommendations of Section 7.2 and 7.3

APPENDIX A

7

INSPECTION CHECKLIST

	INSPECTIO	N CHEC	K LIST
	PARTY OI	RGANIZ	ATION
PRO	JECT: Uncanoonuc Lake Dam #2, NH		DATE: <u>December 13, 1979</u> TIME: <u>9:30 a.m.</u> WEATHER: <u>Cold. cloudy</u> W.S. ELEV. <u>655.1</u> U.S. <u>647.9</u> DN.S (NGVD)
PAR	TY:		
1.	_Kenneth Stewart, S E A	6.	Kenneth Stern, N.H.W.R.B.
2.	Robert Durfee, S E A	7.	
3.	Bruce Pierstorff, S E A	8.	
4. -	Philip Ricardi, S E A	9.	
5.	Ronald Hirschfeld, GEI	10.	
	PROJECT FEATURE		INSPECTED BY REMARKS
1.	Structural Stability		K. Stewart/R. Durfee
2.	Hydrology/Hydraulics		<u>B. Pierstorff/P. Ricardi</u>
3.	Soils and Geology	<u></u>	R. Hirschfeld
4.	·····	<u> </u>	·····
5.			
6.	<u></u>		
7.			
8.			
9.	·		
10.			·

ŀ

.

INSPECTION	CHECK LIST
PROJECT: <u>Uncanoonuc Lake Dam #2, NH</u>	DATE:
PROJECT FEATURE: Dam Embankment	NAME:
DISCIPLINE:	NAME:
AREA EVALUATED	CONDITIONS
DAM EMBANKMENT	······································
Crest Elevation	656.6
Current Pool Elevation	655.1
Maximum Impoundment to Date	Unknown
Surface Cracks	Three large vertical cracks through top of concrete core wall
Pavement Condition	Not paved
Movement or Settlement of Crest	None observed
Lateral Movement	Concrete core wall is tilted downstream
Vertical Alighment	Good
Horizontal Alignment	Poor alignment of concrete core wall
Condition at Abutment and at Concrete Structures	Good
Indications of Movement of Structural Items on Slopes	None observed
Trespassing on Slopes	One footpath on downstream slope
Vegetation on Slopes	One bush on upstream slope. Trees on down- stream slope
Sloughing or Erosion of Slopes or Abutments	None observed
Rock Slope Protection - Riprap Failures	No riprap
Unusual Movement or Cracking at or near Toe	None observed
Unusual Embankment or Downstream Seepage	One minor seepage at downstream toe half- way between spillway and left abutment
Piping or Boils	None observed
Foundation Drainage Features	None observed
Toe Drains	None observed
Instrumentation System	None observed

``·

.

•

•

INSPECTION	CHECK LIST
ROJECT: Uncanoonuc Lake Dam #2, NH	DATE: December 13, 1979
ROJECT FEATURE: Dike Embankment	NAME:
DISCIPLINE:	NAME:
AREA EVALUATED	CONDITIONS
IKE EMBANKMENT	No Dike
rest Elevation	
urrent Pool Elevation	
laximum Impoundment to Date	
urface Cracks	
avement Condition	
lovement or Settlement of Crest	
ateral Movement	
ertical Alignment	
orizontal Alignment	
condition at Abutment and at concrete Structures	
ndications of Movement of Structural tems on Slopes	
respassing on Slopes	
egetation on Slopes	
loughing or Erosion of Slopes or Abutments	
ock Slope Protection - Riprap Failures	
nusual Movement or Cracking t or near Toes	
nusual Embankment or Downstream Seepage	
iping or Boils	
oundation Drainage Features	
oe Drains	
nstrumentation System	

. .

I

ļ

PROJECT:	INSPECTION	CHECK LIST
PROJECT FEATURE: Intake Channel NAME: DISCIPLINE: NAME:	ROJECT: <u>Uncanoonuc Lake Dam #2, NH</u>	DATE: December 13, 1979
DISCIPLINE: NAME: AREA EVALUATED CONDITIONS OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE a. Approach Channel Slope Conditions Bottom Conditions Rock Slides or Falls Log Boom Debris Condition of Concrete Lining Drains or Weep Holes b. Intake Structure Condition of Concrete Stop Logs and Slots	ROJECT FEATURE: Intake Channel	NAME:
AREA EVALUATED CONDITIONS OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE No outlet works a. Approach Channel Slope Conditions Bottom Conditions Bottom Conditions Rock Slides or Falls Log Boom Debris Condition of Concrete Lining Drains or Weep Holes D b. Intake Structure Condition of Concrete Stop Logs and Slots Stop Logs and Slots	SCIPLINE:	NAME:
AREA EVALUATED CONDITIONS OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE No outlet works a. Approach Channel Slope Conditions Bottom Conditions Rock Slides or Falls Log Boom Debris Condition of Concrete Lining Drains or Weep Holes b. Intake Structure Condition of Concrete Stop Logs and Slots Stop Logs and Slots	· · · · · · · · · · · · · · · · · · ·	
OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE a. Approach Channel Slope Conditions Bottom Conditions Rock Slides or Falls Log Boom Debris Condition of Concrete Lining Drains or Weep Holes b. Intake Structure Condition of Concrete Stop Logs and Slots	AREA EVALUATED	CONDITIONS
a. Approach Channel Slope Conditions Bottom Conditions Rock Slides or Falls Log Boom Debris Condition of Concrete Lining Drains or Weep Holes b. Intake Structure Condition of Concrete Stop Logs and Slots	UTLET WORKS - INTAKE CHANNEL AND NTAKE STRUCTURE	No outlet works
Slope Conditions Bottom Conditions Rock Slides or Falls Log Boom Debris Condition of Concrete Lining Drains or Weep Holes condition of Concrete Stop Logs and Slots	. Approach Channel	
Bottom Conditions Rock Slides or Falls Log Boom Debris Condition of Concrete Lining Drains or Weep Holes b. Intake Structure Condition of Concrete Stop Logs and Slots	Slope Conditions	
Rock Slides or Falls Log Boom Debris Condition of Concrete Lining Drains or Weep Holes b. Intake Structure Condition of Concrete Stop Logs and Slots	Bottom Conditions	
Log Boom Debris Condition of Concrete Lining Drains or Weep Holes b. Intake Structure Condition of Concrete Stop Logs and Slots	Rock Slides or Falls	
Debris Condition of Concrete Lining Drains or Weep Holes b. Intake Structure Condition of Concrete Stop Logs and Slots	Log Boom	
Condition of Concrete Lining Drains or Weep Holes b. Intake Structure Condition of Concrete Stop Logs and Slots	Debris	
Drains or Weep Holes b. Intake Structure Condition of Concrete Stop Logs and Slots	Condition of Concrete Lining	
b. Intake Structure Condition of Concrete Stop Logs and Slots	Drains or Weep Holes	
Condition of Concrete Stop Logs and Slots	. Intake Structure	
Stop Logs and Slots	Condition of Concrete	
	Stop Logs and Slots	
I I		
INSPECTIC	ON CHECK LIST	
---	------------------	
PROJECT: <u>Uncanoonuc Lake Dam #2, NH</u>	DATE:	
PROJECT FEATURE:	NAME:	
DISCIPLINE:	NAME:	
AREA EVALUATED	CONDITIONS	
OUTLET WORKS - CONTROL TOWER	No control tower	
a. Concrete and Structural		
General Condition		
Condition of Joints		
Spalling		
Visible Reinforcing		
Rusting or Staining of Concrete		
Any Seepage or Efflorescence		
Joint Alignment		
Unusual Seepage or Leaks in Gate Chamber		
Cracks		
Rusting or Corrosion of Steel		
b. Mechanical and Electrical		
Air Vents		
Float Wells		
Crane Hoist		
Elevator		
Hydraulic System		
Service Gates		
Emergency Gates		
Lightning Protection System		
Emergency Power System		
Wiring and Lighting System		

ĺ

٠.-

.

۰.

INSPEC	TION CHECK LIST
PROJECT: <u>Uncanoonuc Lake Dam #2, NH</u>	DATE: December 13, 1979
PROJECT FEATURE: Transition and Co	onduitNAME:
DISCIPLINE:	NAME:
AREA EVALITATED	CONDITIONS
OUTLET WORKS - TRANSITION	
AND CONDUIT	None
General Condition of Concrete	
Rust or Staining on Concrete	
Spalling	
Erosion or Cavitation	
Cracking	
Alignment of Monoliths	
Alignment of Joints	
Numbering of Monoliths	

1....

Ŕ

.

O

l

•

.

12*

i :

é

INSPECTION	CHECK LIST	
PROJECT: <u>Uncanoonuc Lake Dam #2, NH</u>	DATE: <u>December 13, 1979</u>	
PROJECT FEATURE: <u>Outlet Structure</u>	NAME:	
DISCIPLINE:	NAME:	
AREA EVALUATED	CONDITIONS	
OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL	None	
General Condition of Concrete		
Rust or Staining		
Spalling		
Erosion or Cavitation		
Visible Reinforcing		
Any Seepage or Efflorescence		
Condition at Joints		
Drain holes		
Channel		
Loose Rock or Trees Overhanging Channel		
Condition of Discharge Channel		

È

••.

ľ

i.

- -

•.•

. . . .

-

ł

1

INSPECTION	CHECK LIST
PROJECT: <u>Uncanconuc Lake Dam #2. NH</u>	DATE:
PROJECT FEATURE: Spillway Weir	NAME:
DISCIPLINE:	NAME:
AREA EVALUATED	CONDITIONS
OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS	
a. Approach Channel	
General Condition	Good
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None
Floor of Approach Channel	Sand and gravel
b. Weir and Training Walls	
General Condition of Concrete	Poor
Rust or Staining	None observed
Spalling	Extensive
Any Visible Reinforcing	None
Any Seepage or Efflorescence	None observed
Drain Holes	None
c. Discharge Channel	
General Condition	Fair
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	Trees overhanging channel
Floor of Channel	Soil
Other Obstructions	None

A-3

INSPECTIO	N CHECK LIST	
PROJECT: <u>Uncanoonuc Lake Dam #2, NH</u>	DATE: <u>December 13, 1979</u>	
PROJECT FEATURE:	NAME:	
DISCIPLINE:	NAME:	
AREA EVALUATED	CONDITIONS	
OUTLET WORKS - SERVICE BRIDGE	No service bridge	
a. Super Structure		
Bearings		
Anchor Bolts		
Bridge Seat		
Longitudinal Members		
Under Side of Deck		
Secondary Bracing		
Deck		
Drainage System		
Railings		
Expansion Joints		
Paint		
b. Abutment & Piers		
General Condition of Concrete		
Alignment of Abutment		
Approach to Bridge		
Condition of Seat & Backwall		

L.

. . .

.

ŧ.:

-]

APPENDIX B ENGINEERING DATA

F

(

(

ŧ

١.

AVAILABLE ENGINEERING DATA

No engineering data, other than past inspection reports from the State of New Hampshire Water Resources Board, were available for the existing structure of Uncanoonuc Lake Dam #2.

(

PAST INSPECTION REPORTS

. . 172

4 . .

Ň

1

1

L

I

ŝ

Date: December 20, 1979

To: Vernon A. Knowlton, Chief Engineer

1

From: Ken Stern, Water Resources Engineer

Subject: Corps Inspection of Uncanoonuc Lake No. 2, Dam No. 93.03

On December 13, 1979 I accompanied the inspection team from SEA consultants. Their contract called for the inspection of No. 93.04 which is an earth dike upstream of a vast, undeveloped, swamp area. The Corps inventory photographs in file No. 93.04 were of dam No. 93.03 which is the outlet structure for the impoundment. There is a house directly downstream of No. 93.03 making this dam a menace structure. After considerable discussion the consultants decided to inspect the more hazardous structure.

This dam, No. 93.03, is in fair to poor condition. It is an earth dam with a concrete core wall. The spillway is 16 ft. long with 1.5 ft. of freeboard. There is a concrete apron, which leads to mortared stone slope protection, downstream of the spillway. The major items worthy of note are:

- 1- The concrete core is leaning, cracked, spalled and has a poor alignment,
- 2- The top of the dam is erodible gravel with no vegetative cover,
- 3- There are several large trees on the downstream slope. These trees are stabilizing the slope. There is a combination of various wood planks between some of these trees,
- 4- There is slight seepage coming out of the downstream right toe. The area was wet but there was very little if any discernable flow.

The house just downstream is owned by:

Fran Blazon Mountain Base Road Goffstown, NH

According to her deed her land is bounded by the concrete core wall but makes no mention of the dam or water rights. The dam apparently is owned by the Town.

Dam No. 93.04 is an earthen dike built out of very sandy material. The upstream slope has stone riprap in areas. The dike is used as a bathing area and has very little vegetative cover. Several large seeps were observed at the downstream toe but a thorough inspection was not performed due to the lack of threat to life or property should the dam fail.

I believe any action on these structures can wait until receipt of the Corps' reports.

KS:paf Enc. Page 1

Dam No. 93.03 inspected by Ken Stern on December 13, 1979

View of crest from right side



ľ

View of downstream slope and house from right side



View of Spalled Concrete





Army Corps of Engineers Dam Inventory Program Date 4/22/7/ Dain # ______ Corps # 21-93:4-284 Description: j'un along dans from right side - near road Dam # 93.04Corps # 21-93.04-28.5Description:) ili-i/ 17 pilling first 75 de-unistionic B-

E

D

Army Corps of Engineers Dam Inventory Program Date 4/32/14 Dam # <u>9364</u> Corps # 21-93.64-28.6 Description: Mico of dans from 125 ± upstreame B-7

0

.

MEMORANDUM

Case No. C35-C 73.03

TO: Water Control Commission

5

.

.

0

2

RE: Uncanconuc Brook in Goffstown, N. H.

This dam has been constructed in accordance with our directions and I recommend that final approval be given.

It is our intention to watch this dam rather closely and see that the flashboards are removed during the flood season.

> Richard S. Holmgren Chief Engineer

1/11/39

NEW HAMPSHIRE WATER CONTROL COMMISSION DATA ON DAMS IN NEW HAMPSHIRE

LOCATION	STATE NO93.03
Town	Hillsboro
Stream Uncanconuc Brook	
Basin-PrimaryMerrimack.River: Secondary	
Local Name I.A.I.A.	
Coordinates-Lat	35! -900!
GENERAL DATA	
Drainage area: ControlledSq. Mi.: Uncontrolled	
Overall length of dam 131 ft.: Date of Construction	
Height: Stream bed to highest elev8ft.: Max. Structur	e ft.
Cost—Dam: Reservoir	
DESCRIPTION Gravity- Earth Rock on Timber Waste Gates	crib Concrete
Type	
Number ft. high x	ft. wide
Elevation Invert: Total Area	sq. ft.
Hoist	
Waste Gates Conduit	
Number	
Sizeft.: Lengthft.: Area	sq. ft.
Embankment	
Туре	
Height-Max ft.: Min	ft.
Top-Width: Elev	ft.
Slopes—Upstream on on : Downstream .	on
Length-Right of Spillway: Left of Spillw	/ay
Spillway	
Materials of Construction	·····
Length-Totalft.: Net	ft.
Height of permanent section-Maxft.: Min	ft.
Flashboards—Type	: Height ft.
Elevation—Permanent Crest	p of Flashboard
Flood Capacity180 cfs.:	cfs/sq. mi.
Abutments	
Materials:	
Freeboard: Max ft.: Min	ft.
Headworks to Power Devel(See "Data on Power Developm	ent")
OWNER Uncanconuc Incline Ry- Development	
REMARKS Went out in 1936 (under constructi	on)

11

File C35-C

MEMORANDUM

TO: Richard S. Holmgren, Chief Engineer

D

RE: Dam at Uncanoonuc Mountain. (Henry A. Laxson)

Visited the dam at Uncanconuc Mountain and found eight inches of flash boards on the spill. The water was one inch below the top of the flash boards.

I should say the pond is about at its maximum capacity, the water being up to the road as you approach the pond from the upper dam. There is no water being spilled at the upper dam, either over the flash boards or through the gate and the gate is closed at the lower dam. There seems to be very little leakage at the lower dam.

An extra quantity of fill has been dumped in on the up. stream face of the lower dam and also considerable on the down stream face on the east side. The holes abutting the dam on the west side where fill was taken out have been filled up as you ordered.

I believe this dam can now be given approval such as it is, but I do believe that in case of prolonged rains or high water that flash boards should be pulled on both dams and controll gates opened, as I still question the stability of the structure.

Respectfully submitted,

Charles D. Colman Assistant Engineer





Case No. C35-C

UNCANOONUC BROOK IN GOFFSTOWN Uncanconuc Incline Bailway and Development Company

K

9

K



Locking at Downstream Face of Cverflow Dam at Southeast End of Pond



Upstream Face Looking North - Overflow Dam Southeast of Pond

Manchester Union, October 18, 1921.

START ARTIFICIAL LAKE AT BASE OF UNCANOONUC MTS.

The building of two dams to keep back the waters of the Sam Orr brooks at the base of Uncanoonuc mountain, in Goffstown, which will flood 50 acres of land at the mountain base, will give that summer resort a lake for bathing and boating purposes, which is expected to be ready by next summer. Work has already started on one of the dams and it is expected that both structures will be well on the way to completion before the weather interferes.

Papers were passed last week transferring a strip of land to H. A. LAXSON. manager of the incline railway, which gives him possession. of. land upon which to build the bigger of the two dams, which will be 200° ft. long and 25 foet high. The second dam will be of these letters have been returned to land which will be flooded and the work is being rushed with two large gangs of men working, as the weather has been dry and suited for the work. The new lake, which will be named by the public, will be twice as large as Pine Island or Crystal lake, according to the survey made by Engineer H. A.

The new lake, which will be named by the public, will be twice as large as Pine Island or Crystal lake, according to the survey made by Engineer H. A. Sawyer of this city, who has mapped out the site of the new, lake. The fand on the lake shore is owned by H. A. Laxson, Ferson brothers, Shirley Johnson of the Shirley Hill house and the Uncanconuc Mt. Incline railway. The four land owners expect to develop their property for camp sites and the Shirley Hill house management expects to use some of its land this winter for winter sports as the hotel will open for the winter season on Dec. 10. Besides building two dams and cut-

Besides building two dams and cutting down the timber on the area to be flooded, which investment means an outlay of several thousand dollars, the

incline trailway people are building a new automobile road which will bring the mountain base half a mile nearer to Manchester as it will cut off the treacherous hill at Cram's crossing. The new road will bear towards the right at Cram's crossing, alongside of the surface line of the mountain electric road to the base. Frank A. Hebert is superintendent of construction in charge of the two crews building the dams and clearing the brush. The incline railway intends to build _____

The incline railway intends to build an amusement park on the shore of the new lake, right at the foot of the mountain. There will be a bath house as well as all the attractions that go to make a summer park popular.

PLANS AND DETAILS

Ľ

Ð

6

۰.

1

.



Ì.

APPENDIX C

÷.*.

1

٢

Í

1

.۱

SELECTED PHOTOGRAPHS



П

0

Q

A SHA MAR IN GAMBORTH ASN.44A



Photo No. 1 - General view of lake from dam.



Photo No. 2 - General view of dam from lake.

L



Photo No. 3 - View of upstream face of left side of dam from right shoreline.



Photo No. 4 - View of crest of dam and left abutment from right abutment.



₹

(

Ō

Photo No. 5 - Closeup view of spalling at top of concrete core wall.



Photo No. 6 - View of upstream face of spillway.



Photo No. 7 - View of downstream face of right side of dam.



Photo No. 8 - View of downstream face of left side of dam.

. . .



U BEESESSEE DESERT

Photo No. 9 - Closeup view of seepage between toe of dam and dwelling.



Photo No. 10 - View of downstream face of spillway.



Photo No. 11 - View of downstream channel from top of dam.



Photo No. 12 - View of downstream ponding area and outlet culvert from roadway below dam.

the property processes and

APPENDIX D

C

H

2

•...

ŧ

١

ŧ

۱.

HYDROLOGIC AND HYDRAULIC COMPUTATIONS



E

D

.

SIEIA CONSULTANTS INC. BOSTON , MASS. ENGINEERS / PLANNERS ROCHESTER, N.H. CLIENT I My Corps of Engineers JOB No. 2-2-1901 _ PAGE _____ PROJECT MACINOSTIC LONG DOW HE COMPTO. BY 5 .0 ر حو DATE _ DETAIL _____ Hydrologi- Caler ____ CK'D. By _____ -1/2/30 DATE ___ In Basic Data A Drainage Area 1. 0.26 Sq m. 1- - a defined in 1.5. 0.5 sheets and them planimetered. 2 Prairage area would be Massified as mountainous, and since reservoir linge compared to drainage area as rolling care for astimation MPT. B. Dam and Storage Information 1. SIZE Classification: Small based on storage (250 and 61,000 Fore-22) indicated below, stage at crost it dam estimated to be 151 Bare- it. 2 Husard Potential: SIGNIFICANT May impact I house and 2 town roads 3. Storage Information File thing Sirface Descriptive Storage Area (Acres) (acre- f+) Jairmaron. +1 660 Confour 660.0 33.1 255 657.1 <u>_</u>∵, € 174 test flood bres of am 25.3 650.0 151 Spilling inst office 1 25.2 1.2 Flore 1. clerations . 11513 (2) normal Food planstion is based on an an energia of 655.0 extrapolater from 1.5.6.5. Q12 drangle sheet assumed to be pool electration

r

D

D-2

at pormanent spailway cross.

SEA CONSULTANTS INC. BOSTON , MASS. ENGINEERS / PLANNERS ROCHESTER, N.H. CLIENT JUMP COLOS OF JUNPER JOB NO. 274-721 PAGE 21 22 PROJECT MONTORISTIC AND DATE 200 22 COMPTO. BY DATE 282 32 DETAIL ______ Hoder to 13 13 5. ____ CK'D. BY ____ DATE _____ DATE _____ CK'D. BY C. Sr day Inormation 1. Termining the ported approximation of the sector It the Parth filled strusture, consists of a 16.1 for while of 1.8 foot deep stoplay bay through the top it the concers core will a Ai the time of inspection, all the store bas is d Leen removed Trere for the subsequent calculations it specify it has assumed that the stores yourd not be in place 2. Decourse over the spilling given by prosterestic wer store . I = CLH 3/2 (Standard Gandloss & is SE Perrie Hinere: Q = discharge, Cts 6= discharge coofficient ise 2.3 L: wer ling the front H - hParl acra weir, som IT Estimate I feet a Sarange storage in Maximum Proban & Course A Deven stays discourse curve for some bar han son 1. define surces of outflow a fire our comment of the prophy complet · I man the see a so to a subset and 1. min 655.7 are propherested with paristin 2 = 2.6 I down in a construction of dame - attre sucrage deration and 1) use brood-crester weir equation, C = 3 :. a discourse come and mental-(1) is the second of the second se

R

D

SIEIA CONSULTANTS INC. Engineers / planners

r

P

(en

BOSTON , MASS. Rochester, N.H.

CLIENT_	tering	1.1.23	7. 1.	2 1. A. C.
PROJECT	Jer	02.01	- 2h	tom + "
DETAIL _	1.1			

		PAGE_	5-1-7-2
COMPTO. BY_	PPE	DATE _	6 2-1 21
CK'D. BY	<u></u>	_ DATE _	

2 Description the age Spir and

Electris.	2	L	<i>m1</i>	~
<u> </u>		المحجر	100-	- ي شرح
0555.2 655.5 656.6 550.6 557.0	2. 2 7. 3	3. 15.1	0.5 1.7 	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
558.0			5.2	213
659.5	1	٠.	وب	55
660.0	Ϋ́	Ϋ	5-2	وكطب ا

J. L. inarge over that intrate core wall

Elevation (feet)	Ĵ	(feet)	avs Hi (from)		A (?=5)
656.7			-		7
657.0	×. 0	66	<u>_</u>		ZB
659.0			1.2	;	254
557.0			2.3	ļ	
\$ 50.9	7	$ = \sum_{i=1}^{n} \sum_{j=1}^{n} \sum_{j=1}^{n} \sum_{i=1}^{n} \sum_{j=1}^{n} \sum_{j=1}^{n} \sum_{i=1}^{n} \sum_{i=1}^{n} \sum_{j=1}^{n} \sum_{i=1}^{n} \sum_{j=1}^{n} \sum_{i=1}^{n} \sum_{i=1}^{n} \sum_{j=1}^{n} \sum_{i=1}^{n} $	3.3		: 30

" rischarge over right increte core will

Elen den Geren			an faire	
	-	-		
		63		
تي ور			: • •	· · ·
		,		
and the second	. 7	Ì 'v		- 32

SIEIA CONSULTANTS INC. Engineers / planners

1

9)

(

BOSTON , MASS. Rochester, N.H.

CLIENT_	Prove Proce	JOB NO	PAGE_	
PROJECT	Incontraction -im #Z	COMPTO BY		<u></u>
DETAIL _	Manner Tales	CK'D. BY		4- 9.
	5. Deinarge over rig	nt abutment -		

break who two segments will between concrete which will roadway - 12, roadway and eagend

a. First == ment

Eccutor	C	<u>ل</u> (دمه ر	aug 1H	()
656.8	2.0	0	<u>د</u>	Ċ
57.0 E		2	C.1	(1)
653.0		iD	0.6	12
659.0		01	1.6	53
660.0	4	10		109

b. Second segment

Elevation (feet)	C	L (fee t)	ary H (feet)	
657.3	2.6	0	Ċ	ن ن
655.0		9		
659.0		55	0.6	<i>فاف</i>
660.0	•	100	1.1	300

6 Discharge over lett abuincom

Eleven	C	L (icet)	ane 4 Cont	(بست
s56 . 8	2.6	0	0	-
657.0		=	<i>.</i>	\leq
655.0		د	0.6	1 1 1
659.0			1.	Ľ,
665.5	7	15	1.5	
SIEIA CONSULTANTS INC. ENGINEERS / PLANNERS

BOSTON , MASS. ROCHESTER, N.H.

CLIENT PERM Creco	JOB NO	PAGE_	
PROJECT 1	COMPTO. BY		<u>.: 2 20</u>
DETAIL	CK'D. BY		<u></u>

7. Total Discharge from dam ette

T

D

	-	
\sim	· .	

 Ξ

Fleigt m	سور م <u>∍</u>	iet- cre	O Figure Cire Back	Total Fight Loutment	ier-	
د.ت:∠	-	0	0)	-	ت
655.5 656.0	15 4 2	00			<i>C</i>	
657.C	113	29	27	00	~1	
655.0	213	254	243	3		75
659.0	335	599	57)		5	
	463	1030	432	<u>جرمہ</u> ا	. 22	

Discharge 115 Elevation Crown Oray and Figure 1

シージ



CLIENT_	Army Corps	Joв No. <u>274-730</u>	PAGE
PROJEC1	<u>Lincandeque Lake Van FFE</u> Hudnologio Calco	Сир Ви КИЗ	UATE
UETAIL _	AVURDIOSIC CAICS	UK'D. BY	UATE
В.	Effect of surcharge store	age on max. prob. dis	charge
	1. Pertinent Data		
	a. Drainage area =	0.26 square miles	
	b. Characteristics of	of basin - mountaino	رئىد
	c. Test flood = (CC-Y	'r≈¼PMF	
	d. Follow Army Corps	s' procedure	
	2. <u>STEP 1</u> : Determine Pe	eak Inflow Q _{Pl} from	Guide Curve
	a. the maximum proba	able discharge was es	timated to
	be 3,300 cfs	/sg.mi	
	PMF = (3	,300 c+=/sg.mi)(0	,26 sy. mi)
	- 85	8 cfs	
	1/4 PMF ≈	100 yr- filosi 🕿 Z	215 cfs
	3. <u>STEP 2:</u> Determine su and Q _{P2}	urcharge height to pa	ass Q _{P1} , ^{STOR} 1,
	a. from Figure 1 de $Q_{P1} = 215$	termine surcharge hei Å s	ight to pass
		Survey and	
		elev opining went	en la companya de la La companya de la comp
		Enclored munt	= 2.1
	b. determine volume runoff	of surcharge CT.5.	in inches .:
	- Jetermine Veno	ne ve breze en tra	•: -= 32 A - 22
	(1) Liter mine	"intrace create i	
	a an	ange Lander man	The 2 we let be
	-	>~ 3	

Į

C

.

•

D

_

j.



SIEIA CONSULTANTS INC. Engineers / planners

D

L.

14

BOSTON , MASS. Rochester, N.H.

SLIENT	Army Corps	Jos No. 274-7901	PAGE
PROJECT.	Hudnologia Calos	Сомрто. Ву <u>ВWP</u>	DATE
	(2) Jurner and 3. Milling Nevert		une an sur compt
	STOR ₁ = <u>Volume</u>	of storage (as acre-ir	nches)

STOR₁ =
$$\frac{\left(\frac{23.9 \text{ sime} + 27.8 \text{ sime}}{2}\right)\left(2.1 \text{ ft}\right)\left(12^{2}/\text{ ft}\right)}{(0.20 \text{ sigma})\left(3.0 \text{ sime}/29.000\right)}$$

STOR₁ = 3.91 incluse

c. determine Q_{P2}

$$Q_{P2} = Q_{P1} \left(1 - \frac{\text{STOR}_{1}}{4.75''} \right)$$

$$Q_{P2} = \left(215 \text{ cfs} \right) \left(1 - \frac{3.91''}{4.75''} \right)$$

$$Q_{P2} = 38 \text{ cfs}$$

4. STEP 3: Determine surcharge height on $1.775_{\rm P}$ for $\rm Q_{P2}$ and then $\rm Q_{P3}$

a. From Figure 1 determine surcharge height to pass $Q_{P2} = 38$ cfs

Survivage distantion
$$= 25.0^{\circ}$$

electropy and the $\frac{25.0^{\circ}}{25.0^{\circ}}$
the charge races $= 2.0^{\circ}$

Divit our area in the company will be the 2000 in

2-10



È

SIEIA CONSULTANTS INC. BOSTON , MASS. ENGINEERS / PLANNERS ROCHESTER, N.H. JOB No. 274-7901 CLIENT Army Corps PROJECT Un CANSON N Lake Dam #2 COMPTO. BY BWP DETAIL Hydrologic Calcs _____ Ck'o. By _____ STOR, = 2.93 incles c. determine STOR $STOR_{AVG} = \frac{2.75 \text{ in } + 2.93 \text{ in }}{7}$ STORANG = 2.84 inches d. determine Q_{pu} $Q_{p_{\mu}} = (215 \text{ cfs}) (1 - \frac{2.24}{4.75})$ Qp4 = 86 cfs 6. STEP 5: Determine surcharge height for $Q_{p_{\mu}}$ and STOR_{$\mu}$ </sub> a. From Figure 1 surcharge height for $Q_{Ph} = \frac{1}{2}$ is Surveye elevation = 550.0. in spilling and in the destruction conceases haven't = 1.6 ist what have at the ange eler of 33.3 and b. determine STOR₄ $STOR_{4} = \frac{\left(\frac{23.3 \text{ ac}}{2} + \frac{76.3 \text{ ac}}{2}\right)\left(1.6 + \frac{1}{2}\right)\left(\frac{127}{4}\right)}{\left(0.26 \text{ sg.mi}\right)\left(640 \text{ ac}\right)\left(\frac{1}{2} + \frac{1}{2}\right)}$ STOR4 = 2.43 min c. determine STOR_{AVG} STORAVG = = _____ 1-12

. •

D

SIEIA CONSULTANTS INC. Engineers / planners

BOSTON , MASS. Rochester, N.H.

CLIENT COLOR	JOB NO.	PAGE_	
PROJECT IN THOSE AND AND THE	COMPTO. BY	DATE _	
DETAIL Haten and Bles	Ск'р. Ву	DATE _	

STORL and STOR AND AND THE AND autophine aver accept routed was a outophine at the second it 655.6 -cit

7 In Conclusion

- a. Postal med with and the conducted almost evently equal to the conducted spicing capacity with the conducted at the crest of dam (see scion).
- L Spillway capacity Stoplog (3) remains (1) water level at crest of dam- simultar intervent $Q = (2.6)(16.1fr)(656.6' - 655.0')^{3/2} \approx 35c - 10$

	ENGIN	EERS /	PLAP	NEAS				ROCH	ESTE	R, N.H.				
	CLIEN	т <u>Арл</u>	ny Cor	DS		<u> </u>	`	Jos No	n. <u>27</u>	4-7901	P	AGE	13 of 23	3
i	PROJE	:ст <u>.</u>	<u></u>	nuc hat	<u>ke Da</u>	<u>~ ± 2</u>			3. B Y	BWP	D	ATE _	5/19/90	
÷		•ـــــــــــــــــــــــــــــــــ	<u>arol</u>	<u>. g C.</u>	<u>alos</u>			шк'о. Е	· · ·	<u> </u>	0	ATE _		—
I	11. U Hy	sing ' ydrogi	raphs	or Thu examin	umb" ne im	Guida pact	nce of (ror Es lam faì	tima lure	ting Dou	wnstre.	am Da	m Failure	
		1.	Pert	tinent	Data									
			a.	Failu: dam -	re oc elev	curs ation	whei =	n reser 656.	voir 6 fe	level a et	at cre	st of		
			Ъ.	Storaį	ge at 61 Q	cres رو -	t e.	levatio ±	n es	tìmated	to be	appr	oximately	
	A	. Rea	ich l			٩	•							
		1.	STEI	<u>21</u> : 1	Deter	mine	rese	ervoir	stor	age at a	time o	f fai	lure	
9					fr	om pr	vevi	ous cal	CS.	storage	و: =	1 acr	2	
		2.	STE	<u>2</u> : 1	Deter	mine	Peal	< Failu	.re 0	utflow	Q _{Pl}			
				Q _{Pl}	= (8	/27)	м ^р	Vg Y	3/2 0					
					wh	ere:	м ^Р	= Brea = (0.	.ch w 4) (idth (us 147 fee	se 408 et)	of t	otal lengt	h)
								~ 58	3.3	feet				
							Y _o	= Tota leve	l he. 1 at	ight fro failure	om cha:	nnel	bed to poo	1
							Υ _c	, = 9	.0 f	eet	Lie: Ele:	u Chann	el 20.40m - 377.1	5
				Q _{P1}	= ({	3/27)	(5:	3.34)((32.	ż) ¹ /2 (9.9÷	-2		-
-				Q _{Pl}	=	2.6	70	cfs						
<u></u>				تم الم ال	L P Max	re feu k 	Sur Trafi	e die ared Michael refrait	rentar Le Last	en iver	- inc		ی بیسیل سمدنیال ۶	

SIEIA CONSULTANTS INC. BOSTON , MASS. ENGINEERS / PLANNERS ROCHESTER, N.H. JOB NO. 274-700 CLIENT TE SHE SET PAGE PROJECT LAND THE THE COMPTO BY TUP DETAIL Hatroiser Gles ____ CK'D. By ____ 2 -DATE _ 3. STEP 3 : Prepare Stage- Just and Turse for Reach 1 a. Partment Data (1) Spice the word in Reach 1 ... restal by a road embanisment at the what discharge from the reach will be controlled by the many the sense that he road b. See Figure 3 for sage-discorpe curve 4. STEP 4: Estimate reach sut ou a Determine stage ---- Op = 2,670 che -rom Figure 3 and yourse (1) Stage = 10.3 feet (2) Volume in reach = (Stage) (Average In see) Volume = V, = (10.32) (C. 62.4: - 5.62.m.) V1 = 31.9 aue- Let V < = :. . . b. Determine Opectric) $Q_{P2}(TRMP) = O_{P1}\left(1 - \frac{M_{P1}}{\epsilon}\right)$ $Q_{P2(TRIAL)} = (E, 160 c -)(1 - \frac{E_{1,1}}{M_{1,1}})$

F

D

i

SLIENT HEAL CHES	JOB NO. 274-7971	PAGE5
PROJECT LICATOR CLARED - A #Z	COMPTO. BY CUP	DATE
DETAIL My toploque Cales	CK'D. BY	DATE
PPZ(TR:	$e_{j} = 2,140 cm$	
C. Compute Vz	Using Opskir -	· · · · · · · · · · · · · · · · · · ·
From Figure	e 3 determine stag	a
	a = 9.9 fest	
$V_z = (9.9)$	(ft) (<u>0.620005 +</u> Z	E. 4 acres
$V_{I} = 20$	F and - Oot	
V2		
A Autor >1		te a
U. Aleraye VI	and VZ und is	
(1) Nang =	$\frac{V_1 + V_2}{Z}$	
V	31.9 aure- ++ +	29.7 ace
V W Je	2	
Vava =	30.9 aure - eit	
(2. Opz	$= O_{q_1} \left(1 - \frac{1}{q_1} \right)$	Land States
		- , · _
\mathcal{O}_{ez}	= (2,6=0c=,(
\sim	= 3 160 / -	

lo

.

۲

• • •

<u>_</u>___

-.

. -

SIEIA CONSULTANTS INC. Engineers / planners	BOSTON , MASS. Rochester, N.H.
GLIENT Army Cords	JOB NO. 294-7901 PAGE
PROJECT Lator Malan Dow # 2	_ Сомрто. Ву <u>ВWP</u> Date <u>57 9 90</u>
DETAIL Hydrologic Calcs.	CK'D. BY DATE
B. Reach 2	
STEP 3: Prepare sta	ge-discharge curve for Reach 2
a. Pertinent Data	
(1) Reach lengt	h = 1,250 feet
(2) Channel slo	pe = 0.036
(3) Manning n =	0.05
(4) Channel sha	pe - tracezoidal
(5) Base width	≈ 10 feet
b. See Figure 3 for	stage-discharge curve
•	
2. <u>STEP 4</u> : Estimate Re	ach Outflow
a Determine stage	for $0 = 2 i (0 c - s)$ from Figure 3
a. Determine stage	in reach
(1) Stage (dept	h of flow = 5.0 for +
(2) Volume in r	each = (reach length) (cross-sectional)
	(0.5)(5.01)(104+5.52)
X-area =	
	$(1250 \div)$
volume = V ₁	43,550 1,242
	- J. T acreeet
	$v_1 < \frac{S}{2}$: reach length OK
b. Determine QPATR	IAL)
	(v_1)
QP3(TRIA	$L) = \sqrt{P_2} \left(1 - \frac{1}{S} \right)$
Qostmary	$(2.160ch)(1-\frac{5.2}{151})$
·PS(IRIA	
Qartain	. = 2.040 cAs

•

D

•

Current Annu Conne	JOB NO. 274	-7901	AGE	17 07 7
PROJECT Delacomore Lake Dam +		BWP C	DATE	5 5 25
DETAIL Hydrologic_Calos	Ск'о. Ву	<u></u> (DATE	<u> </u>
c. Compute V $_2$ us	ing Q _{PE(TRIAL)}			
From Figur	re 3 determine sta	ge for $Q_{P\Xi}($	TRIAL)	
Stage :	= 4.9 feet			
X-area	= (0.5)(4.9ft) (10 f+	+ 64	<i>\$</i> +)
	= 181 + 2			
$v_2 = (1 \pm 1)$	(1, 250)	$\left(+ \right)$		
-	- 10, JOU TI / a cre			
$v_2 = 5$. 't ave-test			
	ad 11 and compute	0		
d. Average V ₁ a	$\frac{11}{2}$ 2 and compute	хрЗ		
(1) Vavg =	$\frac{V_1 + V_2}{2}$			
	2			
Vave =	<u>5.4 ac-f+</u>	+ 3.6 ac		
L ~	2			
Vavg =	5. 3 acre-	-ce+		
(2) Q _{P3} = ($\frac{2}{Pz} \left(1 - \frac{\sqrt{a}\sqrt{b}}{S} \right)$			
		5.7		
G =	(2,160 cfs)(1 - 15)	
- 43	`.			
	¢			

CLIENT	S / PLANNERS ROCHESTER, N.H.
	Anny Corps JOB No. 274-7901 PAGE
PROJECT.	Update of the and the Compto By DWF DATE - Field
DETAIL	Reach 3
<u> </u>	STEP 3: Prepare stage-discharge curve for Reach 3
	a. Pertinent Data
	(1) Reach length = $1,050$ feet
	(2) Channel slope = 0.033
	(.3) Manning n = 0.05
	(4) Channel shape - trapezodul
	(5) Base width ≈ 10 feet
	b. See Figure 3 for stage-discharge curve
	° 2. <u>STEP 4</u> : Estimate Reach Outflow
	a. Determine stage for $Q_{p,2} = 2.090$ cfs from Figure 3
	and find volume in reach
	(1) Stage (depth of flow) = 4.3
	(2) Volume in reach = (reach length) (cross-sectional) area of channel)
	$x_{-area} = (0.5)(4.3+.)(10++32+.)$
	= 219 - 4"
	volume = v, =
	= 5,3 ave - it
	$= 5.3 \text{ size} - \frac{1}{2}$ $= 5.3 \text{ size} - \frac{1}{2}$ $= 7_1 < \frac{6}{2} \text{ : reach length OK}$
	= 5.3 are - 42.50 are $= 5.3 are - 42.50 are$ $= 5.3 are - 42.50 are$ $= 5.3 are - 4.50 are$
	$= 5.3 \text{ are} - 42.30 \text{ and}$ $= 5.3 \text{ are} - 4.4$ $V_1 < \frac{S}{2} \text{ are} - 4.4$ b. Determine $Q_{P+(TRIAL)}$
	= 5.3 are - 42.50 are $= 5.3 are - 42.50 are$ $= 5.3 are - 4.5 are$ $= 7.3 are - 4.5 are$
	= 5.3 size - 42.35 size $= 5.3 size - 42.55 size$ $= 5.3 size - 4.5 size$ $= 7.3 size - 4.5 size$
	$= 5.3 \text{ ave} - 43.530 \text{ min}$ $= 5.3 \text{ ave} - 43.530 \text{ min}$ $V_1 < \frac{S}{2} \text{ i.reach length OK}$ b. Determine $Q_{P+(TRIAL)}$ $Q_{P+(TRIAL)} = Q_{P} = \left(1 - \frac{V_1}{S}\right)$ $Q_{P+(TRIAL)} = \left(2.532 \text{ min}\right)$
	$43330 - 4144$ $= 5.3 \text{ ave. Let}$ $V_{1} < \frac{S}{2} : \text{reach length OK}$ b. Determine $Q_{P+(TRIAL)}$ $Q_{P+(TRIAL)} = Q_{P2} \left(1 - \frac{V_{1}}{S}\right)$ $Q_{P+(TRIAL)} = \left(2 \text{ SP2 } 2 - \frac{1}{S}\right)$
	$= 5.3 \text{ acc} + 43.530 \text{ acc}$ $= 5.3 \text{ acc} + 43.530 \text{ acc}$ $= 5.3 \text{ acc} + 43.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$ $V_1 < \frac{S}{2} \text{ acc} + 4.542 \text{ acc}$

.

SIEIA CONSULTANTS INC. Engineers / planners	BOSTON , MASS. Rochester, N.H	
CLIENT Army Corps PROJECT LACAGOR - Luke Dam #2 DETAIL - Hydrologic Cales	Јов No. <u>274-790</u> Сомрто. Ву <u>ВWP</u> Ск'о. Ву <u>Х</u>	Раде Dате Dате
c. Compute V_2 using	Q _{P4(TRIAL)}	بنه • •
From Figure 3	determine stage for	or Qp4(TRIAL)
Stage = 4	.2 feat	<u>د</u>
X-area = ((4.2 +)(10)	$(c^{2} + 1)$
\sim	210 112	<u>-</u>
$V_2 = \frac{(210 f)}{43}$	+2) (1,050 -2) 560 = 21/acre	
$v_2 = 5.8$	acre-Ceet	
d. Average V_1 and V_2	, and compute Q_{pA}	. •

E

E

- (1) $Vavg = \frac{V_1 + V_2}{2}$ $Vavg = \frac{5.3 \text{ ac} \cdot 12}{2}$
- Vavg = 5.2 acre feet(2) $Q_{P4} = Q_{P3} \left(1 \frac{Vavg}{S}\right)$ $Q_{P4} = \left(2.090 \text{ cfs}\right) \left(1 \frac{5.2}{161}\right)$

BIEIA CONSULTANTS INC. ENGINEERS / PLANNERS CLIENT Apmy Corps		BOSTON , MASS. Rochester, N.H.	
		JOB NO. 2744-7901 PAGE	
ROJECT	1 - Lake Lam = 2	COMPTO. BY BWP	
ETAIL <u>Hydrold</u>	ogic Cales.	Ск'о. Ву	DATE
D. Read	ch 4		
1. <u>STE</u>	<u>P3</u> : Prepare stag	e-discharge curve for	Reach 4
a.	Pertinent Data		
	(1) Reach length	= 1,000 - 1	
	(2) Channel slop	e = 0.06	
	(3) Manning n =	J.05	
	(4) Channel shap	e - trapezodal	
	(5) Base width 🗢	= 10 Seat	
b.	See Figure 3 for	stage-discharge curve	1
2. <u>sti</u>	<u>P 4</u> : Estimate Rea	ch Outflow	
a.	Determine stage f and find volume	or $Q_{P4} = 2,020$ cfs in reach	from Figure 3
	(1) Stage (depth	of flow) = 4.4 Lec	et
	(2) Volume in re	ach = (reach length)	(cross-sectional) - area of channel)
	X-area = =	(0.5) $(4.4 ft)$ (10 150 ft ²	<u> </u>
	Volume = V _l	= (150 111) (1,00 43,560 -+ 2/ane	20 4)
		= 3.4 acre	
		$V_1 < \frac{S}{2}$: reach ler	ngth OK
Þ.	Determine QP5(TRI	(AL)	
	Sactart	$r = 2r_1 \left(1 - \frac{v_1}{v_1} \right)$	
	-POURIAL	······································	_ ·
		· · · · · · · · · · · · · · · · · · ·	· · · · ·
	P5(TRIAL	x = (2020 deg)	
	QP5(TRIAL	.) = (2020 dfs)(. = 1,982 dfs)	

· ^ -

۰.

SIEIA CONSULTANTS INC. ENGINEERS / PLANNERS

BOSTON , MASS. Rochester, N.H.

CLIENT Army Cords	JOB NO. 274-7901	PAGE	
PROJECT LACAMONIA Lake The #2	COMPTO. BYBWP		ي الا المراجع الم
DETAIL <u>Hydrologic Cales</u>	CK'D. BY	DATE	

c. Compute V₂ using Q_P =(TRIAL)

From Figure 3 determine stage for Qp5(TRIAL)

Stage = 4.3 feet X-area = (0.5) (4.3 ft) (10 ft + 5 ft-, = 144 ft² $V_2 = \frac{(144 ft^2)(1,000 ft)}{43,560 ft^2/acre}$ $V_2 = 3.3 acre - feet$

d. Average V_1 and V_2 and compute Q_{P5}

- (1) $Vavg = \frac{V_1 + V_2}{2}$ $Vavg = \frac{3.4 ac-f+}{2}$
 - Vavg = 3.35 acre-feet
- (2) $Q_{P5} = Q_{P4} \left(1 \frac{Vavg}{S} \right)$ $G_{P5} = \left(2.020 \text{ cfs} \right) \left(1 - \frac{3.25}{3.5} \right)$

QP5 = 1,930 cfs



.



D-24

NOT AVAILABLE AT THIS TIME

Ē

•

24

Ľ.

.

•

END

FILMED

8-85

DTIC