



	MERRIMACK RIVER BASIN
34	BRISTOL, NEW HAMPSHIRE
N N	INTERNATIONAL PACKINGS
115	CORPORATION
	LOWER DAM
AI	NH-00480
	PHASE I INSPECTION REPORT
	NATIONAL DAM INSPECTION PROGRAM
ad	
8	
	S. G.
3110	DEPARTMENT OF THE ARMY NEW ENGLAND DIVISION CORPS OF ENGINEERS
-	WALTHAM, MASS. 02154
@	APRIL 1979 DISTRIBUTION STATEMENT A APRIL 1979 Approved for public released Distribution Unlimited
	06 26 050 Distribution duminet

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

REPORT DUCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
I. REPORT NUMBER	NO. J. RECIPIENT'S CATALOG NUMBER
NH 00480 AT - AIS	254
TITLE (and Sublitie)	S. TYPE OF REPORT & PERIOD COVERE
International Packings Corporation Lower Dam	INSPECTION REPORT
NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL	5. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(#)	S. CONTRACT OR GRANT NUMBER(+)
U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION	
PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
1. CONTROLLING OFFICE NAME AND ADDRESS	12. REPORT DATE
DEPT. OF THE ARMY, CORPS OF ENGINEERS	april 1979
NEW ENGLAND DIVISION, NEDED	13. NUMBER OF PAGES
424 TRAPELO ROAD, WALTHAM, MA. 02254	/) 15. SECURITY CLASS. (of this report)
	ISE. DECLASSIFICATION/DOWNGRADING
APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMIT	ED
APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMIT	ED
APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMIT	ED 1 frage Report)
APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMIT 7. DISTRIBUTION STATEMENT (of the obstract entered in Black 20, 11 differen 6. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, Na however, the official title of the program is: Na Non-Federal Dams; use cover date for date of repo	ED (Man Report) ational Dam Inspection Program; tional Program for Inspection c ort.
APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMIT APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMIT 7. DISTRIBUTION STATEMENT (of the observed in Block 20, 11 differen 8. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, Ni however, the official title of the program is: Na Non-Federal Dams; use cover date for date of repo 5. KEY WORDS (Continue on reverse side if necessary and identify by block name DAMS, INSPECTION, DAM SAFETY,	ED • Main Report) ational Dam Inspection Program; tional Program for Inspection c ort.
APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMIT APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMIT 7. DISTRIBUTION STATEMENT (of the observed in Block 20, 11 differen Vorer program reads: Phase I Inspection Report, Na however, the official title of the program is: Na Non-Federal Dams; use cover date for date of repo NAMS, INSPECTION, DAM SAFETY, Merrimack River Basin Bristol, New Hampshire Newfound River	ED (from Report) ational Dam Inspection Program; tional Program for Inspection co ort.
APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMIT APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMIT DISTRIBUTION STATEMENT (of the about on order of in Block 20, 11 differen b. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, Na however, the official title of the program is: Nat Non-Federal Dams; use cover date for date of report NAMS, INSPECTION, DAM SAFETY, Merrimack River Basin Bristol, New Hampshire Newfound River 0. ABSTRACT (Continue on reverse side 11 necessory and Identify by block man	ED A man Accord) ational Dam Inspection Program; tional Program for Inspection c ort. New;

DD + JAN 73 1473 EDITION OF 1 NOV SE IS OBSOLETE

1

.



DEPARTMENT OF THE ARMY NEW ENGLAND DIVISION. CORPS OF ENGINEERS 424 TRAPELO ROAD WALTHAM, MASSACHUSETTS 02154

REPLY TO ATTENTION OF: NEDED-E

JUN 1 5 1979

Mr. Roger L. Young, Plant Engineer International Packings Corporation Pleasant Street Bristol, New Hampshire 03222

Dear Mr. Young:

Forwarded herewith for your information and use is a copy of the Inspection Report on the International Packings Corporation Lower Dam. This inspection was made under the authority of Public Law 92-367 by the firm of E.C. Jordan Co., Inc., Portland, Maine under the direction and supervision of the Corps of Engineers. Copies of the finished report have been forwarded to the Governor and the Water Resources Board, the cooperating agency for the State of New Hampshire.

Section 7 of the report contains an evaluation and recommendations. If you have any questions concerning this report, we suggest that you contact the Water Resources Board first. Then, if there are further questions contact the Project Management Branch, Engineering Division of this office. We thank you for your cooperation and assistance in carrying out this program.

Sincerely yours,

u B. Fujar

Incl As Stated As Stated Accession For NTIS GRA&I DTIC TAB Unannounced Justification By Distribution/ Availability Codes Avail and/or Dist Special Availability Codes



DEPARTMENT OF THE ARMY NEW ENGLAND DIVISION. CORPS OF ENGINEERS 424 TRAPELO ROAD WALTHAM, MASSACHUSETTS 02154

ATTENTION OF:

NEDED-E

JUD 1 9 1979

Mr. George M. McGee, Sr. Chairman, New Hampshire Water Resources Board State of New Hampshire Concord, New Hampshire 03301

Dear Mr. McGee:

Forwarded herewith for your information and use is a copy of the Inspection Report on International Packings Corporation Lower Dam. This inspection was performed in accordance with Public Law 92-367 under the direction of the Corps of Engineers. Copies of the finished report have been forwarded to the Governor and the owner. We thank you for your cooperation and assistance in carrying out this program and hope this report will help you to develop an effective dam safety program.

Sincerely yours,

lyan

Incl As stated

JOE B. FRYAR Chief, Engineering Division



DEPARTMENT OF THE ARMY NEW ENGLAND DIVISION, CORPS OF ENGINEERS 424 TRAPELO ROAD WALTHAM, MASSACHUSETTS 02154

REPLY TO ATTENTION OF: NEDED

JUN 1 8 1979

Honorable Hugh J. Gallen Governor of the State of New Hampshire State House Concord, New Hampshire 03301

Dear Governor Gallen:

I am forwarding to you a copy of the International Packings Corporation Lower Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Water Resources Board, the cooperating agency for the State of New Hampshire. In addition, a copy of the report has also been furnished the owner, International Packings Corporation, Pleasant Street, Bristol, New Hampshire 03222, ATTN: Mr. Roger L. Young, Plant Engineer.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Water Resources Board for your cooperation in carrying out this program.

Sincerely yours,

JDHN P. CHANDLER Colonel, Corps of Engineers Division Engineer

Incl As stated

Ċ

MERRIMACK RIVER BASIN BRISTOL, NEW HAMPSHIRE

Ê

•

r

L

•••

Ē

. .

INTERNATIONAL PACKINGS CORPORATION LOWER DAM

NH-00480

PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM

NATIONAL DAM INSPECTION PROGRAM

F

r

.

Ľ

PHASE I INSPECTION REPORT

NH-00480

INTERNATIONAL PACKINGS CORPORATION LOWER DAM

BRISTOL

GRAFTON COUNTY, NEW HAMPSHIRE

NEWFOUND RIVER

November 21, 1978

BRIEF ASSESSMENT

The International Packings Corporation Lower Dam is a timber crib gravity dam with concrete abutment wing walls. The dam is about 14 feet in height and about 87 feet in length between abutments.

Based on the visual inspection and reports of past operational performance, the International Packings Corporation Lower Dam is considered to be in poor condition. Major concerns regarding the safety of the dam include underseepage, downstream scour, deterioration of timbers, serface deterioration and lack of freeboard both at the reservoir banks and between spillway and service bridge.

The International Packings Corporation Lower Dam is a small size dam classified as having a significant hazard potential. In accordance with Corps of Engineers' guidelines for the determination of spillway adequacy, the test flood is cne-half the Probable Maximum Flood (PMF). The test flood is estimated to be 12,760 cfs. The spillway could pass 44 percent of the one-half PMF with all stop logs removed. However, the dam is not a hydraulic control once flooding benins to occur, because the upstream valley section allows a routing of flow upstream of the dam around the north end of the dam. Therefore, during the PMF or one-half PMF occurrence, considerable flooding would be occurring downstream. Thus the spillway is not considered seriously inadequate under Corps of Engineers' Guidelines because a failure caused by over-

i

topping would not significantly increase the downstream hazard potential above that which existed just before failure occurred. Since the dam is a timber crib gravity structure, it can be considered generally stable during overtopping, with the assumption that underseepage and downstream scour conditions are corrected and deteriorated timber crib members are replaced.

As outlined in Section 7 of this report, the downstream scour and underseepage should be evaluated further by a qualified engineer, and recommendations for curtailment of these conditions be prepared and implemented. The following items of remedial maintenance should also be performed; 1) replacement of missing stoplog lift hooks; 2) repair of spalled concrete; 3) repair of deteriorated wood members of the structure; 4) provision of 24 hour surveillance during flood events; 5) development of a warning system; and 6) and institute a program of annual periodic technical inspections. These actions should be implemented within 12 months of receipt of this report by the owner. The annual shutdown and major maintenance should be continued with records to be kept of such work.



F

Ċ

EDWARD C. JORDAN CO., INC.

StanVey E. Walker, P.E. Project Officer

This Phase I Inspection Report on International Packings Corporation Lower Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the <u>Recommended Guidelines for Safety Inspection of</u> <u>Dams</u>, and with good engineering judgment and practice, and is hereby submitted for approval.

hW.F FINEGAN, JR., MEMBER OSEPH W.

Wayer Control Branch Engineering Division

È

-

r

ż

Ċ

CARNEY M. TERZIAN, MEMBER Design Branch Engineering Division

sigh q. Mr Elroy

JOSEPH A. MCELROY, CHAIRMAN Chief, NED Materials Testing Lab. Foundations & Materials Branch Engineering Division

APPROVAL RECOMMENDED:

Mar OE B. FRYAR

Chief, Engineering Division

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its' general condition and the downstream damage potential.

PREFACE

Ê

.

Ċ

.....

Ê

<u>.</u>

TABLE OF CONTENTS

r

Ũ

•

r.

L...

r

PAGE	
------	--

LETTER OF TRANSMITTAL	
BRIEF ASSESSMENT	i
REVIEW BOARD SIGNATURE SHEET	iii
PREFACE	v
TABLE OF CONTENTS	v
OVERVIEW PHOTOGRAPH	vii
LOCATION MAP	viii

SECTION 1 - PROJECT INFORMATION

1.1	GENERAL	1-1
1.2	DESCRIPTION OF PROJECT	1-1
1.3	PERTINENT DATA	1-4

SECTION 2 - ENGINEERING DATA

2.1	DESIGN	2-1
2.2	CONSTRUCTION.	2-1
2.3	OPERATION	2-1
2.4	EVALUATION	2-1

SECTION 3 - VISUAL INSPECTION

3.1	FINDINGS	3-1
3.2	EVALUATION	3-3

SECTION 4 - OPERATING PROCEDURES

4.1	PROCEDURES	4-1
4.2	MAINTENANCE OF DAM	4-1
4.3	MAINTENANCE OF OPERATING FACILITIES	4-1
4.4	DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT	4-2
4.5	EVALUATION	4-2

SECTION 5 - HYDRAULIC/HYDROLOGIC

V

TABLE OF CONTENTS (Continued)

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY	. (6-	Ì
--	-----	----	---

SECTION 7 - ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1	DAM ASSESSMENT	7-1
7.2	RECOMMENDATIONS	7-2
7.3	REMEDIAL MEASURES	7-2
7.4	ALTERNATIVES	7-3

APPENDICES

È

Ŋ

.

63

-

.

Ľ

- A FIELD INSPECTION NOTES
- **B** ENGINEERING DATA
- C PHOTOGRAPHS
- D HYDROLOGIC AND HYDRAULIC COMPUTATIONS
- E INVENTORY FORMS

IPC Lower Dam

vi





PHASE I INSPECTION REPORT

INTERNATIONAL PACKINGS CORPORATION

LOWER DAM

SECTION 1

PROJECT INFORMATION

1.1 GENERAL

Ê

È

/

Ċ

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Edward C. Jordan Co., Inc. has been retained by the New England Division to inspect and report on selected dams in the States of Maine and New Hampshire. Authorization and notice to proceed were issued to Edward C. Jordan Co., Inc. under a letter of December 1, 1978 from Max B. Scheider, Colonel, Corps of Engineers. Contract No. DACW33-79-C-0017 has been assigned by the Corps of Engineers for this work.

b. Purpose

- To perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.
- (2) To encourage and prepare the states to initiate effective dam safety programs for non-Federal dams.
- (3) To update, verify and complete the National Inventory of Dams.

1.2 DESCRIPTION OF PROJECT

<u>a.</u> Location. The International Packings Corporation Lower Dam is located on the Newfound River in the town of Bristol, New Hampshire. N 43° 36.0', W 71°-44.9'.

b. Description of Dam and Appurtenances. The International Packings Corporation Lower Dam is a timber crib dam with concrete abutment-wing walls. The dam is a "run-of-theriver" dam situated in a broad and relatively flat section of the valley of the Newfound River. The river makes a sharp bend both above and below the dam site.

Ċ

Ņ

Ċ

.

Г

The dam is approximately 14 feet in height, with a spillway structure length of about 87 feet. It appears to be founded on soil.

Appurtenant to the dam is a gated canal with concrete sidewalls which diverts water to a power house. After passing through the generator, the water exits through an underground tail race to a channel which rejoins the Newfound River several hundred feet below the dam.

Plan and profile sketches of the dam and appurtenant features are presented in Appendix B.

- <u>c. Size Classification</u>. The IPC Lower Dam is classified as a small size dam, based on its height (14 feet) and storage capacity (31 acre-feet).
- Hazard Classification. In the event of failure of the d. dam, approximately ten commercial and residential buildings located within a distance of 1,500 feet below the dam would be damaged. Flood depths vary with the distance downstream of the dam. Because of the small volume of the reservoir storage and the flatness of the overbank areas, the flood peak would be rapidly attenuated. The commercial/ industrial buildings located directly downstream of the dam on the north bank would suffer the greatest damage. Also of some concern is a propane storage tank located about 100 feet below the dam; if the tank were dislodged from its concrete cradle during a flood event, the tank could pose a serious hazard to downstream residents. Flood depths just below the dam would be two to three feet.

General flooding in the reach downstream of the dam begins at a discharge of 2,000 to 2,500 cfs. The flood peak from failure was estimated to be 3,491 cfs which corresponds to a stage of 7.2 feet at a distance of 100 feet below the dam. Flood stage is at 4.5 to 5 feet in this area. Flood peak from failure would diminish to about 1,700 cfs within 1,500 feet of the dam. This is considered to be below the general flood level. However, some minor localized high water may still occur.

1-2

The duration of the flow from dam failure would be very short. It would take approximately 13 minutes for the reservoir to empty. It is estimated that in no reach of the stream would water be above general flood level for more than 10 minutes.

All of the above discharges do not consider the flow already occurring. With stop logs in place as at the time of inspection, the discharge at the dam with water surface at top of dam would be about 570 cfs. Given this as a base flow at time of failure, downstream water levels would be raised about 0.5 feet above the level resulting from failure alone.

If the spillway were discharging at maximum capacity, a significant flood event would already be occurring downstream and there would not be a significant increase in downstream hazard due to failure of the dam by over-topping.

Based on the above discussion, the International Packings Corporation Lower Dam is given a "significant" hazard potential classification.

e. Ownership.

Current Owner:

International Packings Corporation Pleasant Street Bristol, New Hampshire 03222

Previous Owner and dates:

Dodge-Davis Manufacturing Co. 1934-1949

<u>f.</u> Operator. International Packings Corp. Tel: 1-603-744-2281

- <u>g.</u> Purpose of Dam. This dam is used for hydroelectric power generation to supplement the power requirements of the International Packings Corporation manufacturing facility in Bristol.
- h. Design and Construction History. There is very little design data pertinent to this dam, and that available is limited to information relating to the generating equip-

1-3

ment. The designer of the structure is not known. According to the current owner, the Dodge-Davis Manufacturing Co. constructed the dam about 1934. The International Packings Corporation overhauled the structure in 1973, at which time a concrete apron was added to the upstream face, new timber uprights were installed on the stop log sections, a steel I-beam was installed at the top of the dam, and the low-level outlet was furnished with a steel gate. No plans for this remodeling are available.

Normal Operating Procedure. The International Packings Corporation Lower Dam is used to supply water to a 100foot long power canal located on the south bank just upstream of the dam. A gate house is located at the upstream end of the canal. The stop log spillway is maintained at a level sufficient to provide water for power generation. The invert of the canal is 6.9 feet below the top of dam. During low and normal flows, stop logs are maintained at maximum height. In anticipation of high flows, stop logs are manually removed. If maintenance is required to the spillway section, the water level is lowered and the low level outlet is opened. The low level outlet can only be opened from the upstream apron. Stop logs are not removed during periods of turbine shutdown. When power is being generated, periodic daily checks are reportedly made of the generating equipment and trash screens. The stop logs are not designed to automatically fail during overtopping conditions. Once overtopping of the dam occurred, it would be very difficult to remove the stop logs.

1.3 PERTINENT DATA

Ċ

r

<u>a.</u> Drainage Areas. The drainage area above the International Packings Corporation Lower Dam is 96.1 square miles. The basin is primarily forested with slopes varying from moderate to steep. Elevation in the basin ranges from 3,121 feet (MSL) at Mount Cardigan to about 480 feet at the dam. About 7% of the entire drainage area consists of surface water at Newfound Lake which is located about 1.2 miles upstream of the International Packings Corporation Lower Dam. A dam on Newfound Lake regulates the discharge to the Newfound River. The drainage area above the Newfound Lake Dam is 95.0 square miles. Newfound Lake has a capacity of 38,800 acre-feet.

1-4

Dis the Wat fol ass	<u>charge at Damsite</u> . Based on data visual inspection and discussion er Resources Board personnel and lowing discharges were estimated. ume a water level at top of dam.	collected during with New Hampshire the owner, the All discharges
(1)	Maximum flood at damsite is unk July 1973 was estimated to be 3	nown. The flood of 500 cfs.
(2)	Stop log spillway capacity at t 570 cfs (one port full open, to logs l foot below top of dam).	ime of inspection - op of remaining stop
(3)	Stop log spillway capacity (all place) - 130 cfs.	stop logs in-
(4)	Spillway capacity (all stop log cfs.	s removed) is 5,600
(5)	Total spillway flow at PMF is l elevation of 493.6 feet.	1,635 cfs at flood
(6)	Total spillway flow at 1/2 PMF flood elevation of 490.0 feet.	is 6,592 cfs at
(7)	Total project discharge at PMF feet is 30,000 cfs.	elevation of 493.6
(8)	Total project discharge at 1/2 490.0 feet is 12,780 cfs.	PMF elevation of
Ele ref rea rec of as nat fol	<u>vation</u> . During the field inspect erence of the dam elevation to me dily available. New Hampshire Wa ords dating to 1939 indicate an e the south abutment of about 489.2 an assumed datum, pertinent eleva ional Packings Corporation Lower lows:	tion, no physical can sea level was ter Resources Board elevation at the top feet. Using this tions at the Inter- Dam site are as
	Item	Approximate Elevation Above MSL
(1) (2) (3)	Streambed at centerline of dam Maximum tailwater Invert at entrance to power	474.8 Unknown

È

,

•

C

822

Ē

1-5

	Item	Approximate Elevation Above MSL
(4)	Normal pool	487.9
(5)	Full flood control pool	489.2
(6)	Spillway crest (at lowest point)	481.8
(7)	Design surcharge	Unknown
(8)	Top of dam (at abutment)	489.2
(9)	Test flood elevation (PMF)	493.6
(10)	1/2 PMF elevation	490.0

<u>d.</u> <u>Reservoir</u>. The lengths of the reservoir at normal pool (top of stop log spillway) and maximum pool were estimated using average streambed slopes.

Item	Length (ft.)
Normal Pool	600
Top of Dam	700

e. Storage

Ē

.

_

Ê

Item	Storage
Top of Dam	31
Normal Pool	20

f. Reservoir Surface

Item	Surface Area(ac)
Top of Dam	2.8
Normal Pool	2.1

1-6

g. Dam.

Ē

5

Ċ

•

-

- Type The dam is a timber crib gravity dam with concrete abutment-wing walls.
- (2) Length The length between abutments is approximately 87 feet. The northerly wing-wall extends from the abutment at an angle upstream of about 45° for a distance of about 35 feet; the southerly wing-wall extends upstream about 30 feet where it meets the gate to the power house canal.
- (3) Height The top height of the dam from top of abutment to level of streambed downstream is about 14 feet.
- (4) Top Width See Plan and Cross-sections in Appendix B.
- (5) Side Slopes See Plan and Cross-sections in Appendix B.
- (6) Zoning None.
- (7) Impervious Core None.
- (8) Cutoff Cutoff is formed by sloped plank apron covered with concrete on upstream side of dam, with a mud seal.
- (9) Grout Curtain None.
- h. Diversion and Regulating Tunnel. Not applicable.
- i. Spillway.
 - Type The spillway of the dam consists of timber cribwork supporting timber columns which contain slots for stop logs. The stop log spillway runs the entire length of the timber crib structure.
 - (2) Length The spillway is approximately 87 feet long. There are 18 stop log bays at 4.5 feet wide by 5 to 6 feet high.
 - (3) Crest Elevation Approximately 481.8 feet (MSL) at the low point, based on assumed datum as discussed above.

1-7

- (4) Gates Control gates for the spillway are stop logs across its entire length. Stop logs must be manually removed, as there is no hoisting equipment. A low level outlet gate is provided in the concrete apron on the upstream side of the dam; this gate is a manually operated bulk-head type door which can be operated only during low-water conditions.
- (5) Upstream Channel The upstream approach to the spillway has an apparent slope of 16 feet per 1000 feet and is clear of debris and sediment. No loose rock or trees overhanging the channel. The stream makes a sharp bend as it approaches the dam, and passes beneath a highway bridge as it nears the dam site (see photograph 8, Appendix C); this bridge causes a restriction in the approach channel. Some minor sedimentation is evident in the reservoir.
- (6) Downstream Channel The channel of the Newfound River below the spillway is steep and rocky, with relatively flat overbanks containing some small trees and brush. The overbank is generally low in relation to the stream channel.

A significant amount of scour has occurred at the toe of the dam. The scouring ranges from 1 to 4 feet deep and extends 20 to 30 feet downstream.

j. Regulating Outlets

ř

7

٠.•

٠...

È

- Inverts: Spillway stop log gates elevation varies from 481.8 to 482.8 (MSL). Power house canal gates - elevation 482.3 (MSL).
- (2) 18 stop log gates at 5 to 6 feet high by 4.5 feet wide. 3 canal gates at 6.5 feet high. The width varies from 4 ft., 3 in. to 5 ft., 5 in. Low level outlet - 3 ft. square.

(See Plan and Cross-section sketches in Appendix B)

(3) Description - Spillway stop log gates consist of individual wood plank stop logs which are manually removed or inserted. These stop logs are supported in slots in timber uprights; there are 18 of these stop log sections across the length of the spillway.

The power house canal gates consist of three timber vertical lift gates operated by hoisting equipment housed at the inlet to the canal.

The low level outlet gate is located in the concrete apron which has been installed over the cribwork on the upstream side of the dam. This gate is a three-panel metal bulkhead-type door and can only be operated when the pond has been drained to a low-water condition.

(4) Control mechanisms -

D

r

-

. .

Ē

1,4 4,4 1,4 4,4 1,4 4,4 4,4 4,4

Spillway stop logs - None. Canal gates - Manually operated hoisting equipment. Low level outlet - none.

SECTION 2

ENGINEERING DATA

2.1 DESIGN

e

.

-

.

Ċ

5

Essentially no design data were available for the International Packings Corporation Lower Dam. Drawings of proposed generating equipment for use at the site are on file in the company's plant in Bristol, together with miscellaneous data pertaining to that equipment (See Appendix B).

2.2 CONSTRUCTION

No engineering data were available regarding construction of the dam.

2.3 Operation

No engineering operational data were disclosed.

2.4 EVALUATION

- <u>a. Availability</u>. There are essentially no engineering data or plans available that would be useful in evaluating the integrity of the International Packings Corporation Lower Dam.
- b. Adequacy. The lack of in-depth engineering data did not allow for a definitive review. Therefore, the adequacy of this dam could not be assessed from the standpoint of reviewing design and construction data, but is based primarily on visual inspection, performance history and engineering judgment.

c. Validity. Not applicable.

2-1

SECTION 3

VISUAL INSPECTION

3.1 FINDINGS

- a. <u>General</u>. The International Packings Corporation Lower Dam is a timber crib dam with concrete abutment-wing walls. The dam appears to be founded on soil and is located in a broad, relatively flat section of the valley. The Newfound River makes a sharp bend both above and below the dam site. The dam is a run of the river dam with very little impoundment area or storage capacity.
- b. Dam.

 Structural - The visual inspection of the dam structure revealed that the various elements of the dam are in generally poor condition. See Appendix A for detailed inspection findings. The structure consists of concrete abutments and wing walls with a timber cribwork supporting timber columns and stop logs which form the spillway. See Appendix B for plan, profile and cross-section sketches, and Appendix C for photographs.

The visual inspection of the dam resulted in the following major findings:

- (a) The spillway section and downstream apron of the dam show evidence of settlement and deflection downstream. Settlement of the apron of at least 4 inches has occurred (see overview photograph). Downstream deflection of the stop log section of the spillway of 5 to 7 inches at its' center is evident. (see Appendix C, photograph 2)
- (b) Significant scour has occurred downstream of the apron below the spillway. (see photograph 9) Some undermining of the timber cribs is evident.
- (c) Direct leakage from the upstream face of the dam to the downstream toe is occurring. This was evidenced by eroded depressions and flow

into the depressions along the upstream face of the dam (see photograph 4) and flow from the toe. Past attempts to prevent this seepage are evident; these attempted repairs have not been successful.

(d) Many of the timber members in the cribwork and some of the planking show signs of deterioration. Some timber has rotted seriously, other pieces are cracked or split and some planks are broken.

ŕ

- (e) The concrete abutments and wing walls are badly spalled in many areas. (see photograph 3)
- (f) Stop logs and stop log supports are in generally good condition. The lifting hooks on some of the stop logs are broken, inhibiting easy removal of these stop logs.
- (2) Hydraulics At the time of visual inspection the flow of the river was estimated to be 2 to 5 cfs, all of which was flowing beneath or through the dam structure. It was noted that only about one foot of freeboard exists between the top of the stop logs and the bottom of the service bridge beams. It was also noted that very little freeboard exists between the top of the stop logs and the top of retaining walls upstream of the abutments on both the north and south sides of the impoundment; in fact, the elevation of the top of the concrete abutments is greater than the low points along the reservoir storage area.

Evidence at the dam suggests that the stop logs (which must be removed manually) are not always removed to add capacity to the spillway. Overtopping of stop logs in the spillway apparently occurs frequently.

c. Appurtenant Structures. South of the spillway section of the dam is the gate works and canal to the power house. Below the power house is a covered tailrace to the downstream channel. The gate works and gates were found to be in fair condition and apparently operable, however the gate house is being used for storage and access to the gate hoists is impeded. The canal is in

3-2

generally fair condition; however, considerable spalling of concrete side walls was noted. The bridge over the canal appears to be in good condition. At the inlet to the canal is a log boom which is attached to the shore at its' upstream end by a rope. This log could become loose and swing into the spillway causing obstruction or damage. The trash rack above the power house was observed to be heavily laden with debris. The tailrace is in very poor condition. Erosion has occurred in the floor and beneath support piers and the timber roof has collapsed in one area. See Appendix A for detailed findings.

d. Reservoir Area. At the time of inspection, on 11/21/78, the reservoir was nearly empty. Only a very small flow was being released from the Newfound Lake Dam located upstream. The International Packings Corporation reservoir had been drained by leakage through eroded depressions located upstream of the concrete apron. Three active leaks were discovered. There is evidence of previous attempts to repair the leaks; these have not succeeded. (See photograph 4.)

Some sediment has accumulated in the reservoir area; however, the accumulated sediment is not sufficient to impede flow to the spillway or cause blockage of the approach channel.

The Route 3A highway bridge located approximately 150 feet above the dam causes a restriction in the approach channel to the dam.

e. Downstream Channel. The channel of the Newfound River below the dam is steep and rocky with relatively flat overbanks containing some small tree and brush growth. The overbank is generally low in relation to the stream channel.

A significant amount of scour has occurred at the toe of the dam. The depth of scour ranges from 1 to 4 feet. The scour has occurred for a distance of 20 to 30 feet downstream.

3.2 EVALUATION

D

Based on the visual inspection, the dam appears to be in poor condition. The timber spillway section of the dam shows

3-3

D . . r , -È

evidence of deterioration, settlement, and lateral displacement. Leakage is occurring through and beneath the spillway section of the dam. A very small amount of freeboard exists between the top of the stop logs and service bridge and at the wing walls compared to the top of the stop logs. As outlined in Section 7, rehabilitative construction and maintenance are necessary to assure the long-term safety of the structure.

IPC Lower Dam

3-4

SECTION 4

OPERATING PROCEDURES

4.1 PROCEDURES

È

F

Ė

The International Packings Corporation Lower Dam is used to supply water to the canal located on the south bank just upstream of the dam. A gated power house sits at the end of the 100-foot long canal. The stop log spillway is maintained at a level sufficient to provide water for power generation. The inlet to the canal is 6.9 feet below the top of dam. During low and normal flows, stop logs are maintained at maximum height. In preparation for high flows, stop logs are reportedly manually removed. If maintenance of the spillway section is required, water level is lowered and the low level outlet is opened. The low level outlet can only be opened from the upstream apron. There are no other controlled outlets for this dam. There is evidence of frequent overflow of the stop log spillway. Stop logs are not always removed during periods of turbine shutdown. When power is being generated, periodic daily checks are made of the generating equipment and trash screens. There is an operation log for the generating equipment, located at the power house; otherwise, there are no records of operation and maintenance of the dam.

4.2 MAINTENANCE OF DAM

Maintenance of the dam is on an as needed basis. According to the plant engineer at International Packings Corporation, the dam is shut down once a year for checking and maintenance. There are no maintenance records available.

4.3 MAINTENANCE OF OPERATING FACILITIES

While the spillway stop logs and stop log supports are generally in good condition, some stop log hooks are missing. The inlet gates to the power house canal appear to be operable, but the gate house is used for storing material which presently impedes use of the hoisting equipment. Aside from the once-a-year maintenance effort and attention to immediate conditions needing repair, it appears that there is no scheduled maintenance program for the dam.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

There is no automatic warning system or remote monitoring system in effect. In cases of impending high runoff, the New Hampshire Water Resources Board (which operates a dam upstream at Newfound Lake) contacts the International Packings Corporation.

4.5 EVALUATION

F

Aside from an annual maintenance program for the International Packings Corporation Lower Dam, there is an apparent lack of attention to the upkeep of the dam. Spalling of concrete in many parts of the structure and appurtenances, deteriorated timber work, and broken stop log hooks are in need of repair. A more thorough ongoing maintenance program appears warranted.

Attempted repairs of leaks located just upstream of the concrete apron of the dam were noted during the visual inspection. These repairs have not been successful.

The lack of a warning system or some form of remote monitoring of the dam is of concern, in that the dam has very little freeboard and is not subject to continued surveilance. Personnel who monitor the dam are located several miles from the structure at the International Packings Corporation Plant.

IPC Lower Dam

SECTION 5

HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

F

r:

i i

C

- a. General. The International Packings Corporation Lower Dam is a run of the river dam constructed for low head hydroelectric power production. The structure consists of a stop log spillway above a timber crib dam, concrete wingwalls, and an inlet to a penstock canal with three individual gates. The gates were at various stages of closure, none being fully closed, at the time of inspection. The power production features of the dam are operable. Flow at the dam is highly regulated by Newfound Lake Dam which is located about 1.2 miles upstream of the International Packings Corporation Lower Dam.
- b. Design Data. There are no design data available.
- c. Experience Data. There are no published hydrologic data for the Newfound River Basin. However, for the last three years the New Hampshire Water Resources Board has maintained a flow record of the discharges from Newfound Lake. The maximum flow in these records is 1,280 cfs. According to personnel of the New Hampshire Water Resources Board, no damage occurred downstream of Newfound Lake during this release.
- d. Visual Observations. Water level at the International Packings Corporation Lower Dam is controlled by the stop log spillway at high and normal flows. At very low flows, leakage through the dam may equal or exceed inflow. Gates to the power canal are reportedly left open with inflow to the power house being controlled by the gate at the power house. The tailrace of the power house, although not affecting dam stability, is considered to be unsafe and is not protected from trespass. There is a low level service gate located in the concrete apron of the spillway structure which passes low flows during maintenance of the spillway.
- e. Test Flood Analysis. The International Packings Corporation Lower Dam is classified as having a significant hazard potential. To determine the adequacy of the spillway, the "Probable Maximum Flood" (PMF) was developed and applied to the dam. Discharges at the International

5-1

Packings Corporation Lower Dam are controlled by Newfound Lake. The drainage area above the International Packings Corporation Lower Dam was planimetered from U.S.G.S. quad sheets (1" = 1 mile) and determined to be 96.1 square miles. The drainage area was classified as mountainous. The slope of the longest channel above Newfound Lake averages about 140 feet/mile. Elevations range from 3,121 feet at Mount Cardigan to about 580 feet at the Newfound Lake Dam. The PMF flow into the Newfound Lake was estimated to be 114,000 cfs, using the Corps of Engineers "Preliminary Guidance for Estimating Probable Maximum Discharges." The flood flow was routed through Newfound Lake using HEC-1. (see Appendix D) The peak outflow from the dam was determined to be 28,700 cfs. The one-half PMF was also routed through Newfound Lake. Peak outflow of the one-half PMF was determined to 12,100 cfs.

The intervening drainage area between Newfound Lake Dam and International Packings Corporation Lower Dam is 1.1 square miles. The PMF inflow from this part of the total drainage area would be 1,320 cfs. The one-half PMF contribution from the intervening drainage is 660 cfs. The International Packings Corporation Upper Dam, located upstream from the dam under current study, does not diminish the peak due to surcharge storage. Therefore, the PMF at the International Packings Corporation Lower Dam is 30,000 cfs. The one-half PMF inflow is 12,760 cfs.

The spillway of the International Packings Corporation Lower Dam has a capacity of about 5,600 cfs with all stop logs removed and water surface elevation at top of dam. The spillway could pass 19 percent of the PMF and 44 percent of the one-half PMF. However, the dam is not a hydraulic control once overbank flow occurs upstream of the dam and reservoir. Flooding just upstream of the reservoir occurs at a discharge of about 2,000 to 2,500 cfs. At flows greater than this, water would begin to flow around the dam to the north, completely bypassing the dam. (see Appendix D)

A PMF of 30,000 cfs would overtop the dam by about 4.4 feet. The one-half PMF would overtop the dam by about 0.8 feet.

During the PMF or one-half PMF occurrence, considerable flooding would already be occurring downstream of the

dam. The spillway is not considered seriously inadequate according to the guidelines of ETL 1100-2-234 because failure caused by overtopping would not significantly increase the downstream hazard potential above that which existed just before failure occurred. Since the dam is a timber crib structure, it can be considered as being generally stable during overtopping conditions provided the current downstream scour and underseepage conditions are remedied.

Dam Failure Analysis. The dam failure analysis relied f. upon the "rule of thumb" guidance outlined in an attachment to ETL 1100-2-234. The storage barns and business office of the lumber company located on the north bank just below the dam (see Photograph #9) would incur significant damage. The areas surrounding a large propane tank bolted to a concrete platform about 100 feet below the dam on the south bank could be flooded. If the bolts or concrete supporting structure were to fail during a flood event, the propane tank could pose a serious hazard. The flood peak from failure at the dam was computed to be 3,491 cfs which corresponds to a stage of 7.2 feet at a distance of 100 feet below the dam. Because of the small volume of storage in the reservoir, the dam failure peak is rapidly attenuated. At a distance of 1,000 feet below the dam, peak flow is reduced to 2,200 cfs with a stage of 6 to 6.5 feet. Flood stage in this reach is estimated to be about 5 feet. At a distance of 1,500 feet below the dam, peak flow would be 1,700 cfs corresponding to a stage of about 4 feet. General flooding in the reach concerned begins at a discharge of 2,000 to 2,500 cfs. Within 1,500 feet downstream of the dam, the peak flow from failure would drop below flood level and no significant damage would occur downstream of this area.

Based on the rule of thumb guidelines provided by the Corps of Engineers, it was estimated that it would take 13 minutes to empty the reservoir. Just below the dam, discharge would be above flood level for about 6 to 8 minutes. At a distance of 1,000 feet below the dam, general flood level would be exceeded for less than 4 minutes.

None of the above discharges consider the flow already occurring. Given the condition of the dam at the time of inspection, the discharge at the dam with water surface at top of dam was computed to be about 570 cfs.
Ø ŕ

Given this as a base flow at time of failure, downstream water levels would be raised about 0.5 feet above the level resulting from failure alone. If the dam were to fail while the spillway was discharging at maximum capacity (5,600), the increase in downstream flood stages would be insignificant. During large flood flows, a high tailwater condition exists at the dam.

The dam should remain stable during overtopping conditions if the underseepage from the upstream apron is properly repaired and the downstream scour is remedied. It is important that any further scour be prevented and the current effects of scour be repaired.

SECTION 6

STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

Ċ

-

a. Visual Observations. Based on the visual observations, the International Packings Corporation Lower Dam appears to be in poor structural condition. The timber cribwork section of the dam has settled and deflected downstream at the center. Substantial underseepage and leakage is occurring and apparently erosion of some of the foundation soils has occurred. Undermining of the downstream toe of the cribwork has also occurred. Some of the timber members and planking show evidence of rot and many are cracked, split or broken.

The concrete abutments and wing walls are badly spalled. These sections of the dam show no signs of movement, however.

- b. Design and Construction Data. No data concerning original design or construction of this dam were disclosed in this investigation.
- c. Operating Records. None available.
- d. Post-Construction Changes. In 1973, the spillway structure was overhauled. A concrete apron was installed over the existing crib work on the upstream side of the dam and furnished with a steel door low level outlet gate. New timber uprights were provided for the stop log sections. A steel I-beam and cable were added at the top of the stop log uprights. At the time of inspection, November 21st, the pond level was below the bottom of the stop log section and the cable was slack, thus providing little support for these uprights. However, at the time of the November 30th followup inspection, the pond was full and the cable was taut.

The new timber uprights remain in generally good condition. The older timber crib work shows deterioration, with some members showing signs of rot or cracking. The surfaces of the older concrete portions of the dam have deteriorated over time, as evidenced by considerable spalling in some areas; these concrete sections have apparently received little maintenance in recent years.

6-1

e. Seismic Stability. The dam is located in Seismic Zone No. 2 and in accordance with recommended Phase I guidelines, does not warrant seismic analysis.

C

1

Г

•



SECTION 7

ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES

7.1 DAM ASSESSMENT

F

1

Ċ

- a. Condition. The visual inspection indicates that the International Packings Corporation Lower Dam is in poor condition. Major concerns relative to the dam's physical condition are identified as follows:
 - Seepage under the structure is taking place as evidenced by eroded depressions and inflow along the upstream face and by flow from beneath the toe.
 - (2) There has been considerable scour of the streambed just below the toe of the dam to a depth of one to four feet. Some resultant undermining of the timber crib structure underlying the spillway apron is evident.
 - (3) The older timber structure of the dam and some of the planking show signs of deterioration. Some timber has rotted seriously, while other pieces are cracked or split and some planks are broken.
 - (4) A pronounced settlement and downstream deflection of the spillway structure have occurred.
 - (5) Deterioration of some of the concrete is evident, particularly at the north abutment of the spillway which is pitted in places to a depth of 12 inches and at the east wingwall of the canal entrance which is very seriously eroded.
 - (6) There is a lack of freeboard between the top of the spillway stop logs and the service bridge. Also, there is a lack of freeboard on the reservoir banks relative to the top of the dam.
- <u>b.</u> Adequacy of Information. The information available relative to this dam is very limited. Consequently, assessment of the condition of the dam must be based primarily on the visual inspection, the past operational performance of the dam, and engineering judgment.

7-1

- c. Urgency. Based on the poor condition of the dam, recommendations and remedial measures outlined below should be implemented within 12 months of receipt of this report by the owner.
- d. Need for Additional Investigation. Additional investigation is not considered necessary for the current (Phase I) assessment.

7.2 RECOMMENDATIONS

D

r

2

C

The existing seepage under the dam and the scour of the channel downstream of the spillway apron are considered potentially serious conditions. The settlement and deflection of the structure is also serious. It is therefore recommended that further evaluation of these conditions be made by qualified engineers, and that recommendations be formulated and implemented to curtail both underseepage and downstream scour. It is also recommended that a qualified engineer evaluate the possibility of modifying the existing spillway to allow automatic release of stop logs during overtopping conditions.

7.3 REMEDIAL MEASURES

- a. Operating and Maintenance Procedures. The routine annual inspection and maintenance program by International Packings Corporation personnel should be continued. This annual inspection should be supplemented by a more frequent program of maintenance of the operational features of the dam (gates, stop logs, lifting mechanisms). Records should be kept of all maintenance work performed. The following specific maintenance and operating procedures should also be implemented:
 - (1) Replace missing or broken stop log lift hooks.
 - (2) Repair spalled concrete throughout the structure.
 - (3) Repair rotted or broken timber members and planking.
 - (4) Provide the log boom located at the penstock canal entrance with a more secure anchorage than the rope tie-line now used.
 - (5) Provide for 24 hour surveillance of the structure during flood conditions.

7-2

- (6) Develop a plan for a formal warning system which could be used in the event of an emergency.
- (7) Provide for annual inspection of the facility by qualified engineers.

7.4 ALTERNATIVES

Ť

D

۲

Ē

-

ŕ

An alternative to implementing the recommendations and remedial measures outlined above would be the removal of the dam. Such removal should be under the supervision of a qualified engineer, with consideration given to the potential release of accumulated sediments and other potential environmental impacts which could result from removing the structure.

Another alternative would be the permanent removal of stop logs to reduce the dam's potential hazard under low-flow conditions. Removal of the stop logs as an interim measure until the above outlined recommendations and remedial measures can be implemented may also be considered.

APPENDIX A.

Ē

É.

VISUAL INSPECTION CHECKLIST AND SUPPLEMENTARY INSPECTION NOTES

VISUAL INSPECTION CHECKLIST PARTY ORGANIZATION

Ċ

È

•

.

r

.

Ê

.

Ċ

PROJEC	T <u>International Packings</u> Corporation Lower Dam		DATE 11-21-78	
			WEATHER Snow-Cold	
			W.S. CLEV. <u>480+</u> U.S. <u>4</u>	<u>/)</u> UN.S.
PARTY:				
1	Stephen Cole	6		
2	John Devine	7		
3	David Nyman .	8		
4	Timothy Noonan	9		
51	Daniel Lane	10		
	PROJECT FEATURE		INSPECTED BY	REMARKS
1	Geotechnical		Cole	
21	Hydraulics/Hydrology		Devine	
3	Structural	<u> </u>	Cole, Devine, Nyman	
4	Civil		Nyman	
5	Survey	<u> </u>	Noonan, Lane	·····
6	Photography		Devine, Noonan	
7				
81	Review Inspection			
91	November 30, 1978		Walker, Horstmann	
	Water level in reservoir was w	<u>vithin s</u>	everal inches of top of	stop logs
	in timber spillway. The cable	extend	ing from north to south	at the
	the rever of the 1-beam and wa	iikway W	as taut at full pond.	

<u>NOTE</u>: See Supplementary Inspection Notes Following Checklist

A-1

INSPECTION CHECKLIST

PROJECT	International Packings		
-	Corpor	ation Lower Dam	
PROJECT	FEATURE	Embankment	

DATE	11-21-78	

NAME Cole

NAME

DISCIPLINE Geotechnical

È

۵

t

CONDITIONS

AREA EVALUATED

DAM EMBANKMENT 488.6+ Crest Elevation 480 + Current Pool Elevation Overtopped? Maximum Impoundment to Date None observed Surface Cracks Turf - okay Pavement Condition Movement or Settlement of Crest None Lateral Movement None Okay but very little freeboard Vertical Alignment Okay Horizontal Alignment Okay Condition at Abutment and at **Concrete Structures** Indications of Movement of None Structural Items on Slopes None **Trespassing on Slopes** Some erosion downstream of both Sloughing or Erosion of Slopes or Abutments north and south abutments. Grass, bushes Vegetation



AREA EVALUATED	CONDITIONS
DAM EMBANKMENT (cont.)	
Rock Slope Protection - Riprap Failures	Some loss of slope pro- tection from stream banks below north & south abutments
Unusual Embankment or Downstream Seepage	None
Piping or Boils	None
Foundation Drainage Features	None
Toe Drains	None
Instrumentation System	None

r

A-3

INSPECTION CHECKLIST	ECTION CHE	ECKLIST
----------------------	------------	---------

PROJECT_	International Packings	DATE	11-21-78
_	Corporation Lower Dam		
PROJECT	FEATURE <u>Intake Channel/Structure</u>	NAME	Cole, Nyman
DISCIPLI	NE <u>Geotechnical, Structural H/H</u>	NAME	Devine

t

Ì

r

.

•___

-

r

CONDITION

<u>001</u>	LET WORKS - INTAKE CHANNEL AND NTAKE STRUCTURE	
a.	Approach Channel	
	Slope Conditions	Concrete and masonry retaining walls, upstream wall in poor condition.
	Bottom Conditions	Some silt, no debris.
	Rock Slides or Falls	None
	Log Boom	Attached by rope only on upstream end.
	Debris	None
	Condition of Concrete Lining	No lining
	Drains or Weep Holes	None
b.	Intake Structure	
	Condition of Concrete	Spalled
	Stop Logs and Slots	None
	Debris Screen	None

Low level, low flow outlet trap door through cribwork, and power house canal.

INSPECTION CHECKLIST

PROJECT <u>International Packings</u> Corporation Lower Dam	DATE	11-21-78
PROJECT FEATURE Control Tower	NAME	Cole, Nym
DISCIPLINE <u>Geotechnical, Structural H/H</u>	NAME	Devine

C. V. 5

ŕ

Ŕ

.

ř

NAME	Cole, Nyman
NAME	Devine

	AREA EVALUATED	CONDITION
<u>00</u>	ILET WORKS - CONTROL TOWER	
a.	Masonry and Structural	
	General Condition	Fair
	Condition of Joints	Okay
	Spalling	Some spalling, side walls
	Visible Reinforcing	None
	Rusting or Staining of Concrete	Minor staining
	Any Seepage or Efflorescence	None Evident
	Joint Alignment	Okay
	Unusual Seepage or Leaks in Gate Chamber	None
	Cracks	Horizontal cracks in canal walls
	Rusting or Corrosion of Steel	None
b.	Mechanical and Electrical	
	Air Vents	N/A
	Float Wells	N/A
	Gate Hoist	Appear operable, gates open, gate house full of stored materials
	Elevator	N/A

¹Outlet to power house.

A-5

CONDITIONS

OUTLET WORKS - CONTROL TOWER (cont.)

Hydraulic System	N/A
Service Gates	Timber - okay
Emergency Gates	N/A
Lightning Protection System	N/A
Emergency Power System	N/A
Wiring and Lighting System	N/A

A-6

INSPECTION CHECKLIST

ŕ

Ň

r

Alia

PROJECT <u>International Packings</u> Corporation Lower Dam	DATE 11-21-78
PROJECT FEATURE <u>Transition & Conduit</u>	NAME Cole, Nyman
DISCIPLINE <u>Geotechnical</u> , Structural H/H	NAMEDevine
AREA EVALUATED	CONDITION
OUTLET WORKS - TRANSITION AND CONDUIT	
General Condition of Stone Masonry	Fair to poor
Rust or Staining on Stone Masonry	Some staining
Spalling	Severe spall, roof
Erosion or Cavitation	Floor eroded, undermining of support piers
Cracking	Not observed
Alignment of Monoliths	N/A
Alignment of Joints	N/A
Numbering of Monoliths	N/A
l Tailrace from power house.	
N	DTE: Tailrace has timber roof or

concrete over timber foot or concrete over timber. Timber roof collapsed in one area. Timber seriously deteriorated throughout.

PERIODIC INSPECTION CHECKLI

PROJECT International Packings	DATE	11-21-78
Corporation Lower Dam		
PROJECT FEATURE <u>Outlet Structure/Channel</u>	NAME	Cole, Nyman
DISCIPLINE Geotechnical, Structural H/H	NAME	Devine

Ē

C

.

.

C

.

CONDITION

OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL	
General Condition of Stone Masonry	Fair - masonry loose
Rust or Staining	N/A
Spalling	N/A
Erosion or Cavitation	Erosion of floor
Visible Reinforcing	N/A
Any Seepage or Efflorescence	None
Condition at Joints	N/A
Drain holes	None
Channel	-
Loose Rock or Tr ee s Overhanging Channel	Trees both sides of channel
Condition of Discharge Channel	Clear, unobstructed

l Tailrace from power house.

I	N	S	PE	C.	ΤI	ON	CHECKL	I	S	I
---	---	---	----	----	----	----	--------	---	---	---

PROJECT <u>International Packings</u> Corporation Lower Dam	DATE	11-21-78
PROJECT FEATURE	NAME	Cole, Nyman
DISCIPLINE <u>Geotechnical</u> , Structural H/H	NAME	Devine

CONDITION

OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS

a. Approach Channel

. . .

ľ

(

. .

- General Condition C
- Loose Rock Overhanging Channel
- Trees Overhanging Channel
- Floor of Approach Channel
- b. Weir and Training Walls¹
 - General Condition of Concrete and Masonry
 - Rust or Staining
 - Spalling
 - Any Visible Reinforcing
 - Any Seepage or Efflorescence
 - Drain Holes
- c. Discharge Channel General Condition

1

Timber weir, concrete walls.

- Clear, unobstructed
- none
- None
- Silted, no debris
- Fair, some spall & erosion
- Some rust & lime stain
- Severe
- None
- None
- None
- Clear, unobstructed

CONDITION

OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS (Cont.)

Loose Rock Overhanging Channel

Trees Overhanging Channel

Floor of Channel

Ē

D

.

C

.

ŕ

Other Obstructions

None

Trees on banks both sides of channel

Severe scour below spillway some undermining

None

NOTE: Timber weir has settled and deflected downstream at center. Timber in fair condition.



INSPECTION CHECKLIST

PROJECT	International Packings	
_	Corporation Lower Dam	

PROJECT FEATURE Service Bridge

DISCIPLINE Structural

DATE 11-21-78

NAME Cole

NAME Nyman

AREA EVALUATED

CONDITION

OUTLET WORKS - SERVICE BRIDGE

- a. Super Structure
 - Bearings Anchor Bolts Bridge Seat Longitudinal Members

Under Side of Deck Secondary Bracing

Deck

Drainage System Railings **Expansion Joints**

Paint

Abutment & Piers b.

General Condition of Concrete
Alignment of Abutment
Approach to Bridge
Condition of Seat & Backwall

Timber - okay Okay 0kay Okay - timber Okay Okay - timber Okay - timber N/A Good N/A

Railing good - none on timber deck or beams

Fair Okay

Good

Okay

IPC Lower Dam

A-11

SUPPLEMENTARY INSPECTION NOTES

INTERNATIONAL PACKING COMPANY

LOWER DAM

BRISTOL, NEW HAMPSHIRE

APPENDIX A

The dam consists of concrete abutments and training walls with a timber spillway. Appurtenant to the dam is a gate works to a canal and power house with a tailrace discharging to the downstream channel.

1. CONCRETE STRUCTURES IN GENERAL

Ð

Ċ

A. Concrete Surfaces In General

The concrete wing walls at the dam were found to be in generally poor condition. Substantial spalling and erosion of the concrete has occurred (especially the north abutment on the downstream side of spillway). No reinforcing steel is presently exposed. The sidewalls of the canal to the power house were also found to be spalled in several areas. No reinforcing steel is exposed.

B. Structural Cracking

No structural cracks were observed in the concrete portions of the dam.

C. Movement, Horizontal and Vertical Alignment

No evidence of substantial settlement or horizontal movement was observed in the concrete portions of the dam.

D. Junctions

The junctions between the concrete and timber sections of the dam were found to be generally in good condition with no evidence of significant movement. Some leakage was noted. A junction in the south wing wall at the corner between the wing wall and the canal section was found to be open indicating some movement.

A-12

E. Drains

Ó

r

.

. .

è

No foundation or joint drains were observed in the concrete portions of the structure.

F. Water Passages

The wing walls of the dam were found to be spalled and show some signs of erosion. In particular, the north abutment exhibits severe spalling. The east wing wall of the canal is also deteriorated. Otherwise, no significant erosion of concrete surfaces is evident.

G. Seepage or Leakage

No significant seepage or leakage was observed through or below the faces of the concrete portions of the dam.

H. Monolith Joints, Construction Joints

The joint at the corner between the southerly wing wall or training wall in the canal was found to be open a small amount. No other joints were observed to be open.

I. Foundation

The foundation of the concrete structures at the dam is apparently placed on soil, likely glacial till. No evidence of foundation distress or undermining was noted.

J. Abutments

The abutments of the dam consist of the concrete training walls at the end of the timber section and are apparently founded on soil, likely glacial till. The abutments of the dam show no signs of instability. Some minor seepage was observed downstream of the northerly abutment, in the form of an iron spring.

2. EMBANKMENT STRUCTURES

The only embankment structures at the dam are small areas of backfill behind the abutments of the dam. The embankment structures show no signs of instability or distress.

A-13

A. Settlement

ŕ

ľ

F

.

_

.

C

No settlement of the embankment section of the dam was observed.

B. Slope Stability

The embankment sections of the dam are retained by concrete, stone masonry or timber crib walls. No evidence of instability was observed.

C. Seepage

An iron spring is located just downstream of the north abutment. The volume of seepage was less than 1 gpm at the time of inspection. No evidence of erosion or piping of materials from this spring was noted.

D. Drainage Systems

No drainage systems were observed or are known to exist in the dam.

E. Slope Protection

The embankment sections of the dam are retained by concrete, stone masonry or timber crib walls. No serious erosion or slope instability was noted.

3. TIMBER STRUCTURE IN GENERAL

The spillway section of the dam is constructed of timber cribwork with timber columns forming stoplog slots.

The timber columns are supported at their top by tie rods which run diagonally down to the upstream toe of the dam. A cable extending from the south to the north abutment also supports the top of the stop log columns. The tie rods were found to be corroded but in generally good condition.

A. Condition of Timber

The planking of the dam was found to be in generally fair condition. Some of the planking showed signs of serious deterioration, cracking, rotting and also in some areas the planking was found to be broken due to the action of ice. The timber columns which support the stoplogs are found to be in generally good condition with no serious rot in evidence.

A-14

B. Movement, Horizontal and Vertical Alignment

The timber section of the dam shows signs of settlement in at least two areas; the downstream sill has settled as much as 4 or more inches. The stoplog section as well as the cribs appear to have deflected downstream at least 5 to 7 inches at the midpoint of the dam.

C. Junctions

D

•

r

.

.

_

The junctions between the timber sections and the concrete training walls appear to be in generally fair to good condition. Substantial leakage is occurring through these junctions. Substantial movement has not occurred.

D. Seepage or Leakage

A substantial flow of water was occuring down through the timber cribwork of the dam at the time of inspection. The flow of the stream was estimated to be 2 to 5 cfs, all of which was flowing through and beneath the timber crib section of the dam. Several holes at the upstream toe of the timber crib were observed and water going down through these holes was observed to be flowing out of the downstream face of the cribwork. Some undermining has occurred at the downstream toe of the cribwork which has probably caused the settlement and downstream movement of the structure.

4. SPILLWAY STRUCTURES

The spillway structure consists of the timber section of the dam with stoplogs across its entire length.

A. Control Gates and Operating Machinery

The control gates are stoplogs located at the top of the spillway. The stoplogs have to be manually removed. There is no hoisting equipment available. It was noted that some hooks on the stoplogs have broken, which would make removal of these stoplogs difficult.

B. Unlined Saddle Spillways

It appears that during high flow conditions, the northerly upstream bank may be overtopped with flow

A-15

going through a parking area and road returning to the stream channel below the dam. No erosion is evident, however. Flow is also likely to occur over the sidewall of the canal in the southerly bank and returns to the stream below the dam. Some erosion was noted on the stream bank below the dam on the southerly side.

C. Approach and Outlet Channels

The approach and outlet channel to the spillway was found to be clear and unobstructed. There is a boom log located across the inlet canal to the power house on the southerly side of the spillway. It was noted that the upstream end of the boom log was attached to the shore by a small rope, not by a chain. This log could become loose and swing into the spillway section of the dam, causing an obstruction or damage to the spillway.

D. Stilling Basin

The stilling basin downstream of the spillway consists of a timber deck on top of the cribwork. It was found that the deck was in fair condition and that many planks were broken and others were rotted. Downstream of this deck substantial scouring has occurred. Erosion has occurred in the streambed and some undermining of the cribwork has apparently occurred. This has apparently contributed to the settlement and deflection of the spillway section of the dam.

5. OUTLET WORKS

The only outlet works at the dam, other than the stoplog section in the spillway, consists of a steel trap door located in the upstream face of the timber spillway deck. These outlet works can only be operated in low water conditions to maintain flow downstream through the cribwork for maintenance to the facility.

The canal and gate works upstream of the power house form an outlet only if water is allowed to flow through the generator turbine and out the tailrace. This structure could be used as an outlet for the dam.

A. Intake Structure

The inlet structure at the canal consists of concrete wing walls. There is a log boom upstream of the inlet

structure. It was observed that the inlet is clear and unobstructed.

B. Operating and Emergency Control Gates

The control gates at the canal consist of three vertical lift gates. The gates and hoisting equipment were found to be in generally good condition, however, the gate house is presently used for storage, and operation of the gates is not presently possible due to the amount of material stored in the gate house.

C. Conduit, Sluices and Water Passages

The interior surface of the canal was found to be in fair condition. Substantial spalling of the concrete side walls and erosion of the side walls has occurred. The floor of the canal was found to be in good condition.

D. Stilling Basin

)

Downstream of the power house the tailrace is an enclosed structure with stone masonry sidewalls and a timber and/or a concrete roof. This tailrace runs at least 150 feet downstream to the stream channel. This covered tailrace was found to be in very poor condition. It has no concrete floor, substantial erosion has occurred in the bottom, and undermining of the concrete support piers and also some of the stone masonry walls is evident. The roof of this tailrace was found to be in very poor condition; the timber being seriously rotted, exposed concrete being seriously spalled and in one area the timber roof was found to have collapsed. It appears presently that the tailrace would clog if substantial flow was allowed to pass through the tailrace from the power house.

E. Approach and Outlet Channels

The approach channel to the power house canal was found to be clear and unobstructed, however, the trash rack immediately upstream of the power house was heavily covered by leaves, brush and debris. The downstream channel consists of the tailrace which, as discussed above, is in very poor condition. The outlet channel of the main stream below the tailrace is clear and unobstructed.

A-17

6. INSTRUMENTATION

None.

- 7. RESERVOIR
 - <u>A. Shore Line</u>. No active or inactive landslide areas were observed.
 - B. Sedimentation. There is a small amount of sediment accumulated in the reservoir area; however, it is not sufficient to impede flow to the dam or significantly decrease reservoir storage. Newfound Lake controls the amount of sediment delivered to the reservoir.
 - C. Potential Upstream Hazard Area. A real estate office located on the north bank of the dam would be flooded to a shallow depth (<1') with water at top of dam because of a low area in the reservoir shoreline. However, general flooding would probably be occurring before water was at top of dam during flood events.
 - D. Watershed Runoff Potential. The drainage basin has remained primarily rural and forested.
- 8. __ DOWNSTREAM CHANNEL

The channel downstream of the IPC Lower Dam is not capable of handling moderate to high flows without considerable overbanks flow occurring. In the event of failure of the dam, approximately 10 commercial, industrial, and residential buildings within 1500 feet of the dam would be flooded to depths of 1 to 3 feet.

9. ___OPERATION AND MAINTENANCE FEATURES

A. Operation

Operation of the dam at high head is continued even during times of no power production. Maintenance is on an as-needed basis, with once-a-year shutdown for maintenance of this facility. No records are kept.

B. Maintenance

It was noted that maintenance is apparently done on the dam on as-needed basis, however, little maintenance has

A-18

2 A Same

been done on the dam recently. The timber section shows signs of rot and deterioration, the cable which supports the stop log columns is loose, the stop logs are missing several lifting hooks, and the gate house is cluttered with stored materials.



A-19

APPENDIX B

ENGINEERING DATA

This appendix lists the engineering data collected either from project records and other sources of data developed as a result of the visual inspection. The contents of this appendix are listed below.

Appendix	Description					
B-1	General Project Data					
B-2	Past Inspection Reports					

Γ

r

_

.

Γ

IPC Lower Dam

B-1

APPENDIX B-1

ŕ

Γ

GENERAL PROJECT DATA

- I. The following material relative to the International Packings Corporation Lower Dam is on file at that firm's Bristol, New Hampshire plant.
 - A. Drawing No. 30482: One type "Z" vertical shaft turbine unit for Dodge Davis Mfg. Co., 1922.
 - B. Miscellaneous information relating to generating equipment.
- II. The following material is available at the office of the New Hampshire Water Resources Board, 37 Pleasant Street, Concord, New Hampshire:
 - A. Periodic inspection reports, copies of which are attached as Appendix B-2 of this report.
 - B. Photographs taken of dam at various times during the period 1934 to present.
 - C. Miscellaneous correspondence and survey data.
- III. The following plan, profile and cross-sections of the dam were developed from a limited stadia survey performed during visual inspection, field notes taken by inspection team members, and photographs taken during the visual inspection. The survey was referenced to an arbitrary local datum. Approximate U.S.G.S. elevations were obtained by adding 388.8 to the local reference.







APPENDIX B-2

ſ

Ŋ

r

Ť

_

•

Ĉ

PAST INSPECTION REPORTS

Attached are copies of inspection reports pertaining to the International Packing Corporation Lower Dam on file with the New Hampshire Water Resources Board in Concord, New Hampshire.





MEMORANDUM

DATE: March 2, 1973
FROM: Robert B. Chamball, Avil Engineer
SUBJECT: Inspection of NewFound River Dam - No. 131.07
TO: Vernon A. Knowlton,
Chief Engineer, Water Resources Board

On February 28, 1973, I inspected this dam following a telephone complaint by Bill Swain, of the Corps of Engineers on February 23 concerning the bending of this dam.

The dam is a log crib structure of hard-pan foundation. Height of dam is about four feet and has four foot of flash boards which are held in place by a number of wooden frames. At some time in the past, the flash board structure was reinforced with a cable which runs through the abutments and along the downstream side of the flashboard structure. (See pictures).

Near the abutments there is an abvious bending toward the downstream, while the center section appears to be straight. No visibility was available to the dam itself, due to about a foot of water going over two-thirds of the spillway.

RBC: js

٥

.

•

•

Comin Summer

B-2.3

	IN	TER-DEPARTMENT	COMMUNICA	TION		
om Stephen	C. Burritt. Ci	DA Lvil Engineer		vember 21,	1977	
	•••••••••••		Wter	Resources	Board	
BJECT	Dam 31.07 Bri	istol, N. H.	Y -			
То	File	C)			
	•	· · · •				
	This dam 1	looks to be in good	i shape. At	the time o	f inspection	
t he dam stoplog	was passing abo s has been repl	out 3 [*] to 6". The laced by a steel wi	old wooden b de flange be	eam holding am, and it	g up the still has	
a bow i	n it (see phot	to).	•			
	This dam s	should be inspected	in the summe	2 2 .	•	
					•	
		1	V			
				•	· .	•
	• • • • • • • • • • • • • • • • • • • •			· • • • • • • • • •		· · · · · · · · · · · · · ·
	• • • • • • •		···· ·	•	•	• •
		•	•		. ·	•
•		, B-2.4				•
				IPC Lower	Dam	
					-	



N

•

•

r

WATER RESOURCES BOARD

37 Pleasant Street Concord, N.H. 03301

TELEPHONE 271



International Packing Corp. Bristol, New Hampshire 03222

Dear Sirs:

Under the provisions of RSA Chapter 482, Sections 8 through 15, the New Hampshire Water Resources Board is authorized to inspect all dams in the State which by reason of their physical condition, height and location may be a menace to the public safety.

The dam structure (No. 31.03 & 07) located Bristol, New Hampshire-

Newfound River was inspected on <u>October 19, 1978</u> and as a result of this inspection, certain discrepancies were found which should require corrective measures in order to protect the integrity of the structure. (See attached sheet.)

Your dam has been classified by the Board as a non-menace dam and with this classification, the State will not insist that the item(s) noted on the attached be corrected, but it is advisable that corrective measures be voluntarily initiated to protect the integrity of the structure.

Should you make the repairs and/or maintenance items on the attached sheet in the waters of the State, you will need a permit from the Special Board. Applications can be obtained by writing or calling the Special Board Office, 37 Pleasant Street, Concord, New Hampshire 03301, elephone no. 271-2147.

Please feel free to call or write if you have any questions regarding the evaluation of your structure.

Sincerelv

McGee, Sr. Chairm

CMM:paf Enc.

cc:

B-2.5
Dam No. 31.03 Newfound River inspected on October 19, 1978

Visual Discrepancies (31.03 Upper Dam)

. 1-1

ÿ

.

.

•••

Ċ

1- Spalled concrete should be repaired at the following locations:

a- The wing walls at the stop ne section on the right canal,

b- The left abutment near the lowerhouse,

c- The downstream side of the powerhouse.

- 2- The large crack in the downstream wing wall between the spillway and powerhouse should be repaired.
- 3- There are a few large trees growing very near the concrete and stone appurtenances which should be cut and treated to prevent regrowth. The roots of trees displace stones, crack concrete and increase seepage through earthen embankments.

Dam No. 31.07 Newfound River inspected on October 19, 1978

Visual Discrepancies (31.07 Lower Dam)

- 1- The right spillway abutment is badly spalled and should be patched or completely refaced.
- 2- The left abutment at the head gates is extremely deteriorated and should be reconstructed.
- 3- There are two trees growing at the downstream and of the left abutment which should be cut and chemically treated to prevent regrowth.

P. S. - Please contact Mr. McGee by telephone (271-3406) to arrange for purchase of cinders.

B-2.6

NEW HAMPSHIRE WATER RESOURCES BOARD INSPECTION REPORT Dam Number: 31.07 Town: BRISTOL Name of Dam, Stream and/or Nater Body: NEU ODND FIVER Owner: IPC into! Telephone Number: Mailing Address: Aunt ヨウマン Pond Area: KACRE Length of Dam: 293' Max. Height of Dam: 16' FOUNDATION: EARTH OUTLET WORKS: 87' SPILLWAY 6.2'TOTAL FREEBAARD 1.5 ACTUAL PUE TO STOP LOC -POND DRAIN W STEEL DODR IS FREEBOARD @ FULL POUP LEAKS BAPLY ALLORPING TO OWNERS NOT OBSERVED DUE TO TAILUIATER RT ABUT - EXTREME SPALLING **ABUTMENTS:** HEAD IT ABUT /a WHEEC COMPLETELY SPALLED GATES TO 8'X10' UNDERGROUND TAIL FALE EMBANDOENT Note: Give Sizing, Condition and detailed description for each item, if applicable.

Dam No. 31.07 -2-Length: 87' Frieboard: 1.5 W/STOPLOGS IN SPILLWAY: 6.2 W/ NO STOP LOGS Location, estimated quantity, etc. SEEPAGE: 20-30 CES THROUGH TOE NOT OBSERVED . Changes Since Construction or Last Inspection: CONC US APRON NEW CATULALK, IBEAM, STOP LOG SUPPORTS, STEEL TIE EACKS F÷. REZONSTRUCTED IN 1973 HEAD GATE " 1978 HEAD GATE " Tail Water conditions: CONCRETE ENCASEMENT AROUND WHEEL HOUSE 1978 Overall Condition of Dam: FAIR TO GOOD - SPALLED ABUTMENTS Contact With Owner: YES Date of Inspection: 10/19/78 Suggested Reinspection Date _ Class of Dam: NON-MENACE Signature Kenneth them Date 10/19/78 B-2.8 **IPC Lower Dam**

Dam No. 31.07 - 3 -COMMENTS: ٥ SPALLED ATE PT _____ GATES SPALLED ABUT 0 2 SMALL TREES ABUT _____ Å . ____ r • • _____ . •. B-2.9



APPENDIX C

Γ

••••

ŕ

Ŀ,

-

.

Ľ

PHOTOGRAPHS

The following are photographs referenced in this report. See Sheet B-1.3 for photograph locations and orientations.



Ļ

.

ŕ

.

••••

r

Ċ

IPSTREAM FACE OF DAM; INLET CANAL TO POWERHOUSE IS AT LEFT



2 VIEW OF SPILLWAY STRUCTURE FROM NORTH END; NOTE DEFLECTION OF STRUCTURE TOWARD DOWNSTREAM





3 NORTH ABUTMENT; NOTE SPALLING OF CONCRETE



SEEP ADJACENT TO UPSTREAM APRON; COBBLES & RUBBER SHEET ARE EVIDENCE OF ATTEMPTED REPAIR



INLET TO CANAL TO POWERHOUSE; NOTE DETERIORATION OF LEFT (EAST) WING WALL



6 POWERHOUSE CANAL; NOTE SPALLING OF SIDE WALLS





7 TAIL RACE OUTLET; POWERHOUSE IS IN BACKGROUND; CANAL & DAM ARE TO RIGHT OF POWERHOUSE



8 BRIDGE IMMEDIATELY UPSTREAM FROM DAM

Ī

.

Ľ

Ľ

.

Ē

[



9 DOWNSTREAM VIEW; DEEPER WATER IN FOREGROUND IS RESULT OF SCOUR IMMEDIATELY BELOW DAM

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

E

Ċ

Hydrologic computations pertinent to this investigation are attached. The following figure shows the Newfound River watershed at the International Packings Corporation Lower Dam.



PROJECT	CUMP BY	108 NO. 20797-07
IPC LOWER DAM	CHK BY	DATE 12-19-78

Test Flood Analysis

.

1-1

All Flow at the IPC Lower Dam is affected by the storage - discharge relationships of the Newfound Lake Dam. The drainage area above Newfound Lake Dam is 95.0 square miles. The drainage area shove the IPC Lower Dam is 96.1 square miles.

The PMF and 1/2 PAIF flood flows are to be routed through Newfound Lake. The routed Flow will then be added to the contribution from the remaining drainage (1.1 mis) to determine the peaks discharge rates of the PAIF and 1/2 PAIF. The fact that the peaks will be out of sink due to routing is not considered.

Slope of the longest channel = 140 Ft/Mile Terrain is fully to mountainous

- Using mountaineus curve of Guide Curves :

MPF = 1,200 csm × 95.0 m² = 114,000 cfs (peak to be routed) 1/2 MPF to be routed = 57,000 cfs

Storage Routing (Using HEC-1) A) <u>Inflow hydrograph</u> I. PMF peak = 114,000 cfs 2. ¹/₂ PMF peak = 57,000 cfs 3. Time to peak : 19" runoff from 95 mi² = 96,267 A-F (total area under hydrograph) 96,267 = $\frac{1}{2}$ (114,000) × B



runoff

Time to peak = 20.4 + 2.67 = 7.6 Hours = 7.5 hours



		L. JURUAR LUSS INC.
PROJECT	COMP BY	J03 NO.
	JJD	20799.07
	CHK BY	DATE
	573	12- 9-75

B) Storage - Discharge Relationship

D

. •

IT.

T

Ē

La:a on Newfound Lake : Newfound Lake is prezently owned and operated by the New Hampanic Water Resources Board. The primary purpose of the dam is for lake level control for recreation on Newfound Lake. A minimum release to the Newfound River is provided. During the winter months, normal operating procedure provides for maintenance of the lake level at 4.2 ft with respect to the USGS water surface elevation gage located at the dam. During the summer month, normal operating procedure provides for maintenance of the lake level at 6.5 ft (storage = 35,470 ac.-ft.). For the initial storage volume in the HEC-1 routing subroutine, we input 35,470 acre-feet.

An area - capacity table for Newfound Lake is included in this Appendix.

- capacity at full pond elevation of 589.1 ft = 38,800 A-F
 area at full pond elev
 = 4,100 acres
 capacity at elev 588.4'(6.5' on USGS
 reservoir elevation gage)
 = 35,470 A-F
 there is a storage capacity of about
 13,200 acre-feet below reservoir lovel of 1.3'
- area at elevation 600 ft = 5,500 acres (from USGS quod) interval capacity = $\left(\frac{5500+4100}{2}\right) \times 10.9^{1/2}$ = 52,320 A-F total capacity at 600 ft = 91,120 A-F

- area at elevation 620 ft = 7,350 acres (From USES quad) interval capacity = $\left(\frac{5500 + 7350}{2}\right)_{\times} 20'$ = 128,500 A-F total capacity = 219,620 A-F

- Elevations obtained from N.H. Water Resources Board.

D-4

Ĺ D

C

TORY OF THE TORY OF THE CUBIC FEET PER SECOND

È

SCS GAG	<u>ы</u>								·			
Elev. F					Tenths ol	f Teet					Avc.	Ine
-	0.0	0.1	0.2	0.3	0.4	0.5	0.6	0.7	0.8	0.9	Diff.	Run
1.0(0	0	0	л ⁶¹¹	322	532	735	938	1141	1344	200	5.1(
2.0	0 1554	1757	1967	2170	2380	2590	2793	3003	3213	3423	210	4.4
3.0	0 3633	3843	4053	4263	4473	4690	4900	5110	5327	5537	210	3.67
4.0	5745	5971	6181	6398	6615	6832	7049	7259	7483	7700	220	2.82
5.0	2162 C	8134	8351	8568	8792	9009	9233	9450	9674	9891	220	1,97
ō. • D-	0 10115	10339	10563	10780	11004	11228	11459	11683	11907	12131	220	1.10
ō.^ 5	0 12362	12586	12810*	13041	13272	13496	13727	13958	14182	14413	230	0.21
8.0	14644	14874	15104	15334	15564	15794	16024	16254	16484	16714	230	0.65
<u>0</u> .6	0 16944	17184	17424	17664	17904	18144	18384	18624	18864	19104	240	1.59
10.0	0 19344	19584	19824	20064	20304	20544*					240	2.5/
												3.02
	Gross D Surface).A. : Area	95.05 4106	5 Sq. Mi. Acres								

Based on USGS Capacity Table dated 11/25/42 Computed by V.A.K. - 4/4/74 elevation 1.3' on gage; approximately 13,200 acre-fret. Discharge from the spillway is controlled by a sardlar upstream of the dam. The sardbar control Nole : Storage 15 given in cfs-days. There is storage below C) r r

Elev. 7.24 USGS = 108"

Dam Gage Elev. 7.24 USGS 1" Runoff = 2535 cfs = 1.16' on Lake

581.88 USGS Gage

Zero of Gage

Full Pond Gate Sill

Elev. -2.15 Elev. 7.24

USGS Gage



PROJECT	COMP BY JJD	JOB NO. 20797-07
	CHK BY	DATE 12-20-78

B) Storage - Dismarge Relationship

È

Ŋ

É

.

Newfound Lake Dam and Spillway :

The top of doin at New found take is at elevation 592.4'. The dom 15 110' long. There are three distinct spillway sections. Weir "A" consists of 3 stop log sections measuring 12.7 ft high by 4,0 ft wide. Floor elevation of weir "A" is about 579.7 ft. Weir "B" also consists of 3 stop log sections measuring 12.7 ft high by 6 ft wide. Floor elevation of weir "B" is 579.7 ft. A sandbar upstream of the dam impedes flow below elevation 584.2 ft (~2.3 ft on USGS gage on reservoir). It is assumed there is no discharge with reservoir water surface elevation $\stackrel{<}{=} 584.2$ ft.

Weir "C" consists of 6 bay spillways measuring 7.2 ft wide by 6.2 ft high. Floor elevation of weir "C" is 586.2 ft.

C)	Summary	of	storage	-	discharge	data
----	---------	----	---------	---	-----------	------

Elev (f+)	Storage (A-F)	Discharge (cfs)		E le v. (Ft.)	Storoge (A-F)	Discharge (cfs)
580.2	4,000	0		598.2	82,000	16,009
581. Z	6,000	0		600.2	94,000	20,117
582.2	10,000	0		605.2	117,000	35,637
583.2	13,000	0		610.2	146,000	52,928
584.2	18,000	0		615.2	171,000	71,192
585.2	23,000	1,018		620.0	220,000	89,763
586.2	28,000	1,308				ł
587.2	31,000	1,735		1	1	1
588.2	35,000	2,282				
589.2	40,000	2,923	ļ			
590.2	45,000	3,649				
591. 2						
592 2					1	ļ
593.2	58,000	6,980		1		1
594.Z					1	
595.2	67,000	10,310		1	ł	
	1	•	l	1	1	I

PROJECT	COMP BY	JOB NO.
PATING CURVE - NEW COULD Lake Law Sciences	JJD	20779-01
	CHK BY BTB	DATE 12-20 - 14

ř

,

ASSUME FLOW IS GOVERNED BY Q= CLAI³² AND SHILLWAY ASTE AS A BADAL -CRESTEL WEIR OK WEIR WITH TRAPEZOIDAL CROSS - SETTION.

Upstream sund bar imposes discharge below elevation 587.2 ft (2.3 ft on USGS reservoir elevation gase). Top of tam elevation = 592.4 ft. Discharge at 584.2 ft = 0.0 cfs. Bottom of bay spillways = 586.2 ft. Elevation of gate sill = 579.7 ft

	Elevation	Dischai	rge thr (cfs)	ough W	eir "A"	<u>'</u>	Di	scharge (through cfs)	l weir '	B" Z'
· •.	(#)	Н	کئے	L	Qc	QT_	H	لق	4	Qs	QT.
·											
•	584.7	5.0	2.63	4	118	353	5.0	2.63	6		529
	585.2	5.5		1		407 .	5.5		1		611
		6.0				464	6.0				696
F "	586.2	6.5				523	6.5				785
<i></i>		7.0				585	7.0				877
	<i>5</i> 87. 2	7.5				648	7.5				972
		8.0				714	8.0	:			1,071
	588.2	8.5				782	8.5				1,173
4		9.0				852	9.0				1,278
- '	589.2	9.5				924	9.5	:			1,386
·-•.		10.0				998	10.0		;		1,497
-	590.2	10.5				1,074	10.5		1		1,611
	-	11.0				1,151	11.0		•		1,727
1	591.2	11.5				1,231	11.5				1,846
		12.0				1,312	12.0		•		1,968
	592.2	12.5				1,395	12.5				2,092
P OF DAM	592.4	12.7		ł		1,428	12.7				2,143
•	593.2	13.5				1,565	13.5	•			2,348
^	594.2	14.5				1,743	14.5	•			2,614
	595.2	15.5			•	1,926	15.5				2,889
·	596.2	16.5				2,115	16.5				3,173
	597.2	17.5				2.310	17.5				3.466
⁷ H	598.2	18.5				2,511	18.5				3 766
\mathcal{A}	599.2	19.5				2718	19.5				4.076
r)	600.2	20.5				2.929	20.5				4.394
1/	601.2	21.5				3,146	21.5				4.719
$\sim M$	602.2	22.5				3,368	22.5				5,053
	603.2	23.5				3, 595	23.5				5,393
	604.2	24.5	V I	V	ļ	3,827	24.5				5,741

PROJECT

Ċ

D

Ì

COMP BY	JOB NO. 20749-07
CHK BY	DATE 12-20-75

Flow through Weirs "A" and "B" (cont.)

Elevation (ft)	н	С	La	LB	Q A	Q _B
605.2 606.2 607.2 608.2 609.2 610.2 611.2 612.2 613.2 613.2 614.2 615.2 616.2 616.2 618.2 619.2 620.0	25.5 26.5 27.5 28.5 30.5 31.5 32.5 33.5 34.5 35.5 34.5 36.5 37.5 38.5 39.5 40.3	2.63	4	6	4,064 4,305 4,551 4,802 5,057 5,316 5,580 5,847 6,119 6,395 6,675 6,960 7,247 7,539 7,835 8,074	6,096 6,458 6,827 7,203 7,585 7,974 8,369 8,771 9,179 9,593 10,010 10,439 10,871 11,309 11,752 12,111

D-9

$ \begin{array}{c c c c c c c c c c c c c c c c c c c $	PROJECT				-		CUMP BY	JUB NU.	
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	RATIN'S C	URVE -	NEXTOUR	r Lake	Don' Cp	5 2 21			1
$5L_{11}$ $SP_{11}LWAYS = -$ Toris of 6 b baus w. 0 mensors of 7.2' wise w 6.2'r m							BTR	12-20-75	
BLY SDILLWAYS Total of 6 bous W. Ormers on 5 of 7.2 wise w 6.2 mm Bits Elevation = conjection = 536.2 Lischarge through were C "H (H) H C Crist Grist Str.2 1.0 Str.2 1.0 Str.2 1.0 2.0 2.67 Str.2 1.0 2.0 2.67 2.0 2.67 2.0 2.67 2.0 2.68 3.0 2.75 2.0 2.68 3.0 2.75 3.0 2.75 3.0 2.75 3.0 2.75 3.0 2.76 3.0 2.77 1.18 wer rest total were rest 58.7 3.50 570.7 4.5 58.7 3.50 571.7 5.5 582.2 6.0 592.4 6.2 592.4 6.2 592.2 7.0 592.2 7.0 592.									
Corrow 5" Corr Bernard Corr Corr Corr Corr Corr Corr Corr Co	54 S	SPILLWA	iys - T	total of	is baue	s w, cm	ensions of 7.2's	wise w 6.2'r pa	
Litcharge through were "C"# (rf_2) H C L g_2 g_7 (rf_2) I G g_7 G_7 G_7 G_7 G_7 587.7 1.55 2.62 2.48 327 G_13 G^1 wide g_7 G_7 wide G_7 represents 588.7 2.55 2.72 115 G^2 represents G^2 represents 597.7 4.57 2.88 $I.188$ $I.188$ G^2 wide G^2 represents G^2 wide G^2 represents 597.7 5.5 3.32 $I.188$ $I.188$ G^2 wide G^2 represents 597.2 </td <td></td> <td></td> <td>2</td> <td>tottom o</td> <td>- Co.1 6</td> <td>zievation</td> <td>- 30-6</td> <td></td> <td></td>			2	tottom o	- Co.1 6	zievation	- 30-6		
Elevation (rfs) H C L Q_2 Q_2 (f1) H C L Q_2 Q_2 Q_2 Q_2 Q_1 Q_2 Q_2 Q_2 Q_1 Q_2 Q_2 Q_1 Q_2 Q_2 Q_2 Q_1 Q_2 Q_2 Q_1 Q_2 Q_2 Q_1 Q_2 Q_2 Q_1 Q_2 Q_2 Q_2 Q_1 Q_2 Q_2 Q_2 Q_1 Q_2		Da	scharge	through	weir"C	"出」			
(f') H C L Q_2 Q_7 Weir "A" is the stop log spillung section closest to the right abulates. Loking uptream. There are are an uptream. There are are are are are are are are are	Elevation			rfs)	· · · · · · · · · · · · · · · · · · ·				
(76.7) 0.5 2.61 7.2 40 the right abdives looking 587.7 1.5 2.42 211 3 individual sections $\omega/$ 200 2.428 327 $dimensions of 4' unde by 3 588.7 2.5 2.72 445 10^{2} / high. Q_{3} represents 589.7 3.5 2.74 781 3cction Coresting 589.7 3.5 2.74 781 3cction Coresting 400 2.79 964 flow through a single 571.2 5.0 3.07 1.188 100 spllway sechon constraing 571.2 5.0 3.07 1.483 100 spllway sechon constraing 571.2 5.0 3.07 1.483 100 spllway sechon constraing 572.2 6.0 4 2.108 100^{42} high. Q_{5} represents 572.2 7.0 3.872 7.0 3.872 7.0 3.872 574.2 9.0 3.872 7.0 3.872 7.6 3.872 574.2 $	(f+)	H	C	6	- Qs_	QT_	- Weir "	A" is the stop log) [
76.7 0.5 2.67 7.2 40 the right desting de		ŧ	ļ	ł			spillway	section closest to	
587.2 1.0 2.67 115 uppercent. There are 577.7 1.5 2.64 211 3 individual sections $\omega/$ 588.7 2.5 2.72 445 10^{52} (high. Qs represents) 589.7 3.5 2.76 1781 section, Gr is the tobil 589.7 3.5 2.76 1781 section, Gr is the tobil 570.7 4.5 2.88 1,185 Uppercents 570.7 5.5 3.32 1850 Of three individe stope on the other 571.7 5.5 3.32 1850 Of three individe stope on the other 572.2 6.0 4 2,108 upth Maximum dimensions of 578.2 9.0 3,872 19.0 4 and theories '', Table 578.2 9.0 3,872 10.0	586 7	0.5	2.61	7.2		40	the right	t abut niext looking	2
587.7 1.5 2.42 2.11 3 individual Sections $\omega/$ 588.7 2.5 2.72 445 10^{12} 'high. Q_{5} represents 588.7 3.5 2.72 445 10^{12} 'high. Q_{5} represents 589.7 3.5 2.74 781 section, Q_{7} is the tobol 4.0 2.79 964 flow through a single 597.7 4.5 2.88 $1/88$ 2^{108} 597.7 5.5 3.32 $1/88$ 2^{108} 10^{104} where in form the weir 597.2 5.0 3.07 $1/483$ 100^{104} spillway section consisting 597.4 6.2 - $2,108$ with maximum dimensions of 597.4 6.2 - $2,214$ $6'$ unde by 10^{12} lingt. Q_{5} represents 598.2 7.0 $3,245$ $3/2'$ C value: from Braier & 10^{13} 597.2 9.0 $3,372$ 'low through a single section, Q_{7} 597.2 10.0 $5,223$ 'fon dhesk of Hydrouks'', Table 597.2 13.0 V $6,223$	587.2	1.0	2.67	1		115	upstrea	m. inere are	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	587.7	1.5	2.66			211	5 Indivi	avai sections w/	z
588.7 2.5 2.72 445 10 ⁻¹ mgn. Us represents 3.0 2.73 6.13 flow through a single 589.7 3.5 2.74 781 section, Gr is the tobol 4.0 2.79 964 flow through the weir 590.7 4.5 2.88 1,188 Lag spillway section consisting 591.7 5.5 3.32 1,850 of three individual sections 591.7 5.5 3.32 1,850 of three individual sections 592.4 6.2 - 2,108 with Maximum dimensions of 592.4 6.2 - 2,214 6' wide by 10 ¹² high. Os represents 592.4 6.2 - 2,218 With Maximum dimensions of 592.2 9.0 3,872 "Ho dlook of Hydroulus", faulte 594.2 8.0 3,245 2' C value: from Brater & King 597.2 10.0 5,233 #Weir" C" is the bay 597.2 10.0 5,522 spillway section whick 602.2 10.0 10,653 605.2 603.2		2.0	2.68			327	dimensi	ons of 4 wide by	
3.02.736.13Final A a single 589.7 3.52.76781 300 2179 4.02.79964flow through the weir 570.7 4.52.881,188 2^{1} Weir "B" is the middle stop 571.2 5.03.071,483log spillway section concising 571.7 5.53.321,850of three individual sections 572.2 6.012,108with Maximum dimensions of 572.2 6.012,218of three individual sections 572.2 6.012,218by 10^{12} high. Qs represents 572.2 7.03,872"Idea through a single section, QT 573.2 7.03,872"Idea through a single section, QT 575.2 9.03,872"Idea through a single section, QT 576.2 9.03,872"Idea through a single section, QT 577.2 10.05,233"Idea through a single section, QT 578.2 10.05,922spillway section which 577.2 10.05,922spillway section which 578.2 12.05,922spillway section which 578.2 13.04,7235,942 60.2 14.019.53 60.2 16.019,953 60.2 17.019,053 60.2 20.012,826 67.2 21.013,802 60.2 22.014,800 60.2 23.023,667 60.2 24.019,01	588.7	2.5	2.72			465		n. Ws represence	
389.7 3.5 2.76 781 360.7 4.5 2.79 964 $flow through the weir 570.7 4.5 2.88 1/88 1/88 100 spillway sector consisting 571.7 5.5 3.32 1.850 of three individual sectors 572.2 6.0 4 2.108 with maximum dimensions of 572.4 6.2 2.10 5.972.76 3.245 574.2 9.0 3.872 "Hondbook of Hydroulds", Table 5.753.792.746_0 577.2 10.0 5.762.756.2 5.962.766_0 5.975.2 9.0 579.2 12.0 5.962.7766_0 5.975.2 9.0 9.179.79 602.2 16.0 19.018.776.766_0$		3.0	2.73			613	tlow the	rough a single	
4.02.79764Though the well 590.7 4.52.881,1882/Weir "B" is the middle shop 591.2 5.03.071,483log spillway section consisting 591.2 6.042,108with Maximum dimensions of 592.4 6.2-2,2146' wide by 10 ¹² high. Qs represents 592.4 6.2-2,2146' wide by 10 ¹² high. Qs represents 592.4 6.2-2,656116 widthough a single section, QT 593.2 7.02,65613 the total flow through the weir 574.2 8.03,2452' C' values from Brater & King 578.2 9.03,872"Handbook of Hydrowics", Table 577.2 11.05,233"Weir" C" is the bay 578.2 12.05,962spillway section whick 579.2 13.0V6,723 602.2 14.08,332 602.2 16.010,953 602.2 17.010,053 604.2 18.010,953 604.2 18.011,878 604.2 20.011,878 604.2 20.013,802 612.2 24.014,800 612.2 26.014,800 612.2 26.014,800 612.2 26.021,250 612.2 26.021,250 612.2 26.021,250 612.2 26.021,250 612.2 26.021,250 612.2 23.025,765 <td><i>5</i>8<i>9</i>.7</td> <td>3.5</td> <td>2.76</td> <td></td> <td></td> <td>781</td> <td>Section</td> <td>, Ut is the total</td> <td></td>	<i>5</i> 8 <i>9</i> .7	3.5	2.76			781	Section	, Ut is the total	
590.7 4.5 288 $1,183$ Weit D is the Middle Step 591.2 5.0 3.07 $1,483$ log spillway section consisting 591.2 6.0 1 $2,108$ with Maximum dimensions of 592.2 6.0 1 $2,108$ with Maximum dimensions of 592.4 6.2 $ 2,214$ $6'$ wide by 10^{12} high. Qs represents 593.2 7.0 $3,245$ $3'$ C' value: from Brater & King 593.2 7.0 $3,245$ $3'$ C' value: from Brater & King 593.2 9.0 $3,872$ "Ho adlosis of Hydroulds", fable 597.2 10.0 $4,524$ $5-3$, pg $5-46$. 597.2 10.0 $5,233$ "Weir" C" is the bay 597.2 12.0 $5,962$ spillway section whick 597.2 13.0 V $6,723$ cossiste of 6 bays 60.2 14.0 $9,179$ $10,0533$ $10,953$ 60.2 16.0 $19,193$ $10,953$ $10,953$ 605.2 19.0 $11,878$ $12,2$		4.0	2.79			764	$\frac{1}{2}$	rough the weit	
591.2 5.0 3.07 $1,483$ Ga Spillwad Section Concentry 591.7 5.5 3.32 $1,850$ of three individual Sections 592.2 6.0 4 $2,108$ with Maximum dimensions of 592.4 6.2 $2,108$ with Maximum dimensions of 592.4 6.2 $2,214$ $6'$ unde by $10'2$ high. Qs represents 592.4 6.2 $2,214$ $6'$ unde by $10'2$ high. Qs represents 592.4 6.2 $2,214$ $6'$ unde by $10'2$ high. Qs represents 593.2 7.0 $2,656$ $3,245$ $3'$ C' value: from Brater & King 597.2 10.0 $3,872$ "Handbook of Hydroules", Table 578.2 9.0 $5,762$ $5-3$, pg $5-40$. 578.2 12.0 $5,762$ spillway section whick 578.2 12.0 $5,762$ spillway section whick 578.2 12.0 $5,762$ spillway section whick 60.2 $16,0$ $9,179$ $10,053$ 60.2 $16,0$ $12,828$ $12,828$ $607.$	590.7	4.5	2.88		{	1,188	- Weir D 15 +	ne mianie stop	
591.7 5.5 3.32 $1,050$ Gr There There There there for the there is the form of the maximum dimensions of 392.4 592.4 6.2 - $2,08$ with Maximum dimensions of $6'$ wide by $10'2$ high. Qs represents from the there is 393.2 592.4 6.2 - $2,214$ $6'$ wide by $10'2$ high. Qs represents from 393.2 593.2 7.0 $3,245$ $3'$ C' values from Brater & King 597.2 9.0 $3,872$ "Handbook of Hydroulus", Table 576.2 9.0 $3,872$ "Handbook of Hydroulus", Table 577.2 11.0 $5,233$ "Humbook of Hydroulus", Table 579.2 12.0 $5,762$ spillway section which 579.2 13.0 V $6,723$ consists of 6 bays 602.2 14.0 $8,332$ $9,179$ $10,053$ 603.2 17.0 $10,053$ $10,953$ $12,828$ 604.2 18.0 $12,828$ $12,828$ $12,828$ 607.2 23.0 $14,800$ $12,820$ $12,250$ $61.2.2$ 26.0 $17,014$ $21,250$	591.2	5.0	3.07			1,483	log spiliwau	section consisting	ຳ :
572.2 6.0 $2,108$ With Maximum dimensions of the messale 572.4 6.2 $2,214$ $6'$ wide by $10'^2$ high. Qs represents 573.2 7.0 $2,656$ $5'$ wide by $10'^2$ high. Qs represents 573.2 7.0 $2,656$ $5'$ wide by $10'^2$ high. Qs represents 573.2 7.0 $2,656$ $5'$ wide by $10'^2$ high. Qs represents 573.2 7.0 $3,245$ $3'$ C' values from Brater & King 575.2 9.0 $3,872$ "Hendbook of Hydroules", Table 576.2 10.0 $5,233$ "Weir" C' is the bay 5778.2 12.0 $5,762$ splitway section which 579.2 13.0 $4,533$ $6,723$ splitway section which 600.2 14.0 $6,723$ $consiste of 6 bays$ 607.2 16.0 $10,953$ $10,953$ 605.2 17.0 $10,652$ $12,828$ 606.2 22.0 $14,800$ $12,828$ 607.2 21.0 $13,862$ $17,014$ 612.2 24.0 $17,189$ 2	591.7	5.5	3.32			1,050	of three ind	ividual sections	-
592.4 6.2 $2,214$ $6 bilde 0 ib minut, 05 terms, 05$	592.2	6.0				2,108	with maximur	yzhich Or record	
$535 \ ar \ bm/5)$ 7.0 2:656 is the total flow through a single section, df 574.2 8.0 3:245 2' (' value: from Brater's King) 575.2 9.0 3:872 "Ha dlook of Hydroules", Table 576.2 10.0 4:526 5-3, pg 5-46. 577.2 110 5,233 "Wair" C'' is the bay 578.2 12.0 5,962 spillway section which 578.2 13.0 6,723 consists of 6 bays 600.2 14.0 8,332 602.2 16.0 9,179 605.2 18.0 10,953 607.2 18.0 11,878 606.2 20.0 11,878 606.2 22.0 14,800 607.2 21.0 13,802 607.2 22.0 14,800 607.2 23.0 14,800 607.2 23.0 14,800 607.2 23.0 23,567 612.2 26.0 23,567 614.2 32.0 25,963 619.2 32.0 <	592.4	6.2				2,214	6 wide by ic	o sucho sectors	
593.2 7.0 2.656 3.245 3.245 574.2 8.0 3.245 3.245 3.245 3.245 575.2 9.0 3.872 "Handbook of Hydroulus", Table 576.2 10.0 4.536 5.23, pg 5-46. 577.2 110 5.233 #Weir" C" is the bay 578.2 12.0 5.742 spillway section which 579.2 13.0 6.723 consists of 6 bays 600.2 14.6 8.332 consists of 6 bays 602.2 16.0 9.179 10.053 602.2 18.0 10.953 10.953 605.2 19.0 11.878 10.953 606.2 20.0 12.828 10.953 606.2 20.0 15.820 13.802 606.2 23.0 15.820 14.800 607.2 23.0 14.800 14.800 617.2 23.0 15.820 14.800 617.2 23.0 23.557 14.800 617.2 20.0 23.557 25.763	(TOP OF DAM)?					2101	tion through	a single sectors, a	4T -
374.2 8.0 $3,872$ "Hadbox of Hydroulus", Table 575.2 9.0 $3,872$ "Hadbox of Hydroulus", Table 576.2 10.0 $5,872$ "Hadbox of Hydroulus", Table 577.2 110 $5,233$ $5-46$ 578.2 12.0 $5,762$ spillway section which 578.2 13.0 V $6,723$ consists of 6 bays 600.2 14.0 $7,513$ $8,332.$ 605.2 16.0 607.2 15.0 $8,332.$ 605.3 $10,053$ $10,053$ 605.2 17.0 $10,053$ $12,82.8$ $12,82.8$ 606.2 20.0 $12,82.8$ $12,82.8$ 606.2 20.0 $15,82.0$ $14,800$ 606.2 22.0 $14,800$ $15,82.0$ 617.2 22.0 $14,800$ $12,250$ 617.2 22.0 $12,250$ $14,800$ 617.2 28.0 $27,189$ $25,185$ 617.2 28.0 $25,185$ $27,189$	593.2	7.0				2015	3/10' value E	Bralos & Kus	548 . •
575.2 9.0	594.2	8.0			{	2077	"Ile diet af	Hydraulus" Table	
597.2 110 $5,233$ 44 Weir "C" is the bay 578.2 12.0 $5,962$ spillway section which 579.2 13.0 $6,723$ consists of 6 bays 600.2 14.0 $8,332.$ $6,723$ 600.2 14.0 $8,332.$ $6,723$ 602.2 16.0 $8,332.$ $6,723$ 603.2 16.0 $9,179$ $10,053$ 604.2 18.0 $10,953$ $10,953$ 605.2 19.0 $11,878$ $12,828$ 606.2 20.0 $12,828$ $13,802$ 607.2 21.0 $13,802$ $14,800$ 607.2 22.0 $14,800$ $15,820$ 607.2 23.0 $12,520$ $14,800$ 610.2 24.0 $16,863$ $19,014$ 614.2 30.0 $23,567$ $25,763$ 614.2 35.0 $27,189$ $27,189$	595.2	9.0			1	3,014	Hangwood Of	4/0.	· ·
597.2 110 $5,253$ spillway section which 578.2 12.0 $5,962$ spillway section which 579.2 13.0 4,723 Cousists of 6 bays 600.2 14.0 7,513 Cousists of 6 bays 602.2 16.0 9,179 10,053 602.2 16.0 9,179 10,053 602.2 18.0 10,953 10,953 605.2 19.0 11,878 12,828 606.2 20.0 12,828 13,802 607.2 21.0 13,802 14,800 607.2 22.0 14,800 15,820 607.2 23.0 15,820 14,800 607.2 23.0 15,820 14,800 610.2 24.0 16,863 19,014 612.2 26.0 27,250 27,189 614.2 35.0 27,189 27,189	596.2	10.0				5022	# Way " 15	the bai	ŝ
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	597.2	110				59:23	soullway ser	too which	2
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	540.2	12.0				1. 773	consists of 6	baus	
600.2 14.0 601.2 15.0 602.2 16.0 602.2 16.0 602.2 16.0 602.2 16.0 602.2 17.0 602.2 17.0 602.2 18.0 604.2 18.0 605.2 19.0 605.2 19.0 606.2 20.0 606.2 20.0 607.2 21.0 608.2 22.0 608.2 23.0 610.2 24.0 610.2 24.0 612.2 26.0 612.2 26.0 612.2 26.0 612.2 26.0 612.2 26.0 612.2 26.0 612.2 30.0 23.567 25.763 614.2 35.0	399.2	13.0	I Y			7513			
601.2 15.0 $9,179$ 603.2 17.0 $10,053$ 604.2 18.0 $10,953$ 605.2 19.0 $11,878$ 606.2 20.0 $12,828$ 607.2 21.0 $13,802$ 608.2 22.0 $14,800$ 609.2 23.0 $15,820$ 610.2 24.0 $16,863$ 612.2 26.0 $17,014$ 612.2 23.0 $21,250$ 612.2 30.0 $23,567$ 618.2 32.0 $25,963$ 619.2 35.0 $27,189$	600.2	14.0)	8332			
632.2 16.0 $10, c53$ 604.2 18.0 $10, q53$ 605.2 19.0 $11, 878$ 606.2 20.0 $12, 828$ 607.2 21.0 $13, 802$ 607.2 22.0 $14, 800$ 607.2 23.0 $15, 820$ 607.2 24.0 $16, 863$ 612.2 26.0 $17, 90.14$ 612.2 28.0 $21, 250$ 612.2 30.0 $23, 567$ 618.2 32.0 $25, 963$ 619.2 35.0 $27, 189$	601.2	19.0			1	9179			
603.2 17.0 $10,953$ 604.2 18.0 $10,953$ 605.2 19.0 $11,878$ 606.2 20.0 $12,828$ 607.2 21.0 $13,802$ 608.2 22.0 $14,800$ 609.2 23.0 $15,820$ 609.2 24.0 $16,863$ 612.2 26.0 $19,014$ 612.2 28.0 $21,250$ 614.2 30.0 $23,567$ 618.2 32.0 $25,963$ 619.2 33.0 $27,189$	602.2	16.0		1		10.053			
604.2 16.0 $11,878$ 605.2 20.0 $12,828$ 607.2 21.0 $13,802$ 608.2 22.0 $14,800$ 609.2 23.0 $16,863$ 610.2 24.0 $16,863$ 612.2 26.0 $17,014$ 614.2 28.0 $21,250$ 618.2 32.0 $25,963$ 619.2 35.0 $27,189$	603.2	11.0				10.953			•
605.2 71.0 $12, 52.8$ 607.2 21.0 $13, 802$ 607.2 27.0 $14, 800$ 607.2 23.0 $14, 800$ 607.2 23.0 $15, 820$ 607.2 24.0 $16, 863$ 610.2 24.0 $16, 863$ 612.2 26.0 $17, 014$ 614.2 28.0 $21, 250$ 618.2 32.0 $25, 963$ 619.2 33.0 $27, 189$	604.2	10.0	{ {		1	11.878			
606.2 21.0 $13,802$ 607.2 27.0 $14,800$ 609.2 23.0 $15,820$ 610.2 24.0 $16,863$ 612.2 26.0 $19,014$ 614.2 28.0 $21,250$ 616.2 30.0 $23,567$ 618.2 32.0 $25,963$ 619.2 35.0 $27,189$	605.E	20.0			1 I	12.828			
607.2 27.0 $14,800$ 609.2 23.0 $15,820$ 610.2 24.0 $16,863$ 612.2 26.0 $19,014$ 614.2 28.0 $21,250$ 616.2 30.0 $23,567$ 618.2 32.0 $25,963$ 619.2 35.0 $27,189$	606.4	21.0		1 1	1	13.802			t,
609.2 23.0 $15,820$ 610.2 24.0 $16,863$ 612.2 26.0 $19,014$ 614.2 28.0 $21,250$ 616.2 30.0 $23,567$ 618.2 32.0 $25,963$ 619.2 35.0 $27,189$	607.2	220			1	14,800			-
610.2 24.0 V 16,863 612.2 26.0 19,014 614.2 28.0 21,250 616.2 30.0 23,567 618.2 32.0 25,963 619.2 35.0 27,189	605.6	22.0		11		15,820	·		
6/2.2 26.0 19,014 6/4.2 28.0 21,250 6/1.2 30.0 23,567 6/8.2 32.0 25,963 6/1.2 35.0 27,189	607.2 L 1A 7	24.0		1		16.863			
6/2.2 28.0 6/4.2 28.0 6/6.2 30.0 6/8.2 32.0 6/9.2 35.0	610 -	24.0		1 i		19.014			
6/4 2 6/6 23,567 6/8 23,567 25,963 6/9 23,567	Q16.6	28.0				21.250	,		
6/2.2 32.0 6/9.2 33.0 25,963 27,189		20.0			j.	23,567			
619.2 33.0 27,189	1107	30.0		1 1	1	25,963			
	(14 0	32.0	1	11		27.189			•

Ċ

F

Ż

.

Ĉ

PROJECT	COMP BY	JOB NO.
RATIN'S CURVE - Newfound Dam	JJD	2:74:
	CHK BY	DATE
DAM Over: lows	BTB	12-21-13

Dain overflow :

Ċ

Ŋ

•

0

....

C

Dam width already accounted for in weirs "A"+"B" +"C" = 73.2 ft - remainder of dam acts as a broad-crested weir upon overflow (110'-73.2' = 36.8 ft) Overflow over dam discharge determined below :

Elevation	1		_		1	
(F1)	н	L C	4	0		
592.4.	0		36.8	0	T	
593.4	1.0	2.63	36.8	97		Overlank flow estimate
594.4	2.0		:	274	0	
595.4	3.0			503	Kh.	Q= 1.486 AR 43 5 12
596.4	4.0			174		<u>n</u>
597.4	5.0			1,082	17	at elev 600', A = 1(25')(7.6) + 1(7.6)(1.0)
598.4	6.0			1,422	9	
599.4	7.0			1,793	-7	$A = 589 ft^2$
600.4	8.0			2,190	1	P = 130+26 = 156
601.4.	9.0			2,613	17	R = 3.776 R48 = 2.424
602.4	10.0			3,060	6	S = .0095 (from US65 mp
603 4	11.0			3,531		5 ^{1/2} = , 097
604.4	12.0			4,023	17	η = .065
605.4	13.0			4,537	4	Q = 3,166 efs
606.4	14.0			5,070	4	
607,4	15.0			5,623		al elev 620', A = 589 + 1(20)(80)
608 4	160			6,194	17	
609.4	17.0			6,784	14	$+ \frac{1}{2}(180)(20) = 318$
610 4	18.0			7, 391		6
612 4	20.0			8,657	4	P=156+181+82=419
614.4	22.0			9,987	6	R = 7.610 R ⁴² = 3.869
616.4	24.0			11,379	17	5 ⁿ = .097
618.4	26.0		\mathbf{N}	12,831	15	Q = 27,361 cfs
620.0	27.6		V	14,033	16	
	6.0					Assume a linear rating curve for
						OKTLOW



Ċ ******** (c LOCAL ISANE C **IPRT NSTAN** c INAME ******** **I**SNOW C ROUTING OF PMF THPU NEWFOUND LAKE FOR STUDY OF JPC DAMS JPHT TPLT HATIO 0000.0 • ROUTING OF PMF AND 1 PMF FLOODS SUP-AREA RUNNEE COMPUTATION TMIN METRC . JPL T С С JOH SPECIFICATION 0.00 THSPC HYPROGRAPH DATA LMZ C С THRU NEWFOUND LAKE ****** 1/2 PMF INFLOW HYDROGRAPH TO NEWFOUND LAKE Istaq Icomp Ifcon Itape I HR c 1450A 0.00 JOPFR m, Ì c TDAY С C.O.E. NAM INSPECTION PROGRAM SNAP 0.00 N L WN JOH NO. PAT49-AT AND AA С ******* 95.00 TARFA AHN V 100 Cz C о ЛUнс ----VEHSION DATED JAN 1973 ******************** ***************** IHYDG ī ********* ŕ FD AUG 74 D-13 IPC Lower Dam . NO. 01

Ĵ • C Ì • ŕ

HYTPPOLTING THRU NEWFOLIND LAFF POUTING THRU NEWFOLIND LAFF 100 1 0 0 0 1 0 0 1 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 1 0 0 0 0 0 0 0 0 0 0		*		*	*	*****		* * * *	• •	•		
HOUTING THUL NEWFOLUND LANF 100 1 0 0 0 0 0 0 0 0 0 0 1 0 0 1 0 0 1 0 0 1 0					HY04044	TUNA HAAR	5NG					
100 1 0	HOUTING	THPU NF	WE NUNI	D LAKF		TADE	1	100				
Anuliva nata aloss closs ave ipts isame n.n n.nn n.nn 1 n NSTPS NSTDL Lac амбык x TSK STUHA n n n 0.nnn 0.nnn 3547n. 11014. 2923. 5000. 10310. 16000. 11700. 146000. 171000. 220 -0 11014. 2923. 5000. 10310. 16000. 20117. 35687. 52028. 71102. 80		-	001		c							
-14 NSTPS NSTDL Lac AMSKK X TSK STUHA NSTPS NSTDL Lac AMSKK X TSK STUHA N n n n 0.000 35470. 17100. 17100. 220 1014. 2923. 5980. 10310. 16009. 20117. 35687. 52928. 71192. 89				55070	CLOSS	TING DATA AVG	1 PF S	ISAME				
истре NSTPG NSTDL Lac дискк x TSK STUHA n n n 0.000 35470. LOve 101A. 40000. Sand. A7000. H2000. 94000. 117000. 11000. 220 -1 -1 -1				0 ° 0	0 " 0 " 0	U U	-	c				
асте 23000. 40000. 5900. 67000. H2000. 94000. 117000. 146000. 171000. 720 LOve 1018. 7923. 6980. 10310. 16009. 70117. 35687. 52928. 71192. 89 -1		V: Z	TPS C	NSTOL	50 1	AMSKK 0 • 0 0	0000°0	15K 0.000	5704A	_		
D-14	.ACFE 23000. 4	.0000	1085 103		47000. 10310.	42000. 14009.	94000. 20117.	117 35	000. 687.	146000. 52928.	171000.	0 4 4 0 8
	D-14											

				∿, " ", " ¥, " ₩, " ₩, " ₩, "		· · · · · · · · · · · · · · · · · · ·	
		-					
Ē							5
Ν							
		• • • •			•		
		0					
-							P
	-						
			• • • • • • • •				
		0					
Į							
		- • • • •					
		•••			·		
C							
		121					
	° C		-				
ka nata P		у • • • • Ц • Ш Ф — н					
	z	500					
	C I						
	S	••••	• • • • • • •				
							.
		ຢ ູ ∙ ∙ <u>ຼ</u> ∙	•••••••				
		• •	•				
			-				
-		000		<u>.</u>			
E		Ā	°°0				
			c o				
			0 0				
		0	-				
		<u>م</u> م	•	D-15			P
		5 5 5	-		IPC Lower Dam		
		0-1-4	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~				
L •		• • • • • • • • • • • • •					·····





					Ì	F_
	ARFA 95.00 95.00			•		
• •						
	72-HOUR 3raar 17224					Ī
• • •						
ć	24-HO					ľ
	114000. 28772.					
ā	005					
	F					E
	HAPH A					
·	HYDROG HOUTED	· · ·				
						Ē
		D-16	IPC Lower Dam			
 			······································		· • • • • • • • • • • • • • • • • • • •	

E ć • INFLOW(I). OUTFLOW(O) AND ORSERVED FINW(.) - JODOD. 40000. 50000. 60000. 100 STATION **U** 20000. -C ċ 10000. È C

Ε.

FLOW
AVERAGE
SUMMARY.
RUNOFF

c. .

|. |--

ľ

72-HOUP ARF/ 19548. 95.00 8112. 95.00
74-HOUR 24044. 9905.
6-40UR 51519. 11949.
PFAK 57000. 12117.
100 100
HYDROGRAPH AT Houten to

IPC Lower Dam

D-18

PROJECT ODE DAM INISPECTION PROSRAW!	COMP BY	JOB NO. 20799 -07
TPC Lower Lan	CHK BY BT B	DATE 12 - 21 - 78

Spillway Capacity of IPC Lower Donn

The only spillway provided at the Lower IPC Dam is the stop-log spillway. The spillway consists of 18 stop-log sections measuring 4th ft wide by 5.7 high, the height Levis measured to the top of the stop-log supports. Average neight from spillway crest to top of dom is 7ft. Individual section capocity is determined below

H	C	L	φ	H	C	<u> </u>	Q
0,5	3.25	4.5	5.2	4.0	3.73	4.5	134
1.0	3.41	**	15	4.5	49	4	160
1.5	3.57	*	30	5.0	4	4	188
2.0	3.65	•	46	. 5.7	**	•	228
2.5	3.70	11	66	6.0	**	••	247
3.0	3.72	"	87	7.0	4		311
3.5	3.72	•	110	8.0	**	4	38 0
•	-			10.0		٩	531

Note: "C" values from "Handbook of Hydraulics", King & Brater, Table 5-11 (1) Total capacity = 18×311 = 5,600 cfs (2) Spillway capacity at inspection = 311 + 255 = 570 cfs (others spen to an arg. (3) " with all stoplags in place (H=.63) = 130 cfs of 1.0 ft)

Inflow from remaining 1.1 square miles = 1,320 cfs for PMF (660 cfs for 12 AMF)

PMF = 28,722 + 1320 = 30,000 cfs 1/2 PMF = 12,117 + 660 = 12,780 cfs

Spillway is capable of possing 19% of the PMF and 44% of the 2PMF without overlopping. However, the PMF is approximately equal to PMF + flow from dam failure. The IPC Lower Dam is not a hydraulic control once overbank flow occurs upstream of the dom and reservoir. The valley section, and to a much lesser extent, the highway (Rt. 3A) grade, will control flow in the valley. The river makes a 90° bend just above the dam. The overbank flow will flow around the dam to the North and eventually to the south.

PROJECT	COMP BY JJD	JOB NO. 20799 - 07
	CHK BY BTB	DATE 1-2-79

E

F

-

ŕ

Upstream of the IPC Lower Dain, the Newtound River flows in a relativities widers and steep valley section. Just opstream of the dans, the valley surdrist widers considerably. The IPC Lower Dain sits hyper tran the flood plain to the north. The rough sketch below shows a plan view of the valley. It is estimated that overbank flow begins to occur at a flow rate of about 2,000 second feet in the narrow valley section just upstream of the dam.

-SECTION The x-section location is shown by a dashed line. This x-section is used to determine height of PMF and 12 PMF Flows. D-20 **IPC Lower Dam**





r Nujeui	- UUHI U I	u 100 mu.
	JJD	2=770 117
	CHK BY	DATE
	BTB	1-2-70

A PRIF of 30,000 cfs would overtop the days by 4.4 ft and a 1/2 PMF of 12,780 cfs would overtop the days by 0.8 ft.

The spillway should not be considered seriously inadequate according to the guidelines of ETL 1100 - 2 - 234 because failure from overtopping would not significantly increase the downstream hazard above what it was just before failure occurred. A major flood would be occurring in the valley at the time overtopping occurs. Flow at top of dam, including the flow that would be occurring north of the dam, amounts to about 10,000 cfs. This represents a very significant flood event downstream of the dam.

In addition, based on conversations with the owner, there is evidence that the spillway section becomes submerged at high flows - flows that utilize most of the spillway capacity. In comparing stojes of the flood flow from failure at the dam (using "33 H) and at a cross-section 100° below the dam, no evidence of submergence caused by backwater effects was recognized However, these stage estimates are very rough and do not provide a detailed picture.

D-23
PROJECT	COMP BY	JOS NO.
COE UNIT INSPECTION PROSEDUM	JJD	20797-07
LOW, UN TPC DAM	CHK BY	DATE 12-12-78

DAM FAILURE ANALYSIS

Ê

.

E

.

C

I

.

Ë

- a) Reservor storage at time of failure, 5 S = 2.8 acres × 11.1 ft = 31 acre-feet
- (100.4 89.3) = 11.1'

b) Peak Failure Outflow $Q_{p1} = \frac{8}{27} N_b T g Y_0^{3/2}$ $Y_0 = 100.4 - 86.0 = 14.4 \text{ ft}$ $W_b = 38 \text{ ft} (.4 \times 95 \text{ Ft})$ $Q_{p1} = 3,491$

A dam breach would most likely secur by failure of the timber crib due to loss of foundation material.

Normal perating procedure for the IPC Lower Dam consists of keeping the stop-logs in place to maintain Maximum head for power production. Evidence at the dam indicates that flow has occurred over the top of the stop-logs during this operational procedure. In anticipation of high Nows, spillway stop-logs are removed to prevent overtopping.

With water surface at top of dam and dam in the condition observed during inspection, discharge from the dam would be

through open port, Q = 311 second-feet
 over spillway section.
 avg. H = 1.0'; L = 76.5'; C = 3.41; Q = 260 cfz
 GTOTAL = 570 cfs

With water surface at top of dam, and stop-logs removed

 $Q = 18 \times 3.73 \times 7^{\frac{3}{2}} \times 4.5 = 5,595 \text{ cfs}$

With stop-logs in place, there is very little freeboard existing between the top of stop-logs and the walkway. Nith water at top of dam, some overtopping dong reservoir shoreline would occur.

Time for reservoir to empty :

 $T = \frac{12.1 \text{ S}}{\frac{1}{2} \text{ Qp}} = .21 \text{ hrs } \cong 13 \text{ minutes}$

D-24

IPC Lower Dam

$$S = 31 \text{ acre - feet}$$

$$g_{p1} = 3,491 \text{ cfs}$$

$$frial stage = (475.1 - 468.0^{11}) = 7.1 \text{ ft}$$

$$V_{1} = \left(\frac{758 + 592}{2}\right) \times 900 \times \frac{1}{43,560} = 14 \text{ acre-feet}$$

$$q_{p2} = 3491 \left(1 - \frac{14}{31} \right) = 1,914$$
 efs

Ê

È.

F

C

İ

.

;

5

È

$$V_2 = \left(\frac{380 + 500}{2}\right) \times 900 \times \frac{1}{43,560} = 9.1 \text{ A-F}$$

$$V_{AVE} = 11.6 \ A-F$$

 $Q_{2A} = 3,491 \left(1 - \frac{11.6}{31}\right) = 2,185 \ cfc$
 $Stage = (474.2^{4/2} - 468^{-4/2}) = 6.2 \ Ft$

C) C cross - section, #25 (~ 1,500 downstream, of dam)

$$Q_{2A} = 2,185 \text{ cfs}$$

thial stoge = (463.2 - 459⁻¹¹) = 4.2 ft
 $V_1 = \left(\frac{418 + 872}{2}\right) \pm 500 \times \frac{1}{43,560} = 7.4 \text{ A-F}$
 $q_3 = 2185 \left(1 - \frac{7.4}{31}\right) = 1,663$
 $V_2 = \left(\frac{351 + 692}{2}\right) \times 500 \times \frac{1}{43,560} = 6.0 \text{ A-F}$
 $V_{ave} = 6.7 \text{ A-F}$
 $Q_{2B} = 2,185 \left(1 - \frac{6.7}{51}\right) = 1,712 \text{ cfs}$
 $stage at k-sect 28 = (462.911 - 45911) = 3.9 \text{ ft}$

The peak has dropped sufficiently below general flood level to cease posing a significant hezard (general flood level = 2,000 to 2,500 che according to N.H. Water Resources Board personnal).

All elevations contained in the dam failure analysis were obtained by setimating cross-section streambed elevations from 1" & I mile USES quadrangies and are not directly related to actual elevations of the dam!

PROJECT	COMP BY	J03 NO.
	ここと	10772-57
	CHK BY	DATE
		2-13-75



<u>General</u>

•

r

1

From conversations with personnel of the New Hompshire Water Resources Board, twas determined that general flooding begins 21 flows of about 2,000 to 2,500 cfs in the reach below the IPC Lower Dam. As shown in the above hydrographs, below Z-sect #28, no significant flooding would occur. There may be possibility of some localized, minor damage occurring; however, a extremely datailed analysis would have to be undertaken. Above Z-sect #28, some general flooding occurs. However, flood discharges are maintained for less than ~8 minutes. Maximum flood levels from failure would occur just downstream of the dam and would be opproximately 2 to 3 feet. There are no residences located in this area. Within 1,000 feet of the dami, the flood peak from failure has diopped sufficiently to cease posing a significant hozard, although some minor flooding may still occur.

HAZARD CLASSIFICATION - "SIGNIFICANT": No more than a few inhabitable structures, some notable economic losses

D-26

IPC Lower Dam







APPENDIX E

F

.

.

Ê

Information as Contained in the National Inventory of Dams





9-85

DTIC