



1. 1. 1.

MicReargev, RESOLUTION, TEST 1995.



SECURITY CLASSIFICATION OF THIS PAGE	110-11/68 658
REPORT DOCUMENTA	
la. REPORT SECURITY CLASSIFICATION Unclassified	1b. RESTRICTIVE MARKINGS
2a. SECURITY CLASSIFICATION AUTHORITY	3. DISTRIBUTION AVAILABILITY OF REF Approved for public release; distribution is unlimited
25. DECLASSIFICATION/DOWNGRADING SCHEDULE	
4. PERFORMING ORGANIZATION REPORT NUMBER FPO-1-85(12)	5. MONITORING ORGANIZATION REPORT #
6a. NAME OF PERFORM. ORG. 6b. OFFICE SYM Ocean Engineering & Construction Project Office CHESNAVFACENGCOM	7a. NAME OF MONITORING ORGANIZATION
6c. ADDRESS (City, State, and Zip Code) BLDG. 212, Washington Navy Yard Washington, D.C. 20374-2121	7b. ADDRESS (City, State, and Zip)
Ba. NAME OF FUNDING ORG. 8b. OFFICE SYM	9. PROCUREMENT INSTRUMENT INDENT #
Bc. ADDRESS (City, State & Zip)	10. SOURCE OF FUNDING NUMBERSPROGRAMPROJECT TASK WORK UNITELEMENT ##ACCESS #
11. TITLE (Including Security Classificat Cable Terminations for the BSURE Terminal Review Team Report 12. PERSONAL AUTHOR(S)	•
13a. TYPE OF REPORT 13b. TIME COVERED FROM TO	14. DATE OF REP. (YYMMDD) 15. PAGES 85 201
16. SUPPLEMENTARY NOTATION	
	CT TERMS (Continue on reverse if nec. installation, retrieval & repair,
BSURE	
	ssary & identify by block number)
BSURE 19. ABSTRACT (Continue on reverse if neces The purpose of this report is to document Barking Sands Undervater Range Expansion	the efforts and analyses of the (BSURE) In-water System Replacement
BSURE	the efforts and analyses of the (BSURE) In-water System Replacement Air Systems Command, AIR-630 letter by NAVAIR message 2271220Z of (Con't

ر با الا

BLOCK 19 (Con't)

27 Jan 1982. The DRT was tasked to investigate in detail the redesigned BSURE cable termination to determine its mechanical and electrical adequacy for use in the BSURE cable replacement project. A team consisting of representatives from PACMINSTESTCEN (PMTC), CHESNAVFACENGCOM (CHESDIV), and NUSC conducted a design review of the TATU cable termination seals to be used in the BSURE replacement program.

This is the Design Review Team Report on the Redesigned SD Cable Termination for the BSURE Terminal and Transmission Units (TATU) used in the Barking Sands Underwater Range Expansion In-Water System Replacement Program. The Design Review Team included representatives from the Chesapeake Division, Naval Facilities Engineering Command (CHESNAVFACENGCOM), Washington, DC, the Naval Underwater Systems Center (NUSC), Newport, RI, and the Pacific Missile Test Center (PMTC) at Point Mugu, CA.

Each member organization and its representatives prepared and contributed data contained in this report. The Design Review Team Report was prepared for publication by Chesapeake Division, Naval Facilities Engineering Command, Washington Navy Yard, Washington, DC.

Contributors to this report are R. L. Cox and A. McNairy of CHESNAVFACENGCOM; G. Nussear, R. Polley and Mike Ho of PMTC; R. Ricci and J. A. Millard of NUSC; G. Merry of NOSC; G. MacKenzie of NSWC; Delco Electronics, Santa Barbara, CA; and Columbia Research Corporation, Arlington, VA.

i

PREFACE

CABLE TERMINATIONS FOR THE BSURE TERMINAL AND TRANSMISSION UNITS (TATU) DESIGN REVIEW TEAM REPORT

TABLE OF CONTENTS

•	

Page

`odes _ or

PREFACE					
TABLE OF CONTENTS					
LIST OF ILLUSTRATIONS					
CHRO	NOLOG	Y OF EVENTS	v		
1.0	INTR	ODUCTION	1		
	1.1	Purpose	1		
	1.2	Background	1		
	1.3	Scope	2		
2.0	DESI	GN DESCRIPTION	2		
3.0	INVE	STIGATIONS AND DISCUSSIONS	9		
	3.1	Investigation of Existing Seal Failure Rate Data	9		
	3.2	Investigation of Quality Requirements for Seal Mating Surfaces	9		
	3.3	Investigation of Program Quality Assurance Requirements	9		
	3.4	Tolerance Study, Redesigned Termination Seals	10		
	3.5	Failure Modes and Effects Analysis (FMEA), Redesigned TATU	10		
		Seals			
	3.6	Reliability Analyses, Old and Redesigned TATU Seals	11		
4.0	RELL	ABILITY ANALYSIS AND INTEGRATED TEST PROGRAM FOR THE	13		
	REDE	SIGNED BSURE TERMINATION			
	4.1	Reliability Analysis	13		
		4.'.l Assumptions	13		
	4.2	Reliability Analysis (Success States)	14		
	4.3	Reliability of the Redesign	14		
		ii			

TABLE OF CONTENTS (Continued)

Carlo and the

كحكمت

27

Q

Ķ

.

ľ

Ľ

.

۲.

ŧ

			Page
5.0	RELIAE	ILITY ANALYSIS OF BSURE IN-WATER ELECTRONICS	15
	5.1 R	eliability Analysis Study	15
6.0	COMPAR	ISON OF CHESNAVFACENGCOM (PARAGRAPH 3.6) AND NUSC	15
	(PARAG	RAPH 4.0) ANALYSES	
	6.1 0	Comparison Assumptions	15
	6.2 0	riginal Design/Redesign Block Diagrams	15
	6.3 P	articipants' Conclusions	15
7.0	CONCLU	SIONS	16
8.0	RECOMM	ENDATIONS	16
Арре	ndix A	Excerpts from the Minutes of BSURE Replacement Program	A-1
		Final Design Review Meeting, 13-14 Jan 1982	
Арре	ndix B	NUSC Comments on BSURE Redesign Documentation	B-1
Арре	ndix C	BSURE Cable Termination CHESNAVFACENGCOM Tolerance Study,	C-1
		Dec 1981	
Appe	ndix D	Pacific Missile Test Center Tolerance Study, BSURE Plug-In	D-1
		Termination	
Арре	ndix E	BSURE SD Termination Seal Tolerance Study	E-1
		(Delco Electronics)	
Арре	ndix F	Failure Modes and Effects Analysis of BSURE Connector	F-1
		Sealing System by Pacific Missile Test Center	
Арре	ndix G	Minutes of BSURE Replacement Preliminary Design Review	G-1
		Meeting, 5 Nov 1981	
Appe	ndix H	Reliability Analysis and Integrated Test Program for the	H - 1
		BSURE Termination	
Appe	ndix I	Design/Redesign Block Diagrams for Leak Path Reliability	I-1
		Analysis, CHESNAVFACENGCOM	

i i i

· . 1

LIST OF ILLUSTRATIONS

Page

Ľ

.

<u>`</u>

Ċ

•--

.

Figure l	BSURE System	3
Figure 2	Original Design Termination Cross Section	4
Figure 3	Redesigned Cable Termination Cross Section	5
Figure 4	Termination Showing Unmated SD Cable Termination	7
	and Gimbal Assemblies (External Rubber Boot Not Shown)	

CHRONOLOGY OF EVENTS

THE BARKING SANDS UNDERWATER RANGE EXPANSION PROGRAM

- 1972 Requirement for 1000 square nautical mile (nm²) range established by CINCPACFLT
- 1976 Installation of 1000+ nm² range completed by PMTC
- 1977 TATU failure in April...TATU failure in September reduced area to 850 nm²
- 1979 TATU failure in February reduced area to 750 $nm^2...TATU$ failure in September reduced area to 550 nm^2
- 1981 TATU failure in July reduced area to 535 nm²
- 1981 25-26 August, BSURE In-Water System Status Meeting
- 1981 5-6 November, BSURE In-Water System Replacement Preliminary Termination Redesign Meeting
- 1981 December, BSURE Replacement Cable Termination Redesign Tolerance Study
- 1982 13-14 January, BSURE Replacement Program Termination Redesign Final Design Review Meeting
- 1982 Failure Modes and Effects Analysis of Redesigned BSURE Termination Sealing System
- 1982 Reliability Analysis of the BSURE Redesigned Termination and Integrated Test Program for the In-Water System Replacement Program
- 1982 Comments on BSURE Termination Redesign Documentation
- 1983 Reliability Analysis of BSURE In-Water Electronics

1.0 INTRODUCTION

1.1 <u>Purpose</u>. The purpose of this report is to document the efforts and analyses of the Barking Sands Underwater Range Expansion (BSURE) In-water System Replacement Design Review Team (DRT) formed by Naval Air Systems Command, AIR-630 letter 630-SL-027 of 5 Nov 1981 and additionally by NAVAIR message 271220Z of 27 Jan 1982. The DRT was tasked to investigate in detail the redesigned BSURE cable termination to determine its mechanical and electrical adequacy for use in the BSURE replacement project. A team consisting of representatives from PACMISTESTCEN (PMTC), CHESNAVFACENGCOM (CHESDIV), and NUSC conducted a design review of the TATU cable termination seals to be used in the BSURE replacement program.

1.2 Background. Requirements established by CINCPACFLT in the early 1970's resulted in the installation of the 1000 nm² Barking Sands Underwater Range Expansion (BSURE) in 1976 to support underwater tracking of participants in large scale, free-play, multiple-threat AAW, ASW, and ASUW exercises. The BSURE In-water System is comprised of two instrumented cable strings connected to shore. Each string is a series of sensors (multiplexed onto a single type SD coaxial cable) each consisting of a tethered hydrophone above a cable Terminal and Transmission Unit (TATU). BSURE termination failures by 1991 had reduced the operating area to 530 nm^2 , and further failures would have reduced the area even more. Incident to these TATU failures, COMTHIRDFLT and CINCPACFLT reiterated requirements for the original 1000 nm² tracking range. Over one-half of the TATUS have been recovered and the failures analyzed. The failures were caused by water leakage in the TATU cable termination seals and were attributed to design/manufacturing deficiencies. The deficiencies were identified, and the cable terminations were redesigned to reduce both the cause and effect of the seal failures.

1.3 <u>Scope</u>. The Design Review Team (DRT) was formed to determine the adequacy of the BSURE electronics design and the redesigned BSURE TATU termination design. The first task undertaken was the review of the failure modes and effects analyses (FMEA) of the cable termination redesign prepared by PMTC. The scope broadened as related components became involved and ultimately included the following:

- Failure mode and effects analysis (FMEA) of the redesigned TATU termination seals;
- o Investigation of existing seal failure rate data;
- o Investigation of quality requirements for seal mating surfaces;
- o Investigation of program quality assurance requirements;
- o Tolerance of redesigned TATU termination seals; and
- o Parametric reliability analysis of the old and redesigned TATU termination seals.

2.0 DESIGN DESCRIPTION

ſ

Ľ

The purpose of the BSURE In-water System Replacement program is to replace the existing degraded and failing BSURE in-water system (Figure 1) with an improved system that would function maintenance-free for a period of 20 years. An important aspect of the replacement system is a redesigned cable-to-TATU termination that provides significantly improved sealing capabilities. As originally designed, the termination (Figure 2) did not provide adequate protection against seawater entering through the cable core or sheath when the outer insulation jacket is cut. The termination redesign (Figure 3), developed and tested by the Pacific Missile Test Center, Pt. Mugu, CA, and Delco Electronics, Santa Barbara, CA, has been shown to protect against these conditions in laboratory simulation tests. The redesign has three features which constitute a significant improvement over the original design: concentric electrical feed-throughs; redundant seals; and pressure equalizing oil-filled cavities.

1000 SQUARE MILES

-

1....



TERMINATION BULKHEAD PARTS & GIMBAL (SHORE END)

TATU WITH ELECTRONICS OUTER SD CABLE BULKHEAD TERMINATION & GIMBAL PARTS (SEA END)

TATU KIT

(REPEATER KIT - SAME, EXCEPT BULKHEADS ARE IDENTICAL

AND NO HYD/FLOAT ASSEMBLY)

Figure 1. BSURE System





ŧ.

In the original design, the copper ground sheath was attached to an offcenter pin connected to the coiled cable assembly through a Morrison seal. A leak path developed through this seal as a result of torque experienced by the termination. The torque caused relative rotation between the termination housing and the Morrison seal which in turn caused the pin to move inside the seal. A cable outer jacket leak eventually caused the seal to develop a leak along its interface with the pin which culminated in failure of the termination. In the redesign, the eccentric pin has been eliminated by removing the outer insulating jacket of the SD cable where it enters the termination unit. The copper ground sheath has been folded back and clamped to the metal housing of the TATU to assure reliable grounding of the ground sheath without off-center penetration of the seal.

The redesign intrinsically is more reliable than the original design because it incorporates more redundancy to obtain improved sealing characteristics. In the original design, failure of a single seal could result in failure of the termination unit.

In both the original TATU and the redesign, the termination interconnect housing is filled with castor oil. The redesign, however, provides a mechanism for the oil cavities to be self-pressurizing to the ambient pressure thus reducing the pressure differential across most seals to zero. The oil-filled termination is pressure-balanced by using the gimbal and termination housings as a piston and cylinder, respectively. An air cavity still exists within the cable core, and the differential pressure between the ocean and this cavity (which is at atmospheric pressure) could drive oil into the cable interstices; however, two Morrison seals prevent this from happening.

As shown in Figure 4, the termination consists of two mating assemblies: an SD cable termination assembly and a gimbal assembly. In this figure, the SD

-6



-

....

.

L

Figure 4. Termination Showing Unmated SD Cable Termination and Gimbal Assemblies. (External Rubber Boot not Shown).

cable enters the termination housing from the left. The outer sheath is removed and the copper ground sheath is folded back and clamped. Seawater is in contact with the copper ground sheath at this point. An underlying polyethelyne dielectric protecting the signal carrier is passed through a pair of Morrison seals separated by castor oil. The polyethelyne dielectric is then passed through the load-bearing insulator and terminates within the load-bearing plate. At the termination of the polyethelyne dielectric the high-voltage copper sheath is exposed and secured to the load-bearing plate by a copper compression fitting. An electrical conduction path is established through this fitting, through the steel load-bearing plate, and then through the strength terminator encasement to the center contact. This contact is achieved through use of a Multilam Band (see accompanying detail in Figure 4), designed and patented by Brown Boveri Co. of Switzerland. The Multilam Band is a flat band formed into a cylindrical shape from heat-treated beryllium copper. The material is processed to provide multiple louver-shaped spring contacts at the mating interface. Thus, a highly reliable electric connection is formed with multiple contacts operating at thousands of pounds per square inch.

The termination also provides a mechanical load transfer between the SD cable and the TATU housing. Axial strength is required during deployment and recovery operations to support the cable in 15,000 feet of water. The rated breaking strength of the cable is 16,000 pounds.

When the two assemblies are mated, an electrical path is completed through the gimbal center contact and the core of the gimbal interconnect cable into the TATU. The assembly ring secures the two termination assemblies and permits relative linear motion to achieve pressure equalization. The male and female isolation tubes (MITs and FITs) are designed with band seals which permit

pressure equalization between the two oil cavities while preventing an electrical path to be completed between high voltage and ground. The outer gimbal boot is also oil-filled as shown on Figure 3.

3.0 INVESTIGATIONS AND DISCUSSIONS

3.1 <u>Investigation of Existing Seal Failure Rate Data</u>. An exhaustive search was conducted by the DRT members to acquire data such as manufacturers' test reports and test reports on other systems using Morrison seals in order to establish a failure rate. No meaningful data was found (see Appendix A, Item 6). This obstacle was overcome by using the failure rate of the old seal design.

3.2 <u>Investigation of Quality Requirements for Seal Mating Surfaces</u>. To support the reliability findings of the analysis, NUSC investigated the quality requirements for the machined seal mating surfaces. The investigation (Appendix B, Item 6) indicated that the specifications on the drawings, which control the actual quality during manufacture and inspection, were inadequate in not quantitatively specifying the limits on acceptability. Drawings were annotated: "Indicated surfaces are sealing surfaces and shall be free of axial scratches or other imperfections detrimental to sealing."

Difficulties of this nature would be eliminated by the quality assurance program recommended by the DRT.

3.3 <u>Investigation of Program Quality Assurance Requirements</u>. Preliminary investigations performed by CHESNAVFACENGCOM indicate that:

o The design is well within state-of-the-art manufacturing techniques and practices.

- o It is undetermined if the design is conducive to evaluation tests at various levels of assembly.
- o It is undetermined if the design is overly sensitive to the skill level/ motivation of assembly personnel.
- o An integrated test plan is needed.

CHESNAVFACENGCOM recommended (Appendix A, Item 10) that a Quality Management Team (QMT) be established to oversee the quality assurance program for the BSURE replacement effort. The QMT would assess requirements in areas such as configuration management, documentation, manufacturing, assembly and test.

3.4 <u>Tolerance Study, Redesigned Termination Seals</u>. CHESNAVFACENGCOM performed an initial tolerance study (Appendix C) in December 1981 to determine to what extent it was possible for component part tolerances to build up to the point where the redesigned seals would no longer fit properly. The results indicated that there was a remote possibility for this situation to occur, but that the tolerance changes required to eliminate this were minor; NUSC confirmed this possibility. One solution was that in the event the situation should occur during assembly, resolution would be to interchange parts to provide an adequate seal. This solution was ruled out in favor of changing the drawings to reflect the required tolerance changes because production had not yet begun. CHESNAVFACENGCOM's initial tolerance analysis was checked by PMTC (Appendix D) and DELCO (Appendix E) confirmed the tolerance problem. A final analysis based on the latest drawings was performed by DELCO, PMTC's contractor.

3.5 <u>Failure Modes and Effects Analysis (FMEA), Redesigned TATU Seals</u>. The PMTC team prepared a FMEA (Appendix F) on the TATU connector redesign and the old TATU seals. A FMEA is intended to:

o Examine all potential failure modes and their causes.

- o Assess the reliability status of the various elements of the system.o Assess the effect of each failure mode on system operation.
- Indicate any need for design modification (based on facts disclosed under the items above).

The FMEA answered these items and was centered on possible failure modes, except that it did not determine the reliability of the seal redesign. The FMEA did provide the DRT with insight to the reliability problem and served as a base to determine what other analyses would be necessary.

3.6 <u>Reliability Analyses, Old and Redesigned TATU Seals</u>. Since independent historical seal failure data could not be found, the DRT made an engineering judgement that analyses comparing the actual old seal failures to the predicted redesign seal failures would be the most practical approach to determine the reliability of the seal redesign. CHESNAVFACENGCOM performed a reliability analysis in November 1981. NUSC performed a similar analysis using a slightly different equation. A comparison of the results of the old seal and redesign seal analyses by both team members (Appendix G, Item 7; Appendix A, Item 8) indicates that the redesigned seal intrinsically is 100-500 times more reliable than the old design. Pertinent details of the analyses are presented below.

<u>Assumptions</u>: Due to the lack of applicable data for elastomeric seals (paragraph 3.1), the following simplifying assumptions were used to govern the approach to the analyses:

o <u>Constant Failure Rate for Morrison Seals and O-Rings</u>. It is assumed the Morrison seals and O-rings have a constant failure rate. This assumption is frequently employed in reliability analyses and very little error is caused by its use.

- <u>Identical Failure Rate for all Seals</u>. Because applicable failure rate data was not available, it was assumed that all seals have identical failure rates. There are similarities in the design, elastomeric composition, application, and environment of all the seals. Both designs employ both types of seals. It therefore appears that this assumption is valid for these analyses.
- Negligible Effects Due to the Oil. The effects of castor oil on the failure rate of the seals were disregarded in these analyses. As an engineering judgement, it is believed that the use of oil in the redesign will have beneficial effects on the reliability of the remination unit seals. In the redesign, the oil is pressurized to ambient causing a zero-pressure differential across most of the seals. Therefore, the actual reliability of the redesign will be better than the results of these analyses indicate.

Approach to Analyses:

- o Assess the reliability of the old seals, based on 1,947,640 hours of actual operation, and predict the reliability of the old seals over a 20-year period.
- o Then, using the same failure rates as used for the old seals, predict the intrinsic reliability of the redesigned seals over a 20-year period.
- o Then compare the results of the two analyses to determine if the seal redesign is intrinsically more reliable than the old design.

<u>Results</u>. A comparison of the results of the analyses indicates that the seal's redesign is 100-500 times more reliable than the old design. Comparison tables are presented in Appendices H and I.

4.0 RELIABILITY ANALYSIS AND INTEGRATED TEST PROGRAM FOR THE REDESIGNED BSURE TERMINATION

4.1 <u>Reliability Analysis</u>. Columbia Research Corporation (CRC) conducted a reliability analysis of the termination for NUSC (Appendix H). In this analysis, reliability equations for the redesign and original termination designs were developed from system block diagrams and success state tables. The equations were solved for hypothetical reliability values of Morrison seals and 0-rings. A comparison of the reliability performance characteristics of the redesign and original designs was then made. This comparative analysis confirmed the superior reliability performance of the redesign.

4.1.1 <u>Assumptions</u>. Due to the lack of applicable reliability data for elastomeric seals, the following simplifying assumptions were used to govern the approach of the reliability analysis:

- o <u>Constant Failure Rate for Morrison Seals and O-Rings</u>. The first assumption made for the analysis is that the Morrison seals and O-rings have a constant failure rate. This assumption is frequently employed in failure rate analyses and very little error is caused by its use.
- o <u>Identical Failure Rate for all Seals</u>. The second assumption is that all seals, Morrison seals and O-rings, have identical failure rates. This assumption was made because actual failure rate data for these components could not be located. Since there are similarities in the design, elastomeric composition, application, and environment of both Morrison seals and O-rings, and since both the original and modified designs employ both types of seals, it appears this assumption is valid for a comparative analysis.

Negligible Effects Due to the Oil. In this analysis, the effects of castor oil on the failure rate of seals have been neglected. It is generally believed that the use of castor oil in the redesign will have beneficial effects on the reliability of the permination unit. In the redesign the oil is pressurized to ambient causing a zero-pressure differential across the seals. The reliability analysis neglects this effect. It is therefore felt that the actual reliability performance of the new design might be better than predicted.

4.2 <u>Reliability Analysis (Success States)</u>. The block diagram for the original design and the redesign had been prepared by CHESNAVFACENGCOM (Appendix I) based on the FMEA diagrams prepared by PMTC. Using these block diagrams, all the possible success states of the termination units were listed. A success state is any condition in which the termination unit will function as required even though one or more components have failed. All combinations of failed and functioning components that result in system success comprise the system success states.

4.3 <u>Reliability of the Redesign</u>. From the reliability analysis it was concluded that the redesign is a significant improvement over the original design. The predicted improvement is a result of increased component redundancy in the redesign. Additional performance improvement is expected because the redesigned termination eliminates pressure differentials across all but two seals. The beneficial effects of eliminating the pressure differential were not considered in the reliability analysis. Based on this conclusion it was recommended that the redesigned termination be approved for use in the BSURE and that no further design analysis efforts be conducted unless the need for additional redesign is

subsequently indicated by testing. Two additional recommendations regarding tests were included in paragraphs 5.2 and 5.3 of the CRC Analysis for NUSC (Appendix H).

5.0 RELIABILITY ANALYSIS OF BSURE IN-WATER ELECTRONICS

5.1 <u>Reliability Analysis Study</u>. It was apparent from a study of BSURE in-water electronics that the Hydrophone/TATU Electronics were suitable for re-use in the replacement program (Appendix A, Item 7).

6.0 COMPARISON OF CHESNAVFACENGCOM (PARAGRAPH 3.6) AND NUSC (PARAGRAPH 4.0) ANALYSES

6.1 <u>Comparison Assumptions</u>. The same assumptions were used in both analyses, i.e.:

o Constant failure rate for Morrison seals and O-rings;

o Identical failure rate for all seals; and

o Negligible effects due to the oil.

6.2 <u>Original Design/Redesign Block Diagrams</u>. The block diagrams for the original design and the redesign had been prepared by CHESNAVFACENGCOM and were utilized by NUSC (Appendix I).

6.3 <u>Participants' Conclusions</u>. CHESNAVFACENGCOM and NUSC both concluded that the termination redesign is a significant improvement over the original design. The predicted improvement is a result of increased component redundancy, and additional performance will result from the fact that the unit has been redesigned to eliminate pressure differentials across all the seals but two.

7.0 CONCLUSIONS

The results of the Design Review Team's independent analysis, studies, and investigations show that:

- o The TATU termination seal redesign is intrinsically 100-500 times more reliable than the old design;
- o The intrinsic reliability is considered a fair representation of the actual operational reliability, covided that the design is not compromised through the use of inadequate controls in areas such as configuration, drawings, manufacturing, assembly, test and inspection, packaging, storage, shipping, receiving, and installation; and
- o To ensure the maintenance of reliability standards and the integrity of design requirements for the TATU termination throughout the life of the refurbishment program, that adequate quality assurance controls be established and implemented.

8.0 RECOMMENDATIONS

It is recommended that:

- The TATU termination seals redesign be used for the BSURE refurbishment program;
- Adequate quality control procedures be established and maintained throughout the life of the refurbishment program to ensure that the design is not compromised during manufacture and deployment;
- An independent government Quality Management Team be formed to oversee all aspects of the project quality control to ensure that the controls are adequate; and
- A government Quality Management Team monitor the contractor's quality program to ensure that adequate quality controls are implemented and maintained.

APPENDIX A

Ę

L

,

.

EXCERPTS FROM THE

MINUTES OF BSURE REPLACEMENT PROGRAM FINAL DESIGN REVIEW MEETING

13-14 JAN 1982

1.1.1

OPNAY S216/145 (Bev 3-78) em cierter ma 1633 (d.2 FOR (RSENT LETTER CN) +	Naval S	Speedletter	-
	UNCLASSIFIED AIR-6303D/JGC 630-SL-022	TE FEB 1982	REFEUCTIONIE 1. Menage type presanalicy is permaticle. 2. Both education must be appropriate for with revelope of bulk materia, as present. Inclus-
Te Distribution	a .		 Indoo andm, when known. Use dott And brittles and guiden by employ any address. Give practic to presenting, routing, and self required. Accord time-manining controls. In articrup oper prossence, a reading that a self self requires and employed providence. Of the self self self self self self self sel
dist Ref: (a) 1	tes of BSURE Replace ribution of MAVAIR Spdltr AIR-63	ment Preliminary Des 03D/JGC 630-SL-007 o	f 15 Jan 1982.
I Zncl: (1) 1 (2) 4 (3) 4 (4) 1	leview Mtg; distribu finutes of BSURE Rep of 13/14 Jan 1982 Agenda for BSURE Rep Attendees for BSURE	URE Replacement Prel: tion of lacement Final Design Lacement Final Design Replacement Final Des Ls for BSURE Replacem	n Review Mtg 1 Review Mtg 1 gn Review Mtg
l. Enclosur Final Design	es (1) through (4) at Review mtg called	re provided to docume in reference (a).	mt BSURE Replacemenz
NUSC Newport CompacyIstes	GCOM Washington DC	J. J. By	N. EVER direction
	Systems Command		ADDRESS REPLY AS SHOWN AT LEFT; OR, RE- PLY HEREON AND RETURN

F

(

UNCLASSIFIED

ċ

APPENDIX A

EXCERPTS FROM THE

MINUTES OF BSURE REPLACEMENT PROGRAM FINAL DESIGN REVIEW MEETING

1. This meeting was held 13-14 January 1982 at NAVAIR Headquarters. Final design review analyses of TATUS were presented by CHESNAVFACENGCOM (CHESDIV), NUSC and PACMISTESTCEN (PMTC). Action items and future plans were agreed upon prior to adjournment.

2. Mr. Culver and Mr. Crangle (AIR-6303) opened the meeting and discussed the BSURE funding situation. OPNAV has authorized \$1.8 M FY-82 0&M,N funds to extend the DELCO contract to refurbish TATUs for a second string and provide initial engineering support.

3. Mr. G. Nussear (PMTC) provided a status report of the 30 September 1981 contract with DELCO. Contract milestones and schedule were reviewed. The additional (second string) contract will be awarded in early February 1982 to DELCO. Target completion date of this contract effort is September 1983. The delay in contract award was caused by the need for review and approval by AC Electronics, Detroit, and DCASMA because of the size of the contract amount.

4. Mr. R. Cox (CHESDIV) presented the results of the Design Analysis Team (DAT) seal tolerance efforts, expressed residual concern and recommended minor changes in the seals. (See covering memorandum, Appendix C.) Mr. R. Polley (PMTC) presented results of their tolerance study of BSURE plug-in terminator (Appendix D). Discussion on the subject attempted to resolve different views of CHESDIV and PMTC. The CHESDIV position was that all O-rings should be reviewed by the government as sufficient questions of compression, cavity and seal size exist to warrant this review. PMTC felt that normal (accepted standards) tolerance ranges and inspection/control procedures should eliminate any problems. Different size sealing components could be changed during assembly as a result of quality control and inspection (QC&I) procedures. It was agreed that changes to QC&I procedures should be made as soon as possible, rather than in the future, as a change to the scope of the DELCO contract would be more costly later.

Ľ

E,

5. Mr. R. Cox (CHESDIV) discussed the results of the DAT analysis effort and the action items from the preliminary design review (page A-8). Mr. G. Nussear (PMTC) indicated that 95 percent of the "built to" drawing package had been obtained from DELCO. Considerable discussion ensued as to the status of the remaining 5 percent of the drawings and reasons for reluctance or delay on the part of DELCO. It was agreed that every reasonable effort should be put forth to obtain, or to make available for government review at DELCO, the remaining drawings. PMTC has received the seal tolerance analysis from DELCO and will obtain the seal assembly procedures later as a contract deliverable.

6. Mr. R. Ricci (NUSC) reported on efforts to obtain information of seal failure rate data and on accelerated life testing (pages A-9 thru A-12). No failure rate data for seals suitable for analysis was located. Accordingly, the NUSC approach utilized operational data from existing installations. A reliability figure of .916, based on operational data analysis, was derived.

However, this is highly questionable based on approximately 2 million hours on the two existing BSURE strings. Normally, 8-10 million operating hours are considered the minimum for a representative data sample.

7. Mr. R. Ricci (NUSC) presented an assessment of TATU Electronics with predicted system reliability (pages A-13 thru A-18).

8. Mr. R. Cox (CHESDIV) reviewed the CHESDIV model for seal comparative reliability Figure of Merit (FOM) as presented at the previous meeting in November (pages A-19 and A-20). (NUSC had arrived at a very similar model.) Applying the .916 reliability figure derived by NUSC to the models results in a 100- to 500-fold improvement of the new design over the old design.

9. Mr. R. Cox presented a four phase integrated test plan (page A-20). This was followed by a discussion of the quality control (QC) and test functions (pages A-22 thru A-24). NUSC, CHESDIV and PMTC recommended that an independent activity/contractor, preferably located close to DELCO, perform the QC and test of BSURE replacement assembly. The roles and functions of this activity were discussed at length.

10. Mr. R. Cox (CHESDIV) proposed a Quality Management Team (QMT), to operate in a similar manner as the Design Analysis Team, with one representative each from CHESDIV, PMTC and NUSC. This group would be briefed periodically by the QC/Test contractor and meet quarterly in California to review the assembly/ installation progress (page A-25).

11. A summary of recommendations was presented by the DAT (CHESDIV, NUSC and PMTC) (page A-26). Discussion followed on BSURE replacement program funding.

12. Action items were discussed and agreement reached on the following:

A. DAT will complete the design analysis, write a report, and begin functioning as the QMT. The team will consist of representatives from PMTC, NUSC and CHESDIV. Mr. R. Cox (CHESDIV) will continue as the team chairman.

B. The DAT will complete the Seal Tolerance Analysis. They will conduct an on-site review of DELCO "build-to" drawings to determine the following: 1) drawing changes should be required to eliminate or relieve potential problems resulting from tolerance build-up or O-ring compression, 2) the extent of such changes recommended (if any), 3) the expected effect of such changes (if any) on the assembly and performance of the TATU, 4) the estimated cost impact of such changes (if any), and 5) a comparison of the effectiveness of any alternative solution to the problems (e.g., parts selection). The DAT will submit a report to AIR-6303 with recommendations and identification of any additional drawings desired to have released by DELCO to the DAT prior to the required contract delivery by 15 February 1982.

C. In conjunction with the DAT's visit to the DELCO facility to review the build-to drawings, the Team will review the TATU assembly instructions/ procedures to determine the adequacy of these instructions. They will also determine the need, extent, and feasibility of amending these instructions to include any additional instruction which may be required because of tolerance built up or O-ring compression. These instructions/procedures must be complete and accurate enough to permit the proper assembly of TATUS by an alternate source (other than DELCO). They will submit a letter report to AIR-6303 by 15 February 1982.

D. The DAT will provide inputs to AIR-6303 for the preparation of Project Master Plans (PMP) by 15 February 1982. These inputs should include a brief description of each project task and identification of responsible and performing organizations. Also, the relationship, or interdependence, of the various tasks should be described.

E. NAVAIR will prepare and send a message to the proper Commands describing the disestablishment of the Design Analysis Team and the establishment of the Quality Management Team by 22 January 1982 (complete).

F. QMT will prepare a work statement describing the quality control and test functions required to be performed by the agency (government field activity or contractor) designated as the quality control support agency by 15 February 1982. They will determine if NCEL will accept this responsibility for the BSURE Replacement Project and if such assignment is recommended.

G. The DAT members will provide more refined cost estimates for the various project tasks contained on the BSURE Replacement schedule and funding chart distributed at the 13/14 January design review by 8 February 1982. They will also provide recommendations regarding schedule changes as appropriate. ŕ Ś **1**11 . -i. È

AGENDA

FINAL DESIGN REVIEW OF BSURE REFURBISHMENT PROGRAM

13 JANUARY 1982 (WEDNESDAY)

NAVAIR PMTC	CHESDIV CHESDIV/PMTC/NUSC	NUBG CHESDIVIPMTC	CHESDIVIPMTC	NUSC NUSC CHEENNIJUICA	DenviAmento	NAVAIR
0830-0930 DELCO CONTRACTIPROGRAM STATUS 0830-0930 DELCO CONTRACTIPROCUREMENT STATUS 0930-0945 INTRODUCTION TO ENVIL DECISION CONTRACTION	0046-1000 RESULTS OF PREL. DES. REV. ACTION ITEMS 1000-1030 ASSESSMENT OF TATU ELECTRONICE	1030-1130 RESULTS OF TOLENANCE ANALYSES 1130-1230 LUNCH	1230-1330 RESULTS OF TOLERANCE ANALYSES. 1330-1400 Failure Rate data for sfala	1400-1430 DASIS FOR SEAL RELIADILITY ASSESSMENT 1430-1530 UPDATED SEAL COMPARATIVE RELIABILITY FOM	14 JANUARY 1982 (THURSDAY)	0800-0815 COMMENTS 0816-1015 INTEGRATED TEST PLANNING

COMMENTS	INTEGRATED TEST PLANNING	QUALITY CONTROL AND TEST SIMILATION	LUNCH CONTRACT TURNING	QUALITY MANAGEMENT GROUP SUMPERION	SUMMARY OF RECOMPLEMENTATIONS	COMMENTS	IDENTIFICATION OF ACTION ITEMS	CONTINGENCY
0800-0815	0816-1015	1016-1130	1130-1230	1230-1300	1300-1330	1330-1345	1345-1400	1400-1530

CHESDIVINUSC CHESDIVIPMTCINUSC CHESDIVIPMTCINUSC

CHESDIVIPMTCINUSC NAVAIR NAVAIR/CHESDIV/PMTC1

Enclosure (2)

BSURE DESIGN REVIEW 13 JANUARY 1982

,

•

ATTENDEES

•				
R		ATTENDEES		
	NAME	ORGANIZATION	AUTOVCN	<u>PEONE</u> <u>COMTERCIAL</u>
	Mr. 2. E. Crazgle	LIR-6303	222-7132	(202) 592-9182
	LOR 3. Balivia	AIR-6303A	222-9182	(202) 692-9182
	Mr. J. Culver	LIR-6303D	222 -9 182	(202) 692-9182
I K	Ma. F. L. Faust	AIR-5103J		(202) 692-7688
	Hr. D. Wickes	NUSC, Code 38214	948-3413	(401) 341-3415
i _	¥2. 2. 3. 3. 21cc1	NUSC, Code 38214	948-3415	(401) \$41-3415
	Mz. 2. L. Cox	CHESNAVFACENCOM FF0-1		(202) 433-3881
	Mr. R. Polley	PMTC-3143	351-8904	(805) 982-8904
i in	Mr. G. A. Mussear	PETC	351-8904	(805) 982-8904
	Mr. A. Michael Ho	PERE/PERC		(808) 471 -6 271
	Mr. E. S. Clark	SETAC		(703) 820-9400
	Mr. R. D. Errin	SELAC		(703) 820-9400
	Mr. J. Clastain	521		(703) 524-2053
ir	Yr. M. Di Leo	35		(703) 841-1445
	Mr. J. L. Brady	VSZ		(703) 979-4900 2215
	₩2. Ј. М. Есуе	VSZ		(703) 979-4900
	Mr. F. Ballinger	PHIC-0143	351-8331	(805) 982-8904

Enclosure (3)

CHEBNAVFACENGCOM

PRELIMINARY DESIGN REVIEW **ACTION ITEMS**

Ķ

- OBTAIN "BUILT TO" DRAWING PACKAGE FROM DELCO (PMTC)
- OBTAIN SEAL TOLERANCE ANALYSIS FROM DELCO (PMTC)

A-8

- OBTAIN SEAL ASSEMBLY PROCEDURES FROM DELCO (PMTC)
- (NUSC) FAILURE RATE DATA AND ON ACCELERATED LIFE TESTING **OBTAIN/SEARCH FOR INFORMATION OF SEAL**

. Ì K, . -----. . D • Ļ 6.....



FAILURE RATE DATA FOR SEALS

NO DATA BANK FOR RELIABILITY DATA FOR O-RING OR MORRISON SEALS HAS **BEEN LOCATED**

A-9

USE OF OPERATIONAL DATA CONSIDERED MORE PRUDENT APPROACH




<u>ن</u>

ACTION ITEM

- **CONTACTED NOS/NSWC RE ACCELERATED AGING TEST PROGRAMS**
 - GARY MERRY, NOS
- GERALD MacKENZIE, NSWC

A-12

- RECEIVED ENOUGH INFO TO DEVELOP A STRAWMAN TEST PLAN
- **NOS/NSWC EXPRESSED WILLINGNESS TO ASSIST IN TEST PLANNING AND IMPLEMENTATION**

Ŋ **K**... . . r Ď Ļ

.

<u>.</u>



ASSESSMENT OF TATU ELECTRONICS

- OVERALL SYSTEM PERFORMANCE IN THE FORESEEABLE PUTURE ELECTRICAL AND ACOUSTIC DESIGN DOES NOT IMMINIT 9
- ELECTRICAL DESIGN FEATURES REDUNDANCY IN SIGNAL PATH 0
- **D** INDROPHONE IS EFFECTIVE OVER ENTINE OPERATIONAL BU OF TATU

A-13

POST EXPERIENCE DOES NOT DICTATE THAT NODIFICATIONS TO THE ELECTRONICS DE MADE 0



TATH ELECTRONICS

Ó

Ľ

•

•

D

Ļ

.

ſ

0

o Fuse Board

POMER SEPARATION UNIT(SIGNAL PATH, REDUNDANT)

- O PREAMPLIFIER

o FREQUENCY SYNTHESIZER

o MODULATOR

A-14

- o CAPACITOR MODULE
- O BAND COUPLING AMPLIFIER

.



RIPEATER ELECTRONICS

- o AMPLIFIER HOUULE (SIGNAL PATH, REDUNDANT)
- o PILOT TONE MODULE
- (REDUNDART)
- o POWER SEPARATION UNIT (SIGNAL PATH, REDUNDANT)
- O H. V. CAPACITOR POINTE
- O BALUN COUPLING MODULE (SIGNAL PATH, REDUNDANT)



D

Ľ

•

Ľ

Ļ

.

SEA ANODE ELECTRONICS

- o PASSIVE TERMINATION NETMORK
- **D PLATINUM COATED ANODE (DC RETURN)**



ELECTRONICS RELIABILITY

ġ

TATU

PROBABILITY OF SUCCESS = 95.55% (20 YEARS)

REPEATER

PROBABILITY OF SUCCESS = 99.86% (20 YEARS)

TATU (2 X 8 ARRAY, NO ADJACENT FAILURES) Prorability of success = 95.85x

CABLES

PROBABILITY OF SUCCESS = 99.432

r Ì $P_{S} = .9585$ TATU ARRAY **I**9504 SYSTEM RELIABILITY P_s For system = **2 REPEATERS** $P_{s} = .9972$ Ę ____ $P_{S} = .9943$ CABLES i. • Ī.

A-18

- ,6

CHESNAVFACENGCOM

PÅRALLEL MULTI-ELEMENT SEAL (N= LOG PF/LOG F)

EQUIVALENT SERIES SINGLE SEALS THAT GIVES THE SAME RESULTS AS THE SERIES/ ŧ Ż

PROBABILITY OF FAILURE OF THE NEW SERIES/PARALLEL MULTI-ELEMENT SEAL OVER 20 YEARS 1

PROBABILITY OF NON-FAILURE OF A SINGLE SEAL OVER 20 YEARS (1-F)

- PROBABILITY OF FAILURE OF A SINGLE SEAL OVER 20 YEARS

u,

<u>ل</u> م

ı S

.024 120.

PARAMETRIC RELIABILITY ANALYSES

0.134

...

ᅿ

<u>51</u>E

PF(OLD/PF(NEW)

PF(NEW)

.9860

9199.9

. 100

. 900

.8895

4633

.660

. 340

2.238

6.1

2.512

2.7

2.952

5.7

3.040

7.2

100

.00164

. 1667

878

.122

500

.00018

.0898

930

.070

20

.0037

2076

850

.150

1

£150.

.3711

.730

.270

3.242

13.3

3.298

17.2

1,000

.00007

.0683

245

.055

A-19

5,000

.000007

.0356

9696.

10,000

.0000026

.0270

.976

3.417

31.3

3.448

40.7

Ì

L_____

, ,

۵

.

1

,

• •

•



-

Ì

L

D

COMPARATIVE RELIABILITY EQUATIONS

ORIGINAL DESIGN

 $P_{P} = 1 - (6) \left[1 - (-5^{2}) (1 - 5^{3}) \right] \left\{ 1 - (1 - 5^{3}) \left[1 - (1 - 5^{3}) \right] \left[1 - (1 - 5^{3}) \right] \right\}$

IMPROVED DESIGN

P_{P1} - p²(1-S²)

P_{P2} = 1-5³

 $P_{P_3} = (1-S^2) < 1-[1-P^2] (1-[1-S^2]^2 (1-(1-P^2)^2]) > (1-P^2)^2 (1-P$

Pp - (Pp3) (1-1-Pp1) (1-Pp2)

P - Probability of failure

S - Probability of non-failure (success)

P+S-1



INTEGRATED TEST PLAN

L.

Ō

Ļ

.

A. FABRICATION PHASE

- SUPPLIER FACILITIES INSPECTION
- IN-PROCESS INSPECTIONS
- RECEIVING INSPECTIONS
- ACCEPTANCE INSPECTIONS

B. VALIDATION PHASE

- RECEIVING INSPECTION
- ASSEMBLY TESTS
- INDUCED FAILURE TESTS
- PRESSURE DEMONSTRATION TESTS
 - SIMULATED DEPLOYMENT TESTS
 - IN SITU TEST
 - - RELIABILITY
- **C. INSTALLATION PHASE**
- PERFORMANCE MONITOR TESTS - ASSEMBLY INSPECTION

D. SYSTEM INTEGRATION & CHECKOUT PHASE

- PERFORMANCE MONITOR TESTS

A-21



QUALITY CONTROL & TEST FUNCTIONS

.

.

ģ

I.

Ó

.

Ĺ

. . .

- 1. ASSIST THE QUALITY MANAGEMENT GROUP (QMG) IN THE PREPERATION OF THE INTEGRATED TEST PLAN
- WORK CLOSELY WITH THE DELCO QUALITY CONTROL GROUP 2.
- 3. REVIEW THE DELCO "BUILD TO" DRAWING PACKAGE
- 4. REVIEW THE DELCO DETAILED QUALITY PALN
- 5. REVIEW THE DELCO MANUFACTURING PLAN
- 6. MONITOR ALL SIGNIFICANT INSPECITONS/TESTS PERFORMED BY DELCO
- WORK CLOSELY WITH THE QUALITY CONTROL GROUP OF THE BSURE INSTALLATION CONTRACTOR (BIC) 7.
- 8. REVIEW THE DELCO TERMINATION ASSEMBLY PROCEDURES
- 9. REVIEW ALL INSPECTION/TEST REPORTS

A-22



QUALITY CONTROL & TEST FUNCTIONS (CONTINUED)

[____

Ď

Ļ

•

. .

. بک

- REVIEW THE DELCO PART/EQUIPMENT STORAGE, PACKING, AND SHIPPING PLAN 10.
- ESTABLISH A BONDED STORAGE FACILITY FOR PARTS/EQUIPMENT DELIVERED BY DELCO 11.
- PERFORM DESIGNATED TESTS OF THE INTEGRATED TEST PLAN 12.
- PERFORM ADDITIONAL PART INSPECTIONS AS REQUIRED TO SUPPORT THE INTEGRATED TEST PLAN 13.
- INSTRUCT THE BIC IN THE PROPER HANDLING AND ASSEMBLY PROCEDURES FOR THE EQUIPMENT 14.
- MONITOR THE ACTIVITIES OF THE BIC IN HANDLING AND ASSEMBLING THE EQUIPMENT 15.
- IMMEDIATELY REPORT THE RESULTS OF ALL INPSECTIONS/TESTS TO THE QMG 16.



QUALITY CONTROL & TEST FUNCTIONS (CONTINUED)

-

İ

ſ

6-1

•

ĥ

- PROVIDE QUALITY PROGRESS PRESENTATIONS TO THE QMG EVERY 3 MONTHS 17.
- ASSIST THE QMG IN WRITING THE QUALITY MANAGEMENT FINAL REPORT 18.



QUALITY MANAGEMENT GROUP FUNCTION

ŗ

Ĉ

TASKS

- I. PREPARE AN INTEGRATED QUALITY PLAN
- 2. PREPARE AN INTEGRATED TEST PLAN (SUBSET OF 10P)
- **3. WRITE WORK/TASK STATEMENT FOR QUALITY CONTROL AND TEST ORGANIZATION/CONTRACTOR**
- NEGOTIATE QUALITY CONTROL COOPERATION FROM DELCO
- SELECT/RECOMMEND THE QUALITY CONTROL AND TEST ORGANIZATION/ CONTRACTOR ൎ
- Periodically meet with the quality control and test organization! **CONTRACTOR AND THE TATU CONTRACTOR TO REVIEW PROGRESS OF THE** INTEGRATED QUALITY PLAN ċ
- 7. PERIODICALLY REPORT TO NAVAIR ON PROGRESS OF THE INTEGRATED **QUALITY PLAN**
- 8. WRITE AN INTEGRATED QUALITY PLAN FINAL REPORT

DURATION — 2nd Q FY-82 THROUGH 4th Q FY-84

PARTICIPANTS

ONE REPRESENTATIVE EACH FROM: CHESNAVFACENGCOM PMTC NUSC

ESTIMATED COST CHESNAVFACENGCO

CHESNAVFACENGCOM PMTC NUSC

180 180 180

CHESNAVFACENGCOM



SUMMARY OF RECOMMENDATIONS

.

٥

- **REFURBISHED TATU'S FROM DELCO** I. PROCEED WITH ACQUISITION OF
- 2. ESTABLISH A QUALITY MANAGEMENT GROUP (QMG)
- **3. HAVE THE QMG PERFORM THE TASKS** PREVIOUSLY INDICATED AS THE QMG FUNCTIONS

4. PROVIDE IMMEDIATE FUNDING FOR THE QMG AND Q.C. AND TEST FUNCTIONS

APPENDIX B

Ņ

Ľ

.

K

.

Í

`...

•

NUSC COMMENTS ON BSURE REDESIGN DOCUMENTATION

NUSC COMMENTS ON BSURE REDESIGN DOCUMENTATION

1. The BSURE redesign drawings have been given a cursory review by both NUSC and CHESDIV. The primary purpose of the review was to determine the accuracy and completeness of these drawings to achieve redesign goals. The design depicted on the drawings appears to represent a viable solution. The redesign validity has been verified by a successful test of a prototype. It could not be verified if the drawings accurately reflected the tested prototype. In all probability, they do not.

The design depiected on the drawings was reviewed in some detail particularly in the areas of the Morrison seals and the '0' rings. The investigation did not reveal any obvious flaw in the design or in the use of these seals. This review included a tolerance variation assessment and its effect on the proper function of the seals.

-

Ę

拘

2. The general category of the Delco drawings reviewed, tends to fall into the LEVEL 2 category as defined by DoD-D-1000B. This assessment is based on the fact that many component materials are specified in terms of internal Delco specifications, supplier identification, or general industry nomenclature without specific control reference. In addition, a few key fabrication operations are controlled and qualified by the use of special Delco tool gages. The drawing package references a few tests at assembly, but these tests appear to be minimum in scope and are part of the original design package and may be inadequate and/or inappropriate for the redesign version.

3. The drawing package depicts a design which utilizes extremely complex components containing many precision dimensions which require extreme care in methods of fabrication and inspection. The Quality Assurance Program, due to be submitted for approval 30 days after contract award, is the key document to insure proper fabrication and inspection of all deliverable components in accordance with the drawing package. The Government should review this submittal with care before approval of this document is given.

4. Three drawings are referenced in the contract as defining the deliverable items. These drawings are 7556614 for TATU refurbishment, 7556615 for REPEATER refurbishment, and 7556616 for anode rework. These drawings were not part of the documentation package available for review, therefore, a top-down breakdown of the family tree could not be made. From the contract and all other information available, an exact determination of the total drawing package and revision status which forms the technical and fabrication base for the contract could not be determined. It is essential that the total contract documentation package be accurately identified to establish the production baseline.

5. The contract does not formally establish a Configuration Management Program. A CM program is vital to systematically evaluate and implement changes, waivers, and deviations to the production baseline. It is assumed that Delco has an internal CM Program which may be adequate for the goals of this contract. A severe deficiency in the contract is this internal program will function without government participation and approval. Government participation is mandatory if in-process and end product control is to be adequately established and maintained throughout the contract. 6. The following are general and/or often repeated comments generated from the drawing review:

a. Many key sealing surfaces are controlled by a drawing note which states: "Indicated surfaces are sealing surfaces and shall be free of axial scratches or other imperfections detrimental to sealing." This statement, although of noble intent, does not quantitively specify the limits of acceptability which may be critical to the design success.

b. Most drawings created in 1980 (756XXXX series) were not checked. These drawings contain signatures of the draftsman and an engineer. A checker's signature signifies a very skilled individual who possesses intimate knowledge of all fabrication methods and drafting standards has reviewed the drawing for completeness, adequacy and accuracy.

APPENDIX C

-

-

D

•

BSURE CABLE TERMINATION

CHESNAVFACENGCOM TOLERANCE STUDY, DEC 1981

NOTE: The analysis was performed by CHESNAVFACENGCOM using early release drawings provided by PMTC for review. Subsequent analyses conducted to confirm tolerance design problems noted in this study were undertaken by PMTC and DELCO using the final release drawings. PMTC and DELCO analyses are provided in Appendices D and E. Apparent tolerance problems noted in the CHESNAVFACENGCOM analyses which resulted from use of early release drawings were identified by PMTC and provided to CHESNAVFACENGOM for information. Design changes were made by DELCO to correct tolerance problems noted by CHESNAVFACENGCOM and confirmed by PMTC and DELCO.

스 파트 승규가 아파 동안 속 옷에 가지 않고 하는 것 같아.

FPO-1HF3:mak 29 December 1981

MEMORANDUM

From: FPO-1HF3 To: FPO-1FP4

Subj: BSURE Cable Seal Tolerance Study

Encl: (1) Tolerance Study Calculations

1. A study has been conducted of the Delco Electronics drawings of the BSURE cable termination. The purpose of this study was to determine if there was any possibility, however remote, of any seal leakage in the hardware fabricated and assembled from these drawings. While the effort was burdened by the absence of an assembly drawing and any documentation describing assembly procedure, it was possible to determine that potential for leakage could exist, mostly in the secondary seals. It should be recognized that the leakage would result from tolerance build-up under the worst possible combinations, since such a situation could exist although admittedly unlikely.

2. Enclosure (1) first addressed the Morrison-type seals, numbers 30, 26, 20, 14, 2 and 1 as shown on page 28. This effort was made to determine if there existed any possibility of the seals having greater volume than that available in their cavities. This situation exists for several seals so the effects of the resulting displacement of members forming the seal cavities were investigated. This effect can make at least one of the secondary seals ineffective.

Second, the O-rings, seals number 33, 29, 23, 16, 15, 13, 12, 7, 5, and 4 were checked for maximum and minimum compression, including the effect of stretching. In addition, each O-ring was evaluated for relative volume compared to available volume in the O-ring grooves. In general, the maximum compression was extremely high, considerably above accepted standards, although such standards do not appear to be finite for such static seal applications. In addition, some of the seals can occupy a very large percentage of the available volume in the grooves, approaching 90%. Thus, they must change from a circular to an almost square cross-section. It would seem that both of these problems could result in difficult assembly problems and possible seal material deterioration with time.

The two band seals, numbers 21 and 19 were checked also. No potential problems were apparent.

3. Enclosure (1) has uncovered the following sealing problems:

a. Morrison-Type Seal No. 30 Installation: This seal can be 3.2% volumetrically more than the available volume, or probably greater than this

FPO-1HF3:max 29 December 1981

Subj: BSURE Cable Seal Tolerance Study

_

<u>_</u>

if a minute amount of metal compression occurs in the taper joints. This can cause a gap of .0142 inches minimum between pieces number 27 and 32 and possibly as high as .05 inch. Since a gap of only .017 inch will result in O-ring seal number 29 being exposed and thereby ineffective, it is recommended that the nominal .36 inch seal width be reduced to a nominal .30 dimension. In addition, the assembly procedure should include an accurate measurement to determine that piece number 27 is actually bottomed against piece number 32, which would indicate that the gap problem does not exist.

b. <u>Morrison-Type Seal Number 26 Installation</u>: This seal will not exceed the available volume in the seal cavity. However, there is a seal back up ring drawing number 7564009 which appears to fit this cavity, although this is not clear from the drawing. If indeed it is installed with seal number 26, their combined volume will exceed the available volume by 3%. This will cause gapping between piece number 25 and 27. While this will not present a seal problem, it will have the effect of backing piece number 17 out of the termination housing, piece number 9. This is undesirable, so measurements should be taken at assembly to ascertain that the gap does not exist. If it does, the length of seal number 26 should be reduced, or possibly leave out the seal back-up ring.

c. <u>Morrison-Type Seals Numbers 14 and 20</u>: These are the primary seals, and as such, warrant maximum attention during assembly. Seal number 20 and the seal described by drawing number 7563620 can extend .013 inch into the taper of piece number 18. It is not known if this could present an assembly problem, since the depth of the potting for cable strength members in this taper is unknown.

Seal number 14 can require more volume than available in the seal cavity, causing a .030 inch gap between piece number 18, the cable terminator and the compression nut. This does not appear to present a problem when using the number 20 seal shown on drawing number 7563620-001. However, the -002 seal on this drawing is .80 thick instead of .31. It is much too thick for this installation. It's use is unknown.

d. Morrison-Type Seals Numbers 1 and 2: There are no apparent problems relative to volume versus available space for these seals.

e. <u>O-Ring Seals</u>: The enclosed calculations show O-ring compression as high as 47% maximum and 18 1/2% minimum. These figures are slightly high, since they do not take into account the slight oval cross section which the rings assume when stretched the order of 3% when installed. However, the amount of compression is very much higher than one authority's normally accepted maximum compression of 24% and minimum compression of 17% for static O-rings.

FPO-1HF3:mak 29 December 1981

Subj: BSURE Cable Seal Tolerance Study

It is not known if this presents a problem, other than the obvious difficulty in assembly. In addition, some seals, such as numbers 12 and 13 can occupy 87 1/2% of the rectanglual o-ring cavity. The absence of "ramps" or bevels on some pieces must really complicate assembly when such a high percentage of the seals must be deformed. In addition, as the O-rings swell with time when immersed in salt water or caster oil, they could possibly expand sufficiently to force some members apart. Countering this is the fact that the durometer hardness measurement will increase as the seals are exposed to near freezing temperature at depth after assembly in possible hot sunshine.

f. <u>General</u>: It is imperative that the unit be 100% oil-filled prior to installation. This should effectively prevent any bending at the assembly ring if it is subjected to any bending moment during handling. It is not known if this is possible, since details of handling sheaves, etc. are not available. A brief investigation was made to ascertain if the shrinkage of the caster oil from deck conditions to installed conditions near 33°F could present any problems. No such problems are apparent.

G. W. Milleury

A. W. MCNAIRY

Copy to: FPO-LHF FPO-LHF3 Daily with the

CHESAPEAKE DIVISION	PROJECT: BSURE CABLE TERMINATION
Naval Facilities Engineering Command NDW	Station:
DISCIPLINE	E S R: Contract:
Calcs made by: <u>A.W. MCNARY</u> date: <u>12-8-81</u> Calcs ck'd by: date:	
	RELATED TO SEALS
Note: ALL CALLOUT	NUMBERS REFER TO
NUMBERS ON INTERIN	
INCLUDED AT THE E	nd of these
CALCULATIONS.	
	in, callout NO. 30,
	work werst tocarde
CONDITIONS	37
	THAT THE .36 2. 02
SEAL LENGTH DOOD	
STRETCHED OUTN TH	5.275-,276 DIA.
	SURING SEAL THICKNESS.
L SEAL O, D Max (ON	manopor) = : === + (2) (:++8)
	2-3++ INA
	.275
1 BER OD (may (ou	$(125) = \frac{.275}{.525} + (2)(.125)$
Ì.	= . 526 IN. 17
CROSS SECTION ARE	$\sum_{n=1}^{\infty} = \frac{1}{4} \pi \left[(.526)^2 - (.276) \right]$
1 .TE7 = 14 77 LD - (· 26072]
D = .540	
	page of
(NOTE: The Delco Tolerance analysis in	cluded in COMPMIC LIR

(NOTE: The Delco Tolerance analysis included in COMPMTC LTR 3143, 2012 SERL 475 of 4 MAR 82 should be shown here also as it was the final tolerance analysis used.)

GPO 942-98

	CHESAPEAKE DIVISION PROJECT: BEURE CARLE TERMINATION
·.;	Naval Facilities Engineering Command NDW Station:
	DISCIPLINE E S R: Contract:
	Calcs made by: <u>A, W, Men AIRY date: 12-9-81</u> Calculations for: TOLERANCE STUDY
	Cales ck'd by: date: RELATED TO SEALE
	when ser is stretched over the
	,275-,276 IN DIA, MANDROL, IT ROCOINDS 4.2%
	A 1200 & GISTO CIRCUMETRENTIAL STRETCH
	.374
	265 .374 REDUCING THE .38 CMAY LENGTH TO (EST.) 374
	CHEEK SEAL LENGTH WHEN INSTALLED
	OVER SHAFT #37 AND COMPRESSED
	INTO THE GAVIEY OF THE SPOOL # 32 !!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!
	SEAL CROSS SECTION
	SHAFT (#37) AFEA = (.7854) (.288)
	= .0651 in. (max)
	AND, =(.7854)(.285) ²
	=.0638 in. (MIN)
	. CONTAINED AREA = . 1963 0638 = . 1325 IN . (MAY)
	(MIM) = 1200 0651 = (1297 iui)
1	(157)(100) -10-497
	1. SEAL COMPRESSION = (157)(100) =18,4970 .1325 (11)
ļ	and = (.157)(100)=21.24 70
4	
	, INSTALLED SEAL LENGTH (1.2124) (.357) = .433
-	page 2 of 29
	GPO 442-981
*	C-6



DIVISION PROJECT: ESUPE CABLE TERMINATION CHESAPEAKE Naval Facilities Engineering Command NDW | Station: _____ DISCIPLINE E S R: ___ ____ Contract: Cales made by: A. MANALRY date: 12-9-91 Calculations for: TOLERANCE STUDY Calcs ck'd by:__ _ date: RELATED TO SENJ 1. MW. CAVITY LEHETH = ,87 - ,4512 = ,4188 (ASSUMING NO TEMP. OR PERMANENT DEFORMATION) (REGAT UN LATEM TO : <u>caurey</u> volume = (1297) (.4188) = ,054318 in. <u>SEAL</u> VOLUME (MAY) = (.357)(.157) 2.05605 - OR 3.27 MORE THIN AVAILABLE VOL OR CHECKUNE LENOTHS, INSTALED SOM LENGTH 15 .433 VI .4188 ANALL, UOL, LENGTH Cleannace of 0.0288 in. CAP OF OUT BETWEEN . THERE CAN BE PC. #17 ADD PC. #32, THIS GAP COULD BE GEENEN, IF THERE IS SOME METH COMPRESSION IN THE TAPER JOINTS AND IF THE . 38 IN. LENGTH OF THE JOAL IS MELSURED WHILE IT IS ON 7,45, 275-,276 IN, DIA. MANDAUZ, THUS LATTER IS NOT CLEAN FROM THE DRAWING, IT ALOWE LOULD CAUSE A GAP OF OHLY SO WITH SOME MINOR METAL COMPRESSION IN THE TAPER, THE GAP COULD BF OUTK . OF IN. WITH WORST - ON NORSE TOLERANCES __ WHICH IS NOT LIKELY, Page 4 of 29

C-8

DIVISION PROJECT: BSURS CABLE TERMINATION CHESAPEAKE Naval Facilities Engineering Command NDW Station: E S R: _____ Contract: _ DISCIPLINE Cales made by: A. Menaley date: 12-9-91 Calculations for: TOLERANCE STUDY RELATED TO STALS Cales ck'd by: ____ _ date: __ 1) CHECK EFFECT OF PIECE #27 BEING BACKED- OUT AS A RESULT OF THE POTENTIAL PEOR, EM FROM PRECEDUNG PARAGRAPH. ,045 MAY SPOOL -. 14 (Mmx) SEAL GEOOVE =on #29 JEAL (MIN) CLEARANCE A BETWEEN O-RING GROOVE AND BOGG, WITH SPOOL #32 BOTTOMED ON NUT #27: .001 A = . 345 - . 045 - . 14 - . 143 = . - 017 14 SO, THERE IS ONLY MARGINAL CLEARANCES WITH PIECES # 32 AND # 27 BOTTOMED, THE page 5 of 29 C-9

CHESAPEAKE DIVISION	PROJECT: BEURE CARLE TERMINATION
Naval Facilities Engineering Command NDW	
DISCIPLINE	E S R: Contract:
Calcs made by: <u>A. Mennay</u> date: 12-9-31	
Calcs ck'd by: date:	ZELATED TO SEALS
	SON TO SANGAN ONE OF
IF THERE IS ANY	GAP OF . 017 OR
MORS. THUS, IT WO	
THE PRESONT SEM	
CAUSS A GAP OF	AT LEAST . 014 ,
A DUD DOZZIBLY UP	TO OS GR MUNT
IT MARGINM AT	BEST, AND POSSIBLY
UNSATISFACTOPY, A	EEDVerton in
SFAL 30 5125 POSTI	BULI WIDTH FROM
.36 70 .38 waver	
IN PANY CASE, THE	ASSEMBLY
proconver should	INCLUDU A POSITIVE
I INDECATION THAT NU	- #27 15 BOTTOMED
1 ON SPOOL #31.	
[3) CHECK SEAL #26	INSTALLATION (DWO 7564138) REVA
TINK STRATCH COMPAN	FZ310N i
RIGHT END (AS SHOW	n on interim assembly
DRAWING") _ INSULATOR	
CAVITY IN NUT =	
<u> </u>	page <u>G</u> of <u>29</u>
C-10	GPO 942-981

C-10

1	CHESAPEAKE DIVISION	PROJECT: BSURE CABLE TERMINATION
•••	Naval Facilities Engineering Command NDW DISCIPLINE	Station:
Fri	Cales made by: <u>A.M. NALRY</u> date: 12-9-81	E S R: Contract:
Ņ	Calcs ck'd by: date:	RELATED TO STALS
	, SEAL I.D. OF , 17 4,0	
Ļ	MINIMUM GF . 005 IN.	on DIA., And A
	MAXIMUM OF ,035 IN	ON. DIA O.K.
	THE SEM O.D. OF	SI (MEAJURDO WHOW
	ON MANDRAL EQUIVAL	ENT TO ACTUAL INSTAL.)
	MUST COMPERSS IN	TO CAVITY OF NUT: 499
	0.12.	
	CHOCK AVAILAB	LE VOLUME (MIN.) VJ
	JEAL VOLUME (MAX.)	
Ď	CAVIEY LENGTH	(NUT-PC#27) . 275
	ISOLATION TURE -(PC#27)455
		, 730
	CENTER CONTA	ct. <u>115</u>
		very LENGTH (MIN) = .615
	CAVITY O.D. CM	
	INSULATOR LON	с <i>т</i> н;
	FOR MAX.	TOLERANCE ON
	NOT AND INSUL	ATOR, DISTANCE
:	INTO CAVITY (LEFT	an Azz'y Dw'a)
	ELSON WEAZURING	& POINT IS AS
	Forroms;	. –
		page $7_{of} 29$
· ·		

GPO 942-98



CHESAPEAKE DIVISION PROJECT: BEURE CABLE TERMINATION
Naval Facilities Engineering Command NDW Station:
Calcs ck'd by: date: 12-11-01 Calculations for: TOLERANCE STUDY
: CAVITY VOLUME = # (.615) (.499) - (.362) (.295) - (.23) (.16)
= .0901 in.
$\leq E_{A} \forall \circ L := = = = [(.+9)(.52) - (.17)(.142)^2 - (.+2)(.26)^2]$
0843 IN, 3
0.12 THIS IS 93.57 70 OF AVAIL VOL,
IF BACK- UP SBAL RING, DW'G, NO. 7564009,
15 USB) - (BACE-UP) VOL = # (.065) (. +92) - (.286)
VE ,0085 in 2 OR TOTAL VOL = ,0928 in.3
THIS IS 3% MORE THAN CAVITY VOLUME,
50 A SMALL AMOUNT OF GAPPINE
COULD OCCUR.
4) CHECK MORRIJON JEMJ NOJ. 14 AND 20:
FIRST, CHECK MINIMUM LENGTH OF SPACE
FOR SEM #20:
ASSUME CABLE TERMINATOR,
PIECE NO. # 18, BUTTE FIRMLY INTO
PIECE NO. IU, D'IL FIRMLY INTO
SOCKET OF FEMALE
page 2 of 29
C-13
an a

CHESAPEAKE DIVISION PROJECT: BEURE CABLE TERMINATION Naval Facilities Engineering Command NDW Station: DISCIPLINE E S R: _____ Contract: . Calcs made by: A.W. MENAIRY date: 12-16-81 Calculations for: TOLERANCE STUDY Calcs ck'd by: _ date: _ RELATION 70 CENTER CONTACT - DWG NO. 7564140 IF so, course LENGTH (MIN = 385 m CAMEY DIN, (MIN.) = . 685 . N. AJJUNE (?) POTTED STREW WIN MEMBORS OUT CITABLE TERMINETE PROVISELY AT START OF THERE (, 385 . N FROM OND) " MIN. VOL. MAN LABLE FOR TWO JERNO · - (.7854) (.685) 2 (.386) = .142 in Now, MAY, SEAK NOL ; = ,130 · M. = 016 . Torse Voc - 146 in -0 -ETAL WOULD EXTEND (146-142 (7854)(.634)2 سن، 13 م. ي , wto targe _ THE MAY OR MITY NOT (PROBABLY NOO) BE AN 15200 , SINCE , 7530487100 OF EXACT LOCATION OF END OF POETNO page 10 of $\frac{29}{29}$

CHESAP Naval Facili DISCIPLINE	PEAKE ities Engineering Comm	DIVISION and NDW		
	by: A. MENAIRY	1	Calculations for: TOLERAI	ACE STUDY
Cales ck'd	by:	date:	RELATED TO SEAL	5
	13 UNRAUM	۔۔ م		
	CHECK	3500 H	14 instruction	• • • • •
		1	-) the comp	
	• •		, = BOTTCHUED	
l	INTO STREM	GENA CHA	ارت سر تحل مد مد مر ولد	,
Í	DW'6 #7564	144 (170	NO. 18) -	/
Ì		•	. = تعنى الكرنا . 120- يامن = .	250
	MIN. CAUCEY	LENG-TH	= .620 (PC.756	4244
	". MIN CAVI	-Y Love	TH FOR SOM	
	.620 -	200 7.	370 in .	
	MIN, CAVE	TT DIA.	د , ، من .	
	MAY. CABLE	J DiA	= ,331 in ,	٦.
ĺ	, MIN, VOL	, For 5	BAL = . 7854 [(, 700) -	(331)1.330
1				-
	MAY SEA			Ň
			34)[(.7445)-(.3245)]	(.7354)
Í		=	120	
1	. Compros			/
	BUT CAN	Bo Brete	TO OFF (GAP)	v ´ v
Į	Dist. =	.7854[(.7	$\frac{1}{(-1)^2 - (-3)^2} = .03c$) (u ·
L				page 11 of 29
~		C-1	5	GPO 942

CHESAPEAKE DIVISION PROJECT: BSURE CABLE TERMINATION Naval Facilities Engineering Command Station: _ NDW DISCIPLINE E S R: _____ Contract: _ Calcs made by: <u>A. MCNAIRY</u> date: 12-2-81 Calculations for: TOLERANCE STUDY Calcs ck'd by:_ date: RELATED TO SEA15 CHECK ASSEMBLY OF STRENGTH TERMINARCE AND EURROMADING COMPONENTS : MIN, LENGTH OF STRENGTER TERMINATOR =uppopp TUBE, Divis #7564449 = 3.195 M.S.Y. LENGTH = 3.205 MIN. LENGTH OF TERMILLAROA LOCK NUT, DWG #7564145 = . 375 MAX. LENGTIN - .385 COMBINES LEWGTHS OF THESE, MIN. = 3.570 IN'. MAY = 3.590 INT Now, charte components Assembles WITHIN THESE TWO ITOMSI DISTINEI FROM LOAN- BEARING PLA 130 URPADIO ALL INT -2564133 、エレテ .255 (GAP ₩2\ page 12 of 19 SPO 942.08 C-16


PROJECT: BSURE CABLE TERMINATION DIVISION CHESAPEAKE Naval Facilities Engineering Command NDW Station: ____ Contract: E S R: ____ DISCIPLINE Calcs made by: A. MCNAIRY date: 12-3-81 Calculations for: TOLERANCE STUDY RELATED TO SEALS . Calcs ck'd by: ____ date: . OOC IN. (MIN.). TIHIS GAP NOT USED IN THE DOBJ NOT APPEAR GREAT ENGURA BSURE Cable TEFMINATION Use The 7563620 - 002 3000 IT IS USED IN The UCS A THICKNOW OF WHICH HAS FETFIEVAL Cable .80, RATUREN THAN .31 IT-Uso is vorenanin CHECK VOLUME OF JEALS #182 5) (MOBELSON SERVE) RELATIVO TO AVANL VOL S ===== <u>vol</u>. (mer) = (77)(,7854)[(2.690)-(.880)] = 3.911 10. ··· 707,2 (2) = 1 UOL = 7.812'10, CABLE DIA (MAY) 2,905 TERMINATION (4005106 (Pc*2) 1.0. (min) = 2.398" LENGTH OF CANTER (WIN): page 14 of 29 GPO 942-98 C-18



DIVISION PROJECT: BSURE CABLE TERMINATION CHESAPEAKE Naval Facilities Engineering Command NDW I Station: DISCIPLINE ESR: _____ Contract: Cales made by: <u>A.M.VALRY</u> date: Calculations for: TOLERANCE STUDY Calcs ck'd by: ___ date: SEALS 12VAILABLE VOL. = (1.7989) (.7854) (1.598) - (.905) = 8.379 in THIS IS 7.12% MODES THAN ROO. For street. O.K. May, LINER CAP WOULD BE. 8.379 - 7.822 (.7854)[(2.598) - (.907)] = .1195 -OR DRIROY 18 INCH - - - O.K. 6) CHORE OF 0-PINGS NOT. 33534, WITH UP-DATED DRAWING. UT PIECE NO. 32 -- DWO NO. 7564121, DATON 4-30-80 - NOTE: - C-ZING GRADUES (VIEW A-A) HAVE BEEN (HANGOD, ALSO O-RINGS, FROM OLDER DUG, DLAM. CL. CHE BUTH CROBUSS (5 Now . 197 MIN . 209 MAX FIZOW LIJT "10- CONNECTOR WITH CHILES O-RING= NOJ. 33 AND 34 ARD Now the JAME (AS ARE THE GRAZUEZ > M83248/1-205 page 16 of 29

GPO 942-951

î,	CHESAPEAKE DIVISION	PROJECT: BOURE CABLE TERMINATION
	Naval Facilities Engineering Command NDW DISCIPLINE	
- <u>-</u>	Calcs made by: <u>A. MCNALRY</u> date:	E S R: Contract:
Ì	Calcs ck'd by: date:	RELATED TO SEALS
	Now $T.0. = .421$	
L .	Provid , FOR MIN. CON	to be a cut the
	MAX J.D. 15 STROTCH	LOO NILO. GRANT
2	0.0., .426 70 .488	
	D. TORUE (O-RING)V	
	upor the	r (min) = .139-,004
t :	T_{γ}	
	$r_2 = r_1 \sqrt{\frac{c_1}{c_L}}$	$= 1357 \left(\frac{.726}{.438} = 126 \right)$
		(usino Dimaro (usis)
ľ	· Compileron Or (MIN)	126 = (.2057
	- or 20.577, -	withch is
Ċ	EIGHT IN THIS MI	のひしじ ので ミナノ・ハ に
	Q-RING COMPRESSION	いに いて てい シャクシ
	RECOMMENDATION .	
	Now chiered	COMPLETSION i
1	USING MIN. O.C.UG	
1	: . 416 AND MIN. Grea	ove 0.0, - or
	.416 70.488	
1	1. d = ,135 V. 416 =	.1246
	(いちん かんしょう ー	1246 = 1.1928
	OR 19.28 % -	U. 10, page 17 of 1

.....

٠.. Ĵ,

CHESAPEAKE DIVISION PROJECT: BSURE CABLE TERMINATION Naval Facilities Engineering Command Station: _____ NDW DISCIPLINE E S R: _____ _ Contract: Calcs made by: <u>A.MSNALEY</u> date: Calculations for: TOLERANCE STUDY Calcs ck'd by:_ _____ date: RELATED 70 SEALS NOW, FOR MAY. COMPRESSION ... USE MAY, GREVE DIA., & MAX. C. RING JOIA. & MIN. HOUMNG DIA . R MAY, O-RING X-JOURION O.D. MAY GRADUTE DIA 5,490 MIN. 1400 MNG DIA = . 687 MAY 0. RING J.D. = . 426 MAY 0-RING X-JOCACH OU, =, 139+,004 $\therefore d_{1} = .143 \sqrt{\frac{.+16}{.490}} = .133$ OR 35.0% _ UR 46% alores THAN RECOMMENDED ANY, D THIS MAY BE HIGH, SINCE C-RING X-JORTION WILL PROBABLY BE MORE OF AN ELCIPSE THAN A CIECLE, HER OF LAWON COMPRESS. 100 . IF 35% CONPRIMENON RESULTS (~ 35 ? WOTH (NCREASE (?), THEN O-DINO (UNTH (UNRESTRAINOD) , WOUD BUT (1.35) (.143) 5 .193 W. THE page 18 of 29

GPO 942-951

PROJECT: BSURE CABLE TERMINATION CHESAPEAKE DIVISION Naval Facilities Engineering Command NDW Station: _ E S R: _____ Contract: _ DISCIPLINE Cales made by: A. MENALPY date: _____ Calculations for: TOLERANCE STUDY Calcs ck'd by:____ PELATING TO SEALS O-RIDE GROADE MIN. 15 .235 . N. O.K. BUT, MEE THERE MAY BACK-UP RINGS USED ? NONE ON THE LIST, BOI AT THESE (7500 Pr) ROSULOS (No TWO DU'65 SLAW STALING WASHING Wrong - DUG NG. 756400 - .498 0.0, 207 - . . drowing See page 9 E= .065, \$ NO. 7556276. .749 0.0., 2003 to all - Northon would pir with THOSE O-RINOS, WITHOUT AN ASS'Y DWG, THESE CANNOT BE LOCATED EASING 7) CHUCK FLT OF PC. # 27 50-FING INFO 1+0051NG 126 #21 - - 1.373 1170 1.375 (MIN) 0-121000 GROCUS DH= 1.275 (MAX) 1.273 (MIN) HOUSING (PC#21) = 1.376 (max) 1.375 (MIN) : Dismorte ch. 7 . 103 (march , inc (min)) EDUINE CL. = , USIT (MAK) , 0500 (MIN) 0-RING PC. #29 13 M 83248/1-026 HAS NOW. J.D. OF 1.237 7.006 page 19 of 2

GPO 942-951

CHESAPEAKE DIVISION PROJECT: BSURE CABLE TERMINATION
Naval Facilities Engineering Command NDW Station:
Calcs made by: <u>A. MCNAIEY</u> date: Calculations for: <u>TOLERANUE</u> STUDY
Calcs ck'd by: date: Calculations for: TOLFRANCE STUDY
FOR MAY COMPROSSION, THIS 1.233 DA
STRUCTURES TO 1.275 DIA.
. O-RING DIA DECENTAVON FREM 1073
$\frac{1}{1} = \frac{1}{1} \cdot \frac{1}{1} \cdot \frac{1}{2} \cdot \frac{1}{2} \cdot \frac{1}{2} = \frac{1}{1} \cdot \frac{1}{2} \cdot \frac{1}$
1. MAR COMPRESSION : 10718 = 1.436
CR 43.6 % COMPROSONON - 71415 15
Much avergeon Tital vorenne 24%
MAY SOIL A STATIC G-RING
For MIN COMPLETION, TITE
(.245 (MAN) J. W. 05 0-RING STRETIGIUS
TO 1.273 (MIN) RING EROCUT I.D.
:, 0-RING CROS - 067 1.275
=,0663 012.
$MIN COMPRESSION = \frac{.6663}{.0515} = 1.2866$ or 28.66 $\frac{7}{5}$ compression = $\frac{-1.2866}{.0515}$ or 28.66 $\frac{7}{5}$ compression = $\frac{-1.2}{.05}$
or 28.66 $\frac{7}{2}$ compension = $=$ $=$ ± 1 $\frac{1}{2}$
APPRECIABLY GREATER THAN NORMAL
17 12 Accured THAT O-RING
CROWN - Iberian Beranier - consumin
page 20 of 29

]

٠.

 з.

٠.,

DIVISION PROJECT: BSURE CABLE TERMINATION CHESAPEAKE Naval Facilities Engineering Command NDW | Station: ____ E S R: _____ Contract: DISCIPLINE Calcs made by: <u>A. MENAIRY</u> date: _____ Calculations for: TOLEBANCE STUDY Calcs ck'd by: _ date: RELATING TO SEALS ווישראש בבנו אישים עווישר שרפטרנולטיון RATHER THAN CIRCULAR - 50 THESE WUMBORN WILL BE HIGH - --CHECK O-RING GREEVE WIDTH TO ACCOMMONTER MAY COMPROVING (322000 - WINTH (MIN) = , 093 [- Gin THUS 47.6 TO: COMMIZIENDION, PING WILL TOUD TO MACH-OUT APPROX : (0718)(1.436) = 103 in. or 10.87% MORE THIN GROOM OF CONTH. CHECK ANALDECE VILVENS ? 0-FILG CED 35-3 BETION AREA = .7854 (.0718) = . 00 40 in . 0-RING GROOUT AREA = (050)(093) = .00465 THERE IS 16% SURPLUS ARON AUALLA TOUR SOURS SING AUGT AS WING ALMOST & ROUTINGULAR SHAPE -- 867 17 WILL, B. ADENY, GO 100. - (nem tien a - WOULD = 200 TO RESSONT AN Rulie 125524 -100 TBOBLOS , Dage 21 of 29

DIVISION PROJECT: BSURE CABLE TERMINATION CHESAPEAKE Naval Facilities Engineering Command NDW Station: E S R: _____ Contract: _ DISCIPLINE Calcs made by: A . MENAIRY date: Calculations for: TOLERANCE STUDY Calcs ck'd by: ____ date: ___ RELATING TO SEALS 8) CHECK = ENJ 12 8'13 (0- RING) LOAD BETHEING PLANE ANY Y- ITOM #6 1.702 Hans 1.700 I.D. FERINE ISOLANION TUBO, JTOM #22 1.748 HAND 1.747 0.D. - O. TE, CL. CAMPAG . SO 5 MAX 0-EING GROOVE DID. = 1.648 THE C-RINGS, ITEMS \$12413 AROT M 83248/1-030 _ HAVE 1.614 J.D. J.010 É W = .070 = .003 For MAY COMPRISSION ON G- RING . O-EINE DIA Z . 073 11.624 = .072 : MAX - COMPRESSION = 5(1.750-1.650) = 1. 44 02 44 7 compa FOR MIN COMPROSOLOW _ O-RING STRETCHEN From 1.604 aut. TO 1.640 : O-RING DIA. = .047 7 1.648 = .066 page <u>22 of 29</u>

DIVISION PROJECT: BSURE CABLE TERMINATION CHESAPEAKE Naval Facilities Engineering Command NDW Station: ____ E S R: _____ Contract: _ DISCIPLINE Calcs made by: A. MENANDY date: Calculations for: TOLERANCE STUDY Calcs ck'd by: _____ date: _____ RELATING TO SEALS THE C-RING GROUNDS FOR MAY COMPRESSION ATUS .093 X.05 TON & X-Storion SREA OF, CO465 IN. THE 0-2120 AREA = .7854 (.072) = .00407 in - 30 THORE 13 ROOM BUT ET. JO OF SPACE IS TAKED -TEAM LIND & ROM JAUDON ASSEMBLY PROBLOW #19: 9) CHECK BAND - JEAN AR OVON D ITEM 22 MIN, GROOLE DIA. = 2.20 m. AJJUNE - 002 SELL (LARGER ONN) MAY. I.O. = 1.86 -> 0.12. George WIDTH = . 360 MIN. ----- WIDTIT = ,36 MIN - O.R. (win be rear more eles eles 10) CHECK BAND JEAL # 21 - WRAPED AROUND MALE 1=024-100 - UBE - #20 : MIN GROOVE DIL = 1.63 in. page 23 of 29 GPO 942-951

.

PROJECT: BSURE CABLE TERMINATION DIVISION CHESAPEAKE NDW Naval Facilities Engineering Command Station: _ ____ Contract: DISCIPLINE ESR: ____ Calcs made by: A. MCNALRY date: Calculations for: TOLERANCE STUDY _ date: RELATING _ SEALS Calcs ck'd by: = 10 ADDALE - COL DEVE (DALLER CONC) MAX I.D. = 1.74 -> 0.12. GROOVE WIDTH = . 37.01 = . 34 - 0.4. area ser #23 \$ #29 $\left(1 \right)$ 0-RING ERCOVE I.D. (PEETZ) - [1.900 FEMALE 1306/100 TUBE I.D. (#22) (2.002 C-PING #23 ##14 _ M 83248/1-032 I.0. (min) = 21.8745.073 w = FOR MAX. COMPOSITION, O-PING STREECHEN FROM +.900 1.874 TO 1.900 D.A. on 45% coupe. MIN comprosion, O-RING STRETCHOU FROM 1.900 TO 1.898 : O. RING DLA. =, 067 1.854 2.0662 = 1.273 - 01.27.3 7 comp. page <u>24 of 29</u> C-28

CHESAPEAKE DIVISION PROJECT: BSURE CABLE TERMINATION Naval Facilities Engineering Command Station: _____ NDW DISCIPLINE E S R: ____ ____ Contract: Calcs made by: A . MENALRY date: Calculations for: TOLERANCE STUDY Calcs ck'd by: date: RELATING TO SEALS 12) CHECK SEAL #15 = #16 -O, RING GROOVE J. D. (PIECO 21) (9.528 3.526 TERMINATION HOUSING ID. 0-RING _ MS 28775/1-238 J.D. 2 (3.499 3.469 w = ____ EOR MILLY COMPRESSION, O-PING STRETCHED From 3.489 TO 3.518 DIA. -1 O-EING DLA = . 14 3 V 3. 489 = . 1424 in. = 1.3828, or 19.18% FOR MIN COMPRESSION, O-BING STRATES FROM 3.469 TO 3.726 DID. :. O. RING DIA = . 135 V 3.526 = . 1339 = 1.849 on 18.49 % COMPR. THESE TWO SEALS ARE TO SOME DEGREE, RECIPECTING STALF, AJ COMPARED TO STATIC SETUS IN ALL page 25 of 29 C-29

DIVISION PROJECT: BSURE CABLE TERMINATION CHESAPEAKE Naval Facilities Engineering Command NDW Station: _ DISCIPLINE E S R: _____ Contract: __ Calcs made by: <u>A. Menairy</u> date: Calculations for: TOLERANCE STUDY Cales ck'd by: _____ _ date: _____ RELATING TO SEALS OTHER O-RING APPLICATIONS, DOES THIS 28.28) COUNTRIBUTION (MAX) PRODUCT A PRODUCTION FIN SUCH AN APPLICATION, OK 13 THORE MAY MOVEMENT OF (21) 1070 # 9 ? (DURING PRESSURISMAN DURING DESCENT?) PT MAY COMPRESSION, O-PING OCCUPIES 77.37% OF GROAVE CUSTR TEST 13) 1.438 C-EINE GECOVER (PIECE TG-) ID = 1.436 HOUSING TERMINATION I.D, (PIECE 1) _ 2.600 C-RING_#5-M832481-142 2.372 I.D. = 2,352 .106 $\omega =$ 100 For MAY, CONTRESSION O-BING (278%) STRETCHED FROM 2.438 DW. TO J.438 DIA, : C-RING DIA (W) = .106 V 2.372 = .1046 . MAY COMPRESSION = .1046 .5(2.590-1.438) = 1.3763 on 37.63 % FOR MIN, COMPROSSION O-PINC (3.577) page 26 of 29 SPO 942-95

CHESAPEAKE DIVISION PROJECT: BSURE CABLE TERMINATION Naval Facilities Engineering Command NDW | Station: ____ DISCIPLINE E S R: _____ Contract: Calcs made by: <u>A.M. NARY</u> date: _____ Calculations for: <u>TOLERANCE</u> STUDY Calcs ck'd by: _____ date: ____ Reconverse to State STRETCHES FROM 2.302 DIA. TO 2.436 DIAL :, COMPERSION :, COMPERSION :, COMPERSION (1110) = .0983 .5 (2.600 - 2.436) = 1.198 , or 19.80 % comp 4) CHECK SEALS # 4 & # 7 0-FING GROUPE (PIECE #6)_0.0. [1.062 (1.062 (1.060) [1.062 (1.060) [1.062 (1.062) [1.062 (1.062) [1.062] [1.06 CABLE O.D. C-RING #4 #47 - M 83148/1-118 I.D. = .868, W. - .106 FOR MAX, COMPROVION, O- PING STRETCHES FROM . 368 DIA TO .905 DIA . 0-EING DLA. (W) = .106 V. 860 = .1038.4. = 1.3314 on 3294% EON MIN CONPERSION, O-RING STREACHOS FROM . 856 TO . 900 . . C-RING DIA. (W) = . 100 1.8+6 = .0975 ... page 27 of 29

GPO 942-951



10 - CONNECTOR WITH CABLES

		1	t	, 1
	BLOCK	Derco	JOMENCLATURE	Exorcu
A	DIAGRAM	DREWING		NUMBER
Ú	LUMAGER	NUMEER		
	10.01	7564122	HOUSING, TERMINATION	9
	10.02	7563536	SEAL, CABLE SHEATH	- I - I
	10.03	7563758	SD LABLE, INNER POLYETHYLENE	3
	15.04	756 37 58	SA CABLE. OUTER POLYETINGENE	3
•	10.05	BLANK	-	-
	10.06	7563758	SD CABLE. INNER LOPPER JACKET	11
		7564139	SEAL, CABLE SHEATH	5
	10.08	M83248 / 1- 142	PALKING, PREFORMED	6
	10.09	756 4131	LOAD BEARING PLATE	4
•		MB3248/1-118	PACKING, PRIFORMED	12
		M83248/1-030	PALICING, PRE FORMED	
	10.12	M83248/1-030	PACKING, PREFORMED	(3
	10.13	7564142-001	BAND SEAL	19 21
	10.14	7564142-002	BAND SEAL	
-	10.15	7564147	FEMALE ISOLATION TUBE	22
	10.16	M 83248/1-032	PACKING PREFORMED	14
Ď	10.17	M 83248/1-032	PACKING PLOFORMOD	25
	10.18	•	MALE ISOLATION TUBE	20
	10.19	7564138	SEAL , INTER CON TERMINATION	17
•	10.20		GIMBAL BOOT PACKING PREFORMED	14
		MS18775/1-238	FILL PLUG	28
	10.22		GINBALLED HOUSING	31
ar Ar sin	10.23	1	INTCON LABLE BOOT	35
	10.24	7554776	PACKING PREFORMED	15
		MS28775/1-238		-
		BLANK 7564124	SPOOL, CABLE	32
		M83248/1-205	PACKING PREFORMED	34
	(0.18 (0.19		PACKING PREFORMED	33
	10.30		seal core	30
) 1 -	10.30		CORE INTEON CABLE	36
	11.11		TERMINAL INTLON LABLE	37
•	-	7554780	SGAL, CABLE CORE	10
	-	7555738	SLEEVE TAPERED	20
		7563620	SEAL STRENGTH TERMINATOR	2
		7564128	NUT, TAPER	
		7564133	PLATE, CONDUCTOR TERMINATOR, STRENGTH	8
		7564144	PACKING PREFORMED	29
		MB3248/1-026		ł

APPENDIX D

PACIFIC MISSILE TEST CENTER

TOLERANCE STUDY

BSURE PLUG-IN TERMINATION

.

.

PACIFIC MISSILE TEST CENTER TOLERANCE STUDY BSURE PLUG-IN TERMINATION

1.0 <u>SUMMARY</u>: No changes to detail components or sub-assemblies are recommanded. Any occurrence of assembly problems due to worst-case tolerance values may be easily corrected by selective component assembly.

2.0 <u>BACKGROUND:</u> At the request of the Naval Air Systems Command, Code AIR-630, and based upon questions raised in review of design documents by personnel from the Naval Facilities Engineering Command, a study was undertaken by Code 3144 of the Pacific Missile Test Center to determine whether any specified dimensions or their accumulated tolerance buildup might cause assembly difficulties for the propose design of the SSURE refurbishment, plug in, type SD cable termination, as represented in DL-CO915 and associated shop drawings.

In arriving at final assembly results, absolute worst case tolerance accumulations were considered. Also investigated were assembly under nominal and low-end tolerance conditions and their effect on diametral clearances, part-to-part alignment, o-ring groove design, and Morrison seal design.

3.0 FINDINGS:

3.1 No evidence of diametral interference nor alignment problems could be found. All mating/interfacing components were investigated.

3.2 O-ring gland design on taper nut, part no. 7564128, was found to deviate slightly ofrom manufacturer's (Parker-Hannifin Corp.) specifications. However, as it compresses the o-ring more, it will result in a better seal at low pressures while still functioning well at higher pressures, should a loss of cavity oil occur.

3.3 Morrison seal design and placement are acceptable at nominal dimensional values. This morrison seal (coreseal 7563636), under an unlikely accumulation of tolerance of six individual parts, is still acceptable for high pressure service, and will perform very well under the current, pressure-balanced design.

3.4 The load bearing plate (p/n 7564131), the male ground contact (7564120), the leveled snap ring (7564546) and its groove exhibit no assembly problems at nominal dimension values. However, under worst-case tolerance accumulation, only .010° of the snap ring would seat in its groove. This is easily recognizable during assembly and can be corrected at that time by choosing other parts or by remachining the male ground contact to nominal or low-end dimensions.

4.0 RECOMMENDATIONS:

4.1 No dimensional, tolerance, or part changes are recommended.

4.2 Assembly drawings should be accompanied by contractor manufacturing routings which will alert shop assemblers to check and, if necessary, correct areas discussed in paragraph 3.0. Corrective action may be effected through selected component assembly or remachining of cartain components.



APPENDIX E

BSURE SD TERMINATION SEAL TOLERANCE STUDY

TOLERANCE ANALYSIS CONDUCTED AT DELCO ELECTRONICS, FEBRUARY 1982

Reliability Analysis of BSURE In-Water Electronics

NOTE: This analysis was performed on an early design of the electronics system which differed slightly from the design actually used. The design analyzed included some parts that were not included in the final design, giving reliability results that were slightly lower than those computed by the manufacturer of the system. This analysis is included in the interest of completeness in reporting the analyses performed by the Design Review Team and because the results are considered somewhat indicative of the reliability of the system.

E-1

3 FEB 82

BSURE SD TERMINATION

SEAL TOLERANCE STUDY

Ì

5)

TOLERANCE ANALYSIS CONDUCTED AT DELCO ELECTRONICS FEBRUARY 1982

Encl (2) to PACIMETESTCEN Ltr 3143 4 MAR 1331 SSIC 2012 SALLATS of

(20 MORRISON SEAL (14)3

(LOCATED INSIDE STRENGTH TERMINATOR 7564144)

O ANALYSIS RESULTS

UNDER WORST CASE TOLERANCE CONDITIONS SEALS COULD OVERLAP INTO TAPERED AREA BY .044 (14) AND .042 (20) 224

Lerrepeli

RECOMMENDATION

0

.

.

F

D

44

<u>_</u>

1. CHANGE TERMINATOR, DELCO DWG 7564144, AS FOLLOWS TO PROVIDE MORE SPACE FOR SEAL

FROM:	3.480	TO:	3.520
FROM:	1.000	TO:	1.040
FROM:	.390	TO:	.430
FROM:	.780	TO:	.820

2. CHANGE NUT, DELCO DWG 7563617, TO AS FOLLOWS TO PROVIDE MORE SPACE FOR SEAL (1)

.210

.190

FROM: .670/.660 TO: .630/.620

DELETE .130/.120 DIMENSION

DI:4

ADD .210

.190



١

D

,

• <u>ANALYSIS RESULTS</u> UNDER WORST CASE TOLERANCE CONDITIONS, AN ADEQUATE GLAND VOLUME IS AVAILABLE FOR THE SEAL.

o <u>RECOMMENDATION</u>

USE EXISTING DESIGN

O-RING SEAL (29)

し、自己になったための一般などのためです。

È

Ì

-

1

K

•••

177 200 200

 (LOCATED ON TAPER NUT 7564128

• ANALYSIS RESULTS

UNDER WORST CASE TOLERANCE CONDITIONS O-RING COULD BE OVERLAPPING TAPERED SURFACE OF GIMBAL HOUSING 7564123 BY .001.

• RECOMMENDATION

INCREASE LENGTH OF SEALING SURFACE ON GIMBAL FROM .350 TO .350.

REF DELCO DWG 7564123

MCRRISON SEAL 7563636 (LOCATED IN SPOOL 7564124

• <u>ANALYSIS RESULTS</u> UNDER WORST CASE TOLERANCE BUILDUP, THE "SEAL" VOLUME WILL EXCEED THE AVAILABLE VOLUME BY .008 IN³.

o **RECOMMENDATION**

- INCREASE SPOOL CAVITY LENGTH FROM .88 TO .90, REF DELCO DWG 7564124.
- 2. DECREASE SEAL LENGTH FROM .37 <u>+</u>.02 TO _37/.35 AND SPECIFY .37/.35 BE MET WHEN ON THE .275 - .276 MANDRELL. REF. DELCO DWG 7563636





53.5

$$\label{eq:matrix} \begin{split} \boldsymbol{M} = \boldsymbol{H} &= -i \boldsymbol{A} + -i \boldsymbol{H} \boldsymbol{E} + i \boldsymbol{e} + i \boldsymbol{M} + i \boldsymbol{N} + i \boldsymbol{P} \boldsymbol{N}$$

O-RING GLAND DESIGN

which the sing ing

ANALYSIS RESULTS

O-RING GLAND DESIGN IS PER PARKER DESIGN HANDBOOK OR 5700 FOR STATIC INDUSTRIAL TYPE O-RING SEALS.

RECOMMENDATIONS

RETAIN PRESENT DESIGN



the second s

SEAL (14) 7554780 .630 . 6.20 . 25 ,370 MIN Z .22 D 7564161 7554780 V, SEALA 7563617 ,701 ¢ Lung. VMAX 7554780 = .7854 (.74552-.32552) X.35 1331 1328 ¢ A MAX = . 12365m3 $V_2 MIN 7564141 = .7354 (.700^2 - .331^2) \times .37$ V2MIN = . 11055 in 3 LMAX INSTALLED = . 12365 $\frac{.12365}{.7854(.700^2 - .331^2)} = .4138 \text{ in Alash} \\ - .3700 \text{ in alash}$ <.0438> interference .665 ±.005 . 620 .305 ±,005 -. 250 0 کا قد ، 5.00 2 · 37 MIN :5 ±.005 1.015 35

$$SEAL (2) 756 3620$$

$$\int \frac{32}{72} \frac{32}{710} \frac{3}{10} \frac{3$$



E-11

SEAL 26 CCATO .620 MTN . 6003 Ô 497\$ 4082 .1921 :30\$.166 ø AIN .2208 MIN. GLAND AVAILAELE MAX VOLUME SEAL 7564132 $\mathbf{E}V_{1} = .7854 \left(.52^{2} - .142^{2} \right) \times .17 = .03341^{10}$ $V_2 = .7854 (.52^2 - .26^2) \times .32 = .05097 \text{ is } 3$ MAX INSTALLED ZERETH L,= . 03341 = . 1921 .7859 (. 4992-.1662) .05097 in 3 l2 = = . 4082 .7854 (.4992- .302) . 6003 mattled length anos



E-13

$$\begin{array}{c} \cdot \frac{13}{2} & \pm .07 \\ - \cdot .0475 & \pm .005 \\ 0.825 & \pm .015 \\ \hline \hline 1.245 & \pm .015 \\ \hline \hline 1.245 & \pm .0135 \\ \hline \hline 1.245 & \pm .0135 \\ \hline \hline 1.245 & \pm .0135 \\ \hline \hline 1.310 & \pm .020 \\ \hline \hline 1.310 & \pm .020 \\ \hline \hline 1.355 & \pm .0335 \\ \hline 1.855 & \pm .0335 \\ \hline 1.6355 \\ \hline 1.6412 \\ max \\ \hline \hline 1.6412 \\ \hline 1.6412 \\ max \\ \hline \hline 1.6412 \\ \hline 1.6412 \\ max \\ \hline \hline 1.6412 \\ \hline 1.6$$
2 .350 ŰÐ ±.010 O . 560 1.005 \neq 1 . 910 # .015 \mathcal{O} 6412 T MAX Ļ . 2688 ±,015 B Ð ±,003 030 ,2388 1.018 (20 1921 MAX SEAL LENGTH INSTALLED . ±.018 . 0467 -.018 = .0297 MIN CLEHIRANICE D ļ.,

SEAL - 7563636 (30) MAX VOLUME CALCULATION: $\mathbf{V} = \frac{1}{d\pi} \left[\left(d_{1}^{2} \right) - \left(d_{2}^{2} \right) \right] \times \mathcal{L}$ l, = .276 + (2×.135) d, = .546 Ø $V = .7854 [(.546)^2 - (.276)^2] \times .39$ d2 = .276 p V = .06798 in 3 max l = .39MOA VOLUME CAVITY : 100 .63 75641241 BSC BSC 150 (3) 36 36 36 Ľ 7556495 .003 MAX 12 4412 .444 & MAX [. 444 ø - 430 -CERMANC . 438 ø 1.05 .438 \$ 111 MAX 006 - .003 .065. HOLE MAX L 5003 X cut 150 = .0112 - 4609-+ . 4300 1413 MIN. CAUTY LENGTH . 87 MIN DEPTH (7564124) . 100 BSC .970 - (.4412 + .065) = .4609 $= .7854 \left[(.492)^2 - (.222)^2 \right] \times .4209 = .0598 in 3$

SEAL (7563636) MAX ling The when installed in min & gland. $V_1 = V_2$ $V_1 = .06798 \text{ in }^3$ V2 = .06798^{m3} = .7854 (.498)² - (.288)²] × L ,16506 L = .06798 [.498²-.288²].7854 .12764 L = . ### l,= . 52438 in - Lz . 4609 <. 06348 > inter ferme at worst cice. AVAIL . VOLUME GLAND MAX VOLULIE SEAL ΔV . 0598 in ³ .06798 in 3 <.00318in AVAIL LENGTH GLAND NAX LENGTH SERL 22 4609 in . 5244 in <-.0635 > (.39 MAX INITIAL PLIN) .4975 <-.0355> (.37 MAX INITIAL DIM)

E-17

3143 23 February 1932

COMMENTS ON CHESAPEAKE DIVISION TOLERANCE ANALYSIS OF BSURE CABLE TERMINATION SEALS

1. Possibly due to a lack of familiarity with the BSURE connector, several errors were made by CHESDIV in their analysis of the BSURE Cable Termination Seals.

1.1 MORRISON SEAL NO. 30

F

1.1.1 CHESDIV page 1 of 29: Seal No. 30 is 0.37 inches long not 0.36.

1.1.2 CHESDIV page 3 of 29: Two dimensions were called out on the drawings as basic and are not subject to tolerances as shown here.

1.1.3 CHESDIV page 3 of 29: In computing the minimum cavity length 0.10 inch was not added into the computation.

1.1.4 Delco page 4 shows a final possible interference of 0.008 in³. This is from a tolerance build up on six dimensions. A condition that would be present 0.0002% of the time. The Delco analysis shows the corrective steps that will be taken to eliminate even that remote possibility.

1.2 O-RING SEAL NO. 29

1.2.1 a. CHESDIV page 5 of 29: Dimension 0.045 should be 0.055, dimension 0.143 should be 0.153 for max condition, and dimension 0.14 should be 0.133 for maximum condition.

1.2.2 Delco page 3 shows a 0.001 inch exposure of the O-ring groove beyond the level under worst tolerance case. They will increase the sealing surface on the gimbal by .01 inch to preclude this problem.

1.3 MORRISON SEAL NO. 26

1.3.1 CHESDIV page 9: The wrong backup seal ring was used in this analysis.

1.3.2 Delco page 2: Shows adequate gland volume for the seal. No change to be made.

1.4 MORRISON SEALS NO. 14 AND 20

1.4.1 CHESDIV page 14: The 7563620-002 seal is not used in this assembly

1.4.2 Delco page 1: The seals could overlap into their tapered areas. The terminator end has been lengthened and the 7563617 nut is shortened to eliminate these problems under worst case tolerance conditions.

Enci (=) 1 DI CUTISTESTCEN Lin 3143 SSIC 2012

Technical Note 3100-3-81

APPENDIX F

Ì

с н. н. 1

Į

Ø

R. (1

.

FAILURE MODES AND EFFECTS ANALYSIS

OF

BSURE CONNECTOR SEALING SYSTEM

BY

PACIFIC MISSILE TEST CENTER

Prepared by:

Robert Polley, Code 3143

a fa fa fa ta ta

TABLE OF CONTENTS

Ņ

K,

-

Ľ

.

Ľ

· · ·

1

FOREWORD
INTRODUCTION
SUMMARY
ENVIRONMENT
PARTS QUALITY
FAILURE DEFINITION
FAILURE MODES
RELIABILITY BLOCK DIAGRAM EXPLANATION
DESIGN HISTORY
APPENDICES -
A - SKETCHES OF SEALING SYSTEM
B - FAILURE MODES AND EFFECTS ANALYSIS
C - CROSS INDEX IDENTIFICATION NUMBER TO DELCO DRAWING NUMBER F-35
D - SEALING SYSTEM BARRIER SCHEMATICS

F-2

A. 4.

Technical Note No. 3100-3-81

FOREWORD

سما د ا

D

This document was prepared to provide information on the failure modes of the BSURE plug in cable connector sealing system and the effects of those failures on the BSURE system.

Prepared by:

Robert Polley General Engineer Physical Systems Brance

Reviewed by:

M. A. Bondelia Head. Physical Systems Branch

Reviewed by

A. Scott Head, Measurement

Systems Division

Approved by:

R. Hattabaug Head, Range Development Departmen

This document has been prepared for information purposes only. It does not necessarily represent the official position or conclusions of the Commander, Pacific Missile Test Center (PACMISTESTCEN), and the Commander, PACMISTESTCEN, is not responsible for any action as a result of information contained herein. 1. <u>Introduction</u>. This report presents the Failure Modes and Effects Analysis (FMEA performed on the seals of the in-water equipment of the Barking Sands Underwater Range Expansion (BSURE) System. The FMEA is done in accordance with Task 101 of MIL-STD-1629A with the following exceptions: The FMEA is done only for the seals of the cable connector, Terminal and Transmission Unit (FATU), hydrophone, and tether cable. The identification numbers do not follow MIL-STD-780E but follow the 1970 version of MIL-STD-1629 and the FMEA worksheet format is simplified.

2. <u>Summary</u>. Appendix A presents sketches of the sealing system based on the BSURE as-built drawings of 1976 and the cable connector drawings of 1981. Appendix B presents the FMEA based on the sketches of Appendix A. Appendix C is a cross index of identification numbers to Delco drawing numbers. Appendix D presents schematics of the sealing systems with the seals shown as a series of barriers.

3. Discussion.

ġ.

Ð

3.1 <u>Environment.</u> The in-water units operate in sea water at a depth of 15,000 feet. They lie on the bottom in basalt rock and a thin layer of sandy mud. The temperature at that depth is 3°C. The units are installed from a cable ship. The maximum expected tensile loads during deployment are from 5,000 to 8,000 pounds at the surface, gradually decreasing to zero at the bottom (the cable is layed with 4% slack.) The maximum torsional load expected is 2 to 5 foot-pounds. The TATU will experience a minimum of 180° rotation depending on the swing of the cocoon and the waves. The maximum temperature of the surface is 32°C. However, the TATUs are stored below deck in air-conditioned spaces and are only in the sun a short time.

3.2 Parts Quality. All parts are 100% inspected for defects and deviations.

3.3 Testing.

3.3.1 Metals. All metal housings are helium leak tested.

3.3.2 <u>Seals</u>. All assembled seals are helium leak tested except those in the cable connector. Those are tested by vacuum.

3.3.3 <u>Assemblies</u>. All assemblies are pressure tested at 3° C and 7,500 psi for two hours with the exception of the cable connector.

4. Failure Definition.

4.1 Failure can occur such that the individual TATU no longer works (e.g., the hydrophone tather cable parting) but the rest of the string that it is in still works. This failure is non-catastrophic and the system will still function but in a slightly degraded mode around that TATU position.

4.2 Failure can occur such that the individual TATU no longer works (e.g., a short in the cable connector) and the string seaward of its position no longer works. This failure is catastrophic as the entire string will eventually be shut off.

4.3 Failures other than the TATU seals are not addressed in this FMEA. The mechanical hardware has been proof-tested (i.e., installed) at 15,000 feet for rive years. There have been no problems with any of the electronics in the TATU or the shore system. There have been no problems with deployment of the TATUs, the hydrophones, or their tether cables.

5. Failure Modes

Ĵ.

5.1 The Primary Seals of the BSURE TATU connector are the two seals at either end of the strength terminator. As primary seals, they are the only seals that are operating under the full ambient load for the life of the connector. The primary seals are the only seals in the connector that operate under full load (7500 psi) for 20 years, the rest of the seals in this connector are pressure balanced, that is the pressure is the same on both sides of the seal.

5.2 The intrusion of sea water into the connector is only possible if one of the primary seals should fail or if there is some porosity in the strength terminator or inner copper jacket outside of the primary seal. If either of the primary seals should fail then the gimbal housing would be forced down by the outside sea pressure and oil would be pushed into the voids in the strength member of the SD cable. The amount of oil that could be pushed out would be small, on the order of 40 - 50 cc's. The connector however would still be oil filled and no sea water could enter the cable at this time. However, the load is now taken by the secondary seals, the o-rings (10.21) and the fill plug (10.22). Although the connector is now considered to be operating at a degraded mode in that it is not operating at its full design capability it is working as the old BSURE Terminator was designed to work. The secondary seals of the new connector are the same seals that were operating as the primary seals in the old connector design. As that design was made with a 20 year life this implies that the secondary seals of the new connector should have a 20 year life if they are ever called upon in the event of a primary seal failure. In this condition (primary seal failure)' the connector is still filled with oil, there has been no sea water intrusion and the connector will still function as intended. In the event that the secondary sealing system failed sea water would not be present in the connector. The tertiary seal would take the full load and likewise be good for 20 years.

5.3 In the event of outer cable jacket failure there is no degradation of the connector. If during recovery the cable is cut down into the center conductor the center conductor will be flooded; however, this cable can be used for re-installation because the present system is capped at the strength terminator and pressure balanced so that water can't be forced up the cable into the connector. It is interesting to note that once the cable is flooded the connector is now truely pressure balanced. That is, the primary seals are no longer loaded. Thus, no driving force can be developed to allow the intrusion of sea water into the connector.

6. Relicbility Block Diagram Explanation

6.1 Some explanation is required to view the reliability block diagrams (Appendix B) in the proper light. Each of the blocks represent a particular physical part in the seal system through or around which a leakage could take place. The reliability block diagram has to be reviewed with the sketch of the particular seal system to sea where the leak paths could lie. It must be remembered that the leak paths are not only between the interfaces of the parts but could also be through the parts themselves due to porosity or pinholes. For example, at the interface of the first seal of the connector (10.02), with the housing (10.01) and the cable (10.03), the leakage could not only be at the interfaces but through the parts themselves. This can be more clearly seen in the schematic diagram in Appendix D.

In order to develop the reliability equation careful accounting must be taken by view the sketch of the area of concern as well as the reliability block diagram. A carefu design analysis must not only pay attention to the piece parts but also to the suppli the system quality control, quality control of piece parts and the assembly of those parts.

7. Design History

.

1

Ľ,

7.1 The original BSURE cable termination was designed to be a non pressure balanced connector, that is the oil on the inside would not be at the same pressure as the sea water on the outside. All the pressure would be held by the CuNi outer shell and the seals. The original BSURE termination was extensively tested in the laboratory under pressure and under tension, even going so far as to install two TATUs and one repeate in the ocean near Point Mugu. When the TATUs were installed at Barking Sands, how-ever, several problems were encountered causing the loss of several hydrophones.

Upon examination of recovered BSURE hardware, these problems were classed into two categories; One, a cable termination pull out and two, leakage. It is felt that both of these problems have been solved. The cable termination pullout problem has been solved through extensive testing in the Materials Laboratory at Point Mugu, bringing about the development of a new epoxy-mica mixture and a redesigned strength termination tube. The leakage problem has been solved by the redesign and testing of the sealing system for the SD cable. None of the other seals in the BSURE connecte system have shown any indication of failure in any of the recovered hardware to this date.

7.2 A second termination design was used to terminate the anode to the SD cable for the repair of A and B string. The major changes were that the cable connector was allowed to float, so that its interior cavity would be pressurized, also the ground pin and high voltage pins were coated with RTV silicone rubber to isolate them in the unlikely event of salt water intrusion.

7.3 When the Underwater Communication System Termination was designed this idea was carried further. The sealing system for the SDcable was redesigned along the lines that had been proven in seal testing at Delco, the new strength terminator was used along with the mica mixture. The coil cable assembly was still retained but oil filled silicon rubber boots were placed over the ground and high voltage pins rather than trying to coat RTV silicon rubber over them. This design also used the floating piston effect to pressurize the internal cavity of the connector.

7.4 The present BSURE termination design builds on all these ideas proven in actual installations and extensive laboratory tests. It is a pressure balanced design. However, instead of using the coiled cable assembly it uses the housing itself to carry the electrical ground and a redesigned center contact to carry the high voltage, relying on Multi-Lam contacts to provide a reliable contact thru the sliding connection. The same design concept used in UCS and proven in the laboratory test fixture is used to seal the SD cable entry into the connector and the concept of isolating the high voltage from the ground, is used. Thus, it can be seen that the present BSURE cable connector design is not a new group of untried components but is the result of a gradual evolution from one design that nearly worked, to a design that has been well proven both in a laboratory ocean simulator test chamber and by installation in the ocean at Barking Sands.

¹ Robert Polley, "SD Underwater Cable Strength Termination Design and Testing," No 3100-1-81 Capabilities Development Department, Code 3143, Pacific Missile Test Center, Point Mugu, CA.

APPENDIX

Ì

L

7

L

, ,

i

A

SKETCHES OF SEALING SYSTEM

F-7









APPENDIX

8

FAILURE MODES AND EFFECTS ANALYSIS WITH RELIABILITY BLOCK DIAGRAMS

D

.

-

.

والمراجع والمراجع والمراجع والمراجع

٠...

..... • ٩ . I, ----D I_. .

200

SYSTEM RELIABILITY BLOCK DIAGRAM





Ì Ļ Ď [• . . .

¥

10-CONNECTOR WITH CABLES - RELIABILITY BLOCK DIAGRAM



- 1

. .

10-CONNECTOR WITH CABLES - RELIABILITY BLOCK DIAGRAM

ļ

Ĩ

.

. .

.

.

.

I

Í,



d

•

Ľ

). 1

Ċ

ļ,

.

•

10-CONNECTOR WITH CARLES - RELIABILITY BLOCK DIAGRAM SD CABLE SECTION - 7557344



* SHORT CIRCUIT ESTABLISHED
TO SEA WATER
* * FULL AMBIENT PRESSURE

AN INSIDE OF CABLE

F-17

D . L -. Ē Ĺ • ĩ

•'. 1 = 1





Ï 2 • . D **...** 2

į.





SILORT

Ó . . Ľ Ļ

•





Ż

Ľ,

.

-

ì

Ĺ

E

•--

í

ļ

1

DIAGRAM 30-TATU END CAP, TETHER END-RELIABILITY BLOCK



ř

İ

.

-

¢-

....

.

Í

30-TATU END CAP, TETHER END-RELIAEILITY BLACK DIAGRAM





F-23



f

.. ł,

3

Subdystame TATH Assembly Identifiere Lovel: One Ref. Oraning: 7556515

-1

Ì

.

F

7

•

Í

•

i

ŧ

.

ESLINE TUTU FALLINE MODES AND EFFECTS ANALYSIS IN WATER SEALS

Date: 2 Get 81 Sheet 1 of 1

IDENTIFICATION MANDER		FAILURE	LOCAL EFFECT	END EFFECT	TENAKS
סו	Connector and Cusles: Connects SDL1 casle to TANE and class carries mechanical installation	Shert ta see uster	Shart hydroonane signals and share pawer to see water	Loss of all hydrophanes outbears of this connec- tion	In the event that a TATUS outBeard of this connector are
	land, the set signals,	CPE 1	Hydroenene signals and share pawer lest	All TATUS in this string insportative	fost, the TATU will act as an anese for an inseterminete
-		Haginariezi Bruns	Pleading of connector	Less of all hydrochanes outboard of this connec- tor	longth of time, then it will fail open causing all TATUS in the string to code operation.
28	TATU Ent Cust holds gimma and of commentary, carries entimated installation least, hydrostamo signals, pilot turn and store page	Shirt ta sea valar	Short hydrogeness signals and shore power to see weter. Apply pressure to 20.4, 20.9, and 20.10	Less of all hydronnenee outboard of this conner- tion	
		0 95 0	Hydrophuno signala ant shore panar last	All TATUS in this string insportsive	
		Hattarieni Braak	Floating of out can. Amily pressure to 20.4. 20.9, and 20.10	Loss of all hydrochanas exclosure of this conner- tor	
30	TATE Ent Cas, Tother Ent holds grappi and of car nucler, carries mathemical instalistics lands, nyere- phone signals, silet tune and same power. Also holds the hypersena tather	Shart ta Sab valur	Sharts hydrogeness signals and share power to see water. Amply pressure to 30.09. 30.10, 30.11, 30.12, 30.13, 30.14, and 30.15	Lass of all hydrochenes outdoore of this conner- tion	In the event that all TATUS outboard of Unis connector are lest, the TATUS will att as an areas for as intecordingte
	Cable provides power to the hydropoute and themsets the attentic signals from the	(1986)	Wareshene signals and shore pawer last	All TATUS in this string insportative	it will fail open chaing ail TATUS in
	Bydfignant)	Hocharica i Branc	Flanding of and cm. Apply pressure to 3%.05, 38,10, 30,12, 30,12, 38,13, 30,14, and 30,15	Loss of all mydruonones Authoriz of Unis connec- Lor	the string to cause operation.
Cabler gether signals and s	Hydropanno and Tothur Cable: gothors appastic signals and sense that to the TATE electronics	Hydroghang Lather Broat (start 13 140 votor er metastical Broat	Lass of Individual hydrophane	Degraduction of tracking solution in area of lest hydroshame, no offect an actor hydroshamas	Fuses will blow dis- connecting this TATU from the groken hydromens. The remaineer of the TATUS will continue to work.
			Lana of factividue) Nyaraahane	Degradition of tracking solution in area of lost hydroenene, no offect on other hydroenene	

· · · ·

1

...

والمحاج والمحاج والمحاج والمراجع والمحاج والمحاج والمحاج والمحاج والمحاج والمحاج والمحاج والمحاج والمحاج والمح

.

ENFIFICATION MPDER	ITEN NAME AND FUNCTION	FAILLINE	LOCAL EFFECT	END EFFECT	IGWINS
18-06	Lanor Caspor Jecant: Carries voltage and signels	Loningo	Copper and stael correce	Vill result in weekening the cable second the recovery attempts necessary	Fuil amplement : an inside of a will pressure seeis in terms an orth ends a section
19.03	Liner Pelyethylane 7562758	Leakinge	Will short out signal ,and pawer	All TATU outboard of the brook will not operate	
19.04	50 Cable Outer Polyotaylane	Laninge,	Will allow see ustor to ground tape and to 10.03	Name	The cuter come correce slight will not affec system appress
14. 11	Corv, [storconnet Cable 7386678	Lookingo az 18.36	Short TATU signal and shore power to see weter	Less of all TATUS out- bears of this connection	All of these as are in oil and sure balances. would be very cuit to disela oil with see w
10.30	Seel, Care 7584773	Lastage at 10.27 er 10.31	Short TATU signal and shore power to see water	Loss of all TATUS over Dears of Lbis connection	All of these s are in cil and sure delanced. would be very a cult to display oil the see w
19.27	Seeni, Cable 7554773	Lanimgs at 18.29 er 18.36	Share fills signal and share pawar to see weter	Loss of all TATUS over board of Lois connection	All of these so are in all and sure balanged. whild be very a cuit to display oil the sam we
10.29	0-41 ng	Leadinge	Shert TATU signei and shere paner to see weter	Loss of all faits out- board of this charaction	All of these so are in oil and sure balanced. while be very d calt to displac eil with sea we
14.23	Ginhilled Hausing 7354598	Lastage et 12,23	Shart TATU signal and share genur to see votor	Loss of all TATUS out beard of this connection	All of these set are in all and ; sure balanced. while be very an cuit to displace
10.24	Laten Cable Bost 7554776	Lastage et 10.27	Alles uster to 10.30	Narte	all with see wet
19.27	Seen1, Cable 7554771	Lookage at 10.24	Allow water to 10.30	Nate	
19.23	Gimbolled Housing 7554895	Lastage at. 10.28	Allow uncer to 10.29	Nana	
10. 29	0-ting	Leonage at. 10.23	Allow water to 10.29	Nane	
18.24	Intenn Cable Bost 7554776	Lookayo et. 10.23	Allew weter to 10.22 and 10.27		
10.23	Glumpiled Heasing 7554595	Lookaye et 10.24	Allew water to 18.28 and 10.27	Nane	
10.22	F111 F1ug 7554770	Leakage	Allew weter to agin all covity of connector	Nana	
10.25	0-41 ng	Lookayo at 10.01	Allow water to main all cavity of connector	Nene	
19. 51	Termination Howing 7554742	Leshage at 10.25	Alles weter to main all cavity of convector	Name	

F-25

.....

.

-Ď -E

Ì

I.

insystem: Connector with Cables Manture Loval: Two Met. Grawings: 755625

Ì

•

ľ

.

D

L

.

. •

•

Q

ESUME TUTU FAILURE MODES AND EFFECTS AMALTSIS UN VATER SEALS

Date: 1 Oct 81

Sheet	2	af	7	

IDENTIFICATION NUMBER	ITEN WHE AND FUNCTION	FAILURE	LOCAL EFFECT	ENO EFFECT	REMARKS
<u>w.a</u>	0-41mg	Lestage 45. 10.01	Allow water to 10.25	Hene	
10.01	Terminacian Housing 7554742	Lessage 45. 10.21	Allow weter to 10.25	here	
10.29	Ginnei Beut. 7554580	Lestage 42 10-01	Allow water to 10.21. 10.22, and 10.24	here	
10.29	Giana i Baos. 7554689	Hole or Tear	Allow weter to 10.22. 10.22. and 10.24	Nana	
10.03	50 Cable Lanar Pelystaylane 7536758	Lastage at. 10.02	Alles water to 10.07	Veter	
10.02	Sani, Camie Sheeth 7563836	Lookage at. 10.03 or 10.01	Allew weter to 10.07	News	
19.02	Terminacian Housing 7384742	Lottage st. 18.02	Allew value to 10.07	Ness	
10.02	50 Cable Laner Pelystaylame 7563758	Lankage 48. 10.07	Alles weter to 10.08 and 10.10	Name	
10.07	Sani, Cable Sheeth 7564129	Lashage 28. 10.03 er 10.01	Allew water to 10.08 and 10.10	Name	
10.41	Terminacies Housing 7564742	Lannage at	Alles water to 10.08 and 10.10	Nervo	
10.09	Land Bearing Plate	Lookago 41. 10.10	Short signal and shore- power to see valor	Loss of all TATUS over beard of Unis connection	
10.10	0-41 mg	Lookage	Short signal and shore power to see water	Loss of all TATUS out- bears of this connection	
10.03	50 Cable Long PolyetBylese 7563758	Leatage #1. 10.10	Short signal and shore power to see veter	Lass of all TATUS out- based of this connection	
19.01	Termination Housing 7554742	Lashage 46. 10.08	Alles water to main eil cavity of connector	Nexter	
10.09	Loss Bearing Mate 7564 <u>131</u>	Lettage #1 10.08	Alles weter to ease eil covity of connector	Nexe	
10.08	9-41mg	Lassage at. 10.01 er 10.09	Allow votor to main oil cannot or commetter	Nens	

.....

nture Level: . Grawtnag 71		ر بر ۲ مربع الفلي يا ۲ م	HODES AND EFFECTS ANALYSIS IN WATER SEALS		Date: 2 G Sheet 1 of
BITIFICATION NUMBER	TTER NAME AND PUNCTION	FALLURE	LOCAL EFFECT	BIO EFFECT	REMA
11_10	0-41ng	Lookage	Allow weter to 11.09	None	
12.08	Femile Isolegien Tupe 7564147	Lessage st 11.10	Allow water to 11.09	Mane	
n u	Mie Isolation Tube 7566266	Lestage st 11_10	Allow weter to 11.09	Nena	
л . 19	0-ting	Leekege	Shert TATU signe) and shere power to sad water	Loss at all TATUS entr- Doore of this connection	All of the are in all sure balane woold be ve cuit to dis all with se
12.38	Famile Isolation Tump 7566147	Leonage 21 11,09	Shert TATU signal and shore power to see water-	Lass of all TATUS ont- beard of this connection	All of the are in all sure taland whold be wo cult to dis all with so
11.02	Hele Laslation Tube 7564246	Loonage st 11,09	Shert TATU signai and shore power to san water	Lass of all TARUS owe- beard of Unis connection	All of the are in all sure balance whald be we call to dis all with so
12.07	8ams Saoi 7564242-082		Shert TATU signal and shire pawer to san vacar	Lass of all TATUS out- bound of this connection	All of these are in all sure balance would be ver cuit to also all with te
17.03	Male Isolation Tump 7564246	Laurage of 11.07 or 11.04	Shart TATU signai and share pamer to see wetar	Loss of all TATUS out- beard of Lints connection	All of these are in oil a sure balance useld be ver cuit to disp eil with se
11.94	Seel, Entens TermingEler	Lookage	Shert TATU signal and shere pawer to see weter	Loss of all TATUS out- Deard of Litis connection	All of these are in oll a sure balance useld be ver cuit to disp all with see
пп	Terwingi Intgon Cable 7564127	Laskage st. 12,04	Shert TATU signal and shere power to see veter	Loss of all TATUS out- board of this connection	All of these are in all a sure balance whuld be ver cuit to disp all with sec
11, 26	Sang Sani 7564142-002	Lookaga	Shert TATU signel and shere gener to see water	Loss of all TATUS ous- beard of Lits connection	These sadis oil and pres belanced. I be very diff diselace the See weter
יד, 38	Frante Isolacion Tubo 7566147	Lestage at 12.06	Shert TATO signel and shere pener to see water	Loss of all TATUS out- beard of this connection	These seels of an pres Defance () De rery diff displace the See water
11.05	0-41 ng	Leekage	Allow water to 11.03	Nane	
шa	Lond Boaring Plate 7564231	Laskage st. 11,05	Allow water to 12.03		
11.00	Female Iselation Tube 7564147	Laskage at 11.15	Allow weter to 11.03	Hene	
12.03	9-41 mg	Laakage	Shart signal and share power to see water	Loss of all TATUS out- bears of this connection	All of these are in oil an sure balanced whald be stift

valid be difficul to displace the d with see weter

Р. 1

.

۰.

Į.

-

• <u>.</u>

•

-

Ľ L

- 8

• .

-.

۰.

ار این از معرف المراجع بر این محمد می از مراجع این از معرف می می وارد. محمد محمد می محمد می محمد می محمد می محمد می محمد می محمد می محمد می محمد می محمد می می می می می می می می می م

Subsystem: TATO Ent Cas Identary Lovel: Tus Ref. Granne: 756619

Ň

.

Ļ

.

E

÷.

ESUME TUTU FALLUME MODES AND EFFECTS AMALYSIS IN WATER SEALS

Date: 1 Oct & Sheet 1 of 2

ENTIFICATION MANAGER		FALLURE	LOCAL EFFECT	DIS EFFECT	tenat
28.17	Care Intertannet Caele 7556676	Lescage	Shert TATU signal ane shere pewer to see weter	Loss of all TATUS per- Dears of this connection	Ail of these are in all o sure balance would be ver cult to dise ail with se
20.15	Seal. Core 7334773	Lookage	Shurt TATU signai and shure power to see water	Lass of all TATUS out- beard of this connection	All of these are in all a sure balance would be ver cuit to dist all with see
28.12	Letter Cable Speel 7394771	Leenage .	Share TATU signal and share pawar to see vector	Loss of all TATUS out- board of this connection	All of these I fo ni ena sure ist ena ter sc biane bets at tits see attiv Ite
3.13	(-41mg	Leonago	Shart TATU signal and share pawar to see weter	Loss of all TATUS out- boars of this connection	All of these are in oil a sure being unuid be ver Cuit to dis oil with se
28.03	Ever Case, TATE 7354648	Lastage	Shart TATU signal and share pasar ta see voter	Loss of all TATUS out- boore of this connection	All of thes are in off sure belanc vesid be ve cuit to dis eil with so
28.14	Letertae Cable Seet 7554776	Lastage	Allew water to 20.16	-	
28.13	Seesi , Capie- 7554773,	Lookage	Alles weter to 20,15 or 20,15	Name	
28.03	End Can, TATE 7354663	Lookage	Alles water to 20.15	Nène	
28.12	0-thug	Lookage	Alles weter to 20.15	Nene	
29. 18	Internese Cable Boot. 7954776	Hele or Toor	Alles water to 21.15	Name	
20.13	Lecarcan Cable Bost. 7554776	Loningo	Aller water to 20.12	Hene	
29. 43	End Cap TATE	Lantage	Alles water to 20.12	Name	
28.04	Ginnal Boot 7534589	Lonnage	Allew veter to 20.18 and fill plug 7554595	None	
28.02	TATU Herestre: 7554698	Loonage by 20.11	Alles weter into elec- trenict	Loss of all TATUS out- Deers of this TATU	
22. 63	End Cap 7670 755-4608	Lookago Vy 20.11	Alles uster into elec- tranics	Loss of all TATUS out- bears of this TATU	
20. 11	0-41 mg	Lookage	Allew water into elec- tranics	Loss of all TATUS out- beard of this TATU	
29.10	Feed Thre Terminal Pin 7556356	Lesteşa 87 20.08	Allew weter into elec- tranics	Loss of all TATUS out- bears of this TATU	It is very that water reach this the cavity become pres balanced wh of water he This level would net r pin or care
23. 09	Bu i kimeet 7359424	Leekege 07 20.08	Allew weter into elec- trenics	LESS of all TATUS out- beend of this TATU	It is very that weter reach this the cavity become pres balances we of weter he This level

Subsystam: TATU End Cap Igenture Level: Two Ref. Graning: 7556519

-

Ô

Ľ

Ċ

L

•

i.

. !

ESURE TUTU FALLURE HODES AND EFFECTS AMALTSIS LII WATER SEALS

Date: 1 Get #1 Sheet 2 of 2

IDENTIFICATION NUMBER	TTEN HANE AND PUNCTION	FALLURE	LOCAL EFFECT	00 177657	temas
22.08	Loculated Food Thre Terminal, 7386423	Leetsee 5y 23.03. 28.19	Allow uster into elec- tranics	Lass of sil TATUS out" Deare of Chis TATU	It is very unlike that weter veuid reach this area a the cavity veuid become pressure balances when 30 (of value had intr This level of wall usuld not reach to pin or careate
29.42	TATE Housing 7554588	Lastage by 28.07	Alles unter to 20.11	Hane	
22.03	Ent Cas, 7x70	Lookage by 20_07	Alles water to 20.11	Mene	
29.07	Q=Ring	Lookage	Alles weter to 20.11	Nene	
29.02	TATE Housing 7554590	Lookage by 20.08	Alles weter to 20.07	-	
28.02	End Cap, TATU 7564663	Lasitage by 23.08	Alles weter to 22.07	Name	
28.05	0-Hing	Leanage	Alles weter to 20.07	Nene	
29.42	TATE Housting 7554690	Lastage by 23.06	Alles water to 20.07	Ngant	
29.06	Ptug. F111 7554770	Lastage	Alles weter to 20.07	Nene	

٠.,

2

Sumsystam: TATU Ene Can, Tetner End Lanature Lavel: Tus Ref. Drawing: 7556518

ľ

.....

.

₹ •__

.

ļ

.

مر مر

BSURE TUTU FALLUME MODES AND CFFECTS AMALYSIS IN VATER SEALS

Date: 28 See Al Sheet 1 of 2

er. Drebingr /3					The T Seeks
	TTEN NAME AND PUNCTION	FALLURE	LOCAL EFFECT	DIO EFFECT	temaks
3 0. 13- 1	Pin, Foos Thru: Fooss Electrical Signal from Techor Cable to TATU Electrovica	Lonings	Shert hydrognene signai ta see weter, silow see water inte cavity between builmende	Loss of signal from hydrognome, possible snorting of TATU electronics	The space between buikness of the will emulite su sure before enter where gathers to short out the T/ alegtrunics
¥2. 23-2	Ma, feed Thru: Feeds Veitage ta the Hyero- passe	Leakage	Shert voltage ta sea weter, allew water inte cavity between buikheags	Loos of signal from hydrophone, possible snorting of TATU electronics	The space between the interest of the hulkness of the will equalize pr sure before enained wetwo gathers (a short out the Ti electronics
12.13+1	Min, Feed Three Ground for Veltage to Hydrophone	-aninga	Allan weter into cavity because asituments	Possible snorting of TATU electronics	The space between builtheads of the will equalize pr sure before ena weter gethere to short out the T elastronics
33.23	Saal, Tatlar Paus Thru	Lasingo et corunic ping (38323	Allen weter inte cavity between buikheese	Peasible shorting of TATU electronics	The space between buildness of the vill equalize or sure before ensu- vator gathers to TA short out the TA electronics
¥4.29	Saol, Tether Food Thro	Lookago et. fond tirus pino	500 30.33-123 store	5aa 38.33-1, -2, -3 asovo	The sease because buildness of the will equalize pr sure before enou- water gathers to short out the TA electronics
38. 32	Hydrogname Cable, Wire; Graund for Voltage ta Hydrogname	Laskage	Allaw pee weter to feed tare pin 30,33-3	Nana	Weter in the cas wires implys a c the vires and ca vith weter in hy phone also see 40
39. 30	Nyerephone Cable, Wirs: Foods Veltage to the Hydrophone	Laningo	Short voltage to see weter, silow see weter to feed thre pin 30.12-2	Loss of signal free hydrophene	Veter in the cab vires implys a ca the vires and cat vith veter in hys prese also see 40
38.29	Hydrophane Cable, Vire: Foods Electrical Signal from Tether Cable to TATU Electronica	Leolinge	Short hydrophane signal to see unter, allow see unter to food thru pin 30.33-1	Loss of signal from hydrophone	Water in the cabi wires implys a cu the wires and cab with water in hys phone also see 40
30. 28	Sani, Tether Fead Thra	Leakoge st. food täre pine	See 30.29, 30.30, and 30.32 above	See 30.29, 30.30, and 30.31 canve	
39. 28	Seal, Teller food Thru	Lantago et. ant cap	Alles weter into cavity between buildleads	Presible shorting of TATU electronics	The state between builtness of the vill equalize pre- sure before enoug water gathers to snort out the TAT electronics
39. 03	Ene Cas, Tethor Ene	Lookago at. Saol (30, 28)	Alles uster into cavity between buikheads	Possible shorting of TATU electronics	The space between builtnease of the will equalize gre sure before enoug water gathers to short out the TAT electronics
39.27	Seal, Tether Cable Care	Leenage	Alles water to tether feed thru seel (30.28)	Rene	011 would first b pressurized to 7, pai before weter could reach seel 30.28. Chances a water reaching th seel would be see
30.25	nyananana Cable	Lassinge	Allew water to tether feed thre seal (38_28) F=31	Name	

F-31

Summystame TATU Ene Can, Totner Ene Identure Louel: Tun Ref. Drawing: 7555528

.

Ň

L

.

Ċ

Ē

.

• .

. 1

۰. 1

ور بر در بر بر از بر مرد مرد مرد مرد از مرکز بر مواند مرد مرد مرد مرد از مرکز بر مواند مرد مرد

ESUME TUTU FALLUME MODES AND EFFECTS AMALYSIS IN WATER SEALS

10 **- 1 V**

Secor 28 See 81. Sheet 2 of 3

		FAILURE	LOCAL EFFECT	CHO LIFEST	TEWAKS
30. 03	Ent Cas, Tother Ens	Loonage at 38, 27	Allow water is tether feed thre see! (30,28)	Hene	311 would first pressurized to 7 psi before water could reach seal 30.28. Chances water reaching t seal would be so
38, 05	Tether Cable last	Lockage	Alleu water between beet and tether caple	Hene	This is pressure balances. The o would be displac grammily by gav action and tighl action
19.23	Core-Intertennest Casle	Leanago	Short TATU signai ana shore pewar ta sea watar	Loss of all TATUS out- Deard of this connection	All of these set are in cil and p sure balanced. would be very di cuit to displace of with see write
30. 24	Sami Care	Loamage	Shart TATU signal and share paser to see water	Loss of all TATUS over Deard of Unis connection	All of these set are in eil and pr sure belanced. I would be very di cuit to displace eil with see woth
38.23	Samoi, Cable	Leekege	Shart TATU signai and share power to see votor	Loss of eil TATUS over board of this connection	All of these sea are in eil and pr inre belances. I which be very di Cuit to display all vith see wote
34. 22	0-41mg	Leakage	Shert TATU right and shere power to see weter	Loss of all TATUS over Deard of this connection	All of these see are in gil and pr sure belanced. I would be very dif Colt to give ion oil with see wate
38. 23	Ent Cap, Techer	Leekage.	Short TATU signal and shore power to see vecer	Loss of all TATUS ord- board of this connection	All of these see are in oil and pr sure belonces. I would be very dif this to displace oil with see wate
30.19	Q=Ring	Laskage	Alles water to 30.22	Nene	
39.18	Inten Cable Boot	Leakage	Allow weter to 30.24	None	
30.20	Samel, Cable	Lookage	Allew water to 30.22 or 30.24	Name	
30. 03	Ent Cas, Tether	Losinge	Alles water to 30.22	None	
30.18	Letzan Cable Best	Hele or Tear	Alles weter to 30.24	Nana	
30.15	Intern Cable Boot	Lookage	Alles weter to 30.15	Name	
38. 83	Ent Cap, Tether	Leekage	Alles water to 30.15	None	
10.04	Gimel lest		Allew water to 30.18 and 30.25	Name	
30.04	Gimpel Bast	Hole or Toor	Allew water to 30.18 and 38.25	Nene	
39. 03	End Cap, Tether	Lessage	Allow water to 30.10 and 30.25	None	
30. 01	TATU Heusting	Leanage	Allow weter fets elec- tranics	Loss of all TATUS out- beens of this TATU	
30. 03	End Cap	Lestage	Allow weter into elec- tranics	Lass of all TATUS out-	
39.17	0-Atng	Leakage	Allams water into elec-	Loss of all TATUS out-	
39. IS	Mn, Food Thre Terrinal	Loonage	Allens water fets eler-	Lass of sil TATUS ext- bears of this TATU	It is very unlitud that water would reach this area as the cavity would became pressure belances when 30 c
Subsystam TATU Ens Cap, Tetner End Iganture Lavel: Tun Ref. Drawing: 7356518

S

-

-

Ì

ļ

.

•

i

I.

ESURE TUTU FALLURE MODES AND EFFECTS ANALYSIS IN WATER SEALS

Cata: 28 See 41 Sheet 3 ef 3

LOENTLFICATION HUMBER	ITER MARE AND PUNCTION	FALLURE	LOCAL EFFECT	DIG EFFECT	IDWAKS
32.09	ên î khoas	Lanage	Allous water into elec- tranico	Lass of all TATUS out- bears of this TATU	It is very unital that water would reach this area to the cavity would became pressure balances whot 10 of water had intr
30.14	Landiatar Food Thru Teruinai	Leanage	Allows water into elec- trunics	Loss of all TATUS out- boars of this TATU	It is very united that water would reach this area a the contry would become provide balances ween 10 of water hos inter
30.13	Ma, Foui Thre Tervinai	Shart Teenege	Sharis hydroshana, allous water fets electronics	Less of hyperushana, Less of all TATUS outboard of this TATU	It is very unitar that weter vehic reach this area a the contry vehic became produce belances with 20 o of veter has inter
38.12	Ma, Post Thro Terming)	Shart Teatage	Shartz hydrogenen, allows water into electronicz	Loss of Hyersphene. Loss of all TATUS extenses of this TATU	[2 is very unitad that wear would reach this area at the cavity vould became pressure belances when 30 (of wetar had inter
38, 12	Pla, Food Thre Torains)	_ L initago	Allows water into elect tranica	Loss of all TATUS ang." Boore of Links TATU	-It is very unlited that veter vesid reach this area as the cavity vesid become pressure balances when 30 (of veter has intro
32.13	lasulatar Food Thru Teruinal	Lonnage	Allene water into elec- trunics	LOSS of all TATUS est- Deers of Lnis TATU	It is very unifact that user usual reach this area as the cavity usual become pressure that the second second of user has intro
33, 29	Bu i thead	Lestings	Allows water ista elec- trunica	Lass of all TATUS aug- beard of this TATU	It is very unifuel that water veule reach this erve as the cavity tould became pressure beinness with 30 c of water has intru
39. 01	TATU Housing	Loonage	Allows weter to 30.16	Nenz	
30.03	Ent Cap	Lestage	Allene water to 30.16	Nene	
35. 08	0-ting	Leanage	Alleus weter to 30.15	Make	
38.07	P1wg F111	Lashage	Allens water to 30.16	Marup	
30. 01	TATE Hereing	Loningo	Allows water to 30.15 or 30.08	hane	
30. 03	Ent Cap	Loonoge	Allens water to 30.08	Name	
30.05	0-R1ng	Loonage	Allows weter to 30.08	New	
38. 61.	TATU Harsting	Leanage	Allows weter to 38.06	Nore	
30.02	Boot, End Cap	Leakage	Allems water to 30.06	Nene	

/

____**|**

Summystam: Hydraphano ang Tether Camie Idanture Loval: Tun Mef. Grawing:

Ì

۵

5

ESURE TUTU FALLURE HODES AND EFFECTS AMALYSIS LIN WATER SEALS

Date: 24 Sep 41 Sheet 1 of 3

.....

	ITER HARE AND PUNCTION	FAILURE	LOCAL EFFECT	ENO EFFECT	REWARS
48.09-1	Food Thru Shalder Pinc Foods Electrical Signal from Hydrosene La Techor Cable	Loonage	Short signal to see water, allow water into hydro- phone Covity	Lass of signal from nyare- prene	very unifacity the semi will lead as is pressure balanc Other TATUS in str will still functio
46. 09-2	Food Thru Shalder Maz Foods Valtage to Hydro- phone	Laanaga	Short voitage to see vator, allev vator into hydrupnene cavity	Loss of signal from hydro- phone, blown fuze in TATU	Very unlikely the seel will leam as is pressure balanc Other TATUS in str will still fungtion
44, 09-5	Food Thru Shalesr Mot Ground for Voltage ta Hydrophase	Laskage	Aller wetar inte hydro- phane cavity	Depends on quartity of weter, a sector annuat webid have no offect	Yery unlikely the seal will leak as is pressure balanc: Other TATUS in str will still function
44, 19	Sadi Tetilar food Thro	Lockogo	Shart and hydrochand, allow water into hydro- phone county	Lass of signal to hydro- phone	Very unitary the seei will leas as is pressure belance Other TATUS in str- will still function
4.12	Hydruganne Eane	Laakaga er Hale in Base	Alles weter time hydro- phone carity	Depends on quantity of weter, a small" amount would have no effect	Yery unificity the semi will leas as ' is pressure balance Other TATUS in stru- will still function
44. 08	Lanur Hydrogiano Baas	Leanage	Alles water into hydrom phone cavity	Loss of signal from nyara- phone, blave fute in TATU	Very unitary the seni will leak as ' is pressure belance Other TATUS in stru- will still fumction
* 4 .08	Nyarashana Susport Elanant.	Lashage	Allen water into hydro- phone cavity	Loss of signal from nyaro- phone, aloue fuzz in TATU	Yory unitary the seel will leas as i is pressure balance Other TATUS in stru- will still function
42.07	Saal Tether Casle Care	Lookaga	Alles veter to 40,09 and 40,10	Pessible less of signal	Very unitarity the seal will leas as i is pressure balance Other TATUS in stri- will still function
44. 02	Nydruphana Base	Loombye er hele before 48.07	Allew water to 40.09 and 48.10	Peasibly less of signal	Lass of signal depends on lass pat: Very unlikely the seel will less as 1- is pressure balance Other TATUS in stri- will still function
44.08	Cable Techer	Lannage er Role im coble Jacket	Alles voter to 40.09 see 40.10	Peasible less of signal	Loss of signal comments on loss patt Also allows water to TATU and.
49.01	Hutrastana Sast Outer	Lesson	Alles uster between inner	1000	Cap tether and 30.25
	,		and exter best		Also allows water to TATU and
40. 02	Hydrophone Basic	Lookage	Allow weter between inner and enter best	None	Also allows water to TATU end
44. 63	Lover Tether Cable Boot	Leasage	Alles wher between best and cable, weter on 40.07	Nana	Also allows water to TATU end
48.04	Upper fether Cable Sect	Lostage	Allew voter between best and cable, veter an 40.07	hene	Also allows water to TATU and

Tuess then 44 cc

APPENDIX

f.___

.

i.

C

CROSS INDEX IDENTIFICATION NUMBER TO DELCO DRAWING NUMBER

Block Diagram Number	Delco Drawing Number	Nomenclature	Sketch Number
10.01	7554742	Housing, Termination	9
10.02	7563536	Seal, Cable Sheath	1
10.03	7563758	SD Cable Inner Polyethylene	9 1 3 3
10.04 10.05	7557344	SD Cable Outer Polyethylene	3
10.06	7557344	SD Cable Inner Copper Jacket	2
10.07	7564139	Seal, Cable Sheath	2
10.08		0-Ring	· 5
10.09	7564131	Load Bearing Plate	5
10.10		0-Ring	3 2 5 6 4
10.11		0-Ring	12
10.12		0-Ring	13
10.13	7564142-001	Band Seal	19
10.14	7564142-002	Band Seal	21
10.15	7564147	Female Isolation Tube	22
10.16		0-Ring	23
10.17		0-Ring	23 24
10.18	7564146	Male Isolation Tube	25
10.19	7564138	Seal, Intercon Termination	25
10.20	7554589	Gimbal Boot	17
10.21		0-Ring	15
10.22	7554770	Fill Plug	28
10.23	7554595	Gimballed Housing	28 31
10.24	7554776	Intcon Cable Boot	35
10.25		0-Ring	55 15
10.25	7554595	Housing, Gimballed	31
10.27	7554771	Spool, Cable	32
10.28		O-Ring	
10.29		0-Ring	34
10.30	7554775	Seal, Core	33
10.31	7556676	Core Intcon Cable	30
11.11	7564127	Terminal Intcon Cable	36 37

10 - Connector with Cables

Ì

K

.

1

•

1.

20 - TATU End Cap

Ι,

•

.

۵

Ĺ

•

, . . .

Block Diagram Number	Delco Drawing Number	Nomenclature	Sketch Number
20.01	7554588	Boot, End Cap	6
20.02	7554590	TATU Housing	3
20.03	7554593	End Cap, TATU	3 2
20.04	7554589	Gimbal Boot	17
20.05		0-Ring	20
20.06	7554770	Plug, Fill	8
20.07		0-Ring	21
20.08	7555423	Feed Thru, Terminal	
20.09	7555424	Bulkhead	5
20.10	7555356	-	4
20.11	/ 333330	Feed Thru, Terminal Pin	
20.12		0-Ring	22
	7651774	0-Ring	34
20.13	7554771	Spool, Cable	32
20.14	7554776	Cable, Boot Intcon	35
20.15		0-Ring	33
20.16	7554775	Seal, Core	30
20.17 20.18	7556676	Core, Intcon Cable Blank	36
20.19		0-Ring	19

Block Diagram Number	Delco Drawing Number	Nomenclature	Sketch Number
30.01	7554590	TATU Housing	3
30.02	7554588	Boot, End Cap	6
30.03	7554594	End Cap Tether	6 2
30.04	7554589	Gimbal Boot	17
30.05	7555355	Boot, Lower Tether Cable	41
3 0. 06		0-Ring	19
30.07	7554770	Plug, Ffil	8
30.08		0-Ring	20
30.09	7554590	Bulkhead	4
30.10	7555349	Feed Thru Terminal Insulator	13
30.11	7555356	Pin, Feed Thru Terminal	14
30.12	7555356	Pin, Feed Thru Terminal	15
30.13	7555356	Pin, Feed Thru Terminal	16
30.14	7555423	Insulator, Feed Thru Terminal	5
30.15	7555356	Pin, Feed Thru Terminal	5
30.16		0-Ring	21
30.17		0-Ring	22
30.18	7554776	Intcon Cable Boot	35
30.19		0-Ring	.34
30.20	7554771	Spool, Cable	32
30.21 30.22 30.23		0-Ring	33
30.24	7554775	Seal, Core	30
30.25	7556676	Core Interconnect Cable	36
30.26	E511281	Hydrophone Cable	C C
30.27	7554781	Seal, Tether Cable Core	40
30.28	7555357	Seal Tether Feed Thru	44
30.29	ES11281	Hydrophone Cable Wire	Č.
30.30	ES11281	Hydrophone Cable Wire	C_1 C_2
30.31	ES11281	Hydrophone Cable Wire	
30.32	7556497	Plug, Tapered Alumina Ceramic	C ₃ 45
30.33	7555607	Pin Feed Thru	46

30 - TATU End Cap, Tether End

....

ľ

(

.

Ŭ

•

ſ

Block Diagram Number	Delco Orawing Number	Nomenclature	Sketch Number
40.01	7554814	Hydrophone Boot, Outer	
40.02	7555353	Hydrophone Base	4
40.03	7555355	Boot, Lower Tether Cable	41
40.04	7555354	Boot, Upper Tether Cable	51
40.05	7554813	Hydrophone Boot, Inner	10
40.06	7555352	Hydrophone Support Element	14
40.07	7556984	Seal, Tether Cable Core	3
40.08	E511284	Cable, Tether	
		-	C, C ₁ , C ₂ , C ₃
40.09	7555608	Pin, Feed Thru, Sholder	7 7
40.10	7555357	Seal Tether Feed Thru	8

40 - Hydrophone and Tether Cable

.

ģ

.

Ľ,

D

.

Į,

•

.

•

. • •

A State State States

•

APPENDIX

. .

Ì

-

•••

. .

•

İ,

D

SEALING SYSTEM BARRIER SCHEMATICS



.

.

Ì





•

I

D

. . .

١.

.

1

an an an an an an an



30-TATU END CAP, TETHER END

. . .

Ì

-

•••

Ď

.

r te

ر. م

,

. •

F-43



متنعته

ļ

C

.

Į

l

, ` , `

_

D

ŗ

.



. .

F-44

APPENDIX G

ر) ۲

Í

•

.

•

È

MINUTES OF BSURE REPLACEMENT PRELIMINARY DESIGN REVIEW MEETING

5 NOV 1981

		• • • • •	ngla	
		UNCL FFFFED	JAN 15 19	
	<u> </u>	AIR-6303D/JGC 630-SL-007	AV 222-9182	یر میں اور میں میں اور اور اور اور اور اور اور اور اور اور
	•		•	 An additional statistics and statiste and statistics and statistics and statistics and statistics
1a.	Distribution	a		3. Give process is product the fact that is a required As not "morement of a loss the
ŧ				4 La orner su envel processing a readu shis energia su a avec a serie
				ವರೆಗಳಕ್ಕೆ ಭರದಿದ್ದ ವಿಡಿದಿದ್ದ ನಿರ್ದೇಶ ಮತ್ತು ರಂಗಿಸಿ ಕ್ರಮಿಗಳು ದರೆಗಳಕ ಭರದಿದ್ದ ವಿಡಿದ
<u></u>		FART TO TANK RIGNAL (M. 1.32)		
	Subj: Minutes of BS	JRE Replacement Pr	eliminary Design R	eview Mtg; distribution
	Ref: (a) NAVAIR spo TATU Desig	iltr AIR-6303D/JGC m Analysis	630-SL-027 of 5 N	ov 81, Subj: BSURE
	Encl: (1) Minutes of	E BSURE Replacement	t Preliminary Desi	gn Review Mtg of 17/18 N
	L. Enclosure (1) is	provided to docu	ment BSURE Design	Review mtg of reference
			4	ed to
				Gallenter
1)istribution:	shington, DC		Li de localian Li localian
1	THESNAVFACENGCOM Was NUSC Newport, RI			
1	USC Newport, RI COMPACMISTESTCEN Pt.	Mugu, CA		
1	NUSC Newport, RI	Mugu, CA		
1	USC Newport, RI COMPACMISTESTCEN Pt.	Mugu, CA		
1	USC Newport, RI COMPACMISTESTCEN Pt.	Mugu, CA		
1	USC Newport, RI COMPACMISTESTCEN Pt.	Mugu, CA		
1	USC Newport, RI COMPACMISTESTCEN Pt. PACMISRANFAC Barking	Mugu, CA		
fod	USC Newport, RI COMPACMISTESTCEN Pt. PACMISRANFAC Barking	Mugu, CA		
fod	USC Newport, RI COMPACMISTESTCEN Pt. PACMISRANFAC Barking	Mugu, CA		
fod	USC Newport, RI COMPACMISTESTCEN Pt. PACMISRANFAC Barking	Mugu, CA Sands, HI		ADDRESS REPLY A SHOWN AT LEFT: OR RE PLY HEREON AND RETURN
fod	USC Newport, RI COMPACMISTESTCEN Pt. PACMISRANFAC Barking	Mugu, CA Sands, HI	•	
1 () Fod	Commander NUSC Newport, RI COMPACMISTESTCEN Pt. PACMISRANFAC Barking Commander Naval Air	Mugu, CA Sands, HI	•	SHOWN AT LEFT: OR RE PLY HEREON AND RETURN

MINUTES OF BSURE REPLACEMENT PRELIMINARY DESIGN REVIEW MEETING

•

.

An instruction for the first of the first of the for the for

1. This meeting was held 17-18 November 1981 at NAVAIR Headquarters. Attachments (1) and (2) are the revised agenda and list of attendees, respectively. Status of preliminary design analysis of Terminal and Transmission Units (TATUS), sea/ shore interface, contract status, and hydrophone spacing were presented by CHESNAVFACENGCOM (CHESDIV), NUSC, and PACMISTESTCEN (PMTC). Design, analysis is continuing and will be presented at the next design review meeting on 13-14 January 1982.

2. LCDR M. Praskievicz (CHESDIV) presented the status of the sea/shore interface investigation. BARSTUR hydrophone, BARSTUR UQC, BSURE hydrophone, and BSURE UCS cables are in jeopardy of failing because of surf damage. CHESDIV will submit a formal report and a proposal recommending a FY-82 short-term repair and a long-term repair after further investigation of courses of action.

3. Mr. R. Cox (CHESDIV), as the design analysis team leader, described the objectives of the analysis. The presentations that followed reported the status of the analysis.

4. Mr. R. Polley (PMTC) presented a history of the TATU design. Vugraphs and some actual components were displayed while the evolution of the design from initial design to the latest redesign was described.

5. Mr. R. Ricci (NUSC) reported on the documentation search conducted at PMTC in early November. There was insufficient time to find, review, and copy all the documentation desired by CHESDIV and NUSC. Concern was expressed about the currentness and completeness of the drawings. An additional concern was that documentation reflects that quality assurance would be completed by Delco with little Government involvement.

6. CHESDIV and NUSC representatives discussed the results of the review of drawings and specifications. CHESDIV did a worse-case tolerance analysis and found that tolerance build-up could prohibit assembly in one case. All O-rings would be compressed 25 to 50% (industry standards are 17 to 24% compression) but no problems are foreseen. No other obvious deficiencies were found. Of some concern to the investigators was a lack of access to the TATU basic design philosophy. Unfortunately the investigators do not have access to the chief designer of the TATU.

7. CHESDIV and NUSC presented results of independent reliability analyses and a review of the preliminary FMEA. Both activities identified lack of empirical reliability data for static seals. Both activities derived equations for the new and old TATU designs and, given hypothetical failure probabilities, arrived at similar results. Their results show, if one assumes each seal has a probability of failure of .10 and all seals have the same probability of failure, the reliability of the new design is greater than 100 times better than the old design. Past failures have been caused by unanticipated problems during assembly of the TATUS. These known problems have been eliminated in the new design but a QA program and environmental testing are required to reduce the chance of other assembly problems causing a failure.

G-3

Enclosure (1)

8. Mr. Mike He (PMTC) reported on studies done to establish a four-mile hydrophone spacing on each BSIRE replacement string. Full representatives feel the new spacing will provide a tracking area of 1,000 SNM with 18 hydrophones. Scenarios were shown where tracking would not be compromised between the strings by loss of any one hydrophone. A documented investigation will be accomplished when a definite replacement program is identified.

9. Mr. G. Nussear (PMTC) reported on the status of the refurbishment contract with Delco. A list of configuration of deliverables were described.

10. The status of the design analysis objectives were discussed by all participants. The following is a summary of the objectives and comments:

SD A. Determine whether the new Schedule-D termination design is worthy of manufacture.

A-1 The Analysis Team agrees that the design approach is fundamentally sound.

A-2 The Analysis Team showed the new design is capable of a significantly higher reliability than the old design and the team will develop tests to verify reliability.

A-3 The Analysis Team did not receive the latest drawings. When the latest drawings are received the team willdetermine whether inherent capability of the new design has been achieved through adequate design particulars as expressed in drawings and specifications. Tolerance analysis needs to be done.

Π

A-4 The Analysis Team agrees that the design is well within state-ofthe-art manufacturing techniques and practices.

A-5 The Analysis Team will determine whether design is conducive to acceptance of individual parts through parts inspections when the latest drawings are received.

A-6 The Analysis Team has not seen assembly procedures to determine whether the design is conducive to evaluation test at various levels of assembly.

A-7 The Analysis Team determined that some development tests have been conducted but an integrated test plan is needed.

A-8 Whether the design is overly sensitive to the skill level/motivation of the assembly personnel has yet to be determined.

A-9 The Analysis Team will investigate, including checking with NOS Indian Head, whether the design is conducive to accelerated life tests.

B. Determine whether Delco should be the Manufacturing contractor.

B-1 The Analysis Team has no reservations about Delco.

B-2 It is presently unknown what the impact is if Delco does not provide follow-on support after this manufacturing effort.

G-4

C. Determine what additional measures should be taken to assure program success.

C-1 The Analysis Tear will continue to provide technical support throughout the program.

C-2 Special quality assurance plans/procedures should be developed/ implemented.

C-3 An integrated test plan should be developed/implemented.

C-4 A Level III drawing package is not required from Delco. The next contractor will formalize drawings if required.

C-5 A quality control and test organization/contractor is required for program success and continuity.

C-6 The Government should participate in, or be involved with, the Delco configuration management plan as much as possible within contract allowance.

11. The following action items were assigned:

7

-

-

4

...

a. PMTC to deliver final build-to-print drawings to CHESDIV and NUSC by 1 December 1981.

b. PMTC to obtain assembly procedures and tolerance analyses from Delco Electronics.

c. CHESDIV to coordinate production analysis.

d. NUSC to investigate NOS Indian Head capability to define and conduct accelerated life tests on underwater systems.

12. A critical design review meeting will be held at NAVAIRSYSCOM on 13 and 14 January 1982. Subjects to be discussed are:

a. Status of existing Delco contract.

b. Statement of Work for renegotiated Delco contract.

c. Final report TATU FM&EA

d. Status of design analysis, tolerance analysis, quality assurance plan, integrated test plan, and accelerated life test technique search.

Enclosure (1)

Ģ-5

AGENDA

PRELIMINARY DESIGN REVIEW OF SD TERMINATION (11/17/81)

INTRODUCTION (NAVAIR)

SEA/SHORE INTERFACE STATUS (CHESDIV)

DESIGN ANALYSIS OBJECTIVES (CHESDIV)

SD TERMINATION DESIGN HISTORY (PMTC)

DESIGN DESCRIPTION AND THEORY OF OPERATION OF NEW SD TERMINATION AIDED BY ACTUAL TERMINATION COMPONENT (PMTC)

RESULTS OF OCT 20-23 DOCUMENTATION REVIEW (NUSC)

CURRENT RESULTS OF DRAWING/SPECIFICATION REVIEW (CHESDIV/NUSC)

RESULTS OF FOLLOW-ON FMEA (NUSC)

CURRENT RESULTS OF RELIABILITY ANALYSES (NUSC/CHESDIV)

RESULTS OF HYDROPHONE SPACING INVESTIGATION (PMTC)

STATUS OF REFURBISHMENT CONTRACT (PMTC)

STATUS OF DESIGN ANALYSIS OBJECTIVES (CHESDIV/PMTC/NUSC)

FUTURE PLANS (CHESDIV)

D

OPEN DISCUSSION AND DETERMINATION OF ACTION ITEMS

Attachment (1)

EVENAL DESIGN REVIEW MEETING 17 November 1981

Ę

•

. .

.

•

NAME	ORGANIZATION	PHONE
JOE CULVER	NAVAIR 6303D	202-692-9182
DON WITKOS	NUSC 38214	401-841-3415
ROBERT RICCI	NUSC 38214	401-841-3415
MIKE DI LEO	CRC	703-841-1445
FRED BALLINGER	PMTC 0143	AV 351-8331
GEORGE NUSSEAR	PMIC 3144	AV 351-8904
ROBERT POLLEY	PMTC 3143	805-982-8904
MIKE HO	PMIC 3144/PMRF	808-335-4330
DICK CRANGLE	NAVAIR 6303	202-692-9182
JOHN CHASTAIN	SRI	703-524-2053
DAN ERWIN	SETAC	703-820-9400
JIM HOYE	VSE	703-979-4900
JIMMIE MARTIN	CHESNAVAFC	202-433-3881
ROBERT L. COX	CHESNAVAFC	202-433-3881
R. CLARK	SETAC	703-820-9400
M. PRASKIEVICZ	CHESNAVFAC	202-433-3881

G-7

APPENDIX H

đ

,

.

5

.

Ē

•

RELIABILITY ANALYSIS AND INTEGRATED

TEST PROGRAM FOR THE BSURE TERMINATION

Prepared for

Naval Underwater Systems Center

Newport, RI

Under Contract

N00140-81-D-BB34

Columbia Research Corporation

Arlington, VA

TABLE OF CONTENTS

Ē

.

. ب

D

-

		Page
1.	INTRODUCTION	1-1
2.	DESIGN DESCRIPTION	2-1
3.	RELIABILITY ANALYSIS	3-1
3.1 3.2	Assumptions	
4.	INTEGRATED TEST PROGRAM	4-1
4.1 4.2 4.3 4.3.1 4.3.2 4.3.3 4.3.4	Test Objectives	4-1 4-3 4-3 4-5 4-5 4-8
5.1 5.2 5.3	Reliability of New Design	5-1

LIST OF FIGURES

Figure Page 2-1 Original Design Termination Unit Cross Section 2-2 2-2 2-3 2-3 Termination Unit Showing Unmated SD Cable Termination and 2 - 42-4 TATU Termination Unit Showing Components and Color-Coded 2-5 Slock Diagram of the Original Termination Unit 3-1 3-3 . . • • • 3-2 Reliability of Original Design Versus Seal Reliability 3-6 3-3 Block Diagram for the New Termination Unit Design 3-7 3-4 Reliability Comparison of the Original and New Designs 3-12 4-1 4-9

TABLE OF CONTENTS (Cont'd)

LIST OF TABLES

Table

-

.

D

Į.

Ľ

ļ,

<u>:</u>:

. .

ŧ.-

P	ag	e

2-1	Termination Unit Components	2-6
3-1	Success States for Original Termination Unit Design	
3-2	Reliability of the Original Design Versus Seal Reliability	3-5
3-3	System Success States for the New Design	3-8
3-4	Reliability Equation for the New Termination Unit Deisgn	3-10
3-5	Simplified Equation for the New Termination Unit Design	3-11
4-1	Synopsis of Recommended Tests	4-4
4-2	Termination Unit Mission Profile Environmental Conditions	1-6
4-3	Environmental Stress Tests	4-3 4-7

1. INTRODUCTION

J)

Under Contract Number N00140-81-D-BB34 Columbia Research Corporation (CRC) conducted a reliability analysis of the newly designed termination unit used in the Barking Sands Underwater Range Expansion (BSURE) refurbishment program. In addition, CRC developed a test program designed to provide assurance that the termination unit will be capable of functioning, maintenance free, for a period of twenty years. CRC's effort focused on the fluid seals of the termination unit (Morrison seals and O-Rings in a series-parallel configuration). As part of the reliability analysis CRC developed a mathematical model that predicts the performance of the termination unit sealing system as a function of component reliability. The test program is designed primarily to demonstrate the reliability of the termination unit sealing system over the designed service life of the BSURE syst_m.

This report is divided into five sections. Section 1 is the Introduction. Section 2 is the Design Description and contains background information on the BSURE system and a description of the original and the new termination unit design. Section 3 contains the Reliability Analysis; Section 4 provides a series of recommended tests for the New Design; and Section 5 contains Conclusions and Recommendations.

2. DESIGN DESCRIPTION

Ď

The DUFDOSE of the BSURE refurbishment program is to replace the existing BSURE in-water system with an improved system designed to function maintenance-free for a period of twenty years. An important aspect of the replacement system is a newly designed termination unit that provides significantly improved sealing capabilities. As originally designed, the termination unit does not provide adequate protection against seawater entering through the cable core or sheath when the insulation jacket is cut. The new design developed and tested by Delco Electronics, Santa Barbara has been shown to protect against these conditions in laboratory simulation tests. Figures 2-1 and 2-2 are cross-sectional views of the original and new termination unit designs, respectively. The new design has three features which constitute a significant improvement over the original design. These features are: concentric electrical feed-throughs, redundant seals, and pressurized oil cavities.

In the original design, the concer ground sheath is attached to an offcenter bin connected to the termination housing bulkhead through a Morrison Seal. A leak bath developed through this Morrison seal as a result of torque that is normally experienced by the unit. This torque caused relative rotation between the two termination unit sections which in turn caused the bin to move back and forth inside the Morrison seal. The Morrison seal then developed a leak along its interface with the bin causing failure of the termination unit. In the new design, the eccentric bin is eliminated by removing the outer insulating jacket of the SD cable where it enters the termination unit. The concer ground sheath is then folded back and clamped to assure reliable grounding of the termination housing without penetration of the Morrison seal.

The new design is intrinsically more reliable than the original design because it incorporates redundancy to obtain improved sealing characteristics. In the original design, failure of a single seal can result in failure of the termination unit. In the new design, it would take a failure of at least three seals to cause failure of the termination unit.

In both the original and new designs, the termination unit interconnect housing is filled with castor oil. The new design, however, provides a mechanism for the oil cavities to be pressurized to the ambient pressure thus reducing the pressure differential across all seals to zero. The oil-filled termination is pressure-balanced by means of a piston and cylinder mechanism incorporated into the design. An air cavity exists within the cable core, the differential pressure between the ocean and this cavity (which is at atmospheric pressure) tends to drive oil into the cable intersticies. A Morrison seal and a cap seal prevent oil from leaking into the cable.

Figures 2-3 and 2-4 show the termination unit assembly components, and Table 2-1 identifies these components by number, name, material, and function. In Figure 2-4 the termination unit is color-coded to identify various features of the design. Shades of red, blue and grav correspond, respectively, with the paths of high voltage, ground and isolation.

As shown in Figure 2-3, the termination unit concists of two mating assemblies: an SD cable termination assembly and a gimbal assembly. In this figure, the SD cable enters the termination he wing from the left. The outer





H-7



H-8



TABLE 2-1 TERMINATION UNIT COMPONENTS

.

.

٢.

.

, I a m

.

۵

.

· Ì

Fig. 2- Ident. Nomber			
	NOMENCLATURE	MATERIAL	FUNCTION
1	Morrison Seal, Cable Sheath	Silicon Elastomer	Secondary sealing, termi- nation housing-to- polvethelyne sheath
2	Morrison Seal, Cable Sheath	Butvl	Secondary sealing, termi- nation housing-to- polyethelyne sheath
3	SD Center Insulation	Polvethelyne	Multiplex signal carrier
4	O-Ring	Butyl	Seal, fiberglass-to- polvethelyne sheath
۶	0-Ring	Butyl	Seal, housing-to- fiberglass
6	Load Bearing Insulator	Epoxy- Piberglass	Encases and isolates load bearing plate from ground
7	O-Ring	Butvl	Seal, load bearing plate- to-polvethelvne sheath
8	Load Rearing Plate	Steel	Assumes axial loads applied to TATU
q	Termination Housing	Conver Nickel Bervllium	Encasement and ground conductor
10	Compression Fitting	199902	Secures high-tension Copper conductor to load bearing plate
11	Righ-Tension Cable Conductor	Corper	Multiplex Signal Carrier
12	O-Ring	Butvl	Tertiarv seal, load bearing insulator-to- tertiarv Female Insulator Tube (FIT)
1.3	0-Ring	Butvl	Seal, load bearing insulator-to-FIT
14	Morrison Seal	Butvl	Primary seal, blocks oil passage into cable core

÷.

TABLE 2-1

TERMINATION UNIT COMPONENTS (Contd)

-

2

Г., .

FTG. 2- Ident.			
NUMBER	NOMENCLATURE	MATERIAL	FUNCTION
15	O-Ring	Butyl	Secondary seal, termina- tion housing to gimbal housing
16	0-Ring	Butvl	Secondary seal, termina- tion housing to gimbal housing
17	Gimbal Root	Butyl	Plexible rubber bellows Covering gimbal joint
1.8	Strength Terminator	Stael & Epoxy	Potted cable core termination
19	Female Isolation Tube (FIT) Band Seal	Silicone Elastomer	Fluid pressure equalizer and conductive path seal between oil cavities
20	Morrison Seal	Butyl	Primary seal
21	Male Isolation Tube (MIT) Band Seal	Silicone Blastomer	Fluid pressure equalizer and conductive path seal between oil cavities
22	Female Isolation Tube (FIT)	PAC	Termination housing Center contact isolator
23	Male Isolation Tube (MIT) O-Ring	Butyl	Tertiary seal, MIT-to-FIT
74	MIT O-Ring	Butyl	Tertiarv seal, MIT-to-FIT
25	Male Isolation Tube (MIT)	ЪАС	Gimbal housing center contact isolator
25	Interconnect Termination Seal	Butyl	Tertiary seal, MIT-to- interconnect cable
27	Taper Unit	Couper Nickel Beryllium	To retain interconnect cable termination
29	Oil-Fill Plug	Copper Nickle	Oil-fill and Pressurization
79	0-Ring	Butyl	Seal

TABLE 2-1 TERMINATION UNIT COMPONENTS (Contd)

Ŗ

. .

i

r

5

PIG. 2-4 Ident. Nomber	NOMENCLATURE	MATERIAL	FUNCTION
30	Core Seal	Butvl	Secondary seal, cable spool-to-interconnect cable
71	Gimballed Housing	Corper Nickel Beryllium	Flexible joint-to-end cap assembly
32	Cable Speel	7030 Copper	Interfaces the cable boot and the interconnect cable terminal
33	0-Ring	Butvl	Secondary seal, cable spool-to-gimbal neck
34	O-Ring	Butvl	Secondarv seal, cable spool-to-gimbal neck
35	Interconnect Cable Root	Butyl	Provides secondary seal between the cable spool and the gimbal
36	Interconnect Cable Core	Cooper	Connects interconnect cable core to the ter- mination unit
37	Interconnect Cable Terminal	Copper	Terminates conductor

sheath is removed and the covver ground sheath is folded back and clamped. Seawater is in contact with the cable sheath at this point. An underlying polvethelvne dialectric protecting the signal carrier is passed through a cair of Morrison seals separated by castor oil. The polvethelvne dialectric is then bassed through the load bearing insulator and terminates within the load bearing place. At the termination of the polyethelyne dialectric the highvoltage copper sheath is exposed and secured to the load bearing plate via a cover compression fitting. An electrical conduction path is established through this fitting, through the steel load bearing plate and then through the strength terminator encasement to the center contact. This contact is achieved through use of a Multilam Band (see accompanying detail in Figure 2-3), designed and patented by Brown Boveri Co. of Switzerland. The Multilam Band is a flat hand formed into a cylindrcal shape from heat-treated and gold-plated hervllium copper. The material is processed to provide multiole louver-shaped spring contacts at the mating interface. Thus, a highly reliable elastic connection is formed with multiple-line contacts operating at thousands of bounds per square inch.

The termination unit provides a mechanical connection between the SD cable and the TATU housing. Axial strength is required during deployment operations to support the cable in 15,000 feet of water.

When the two assemblies are mated, an electrical bath is completed through the gimibal center contact and out through the core of the gimbal interconnect cable into the TATU housing. The assembly ring secures the two termination unit assemblies and permits relative linear motion to achieve pressure equalization. The male and female isolation tubes (MITs and FITs) are designed with band seals which permit pressure equalization between the two oil cavities while preventing an electrical path to be completed between high voltage and ground. The outer gimbal boot is also oil-filled.

D

3. RELIABILITY ANALYSIS

CRC conducted a reliability analysis of the termination unit. In this analysis reliability equations for the new and original termination unit designs were developed from system block diagrams and success state tables. The equations were solved for hypothetical reliability values of Morrison seals and O-rings. A comparison of the reliability performance characteristics of the new and original designs was then made. This comparative analysis confirmed the superior reliability performance of the new design. The details of the reliability analysis are presented in this section of the report.

3.1 Assumptions

Due to the lack of applicable reliability data for elastomeric seals, the following simplifying assumptions are used to govern the approach of the reliability analysis:

(1) Constant Failure Rate For Morrison Seals and O-Rings. The first assumption made for this analysis is that Morrison seals and O-rings have a constant failure rate. This assumption is frequently employed in reliability analyses and very little error is caused by its use. This assumption simplifies the mathematics and allows the use of the equation:

> $R = e^{-\lambda t}$ where R = probability of survival, (dimensionless) λ = the constant failure rate, (hrs ⁻¹) t = time (hrs) e = 2.71828, (dimensionless)

(2) <u>Identical Failure Rate For All Seals</u>. The second assumption is that all seals, Morrison seals and O-rings, have identical failure rates. This assumption was made because actual failure rate data for these components could not be located. Since there are similarities in the design, elastomeric composition, application, and environment of both Morrison seals and O-rings, and since both the new and original design employ both types of seals, it appears that this assumption is valid for a comparative analysis.

(3) <u>Negligible Effects Due To The Oil</u>. In this analysis the effects of castor oil on the failure rate of the seals have been neglected. It is generally believed that the use of oil in the new design will have beneficial effects on the reliability of the termination unit. In the new design the oil is pressurized to ambient causing a zero pressure differential across the seals. The reliability analysis neglects this effect. It is therefore felt that the actual reliability performance of the new design might be betta: than predicted.

3.2 Comparative Reliability Analysis

At the beginning of the reliability analysis, failure rate data on O-Rings and Morrison seals was not available and therefore an accurate prediction of termination unit reliability could not be made. In the absence of this data, it was decided to conduct a comparative analysis between the original termination unit design and the new design. The first step in conducting the comparative reliability analysis was to develop a block diagram. The block diagrams for the original design and the new design had been prepared by CHESNAVFACENGCOM and PMTC. Figure 3-1 shows the block diagrams for the original design. Using this block diagram, all the possible success states of the termination unit were listed. A success state is any condition in which the termination unit will function as required even though one or more components have failed. All combinations of failed and functioning components that result in system success comprise the system success states. These success states are shown in Table 3-1. The letter "A" in the table indicates that the Morrison seal at position A in the block diagram has failed.

The reliability equation for the unit can be written directly from the table of success states. This is accomplished by writing a probability term for each success state. For instance, the success state A B C D E vields the term X^5 . Similarly the success state A B F G C D E vields the term X^6 (1-X). Adding all these terms gives the equation shown in Table 3-2. Substituting various values for X and solving for R_{od} (reliability of original design) gives the values shown in Table 3-2. These values were then plotted as shown in Figure 3-2.

The same process was accomplished for the new design. Figure 3-3 shows the block diagram for the new design, Table 3-3 shows the success states for the new design, Table 3-4 shows the reliability equation derived from the success states, and Table 3-5 shows the simplified reliability equation for the new design and the reliability values. Figure 3-4 shows the comparison of original unit reliability to new unit reliability. From this figure it can be seen that the new design is considerably more reliable than the original.



•

| -

D

Ļ

•

.. .

-
Ń
-
"
b a
Ĕ
E E

....

1-	A	3	С	D	E								
2-	λ	₿	F	G	с	ם	E						
3-	A	B	c	Ħ	I	J	ĸ						
4-	A	B	P	G	c	·Ħ	I	J	R				
5-	A	B	c	· E	I	L	J	ĸ					
5-	λ	B	2	G	c	Ħ	I	L	J	R			
7-	λ	B	5	E	I	<u>J</u>	M	N	R				
8-	A	B	F	G	C	Ħ	I	<u>J</u>	M	N	R		
9-	A	B	<u>c</u>	Ħ	ī	L	<u>J</u>	M	N	π			
10-	A	B	2	G	Ē	Ħ	Ī	L	J	м	N	R	
11-	A	閇	<u>c</u>	Ħ	I	<u>J</u>	M	0	N	R			
12-	A	<u>B</u>	2	G	C	Ħ	I	<u>J</u>	M	0	N	R	
13-	A	B	<u>c</u>	Ħ	I	Ľ,	J	M	٩	N	R		
14-	A	<u>B</u>	P	G	<u>c</u>	Ħ	I	L	<u>5</u>	M	0	N	R
15-	A	8	<u>c</u>	Ħ	Ĩ	<u>J</u>	M	0	N	P			
16-	A	<u>B</u>	2	G	<u>c</u>	Ħ	I	<u>J</u>	M	0	N	P	
17-	A	3	<u>c</u>	Ħ	Ī	L	<u>J</u>	M	0	N	P		
18-	A	8	2	G	<u>c</u>	Ħ	Ī	L	<u>J</u>	M	0	N	P
19-	A	8	<u> </u>	Ħ	I	J	K	P					
?0 -	λ	B	P	G	5	Ħ	I	J	K	P			
21-	A	В	5	Ħ	I	L	J	<u>.</u>	P				
22-	A	B	P	G	<u>5</u>	Ħ	ī	L	J	R	P		
23-	A	B	<u>c</u>	Ħ	ī	L	<u>J</u>	M	N	R	P		
24-	A	3	P	G	<u>c</u>	Ħ	ī	L	7	M	N	R	P
25-	λ	B	<u>c</u>	Ħ	ī	L	<u>J</u>	M	0	N	<u>R</u>	P	
25-	A	8	P	G	Ē	Ħ	Ī	L	ī	M	0	N	<u>x</u>
27-	A	B	<u>c</u>	Ħ	I	<u>J</u>	M	N	R	P			-
28-	λ	B	P	G	<u>c</u>	Ħ	I	<u>J</u>	M	N ·	<u>R</u>	P	

TABLE 3-1 SUCCESS STATES FOR THE ORIGINAL TERMINATION UNIT DESIGN

29-54-Same as states 3 through 28 but replace C with D.

55-80-Same as states 3 through 28 but replace C with E.

5
TABLE 3-2 RELIABILITY OF THE ORIGINAL DESIGN VERSUS SEAL RELIABILITY

X = Rs	R Od
.0	.0
.4	.0048
.5	.137
.5	.292
.7	.500
. 9	.718
.82	.757
.84	.794
.85	.829
. 88	.850
.90	.889
.92	.917
.94	.938
.95	.96
.98	.99
.999	.999
1.0	1.0

R_{orl} =

.

, ,

-

۲. ۲

2.Z

- 4

ř

6

 $= x^{5} + 4x^{6}(1-x) + 6x^{6}(1-x)^{2} + 3x^{6}(1-x)^{3}$ $+ 3x^{6}(1-x)^{4} + 3x^{5}(1-x)^{5} + 9x^{7}(1-x)^{2} + 12x^{7}(1-x)^{3}$ $+ 9x^{7}(1-x)^{4} + 6x^{7}(1-x)^{5} + 3x^{7}(1-x)^{5} + 6x^{8}(1-x)^{3}$ $+ 6x^{9}(1-x)^{4} + 6x^{8}(1-x)^{5} + 3x^{8}(1-x)^{6}$



Figure 3-2. Reliability of Original Design (R_{Od}) Versus Seal Reliability (Rs)



٥

D

1



1. S. C. I.

۰,

A չ որ որ որորդերին որ որ որորդերություն որ որորդերություն որ որոնդերին որորդերին որորդերին որորդերին որ որ որ որ ~~~~~~~~~~~ F ╫**。╻。┎╻╻╻╻╻╻╻** Η - מממ האאא אממה האאאא ממה האאאא ממה הממה הממה הממה הממה הממה הכומה מרצו אישר ארא M ムドへんたんととくれんんだんととくなんんたんとくたちんんだれんんだれんんだたんただたんただのよう 시 스러 번째에 시시에 실제 번째에 시시에 실패 번째에 시시에 실패 번에 스러 번에 스러 번째에 스러 번 에이 아이 r Q [김 0 시 입 1 스 차 채 입 6 시 입 가 시 차 채 입 6 시 6 가 6 가 6 가 6 시 6 기 6 시 6 기 6 시 6 기 6 시 6 기 6 시 6 가 6 가 6 0 가 6 0 가 6 0 R אפאא רופר צרופר צורפר אנושר או Η M K Z Z O Z Z Z Z Z Z Z Z M 0 20 2 0 2 0 เป็นจะ ร่อ สุดีกำได้ระเอ สุดการ์ด รูด รูด รูด รูด รูด รู H H G H н ※ 그 ※ 한다!에다 ㅈ 같이 ㅎ 또 다이 한 같 것 М M L M M **MARKOZITZ W W K** М M N M 0 0 0 0 u N

TABLE 3-3

SYSTEM SUCCESS

STATES FOR THE NEW DESIGN

Ì

Ľ.

, ,

Ć

ļ.

•

R

0

ROR

М

0

61 - A 62 - A 63 - A 65 - A 65 - A 66 - A 66 - A 67 - A 69 - A 70 - A		ախխա ա ա ախխխ	~~~~		5 5 5 T T T T 5 5 5 5		ממה ה x x ג ממה	X X V ¥ V V ¥ V X X V	<u>२</u> २ २ ४ ५ ४ ७४ ४ ४	ଏହ ଅଭିତ ଏହାମ ଏହ ନ	פד הלהושר צום עם	기요니 저 지 집 집 []	거니 거 과 거제이 났다.	3 김회이어코 이 제도 실로	ସାସାତ ଅଧିତ ଅ	O R R O R	R
iteps 72 iteps 14	Thru 3 Thr	142. U 213	Rep , Re	eat S peat	teps i Steps	L Thru 1 Thr	71 F u 71	Replac Repla	inn (Ά) Β <u>γ</u> (Α) Β	- / AD'	_			-		
214- AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA	<u>ାବବସସସସସ</u> ସ୍ଥର		<u>।</u> त्वत्वत्वत्वत्वत्वत्वः	~~~~~~	™™™™™™™™™™™™™™™™™™™™™™™™™™™™™™™™™™™™	ממכ ה ממכ ה ממכ ה ממה ה	X X A X X A X X A X X A X X A X X A X X A X X A X X A X X A X X A X X A X X A X X A X X A X X A X	A A A A A A A A A A A A A A A A A A A	소재 건물 소재 전물 소재 전물 소재 전 물	C 8 Y 8 E 8 Y 8 E 8 Y 8 E Y		0 9 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	tgrggrxf l	IGIIGK GK	H HGH	н	
29- 30- <u>A</u> 31- 32-	0	I	<u>J</u>	\$ \$	T T	ប	V V X	พ. พ.	8	<u></u> .	ĸ	F	G	L	м		
12 - 13 - 14 - <u>A</u> 15 - 16 - 17 -	<u>0</u>	I	Ţ	~~~~~		ववद द वबद	X V X X	¥ พ V V V	W Y B W W	Y E Y	F	G	<u>L</u>	N	M		
18- A 19	<u>0</u>	I	<u>J</u>	2222	T T T	ប ប ប ប	V V X X	พ พ ง ง	7 8 17 14	<u>E</u>	×	F	G	L	N	м	
1 - 12 - <u>A</u> 13 -	<u>0</u>	I	<u>7</u>		T T T	वत्तत व व	V V X X	W V V	NY BW WY	Y E Y	F.	G	L	N	M	0	
5- 6- <u>A</u> 7-	<u>0</u>	1	ī	222	T T T	U	V V X	W W V	Y BW WY	<u></u>	ĸ	F	G	Ĺ	м	M	0
8- 9- 0- <u>A</u> 1- 2-	<u>0</u>	I	<u>1</u>	~~~~~~~~~~~~~~~~	T T T T	נוחה ה ממה מ	X V X X	२ २ ह्य २ २	W P B W W	Y E Y	F	G	L	N	M	0	R
3 - <u>A</u> 5 - <u>7</u> 5 - 7 -	<u>0</u>	I	7	122222			V V X X V	K < < KIN	Y BW WY	<u>ε</u> γ	ĸ	F	<u>G</u>	L	н	<u>M</u>	<u>0</u>

TABLE 3-3 SYSTEM SUCCESS STATES FOR THE NEW DESIGN (Contd)

r

.

Â

•

.

-

È.

. .

H-22

R

TABLE 3-4 BELIABILITY EQUATION FOR THE NEW TERMINATION UNIT DESIGN

 $= x^{3} + x^{3}(1 - x) + x^{4}(1 - x)^{2}$ + $2x^{5}(1 - x) + 5x^{5}(1 - x)^{2} + 8x^{5}(1 - x)^{3}$ + $8x^{5}(1 - x)^{4} + 6x^{5}(1 - x)^{5} + 2x^{5}(1 - x)^{6}$ + $2x^{5}(1-x)^{3}$ + $4x^{5}(1-x)^{4}$ + $4x^{6}(1-x)^{5}$ + $4x^{6}(1 - x)^{6} + 2x^{6}(1 - x)^{7} + 2x^{7}(1 - x)^{5}$ + $4x^{7}(1 - x)^{6}$ + $2x^{7}(1 - x)^{7}$ + $3x^{8}(1 - x)^{3}$ + $10x^{8}(1 - x)^{4} + 14x^{8}(1 - x)^{5} + 18x^{8}(1 - x)^{5}$ + $24x^{8}(1 - x)^{7}$ + $24x^{8}(1 - x)^{8}$ + $16x^{8}(1 - x)^{9}$ + $10x^{8}(1 - x)^{10}$ + $6x^{8}(1 - x)^{11}$ + $2x^{8}(1 - x)^{12}$ + $2x^{9}(1 - x)^{2}$ + $10x^{9}(1 - x)^{3}$ + $22x^{9}(1 - x)^{4}$ + $35x^{9}(1 - x)^{5} + 46x^{9}(1 - x)^{6} + 52x^{9}(1 - x)^{7}$ + $46x^{9}(1 - x)^{8} + 34x^{9}(1 - x)^{9} + 22x^{9}(-x)^{10}$ + $10x^{9}(1 - x)^{11} + 2x^{9}(1 - x)^{12} + 4x^{10}(1 - x)^{4}$ + $16x^{10}(1 - x)^{5} + 28x^{10}(1 - x)^{6} + 32x^{10}(1 - x)^{7}$ + $32x^{10}(1 - x)^8$ + $28x^{10}(1 - x)^9$ + $16x^{10}(1 - x)^{10}$ $+ 4x^{10}(1 - x)^{11}$

-

Ď

Rns

TABLE 3-5 SIMPLIFIED FOUNTION FOR THE NEW TERMINATION UNIT DESIGN

X=RS	Rns
.3	.073
.4	.181
. 5	. 393
• 5	.550
.7	.752
. 8	.902
.82	
.84	.946
.86	.961
. 98	.973
. 90	.988
.92	.991
.94	.995
.96	.998
.98	.9995
.999	.999999
1.0	1.0

Rns

. .

Ì

.

.

D

Ļ

 $x^{3} + x^{3} (1-x) + x^{4} (1-x)^{2} + 2x^{5} (1-x)$ $6x^{5} (1-x)^{2} + 8x^{5} (1-x)^{3} + 8x^{5} (1-x)^{4}$ $+ 2x^{6} (1-x)^{3} + 4x^{6} (1-x)^{4} + 3x^{8} (1-x)^{3}$ $+ 10x^{8} (1-x)^{4} + 2x^{9} (1-x)^{2} + 10x^{9} (1-x)^{3}$ $+ 22x^{9} (1-x)^{4} + 4x^{10} (1-x)^{4}$



*.*__

Ì

٠.

.

•

i

.,

!

SYSTEM RELIABILITY

RELIABILITY OF SEALS



4. INTEGRATED TEST PROGRAM

This section describes a recommended program of testing that will provide a degree of assurance (both quantitative and qualitative) that the termination unit, as designed, fabricated, assembled and deployed, will perform successfully for the duration of its mission and will not lead to system degradation or failure. The topics covered in this section include the Test Objectives, Provisional Definition of System Failure, and the Test Plan.

4.1 Test Objectives

E

.

-

Ę

Ē.

P.

 The objectives of the integrated test program are first to provide assurance that the termination unit will be capable of operating maintenance free for a period of twenty years, and second to identify any potential problem area in the design, handling, transportation, assembly and storage, and deployment of the termination unit.

4.2 Provisional Definition of System Failure

In order to properly develop the test plan and satisfy the test objectives, the relationship between failure of a termination unit and the BSURE system must be analyzed and quantified. The following discussion relates the termination unit failure to system failure and offers a definition of system failure to be used only for purposes of developing a test plan.

The failure of a single termination unit does not necessarily consitute a BSURE system failure. Since the system is designed with two strings of nine TATUS in series, a termination unit failure will impact system performance differently depending on where the failure occurs along the string. A failure of the unit nearest the shore in a string will result in a loss of the entire string. A failure of the unit furthest from shore in a string will not affect any other units. For the purposes of this analysis, the system is said to be in a failed condition if four or more TATUS are inoperative.

A summation of operate time for the termination units in the in-water BSURE system totals 1.945 x 10^6 hours. Because of the design of the original unit, this operate time can also be applied to the Morrison seal around the SD cable. To determine the reliability of this Morrison seal, operate time was rounded to 2.0 x 10^6 and one failure was assumed. A twenty-year life was the desired goal. Hence,

- $R = e^{-\lambda t} = 0.916$ where,
- λ = number of failures/system time = 1/(2 x 10⁶)
- t = 175,200 hours (20 years)

The reliability of all seals and O-rings has been assumed the same. Thus, the probability of survival for each O-ring and seal is 0.916. When this part reliability (rounded to 0.92) is put in the reliability equation for the new termination unit design, the reliability is computed to be 0.991. Thus, the probability that any given termination unit will survive twenty years is 0.991. Using a termination unit reliability of 0.99 the following table shows the probability of unit failure.

n		Number	of	Termination	Units	Failing	P(n)
	·			0			.6826
				1			. 26 20
				2			.0490
				3			.0059
				4			.0005

For purposes of this analysis it has been assumed that a system failure occurs if a total of four or more TATUS fail to operate on either string. The two strings are structured as indicated by the following schematic:



Each TATU is attached to the cable by means of a termination unit on each end. A failure of a termination unit will cause the loss of all TATUS to the seaward side of that unit. For instance, the failure of termination unit A4 will cause the loss of TATUS A2 and A1. The failure of termination unit A5 will cause the system to lose TATUS A3, A2, and A1.

D

*-

Based on the preceding definition a termination unit failure may be "critical" (cause a system failure) or non-critical. The following table shows the probability of a critical failure as one or more unit failures occur.

Number of Termination Unit Failures	P (failure is critical)
1	.6842 (26/38)
2	.9403 (661/703)
3	.9924 (8372/8436)
4	.9992 (73755/73815)

Multiplying the probability that a given number of units fail times the probability that those failures are critical, yields the probability that a system failure will occur.

P (No. of Unit Failures)	X	P_(Failure is Critical) = P (System Fails)
(P(1) = .2520)	X	$(P(F_1) = .6842) = .1793$
(P(2) = .0490)	X	$(P(F_2) = .9403) = .0460$
(2 (3) = .0059)	X	$(P(P_3) = .9919) = .0059$
(P (4) = .0005)	Х	$(P(F_4) = .9992) = .0005$
TOTAL		.2317

Thus, the probability that one, two, three, or four termination failures occur and that these failures are critical is 0.2317. Conversely, the probability that zero to four termination unit failures occur without causing a system failure is 1 - 0.2317 or 0.7683. Hence, based on the above stated assumption, the probability that the system will survive twenty years is 0.7683 where survival is defined as having at least 15 TATUS operating. It should be noted that this analysis covers only the sealing system of the termination unit. Probability of survival would be somewhat reduced if other aspects of the system, such as electronics, were included in this analysis.

4.3 Test Plan

The plan to test the termination units includes four types of tests: reliability/TAAF tests, environmental stress tests, accelerated aging tests, and assembly tests. Table 4-1 is a synopsis of these tests and provides the objective, anticipated duration, required hardware, parameters, and references for each test. The following four paragraphs discuss each of these tests in more detail.

4.3.1 Reliability/TAAF Tests. MIL-STD-781 prescribes the reliability tests to be performed on military systems and equipment. These tests are used to determine the probability that the system or equipment being tested will achieve a specified MTTF. The duration of these tests is in multiples of specified MTTP. The BSURE system includes 42 termination units each designed for 20 years of operation. Of the 42 units, only 38 can contribute to system failure. (In this analysis we are only dealing with the sealing system which operates continuously after deployment, whether the range is being operated or not.) Therefore the total operate hours are: 38 units x 8760 hours per year x 20 years or 6,657,600 hours. Thus, the specified MTTF of a unit should be close to 6.7 million hours to achieve an expected range life of 20 years. For items with extremely high MTTP, such as the termination unit, the tests in MIL-STD-781 do not apply because test times are in multiples of the specified MTTP. It is, of course, impractical to test the unit to millions of operate hours. Since the usual reliability test methods are not practical, other test techniques have been examined to determine if any of them could provide some assurance of termination unit reliability performance.

The most promising reliability test for this situation is the Bayes test. This test permits the use of operational data if the unit being tested is at least as reliable as the unit from which operational data is being used. As was shown in Section 3 of this report the new termination unit design is inherently move reliable than the original design. Since this is the case, a Bayes test allows operational data on the original design to be combined with reliability test data on the new design to predict the reliability of the new design. In order to do this, however, certain criteria must be satisfied. First, none of the BSURE failures can be attributed to the system ana'yzed, i.e., the sealing system for the new termination unit. Second, there has to be reasonable assurance that no new failure mechanisms have been introduced via the new design. The BSURE range has been operated for approximately five years without experiencing a unit failure that can be attributed to an O-ring or a Morrison seal failure. Three types of failures have occurred on the BSURE range. The first type was seawater leaking between the SD cable polyethylene sheath and the Morrison seal. Upon inspection, it was determined that this failure was caused by grooves in the polyethylene

MIL-STU 810-C Design of Re-Prior Distri-MIL-STD-781, References Test Plans liability based on bution None None units sealing sys-Condit_on of sill-Capability of the Length of continsubjected to de-Physical properwous successful and butyl compotem after being ties of silicon simulated aging in moist air, seawater, and con and butyl fined stress Parameters nents after conditions castor oil operation properly assem-All silicon and Assembled Unit and butyl coma spare set of SYNOPSIS OF RECOMMENDED TUSTE Two unit com-One unit with rubber compopletely and Hardware Reguired ponenta bled TABLE 4-1 2400 Nours Duration **3 Montha** 2 Years 2 Weeks ture, and assembly tions to the which on all components To determine the the worst condithe unit sealing design, manufacunit is expected effects of aging deficiencies in to be subjected reliability of detect and fix ciencies in the Bystem in ways that represent To predict the system and to of the sealing inherent defl-To stress the Objective any Inherent unit sealing To identify Bystem Accelerated Aging Reliability/TMAP Assembly Tests Type of Test Streas Tests 'fest Tests

approved procedures

In accordance with

components after

heing assembled

nenta

termination unit

procedures

<u>م</u>ا

ģ

.

K

-

Ľ

.

.

: : :

۰.

sheath resulting from the manufacturing process. The new assembly procedure calls for eliminating these grooves by machining. It appears, therefore, that this failure was not caused by failure of the Morrison seal but rather by inadequate assembly procedures. The second type of failure was due to a torque applied to an off center pin that ran through the cup seal. The torquing destroyed the seal around the pin and allowed seawater to penetrate. This pin has been eliminated in the redesign of the termination unit. In the third type of failure, an SD cable pulled out of termination. This was obviously not caused by a Morrison seal or an O-ring. It appears, therefore, that we can justifiably assume that during the BSURE operation there has not been a failure of the termination unit sealing system. This represents about 2X10⁶ hours of failure-free operation of the termination unit sealing system.

-

FT.

Ζ.

Ņ

The second criteria (no new failure mechanisms introduced via the new design) is impossible to justify now. However, at some point in the test program it will be possible to detect inherent flaws in the new design or in the manufacture, assembly, etc. of the components.

At this point various Bayes test plans were examined to identify those that appeared applicable to the BSURE system. It was discovered that no reliability testing would be required if the Government accepts a ten percent average consumers risk. This means that the Government accepts a ten percent risk defined by the fraction: <u>Number of bad systems accepted</u>.

Total number of bad systems tested This is a fairly reasonable risk and CRC recommends its acceptance by the Government. Since no reliability tests are required, CRC recommends that a reliability/TAAF test be performed to examine the postulate that no inherent design flaws exist in the unit. CRC recommends that two properly assembled units representing production units be tested in simulated deployment conditions for fifty days each, or a total of 2400 operate hours. With an MTTF of about 5 X 10⁶ hours, the unit is expected to function failure-free over the test period. Therefore if any failures occur during the test, the test should be terminated and a complete failure analysis should be conducted. The failure analysis will indicate the necessity for a design and/or procedure change. The indicated changes should be incorporated into two new units and the tests should begin all over again. This process should continue until the entire test duration is completed without experiencing a failure of the termination unit sealing system. 4.3.2 Environmental Stress Tests. Environmental stress tests are used to determine the capability of the unit to withstand the normal stresses it is expected to encounter from the time it is manufactured through its operational service life. Table 4-2 lists the environmental conditions that the termination unit is expected to encounter, and Table 4-3 lists a salies of environmental stress tests that should be conducted on the unit.

Eleven tests are recommended as s wn in Table 4-3. Detailed description of the first ten tests may be found in MIL-STD-810C. The pressurization test is described in the 100 Percent Design Plan.

4.3.3 <u>Accelerated Aging Tests</u>. Since the termination unit is expected to function for twenty years, it was decided to examine the possibility of conducting accelerated aging tests on the Morrison seals and O-rings. Accelerated aging tests do not accurately predict when the components will fail. All they really do is identify the failure modes that will occur due to

L. ٥ · •

TABLE 4-2 TEIMINATION UNIT MISSION PROFILE ENVIRONMENTAL CONDITIONS

Tor Boon	N/A N/A N/A N/A N/A 4 N/A 4 N/A 4 N/A
Tension	N/A N/A N/A N/A N/A N/A
Humidity	0-1001 0-1001 0-1001 0-1001 0-1001 0-1001
Bhock	N/A 4 FT. Drop 4 FT. Drop 4 FT. Drop 4 FT. Drop 4 FT. Drop 4 FT. Drop
Vihration	N/A 0-500Hz N/A N/A N/A NOTE NOTE
Temperature	$40^{\circ} P = 120^{\circ} P$ $20^{\circ} P = 110^{\circ} P$ $60^{\circ} P = 100^{\circ} P$ $40^{\circ} P = 110^{\circ} P$
Mission Plase	Storage Ground Transport Gimbal Assembly Shipboard Transport Assembly Deployment Operation

NDTE: See MIL-STD-167

TABLE 4-3 ENVIRONMENTAL STRESS TESTS

.

þ

ľ

÷

Ď

.

l

•

.

METHCD	TEST	REMARKS
¥ 501.1	High Temperature	This test is used to determine the effects of high temperature on the termination. The test should be conducted with an unpressurized and a pressurized termination.
¥ 502.1	Low Temperature	This test is conducted to determine the effects of low temperature on the equipment during storage.
\$ 503.1	Temperature Shock	This test simulates possible deploy- ment conditions.
≱ 507.1	Bumidity	This test is conducted on silicon and butyl components only to determine the amount of moisture absorbed by these component and long term effects.
\$ 508.1	Fungus	This test is used to determine the resistance of the equipment to fungus.
≱ 509.1	Salt Pog	This test is conducted to determine the the effects of a salt atmosphere on the equipment.
\$ 510.1	Dust	This test is used to determine the effects of dust on the equipment, par- ticularly the effects of dust on equipment assembly.
\$ 512.1	Leak age	A modification of this test could be used to determine the integrity of the seals after pressurizing and just prior to deployment.
\$ 514.2	Vibracion	This test is used to determine if the equipment is capable of withstanding the vibration encountered during handling and transportation.
\$ 516.2	Shock	This test is performed to determine the capability of the equipment to withstand the shock stresses likely to be encountered during its life cycle.
	Over Pressurization	This test is performed to demon- strate the integrity of the seals after termination unit assembly.

the aging process. Only after extensive testing can an accurate correlation be made between induced and actual aging.

Accelerated aging tests are usually based on a rule of thumb that says, "an increase of 10°C doubles the aging rate." Applying this rule, an accelerated aging test plan was developed for the termination unit sealing components. This plan is summarized in Figure 4-1. The verticle axis in the figure is storage temperature in degrees centigrade, and the horizontal axis is storage time shown in both years and days. The family of curves in the figure represents equivalent ages. The curve at the left, for instance, represents the possible ways of storing a component to achieve an equivalent age of two years. Following this curve upward, it can be seen that this first point indicates that storing a sample at 14°C for one year is equivalent to two years of actual operation at 4° C. The next point shows that storing the components for 180 days at 24 °C is also equivalent to two years of actual operation at 4°C. As shown in the figure, it is then planned to conduct tests for equivalent ages of 2, 4, 6, 8, 10, 15, and 20 years. A total of 19 test points is recommended resulting in a total test duration of approximately two years. According to current planning, this will permit all the accelerated aging tests to be conducted prior to system deployment. That way, if serious aging problems are anticipated due to testing, a fix can be incorporated prior to deployment. For each of the 19 sample withdrawals, a control sample should also be withdrawn permitting a direct comparative analysis between actual and equivalent ages. Also, as indicated in the figure, the samples should be tested in oil, seawater, and moist air thus giving a total test sample size of 57 with 57 control samples. After withdrawal, each sample should be inspected and tested to determine: weight change, elastic modulus, hardness, ID, CD, roundness, and surface condition.

U.

.

<u>, . . .</u>

•

لعا

4.3.4 <u>Assembly Test</u>. The termination unit should be subjected to tests to determine what effects assembly will have on unit performance. Particularly, the effects of assembly on the condition of the Morrison seals and O-rings should be determined. Assembly tests should be conducted on both the ginbal side and the SD cable side. In these tests, the unit should be assembled under conditions that simulate, as closely as possible, the actual assembly conditions including skill levels of assembly technicians. All components should be thoroughly inspected prior to assembly. The unit should then be carefully disassembled by the most skilled individual. After disassembly, the components should be visually and microscopically examined to determine if the assembly procedure causes component damage.





MERCENCE SOUTHIN TEST TO A



F

ġ

Ļ

r

.

D

.

Ļ

•

- -ļ

TRUSS S



5. CONCLUSIONS AND RECOMMENDATIONS

5.1 Reliability of New Design

From the reliability analysis, it has been concluded that the new termination unit design is a significant improvement over the original design. The predicted improvement is a result of increased component redundancy in the new design. Additional performance improvement should result from the fact that the unit has been redesigned to eliminate pressure differentials across all seals except one. The beneficial effects of eliminating the pressure differential were not considered in our reliability analysis. Based on this conclusion, it is recommended that the currently designed termination unit be approved for use in the BSURE and that no further design efforts be conducted unless the need for redesign is subsequently indicated by testing.

5.2 Testing of the New Design

Numerous development tests have been conducted on the termination unit as indicated on the 100 Percent Design Plan. These tests, however, were conducted a number of years ago prior to final design approval. In addition, no qualification tests have been conducted on the unit. It is recommended, therefore, that the tests described in Section 4 be conducted to determine the design integrity, adequacy of assembly procedures, and to verify expected system reliability. It is further recommended that the Government accept the ten percent average consumers risk described in paragraph 4.3.1. Acceptance of this risk by the Government eliminates the need for extensive reliability testing.

5.3 Test Planning

-

Ď

Lastly, it is recommended that the testing requirements for the termination unit be thoroughly examined in relationship to the design, development and implementation schedule, and that a detailed test plan be developed covering all phases and aspects of termination unit testing.

GLOSSARY

BARSTUR Barking Sands Tracking Underwater Range

BSURE Barking Sands Underwater Range Expansion

FIT Female Isolation Tube

ID Inside Diameter

MIT Male Isolation Tube

MTTF Mean Time To Failure

NAVFACENGCOMCHESDIV Naval Facilities Engineering Command, Chesapeake Division

OD Outside Diameter

P(Fn) Probability that the "n" failed termination units each occur in a critical location

PMTC Pacific Missile Test Center

P(n) Probability that any number, n, of termination units will fail

Rns Reliability of New Design

Rod Reliability of Original Design

R₃ Reliability of Seal

3D (Prefix identifying type of submarine cable)

TAAF Test Analyze and Fix

TATU Termination and Transmission Unit

APPENDIX I

è

Į

Ď

•--

DESIGN/REDESIGN BLOCK DIAGRAMS FOR

LEAK PATH RELIABILITY ANALYSIS

CHESNAVFACENGCOM

CHESNAVFACENGCOM

r

i

i,



NEW DESIGN LEAK PATH DIAGRAM (ADAPTED FROM PMTC FMEA)

1 Ì <u>ند</u> Ė • Ļ ì . ; ÷ i Ĺ,

CHESNAVFACENGCOM



NEW DESIGN LEAK PATH DIAGRAM - SIMPLIFIED

CHESNAVFACENGCOM

۴

Q

12.12.23

I.

•---

• • •

1



SIMPLIFIED RELLABILITY BLOCK DLAGRAM (NEW DESIGN)

CHESNAVFACENGCOM

Ň

Ľ

D

Ĺ

.

.

i

-. |



SIMPLIFIED RELIABILITY BLOCK DIAGRAM (OLD DESIGN)

I-5

in the second second second second second second second second second second second second second second second

Ņ _____ -Ľ l . ____ • i - . |_____

1

CHESNAVFACENGCOM



OLD DESIGN LEAK PATH DIAGRAM - SIMPLIFIED

CHESNAVFACENGCOM



OLD DESIGN LEAK PATH DIAGRAM (FROM PMTC INFO) I-7

ŗ

i.

F - Probability of failure
S - Probability of non-failure (success)
F+S=1

 $P_{F2} = 1 - S^{3}$ $P_{F3} = (1 - S^{2}) < 1 - [1 - F^{2}] (1 - [1 - S^{2}]^{2} [1 - (1 - F^{2})^{2}] >$ $P_{F} = [P_{F3}] [1 - 1 - P_{F1}] (1 - P_{F2}]$

IMPROVED DESIGN $P_{F1} = F^2(1-S^2)$

ORIGINAL DESIGN $P_F = 1 - (S) [1 - (-S^2) (1 - S^3)] \{ 1 - (1 - S^3) [1 - (1 - F^2)^2 (1 - F^3)] \}$

COMPARATIVE RELIABILITY EQUATIONS

CHESNAVFACENGCOM

D

. D .

PARAMETRIC RELIABILITY ANALYSES

CHESNAVFACENGCOM

zi	0.134	2.238	2.512	2.952	3.048	3.242	3.298	3.417	3.448
<u>5/F</u>	0.1	1.9	2.7	5.7	7.2	13.3	17.2	31.3	40.7
<u>PF(OLD/PF(NEW)</u>	I	5	10	50	100	500	1,000	5,060	10,000
PF(NEW)	.9860	.8895	.0373	.6037	.00164	.00018	.0000.	.00000.	.0000026
PF(010)	6166.	.4633	.3711	.2076	. 1667	.0898	.0683	.0356	.0270
ŝ	.100	.660	.730	.850	.878	.930	545.	.969	9/6.
ند :	006.	. 340	.270	.150	.122	.010	.055	.031	.024

EQUIVALENT SERIES SINGLE SEALS THAT GIVES THE SAME RESULTS AS THE SERIES/ PÅRALLEL MULTI-ELEMENT SEAL (N= LOG PF/LOG F)

PROBABILITY OF FAILURE OF THE NEW SERIES/PARALLEL MULTI-ELEMENT SEAL OVER **20 YEARS** ı ين م

PROBABILITY OF NON-FAILURE OF A SINGLE SEAL OVER 20 YEARS (1-F)

t

S

- PROBABIL'TY OF FAILURE OF A SINGLE SEAL OVER 20 YEARS

ı Z

