SUMMARY REPORT FOR

NAVAL SURFACE WARFARE CENTER, CARDEROCK DIVISION

LVS MOD DEMO VEHICLE ARMOR PROTECTION KIT INSTALLATION

NATC PROJECT NO. 17859

CONTRACT NUMBER: N00167-98-C-0017

AUGUST 2001

DISTRIBUTION STATEMENT A
Approved for Public Release
Distribution Unlimited

PREPARED BY: COLIN ASHMORE

DIRECTOR OF ENGINEERING

20020503 073

NEVADA AUTOMOTIVE TEST CENTER
A DIVISION OF HODGES TRANSPORTATION, INC.
POST OFFICE BOX 234, CARSON CITY, NEVADA 89702
PHONE: (775) 629-2000 FAX: (775) 629-2029
EMAIL: info@natc-ht.com WEBSITE: www.natc-ht.com

REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing this collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0704-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. PLEASE DO NOT RETURN YOUR FORM TO THE ABOVE ADDRESS.

1. REPORT DATE (DD-MM-YYYY)	2. REPORT TYPE	3. DATES COVERED (From - To)			
31-08-2001	Armour Protection Kit Analysis				
4.Title AND SUBTITLE	5a. CONTRACT NUMBER				
Logistic Vehicle System (L					
	,	5b. GRANT NUMBER			
Protection Kit Installatio	n				
		5c. PROGRAM ELEMENT NUMBER			
6. AUTHOR(S)	5d. PROJECT NUMBER				
Colin Ashmore					
		5e. TASK NUMBER			
		5f. WORK UNIT NUMBER			
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)		8. PERFORMING ORGANIZATION REPORT NUMBER			
Jacobs Sverdrup Technology					
Inc,					
25 Clement Drive, Suite 10					
Quantico, Virginia 22554					
9. SPONSORING / MONITORING AGENCY	10. SPONSOR/MONITOR'S ACRONYM(S)				
Marine Corps Systems Command		MARCORSYSCOM			
2033 Barnett Ave Suite 315					
Quantico, Virginia 22134-5	11. SPONSOR/MONITOR'S REPORT				
	NUMBER(S)				
12. DISTRIBUTION / AVAILABILITY STAT	EMENT				
Distribution Statement A					

13. SUPPLEMENTARY NOTES

None

14. ABSTRACT

The purpose of this analysis was to discuss the two approaches to armor kits on vehicles, a bolt-on removable approach and an integrated approach. The study used a vehicle-modeling concept of a bolt-on removable armor approach and an integrated armor kit installed as a way to improve and modify the current protection for the LVS.

15. SUBJECT TERMS

NATA, ATD, HMMWV, HEMTT, TACOM, YPG, ATC, and LVS.

16. SECURITY CLASSIFICATION OF: Unclassified		17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON Timothy L. McMahand	
a. REPORT	b. ABSTRACT Unclassified	c. THIS PAGE	SAR	20	19b. TELEPHONE NUMBER (include area code) (540) 657-8000 ext#113

Standard Form 298 (Rev. 8-98) Prescribed by ANSI Std. Z39.18

AgMoz-08-1414

1.0 BACKGROUND

The Naval Surface Warfare Center, Carderock Division, contracted Simula Safety Systems, Inc., located in Tempe, Arizona, to install an armor protection kit on the Logistics Vehicle System (LVS). Concurrently, NATC was developing several Advanced Technology Demonstration (ATD) vehicles to support the USMC's LVSR program. The vehicle selected for the prototype installation of the armor kit was the Mod Demo LVS (MOD DEMO LVS) vehicle modified with the Raydan Air-Link tandem arm suspension at the #1, #2 #4 and #5 axles and a modified Hendrickson HT trailing arm air ride suspension at the #3 axle. This was an intermediate LVSR ATD vehicle built during 1998. The armor kit was installed from 23 - 25 July 2001 at the Nevada Automotive Test Center (NATC), located near Carson City, Nevada.

2.0 DESCRIPTION OF ARMOR KIT PROTECTION

There are two approaches to armor kits on vehicles, a bolton removable approach and an integrated approach. The bolt-on approach adds approximately 900 pounds to a HMMVWV, 1,000 pounds to a 5-ton and 1,500 pounds to the HEMTT and LVS. These bolt-on kits are typically retrofit installations that secure the armor to the existing cab and vehicle structure without extensive modification to the This type of approach was required by TACOM because the vehicles involved were used in different roles depending on the mission profile. When the high-risk mission was completed, the armor kit was simply removed from the vehicle and the vehicle returned to normal condition without the need to "fix" any structural modifications necessary for integral armor. Depending on the vehicle type and armor protection kit involved, ther is some concern with bolt-on kits regarding fatigue and body mount degradation due to the added weight.

An alternate approach is the use of integrated armor mounted directly to the structural members of the vehicle. This approach also offers some degree of crash protection. For example, making the skid plate of armor material and integrating its mounting into the frame of the vehicle provides armor protection and crash protection in the event of a frontal collision at a fraction of the weight penalty. Because of the mounting, fatigue and body mount degradation is eliminated.

The prototype armor protection bolt-on kit installed by Simula Safety Systems, Inc. on the MOD DEMO LVS is composed of the same materials as the M977 HEMTT armor kit that was developed for TACOM. The kit will defeat the 7.62 mm M80 ball projectile at muzzle (2,750 fps) velocity for both the opaque and transparent armor components. The kit was designed to stop all horizontal shots fired at the vehicle. The roof was designed to defeat shots made at 30 degrees obliquity. The LVS has not been tested for mine blast, however, the HEMTT was tested at Aberdeen Test Center using Soviet TM-46 anti-tank mines (12 pounds TNT equivalent). The LVS kit employs the same type of blast deflectors. This mine testing was conducted for wheel-detonated mines. However, due to the clearances for the #1 axle nose box on the LVS, underbody blast protection is reduced.

3.0 SUMMARY

The prototype armor protection kit was installed on the LVS by Simula from 23 - 25 July 2001. Measurements and mockups were recorded in February 2000 and August 2000. The armor kit will need refinement before it becomes a production item. The following is a list of items that need to be addressed should this kit become a kit option for the LVS:

- 1. The black out lights were not connected through the armor kit (Photograph number 20238-001),
- 2. The upper clearance lights were not connected through the armor kit (Photograph number 20238-001),
- 3. Visibility is limited/restricted by the new cab enclosure (Photographs numbered 20238-030 and 031),
- 4. The air flow is restricted to the cab (Photographs numbered 20238-030 and 031),
- 5. The window locks may protrude into the occupant's head/body during an accident (Photograph number 20238-016),
- 6. The door handle (inside cab) is hard to reach next to the seat (Photographs numbered 20238-019 and 020),

- 7. There is no exit point for the occupants during an accident; i.e., the window can not be kicked out (Photographs numbered 20238-001 through 004),
- 8. The dead bolt door locks automatically lock during vehicle operation (Photographs numbered 20238-017 and 018),
- 9. The bolts in the roof are protruding into the cab area creating a probability of head injury (Photographs numbered 20238-013 and 015),
- 10. The roof hatch is hard to lift and does not seem to slide; no 95th percentile provisions (Photographs numbered 20238-004 and 005),
- 11. The entire cab has protruding bolts into the cab space creating a probability of head injuries (Photographs numbered 20238-013, 014, 015, 023, 024, 025 and 027),
- 12. The underbody plate will act as a mud trap and corrosion issues are probable (Photographs numbered 20238-003 and 029),
- 13. The doors are too heavy for the hinges; occupants get trapped inside the vehicle due to hinges getting off track (Photograph number 20238-010),
- 14. The armor kit is bolted through the gunner's platform; platform not operational (Photographs numbered 20238-024 and 027),
- 15. The cab structure tube is crushed due to no support for bolts (Photograph number 20238-025),
- 16. The driver and passenger side upper door pins are loose (Photograph number 20238-011),
- 17. There is a gap in the armor plate on both sides; only one bolt holds the armor kit on, the other bolt is only through the sheet metal (Photograph number 20238-012),
- 18. There is no thread engagement on the nylon bolts inside the cab in the front and gunner's hatch areas (Photograph number 20238-026),

- 19. There is no access to clean the headlights; space will serve as a mud trap (Photograph number 20238-028), and
- 20. The cab mounts are deteriorating due to the additional weight (Photographs numbered 20238-021 and 022).


It is recommended that these items be addressed should this kit become a LVS option.

This kit was developed from the M977 (HEMTT) armor kit. The HEMTT kit was developed under short timelines for use in Bosnia. The HEMTT kit was designed, fabricated and tested in 3 months time, which left little time for any detailed structural analysis. All operating acceptance testing was done at Yuma Proving Grounds (YPG) and the results recorded at the M977 PM office at TACOM. ballistic testing was performed at Aberdeen Test Center (ATC) and the results recorded at the M977 PM office at White the HEMTT (and therefore the LVS) kit has some shortcomings, the intent of fielding a "bolt-on" kit for use in a major military deployment was achieved. of these changes are simple and can be accomplished with little effort (as in changing the protruding bolts to face outward), and some will require more effort (such as emergency escape during roll over).


4.0 RECOMMENDATIONS

- 1. Address the twenty-one items identified should further development be merited.
- 2. Perform accelerated fatigue testing of the vehicle.
- 3. Redesign the cab mounts to consist of a stiffer material.


APPENDIX A PHOTOGRAPHIC SUPPLEMENT




PHOTOGRAPH NO. 20238-001 LVS ARMOR PROTECTION KIT FRONT VIEW




PHOTOGRAPH NO. 20238-002 LVS ARMOR PROTECTION KIT PASSENGER SIDE VIEW




PHOTOGRAPH NO. 20238-003 LVS ARMOR PROTECTION KIT DRIVER SIDE VIEW




PHOTOGRAPH NO. 20238-004 LVS ARMOR PROTECTION KIT TOP CENTER VIEW




PHOTOGRAPH NO. 20238-005 LVS ARMOR PROTECTION KIT TOP PASSENGER SIDE VIEW




PHOTOGRAPH NO. 20238-006 LVS ARMOR PROTECTION KIT TOP DRIVER SIDE VIEW




PHOTOGRAPH NO. 20238-007 LVS ARMOR PROTECTION KIT FRONT UNDERCARRIAGE VIEW




PHOTOGRAPH NO. 20238-008 LVS ARMOR PROTECTION KIT FRONT UNDERCARRIAGE PASSENGER SIDE VIEW




PHOTOGRAPH NO. 20238-009 LVS ARMOR PROTECTION KIT FRONT UNDERCARRIAGE DRIVER SIDE VIEW




PHOTOGRAPH NO. 20238-010 LVS ARMOR PROTECTION KIT DRIVER SIDE DOOR HINGE




PHOTOGRAPH NO. 20238-011 LVS ARMOR PROTECTION KIT UPPER DOOR PIN LOOSE – CONTACT MARKS FROM DOOR




PHOTOGRAPH NO. 20238-012 LVS ARMOR PROTECTION KIT ARMOR PLATE NOT CONNECTED PROPERLY – GAP BETWEEN PLATE AND CAB




PHOTOGRAPH NO. 20238-013 LVS ARMOR PROTECTION KIT PROTRUDING BOLTS – DRIVER'S SIDE ROOF




PHOTOGRAPH NO. 20238-014 LVS ARMOR PROTECTION KIT PROTRUDING BOLTS BEHIND DRIVER'S SEAT




PHOTOGRAPH NO. 20238-015 LVS ARMOR PROTECTION KIT PROTRUDING BOLTS – PASSENGER'S SIDE HATCH




PHOTOGRAPH NO. 20238-016 LVS ARMOR PROTECTION KIT WINDOW LOCKS NOT TIGHT/OPERATIONAL




PHOTOGRAPH NO. 20238-017 LVS ARMOR PROTECTION KIT DEAD BOLT DOOR LOCK NOT TIGHT - RATTLES




PHOTOGRAPH NO. 20238-018 LVS ARMOR PROTECTION KIT DEAD BOLT DOOR LOCK NOT TIGHT - RATTLES




PHOTOGRAPH NO. 20238-019 LVS ARMOR PROTECTION KIT DOOR HANDLE LOCATION




PHOTOGRAPH NO. 20238-020 LVS ARMOR PROTECTION KIT DOOR HANDLE LOCATION




PHOTOGRAPH NO. 20238-021 LVS ARMOR PROTECTION KIT DRIVER SIDE CAB MOUNTS




PHOTOGRAPH NO. 20238-022 LVS ARMOR PROTECTION KIT PASSENGER SIDE CAB MOUNTS




PHOTOGRAPH NO. 20238-023 LVS ARMOR PROTECTION KIT PROTRUDING BOLTS PASSENGER SIDE




PHOTOGRAPH NO. 20238-024 LVS ARMOR PROTECTION KIT PROTRUDING BOLTS PASSENGER SIDE




PHOTOGRAPH NO. 20238-025 LVS ARMOR PROTECTION KIT CRUSHED CAB STRUCTURE TUBE




PHOTOGRAPH NO. 20238-026 LVS ARMOR PROTECTION KIT NYLON BOLT NOT ENGAGED




PHOTOGRAPH NO. 20238-027 LVS ARMOR PROTECTION KIT GUNNER'S PLATFORM BOLTED TO ARMOR



PHOTOGRAPH NO. 20238-028 LVS ARMOR PROTECTION KIT HEADLIGHT ACCESS ELIMINATED/ MUD TRAP AREA



PHOTOGRAPH NO. 20238-029 LVS ARMOR PROTECTION KIT NO TRACTION ON ARMOR PLATE STEP



PHOTOGRAPH NO. 20238-030 LVS ARMOR PROTECTION KIT DRIVER'S VISIBILITY