### UNCLASSIFIED

## AD NUMBER

AD366711

## **CLASSIFICATION CHANGES**

TO: unclassified

FROM: confidential

# **LIMITATION CHANGES**

#### TO:

Approved for public release, distribution unlimited

#### FROM:

Notice: Release only to U. S. Government Agencies is authorized. Other certified requesters shall obtain release approval from Director, Defense Atomic Support Agency, Washington, D. C. 20301.

## AUTHORITY

DSWA ltr., 10 Apr 97; DSWA ltr., 10 Apr 97

## THIS PAGE IS UNCLASSIFIED



By Anthority of Joint Chiefs or Starr (Action 15 Apr 49)

By Anthority of Joint Chiefs or Starr (Action 15 Apr 49)

# U.S.S. PENSACOLA (CA24)

TEST ABLE

Defende A comic Eupport Agency Westington, D. C. 20301

VOLUME 2 OF 2

TECHNICAL LIBRARY

of the

ARMED FORCES
SPECIAL WEAPONS PROJECT

OPERATION CROSSROADS DDC

DIRECTOR OF SHIP MATERIA

JOINT TASK FORCE ONE

NOV 2 1905

1965

1965

1965

1965

1965

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966

1966


1966

1966

CONFIDENTIAL







REG. NO.  $\frac{3}{2}$ 

# PHOTOGRAPHS

TEST ABLE

CONFIDENTIAL

Classification (Camadaed) (Changed to

The same of the initial States within the meaning of the downer to an unauthorzied person is promitted by law.

CONFIDENTIAL





U.S.S. PENSACOLA (CA24)


Page 1 of 265 Pages

GROUP-3

Downgraded at 12 year intervals:

Not automatically declassified.





AA-CR-227-50-127. View looking at bow.

Page 2 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-98-1965-3. View from off port bow (forward of after stack).

USS PENSACOLA (CA24)


Page 3 of 265 Pages



AA-CR-227-50-126. View looking at port bow.

USS PENSACOLA (CA24)

Page 4 of 265 Pages



AA-CR-98-1965-2. View from off port beam (forward of No. 4 mount).

USS PENSACOLA (CA24)

Page 5 of 265 Pages



AA-CR-62-1832-2. View from off port beam (aft of No. 1 mount).

USS PENSACOLA (CA 24)

Page 6 of 265 Pages



AA-CR-62-1860-3. View from off port beam (midbody and masts).

Page 7 of 265 Pages

USS PENSACOLA (CA24)



AA-CR-98-1965-4. View from off port beam. (after three-quarters).

Page 8 of 265 Pages

USS PENSACOLA (CA 24)



AA-CR-227-93-45. View looking at starboard beam.

Page 9 of 265 Pages

USS PENSACOLA (CA24)



AB-CR-79-4073-1. Port quarter showing dishing of shell plating which resulted from Test A.

Page 10 of 265 Pages

USS PENSACOLA (CA24)



AA-CR-98-1968-6. Looking upward and to starboard at foremast, showing mast bent forward. Note condition of equipment.

USS PENSACOLA (CA24)


Page 11 of 265 Pages



AA-CR-68-1759-8. Forward radar mast and rigging, looking to starboard. Note rigging still in place.

USS PENSACOLA (CA24)


Page 12 of 265 Pages



AA-CR-68-1758-4. Looking forward at forward superstructure from frame 74 starboard side.

USS PENSACOLA (CA24)

Page 13 of 265 Pages



AA-CR-68-1761-12. General view, looking at forward superstructure and radar polemast.

USS PENSACOLA (CA24)


Page 14 of 265 Pages



AB-CR-79-2959-10. Main mast looking to starboard from off port beam.

USS PENSACOLA (CA24)

Page 15 of 265 Pages



AA-CR-68-1759-4. Looking aft at mainmast showing yardarm and stays.

USS PENSACOLA (CA24)


Page 16 of 265 Pages



AA-CR-68-1757-11. Mainmast, strut and stays.

USS PENSACOLA (CA24)


Page 17 of 265 Pages



AA-CR-68-1754-1. Main Deck, forward gun mounts and bridges looking aft from bow.

Page 18 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-98-1968-3. Broken pedestal of 24" searchlight, port side of radar control room house top, frame 45.

Page 19 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-98-1968-4. Cracked pedestal of 24" searchlight, starboard side of radar control room house top, frame 45.

USS PENSACOLA (CA24)


Page 20 of 265 Pages



AA-CR-98-1968-5. Damage to ladder between radar control room house top and forward fire control station platform, frame 49, starboard. Cast aluminum treads failed at connections.

USS PENSACOLA (CA24)

Page 21 of 265 Pages



AA-CR-68-1760-12. Right side of forward 5 inch director showing damage to light dogged door.

USS PENSACOLA (CA24)


Page 22 of 265 Pages



AA-CR-98-1967-11. 5 inch A.A. gun director forward, looking to port at starboard side of director, showing door blown through door frame.

USS PENSACOLA (CA24)


Page 23 of 265 Pages



AA-CR-68-1759-9. Mark 33 Director from frame 48 port.

USS PENSACOLA (CA24)


Page 24 of 265 Pages



AA-CR-68-1760-10. Looking aft on starboard side of top of sea cabin and radar control room from about frame 45. Note failure of riveted joint connecting aluminum portion of house top to steel portion (lower left).

USS PENSACOLA (CA24)

Page 25 of 265 Pages



AA-CR-68-1760-9. Looking aft from top of sea cabin and Ready Service room at about frame 48, port side. Note position of stacks.

USS PENSACOLA (CA24)

Page 26 of 265 Pages



AA-CR-68-1759-6. General view to starboard on navigation bridge level from frame 48, port.

USS PENSACOLA (CA 24)


Page 27 of 265 Pages



AA-CR-68-1759-11. Navigation bridge, starboard side looking aft at frame 49.

USS PENSACOLA (CA24)


Page 28 of 265 Pages



AA-CR-98-1967-12. Navigating bridge, looking forward and to port, showing condition of equipment and bent wind-screen.

USS PENSACOLA (CA24)

Page 29 of 265 Pages



AA-CR-68-1760-8. Port side of signal booth looking to starboard on navigating bridge, frame 49, centerline.

USS PENSACOLA (CA24)


Page 30 of 265 Pages



AA-CR-68-1761-1. Looking forward on starboard side of navigating bridge showing damage to sluminum deck house.

USS PENSACOLA (CA24)

Page 31 of 265 Pages



AA-CR-98-1967-10. Damage to starboard after corner of house on navigating bridge level, looking aft and to port from about frame 46. Debris beyond house are remains of starboard flag bag.

USS PENSACOLA (CA24)

Page 32 of 265 Pages



AA-CR-68-1760-1. Navigating bridge, looking to port from frame 50, starboard, showing damage to after portion of navigating bridge level.

USS PENSACOLA (CA24)


Page 33 of 265 Pages



AA-CR-68-1760-5. Navigating bridge, showing diagonal after face of starboard side of deck house.

Page 34 of 265 Pages

USS PENSACOLA (CA21)



AA-CR-98-1968-2. Demolished port flag bag on navigating bridge level, looking to port and aft from about frame 49, centerline. Flag bag and railing have been blown forward. Structure at upper left is forward smoke stack.

USS PENSACOLA (CA24)


Page 35 of 265 Pages



AA-CR-98-1968-1. Emergency cabin on port after side of navigating bridge level, looking forward and to starboard. Cabin bulkhead is aluminum. Note piece of port flagbag at lower right.

USS PENSACOLA (CA24)

Page 36 of 265 Pages



AA-CR-68-1759-1. Looking down vertically on port flag bag at frame 50. Bag is completely demolished.

USS PENSACOLA (CA24)

Page 37 of 265 Pages



AA-CR-68-1760-11. Remains of flag bag on port side of after edge of navigation bridge, frame 50.

USS PENSACOLA (CA24)


Page 38 of 265 Pages



AA-CR-68-1760-7. Break in aluminum bulkhead seam, port side of deckhouse on navigating bridge.

USS PENSACOLA (CA 24)

Page 39 of 265 Pages



AA-CR-68-1761-2. Emergency platform, athwartships passageway at frame 48, looking to port, between radar transmitter room (left) and chart house (right).

USS PENSACOLA (CA24)


Page 40 of 265 Pages



AA-CR-68-1758-12. After portion of communication platform looking to port, taken from approximately frame 49.

USS PENSACOLA (CA24)


Page 41 of 265 Pages



AA-CR-98-1967-8. Damage to ladder between communication platform and emergency platform, frame 48, starboard side. Cast aluminum treads failed at connections.

USS PENSACOLA (CA24)

Page 42 of 265 Pages



AA-CR-68-1761-6. Damaged joiner door to captain's cabin on port side of superstructure deck.

USS PENSACOLA (CA24)

Page 43 of 265 Pages

65N11



AA-CR-68-1761-8. Damaged vent duct in passage on superstructure deck, frame 50. This duct exhausts battery room below.


Page 44 of 265 Pages

USS PENSACOLA (CA24)



AA-CK-68-1761-4. Interior view of trunk at main deck level, frames 46-47, looking to port. Note inward deflection of trunk bulkhead 47.


USS PENSACOLA (CA24)



AA-CR-68-1754-4. View on main deck, port side, looking forward to bulkhead 46 showing overhang of superstructure deck pulled away from deck beam at frame 47.

USS PENSACOLA (CA24)


Page 46 of 265 Pages



AA-CR-68-1754-12. Ladder trunk, main deck, frames 46 - 47, starboard, looking to port.

USS PENSACOLA (CA24)

Page 47 of 265 Pages



AA-CR-68-1761-5. View of damage to quick acting watertight door leading into Wardroom, frame 46, starboard, main deck looking forward.

USS PENSACOLA (CA24)


Page 48 of 265 Pages



AA-CR-68-1754-2. View on main deck, port side, looking forward and to starboard, showing damage to bulkheads 46 and trunk bulkhead 47.

USS PENSACOLA (CA24)


Page 49 of 265 Pages



AA-CR-88-2161-10. Looking to starboard at bulkhead 49, main deck, showing dished door.

USS PENSACOLA (CA24)


Page 50 of 265 Pages



AA-CR-68- 1755-1. Looking to port on main deck showing damaged doors in bulkhead 49.

USS PENSACOLA (CA24)


Page 51 of 265 Pages



AA-CR-68-1754-3. Damage to door in bulkhead 49 on port side of main deck looking aft and to starboard.

USS PENSACOLA (CA24)


Page 52 of 265 Pages



AA-CR-98-1966-8. View of forward stack and foremast structure, looking forward on port side.

USS PENSACOLA (CA24)

Page 53 of 265 Pages



AA-CR-98-1966-9. View of after side of forward superstructure showing damage to forward stack and bridge area.

USS PENSACOLA (CA24)


Page 54 of 265 Pages



AA-CR-98-1968-8. Looking down and aft from fire control platform show-ind damage to starboard side of forward stack.

USS PENSACOLA (CA24)

Page 55 of 265 Pages



AA-CR-98-1968-7. General view looking aft.

Page 56 of 265 Pages

USS PENSACOLA (CA24)



AA-CR-98-1967-7. Looking aft from communication platform. Base of forward stack is at lower right.

USS FENSACOLA (CA24)


Page 57 of 265 Pages



AA-CR-98-1967-9. Looking aft from navigating bridge.

USS PENSACOLA (CA24)


Page 58 of 265 Pages



AA-CR-98-1966-7. Damage to after stack from starboard side of main deck at frame 60, looking aft.

USS PENSACOLA (CA24)


Page 59 of 265 Pages



AA-CR-68-1758-7. Galley skylight looking to starboard on superstructure deck from frame 75.

USS PENSACOLA (CA24)

Page 60 of 265 Pages




AA-CR-68-1758-10. Forward face of emergency radar and fire control station, frame 85, superstructure deck. Pipe bracing supports a clipping room and searchlight platform above. Note collapsed bulkhead by pressure differential. This room was sealed off and all sides were similiarly dished.

SECRET

USS PENSACOLA (CA24)


Page 61 of 265 Pages



AA-CR-65-1851-4. Galley skylight on superstructure deck, frame 84-85, looking to starboard. Note searchlight at left which fell about 22 feet to skylight. Superstructure deck has been pushed down along the forward edge of skylight.

USS PENSACOLA (CA24)


Page 62 of 265 Pages



AA-CR-68-1758-8. Starboard bulkhead of emergency radar and fire control station, frame 87, superstructure deck.

USS PENSACOLA (CA24)

Page 63 of 265 Pages



AA-CR-98-1966-12. Looking forward at starboard side to 40 mm quad on superstructure deck at frame 95 1/2.

USS PENSACOLA (CA24)

Page 64 of 265 Pages



AA-CR-68-1758-9. Looking to port on superstructure deck at frame 97. Note tear in deck in way of 40 mm gun shield.

USS PENSACOLA (CA24)


Page 65 of 265 Pages



AA-CR-68-1759-7. View looking to starboard from tub in port leg of main mast.

USS PENSACOLA (CA24)


Page 66 of 265 Pages



AA-CR-68-1761-3. Mainmast, looking forward and up at junction of struts.

USS PENSACOLA (CA24)


Page 67 of 265 Pages



AA-CR-68-1755-9. View looking aft at mainmast and airplane boom tripod.

Page 68 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1755-10. Mainmast strut and stay.

USS PENSACOLA (CA24)

Page 69 of 265 Pages



AA-CR-88-2161-5. Damage to base of port strut to main mast after Test A.

USS PENSACOLA (CA24)

Page 70 of 265 Pages



AA-CR-68-1757-6. Looking upward and aft at underside of superstructure deck in way of damage to base of port mainmast strut.

USS PENSACOLA (CA24)


Page 71 of 265 Pages



AA-CR-88-2161-6. Damage to base of starboard mainmast strut, frame 90, on superstructure deck level.

USS PENSACOLA (CA24)

Page 72 of 265 Pages



AA-CR-68-1757-7. Looking upward and aft at underside of superstructure deck in way of damage to starboard mainmast strut.

USS PENSACOLA (CA24)


Page 73 of 265 Pages



AA-CR-88-2161-7. Underside of superstructure deck in way of starboard strut to mainmast.

USS PENSACOLA (CA24)

Page 74 of 265 Pages



AA-CR-88-2161-8. Underside of superstructure deck in way of port mainmast strut.

USS PENSACOLA (CA24)


Page 75 of 265 Pages



AA-CR-88-2161-9. #5 bulkhead and door panel under mainmast buckled.

USS PENSACOLA (CA24)


Page 76 of 265 Pages



AA-CR-68-1757-1. General view from main deck taken from port side aft showing forward radar polemast and port mainmast stay.

USS PENSACOLA (CA24)


Page 77 of 265 Pages



AA-CR-68-1757-2. General view taken from starboard side of main deck, aft, showing forward radar polemast and starboard mainmast stay.

USS PENSACOLA (CA24)


Page 78 of 265 Pages



AA-CR-68-1758-11. Looking aft on main deck to well deck bulkhead 71 1/2.

Page 79 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1755-12. Looking to port on main deck from frame 72, starboard, showing afterward dishing of bulkhead 72.

Page 80 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1755-11. Damaged door to shipfitter shop, main deck, starboard, frame 74, looking aft and to starboard.

USS PENSACOLA (CA24)


Page 81 of 265 Pages



AA-CR-68-1757-9. Shock derangement and blast damage, looking forward along port passageway, main deck, from frame 83.

USS PENSACOLA (CA24)


Page 82 of 265 Pages



AA-CR-68-1756-4. View of galley, main deck, from starboard passageway. The stanchions at frame 85 have buckled under the load imposed by the pipe bracing used as supports for a clipping room and search light platform directly above.

USS PENSACOLA (CA24)


Page 83 of 265 Pages



AA-CR-68-1757-8. Blast damage, looking forward port main deck passageway, from frame 87.

Page 84 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1757-5. Looking forward along port main deck passageway from frame 93.

USS PENSACOLA (CA24)

Page 85 of 265 Pages



AA-CR-68-1756-5. Looking forward along starboard main deck passageway from frame 92. Note demage to light doors and expanded mesh bulkhead due to blast pressure funneled through passageway.

USS PENSACOLA (CA24)


Page 86 of 265 Pages



AA-CR-68-1756-3. Starboard main deck passageway, looking forward from frame 89.

USS PENSACOLA (CA24)


Page 87 of 265 Pages



AA-CR-68-1755-7. Main deck, starboard, looking toward bow from just aft of No. 1 mount.

USS PENSACOLA (CA24)


Page 88 of 265 Pages



AA-CR-1968-9. Looking forward from starboard edge of first level above navigating bridge. Note scorching of decking directly exposed.

USS PENSACOLA (CA24)


Page 89 of 265 Pages



AA-CR-68-1755-8. Main deck port side, looking toward bow from just aft of No. 1 mount.

USS PENSACOLA (CA24)


Page 90 of 265 Pages



AA-CR-98-1967-3. Looking forward from starboard side of main deck at about frame 17. Note protection from radiation afforded decking at left by No. 1 mount.

USS PENSACOLA (CA24)


Page 91 of 265 Pages



AA-CR-98-1967-5. Starboard side of main deck in way of frame 20, looking aft.

USS PENSACOLA (CA24)

Page 92 of 265 Pages



AA-CR-98-1967-2. Starboard side of main deck in way of frame 30, looking aft.

Page 93 of 265 Pages

USS PENSACOLA (CA24)




AA-CR-98-1967-4. Port side of main deck in way of frame 20, looking aft.

USS PENSACOLA (CA24)

6544


Page 94 of 265 Pages



AA-CR-68-1755-6. Fire damage on main deck under No. 1 mount just forward of bulkhead 29.

USS PENSACOLA (CA24)

Page 95 of 265 Pages




AA-CR-98-1966-6. Starboard side of main deck, looking forward from frame 60. Smoke hood from forward stack is lying across passageway.

SECRE'I'

USS PENSACOLA (CA24)


Page 96 of 265 Pages



AA-CR-68-1754-11. Main deck looking forward on starboard side showing tear of lighter plating along stringer strake in well deck area.

USS PENSACOLA (CA24)


Page 97 of 265 Pages



AA-CR-68-1767-3. Looking forward on main deck in well deck area, starboard, from frame 72. (deck deflection survey in progress.)

USS PENSACOLA (CA24)


Page 98 of 265 Pages



AA-CR-68-1758-1. Main deck well deck area looking forward on starboard side showing tear of lighter plating along stringer strake.

USS PENSACOLA (CA24)

Page 99 of 265 Pages



AA-CR-58-1767-4. Closeup of main deck failure along starboard stringer strake in well deck area aft of frame 61, looking to port from starboard deck edge.

USS PENSACOLA (CA24)

Page 100 of 265 Pages



AA-CR-68-1767-7. Looking to port from starboard deck edge in main deck, well deck area showing area of severe dishing, also plate failure along edge of starboard stringer strake.

USS PENSACOLA (CA24)


Page 101 of 265 Pages



AA-CR-68-1754-8. Close-up of starboard forward portion of main deck, well deck area, looking to port, showing tear of lighter plating along stringer strake, deck dishing and damage to deck house bulkhead 61.

USS PENSACOLA (CA24)


Page 102 of 265 Pages




AA-CR-98-1966-4. Close-up of failure at riveted seam in inboard edge of heavy stringer strake, frames 61-63, on starboard side of main deck.

USS PENSACOLA (CA24)

Page 103 of 265 Pages



AA-CR-175-2157-7. Main deck dishing in well deck area looking forward and to starboard.



AA-CR-175-2157-10. Main deck dishing in well deck area looking forward and to starboard. Torn portion of deck house bulkhead has been cut away.

USS PENSACOLA (CA24)


Page 105 of 265 Pages



AA-CR-175-2157-8. Main deck, well deck area, looking forward and to port, showing deck dishing and damage to forward stack cape and rear of deck house.

USS PENSACOLA (CA24)


Page 106 of 265 Pages



AA-CR-175-2157-9. Main deck dishing in well deck area and damage to bulkhead 61, looking forward and to port.

USS PENSACOLA (CA24)


Page 107 of 265 Pages



AA-CR-68-1767-2. Looking forward in main deck, well deck area, showing area of severe deck deflection. Note deck plating failure athwartship at starboard after corner of hatch and fore and aft failure along edge of starboard stringer strake. SECRET

Page 108 of 265 Pages

USS PENSACOLA (CA24)




AA-CR-68-1767-1. Looking forward on main deck in well deck area, port side, from frame 72, (deck deflection survey in progress).

SECRFT

USS PENSACOLA (CA24)


Page 109 of 265 Pages



AA-CR-68-1754-7. Main deck dishing in well deck area looking forward on centerline to bulkhead 61.


USS PENSACOLA (CA24)

Page 110 of 265 Pages



AA-CR-68-1767-8. Looking aft and to port on main deck in well deck area, from bulkhead 61 starboard.

USS PENSACOLA (CA24) Page 111 of 265 Pages



AA-CR-68-1767-6. Looking to starboard on main deck just aft of bulkhead 61 in well deck area showing deck deflection in way of centerline hatch.

USS PENSACOLA (CA24)


Page 112 of 265 Pages



AA-CR-68-1767-5. Looking aft on main deck in well deck area showing ruptures at frame 62 1/2 in way of port ventilation trunk and hatch.

USS PENSACOLA (CA24)

Page 113 of 265 Pages



AA-CR-68-1761-11. Looking to starboard and forward on main deck in well deck area showing damage to bulkhead 61.

Page 114 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1754-9. Failure of main deck plating-butt at frame 62 1/2 to starboard of centerline hatch in well deck area.

USS PENSACOLA (CA24)


Page 115 of 265 Pages



AA-CR-68-1757-4. Blast damage, looking forward from frame 102, port side, main deck.

USS PENSACOLA (CA24)


Page 116 of 265 Pages



AA-CR-68-1757-3. Collapsed ventilation duct, frame 100, port, main deck, looking forward.

USS PENSACOLA (CA24)


Page 117 of 265 Pages



AA-CR-68-1756-6. Looking aft at bulkhead 104 starboard, main deck, from frame 99.

USS PENSACOLA (CA24)


Page 118 of 265 Pages



AA-CR-98-1965-7. Main deck, port side looking forward from frame 108, showing scorched wood deck.

USS PENSACOLA (CA24)


Page 119 of 265 Pages



AA-CR-68-1756-7. General view looking aft from frame 160 showing condition of starboard side of main deck.

USS PENSACOLA (CA24)

Page 120 of 265 Pages



AA-CR-68-1766-12. General view of main deck aft, looking aft and to port, showing deck dishing just aft of No. 4 mount.

USS PENSACOLA (CA24)

Page 121 of 265 Pages



AA.CR-175-2158-10. Main deck, starboard, looking from frame 120, after removal of burned Army equipment showing damage to wood decking; also the downward deflection of the deck further aft is noticeable.

USS PENSACOLA (CA24)

Page 122 of 265 Pages



AA-CR-68-1764-6. Looking aft and to port on main deck, showing burned wood deck in way of special Army equipment stowage.

USS PENSACOLA (CA24)


Page 123 of 265 Pages



AA-CR-68-1756-8. Damaged portion of main deck, frame 122, starboard showing former location of Army equipment destroyed by fire.

USS PENSACOLA (CA24)


Page 124 of 265 Pages



AA-CR-68-1764-10. Looking athwartship to port on main deck in dished area just aft of No. 4 mount.

USS PENSACOLA (CA24)

Page 125 of 265 Pages



AA-CR-68-1764-11. Looking athwartship to port on main deck in dished area between winch and No. 4 mount.

USS PENSACOLA (CA24)

Page 126 of 265 Pages



AA-CR-98-1965-10. Close-up of burned special equipment on main deck abreast No. 4 mount, looking aft and to starboard, showing deck dishing aft.

USS PENSACOLA (CA24)


Page 127 of 265 Pages



AA-CR-98-1965-9. Close-up of burned special equipment on main deck to port of No. 4 mount, looking aft.

Page 128 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-98-1965-8. Looking aft on port side in way of burned special equipment on main deck abreast No. 4 mount.

USS PENSACOLA (CA24)

Page 129 of 265 Pages



AA-CR-68-1756-12. Port side of weather deck, looking forward from frame 125 showing some of remains of burned Army equipment.

USS PENSACOLA (CA24)


Page 130 of 265 Pages



AA-CR-68-1756-11. Looking forward on weather deck from frame 130; the deflection of the deck is noticeable from edge of number 4 mount aft. Note pocket of water, also separation in deck just aft of turret foundation.

Page 131 of 265 Pages

USS PENSACOLA (CA24)



AA-CR-175-2158-9. Looking to port on main deck, frame 125, after burned Army equipment had been removed and the deck made watertight.

Page 132 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1764-7. Looking forward on main deck aft from frame 133, (APA 229 alongside).

Page 133 of 265 Pages

USS PENSACOLA (CA24)



AA-CR-175-2158-8. Looking forword along weather deck to starboard from frame 135 after debris had been removed.

USS PENSACOLA (CA24)


Page 134 of 265 Pages



AA-CR-68-1756-10. Looking forward on weather deck from frame 138. Note maximum deflection of deck occurs in way of the two companion hatches in the background, frames 125-126.

USS PENSACOLA (CA24)


Page 135 of 265 Pages



AA-CR-68-1764-5. General view of main deck aft, looking toward stern on port side.

USS PENSACOLA (CA24)


Page 136 of 265 Pages



AA-CR-98-1965-11. Looking forward and to port on main deck aft to area of burned special equipment stowed to port of No. 4 mount.

USS PENSACOLA (CA24)

Page 137 of 265 Pages



AA-CR-68-1756-9. Looking aft and to port on weather deck from frame 125. Note light charring of wooden decking on port side where deck was directly exposed.

USS PENSACOLA (CA24)


Page 138 of 265 Pages



AA-CR-175-2158-5. Looking to starboard on weather deck, frame 122, after burned equipment stowed on deck during test, had been removed.

USS PENSACOLA (CA24)

Page 139 of 265 Pages



AA-CR-175-2158-6. Looking aft and to starboard on weather deck from frame 126, in way of the maximum deck deflection.

Page 140 of 265 Pages

USS PENSACOLA (CA24)



AA-CR-175-2158-11. Looking aft and to starboard from frame 134 after debris had been removed.

Page 141 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-175-2158-12. Looking to port on weather deck from frame 134 after debris had been removed.

Page 142 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-98-1965-12. Looking aft and to port on main deck showing deck dishing at frame 135.

USS PENSACOLA (CA24)


Page 143 of 265 Pages



AA-CR-68-1762-1. Cracked bracket at frame 16 port side under main deck.

Page 144 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1761-10. Typical damage to metal joiner bulkhead over a door, from pressure above.

Page 145 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1761-9. Typical bulge in metal joiner bulkhead from pressure above.

USS PENSACOLA (CA24)


Page 146 of 265 Pages



AA-CR-68-1762-4. Looking aft on 2nd deck from frame 48 into starboard passage B-201L showing damage to Marine Office bulkhead caused by venting of blast pressure from air intake area.

USS PENSACOLA (CA24)


Page 147 of 265 Pages



AA-CR-175-2157-12. C-201-L. Looking forward on 2nd deck through door in bulkhead 62 showing damage in port passageway B-201L caused by blast pressure in air intake area. Note crushing of bulkhead 62 near overhead as a result of deflection of the overhead.

Page 148 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1768-8. C-201L. Looking forward on 2nd deck in crew's space starboard, through door into engine room exhaust trunk showing damage to bulkhead 62.

USS PENSACOLA (CA24)


Page 149 of 265 Pages



AA-CR-68-1768-7. C-201L. Looking to port on 2nd deck, starboard side, in crew's space showing buckled stanchion at frame 63 and deflected main deck longitudinals. Note door to engine room exhaust trunk lying on deck.

USS PENSACOLA (CA24)


Page 150 of 265 Pages



AA-CR-68-1768-4. C-201L. Looking forward and to starboard on 2nd deck in crew's space on port side showing buckled stanchion at frame 68 and damaged ventilation duct.

USS PENSACOLA (CA24)


Page 151 of 265 Pages



AA-CR-68-1762-8. C-201L. Looking forward on 2nd deck along port side of ship's service store, showing damage to vent ducts.

Page 152 of 265 Pages

USS PENSACOLA (CA24)



AA-CR-175-2158-1. C-201L. Looking to starboard on 2nd deck showing stanchion failures at web frame 65.

USS PENSACOLA (CA24)


Page 153 of 265 Pages



AA-CR-68-1767-12. C-201L Looking to starboard on 2nd deck along forward side of ship's service store showing stanchion failure at web frame 65.

USS PENSACOLA (CA24)

Page 154 of 265 Pages



AA-CR-68-1762-7. C-201L. Looking to port on 2nd deck showing damage at frame 65 to forward side of ship's service store.

USS PENSACOLA (CA24)


Page 155 of 265 Pages



AA-CR-175-2158-4. C-201L. Looking forward on port side, 2nd deck, to bulkhead 62 and passage B-201L showing stanchion failures at frames 63 and 64. Note crushing of bulkhead 62 near overhead.

USS PENSACOLA (CA24)

Page 156 of 265 Pages



AA-CR-68-1762-9. Looking aft on 2nd deck along broken deck longitudinal located 8 feet to port of centerline. The forward port corner of the ship's service store appears in left background. The break in the longitudinal is approximately at frame 62.

USS PENSACOLA (CA24)

Page 157 of 265 Pages



AA-CR-88-2158-3. Looking to port on 2nd deck, port side, showing stanchion failures at frame 64 and under web frame 65.

Page 158 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1767-9. C-201L. Looking to starboard on 2nd deck at frame 61 in crew's space showing failure of main deck longitudinal at frame 62 1/2.

USS PENSACOLA (CA24)

Page 159 of 265 Pages




AA-CR-68-1767-10. C-201L. Looking aft on 2nd deck, port side in crew's space, showing failure of main deck longitudinal at frame 62 1/2 and damaged ventilation duct.

USS PENSACOLA (CA24)

Page 160 of 265 Pages




AA-CR-68-1767-11. C-201L. Looking to port on 2nd deck from centerline in crew's space showing failure of main deck longitudinal at frame 62 1/2.



AA-CR-175-2158-2. C-201L. Fractured longitudinal under main deck, frame 62.

USS PENSACOLA (CA24)


Page 162 of 265 Pages



AA-CR-68-1768-11. C-201L. Looking aft and to port on 2nd deck in crew's space starboard, showing buckled stanchion at frame 68.

USS PENSACOLA (CA24)


Page 163 of 265 Pages



AA-CR-68-1768-10. C-201L. Looking aft and to port on 2nd deck in ship's service store showing buckled centerline stanchion at frame 68.

USS PENSACOLA (CA24)

Page 164 of 265 Pages



AA-CR-68-1768-9. C-201L. Looking forward on 2nd deck at centerline, in ship's service store, showing deflection of frame 65 and ventilation duct damage.

USS PENSACOLA (CA24)


Page 165 of 265 Pages



AA-CR-98-1762-6. Looking to port on 2nd deck in ship's service store. Note buckled stanchion has tripped flange of web frame 68.

USS PENSACOLA (CA24)

Page 166 of 265 Pages



AA-CR-175-2157-11. Looking aft on 2nd deck port side in barber shop showing damage to web frame 65.

USS PENSACOLA (CA24)

Page 167 of 265 Pages



AA-CR-68-1768-6. C-201L. Looking to starboard on 2nd deck in crew's space showing damage to port side of port engine room exhaust trunk just aft of frame 70.

USS PENSACOLA (CA24)


Page 168 of 265 Pages



AA-CR-68-1768-5. C-201L. Looking forward and to port on 2nd deck in crew's wash room showing buckling of bulkhead 70.

USS PENSACOLA (CA24)

Page 169 of 265 Pages




AA-CR-68-1768-12. C-201L. Starboard side just forward of bulkhead 72 looking to port in crew's space, showing damaged longitudinal starboard bulkhead of crew's washroom (bulkhead 72 appears at left of view.)

BECRET

USS PENSACOLA (CA24)


Page 170 of 265 Pages



AA-CR-90-574-10. Looking forward at frame 94, port. Main deck. Note distortion of flange.

Page 171 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-90-574-12. C-202-L. Second deck, frame 97, port side. Note deformation of stanchions and crack around top under beam.

USS PENSACOLA (CA24)


Page 172 of 265 Pages



AA-CR-68-1766-4. Compartment D-203-1L. Crew's space, 2nd deck, looking forward on starboard side from frame 119.

Page 173 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1766-5. Compartment D-203-1L, crew's space, 2nd deck, looking aft from frame 11B on port side.

USS PENSACOLA (CA24)


Page 174 of 265 Pages



AA-CR-68-1766-3. Compartment D-203-L. Crew's space, 2nd deck, looking aft and to port along starboard deck plating from frame 119.

USS PENSACOLA (CA24)


Page 175 of 265 Pages



AA-CR-68-1766-2. Compartment D-203-L. Crew's space, 2nd deck, looking aft along port side deck plating from frame 119.

USS PENSACOLA (CA24)


Page 176 of 265 Pages



AA-CR-175-2178-10. Looking forward and to starboard shell on 2nd deck showing flange failure of web frame 122.

USS PENSACOLA (CA24)

Page 177 of 265 Pages




AA-CR-175-2178-6. Looking forward and to port shell on 2nd deck showing damage to web frame 122.

USS PENSACOLA (CA24)

Page 178 of 265 Pages


654,4



AA-CR-175-2178-9. Looking aft and to port on 2nd deck, starboard side, showing stanchion failure at web frame 122.

Page 179 of 265 Pages

USS PENSACOLA (CA24)



AA-CR-175-2178-7. Looking forward and to starboard on 2nd deck, port side aft of No. 4 barbette, showing stanchion failure at web frame 122. (Note crushing at stanchion foot).

USS PENSACOLA (CA24)


Page 180 of 265 Pages



AA-CR-175-2178-1. Looking aft and to starboard shell on 2nd deck showing damage to web frame 125.

USS PENSACOLA (CA24)

Page 181 of 265 Pages




AA-CR-68-1755-3. D-203-L. Test A damage. Looking aft and to port at bulkhead 128, starboard.

USS PENSACOLA (CA24)

Page 182 of 265 Pages


6544.



AA-CR-68-1765-4. Compartment D-203-L. Crew's space, 2nd deck, details of damage to frame 125, looking forward from frame 128.

USS PENSACOLA (CA24)

Page 183 of 265 Pages



AA-CR-68-1765-2. Compartment D-203-L. View of crew space, 2nd deck, looking forward and to starboard from frame 125, showing damage to frame 122.

USS PENSACOLA (CA24)


Page 184 of 265 Pages



AA-CR-175-2178-5. Looking aft and to port shell on 2nd deck showing failure of web frame 125.

USS PENSACOLA (CA24)


Page 185 of 265 Pages



AA-CR-175-2178-2. Looking forward on 2nd deck showing failure of stanchion at web frame 125.

USS PENSACOLA (CA24)


Page 186 of 265 Pages



AA-CR-68-1766-1. Compartment D-203L. Crew's space 2nd deck, looking aft on port side from frame 118.

USS PENSACOLA (CA24)


Page 187 of 265 Pages



AA-CR-175-2178-4. Looking aft on 2nd deck showing stanchion failure, starboard side, in way of web frame 125.

USS PENSACOLA (CA24)


Page 188 of 265 Pages



AA-CR-175-2178-11. Looking aft and to port on 2nd deck showing damage to centerline stanchion at frame 125.

USS PENSACOLA (CA24)


Page 189 of 265 Pages



AA-CR-68-1755-2. Looking aft and to port on 2nd deck showing damage to stanchions and to blower duct. Note web frame 125 and deck displacement gauge in foreground.

USS PENSACOLA (CA24)


Page 190 of 265 Pages



AA-CR-68-1765-5. Compartment D-203-L, crew's space; 2nd deck, looking aft and to port from frame 123, starboard side.

USS PENSACOLA (CA24)


Page 191 of 265 Pages



AA-CR-68-1765-1. Compartment D-203-L. View of crew's space, 2nd deck, looking aft and to port from starboard access at frame 120. The overhead is down several inches.

USS PENSACOLA (CA24)


Page 192 of 265 Pages



AA-CR-68-1765-3. Compartment D-203-L. Crew's space, 2nd deck, close-up of deck deflection scratch gage at frame 124, starboard side, looking forward and to port.

USS PENSACOLA (CA24)


Page 193 of 265 Pages



AA-CR-175-2178-3. Looking to port on 2nd deck showing failure of center-line stanchion at web frame 125 and damage to blower duct.

Page 194 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1765-7. Compartment D-203-L. Crew's space, 2nd deck, looking aft and to starboard, from frame 124, port side.

USS PENSACOLA (CA24)


Page 195 of 265 Pages



AA-CR-68-1765-9. Compartment D-203-L. Crew's space, 2nd deck, looking aft on starboard side showing damage to bulkhead 128.

Page 196 of 265 Pages

USS PENSACOLA (CA24)



AA-CR-175-2178-12. Looking aft and to starboard shell on 2nd deck showing damage to bulkhead 128 and web frame.

Page 197 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1765-10. Compartment D-203-L, crew's space, 2nd deck, forward face of bulkhead 128, just inboard of starboard access.

USS PENSACOLA (CA24)


Page 198 of 265 Pages



AA-CR-68-1765-11. Compartment D-203L, crew's space, 2nd deck, looking aft at center portion of bulkhead 128.

USS PENSACOLA (CA24)


Page 199 of 265 Pages



AA-CR-175-2179-1. D-203L. Looking aft and to starboard on 2nd deck showing stanchion failure at bulkhead 128 starboard.

USS PENSACOLA (CA24)

Page 200 of 265 Pages



AA-CR-68-1765-12. Compartment D-203L, crew's space, 2nd deck, forward face of bulkhead 128 in way of port access.

USS PENSACOLA (CA24)


Page 201 of 265 Pages



AA-CR-175-2179-2. D-203L. Looking aft on 2nd deck, port side, showing damage to web frame 128 and door to C.P.O. Mess.

USS PENSACOLA (CA24)


Page 202 of 265 Pages



AA-CR-68-1766-6. Compartment D-203-2L. C.P.O.'s mess, 2nd deck, looking forward and to port from starboard passageway.

USS PENSACOLA (CA24)

Page 203 of 265 Pages



AA-CR-68-1755-5. Looking to port and forward to bulkhead 128 on 2nd deck.

USS PENSACOLA (CA24)


Page 204 of 265 Pages



AA-CR-175-2179-3. D-203-2L. Looking aft on 2nd deck in C.P.O. mess showing damage to stanchion at frame 130, starboard.

Page 205 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-175-2179-4. D-203-2L. Looking aft at centerline stanchion and girder at frame 130.

Page 206 of 265 Pages

USS PENSACOLA (CA24)



AA-CR-175-2179-6. D-203-2L. Looking aft on 2nd deck in C.P.O. mess showing damage to stanchion at frame 130, port.

Page 207 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1766-7. Compartment D-203-2L. C.P.O.'s mess, 2nd deck, looking to starboard showing buckled and fractured stanchion at frame 130 and damage to C.P.O. pantry.

USS PENSACOLA (CA24)

Page 208 of 265 Pages



AA-CR-175-2179-7. D-204-L. Looking aft at failure in transverse girder 135 in way of lightening hole.

Page 209 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1766-8. Compartment D-204-L. C.P.O. quarters, 2nd deck, looking aft on starboard side showing damage to frame 135.

USS PENSACOLA (CA24)

Page 210 of 265 Pages



AA-CR-175-2179-11. D-204L. Looking forward and to port on 2nd deck showing failure of bulkhead 139 1/2 at port shell.

USS PENSACOLA (CA24)


Page 211 of 265 Pages



AA-CR-175-2179-12. Looking forward on 2nd deck showing failure of port side stanchion at frame 135. Note deflection of deck beam toward centerline.

USS PENSACOLA (CA24)


Page 212 of 265 Pages



AA-CR-68-1766-9. Compartment D-205-L. C.P.O. quarters, 2nd deck, looking to port and forward showing damage to centerline longitudinal at frame 136 1/2.

Page 213 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-175-2180-1. Looking forward on 2nd deck showing failure of center-line stanchion at frame 135 in C.P.O. quarters.

USS PENSACOLA (CA24)


Page 214 of 265 Pages



AA-CR-175-2179-8. D-204L. Looking aft and to starboard on 2nd deck showing failure of main deck longitudinal at frame 137.

Page 215 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-68-1766-10. C.P.O. wash room, 2nd deck after side of bulkhead 139 1/2 looking to port from starboard access.

USS PENSACOLA (CA24)


Page 216 of 265 Pages



AA-CR-68-1766-11. C.P.O. wash room, 2nd deck, failure of riveted connection of bulkhead 139 1/2, in way of intersection of main deck and port shell.

USS PENSACOLA (CA24)


Page 217 of 265 Pages



AA-CR-68-1763-5. Bulkhead No. 43, looking forward at centerline of ship between 1st and 2nd platforms.

Page 218 of 265 Pages

USS PENSACOLA (CA24)



AA-CR-68-1763-6. Bulkhead No. 43, looking forward at centerline of ship between 1st and 2nd platforms.

USS PENSACOLA (CA24)

Page 219 of 265 Pages



AA-CR-68-1762-2. Bulkhead No. 43, showing crushing at centerline under forward leg of forward tripod. Looking aft from starboard side.

USS PENSACOLA (CA24)

Page 220 of 265 Pages



AA-CR-68-1762-3. Bulkhead No. 43, lower end of starboard bracket about 18 inches off centerline. Looking aft, between first and second platform.

USS PENSACOLA (CA24)

Page 221 of 265 Pages



AA-CR-68-1763-1. View in No. 2 fireroom, upper level, looking aft between boilers to centerline column. Note stress lines on column.

USS PENSACOLA (CA24)


Page 222 of 265 Pages



AA-CR-90-575-1. B-2. Looking aft in after fireroom showing centerline stanchion at frame 78 1/2.

USS PENSACOLA (CA24)

Page 223 of 265 Pages



AA-CR-68-1763-2. B-2. Close-up of stressed paint near upper end of centerline stanchion in after fireroom at frame 78 1/2, looking to starboard.

USS PENSACOLA (CA24)


Page 224 of 265 Pages



AA-CR-90-575-4. B-2. Close-up of stressed paint on centerline stanchion in after fireroom at frame 78 1/2.

USS PENSACOLA (CA24)


Page 225 of 265 Pages



AA-CR-90-575-3. B-2. Close-up of stressed paint on centerline stanchion in after fireroom at frame 78 1/2, looking to starboard.

USS PENSACOLA (CA24)


Page 226 of 265 Pages



AA-CR-90-574-9. Looking aft in after engine room, starboard side, showing buckle in flange of transverse girder at frame 93 under 2nd deck.

USS PENSACOLA (CA24)


Page 227 of 265 Pages



AA-CR-90-574-7. C-2. Looking aft in after engine room, port side, showing buckle in flange of transverse girder at frame 93 under 2nd deck.

USS PENSACOLA (CA24)


Page 228 of 265 Pages



AA-CR-90-574-2. C-2. Looking forward on lower level in after engine room showing damage to centerline stanchion at frame 93.

USS PENSACOLA (CA24)


Page 229 of 265 Pages



AA-CR-90-574-3. C-2. Looking aft on lower level in after engine room showing centerline stanchion at frame 93.

USS PENSACOLA (CA24)

Page 230 of 265 Pages



AA-CR-90-574-4. C-2. Connection of centerline stanchion in after engine room at frame 93, to longitudinal girder under 2nd deck.

Page 231 of 265 Pages


USS PENSACOLA (CA24)



AA-CR-90-574-6. Looking aft in after engine room showing centerline girder, frames 95-96.

USS PENSACOLA (CA24)

Page 232 of 265 Pages



AA-CR-90-574-5. C-2. Looking to starboard in after engine room just forward of after bulkhead, showing centerline girder, frames 95-96.

USS PENSACOLA (CA24)

Page 233 of 265 Pages



AA-CR-62-1879-3. #2 Boiler, upper port side casing.

USS PENSACOLA (CA24)


Page 234 of 265 Pages



AA-CR-62-1879-8. #4 Boiler, outboard casing.

USS PENSACOLA (CA24)


Page 235 of 265 Pages



AA-CR-62-1879-9. #8 Boiler, cutboard casing.

Page 236 of 265 Pages

USS PENSACOLA (CA24)



AA-CR-62-1878-12. #1 Boiler, outboard side casing.

USS PENSACOLA (CA24)

Page 237 of 265 Pages



AA-CR-62-1879-2. #2 Boiler, upper front casing, outboard.


USS PENSACOLA (CA24) Page 238 of 265 Pages



AA-CR-62-1879-4. #2 Boiler, upper front casing.

USS PENSACOLA (CA24)

Page 239 of 265 Pages




AA-CR-62-1879-5. Space between boilers #1 and #2 from rear.

USS PENSACOLA (CA24)

Page 240 of 265 Pages


КБЦЦ



AA-CR-62-1879-6. Space between boilers #3 and 4 from rear.

USS PENSACOLA (CA24)

Page 241 of 265 Pages



AA-CR-62-1879-1. #1 Boiler corbel at front wall, starboard side.

USS PENSACOLA (CA24)

Page 242 of 265 Pages



AA-CR-62-2173-1. #7 Boiler, repaired outboard casing.

USS PENSACOLA (CA24)


Page 243 of 265 Pages



AA-CR-62-2173-2. #7 Boiler, repaired outboard casing.

Page 244 of 265 Pages

USS PENSACOLA (CA24)



AA-CR-62-1879-10. Forward stack, port side from main deck.

USS PENSACOLA (CA24)


Page 245 of 265 Pages



AA-CR-62-1879-11. After stack.

USS PENSACOLA (CA 24)

Page 246 of 265 Pages



AA-CR-62-1879-12. Forward stack, starboard side, (Diagonal shot).

USS PENSACOLA (CA24)

Page 247 of 265 Pages



AA-CR-68-1757-12. After stack.

USS PENSACOLA (CA24)

Page 248 of 265 Pages



AA-CR-68-1758-5. Forward stack.

USS PENSACOLA (CA24)


Page 249 of 265 Pages



AA-CR-68-1759-2. Forward stack.

USS PENSACOLA (CA24)

Page 250 of 265 Pages




AA-CR-68-1760-4. Forward stack.

USS PENSACOLA (CA24)

Page 251 of 265 Pages


R H H



AA-CR-62-1878-9. #3 Boiler uptake showing connection to base of stack.

USS PENSACOLA (CA24)


Page 252 of 265 Pages



AA-CR-62-1878-10. #1 Boiler uptake showing division plate for #3 uptake. Photograph taken inside uptake from battle bars looking up and aft.

USS PENSACOLA (CA24)


Page 253 of 265 Pages



AA-CR-62-1878-10. #1 Boiler uptake showing division plate for #3 uptake. Photograph takes inside uptake from battle bars looking up and aft.

USS PENSACOLA (CA24)


Page 253 of 265 Pages



AA-CR-62-1878-8. #2 Boiler uptake above battle bars, forward side.

USS PENSACOLA (CA24)

Page 254 of 265 Pages



AA-CR-62-2168-5. Airplane crane, control shafting.

USS PENSACOLA (CA24)


Page 255 of 265 Pages



AA-CR-68-1762-9. Cable pulled through hangars due to structural failures.

USS PENSACOLA (CA24)

Page 256 of 265 Pages




AA-CR-68-1754-12. Cable ruptured by blown in door.

SECRET '

USS PENSACOLA (CA24)

Page 257 of 265 Pages



AA-CR-68-2179-1. Cable in way of structural damage.

USS PENSACOLA (CA24)


Page 258 of 265 Pages



AA-CR-68-1760-6. Cable pulled out of box due to ruptured bulkhead.

USS PENSACOLA (CA 24)

Page 259 of 265 Pages



AA-CR-68-1755-3. Various electrical wiring and appliances on ruptured bulkhead.

USS PENSACOLA (CA24)

Page 260 of 265 Pages



AB-CR-234-1692-6. Resistance unit for after warping winch, framework distorted to dishing of deck overhead.

USS PENSACOLA (CA24)

Page 261 of 265 Pages



AA-CR-68-1755-12. Motor controller for radio motor generator, panel is cracked due to distortion of supporting bulkhead.

USS PENSACOLA (CA24)


Page 262 of 265 Pages



AA-CR-68-1758-7. 36" searchlight blown off platform - wrecked.

Page 263 of 265 Pages

USS PENSACOLA (CA24)




AA-CR-98-1968-4. Cracked pedestal of 24" searchlight, starboard side of radar control room house top, frame 45.

USS PENSACOLA (CA24)

Page 264 of 265 Pages

CONFIDENTIAL

Confidence of Changed to Chority of Joint Chiefs of Staff (Action, 15 Apr 49)



CONFIDENTIAL



## Defense Special Weapons Agency 6801 Telegraph Road Alexandria, Virginia 22310-3398

10 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER ATTENTION: OMI/Mr. William Bush

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency (formerly Defense Nuclear Agency) Security Office has reviewed and declassified the following reports:

AD-366718	XRD-32-Volume 3
AD-366726~	XRD-12-Volume 2
AD-366703~	XRD-16-Volume 1
AD-366702-	XRD-14-Volume 2
AD-376819L~	XRD-17-Volume 2
AD-366704~	XRD-18
AD-367451	XRD-19-Volume 1
AD-366700 <b>5</b> -	XRD-20-Volume 2 AD-366705
AD-376028L-	XRD-4
AD-366694 -	XRD-1
AD-473912 -	XRD-193
AD-473891-	XRD-171
AD-473899~	XRD-163
AD-473887~	XRD-166 57-A 28-ANSO
AD-473888=	XRD-166  XRD-167  ST-A 28 TAN80  MADE TAIGET
AD-473889 -	XRD-168

Declassification of Reports SUBJECT:

> AD-B197749 XRD-174

> AD-473905~ XRD-182

AD-366719~ XRD-33 Volume 4

AD-366700 XRD-10

AD-366712-XRD-25 Volume 1

AD-376827L XRD-75

AD-366756 \* XRD-73

AD-366757~ XRD-74

AD-366755 \* XRD-72

AD-366754 XRD-71

AD-366710~ XRD-23 Volume 1

AD-366711-XRD-24 Volume 2

AD-366753~ XRD-70

AD-366749-XRD-66

AD-366701~ XRD-11

AD-366745 XRD-62.

All of the cited reports are now approved for public release; distribution statement "A" applies.

Andith Jarrett

Chief, Technical Resource Center

copy furn: FC/DSWA (DASIAC)

Conglitud L.w