UNCLASSIFIED

AD NUMBER

AD367480

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited


FROM:

Distribution: USGO: others to Director, Defense Atomic Support Agency, Washington, D. C. 20301.

AUTHORITY

DSWA ltr., 18 Apr 1997; DSWA ltr., 18 Apr 1997

THIS PAGE IS UNCLASSIFIED



BUREAU OF SHIPS GROUP TECHNICAL INSPECTION REPORT

Classification (Gancelles) (Changed to CONFIDENTIAL By Minority of Janet Chiefs of Staff Action of 11- April 1989
By Jahret (Benedict Date 2 4 4 Plain Date 3-441

U. S. GOVERNMENT AGENCIES MAY OBTAIN COPIES OF THIS REPORT DIRECTLY FROM DDC. OTHER QUALIFIED DDC USERS SHALL REQUEST THROUGH

> Director Defense Atomic Support Agency Washington, D. C. 20301


CONFIDENTIAL

Many May

APPROVED:

F.X. Forest, Captain, U.S.N.

December dictions



USS BUTTE (APA68)

Page 1 of 41 Pages

GROUP-3 Downgraded at 12 ear intervals;
Not automatically declaratified.

TABLE OF CONTENTS

	PAGE NO.
Ships Characteristics Sheet	. 3
Midship Section	. 4
Overall Summary of Damage	. 5
Hull Technical Inspection Report (Section I)	- 11
Machinery Technical Inspection Report (Section II)	- 17
Electrical Technical Inspection Report (Section III) -	25
Photographic Section (Section IV)	· 31
Ships Measurement Diagram (Appendix)	- 36
Commanding Officers Report (Appendix)	40

SECRET

USS BUTTE (APA68)

Page 2 of 41 Pages

U.S.S. BUTTE (APA 68)

SHIP CHARACTERISTICS

Building Yard: Consolidated Steel Corp.; Wilmington, California.

Commissioned: 21 November 1944.

HULL

Length Overall: 426 feet 0 inches.

Length on Waterline: 400 feet 0 inches.

Beam (extreme): £8 feet 0 inches.

Depth (molded to upper deck): 37 feet 0 inches.

Drafts at time of test: Fwd. 8 feet 8 inches.

Aft. 18 feet 4 inches.

Limiting displacement: 7,080 tons.

Displacement at time of test: 5,880 tons.

MAIN PROPULSION PLANT

Main Engines: Two sets of Westinghouse steam turbines, directly connected to Westinghouse main generators, Two main shaft motors.

Main Condensers: Two are installed in ship.

Boilers: Two Babcock and Wilcox boilers are installed in ship. 450 psi gauge - 750° F.

Propellers: Two are installed in ship.

Main Shafts: Two are installed in ship.

Ships Service Generators: Five are installed in ship.


Three - 250 KW. - 450 V. - A.C.

Two - 100 KW. - 120/240 V. - D.C.

SECRET

USS BUTTE (APA68)

Page 3 of 41 Pages



FRAME 78 LOOKING AFT

MIDSHIP

SECTION

TEST

В

SECRET

U.S.S. BUTTE (APA 68)

PAGE 4 OF 41

7783

TECHNICAL INSPECTION REPORT

OVERALL SUMMARY

- I. Target Condition After Test.
 - (a) Drafts after test; general areas of flooding, sources.

 There was no flooding, hence no change in drafts or list.
 - (b) Structural damage.

HULL

There is no apparent structural damage. A fragment pierced the upper deck at frame 150, starboard.

MACHINERY

No comment.

ELECTRICAL

No structural damage observed which affected electrical equipment.

(c) Other damage.

HULL

Not observed.

MACHINERY

The machinery of this vessel was not damaged by Test B, so far as can be determined by visual inspection.

SECRET

U.S.S. BUTTE (APA68)

Page 5 of 41 Pages

ELECTRICAL

No electrical damage was observed as a result of Test B.

- II. Forces Evidenced and Effects Noted.
 - (a) Heat.

HULL

None.

MACHINERY

No evidence.

ELECTRICAL

There was no evidence of heat.

(b) Fires and explosions.

HULL .

None.

MACHINERY

No evidence.

ELECTRICAL

There was no evidence of fires or explosions.

(c) Shock.

HULL

None.

SECRET

U.S.S. BUTTE (A PA 68)

Page 6 of 41 Pages

MACHINERY

Leads left in the bearings of one main turbo-generator and one ship's service generator during the test indicate very slight motion of the rotors. This indicates that the BUTTE received a slight underwater shock.

ELECTRICAL

There was no evidence of shock on electrical equipment.

(d) Pressure.

HULL

None.

MACHINERY

No evidence.

ELECTRICAL

There was no evidence of pressure on electrical equipment.

(e) Effects peculiar to the Atomic Bomb.

HULL

None.

MACHINERY

None, except radioactivity.

ELECTRICAL

There was no effects noted that are considered peculiar to the atomic bomb other than radioactivity.

WCRET

U.S.S. BUTTE (APA68)

Page 7 of 41 Pages

- III. Results of Test on Target.
 - (a) Effect on machinery, electrical, and ship control.

HULL

Not observed.

MACHINERY

None, as far as can be determined by visual inspection. No machinery except the emergency diesel generator and diesel fire pump were operated on this vessel after Test B, because of radiological hazard. Radioactivity was moderately high topside and was present in the machinery spaces in a few isolated spots, all near the shell of the ship, when she was inspected 15 days after the test.

ELECTRICAL

Although operability tests were not made, no evidence could be found that electrical equipment or ship control were affected by this test.

(b) Effect on gunnery and fire control.

HULL

Not observed.

MACHINERY

No comment.

ELECTRICAL

Gunnery and fire control were unaffected, electrically.

SECRET

U.S.S. BUTTE (APA68)

Page 8 of 41 Pages

(c) Effect on watertight integrity and stability. HULL None. MACHINERY No comment. ELECTRICAL None. (d) Effect on personnel and habitability. HULL None. MACHINERY None, except radioactivity. ELECTRICAL It is considered the only effect on personnel and habitability would have been that due to radioactivity. (e) Effect on fighting efficiency. HULL None.

MACHINERY

None, except radioactivity. It should be noted that the boats, stowed inboard of the davits, had much higher radioactivity than any

SECRET

U.S.S. BUTTE (APA68)

Page 9 of 41 Pages

other place on the ship. In view of the ship's mission as a transport, this might have a serious effect on her fighting efficiency. As all machinery was fully operable, she could presumably have steamed out of the contaminated area without being seriously affected by radioactivity in water around the ship. This, however, would not affect the radioactivity topside, as in the boats, which came from the water thrown upon the vessel by the explosion.

ELECTRICAL

There was no effect on the fighting efficiency of this vessel as a result of test B from electrical failures. It is considered that except for personnel casualties due to radioactivity, this vessel's fighting efficiency would have been unimpaired.

IV. General Summary.

HULL

No comment.

MACHINERY

The BUTTE was outside the effective range of physical damage from the explosion in Test B.

ELECTRICAL

The distance of this vessel from the blast was too great for electrical damage to occur.

HULL

None.

MACHINERY

None.

ELECTRICAL

None.

SECRET

U.S.S. BUTTE (APA68)

Page 10 of 41 Pages

TECHNICAL INSPECTION REPORT

SECTION I - HULL

GENERAL SUMMARY OF HULL DAMAGE

- I. Target Condition After Test.
 - (a) Drafts after test, general areas of flooding, sources.

 There was no flooding, hence no change in drafts or list.
 - (b) Structural damage.

There is no apparent structural damage. A fragment pierced the upper deck at frame 150, starboard.

(c) Other damage.

Not observed.

- II. Forces Evidenced and Effects Noted.
 - (a) Heat.

None.

(b) Fires and explosions.

None.

(c) Shock.

None.

(d) Pressure.

None.

SECRET

USS BUTTE (APA68)

Page 11 of 41 Pages

(e) Effects peculiar to the atomic bomb.

None.

III. Results of Test on Target.

- (a) Effect on machinery, electrical and ship control.

 Not observed.
- (b) Effect on gunnery and fire control.

 Not observed.
- (c) Effect on watertight integrity and stability.

 None.
- (d) Effect on personnel and habitability.

 None.
- (e) Effect on fighting efficiency.

 None.

IV. General Summary.

No comment.

V. Recommendations.

None.

VI. Instructions for Loading the Vessel Specified the Following:

Item	Loading
Fuel Oil	95%
Diesel Oil	95%
Ammunition	100%
Potable and reserve feed water	95%
Salt water ballast	None

SECRET

U. S. S. BUTTE (APA68)

Page 12 of 41 Pages

Details of the actual quantities of the various items aboard are included in Report 7, Stability Inspection Report, submitted by the ship's force in accordance with "Instructions to Target Vessels for Tests and Observations by Ship's Force" issued by the Director of Ships Material. This report is available for inspection in the Bureau of Ships Crossroads Files.

USS BUTTE (APA68)

SECRET

Page 13 of 41 Pages

DETAILED DESCRIPTION OF HULL DAMAGE

A. General Description of Hull Damage.

No significant damage. General views of the ship after Test B are on pages 32 and 33.

B. Superstructure.

No damage.

C. Turrets, guns and directors

No damage.

D. Torpedo mounts, depth charge gear.

Not applicable.

E. Weather deck.

Sixteen hatch boards from the forward cargo hatch and ten hatch boards from the after hatch were dislodged and fell through to the main deck. A fragment pierced the upper deck at frame 150, starboard (Photos. 1674-1 and 2; pages 34 and 35).

F. Exterior hull.

No damage.

G. Interior comp stments (above waterline).

No damage.

SECRET

USS BUTTE (APA68)

Page 14 of 41 Pages

H. Armor decks and miscellaneous armor.Not applicable.

Interior compartments (below waterline).No damage.

J. Underwater hull.

No damage.

K. Tanks.

No damage.

L. Flooding.

None.

M. Ventilation.

No damage.

N. Ship control.

No damage.

O. Fire control.

No damage.

P. Ammunition behavior.

No damage.

Q. Ammunition handling.

No damage.

SECRET

USS BUTTE (APA68)

Page 15 of 41 Pages

R. Strength.

No damage.

S. Miscellaneous.

No comment.

SECRET

USS BUTTE (APA68)

Page 16 of 41 Pages

TECHNICAL INSPECTION REPORT

SECTION II - MACHINERY

GENERAL SUMMARY OF MACHINEP" DAMAGE

- I. Target Condition after Test.
 - (a) Drafts after test; list; general areas of flooding, sources.

No data taken by machinery group.

(b) Structural damage.

No comment.

(c) Other damage.

The machinery of this vessel was not damaged by Test B, so far as can be determined by visual inspect in.

- II. Forces Evidenced and Effects Noted.
 - (a) Heat.

No evidence.

(b) Fires and explosions.

No evidence.

(c) Shock.

Leads left in the bearings of one main turbogenerator and one ship's service generator during the test indicate very slight motion of the rotors. This indicates that the BUTTE received a slight underwater shock.

SECRET

USS BUTTE (APA68)

Page 17 of 41 Pages

(d) Pressure.

No evidence.

(e) Effects apparently peculiar to the atom bomb.

None, except radioactivity.

III. Effects of Damage.

(a) Effect on machinery and ship control.

None, as far as can be determined by visual inspection. No machinery except the emergency diesel generator and diesel fire pump were operated on this vessel after Test B, because of radiological hazard. Radioactivity was moderately high topside and was present in the machinery spaces in a few isolated spots, all near the shell of the ship, when she was inspected 15 days after the test.

(b) Effect on gunnery and fire control.

No comment.

(c) Effect on water-tight integrity and stability.

No comment.

(d) Effect on personnel and habitability.

None, except radioactivity.

(e) Total effect on fighting efficiency.

None, except radioactivity. It should be noted that the boats, stowed inboard of the davits, had much higher radio-activity than any other place on the ship. In view of the ship's mission

SECRET

USS BUTTE (APA68)

Page 18 of 41 Pages

as a transport this might have a serious effect on her fighting efficiency. As all machinery was fully operable she could presumably have steamed out of the contaminated area without being seriously affected by radioactivity in water around the ship. This, however, would not affect the radioactivity topside, such as in the boats, which came from the water thrown upon the vessel by the explosion.

IV. General Summary.

The BUTTE was outside the effective range of physical damage from the explosion in Test B.

V. Preliminary Recommendations.

None.

USS BUTTE (APA68)

SECRET

Page 19 of 41 Pages

DETAILED DESCRIPTION OF MACHINERY DAMAGE

- A. General Description of Machinery Damage.
- 1. This vessel custained no apparent damage to machinery as a result of Test B.
 - (a) Overall Condition.

The overall condition of the machinery was unchanged by Test B.

(b) Areas of major damage.

There was no area of major damage.

(c) Primary cause of damage in each area of major damage.

Not Applicable.

(d) Effect of target test on overall operation of machinery plant.

The test had no apparent effect on the operation of the machinery plant.

NOTE: Because of radiological hazard no machinery on this vessel except the emergency diesel generator and diesel fire pump has been operated since Test B.

B. Boilers.

No apparent damage.

C. Blowers.

No apparent damage.

D. Fuel Oil Equipment.

No apparent damage.

SECRET

USS BUTTE (APA68)

Page 20 of 41 Pages

E. Boiler Feedwater Equipment.

No apparent damage.

F. Main Propulsion Machinery.

No apparent damage. Leads left in the bearings of the forward main turbo-generator indicate a slight vertical motion of the rotor during the test, with a possible maximum of .003 inch.

BEARING LEAD DATA

No. 1 MAIN GENERATOR - FORWARD BEARING

Forward lead	Before Test B	After Test B	Difference
Port Top Stb'd	.008 .013 .008	.008 .012 .007	.000 .001 .001
Center lead			
Port Top Stb'd	.007 .012 .007	.007 .011 . 007	.000 .001 .000
After lead			
Port Top Stb'd	.007 .014 .007	.006 .012 .006	.001 .002 .001
No. 1 MAIN GE	NERATOR - A	FTER BEARING	· T
Forward lead			
Port Top Stb'd	.008 .013 .007	.007 .010 .008	.001 .003 + .001
SECRET		USS BUTT	E (APA68)

Page 21 of 41 Pages

G. Reduction Gears.

Not applicable to this vessel.

H. Shafting and Bearings

No apparent damage.

I. Lubrication System.

No apparent damage.

J. Condensers and Air Ejectors.

No apparent damage.

K. Pumps.

No apparent damage.

L. Auxiliary Generators (Turbine and Gears).

No apparent damage. Leads left in the bearings of No. 1 ship's service generator indicate the possibility of very slight motion of the rotor (not over .001 inch) during the test.

BEARING LEAD DATA No. 1 SHIP'S SERVICE GENERATOR - BEARING BETWEEN TURBINE AND REDUCTION GEAR

Forward lead	Before Test B	After Test B	Difference
Port Top	.011 .012	.010 .011	.001 .001
Stb'd	.011	.010	.001
After lead			
Port	.010	.009	.001
Top Stb'd	.011 .010	.010 .009	.001 .001
SECRET		USS BUT	TE (APA68)

Page 22 of 41 Pages

M. Propellers.

Not inspected. There is no reason to believe that they were damaged.

N. Distilling Plant.

No apparent damage.

O. Refrigeration Plant.

No apparent damage.

P. Winches, Windlasses, and Capstans.

No apparent damage.

Q. Steering Engine.

No apparent damage.

R. Elevators, Ammunition Hoists, Etc..

No apparent damage.

S. Ventilation (Machinery).

No apparent damage.

T. Compressed Air Plant.

No apparent damage. .

- U. Diesels (Generators and Boats).
- 1. The diesel generator and the diesel fire pumps are undamaged. They were operated under service conditions after Test B.

SECRET

USS BUTTE (APA68)

Page 23 of 41 Pages

- 2. Boats stored aboard during the test are apparently undamaged mechanically, but have fairly high radioactivity. The highest radioactivity of any locality on this vessel is in these boats.
- V. Piping Systems.

No apparent damage.

W. Miscellaneous.

No apparent damage.

SECRET

USS BUTTE (APA68)

Page 24 of 41 Pages

TECHNICAL INSPECTION REPORT

SECTION III - ELECTRICAL

GENERAL SUMMARY OF ELECTRICAL DAMAGE

- I. Target Condition After Test.
- (a) Drafts after test; list; general areas of flooding, sources.

 Drafts or list were not observed. There was no flooding.
 - (b) Structural damage.

No structural damage observed which affected electrical equipment.

(c) Other damage.

No electrical damage was observed as a result of Test B.

- II. Fo ces Evidenced and Effects Noted.
 - (a) Heat.

There was no evidence of heat.

(b) Fires and explosions.

There was no evidence of fires or explosions.

(c) Shock.

There was no evidence of shock on electrical equipment.

SECRET

USS BUTTE (APA68)

Page 25 of 41 Pages

(d) Pressure.

There was no evidence of pressure on electrical equipment.

(e) Any effects apparently peculiar to the atom bomb.

There was no effects noted that are considered peculiar to the atomic bomb other than radioactivity.

III. Effects of Damage.

(a) Effect on propulsion and ship control.

Although operability tests were not made, no evidence could be found that electrical equipment or ship control were affected by this test.

(b) Effect on gunnery and fire control.

Gunnery and fire control were unaffected, electrically.

(c) Effect on water-tight integrity and stability.

None.

(d) Effect on personnel and habitability.

It is considered the only effect on personnel and habitability would have been that due to radioactivity.

(e) Total effect on fighting efficiency.

There was no effect on the fighting efficiency of this vessel as a result of Test B from electrical failures. It is considered that except for personnel casualties due to radioactivity, this vessel's fighting efficiency would have been unimpaired.

SECRET

USS BUTTE (APA68)

Page 26 of 41 Pages

IV. General Summary of Observers' Impressions and Conclusions.

The distance of this vessel from the blast was too great for electrical damage to occur.

V. Any Preliminary General or Specific Recommendations of the Inspecting Group.

None.

SECRET

USS BUTTE (APA68)

Page 27 of 41 Pages

DETAILED DESCRIPTION OF ELECTRICAL DAMAGE

- A, General Description of Electrical Damage.
 - (a) Overall condition.

This vessel received no damage to electrical equipment as a result of Test B.

(b) Areas of major damage.

None.

(c) Primary causes of damage in each area of major damage.

There was no electrical damage.

(d) Effect of target test on overall operation of electric plant.

Although operability tests were not conducted, the overall operation of the electric plant was apparently unaffected by this test.

(e) Types of equipment most affected.

None.

B. Electric Propulsion Rotating Equipment.

No damage.

C. Electric Propulsion Control Equipment.

No damage.

D. Generators - Ships Service.

No damage.

SECRET

USS BUTTE (APA68)

Page 28 of 41 Pages

E. Generators - Emergency.

No damage.

F. Switchboards, Distribution and Transfer Panels.

No damage.

G. Wiring, Wiring Equipment and Wireways.

No damage.

H. Transformers.

No damage.

I. Submarine Propelling Batteries.

Not Applicable.

J. Portable Batteries.

No damage.

K. Motors, Motor Generator Sets and Motor Controllers.

No damage.

L. Lighting Equipment.

No damage.

M. Searchlights.

No damage.

N. Degaussing Equipment.

No damage.

SECRET

USS BUTTE (APA68)

Page 29 of 41 Pages

O. Gyro Compass Equipment.

No damage.

P. Sound Powered Telephones.

No damage.

Q. Ship's Service Telephones.

Not Applicable.

R. Announcing Systems.

No damage.

S. Telegraphs.

No damage.

T. Indicating Systems.

No damage.

U. I.C. and A.C.O. Switchboards.

No damage.

V. F.C. Switchboard.

No damage.

W. Miscellaneous.

No comment.

SECRET

USS BUTTE (APA68)

Page 30 of 41 Pages

SECTION IV


PHOTOGRAPHS

TEST BAKER

SECRET

USS BUTTE (APA68)

Page 31 of 41 Pages




AB-CR-227-283-145. Starboard bow after Test B.

Page 32 of 41 Pages

USS BUTTE (APA68)

7783




AB-CR-277-283-149. Port quarter after Test B.

Page 33 of 41 Pages

USS BUTTE (APA68)

7783



AB-CR-81-1674-1. Fragment on upper deck and hole in deck.

Page 34 of 41 Pages

USS BUTTE (APA68)



AB-CR-81-1674-2. Fragment hole in upper deck.

Page 35 of 41 Pages

USS BUTTE (APA68)

7783

APPENDIX

SHIPS MEASUREMENT DIAGRAM

SECRET

USS BUTTE (APA68)

Page 36 of 41 Pages

Appendix

Ship Measurement Data

Deflection scratch gages were installed in the after machinery space and beneath the upper deck to record relative movement of structural members. Gage locations and headings are recorded on pages 38 and 39.

USS BUTTE (APA68)

SECRET

Page 37 of 41 Pages

			ECK DE	ECK DEFLECTION	1	GAGES	
SHIP		BUTTE (APAGE)	2				TEST B
	LOCATION	2	MAXIMUM	MAXIMUM	PERMANENT	11 3	DEWADYS
FR. NO.	DECK		COMP.	EXP.	DISTANCE	EXP. / COMP.	SAFATA S
22 1/2		Center-	None	None	None	None	None
48		Stp41	0-0-1/2	0-0-1/16	-	-	-
<u> </u>	÷	Port 91711	None	None	-	-	-
ي ش	=	Stbd. 2017!!	0-0-9/16 0-0-1/4	0-0-1/4	-	-	-
48	:	Port 20'2''	0-0-9/16 0-0-3/16	0-0-3/16	-		-
129	Ξ	Stbd 14'2''	0-0-3/32	None	-	=	-
		`					-

uss butte (APA-68)

		۵		EFLECTI	ECK DEFLECTION GAGES	3ES	
SHIP	U.S.S. B	BUTTE (APA-68	3)	·			TEST B
	LOCATION	Z	MAXIMUM	MAXIMUM	PERMANENT	SET	
FR. NO.	DECK	DIST. OFF &	COMP.	EXP.	DISTANCE	EXP. / COMP.	REMARKS
66	After Eng Bm.	Port	None	None	None	None	None
ю	-	Athwart-	1 4	11	8 8	1.1	11
103	:	Stbd.	8 1	11		1.1	1.1
104	•	Center- Line	11	11	11	1 1	• •
		·				ı	

USS BUTTE (APA-68)

APPENDIX

COMMANDING OFFICERS REFORT

TEST BAKER

SECRET

USS BUTTE (APA68)

Page 40 of 41 Pages

COMMANDING OFFICERS REPORT

REPORT # 11

SECTION - I

There was no apparent damage to the USS BUTTE (APA-68) as a result of the BAKER Test other than radioactive contamination.

SECRET

USS BUTTE (APA-68)


Page 41 of 41 Pages

Classification (Canonical) (Changed to CONFIDENTIAL)

By Althority of Island Chiefe AF STAFE AFFIDE OF 13-APril 1749

By Althority Of Island Chiefe AF STAFE AFFIDE OF 13-APril 1749

By AFS WP



CONFIDENTIAL



Defense Special Weapons Agency 6801 Telegraph Road Alexandria, Virginia 22310-3398

TRC

18 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER ATTENTION: OMI/Mr. William Bush (Security)

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency has declassified the following reports:

✓AD-366588 	XRD-203-Section 12 ✓
AD-366589	XRD-200-Section 9
AD-366590 L	XRD-204-Section 13
AD-366591 ►	XRD-183
✓ AD-366586 ℃	XRD-201-Section 10
∠ AD-367487. 以	XRD-131-Volume 2-
✓AD-367516¥	XRD- \$ 143 ✓
✓AD-367493 ८	XRD-142 ►
AD-801410L ✔	XRD-138
AD-376831L 🗸	XRD-83
AD-366759 ►	XRD-80
✓AD-376830L ❖	XRD-79 ✓
✓AD-376828L ❤	XRD-76✓
∠ AD-367464. ¾	XRD-106 ✓
AD-801404L 🗸	XRD-105-Volume 1
✓AD-367459 🗴	XRD-100✓

Subject: Declassification of Reports

, 425, 555,	20014001110401011 01	
	✓ AD-367517 🔾	XRD-141 ✔
	AD-366762 ▶	XRD-84
	AD-366760 ✓	XRD-81
	AD-366761	XRD-82
	AD-367501 ✓	XRD-158-Volume 1
	AD-367507L 🗸	XRD-152-Volume 4
	✓ AD-367495 🔏	XRD-184~
	✓AD-367485 ¥	XRD-129 ≻
	AD-367484 💘	XRD-128 ✓
	✓ AD-367483 ⋌	XRD-127 ⊬
	✓AD-367482 ¥	XRD-126 ⊬
	AD-367488	XRD-132
	AD-367480 🗡	XRD-124~
	AD-801409L ✓	XRD-135
	AD-367490 ⊀	XRD-136 ℃
	AD-367492 🔨	XRD-137►
	AD-801411L 🗸	XRD-139
	AD-367518 🗶	XRD-140 ✓
	AD-367515 ✓	XRD-144
	AD-367514 ✔	XRD-145
	AD-367468 X	XRD-110-Volume 2 🗸
	AD-367513 √	XRD-146
	AD-367497 X	XRD-162

TRC

Subject: Declassification of Reports

AD-801406L ✓ XRD-114.

In addition, all of the cited reports are now approved for public release; distribution statement "A" now applies.

ARDITH JARRETT
Chief, Technical Resource Center