### UNCLASSIFIED

## AD NUMBER

AD367512

# **CLASSIFICATION CHANGES**

TO: unclassified

FROM: confidential

# **LIMITATION CHANGES**

#### TO:

Approved for public release, distribution unlimited


#### FROM:

Distribution: USGO: others to Director, Defense Atomic Support Agency, Washington, D. C. 20301.

# AUTHORITY

DSWA ltr., 18 Apr 1997; DSWA ltr., 18 Apr 1997

## THIS PAGE IS UNCLASSIFIED



# CONFIDENTIAL

# BUREAU OF SHIPS GROUP TECHNICAL INSPECTION REPORT

"This document contains information affecting the Matiema. Defence of the United States within the meaning of the Ballonage Laws, Title 18, U. S. C., Section 793 and 794. Pts transmission or the revelation of its contents in any manner to an unauthorzied person is prohibited by law."

U. S. GOVERNMENT AGENCIES MAY OBTAIN COPIES OF THIS REPORT DIRECTLY FROM DDC. OTHER QUALIFIED DDC USERS SHALL REQUEST THROUGH

Director
Defense Atomic Support Agency
Washington, D. C. 20301

APPROVED:

F.X. Forest, Captain, U.S.N.

SECRET

USS YOG 83


Page 1 of 24 Pages

CONFIDENTIAL

GROUP-3

Downgraded at 12 year interfals AN SSS

Not automatically declaration.



SECRET

USS YOG 83

Page 2 of 24 Pages

#### TECHNICAL INSPECTION REPORT

#### OVERALL SUMMARY

- I. Target Condition After Test.
  - (a) Drafts after test, general areas of flooding, sources.

There was no flooding, hence no change in drafts

or list.

(b) Structural damage.

HULL

No damage.

MACHINERY

No comment.

ELECTRICAL

Not observed.

(c) Other damage.

HULL

Not observed.

#### MACHINERY

Machinery was not inspected, as radioactivity after Test B limited the time personnel could remain aboard YOG 83 to less than 15 minutes per day. A very cursory examination disclosed response to machinery. She was sunk by demolition charge atter Test B.

SECRET

USS YOG 83

Page 3 of 24 Pages

#### ELECTRICAL

Due to the intense radioactivity this vessel was not inspected by the Electrical Group. The Hull Group inspection report indicates no apparent structural damage. The lack of apparent structural damage indicates that electrically the vessel is in essentially the same condition as before Test B.

- II. Forces evidenced and effects noted.
  - (a) Heat.

HULL

None.

MACHINERY

No evidence.

ELECTRICAL

Evidence of heat, if any, was not observed as inspection was not made.

(b) Fires and Explosions.

HULL

None.

MACHINERY

No evidence.

ELECTRICAL

Not observed.

(c) Shock.

SECRET

USS YOG83

Page 4 of 24 Pages

#### HULL

None.

#### MACHINERY

No evidence from very cursory inspection. See I (c) above.

#### ELECTRICAL

Evidence of shock, if any, was not observed as no inspection was made by this group.

(d) Pressure.

HUI L

None.

#### MACHINERY

No evidence from very cursory inspection. See I (c) above.

#### ELECTRICAL

Evidence of pressure, if any existed, was not noted as no inspection was made.

(e) Effects peculiar to the Atom Bomb.

HULL

None.

MACHINERY

High radioactivity.

SECRET

USS YOG83

Page 5 of 24 Pages

#### ELECTRICAL .

It being impractical to inspect this vessel after Test B the only known effects apparently peculiar to the Atom bomb was the intense radioactivity.

III. Besults of Test on Target.

(a) Effect on machinery, electrical, and ship control.

HULL

Not observed.

#### MACHINERY

Unknown. See I (c) above. Believed to have been none except for radioactivity.

ELECTRICAL

Not known.

(b) Effect on gunnery and fire control.

HULL

Not observed.

MACHINERY

No commont.

ELECTRICAL

Not known.

(c) Effect on watertight integrity and stability.

HULL

None,

SECRET

USS YOG83

Page 6 of 24 Pages

#### MACHINERY

No comment.

#### ELECTRICAL

Not known.

(d) Effect on personnel and habitability.

HULL

None, except for radioactivity which rendered the barge uninhabitable.

#### MACHINERY.

The craft was made uninhabitable by radioactivity. All personnel would probably have been casualties either from direct effects of the explosion or from radioactivity.

#### ELECTRICAL

The only known effect on personnel and habitability would have been that due to the intense radioactivity. It is considered this would have been great.

(e) Effect on fighting efficiency.

HULL

Efficiency of the barge was unaffected structurally or mechanically.

MACHINERY

High radioactivity destroyed the usefulness of the

craft.

ELECTRICAL

Not known.

SECRET

USS YOG83

Page 7 of 24 Pages

IV. General Summary of Observer's Impressions and Conclusions.

HULL

No comment.

MACHINERY

YOG 83 is an outstanding example of the seriousness of the radiological aspects of this form of attack.

ELECTRICAL

None.

V. Preliminary General or Specific Recommendations of Inspection Group.

HULL

None.

MACHINERY

None.

ELECTRICAL

None.

SECRET

USS YOG83

Page 8 of 24 Pages

#### TECHNICAL INSPECTION REPORT

#### SECTION I - HULL

#### GENERAL SUMMARY OF HULL DAMAGE

- I. Target Condition After Test.
  - (a) Drafts after test; lists; general areas of flooding, sources.

There was no flooding, hence no change in drafts or

list.

(b) Structural damage.

No damage.

(c) Other damage.

Not observed.

- II. Forces Evidenced and Effects Noted.
  - (a) Heat.

None.

(b) Fires and explosions.

None.

(c) Shock.

None.

(d) Pressure.

None.

SECRET

U.S.S. YOG83

Page 9 of 24 Pages

(e) Effects peculiar to the Atomic Bomb.

None.

- III. Results of Test on Target.
  - (a) Effect on machinery, electrical, and ship control.

    Not observed.
  - (b) Effect on gunnery and fire control.Not observed.
  - (c) Effect on watertight integrity and stability.

    None.
- (d) Effect on personnel and habitability.

  None, except for radioactivity which rendered the barge uninhabitable.
- (e) Effect on fighting efficiency.

  Efficiency of the barge was unaffected structurally or mechanically.
- IV. General Summary of Observers Impressions and Conclusions.

  No comment.
- V. Preliminary Recommendation.

  None.

SECRET

U. S. S. YOG83

Page 10 of 24 Pages

#### VI. Instructions for Loading the Vessel Specified the Following:

#### ITEM

# Fuel oil. Diesel oil. Ammunition. Potable and reserve feed water. Salt water ballast.

#### LOADING

No special adjustment required. Except that no inflammable cargo shall be carried in tanks. Tanks may be ballasted with salt water to adjust trim, immersion and list.

Details of the actual quantities of the various items aboard are included in report 7, Stability Inspection Report, submitted by the ship's force in accordance with "Instructions to Target Vessels for Test and Observations by Ship's Force" issued by the Director of Ships Material. This report is available for inspection in the Bureau of Ships Crossroads Files.

SECRET

U. S. S. YOG83

Page 11 of 24 Pages

# DETAILED DESCRIPTION OF HULL DAMAGE

A. General Description of Hull Damage.

No damage.

B. Superstructure.

No damage.

C. Turrets, Guns and Directors.

No damage.

D. Torpedo Mounts, Depth Charge Gear.

Not applicable.

E. Weather Deck.

No damage.

F. Exterior Hull.

No damage.

G. Interior Compartments (Above W.L.).

No damage.

H. Armor Decks and Miscellaneous Armor.

Not applicable.

I. Interior Compartments (Below W.L.).

No damage.

SECRET

U. S. S. YOG83

Page 12 of 24 Pages

J. Underwater Hull.

No damage.

K. Tanks.

No damage.

L. Flooding.

None.

M. Ventilation.

No damage.

N. Ship Control.

No damage.

O. Fire Control.

No damage.

P. Ammunition Behavior.

No damage.

Q. Ammunition Handling.

Not applicable.

R. Strength.

No damage.

S. Miscellaneous.

No comment.

SECRET

U. S. S. YOG83

Page 13 of 24 Pages

# TECHNICAL INSPECTION REPORT

#### SECTION II - MACHINERY

#### GENERAL SUMMARY OF MACHINERY DAMAGE

- I. Target Condition After Test.
  - (a) Drafts after test; list; general areas of flooding, sources.

No comment.

(b) Structural damage.

No comment.

(c) Other damage.

Machinery was not inspected, as radioactivity after Test "B" limited the time personnel could remain aboard YOG 83 to less than 15 minutes per day. A very cursory examination disclosed no apparent damage to machinery. She was sunk by demolition charge after Test "B".

- II. Forces Evidenced and Effects Noted.
  - (a) Heat.

No evidence.

(b) Fires and explosions.

No evidence.

(c) Shock.

No evidence from very cursory inspection. See I (c)

above.

SECRET

U. S. S. YOG 83

Page 14 of 24 Pages

(d) Pressure.

No evidence from very cursory inspection. See I (c) above.

(e) Any effects apparently peculiar to the Atom Bomb.

High radioactivity.

#### III. Effects of Damage.

(a) Effect on machinery and ship control.

Unknown. See I (c) above. Believed to have been none except for radioactivity.

(b) Effect on gunnery and fire control.

No comment.

(c) Effect on water-tight integrity and stability.

No comment.

(d) Effect on personnel and habitability.

The craft was made uninhabitable by radioactivity. All personnel would probably have been casualties either from direct effects of the explosion or from radioactivity.

(e) Total effect on fighting efficiency.

High radioactivity destroyed the usefulness of the craft.

77. General Summary (Not over 6-8 lines) of Observers' Impressions and Conclusions.

YOG 83 is an outstanding example of the seriousness of the radiological aspects of this form of attack.

SECRET

U. S. S. YOG 83

Page 15 of 24 Pages

v.	Any Preliminary	General	or	Specific	Recommendations	œf	thė
	Inspecting Group.			_			

None.

SECRET

U. S. S. YOG 83

Page 16 of 24 Pages

# DETAILED DESCRIPTION OF MACHINERY DAMAGE

NOTE: The only items discussed below are those where damage occurred. All items omitted either received no damage or are not applicable.

There was no damage.

SECRET

U. S. S. YOG 83

Page 17 of 24 Pages

#### TECHNICAL INSPECTION REPORT

#### SECTION III - ELECTRICAL

#### GENERAL SUMMARY OF ELECTRICAL DAMAGE

- L Target Condition After Test.
  - (a) Drafts after test; list; general areas of flooding, sources.

Drafts or list were not observed.

(b) Structural damage.

Not observed.

(c) Other damage.

Due to the intense radioactivity this vessel was not inspected by the Electrical Group. The Hull Group inspection report indicates no apparent structural damage. The lack of apparent structural damage indicates that electrically the vessel is in essentially the same condition as before Test "B".

- II. Forces Evidenced and Effects Noted.
  - (a) Heat.

Evidence of heat, if any, was not observed as inspection was not made.

(b) Fires and explosions.

Not observed.

(c) Shock.

Evidence of shock, if any, was not observed as no inspection was made by this group.

SECRET

U.S.S.YOG 83

Page 18 of 24 Pages

(d, Pressure.

Evidence of pressure, if any existed, was not noted as no inspection was made.

(e) Effects apparently peculiar to the Atomic Bomb.

It being inpractical to inspect this vessel after Test "B" the only known effects apparently peculiar to the Atom Bomb was the intense radioactivity.

#### III. Effects of Damage.

(a) Effect on electrical equipment and ship control.

Not known.

(b) Effect on gunnery and fire control.

Not known.

(c) Effect on water-tight integrity and stability.

Not known.

(d) Effect on personnel and habitability.

The only known effect on personnel and habitability would have been that due to the intense radioactivity. It is considered this would have been great.

(e) Total effect on fighting efficiency.

Not known.

IV. General Summary of Observer's Impressions and Conclusions.

None.

SECRET

U.S.S. YOG 83

Page 19 of 24 Pages

V. Any Preliminary, General or Specific Recommendations of the Inspection Group.

None.

SECRET

U. S. S. YOG 83

Page 20 of 24 Pages

#### DETAILED DESCRIPTION OF ELECTRICAL DAMAGE

NOTE: The only items discussed below are those where damage occurred. All items cmitted either received no damage or are not applicable.

There was no inspection made.

SECRET

U. S. S. YOG 83

Page 21 of 24 Pages

SECTION IV

PHOTOGRAPHS

TEST BAKER

SECRET

USS YOG 83

Page 22 of 24 Pages



AB-CR-227-283-26. View from starboard bow after Test B.

SECRET

Page 23 of 24 Pages

YOG-83

9191



Page 24 of 24 Pages CONFIDENTIAL

YOG-8,

9191



#### Defense Special Weapons Agency 6801 Telegraph Road Alexandria, Virginia 22310-3398

TRC

18 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER ATTENTION: OMI/Mr. William Bush (Security)

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency has declassified the following reports:

✓AD-366588 <b>4</b>	XRD-203-Section 12
× —— AD-366589	XRD-200-Section 9
AD-366590 L	XRD-204-Section 13
AD-366591	XRD-183 /
✓ <b>✓</b> AD-366586 <b>∢</b>	XRD-201-Section 10
V AD-367487. K	XRD-131-Volume 2-
✓AD-367516 <b>屮</b>	XRD- <b>₹</b> 143 ✓
VAD-367493 <b>U</b>	XRD-142►
AD-801410L ✔	XRD-138✓
AD-376831L 🗸	XRD-83✓
AD-366759	XRD-80 ✓
√ <b>∠</b> AD-376830L <b>↓</b>	XRD-79 ✓
/ AD-376828L <b>\</b>	XRD-76/
✓VAD-367464· <b>X</b>	XRD-106 ✓
AD-801404L	XRD-105-Volume 1
√AD-367459 <b>X</b>	XRD-100✓

Subject: Declassification of Reports

```
✓AD-367491 💢
               XRD-134-Volume 2 ~
✓AD-367479 H
               XRD-123 ✓
✓ AD-367478以
               XRD-122 ✓
✓AD-367481 💢
               XRD-125 ✓
 AD-367500 V
               XRD-159-Volume
✓ AD-367499 → XRD-160-Volume 3 ►
AD-367512
               XRD-147 ✓
 AD-367511
               XRD-148 ✓
✓ AD-367465 🗱
               XRD-107 ►
 AD-366733 V
               XRD-43 ✓
✓AD-367477 🗡
               XRD-121 ✓
✓AD-367476 ►
               XRD-120 ℃
✓AD-367467 💢
               XRD-109-Volume 1
✓AD-367475 💢
              XRD-119 ✓
✓AD-367474 🔏
               XRD-118
✓AD-367473 🔏
               XRD-117 ✓
✓AD-367472 \
               XRD-116 ✓
✓AD-367471 🔏
               XRD-115 ►
✓ AD-367466 🖟
               XRD-108 ✓
 AD-801405L V
               XRD-113 ✓
✓ AD-367470 💸
               XRD-112 /
/AD-367469 X
               XRD-111 ✓
```

TRC

Subject: Declassification of Reports

AD-801406L Y XRD-114.

In addition, all of the cited reports are now approved for public release; distribution statement "A" now applies.

Andith Sanets
ARDITH JARRETT

Chief, Technical Resource Center