


# LOGISTICS MANAGEMENT REPORT FOR U.S. NAVY PROPELLANT-ACTUATED DEVICES (PAD)







Form Approved

QMB No. 0704-0188

Approved for public release; distribution is unlimited.

REPORT DOCUMENTATION PAGE

Approved for public release; distribution is unlimited.

#### Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestion for reducing this burden. to Washington Headquarters Services, Directorate for Information Operations and Reports. 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction project (0704-0188), Washington, DC 20503 1. AGENCY USE ONLY (Leave 2. REPORT DATE 3. REPORT TYPE AND DATES COVERED Blank) Final Report 31 January 2003 5. FUNDING NUMBERS 4. TITLE AND SUBTITLE LOGISTICS MANAGEMENT REPORT FOR U.S. NAVY PROPELLANT(PAD) **ACTUATED DEVICES** 6. AUTHOR(S) M.P. Audiey 7. PERFORMING ORGANIZATIONS ME(S) AND ADDRESS(ES) PERFORMING ORGANIZATION REPORT NUMBER Indian Head Division **Naval Surface Warfare** IHSP 03-486 Center Indian Head, MD 20640-5035 9. SPONSORING/MONITORING AGENC NAME(S) AND ADDRESS(ES) 10. SPONSORING/MONITORING AGENCY REPORT NUMBER **Program** Executive Aviation Officer Strike Weapons and Unmanned Washington, DC 20361-1010 11. SUPPLEMENTARY NOTES 12a. DISTRIBUTION/AVAILABILITY STATEMENT 12b. DISTRIBUTION CODE

| 13. | ABSTRACT (Maximum 200 words)  | stocks,    | to    | detail   | the   |
|-----|---|------------|-------|----------|-------|
|     | This report is prepared to summarize the status of propellant-actuated device | gistics ma | tters | pertaini | ng to |
|     | (PAD) support given or required for aircraft escape system changes, and to    | S. Navy a  | refe  | rence so | urce  |
|     | highlight other PAD logistics support and acquisition management. The subject | r general  |       |          |       |
|     | report also serves as PAD information.  |            |       |          |       |

| 1 | 14. SUBJECT TERMS                        | 15. NUMBER OF PAGES 54                   |   |                            |
|---|--|--|---|----------------------------|
|   | Propellant-actuated device               |  |   |                            |
|   | Tropellant actuated device               | 16. PRICE CODE                           |   |                            |
|   |  |  |   |                            |
| 1 | 17. SECURITY CLASSIFICATION<br>OF REPORT | 18. SECURITY CLASSIFICATION OF THIS PAGE | 19. SECURITY CLASSIFICATION OF ABSTRACT | 20. LIMITATION OF ABSTRACT |
|   | UNCLASSIFIED                             | UNCLASSIFIED                             | UNCLASSIFIED                            | SAR                        |

NSN/640-01280-5500

Standard Form 298 (Rev. 2-89)

Prescribed by ANSI Std. 239-18 298-102

**IHSP** 

This page intentionally left blank.

#### **FOREWORD**

The Indian Head Division, Naval Surface Warfare Center, Indian Head, MD, is the cognizant field activity (CFA) for U.S. Navy propellant-actuated devices (PAD). The PAD Engineering Division (Code 5 10) at Indian Head is delegated the responsibility of maintenance engineering for PAD devices by PEO (W) PMA-201. The logistics management report is prepared by Mike Audley (Code 51 1 OH) to summarize the status of Navy PAD stocks, detail the logistics support given or required for aircraft escape system changes, and highlight other matters pertaining to Navy PAD logistics support and acquisition management. The subject report also serves as a reference source for general Navy PAD information.

Anyone desiring to make inquiries about the material covered herein or to receive subsequent editions of this semiannual report should contact Mike Audley (Code 51 1 OH), DSN 354-2105 or commercial line 301-744-2105.

Diane L. Sabal

Diane L. Satol

Manager, PAD Branch

Approved and released by: e—P/L.3

C.A. Pfleegor

Director, AEPS/PAD Engineering Division

IHsp

iv

# CONTENTS

|                             | age            |
|-----------------------------|----------------|
| tics System Notes           | <b>ji</b><br>1 |
|                             | 2              |
| Propellant-Actuated Devices | 3              |
| TA-4J Aireraft              | 5              |
| A V/TAV-8B Aircraft         | 7              |
| EA-6B Aireraft              | . 11           |
| F-5E/F-T-38A Aircraft       | . 14           |
| F-14A/B and NF-14A Aircraft | . 14           |
| F-14D and NF-14D Aircraft   | . 17           |
| FA-18A/B/C/DAircraft        | . 20           |
| FA-18C/D/Pe/FAircraft       | . 25           |
| OV-IOA Aircraft             | . 30           |
| QF-4N/S Series Aircraft     | . 31           |
| S-3B Aircraft               | . 32           |
| T-2C Series Aircraft        | . 38           |
| T-45A/C Aireraft            | . 39           |
|                             |                |
| reword                      |                |
| egrated Logistics System    |                |
| D Inventory                 |                |

# 03-486 PAD Summary

# Tables

| 1.   | Service     | Life    | Li      | sting |                | . 42 |
|------|-------------|---------|---------|-------|----------------|------|
|      |             |         | 42      | Il.   | mary           | . 44 |
| Prop | ellant-Act  | uated   | De      | vices | Lot Number     | . 46 |
| Sum  | ımary       | 44      |         |       | Lot i tuliloci | . 72 |
| 111. | Total Insta | alled A | Assets  | S     |                |      |
| IV.  | Total Rep   | orted l | Install | ed By |                |      |

This page intentionally left blank.

vi

#### INTEGRATED LOGISTICS SYSTEM NOTES

#### NAVAIR 11-100-1.1-CD Electronic Technical Manual

Basic Issued Dtd 1 February 2001, IRAC 10 Dtd 23 June 00, IRAC 12 Dtd 6 October 00, IRAC 13 Dtd 21 November 2000, IRAC 14 Dtd 20 December 2000, IRAC 15 Dtd 25 June 2001, IRAC 16 Dtd 24 July 2001, IRAC 17 Dtd 1 August 2001, IRAC 18 Dtd 1 1 September 2001, IRAC 19 Dtd 17 January 2002, IRAC 20 Dtd 29 January 2002, IRAC 21 Dtd 7 March 2002, IRAC 22 Dtd 28 June 2002, IRAC 23 Dtd 26 July 2002, IRAC 24 Dtd 18 September 2002, IRAC 25 Dtd 08 October 2002, IRAC 26 Dtd 29 October 2002.

#### **Production Lot Designation Change**

All assets now entering the stock system will have ammunition lot numbers per MIL-STD- 1 168. An illustration is given below:

IHM01A002-OO 1

#### abcde

a Manufacturer's identification symbol b Two-digit numeric code identifying the year of production of the oldest propellant batch used in the propellant actuated device (PAD) lot c Single alpha code signifying the month of production of the oldest propellant batch used in the PAD lot d Lot interfix number (controlled by Indian Head Division, Naval Surface Warfare Center, Indian Head, MD 20640-5035) e Lot sequence number.

# **PAD Spares Policy**

Because PAD assets are limited and are not allocated items, refer to NAVSURFWARCENDIV Indian Head Naval Message 121339Z October 2000 for the Management Policy on CAD/PAD.

#### Corrosion

The service life for PAD devices is determined by an extensive type-life and ordnance evaluation test program. Corrosion is considered to be a maintenance discrepancy reportable via a safety report or quality deficiency report in accordance with OPNAVINST 8600.2. Corrosion is not a criterion for reducing the service life of an entire lot or specific type of PAD device, but should be reported on a case-by-case basis.

#### PAD INVENTORY

The following section contains information concerning the Navy PAD devices utilized in U.S. Navy and Marine Corps aircraft. Each aircraft is reported separately. The PAD devices are listed under their respective ejection seat configurations. In general, each PAD device is identified as to national stock number, Department of Defense identification code/Navy ammunition logistics code (DODIC[NALC), service life, and quantity per aircraft. The serviceable inventory is reported, with both production lot quantities and quantities per lot installed in aircraft. Quantities installed in aircraft are from the CAD/PAD Traceability System (CATS). These inventories of installed assets conducted in cooperation with type commanders and aircraft manufacturers are compiled at Indian Head. Lot quantity figures indicate the amount delivered by a contractor for Navy use/Navy stock.

The following color code applies to each lot table per aircraft type:

Red = Lot expiring in the next 6 months.

Dark Red = Lot that has expired in last 6 months.

Blue = Lot is on a world-wide service life extension.

Green = A new mod change and affected lots from that change

Violet = The service life of this unit has been increased since we last published this report.

# Propellant-Actuated Devices

[As of 31 January 2003]

|   |  | [A   | 15 OI 51 Janu                                 | ary 2003]                  |                     |                         |  |
|---|--|--|---|----------------------------|---------------------|-------------------------|--|
|   | PAD device                                 | NSN  | DODIC   | Series<br>aircraft         | No. per<br>aircraft | Service life<br>(mo/yr) |  |
| -   |  |  | Rocket Cat                                    | tapults                    | IL.                 |                         |  |
| MK 12 Mod 1<br>IOA2120/10 Mk<br>4J2156/13 |  | <sup>1</sup> 1377-00-276-<br>16 Mod 1 <sup>2</sup> 1377-             | 2364MC770V-<br>9324MD72TA-                    |                            |                     |                         |  |
|   | Mk 18 Mod                                  | 0¹1377-00-250-   |   | S-3B4156/13                |                     |                         |  |
|   | 0206M941TQC212<br>7777MS15F_5E1120         |  | ı   | 7A121377-00-               | 125-                | l                       |  |
|   | _  |  |   | F_5F2120/10                | T-38A2120/1         | 0                       |  |
|   |  | ,  | Man/Seat Se                                   | parators                   |                     |                         |  |
|   | Mk82 2 odi 1377-01- dO 1377-00- 2          | ModO 1377-00-<br>412-<br>201-  | S-3B2192/<br>6530MU76<br>S-3B2108/<br>9554MC5 | TA-4JI108/9 79 S-3B2192/16 |                     |                         |  |
|   | Mk 90 Mod                                  | 1377-01412-6462MU7   | 75<br>Yaw Thru                                |                            | 2108/9              |                         |  |
|   |  | ı  |   | sters                      |                     | ı                       |  |
|   | Mk 83 Mod<br>Mk 85                         | 0 <sup>2</sup> • <sup>3</sup> 1377-00-119-2031<br>Mod1377-00-119Q045 | M929S-<br>M932S-                              | 3B284/7<br>3B284/7         |                     |                         |  |
|   |  |  | Vernie  | er                         |                     |                         |  |
|   | Mk 84 Mod 2 <sup>2</sup> • <sup>4</sup>    | 1377-01-199-8315   | MF57<br>Seatback F                            | l s-3B<br>Rocket           | 4                   | 156/13                  |  |
| Mk 79 Mo                                  | d 1/2 <sup>1</sup> • <sup>4</sup> 1377-01- | 069-1787<br>TAV-8B4132/11  | MF21  | AV-8B2132/11               |                     |                         |  |
|   |  | V  | WORD/Drogue                                   | Assembly                   |                     |                         |  |
| J   | Mk 113 Mod 0/1 <sup>2</sup> • <sup>4</sup> | 1377-01-149-   |   | 3516MG67AV-8B<br>TAV-8B    | 196/8<br>296/8      |                         |  |
|   |  |  | Catapult Ca                                   | rtridge                    |                     |                         |  |
|   | Mk 205 Mod                                 | <b>1/2</b> <sup>4</sup> 1377-01-138-38                               | 329XW36                                       | AV-8B9                     | 96/8                |                         |  |
|   | '  |  |   | TAV-8B                     | 296/8               |                         |  |
|   |  | U  | Inderseat Roc                                 | ket Motor                  |                     |                         |  |

| Mk 74 Mod    | 0 <sup>5</sup> 1377-00-181- | 9532M572NF-14AJB1240/20                 |         |      |
|--------------|-----------------------------|---|---------|------|
| Mk 74 Mod 1  | <sup>1</sup> 1377-01-246-   | 5282M572 F_14AjB, NF-                   |         |      |
| 14A/B1240/20 | Mk 75 Mod                   | 0 <sup>5</sup> 1377-00-181-9533M573 F_  | 14AJB , | N F- |
| 14A/B240/20  | Mk 75 Mod 1                 | <sup>1</sup> 1377-01-246-5283M573NF-    |         |      |
| 14A/B240/20  | Mk 86 Mod                   | 0 <sup>5</sup> 1377-00-201-9543M938 EA- |         |      |
| 6B2240/20 Mk | 86 Mod I <sup>1</sup> 1377- | 01-246-5286M938 EA-                     |         |      |
| 6B2240/20 Mk | 87 Mod 0 <sup>5</sup> 1377- | 00-201-9545M939 EA-                     |         |      |
| 6B1240/20 Mk | 87 Mod 1 <sup>1</sup> 1377- | 01-246-5287M939 EA-                     |         |      |
| 6B1240/20 Mk | 88 Mod 0 <sup>5</sup> 1377- | 00-201-9533M940 EA-                     |         |      |
| 6B1240/20 Mk | 88 Mod 1 <sup>1</sup> 1377- | 01-246-5288M940 EA-                     |         |      |
| 6B1240/20    |                             |   | '       |      |

Mk 92 Mod 1  $^1$ 1377-01-036-8514M933 QF4N, QF-4S2192/16 Mk 100 Mod 0 $^5$ 1377-01-039-2927MD68 FA-18AJC/B/DI216/18

See footnotes at end of table.

#### Pro ellant-Actuated Devices—Continued

| PAD device  | NSN  | DODIC                             | Series<br>aircraft   | No. per<br>aircraft | Service life<br>(mo/yr)                                  |
|---|--|-----------------------------------|--|---------------------|--|
| Mk 101 Mod 0 <sup>5</sup><br>Mk 123 Mod 0 <sup>25</sup><br>Mk 124 Mod | 1377-01-039-2928<br>1377-01-246-5280<br>1377-01-246-5281           | MD69<br>MT30<br>MT31              | FA-18B/D/E<br>F_14D<br>18 DIF<br>T-45A/C<br>F_14D<br>FA-18C/D/E/F<br>T-45AJC | 1 1 1               | 216/18<br>180/15<br>180/15<br>180/15<br>180/15<br>180/15 |
|   | Cano   | ppy Remover                       | Rocket Motor   | 1                   | 100/13   |
| Mk 109 Mod 0 <sup>24</sup><br>Mk 109 Mod 1 <sup>24</sup>              | 1377-01-101-1443<br>1377-01-454-9321<br>R                          | MF56FA-<br>SS67FA-<br>ocket Motor | Divergence   |                     | 18A/C/B/D/E/F2132<br>18A/C/B/D/E/F2132                   |
| Mk 121 Mod 0 <sup>2.</sup><br>Mk 122 Mod                              | <sup>3</sup>   1377-01-242-8859   M<br>Paracht<br>1377-01-246-5279 |                                   | ITAV-8B<br>ent Rocket Motor<br>F-14D<br>FA-18C/D/E/F<br>T-45A/C              | 2 2 2               | 84/676<br>84176<br>84176<br>120/10                       |

<sup>&</sup>lt;sup>1</sup>NAVSURFWARCENDIV, Indian Head (IH).<sup>2</sup>

# TA-4J AIRCRAFT

<sup>1</sup>Jniversal Propulsion Company (UPC).

<sup>3</sup> 

Pacific Scientific.

<sup>&</sup>quot;alley Defense Systems (TAC).

Martin-Baker Aircraft Co., Ltd. (MBA).

 $<sup>^6\</sup>text{All}$  lots manufactured in 1998 and after are extended to 120/10; all others remain 84/7.

# Douglas ESCAPAC IG-3 Ejection Seats

1. Rocket Motor Mk 82 Mod 0/1 (Man/Seat Separator, Left)


a. NSN: Mod 0 1377-00-119-2022/Mod 1 1377-01-412-6530

b. DODIC: M928/MU76

c. Service life: Mod 0: 192 months (16 years); Mod 1: 108 months (9 years)

d. Rocket motor WUC: Mod 0 97D11/Mod 1 97D12

e. Two per TA-4J aircraft.



|                        | Lot      |      | Total              | Service life    |
|------------------------|----------|------|--------------------|-----------------|
| Lot No.                | quantity | T-4J | units<br>installed | expiration date |
| UPC93B001-021          | 391      | 10   | 10                 | February 2009   |
| UPC94COO 1-022         | 25       | O    | 0                  | March 2010      |
| UPC99F001-003A2        | 10       | 0    |                    | June 2008       |
| UPCOOE001-0042         | 90       | 0    |                    | May 2009        |
| IHMOOB002-0062         |          | O    |                    | February 2010   |
| Total installed:       |          | 10   |                    | ř               |
| Grand total installed: |          |      | 10                 |                 |

#### ILS Notes:

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. These lots of Mk 82 Mod 1 Man/Seat Separator Rocket Motors can be used in all applications in which the Mod 0 unit is currently being used. The Mod 1 is a one-for-one exchange with the Mk 82 Mod 0 (M928) unit. Mod 0 units will still be issued until stock is exhausted.
- 3. Indian Head has changed its manufacturer's identification symbol from IH to IHM.
- 4. The following lot has expired since the last publication of this report:

UPC86K001-017

October 2002

- 5. The next lot scheduled to expire will expire in February 2009.
- 6. We have increased the service life of the Mk 82 Mod 1 (MU76) Man/Seat Separator Rocket Motor from 84 months (7 years) to 108 months (9 years).
- 7. We have not received any Mk 82 Mod 0 (M928) conventional ordnance deficiencies or Els on the TA-4 aircraft since last publication of this report.

#### 2. Rocket Catapult Mk 16 Mod 1


a. NSN: 1377-01-040-9324

b. DODIC: MD72

c. Service life: 156 months (13 years)

d. Rocket motor WUC: 97D44

e. Two per TA-4 series aircraft.



|                        | Lot      |       | Total              | Service life       |
|------------------------|----------|-------|--------------------|--------------------|
| Lot No.                | quantity | TA-4J | units<br>installed | expiration<br>date |
| UPC90B004-026          | 279      | 3     | 3                  | February 2003      |
| UPC90C004-027          | 279      | 4     | 4                  | March 2003         |
| UPC90H004-028          | 69       |       | 0                  | August 2003        |
| UPC93B004-031          | 14       | 2     | 2                  | February 2006      |
| UPC97BOO I -032        | 7        |       | 0                  | February 2010      |
| UPC99J001-034          | 173      |       | O                  | September 2012     |
| UPC99L001-035          | 183      | 5     | 5                  | November           |
| Total installed:       |          | 14    |                    | 2012               |
| Grand total installed: |          |       | 14                 |                    |

#### ILS Notes:

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. The following lots have expired since the last publication of this report:

| UPC89G003-021 | July 2002    |
|---------------|--------------|
| UPC89G003-022 | Julv 2002    |
| UPC89K003-023 | October 2002 |
| UPC89M004-025 | December     |
|               | 2002         |

- 3. The next lot scheduled to expire will expire in February 2003.
- 4. We have not received any Mk 16 Mod I (MD72) conventional ordnance deficiencies or Els on the TA-4 aircraft since last publication of this report.

#### **AVITAV-8B AIRCRAFT**

#### Stencel SJU-4A AV-8B

# Stencel TAV-8B SJU-13/A Fwd, SJU-14A Aft

1. Seatback Rocket Motor Mk 79 Mod 1/2

a. NSN: 1377-01-069-1787

b. DODIC: MF21

c. Service life: 132 months (1 I years)d. Rocket motor WUC: 97DIM

e. Two per AV-8B aircraft, four per TA V-8B aircraft.



| Lot No.                | Lot<br>quantity | AV-8B | NAV-8B | TAV-8B | units<br>installed | expiration<br>date |
|------------------------|-----------------|-------|--------|--------|--------------------|--------------------|
| TAC92H001-055          | 88              |       | 0      |        | 0                  | August 2003        |
| TAC93L001-056          | 18              | 2     | 0      | 0      | 2                  | November 2004      |
| TAC97D001-001          | 135             | 57    |        | 20     | 77                 | April 2008         |
| TAC97J002-001          | 171             | 124   | 2      | 20     | 146                | September 2008     |
| TAC99H002-0022         | 261             | 29    | 0      | 6      | 35                 | August 2010        |
| IH-98A003-002          | 110             | 34    | 0      | 16     | 50                 | January 2009       |
| IH-99M002-003          | 50              | 2     | О      |        | 2                  | December 2010      |
| TACOOL002-0032         | 30              | O     | O      | 0      | O                  | November<br>2011   |
| TAC01E002-0042         | 80              |       | 0      | O      | 0                  | Mav 2012           |
| TACOOE002-0052         | 16              | 0     |        | О      | О                  | Mav 2012           |
| Total installed:       |                 | 248   | 2      | 62     |                    |                    |
| Grand total installed: |                 |       |        |        | 312                |                    |
|                        |                 |       |        |        | Total              |                    |

Service life

#### ILS Notes:

1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).

- 2. NSWC IHDIV has qualified and released a Mk 79 Mod 2 (MF21) Seatback Rocket Motor. This new unit can be used in all applications in which the Mod 1 unit is currently being used. The Mod 2 is a one-for-one exchange with the Mk 79 Mod 1 (MF21) unit.
- 3. No lots have expired since the last publication of this report.
- 4. The next lot scheduled to expire will expire in August 2003.

5. We have not received any Mk 79 Mod I (MF21) conventional ordnance deficiencies or Els on the AV-8 aircraft since the last publication of this report.

2. WORD Rocket Motor/Drogue Release Assembly Mk 1 13 Mod 0/1

a. NSN: 1377-01-149-3516

b. DODIC: MG67

c. Service life: 96 months (8 years)d. Rocket motor WUC: 97D3C

e. One per AV-8B aircraft, two per TAV-8B aircraft.

| e. One per 11 v | ob uncluit, two | per III v | B unorum. |        |                    |                    |  |
|-----------------|-----------------|-----------|-----------|--------|--------------------|--------------------|--|
|                 | Lot             |           |           |        | Total              | Service life       |  |
| Lot No.         | quantity        | AV-8B     | NAV-8B    | TAV-8B | units<br>installed | expiration<br>date |  |
| TAC98M003-0012  | 64              | 8         | 0         | 0      | 8                  | December 2006      |  |
| UPC99DOO1-001   | 237             | 128       |           | 29     | 159                | April 2007         |  |
| UPCOOGOO 1-002  | 32              | 0         |           | 0      | О                  | July 2008          |  |
| TACOOJ004-0032  | 30              | 0         | O         | 0      | 0                  | Septem ber         |  |

Grand total installed:

Total installed:

ILS Notes:

1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).

129

2. NSWC IHDIV has qualified and released a Mk 113 Mod 1 (MC,67) WORD Rocket Motor/Drogue Release Assembly. This new unit can be used in all applications in which the Mod 0 unit is currently being used. The Mod 1 is a one-for-one exchange with the Mk 113 Mod 0 (MG67) unit.

29

2008

167

- 3. No lots have expired since the last publication of this report.
- 4. The next lot scheduled to expire will expire in December 2006.
- 5. We have not received any Mk 1 13 Mod 0 (MG67) conventional ordnance deficiencies or Els on the A V-8 aircraft since the last publication of this report.

#### 3. Catapult Cartridge Mk 205 Mod 1/2


a. NSN: 1377-01-138-3829

b. DODIC: XW36

c. Service life: 96 months (8 years)d. Rocket motor WUC: 97D34

d. Rocket motor Wee. 77254

e. One per AV-8B aircraft, two per TAV-8B aircraft.



|                                 | Lot       |          |        |         | Total              | Service life                     |
|---------------------------------|-----------|----------|--------|---------|--------------------|----------------------------------|
| Lot No.                         | quantity  | AV-8B    | NAV-8B | TAV-8B  | units<br>installed | expiration<br>date               |
| TAC95G001-002<br>TAC95JOO 1-003 | 112<br>69 | 23<br>19 |        | 3       | 26<br>19           | July 2003<br>September<br>2003   |
| TAC96A001-004<br>TAC98M002-0012 | 36<br>77  | 10<br>29 | 0      | 17<br>1 | 27<br>30           | January 2004<br>December<br>2006 |
| TAC98M002-0022                  | 50        | 33       | 1      | 5       | 39                 | December 2006                    |
| TACOOB002-003A2                 | 60        | 3        | О      | 0       | 3                  | Februarv<br>2008                 |
| TACOI B002-004 <sup>2</sup>     | 126       | 0        | O      |         |                    | Februarv<br>2009                 |
| Total installed:                |           | 117      | 1      | 26      |                    |                                  |

Grand total installed:

#### ILS Notes:

- 1. Quantity per lot repotted installed in CAD/PAD Traceability System (CATS).
- 2. NSWC IHDIV has qualified and released a Mk 205 Mod 2 (XW36) Catapult Cartridge. This new unit can be used in all applications in which the Mod 1 unit is currently being used. The Mod 2 is a one-for-one exchange with the Mk 205 Mod I (XW36) unit.
- 3. No lots have expired since the last publication of this report.
- 4. The next lot scheduled to expire will expire in July 2003.
- 5. We have not received any Mk 205 Mod I (XW36) conventional ordnance deficiencies or Els on the AV-8 aircraft since the last publication of this report.

#### ILS Notes:

Lot No. Lot

quantity

86

ESDOOA001-0015 Total installed:

Grand total installed:


4. Rocket Motor Divergence Mk 121 Mod 0

a. NSN: 1377-01-242-8859

b. DODIC: MT28

c. Service life: 84 months (7 years)d. Rocket motor WUC: 93046

e. Four per TAV-8B aircraft.



Total Service life

1.Quantity per lot reported installed in CAD/PAD Traceability System (CATS).

- 2. The following lot has expired since the last publication of this report: UPC95H001-019 August 2002.
- 3. The next lot scheduled to expire will expire in January 2007.
- 4. We have not received any Mk 121 Mod 0 (MT28) conventional ordnance deficiencies or Els on the TAV-8 aircraft since last publication of this report.
- 5. We have qualified Pacific Scientific (EST)) as a manufacturer.

#### **EA-6B AIRCRAFT**

# Martin-Baker Mk GRUEA7 Ejection Seats

- 1. Underseat Rocket Motor Mk 86 Mod 0 and Mod 1
  - a. NSN: 1377-00-201-9543 (Mod 0), 1377-01-246-5286 (Mod 1)
  - b. DODIC: M938 (Mod 0), M938 (Mod 1)
  - c. Service life: Mod 0: 240 months (20 years); Mod 1: 240 months (20 years)
  - d. Rocket motor WUC: 97D3M Mod O and Mod 1
  - e. Two per aircraft (Pilot/ECMO-3).



| Total | Lot No.                            | Lot<br>quantity | EA-6B     | units<br>installed | expiration date |
|-------|------------------------------------|-----------------|-----------|--------------------|-----------------|
|       | MBA84B001-013                      | 12              | 9         | 9                  | February 2004   |
|       | MBA85E001-015                      | 16              | 13        | 13                 | May 2005        |
|       | MBA85EOOl-017                      |                 | 21        | 21                 | May 2005        |
|       | MBA85H001-018                      | 32              | 30        | 30                 | August 2005     |
|       | MBA86JOO 1-021                     | 24              | 20        | 20                 | September 2006  |
|       | UPC86J001-001(A) or (B)            | 37              | 20        | 20                 | September 2006  |
|       | MBA86JOOIH020                      | 27              | 43        | 43                 | September 2006  |
|       | MBA88B001 H023                     | 7               | 2         | 2                  | February 2008   |
|       | MBA88E001-027                      | 22              | 13        | 13                 | June 2008       |
|       | MBA89F001-030                      |                 | 14        | 14                 | June 2009       |
|       | IH-94L002-003A<br>Total installed: | 76              | 43<br>219 | 43                 | November 2014   |
|       | Grand total installed:             |                 | -         | 219                |                 |
|       |                                    |                 |           |                    | Commisso        |

Service life

ILS Notes:

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. The following lot has expired since the last publication of this report: MBA83A001-011 January 2003
- 3. The next lot scheduled to expire will expire in February 2004.
- 4. We have not received any Mk 86 Mod 0/1 (M938) conventional ordnance deficiencies or Els on the EA-6B aircraft since the last publication of this report.
- 2. Underseat Rocket Motor Mk 87 Mod 0 and Mod 1
- a. NSN: 1377-00-201-9545 (Mod 0), 1377-01-246-5287 (Mod 1)
- b. DODIC: M939 (Mod 0), M939 (Mod 1)
  - c. Service life: Mod 0: 240 months (20 years); Mod 1: 240 months (20 years)
  - d. Rocket motor WUC: 97D3N Mod O and Mod I
  - e. One per aircraft ). (ECMO-I

| Lot No.                          | Lot<br>quantity | EA-6B | units<br>installed | expiration date         |
|----------------------------------|-----------------|-------|--------------------|-------------------------|
| MBA84BOOI-013                    | 6               | 5     | 5                  | February 2004           |
| MBA85EOOI-015                    | 8               | 7     | 7                  | May 2005                |
| MBA85E001-017                    | 12              | 9     | 9                  | May 2005                |
| MBA85H001-018                    | 25              | 23    | 23                 | August 2005             |
| MBA86JOO I H020                  | 21              | 27    | 27                 | September 2006          |
| MBA86J001-021                    | 12              | 1 1   | I 1                | September 2006          |
| UPC86JOO1 -001 (A) or (B)        | 25              | 7     | 7                  | September 2006          |
| MBA88BOO1H023                    | 5               | 6     | 6                  | February 2008           |
| MBA88E001-025                    |                 | 0     | 0                  | May 2008                |
| MBA88EOO1-028<br>MBA 88HOOI H029 | 10<br>1         | 6     | 6                  | May 2008<br>August 2008 |

|     | Total  |
|-----|--------|
| 201 | 88     |
| 938 | 600.   |
|     |        |
|     | LOADED |
| 4   |        |

| alMBA88E001-030<br>MBA89F001-031 | 12 | 7<br>0 | 7<br>o | May 2008<br>June 2009 |
|----------------------------------|----|--------|--------|-----------------------|
| IH-94L002-003A                   | 26 | 6      | 6      | November              |
| Total installed:                 |    | 116    |        | 2014                  |
| Grand total installed:           |    |        | 1 16   |                       |
|                                  |    |        |        | Service               |
|                                  |    |        |        | life                  |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. The following lot has expired since the last publication of this report: MBA83A001-011 January 2003
- 3. The next lot scheduled to expire will expire in February 2004.
- 4. We have not received any Mk 87 Mod 0/1 (M939) conventional ordnance deficiencies or Els on the EA-6B aircraft since the last publication of this report.
- 3. Underseat Rocket Motor Mk 88 Mod 0 and Mod 1
- a. NSN: 1377-00-201-9551 (Mod 0), 1377-01-246-5288 (Mod 1)
- b. DODIC: M940 (Mod 0), M940 (Mod 1)
  - c. Service life: Mod 0: 240 months (20 years); Mod 1: 240 months (20 years)
  - d. Rocket motor WUC: 97D3P Mod O and Mod 1
  - e. One per aircraft (ECMO-2).



|                        | Lot      |       |                    | Service life       |
|------------------------|----------|-------|--------------------|--------------------|
| Lot No.                | quantity | EA-6B | units<br>installed | expiration<br>date |
| MBA84BOOl-013          | 6        | 3     | 3                  | February 2004      |
| MBA85E001-015          | 8        | 6     | 6                  | May 2005           |
| MBA85E001-017          | 12       | 9     | 9                  | May 2005           |
| MBA85H001-018          | 31       | 16    | 16                 | August 2005        |
| MBA86J001-021          | 13       | 11    | 11                 | September 2006     |
| MBA88B001H023          | 6        | 0     | 0                  | February 2008      |
| MBA88E001025           | 11       | 11    | 11                 | May 2008           |
| MBA 88EOO 1-027        | 12       | 6     | 6                  | May 2008           |
| MBA89F001-030          | 13       | 7     | 7                  | May 2009           |
| IH-94L002-003A         | 33       | 30    | 30                 | November 2014      |
| IH-94L002-004          | 25       | 1     | 1                  | November 2014      |
| MBAOOL002-031          |          | 13    | 13                 | November           |
| Total installed:       |          | 116   |                    | 2020               |
| Grand total installed: |          |       | 116                |                    |
|                        |          |       | Total              |                    |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. The following lot has expired since the last publication of this report: MBA83A001-011 January 2003
- 3. The next lot scheduled to expire will expire in February 2004.
- 4. We have not received any Mk 88 Mod 0/1 (M940) conventional ordnance deficiencies or Els on the EA6B aircraft since the last publication of this report.

F-5E/F-T-38A AIRCRAFT

Northrop Improved Ejection Seat Assembly Number 14-70202-505


#### 1. Rocket Catapult CKU-7A

a. NSN: 1377-00-125-7777

b. DODIC: MS15

c. Service life: 120 months (10 years)d. Rocket catapult WUC: 97ABA

e. One per F-5E aircraft, two per F-5F aircraft, two per T-38 aircraft.



|                        | Lot      |      |      |       | Total              | Service life       |
|------------------------|----------|------|------|-------|--------------------|--------------------|
| Lot No.                | quantity | F-5E | F-5F | T-38A | units<br>installed | expiration<br>date |
| IH-95EOO -046          | 8        | 4    | 3    | O     | 7                  | Mav 2005           |
| IH-96HOO I -048        | 5        |      | 0    | 2     | 3                  | August 2006        |
| IH-98FOO1 -049         | 21       | 16   | 0    | 5     | 21                 | August 2006        |
| IHMOOC001-051          |          | 10   | 5    | 7     | 22                 | March 2010         |
| IHMOOEOO1-052          | 22       |      | 0    | 4     | 5                  | May 2010           |
| Total installed:       |          | 32   | 8    | 18    |                    |                    |
| Grand total installed: |          |      |      |       | 58                 |                    |

#### ILS Notes:

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. No lots have expired since the last publication of this report.
- 3. The next lot scheduled to expire will expire in May 2005.
- 4. We have not received any CKU-7A (MS 1 5) conventional ordnance deficiencies or Els on the F-5 or T-38 aircraft since the last publication of this report.

# F-14A/B AND NF-14A AIRCRAFT

#### Martin-Baker Mk GRU-7A Ejection Seats

- 1. Underseat Rocket Motor Mk 74 Mod 0 and Mod 1
  - a. NSN: 1377-00-181-9532 (Mod 0), 1377-01-246-5282 (Mod 1)
  - b. DODIC: M572 (Mod 0), M572 (Mod 1)
  - c. Service life: Mod 0: 240 months (20 years); Mod 1: 240 months (20 years)
  - d. Rocket motor WuC: 97DIR Mod O and Mod I
  - e. One each per aircraft (pilot).



| Lot No.                | Lot<br>quantity | F-14A | F-14B | Total<br>units<br>installed | Service life<br>expiration<br>date |
|------------------------|-----------------|-------|-------|-----------------------------|------------------------------------|
| MBA84B001-013          | 24              | 3     | 3     | 6                           | February 2004                      |
| MBA85E001-015          | 18              | 1     | 5     | 6                           | May 2005                           |
| MBA85E001-017          | 18              | 1     | 12    | 13                          | May 2005                           |
| MBA85HOOl-018          | 126             | 16    | 18    | 34                          | August 2005                        |
| UPC86J001 -OOIA (or) B | 25              | 1     | 3     | 4                           | September 2006                     |
| MBA88B001-024          | 15              | 0     | 9     | 9                           | February 2008                      |
| MBA88H001-026          | 6               | 2     | 1     | 3                           | August 2008                        |
| IH-94L002-003A         | 23              | 7     | 5     | 12                          | November 2014                      |
| IHM94L002-004          | 15              | 5     | 3     | 8                           | November                           |
|                        |                 |       |       |                             | 2014                               |
| Total installed:       |                 | 37    | 62    |                             |                                    |
| Grand total installed: |                 |       |       | 99                          |                                    |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. The following lot has expired since the last publication of this report: MBA83A001-011 January 2003
- 3. The next lot scheduled to expire will expire in February 2004.
- 4. We have not received any Mk 74 Mod 0/1 (M572) conventional ordnance deficiencies or Els on the F-14A/B aircraft since last publication of this report.
- 2. Underseat Rocket Motor Mk 75 Mod 0 and Mod I
  - a. NSN: 1377-00-181-9533 (Mod 0), 1377-01-246-5283 (Mod 1)
  - b. DODIC: M573 (Mod 0), M573 (Mod 1)
  - c. Service life: Mod 0: 240 months (20 years); Mod 1: 240 months (20 years)
  - d. Rocket motor WUC: 97D3J Mod O and Mod 1
  - e. One per aircraft (NFO).

|               | Lot      |       |       | Total              | Service life       |
|---------------|----------|-------|-------|--------------------|--------------------|
| Lot No.       | quantity | F-14A | F-14B | units<br>installed | expiration<br>date |
| MBA84BOOl-013 |          | 2     | 2     | 4                  | February 2004      |
| MBA85EOOl-015 | 18       | 2     | 7     | 9                  | May 2005           |
| MBA85E001-017 | 18       | O     | 13    | 13                 | May 2005           |
| MBA85HOOl-018 | 134      | 15    | 14    | 29                 | August 2005        |

| UPC86JOOl-OOlA (or) B  | 25 | 4  | 0  | 4  | September     |
|------------------------|----|----|----|----|---------------|
|                        |    |    |    |    | 2006          |
| MBA88BOO I -024        | 13 | 0  | 8  | 8  | February 2008 |
| MBA88H001-026          | 5  | 0  | 2  | 2  | August 2008   |
| IH-94L002-003A         | 22 | 4  | 8  | 12 | November      |
|                        |    |    |    |    | 2014          |
| IHM94L002-004          | 12 | 5  | 1  | 6  | November      |
|                        |    |    | •  |    | 2014          |
| Total installed:       |    | 34 | 61 |    |               |
| Grand total installed: |    |    |    | 95 |               |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. The following lot has expired since the last publication of this report:

MBA83A001-011

January 2003

- 3. The next lot scheduled to expire will expire in February 2004.
- 4. We have not received any Mk 75 Mod 0/1 (M573) conventional ordnance deficiencies or Els on the F- 14A/B aircraft since last publication of this report.

#### F-14D AND NF-14D AIRCRAFT

# SJU-17/(V)3/A(Forward seat) and SJU-17/(V)4/A(Aft seat)

1. Parachute Deployment Rocket Motor Mk 122 Mod 0


a. NSN: 1377-01-246-5279

b. DODIC: MT29

c. Service life: 84 months (7 years), 120 months (10 years)

d. Rocket motor WUC: 97D4A

e. Two each per aircraft (pilot and MCC)).



|                | Lot      |       | Total     | Service life   |
|----------------|----------|-------|-----------|----------------|
| Lot No.        | quantity | F-14D | units     | expiration     |
|                |          |       | installed | date           |
| UPC94C003-0045 | 229      | 19    | 19        | March 2003     |
| MBA96C003-013  | 49       | 8     | 8         | March 2003     |
| UPC97H003-005  | 192      | 25    | 25        | August 2004    |
| MBA98J004-0144 | 300      | 28    | 28        | September 2008 |
| MBA99J004-0164 | 206      | 4     | 4         | September 2009 |
| MBAOOF004-0174 | 257      | 2     | 2         | June 2010      |

| UPC01E005-0014         | 270 |    | 0  | May 2011 |
|------------------------|-----|----|----|----------|
| Total installed:       |     | 86 |    |          |
| Grand total installed: |     |    | 86 |          |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. No lots have expired since the last publication of this report.
- 3. The next lots scheduled to expire will expire in March 2003.
- 4. We have increased the service life on all lots manufactured after 1998 from 84 months (7 years) to 120 months (10 years). All other lots will remain at 84 months (7 years).
- 5. Indian Head has extended the service life 24 months from 84 months (7 years) to 108 months (9 years for the following lot:

UPC94C003-004

March 2003

- 6. We have received a CODR on stirrups installed incorrectly on a Mk 122 Mod 0 (MT29) Parachute Deployment Rocket Motor (lot UPCO I E005-001). The stirrup links are making contact with the ejection seat main beam, thus making it impossible to connect the parachute withdrawal line. We have contacted the activity and requested photos. We will request that the unit be returned for an engineering investigation. We are pulling sample Condition Code "A" units from the same lot for inspection. The manufacturer has also been contacted and is in the process of verifying this condition with their x-rays.
- 2. Underseat Rocket Motor Mk 123 Mod 0 (front)

a. NSN: 1377-01-246-5280

b. DODIC: MT30

c. Service life: 180 months (15 years)d. Rocket motor WUC: 97D4B

e. One per aircraft (pilot).

|                 | Lot      |       | Total              | Service life    |
|-----------------|----------|-------|--------------------|-----------------|
| Lot No.         | quantity | F-14D | units<br>installed | expiration date |
| MBA89F001-003   | 31       | 0     | 0                  | June 2004       |
| MBA89F001-005   | 16       | 0     | 0                  | June 2004       |
| MBA90HOO I -006 | 35       | 13    | 13                 | August 2004     |
| MBA90HOOl-007   | 6        |       | O                  | August 2004     |
| MBA90KOOl-008   | 50       | 0     | 0                  | October 2004    |

| UPC90LOOI HOO 1B       | 17  |    | 1  | November 2005  |
|------------------------|-----|----|----|----------------|
| MBA91J001-009          | 21  | 4  | 4  | September 2006 |
| UPC91 KOO I H002A      | 14  | 2  | 2  | October 2006   |
| MBA92C001-OlO          | 10  | 0  | 0  | March 2006     |
| UPC93E002H005          | 27  |    | 0  | May 2008       |
| MBA93F002-Ol I         | 54  | 9  | 9  | June 2008      |
| UPC94B003H006          | 80  | 5  | 5  | February 2009  |
| MBA95C003-012          | 236 | 3  | 3  | March 2010     |
| MBA96C003-013          | 71  | 0  | O  | March 2011     |
| MBA97G003-014          | 33  | 1  | 1  | July 2012      |
| MBA98J003-017          | 33  |    | 0  | September 2013 |
| MBA99H003-019          | 53  | 0  | 0  | August 2014    |
| MBAOI A003-020         | 47  | 0  | 0  | January 2016   |
| MBAO E003-024          | 22  | 0  | 0  | May 2016       |
| Total installed:       |     | 38 |    |                |
| Grand total installed: |     |    | 38 |                |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. No lots have expired since the last publication of this report.
- 3. The next lots scheduled to expire will expire in June 2004.
- 4. We have increased the service life of the Mk 123 Mod 0 (MT30) Underseat Rocket Motor from 156 months (13 years) to 180 months (15 years). We issued this increase in IRAC 18, Naval message DTG 111036Z sept 01.
- 5. We have not received any Mk 123 Mod 0 (MT30) conventional ordnance deficiencies or Els on the F- 141) aircraft since the last publication of this report.

#### ILS Notes:

| Lot No.        | Lot<br>quantity | F |
|----------------|-----------------|---|
| MBA89F001-004  | 57              |   |
| MBA89F001-005  | 7               |   |
| MBA90HOO 1-006 | 68              |   |
| MBA90H001-007  | 36              |   |
| MBA90K001-008  | 91              |   |
| UPC90LOO 1B    | 36              |   |

# Total Service MBA91J001-009 life

| 1.  | Quantity per lot reported installed in CAD/PAD Traceability System  | UPC91K0  | 01H002A         | 29  |
|-----|---|----------|-----------------|-----|
| (CA | ΓS).  | UPC91KO  | O1H003          | 6   |
| 2.  | No lots have expired since the last publication of this report.   | MBA92C   | 001-010         | 27  |
| 3.  | The next lots scheduled to expire will expire in June 2004.   | UPC93D0  | 02H004          | 62  |
| 4.  | We have increased the service life of the Mk 124 Mod 0 (MT31)   | MBA93F0  | 002-011         | 104 |
| 4.  | Underseat Rocket Motor from 156 months (13 years) to 180 months   | UPC94C0  | 03H005          | 142 |
|     | (15 years). We issued this increase in IRAC 18, Naval message DTC   | MBA95C   | 165             |     |
|     | 111036Z sept 01.  | MBA96C0  | 003-013         | 71  |
| _   | We have not received any Mh 124 Med 0 (MT21) conventions  | MBA97G   | 003-014         | 70  |
| 5.  | We have not received any Mk 124 Mod 0 (MT31) conventional ordnance deficiencies or Els on the F-14D aircraft since the last |          | 03-017          | 66  |
|     | publication of this report.   | MBA99H0  | 003-019         | 84  |
|     |   | MBA01A0  | 003-020         | 76  |
|     |   | MBAOI    | E003-024        | 37  |
|     |   | Total in |                 |     |
|     |   | Grand to | otal installed: |     |

#### 3. Underseat Rocket Motor Mk 124 Mod 0 (rear)

a. NSN: 1377-01-246-5281

b. DODIC: MT31

c. Service life: 180 months (15 years)

d. Rocket motor WUC: 97D48

e. One per F-14D and NF-14D aircraft (NFO).



# FA-181AIBICID AIRCRAFT

Martin-Baker SJU-5/A Ejection Seat F-18 and Rear Seat of HA-18 B/D and

# SJU-6/A Ejection Seat (Front Seat of FIA-18 B/D)

#### 1. Rocket Motor Mk 100 Mod O


a. NSN: 1377-01-039-2927

b. DODIC: MD68

c. Service life: 216 months (18 years)

d. Rocket motor WUC: 97D38

e. One per F/A-1 8 A/C and one per F/A-18 B/D (rear seat only).



|                 | Lot |        |        |        |        |                    | Service life    |
|-----------------|-----|--------|--------|--------|--------|--------------------|-----------------|
| Lot No.         |     | FA-18A | FA-18B | FA-18C | FA-18D | units<br>installed | expiration date |
| MBA86GOOl-012   | 57  | 24     |        | 0      | О      | 24                 | July 2004       |
| MBA86GOO 1-013  | 47  | 6      | 5      | 3      | O      | 14                 | July 2004       |
| MBA86GOO 1-015  | 30  | 1      | 0      | 6      | 0      | 7                  | July 2004       |
| MBA86JOOl-016   | 56  | 7      | 1      | 2      | 1      | 11                 | September 2004  |
| MBA86MOOl-017   | 29  |        | O      | 10     | 2      | 12                 | December 2004   |
| MBA86JOOl-018   | 18  |        | 0      | 3      | 2      | 5                  | September 2004  |
| MBA86JOOI-020   | 7   | 0      | 0      | 1      |        | 2                  | September 2004  |
| MBA87K001-024   | 21  | O      |        | 7      | 3      | 10                 | October 2005    |
| MBA87K001-025   | 15  | 1      | 0      | 4      |        | 6                  | October 2005    |
| MBA88B001-026   | 23  | 1      | 0      | 15     | 5      | 21                 | February 2006   |
| MBA88GOOl-027   | 5   |        | 0      | 1      | 0      | 1                  | July 2006       |
| MBA88BOOl-028   | 11  | 0      |        | 3      |        | 3                  | February 2006   |
| MBA88G001-029   | 55  | 2      | О      | 37     | 1      | 40                 | July 2006       |
| MBA88GOO1_031   | 16  |        | 0      | 3      |        | 3                  | July 2006       |
| MBA89A001-033   | 128 | 4      | 10     | 5      | 1      | 62                 | January 2007    |
| MBA89B001-032   | 66  | 4      | O      | 34     | 22     | 60                 | February 2007   |
| MBA89FOO -034   | 8   | 0      |        | 4      | 2      | 6                  | June 2007       |
| MBA91 BOO 1-038 | 66  | 33     | 7      | 7      | 1      | 48                 | February 2009   |
| MBA93C002-040   | 182 | 47     | 8      | 7      | 2      | 64                 | March 2011      |
| MBA94C003-041   | 46  | 5      | 0      | 1      |        | 7                  | March 2012      |

Total

|                        | Lot |        |        |        |        | Total     | Service life             |
|------------------------|-----|--------|--------|--------|--------|-----------|--------------------------|
| Lot No.                | Lot | FA-18A | FA-18B | FA-18C | FA-18D | units     | expiration               |
|                        |     |        |        |        |        | installed | date                     |
| MBA96L003-047          | 47  | 4      |        | 1      |        | 6         | November                 |
| MBA99M003-050          | 7   | 0      | 0      | 0      | 0      | O         | 2015<br>December<br>2017 |
| Total installed:       |     | 181    | 32     | 154    | 45     |           |                          |
| Grand total installed: |     |        |        |        |        |           |                          |
| Grand total installed: |     |        |        |        |        | 412       |                          |

#### quantity

#### ILS Notes:

1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).

2. The following lots have expired since the last publication of this report:

MBA85H001-009 August 2002 MBA85H001-010 August 2002 MBA85K001-011 October 2002

3. The next lot scheduled to expire will expire in July 2004.

4. We have increased the service life on all lots from 204 months (17 years) to 216 months (18 years).

5. We received a CODR from a fleet activity reporting that while maintenance personnel were performing an acceptance inspection, they discovered gouges. Indian Head requested this motor be returned for possible placement in its quality evaluation program.

#### 2. Rocket Motor Mk 101 Mod O

a. NSN: 1377-01-039-2928

b. DODIC: MD69

c. Service life: 216 months (18 years)

d. Rocket motor WUC: 97D3A

e. One per F/A- 18 (front seat only).

|                | Lot      |        |        | Total     | Service life   |
|----------------|----------|--------|--------|-----------|----------------|
| Lot No.        | 200      | FA-18B | FA-18D | units     | expiration     |
|                | quantity |        |        | installed | date           |
| MBA86GOOl-012  | 2        | 0      | 1      | 1         | July 2004      |
| MBA86GOO 1-013 |          |        | 1      | 2         | July 2004      |
| MBA86J001-020  | 8        | 2      | 4      | 6         | September 2004 |
| MBA86M001-017  | 7        |        | 2      | 2         | December 2004  |

| MBA87KOOl-024    | 2  | 0  | 2  | 2  | October 2005  |
|------------------|----|----|----|----|---------------|
| MBA87K001-025    | 3  | 0  | 2  | 2  | October 2005  |
| MBA88BOO 1-026   | 7  |    | 5  | 5  | February 2006 |
| MBA88G001-029    | 8  | 0  | 6  | 6  | July 2006     |
| MBA89AOO 1-033   | 25 | 4  | 3  | 7  | January 2007  |
| MBA89BOO 1-032   | 30 | 5  | 15 | 20 | February 2007 |
| MBA91BOOl-038    | 17 | 10 | 2  | 12 | February 2009 |
| MBA93C002-040    | 23 | 4  | 1  | 5  | March 201 1   |
| MBA94C003-041    | 33 | 7  | 7  | 14 | March 2012    |
| MBA96L003-047    | 47 | О  | О  | 0  | November 2015 |
| MBA99M003-050    | 15 |    |    |    | December 2017 |
| Total installed: |    | 33 | 51 |    |               |

Grand total installed:

#### ILS Notes:

1. Quantity per lot reported installed in CAD/PAD Traceability System (CA TS).

2. The following lots have expired since the last publication of this report:

MBA85H001-009 August 2002 MBA85K001-011 October 2002

- 3. The next lot scheduled to expire will expire in September 2004.
- 4. We have increased the service life on all lots from 204 months (17 years) to 216 months (18 years).
- 5. We received a CODR on the Mk 101 (MD69) Underseat Rocket Motor. During the de-arm process for 448day inspection, the technician discovered a broken lockwire. This squadron conducted an investigation to determine if the tubes had rotated. The investigation was inconclusive since rotation could not be verified because ofthe absence of the torque stripe. We are currently looking into the best method for incorporating torque striping on installed units. We have requested this unit be returned for potential use as a QE sample.
- 3. Rocket Motor Mk 109 Mod 0 and Mod I
  - a. NSN: 1377-01-101-1443 (Mod 0), 1377-01-454-9321 (Mod 1)
  - b. DODIC: MF56 (Mod 0), SS67 (Mod 1)
  - c. Service life: 132 months (1 1 years)
  - d. Rocket motor WUC: 97D47
  - e. Two per F/A-18.
  - f. For non-NACES FA-18 aircraft

Lot Total Service life

| Lot No.  UPC92B001-033  UPC92D001-034  UPC92GOO 1-035 | quantity 46 48 45 | FA-18A<br>o | FA-181      | B FA-18C  | FA-18D  | units<br>installed<br>O | expiration date February 2003 April 2003 |
|---|-------------------|-------------|-------------|-----------|---------|-------------------------|--|
|   |                   |             |             |           |         | О                       | July 2003                                |
| UPC92G001-036<br>UPC92K001-038                        | 343<br>49         | 95          | 24          | 106<br>0  | 26<br>0 | 251<br>o                | July 2003<br>October 2003                |
| UPC93A001-039   | 35                |             | 0           |           |         | О                       | January 2004                             |
| UPC93C001-<br>March 2004                              |                   |             | 0           | 041       | 48      | 0o                      | 0 о                                      |
| UPC93JOO -<br>September 2004                          |                   |             | 0<br>0<br>0 | 042       |         | 25                      | 00 0                                     |
| TAC94A002-001A  |                   | 1           | 50          |           | 0       | 0                       | January 2005                             |
| UPC 94DOO I -043                                      |                   | 6           | 0o          |           | O       | 0                       | April 2005                               |
| UC95D001-044  |                   | 2           | 90          |           | 0       | O                       | April 2006                               |
| UPC95G001-045   | 27                | 0           | 0           | 0         | 0       | 0                       | July 2006                                |
| UPC95HOO 1-046  | 25                | O           |             |           |         | 0                       | A ugust 2006                             |
| UPC95L001-047   | 20                |             | 0           | 0         | 0       | 0                       | November 2006                            |
| UPC96BOO -048   | 48                | 10          | 2           | 26        | 8       | 46                      | February 2007                            |
| UPC96C001-049   | 8                 |             |             |           |         | 0                       | March 2007                               |
| UPC96G001-050<br>UPC96EOOl-                           | 195               | 34          | 2           | 47<br>051 | 28      | 111<br>180              | July 2007<br>o May 2007                  |
| UPC97B001-<br>February 2008                           |                   |             | 0<br>0<br>0 | 053       |         | 40                      | 0  |
| UPC97G001-<br>2008                                    |                   |             | 0           | 054       |         | 7                       | 00 0 July                                |
| UPC97G001-055   |                   | (           | 6о          |           |         | 0                       | July 2008                                |
| UPC98BOO1 -056  | 54                |             |             | 0o        |         |                         | February 2009                            |
| UPC99BOO1-057   |                   | 1:          | 20          |           | 0       | 0                       | February 2010                            |
| IH-98D001-0012  | 57                | 10          | 4           | 19        | 11      | 44                      | April 2009                               |
| TAC99D001-0022  | 250               | 100         | 10          | 34        | 20      | 164                     | April 2010                               |
| TACOOA001-0032  | 273               | 26          | 7           | 45        | 6       | 84                      | January 2011                             |
| TAC01H001-0052  | 109               | 2           | 1           | 3         | 0       | 6                       | August 2012                              |

| TAC01K001-0062         | 60 | 18  |    | О   |    | 18  | October       | 2012 |
|------------------------|----|-----|----|-----|----|-----|---------------|------|
| TAC01M001-0072         | 1  | 2   | О  |     | 0  | 2   | Decem<br>2012 | ber  |
| Total installed:       |    | 297 | 50 | 280 | 99 |     |               |      |
| Grand total installed: |    |     |    |     |    | 726 |               |      |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. NSWC IHDIV has qualified and released a Mk 109 Mod 1 (SS67) Canopy Jettison Rocket Motor (C.JRM). This new unit can be used in all applications in which the Mod 0 unit is currently used. The Mod 1 is a one-for-one exchange with the Mk 109 Mod 0 (MF56) unit. Mod 0 units will still be issued until stock is exhausted.
- 3. The following lots have expired since the last publication of this report:

| UPC91G001-031 | July 2002      |
|---------------|----------------|
| UPC90K001-026 | October 2002   |
| UPC90J001-027 | September 2002 |
| UPC91J001-032 | September 2002 |
| UPC90M001-028 | December 2002  |

4. The f0110"ing lot will expire "ithin the next six months:

UPC92B001-033 February 2003

5. We have not received any Mk 109 Mod 0/1 (MF56/SS67) conventional ordnance deficiencies or Els on the FA- 18 aircraft since the last publication of this report.

# FA-18C/D/E/F AIRCRAFT

# SJU-17/(V)2/AFIA-18D (Forward seat) and SJU-17/(V)1/AFIA-18C/D (Aft seat)

1. Parachute Deployment Rocket Motor Mk 122 Mod 0


a. NSN: 1377-01-246-5279

b. DODIC: MT29

c. Service life: 84 months (7 years), 120 months (10 years)

d. Rocket motor WUC: 97D4A

e. One per aircraft F/A-18C, E, two per aircraft F/A-18E, F (pilot and copilot).



|                  | Lot      |        |          |         |               | Total        | Service life   |
|------------------|----------|--------|----------|---------|---------------|--------------|----------------|
| Lot No.          | Lot      | FA-18C | FA-18D F | A-18E F | <b>A-18</b> F | units        | expiration     |
|                  | quantity | ,      |          |         |               | installed    | date           |
| UPC94C003-0045   | 229      | 21     | 11       | 2       |               | 34           | March 2003     |
| MBA 96003-013    | 49       | 6      | 2        |         | 2             | 11           | March 2003     |
| UPC97H003-005    | 192      | 34     | 25       | 10      | 11            | 80           | August 2004    |
| MBA98J004-0144   | 300      | 72     | 43       | 9       | 21            | 145          | September 2008 |
| MBA99J004-0164   | 206      | 42     | 32       | 14      | 36            | 124          | September 2009 |
| MBAOOF004-0174   | 257      | 28     | 32       | 15      | 18            | 93           | June 2010      |
| UPC01E005-0014   | 270      | 3      | 10       |         | 4             | 17           | May 2011       |
| Total installed: |          | 206    | 155      | 51      | 92            |              |                |
| G 1 11 .         | 11 1     |        |          |         |               | <b>5</b> 0.4 |                |

Grand total installed:

504

#### ILS Notes:

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. The following lot has expired since the last publication of this report: MBA95F003-010 June 2002
- 3. The next lot scheduled to expire will expire in March 2003.
- 4. We have increased the service life on all lots manufacture after 1998 from 84 months (7 years) to 120 months (10 years). All other lots will remain at 84 months (7 years).

5. Indian Head has extended the service life 24 months from 84 months (7 years) to 108 months (9 years for the following lot:

UPC94C003-004 March 2003

6. We have received a CODR on stirrups installed incorrectly on a Mk 122 Mod 0 (MT29) Parachute Deployment Rocket Motors (lot UPCO I E005-001). The stirrup links are making contact with the ejection seat main beam, thus making it impossible to connect the parachute withdrawal line. We have contacted the activity and requested photos. We will request that the unit be returned for an engineering investigation. We are pulling sample Condition Code "A" units from the same lot for inspection. The manufacturer has also been contacted and is in

the process of verifying this condition with their x-rays.

2. Underseat Rocket Motor Mk 123 Mod 0

a. NSN: 1377-01-246-5280

b. DODIC: MT30

c. Service life: 180 months (15 years)

d. Rocket motor WUC: 97D4B

e. One per F/A-18D and F aircraft (pilot).



| 1      | Lot        |          |  |
|--------|------------|----------|--|
|        |            | Quantity |  |
| MBA89F | FOO1-003   | 31       |  |
| MBA 89 | FOO1-005   | 16       |  |
| MBA90F | HOO1 -006  | 35       |  |
| MBA90F | HOO1-007   | 6        |  |
| MBA90  | K001-008   | 50       |  |
| UPC90L | OO HOC) 1B | 17       |  |

|                             |                |    |                   | Total | Service life  |
|-----------------------------|----------------|----|-------------------|-------|---------------|
| MBA91JOOl-                  |                |    | 0 009             |       | 21            |
| 66                          | September 2006 |    | 0                 |       |               |
| UPC91 KOO 1<br>October 2006 |                |    | $\frac{0}{0}$ H00 | )2A   | 14 22         |
| MBA92C001-OlO               | 10             |    | 00                |       | March 2007    |
| MBA93F002-O1 I              | 54             | 12 | 0                 | 12    | June 2008     |
| UPC94B003H006               | 80             | 14 | 0                 | 14    | February 2009 |
| MBA95C003-012               | 236            | 7  |                   | 8     | March 2010    |
| MBA96C003-013               | 71             | 4  | 3                 | 7     | March 2011    |

|                        |    |     | _  |     |                |
|------------------------|----|-----|----|-----|----------------|
| MBA97G003-014          | 33 | 10  | 8  | 18  | July 2012      |
| MBA98J003-017          | 33 | 7   | 7  | 14  | September 2013 |
| MBA99H003-019          | 53 | 0   | 21 | 21  | August 2014    |
| MBA01A003-020          | 47 | 0   | 2  | 2   | January 2016   |
| MBA01E003-024          | 22 | 0   | 3  | 3   | May 2016       |
| Total installed:       |    | 92  | 45 |     |                |
| Grand total installed: |    |     |    | 137 |                |
| UPC93E002H005          |    | 271 |    |     | May 2008       |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. No lots have expired since the last publication of this report.
- 3. The next lots scheduled to expire will expire in June 2004.
- 4. We have not received any Mk 123 Mod 0 (MT30) conventional ordnance deficiencies or Els on the FA-18 aircraft since last publication of this report.

#### 3. Underseat Rocket Motor Mk 124 Mod 0


a. NSN: 1377-01-246-5281


b. DODIC: MT31

c. Service life: 180 months (15 years)

d. Rocket motor WUC: 97D48

e. One per F/A-18D, and F aircraft (copilot), one per F/A-18C, E aircraft (pilot).





IHSP 03-486

|                       |     | A STATE OF THE PARTY OF |    |    | to the second | A STATE OF THE PARTY OF THE PAR | After the second section and the second section and |
|-----------------------|-----|-------------------------|----|----|---------------|--|---|
| MBA91JOO 1-009        | 34  | 11                      | 8  | 0  |               | 19   | September   |
|                       |     |                         |    |    |               |  | 2006  |
| UPC91 KOO H002A       | 29  |                         | 2  | O  | O             | 2  | October 2006  |
| UPC91 KOO I H003      | 6   | 0                       | O  | О  | 0             | 0  | October 2006  |
| MBA92C001-010         | 27  | 8                       | 2  | 0  |               | 10   | March 2007  |
| UPC93D002H004         | 62  | 4                       | 2  | 0  | 0             | 6  | April 2007  |
| MBA93F002-O1 1        | 104 | 58                      | 7  | 1  | 1             | 67   | June 2008   |
| UPC94C002H005         | 142 | 23                      | 13 | 0  | 0             | 36   | March 2009  |
| MBA95C003-012         | 165 | 77                      | 7  | 5  | 1             | 90   | March 2010  |
| MBA96C003-013         | 71  | 7                       | 5  | O  | 1             | 13   | March 2011  |
| MBA97G003-014         | 70  | 10                      | 12 | 11 | 10            | 43   | July 2012   |
| MBA98J003-017         | 66  | 3                       | 6  | 6  | 9             | 24   | September   |
|                       |     |                         |    |    |               |  | 2013  |
| MBA99H003-019         | 84  | 1                       | 0  | 22 | 1             | 40   | August 2014   |
| MBA01A003-020         | 76  |                         | 0  | 4  | 5             | 9  | January 2016  |
| MBAOI E003-024        | 37  |                         | 0  | O  | 0             | 0  | May 2016  |
| Total installed:      |     | 249                     | 92 | 49 | 44            |  |   |
| Grand total installed | l:  |                         |    |    |               | 434  |   |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. No lots have expired since the last publication of this report.
- 3. The next lots scheduled to expire will expire in June 2004.
- 4. We have not received any Mk 123 Mod 0 (MT30) conventional ordnance deficiencies or Els on the FA-18 aircraft since last publication of this report.
- 4. Rocket Motor Mk 109 Mod O, and Mod I
  - a. NSN: 1377-01-101-1443 (Mod 0), 1377-01-454-9321 (Mod 1)
  - b. DODIC: MF56 (Mod 0), SS67 (Mod 1)
  - c. Service life: 132 months (1 I years)
  - d. Rocket motor WUC: 97D47
  - e. Two per F/A-18
  - f. For NACES FA-18 Aircraft



Total Service life

| Lot No.                        | Lot quantity FA | A-18C    | FA-18D                                      | FA-18E |                       | units<br>installed | expiration<br>da te         |     |
|--------------------------------|-----------------|----------|---|--------|-----------------------|--------------------|-----------------------------|-----|
| UPC92B001-033<br>UPC92D001-034 | 48              | 7<br>14  | 12  | 0      | o<br>721 <sup>0</sup> | 19                 | February 2003<br>April 2003 |     |
| UPC92GOO 1-                    | 026 J           | uly 2003 |   |        | $\frac{0}{0}$ 035     | 5                  | 45 18 8                     |     |
| UPC92GOO 1-036                 | 343             | 10       |   | (      | 010 $\frac{0}{0}$     |                    | July 2003                   |     |
| UPC92KOO 1-038                 | 49              | 20       |   | (      | 626                   |                    | October 2003                |     |
| UPC93A001-039                  | 35              | 11       | 8   |        | 019                   |                    | January 2004                |     |
| UPC93C001-041                  | 48              | 22       | 10  |        | 0                     | 32                 | March 2004                  |     |
| UPC93JOO -042                  | 25              | 24       | 1   | 0      |                       | 25                 | September 2004              |     |
| TAC94A002-OOIA                 | 15              |          | 1   |        | 0                     | I                  | January 2005                |     |
| UPC94DOO1 -043                 | 60              | 34       | 20  | 3      | 0                     | 57                 | April 2005                  |     |
| UPC95DOO1-                     |                 |          | 0 0   | 44     | 29                    | 263                | 0 29                        |     |
| UPC95GOOl-<br>2006             | April 2006      |          | $\begin{array}{cc} 0 \\ 0 \\ 0 \end{array}$ | 15     |                       | 27                 | 251 27 Ju                   | ıly |
| UPC95HOO1-046                  | 25              |          | 222   |        |                       | 25                 | August 2006                 |     |
| UPC95L001-047                  | 20              |          |   | 00     |                       | 20                 | November 2006               |     |
| UPC96BOOl-048                  | 48              | 0        | 0   | 0      | 0                     | 0                  | February 2007               |     |
| UPC96COO1 -049                 | 8               | 5        | 0   | 1      | 2                     | 8                  | March 2007                  |     |
| UPC96GOO1-050                  | 195             | 7        | 0   | 28     | 32                    | 67                 | July 2007                   |     |
| UPC96E001-051                  | 18              | 16       |   |        | 0                     | 16                 | May 2007                    |     |
| UPC97B001-053                  | 18              | 10       | 5   | 2      | 0                     | 17                 | February 2008               |     |
| UPC97G001-054                  | 14              | 6        | 9   | O      | 0                     | 15                 | July 2008                   |     |
| UPC97G001-055                  | 6               | 4        |   | 0      | 0                     | 4                  | July 2008                   |     |
| UPC98B001-056                  | 54              | 2        | 18  | 18     | 16                    | 54                 | February 2009               |     |
| UPC99BOO1-057                  | 57              | 0        | 10  | 2      | 4                     | 16                 | February 2010               |     |
| IH-98D001-0012                 | 57              | 4        | 0   |        |                       | 4                  | April 2009                  |     |
| TAC99D001-0022                 | 250             | 14       | 14  | 12     | 10                    | 50                 | April 2010                  |     |
|                                | Lot             |          |   |        |                       | Total              | Service life                |     |
| Lot No.                        | quantity        | FA-18C   | FA-18D                                      | FA-18E | E FA-18F              | units<br>installed | expiration<br>date          |     |
| TACOOA001-003                  | 32 273          | 41       | 18  | 18     | 8                     | 85                 | January                     |     |
| TAC01H001-00                   | 52 109          | 34       | 6   | 0      | 6                     | 46                 | 2011<br>August 2012         |     |
| TAC01K001-00                   |                 | 16       | 1   | 0      | 0                     | 17                 | October 2012                |     |
|                                | - 00            | 10       | 1   | ~      | Ŭ                     |                    |                             |     |

|                        |     |     |    |    |     | Setting year |
|------------------------|-----|-----|----|----|-----|--------------|
| Total installed:       | 412 | 154 | 90 | 80 |     |              |
| Grand total installed: |     |     |    |    | 736 |              |
| II C Madani            |     |     |    |    |     |              |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. NSWC IHDIV has qualified and released a Mk 109 Mod 1 (SS67) Canopy Jettison Rocket Motor. This new unit can be used in all applications in which the Mod 0 unit is currently used. The Mod I is a one-for-one exchange with the Mk 109 Mod 0 (MF56) unit. Mod 0 units will still be issued until stock is exhausted.
- 3. The following lots have expired since the last publication of this report:

UPC91G001-031 July 2002
UPC90K001-026 October 2002
UPC90J001-027 September 2002
UPC91J001-032 September 2002
UPC90M001-028 December 2002

4. The following lot will expire within the next six months:

UPC92B001-033 February 2003

5. We have not received any Mk 109 Mod 0/1 (MF56/SS67) conventional ordnance deficiencies or Els on the FA-18 aircraft since last publication of this report.

### **OV-IOA AIRCRAFT**

## North American LW-3B Ejection Seats

1. Rocket Catapult Mk 12 Mod 1


a. NSN: 1377-00-276-2364

b. DODIC: MC77

c. Service life: 120 months (10 years)

d. Rocket motor WUC: 97D3D

e. Two per aircraft.



|                        | Lot      |        | Total              | Service life        |
|------------------------|----------|--------|--------------------|---------------------|
| Lot No.                | quantity | OV-IOA | units<br>installed | expira tion<br>date |
| IH-96KOO -007          | 10       | 6      | 6                  | October 2006        |
| IHOOC002-009           | 14       | O      | 0                  | March 2010          |
| IHM02B002-010          | 21       | O      |                    | February            |
| Total installed:       |          | 6      |                    | 2010                |
| Grand total installed: |          |        | 6                  |                     |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. We have increased the service life of the Mk 12 Mod 1 (MC77) Rocket Catapult from 96 months (8 years) to 120 months (10 years).
- 3. No lots have expired since the last publication of this report.
- 4. The next lot scheduled to expire will expire in October 2006.
- 5. We have not received any Mk 12 Mod I (MC77) conventional ordnance deficiencies or Els on the OV- 10 aircraft since the last publication of this report.

## QF-4N/S SERIES AIRCRAFT

## Martin-Baker Mk H-7 Ejection Seats

1. Underseat Rocket Motor Mk 92 Mod 1

a. NSN: 1377-01-036-8514

b. DODIC: M933

c. Service life: 192 months (16 years)

d. Rocket motor WUC: 97D3R

e. Two per aircraft (pilot and RIO).



|                | Lot      |       |       | Total              | Service life       |
|----------------|----------|-------|-------|--------------------|--------------------|
| Lot No.        | quantity | QF-4N | QF-4S | units<br>installed | expiration<br>date |
| IH-88JOO 1-005 | 306      | 5     | 43    | 48                 | September 2004     |

| WHEN SEVERAL SECTION OF THE SECTION |   |    | The second state of the second |
|---|---|----|--|
| Total installed:  | 5 | 43 |  |
| Grand total installed:  |   |    | 48   |
|   |   |    |  |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. No lots have expired since the last publication of this report,
- 3. The next lot scheduled to expire will expire in September 2004.
- 4. We have not received any Mk 92 Mod I (M933) conventional ordnance deficiencies or Els on the F-4 aircraft since the last publication of this report.

### S-3B AIRCRAFT


## Douglas ESCAPAC I E-I Ejection Seats

Rocket Catapult Mk 16 Mod 1a. NSN: 1377-01-040-9324

b. DODIC: MD 72

c. Service life: 156 months (13 years)d. Rocket motor WUC: 97D44

e. Four per aircraft.



|                        | Lot      |      | Total     | Service life   |
|------------------------|----------|------|-----------|----------------|
| Lot No.                | 200      | S-3B | units     | expiration     |
|                        | quantity |      | installed | date           |
| UPC90B004-026          | 279      | 27   | 27        | February 2003  |
| UPC90C004-027          | 279      | 66   | 66        | March 2003     |
| UPC90H004-028          | 69       | 24   | 4         | August 2003    |
| UPC93B004-031          | 14       | 7    | 7         | February 2006  |
| UPC97B001-032          | 7        |      | 1         | February 2010  |
| UPC99JOO 1-034         | 173      | 151  | 151       | September 2012 |
| UPC99LOO1-035          | 183      | 127  | 127       | November       |
| Total installed:       |          | 403  |           | 2012           |
| Grand total installed: |          |      | 403       |                |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. The following lots have expired since the last publication of this report:

| UPC89G003-021 | July 2002    |
|---------------|--------------|
| UPC89G003-022 | July 2002    |
| UPC89K003-023 | October 2002 |
| UPC89M004-025 | December     |
|               | 2002         |

- 3. The next lot scheduled to expire will expire in February 2003.
- 4. We have not received any Mk 16 Mod I (MD72) conventi07 nal ordnance deficiencies or Els on the S-3 aircraft since the last publication of this report.

#### Rocket Motor Mk Mod

a. NSN:

2. 82 0/1 (Man/Seat Separator, Left)

Mod 0 1377-00-119-2022/Mod 1 1377-01-412-6530

- b. DODIC: M928/MU76
- c. Service life: Mod 0: 192 months (16 years); Mod 1: 84 months (7 years)
- d. Rocket motor WUC: Mod 0 97D11/Mod 1 97D12
- e. Two per aircraft (copilot/TACCO).



|                               | Lot      | Lot  |           | Service life  |  |
|-------------------------------|----------|------|-----------|---------------|--|
| Lot No.                       |          | S-3B | Units     | expiration    |  |
|                               | quantity |      | Installed | date          |  |
| UPC93B001-021                 | 391      | 180  | 180       | February 2009 |  |
| UPC94C001-022                 | 25       | 12   | 12        | March 2010    |  |
| UPC99F001-003A2               | 10       | 4    | 4         | June 2006     |  |
| U PC00E001-0042               | 90       | 8    | 8         | May 2007      |  |
| 1 H MOO B002-006 <sup>2</sup> |          | 2    | 2         | February      |  |
| Total installed:              |          | 206  |           | 2008          |  |
| Grand total installed:        |          |      | 206       |               |  |

#### ILS Notes:

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. These lots of Mk 82 Mod 1 Man/Seat Separator Rocket Motors can be used in all applications in which the Mod 0 unit is currently being used. The Mod 1 is a one-for-one exchange with the Mk 82

Mod 0 0/1928) unit. Mod 0 units will still be issued until stock is exhausted.

- 3. Indian Head has changed its manufacturer's identification symbol from IH to 11-1M.
- 4. The following lot has expired since the last publication of this report:

#### Rocket Motor Mk Mod

#### a. NSN:

#### 3. Rocket Motor Mk 90 Mod 0/1 (Man/Seat Separator, Right)

a. NSN: Mod 0 1377-00-201-9554/Mod 1 1377-01-412-6462

b. DODIC: MC51/MU75


c. Service life: Mod 0: 192 months (16 years); Mod 1: 84 months (7 years)


d. Rocket motor WUC: Mod 0 97D3Q/Mod 1 97D3S

e. Two per aircraft (Pilot/SENSO).

UPC86K001-017

October 2002





7. We have not received any Mk 82 Mod 0 (M928) conventional ordnance deficiencies or Els on the S-3 aircraft since the last publication of this report.

| Service lif | Ee Lot No.             | Lot<br>quantity | S-3B | units<br>installed | expiration date | Total        |
|-------------|------------------------|-----------------|------|--------------------|-----------------|--------------|
| Notes:      |                        |                 |      |                    | A: 1 2002       |              |
|             | IH-96D001-0041         | 175             | 60   | 60                 | April 2003      | 1.These lots |
|             | IH-99H001-0051         | 106             | 95   | 95                 | August 2006     | of Mk 90     |
|             | IHM00B002-0061,2       | 110             | 21   | 21                 | February        | Mod 1        |
|             | Total installed:       |                 | 176  |                    | 2008            | Man/Seat     |
|             | Grand total installed: |                 |      | 176                |                 | Separator    |
|             |                        |                 |      |                    |                 | Rocket       |

Motors can be used in all applications in which the Mod 0 unit is currently being used. The Mod 1 is a one-for-one exchange with the Mk 90

Mod 0 (MU75) unit. Mod 0 units "ill still be issued until stock is exhausted.

- 2. Indian Head has changed its manufacturer's identification symbol from IH to IHM.
- 3. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).



### IHSP 03-486

a. NSN:

- 4. The following lot has expired since the last publication of this report: UPC86J001-004 September 2002
- 5. The next lot scheduled to expire "ill expire in April 2003.
- 6. We have increased the service life of the Mk 90 Mod 1 (MU75) Man/Seat Separator Rocket Motor from 84 months (7 years) to 108 months (9 years).
- 7. We have not received any Mk 90 Mod 0/1 (MC51 [MU75) conventional ordnance deficiencies or Els on the S-3 aircraft since the last publication of this report.

### ILS Notes:

Total Service life

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. The following lot has expired since the last publication of this report: UPC95E001-013 May 2002

### 4. Rocket Motor Mk 83 Mod 0 (Low Yaw Thruster)

a. NSN: 1377-00-119-2031

b. DODIC: M929

c. Service life: 84 months (7 years)d. Rocket motor WUC: 97D31e. Two per aircraft (pilot/copilot).



| Lot No.                | Lot      | S-3B | units     | expiration  | 3.      | The   |
|------------------------|----------|------|-----------|-------------|---------|-------|
|                        | Quantity |      | installed | date        | next    | lot   |
|                        | •        |      |           | uate        | schedul | ed to |
|                        |          |      |           | September   | expire  | will  |
| UPC97J002-014R         | 84       | 69   | 69        | 2004        | expire  | in    |
| ESDOOB001-0015         | 96       | 77   | 77        | February    | Septe   | ember |
|                        |          |      |           | 2007        | 2004.   |       |
| ESDOOH001-0025         | 119      | 56   | 56        | August 2007 |         |       |
| Total installed:       |          | 202  |           | _           | 4.      | We    |
| Grand total installed: |          |      | 202       |             | have    | not   |
|                        |          |      |           |             | receive | d any |

Mk 83 Mod 0 (M929) conventional ordnance deficiencies or Els on the S-3 aircraft since the last publication of this report.

5. We have qualified Pacific Scientific (ESD) as a manufacturer.

| S- | Lot No.                                 | Lot<br>quantity | S-3B | ACB 8 |
|----|---|-----------------|------|-------|
|    | TAC90MOO 1-005A                         | 213             |      | 38    |
|    | TAC93L001-006A                          | 107             | 1    | 71    |
|    | TAC95J001-007A                          | 86              | 1    | 82    |
|    | TAC96H001-001A                          | 286             | 8    | 209   |
|    | TACOOKOO 1-008                          | 96              | O    | О     |
|    | TACO 1 GOO 1-009                        | 96              |      |       |
|    | Total installed: Grand total installed: |                 | 11   | 400   |

5. Rocket Motor Mk 84 Mod 2 (Vernier)

a. NSN: 1377-01-199-8315

b. DODIC: MF57

c. Service life: 156 months (13 years)d. Rocket motor WUC: 97D3L

e. Four per aircraft.

3B Total

Service life

## ILS Notes:

1.Quantity per lot reported installed in CAD/PAD Traceability System (CATS).

2. The following lots have expired since the last publication of this report:

TAC89D001-003A April 2002 TAC89D001-004A April 2002

- 3. The next lot scheduled to expire will expire in December 2003.
- 4. We have not received any Mk 84 Mod 2 (MF57) conventional ordnance deficiencies or Els on the S-3 aircraft since the last publication of this report.

#### ILS Notes:

| Lot No.                            | Lot<br>Quantity |
|------------------------------------|-----------------|
|                                    | Quartery        |
| UPC96J002-014                      | 176             |
| UPC97D002-015                      | 100             |
| ESD99M001-0015                     | 121             |
| ESDOOK001-0025                     | 57              |
| ESD01F001-003A<br>Total installed: | 57              |
| Grand total installed:             |                 |
| Ciana total instanca.              |                 |

6. Rocket Motor Mk 85 Mod 0 (High Yaw Thruster)

a. NSN: 1377-00-119-2045

b. DODIC: M932

c. Service life: 84 months (7 years)

d. Rocket motor WUC: 97D43

e. Two per aircraft (SENSO/TACCO).



Total Service life

1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).

- 2. No lots have expired since the last publication of this report.
- 3. The next lot scheduled to expire will expire in September 2003.
- 4. We have not received any Mk 85 Mod 0 (M932) conventional ordnance deficiencies or Els on the S-3 aircraft since the last publication of this report.
- 5. We have qualified Pacific Scientific (ESD) as a manufacturer.

### T-2C SERIES AIRCRAFT

## North American LS-IA Ejection Seats

1. Rocket Catapult Mk 18 Mod O


a. NSN: 1377-00-250-0206

b. DODIC: M941

c. Service life: 120 months (10 years)

d. Two per aircraft

e. Rocket motor WUC: 97DIF



f. This device can also be utilized in the LS-I configuration seat if installed in pairs.

|                        | Lot      |      | Total              | Service life    |
|------------------------|----------|------|--------------------|-----------------|
| Lot No.                | quantity | T-2C | units<br>installed | expiration date |
| IH-95COO 1-015         | 144      | 133  | 133                | March 2005      |
| IH-96KOOl-016          | 56       | 52   | 52                 | October 2006    |
| _96K001-017            | 27       |      |                    | October 2006    |
| IH-99F002-018          | 46       | 2    | 2                  | June 2009       |
| IH-OOC002-019          | 31       | 4    | 4                  | March 2010      |
| IHM02B002-020          | 12       |      | 0                  | February        |
| Total installed:       |          | 192  |                    | 2012            |
| Grand total installed: |          |      | 192                |                 |

#### ILS Notes:

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. We have increased the service life for the Mk 18 Mod 0 (M941) Rocket Catapult from 96 months (8 years) to 120 months (10 years).
- 3. No lots have expired since the last publication of this report.
- 4. The next lot scheduled to expire will expire in March 2005.
- 5. We have not received any Mk 18 Mod 0 (M941) conventional ordnance deficiencies or Els on the T-2 aircraft since the last publication of this report.

### T-45A/C AIRCRAFT

## SJU-17/(V)5/A (F SJU-17/(V)6/A

(Forward seat)
(Aft seat)

1. Parachute Deployment Rocket Motor Mk 122 Mod 0

a. NSN: 1377-01-246-5279

b. DODIC: MT29

c. Service life: 84 months (7 years), 120 months (10 years)

d. Rocket motor WUC: 97D4A

e. Two per aircraft.



|                  |          |     | A THE STATE OF THE |           |             |
|------------------|----------|-----|--|-----------|-------------|
|                  | quantity |     |  | installed | date        |
| UPC94C003-0045   | 229      | 23  | 2  | 25        | March 2003  |
| MBA96C003-013    | 49       |     | 13   | 13        | March 2003  |
| UPC97H003-005    | 192      | 33  | 24   | 57        | August 2004 |
| MBA98J004-0144   | 300      | 48  | 33   | 81        | September   |
|                  |          |     |  |           | 2008        |
| MBA99J004-0164   | 206      | 15  | 29   | 44        | September   |
|                  |          |     |  |           | 2009        |
| MBAOOF004-0174   | 257      | 14  | 39   | 53        | June 2010   |
| UPC01E005-0014   | 270      | 4   |  | 4         | May 2011    |
| Total            |          | 137 |  |           |             |
| installed: Grand |          |     |  | 277       |             |
| total ILS Notes: |          |     |  |           |             |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. The following lot has expired since the last publication of this report: MBA95F002-010 June 2002
- 3. The next lot scheduled to expire »ill expire in March 2003.
- 4. We have increased the service life on all lots manufacture after 1998 from 84 months (7 years) to 120 months (10 years). All other lots will remain at 84 months (7 years).
- 5. Indian Head has extended the service life 24 months from 84 months (7years) to 108 months (9 vears for the following lot:

UPC94C003-004 March 2003

- 6. We have received a CODR on stirrups installed incorrectly on a Mk 122 Mod 0 (MT29) Parachute Deployment Rocket Motors (lot UPCO I E005-001). The stirrup links are making contact with the ejection seat main beam, thus making it impossible to connect the parachute withdrawal line. We have contacted the activity and requested photos. We will request that the unit be returned for an engineering investigation. We are pulling sample Condition Code "A" units from the same lot for inspection. The manufacturer has also been contacted and is in the process of verifying this condition with their x-rays.
- 2. Underseat Rocket Motor Mk 123 Mod 0

a. NSN: 1377-01-246-5280

b. DODIC: MT30

c. Service life: 180 months (15 years)

d. Rocket motor WUC: 97D4B

e. One per aircraft (Pilot Seat)

|                                | Lot      |       |        | Total              | Service life           |
|--------------------------------|----------|-------|--------|--------------------|------------------------|
| Lot No.                        | quantity | T-45A | T-45C  | units<br>installed | expiration<br>date     |
| MBA89F001-003<br>MBA89F001-005 | 31<br>16 | 0     | o<br>0 | 0                  | June 2004<br>June 2004 |
|                                |          |       | O      |                    |                        |
| MBA90H001-006                  | 35       | 3     |        | 3                  | August 2005            |
| MBA90HOOl-007                  | 6        | 1     |        | 1                  | August 2005            |
| MBA90KOO1 -008                 | 50       | 5     |        | 5                  | October 2005           |
| UPC90L001H001B                 | 17       | 3     | 0      | 3                  | November 2005          |
| MBA91JOO 1-009                 | 21       | .1    | 0      |                    | September 2006         |
| UPC91 KOO I H002A              | 14       | 1     | 0      |                    | October 2006           |
| MBA92COO 1-010                 | 10       | 5     |        | 5                  | March 2007             |
| UPC93E002H005                  | 27       |       | 0      |                    | May 2008               |
| MBA93F002-011                  | 54       | 29    | 4      | 33                 | June 2008              |
| UPC94B003H006                  | 80       | 16    | 4      | 20                 | February 2009          |
| MBA95C003-012                  | 236      | 6     | 7      | 13                 | March 2010             |
| MBA96C003-013                  | 71       | O     | 7      | 7                  | March 201 1            |
| MBA97G003-014                  | 33       | О     | 14     | 14                 | July 2012              |
| MBA98J003-017                  | 33       | O     | 9      | 9                  | September 2013         |
| MBA99H003-019                  | 53       | O     | 18     | 18                 | September 2014         |
| MBAO1A003-020                  | 47       | 0     | 9      | 9                  | January 2016           |
| MBAO I E003-024                | 22       | 0     | О      | 0                  | May 2016               |
| Total installed:               |          | 71    | 72     |                    |                        |
| Grand total                    |          |       |        | 143                |                        |

- 1. Quantity per lot reported installed in CAD/PAD Traceability System (CATS).
- 2. No lots have expired since the last publication of this report.
- 3. The next lots scheduled to expire will expire in June 2004.
- 4. We have not received any Mk 123 Mod 0 (MT30) conventional ordnance deficiencies or Els on the T-45 aircraft since the last publication of this report.
- 3. Underseat Rocket Motor Mk 124 Mod 0

a. NSN: 1377-01-246-5281

b. DODIC: MT31

c. Service life: 180 months (15 years)

d. Rocket motor WUC: 97D48

e. One per aircraft (Aft seat).



|                                | Lot      |       |       | Total              | Service life           |
|--------------------------------|----------|-------|-------|--------------------|------------------------|
| Lot No.                        | quantity | T-45A | T-45C | units<br>installed | expiration<br>date     |
| MBA89F001-004<br>MBA89F001-005 | 57<br>7  | 0     |       | 0                  | June 2004<br>September |
| MBA69F001-003                  | /        |       |       | U                  | 2004                   |
| MBA90H001-006                  | 68       | 3     | 0     | 3                  | August 2005            |
| MBA90HOO1 -007                 | 36       | 0     |       | 0                  | August 2005            |
| MBA90K001-008                  | 91       | 4     | 0     | 4                  | October 2005           |
| UPC90L001H001B                 | 36       | 2     |       | 2                  | November 2005          |
| MBA91J001-009                  | 34       | 4     | 0     | 4                  | September 2006         |
| UPC91KOOlH002A                 | 29       | 2     | О     | 2                  | October 2006           |
| UPC91KOO 1 H003                | 6        |       |       |                    | October 2006           |
| MBA92C001-010                  | 27       | 5     |       | 5                  | March 2007             |
| UPC93D002H004                  | 62       | 2     | 0     | 2                  | April 2008             |
| MBA93F002-011                  | 104      | 20    | 0     | 20                 | June 2008              |
| UPC94C003H005                  | 142      | 19    | 5     | 24                 | March 2009             |
| MBA95C003-012                  | 165      | 4     | 4     | 8                  | March 2010             |
| MBA96C003-013                  | 71       | 1     | 7     | 8                  | March 2011             |
| MBA97G003-014                  | 70       | 5     | 16    | 21                 | July 2012              |
| MBA98J003-017                  | 66       | 0     | 16    | 16                 | September 2013         |
| MBA99H003-019                  | 84       | 0     | 16    | 16                 | August 2014            |
| MBAO1A003-020                  | 76       |       | 7     | 7                  | January 2016           |
| MBA01E003-024                  | 37       |       | O     | 0                  | May 2016               |
| Total installed:               |          | 71    | 71    |                    |                        |
| Grand total installed:         |          |       |       | 142                |                        |

ILS Notes:

 $<sup>1\,.\</sup>quad Quantity\ per\ lot\ reported\ installed\ in\ CAD/PAD\ Traceability\ System\ (CATS).$ 

- 2. No lots have expired since the last publication of this report.
- 3. The next lot scheduled to expire will expire in June 2004.
- 4. We have not received any Mk 123 Mod 0 (MT30) conventional ordnance deficiencies or Els on the T-45 aircraft since the last publication of this report.

#### **PAD SUMMARY**

The following section summarizes the service life, identification data, and total installed assets for each PAD device. Table I contains the PAD device, service life, and operating temperature range. Table I is based on the information current in NAVAIR 1 1-100-I . I-CD at the time this report was printed; NAVAIR 1 1-100-I .1 -CD is the official source for the service life of PAD devices. Table II identifies each PAD device by DODIC, propellant type, explosive weight, manufacturer, NAVAIR part number, applicable specification (procurement description), applicable aircraft, and aircraft manufacturer. Table III presents the total installed assets for the PAD devices, and Table IV provides this information by lot numbers.

Table 1. Service Life Listing<sup>a</sup>

| 1 aute   | 1. Service Life i      | Listing            |
|--|------------------------|--------------------|
| Device   | Service life<br>(mo)   | Operating range    |
|  | Rocket Catapult        |                    |
| Mk 12 Mod 1120—40 to<br>Mk 16 Mod 1156—40 to 160 | 165                    |                    |
| Mk 18 Mod O120—40 to                             | 165 CKU-               | 7A120—40 to 160    |
| I  | Man/Seat Separato      | rs                 |
| Mk 82 Mod O192—40 to                             | 160                    |                    |
| Mk 82 Mod 1108—40 to                             | 160                    |                    |
| Mk 90 Mod O192—40 to                             | 160 Mk 90              | Mod 1108-40 to 160 |
|  | Yaw Thrusters          | '                  |
| Mk 83 Mod O                                      | 84                     | —40 to 160         |
| Mk 85 Mod O                                      | 84                     | -40 to 160         |
|  | Vernier Rocket         |                    |
| Mk 84 Mod 2                                      | 156                    | _40 to 160         |
|  | Seatback Rocket        |                    |
| Mk 79 Mod 1                                      | 132                    | _40 to 160         |
| Mk 79 Mod 2                                      | 132                    | -40 to 160         |
| WORL   | D/Drogue Release Asset | mbly               |
| Mk 113 Mod O                                     | 96                     | -40 to 160         |
| Mk 113 Mod O                                     | 96                     | -40 to 160         |
|  | Catapult Cartridge     |                    |

Mk 205 Mod 1 96 -65 to 165 Mk 205 Mod 2 96 -65 to 165

See footnote at end of table.

### Table I—Continued

| Device   | Service life<br>(mo)                         | Operatin range                                      |
|--|--|---|
|  | Underseat Rocket Me                          | otor  |
| Mk 74175 Mod O240-40 to<br>160 Mk 86/87/88 Mod<br>Mod 1240—40 to 160 Mk 92<br>O204—40 to 160 | 160 Mk 74175<br>O240—40 to<br>Mod 1192-40 to | Mod 1240—40 to<br>160 Mk 86/87/88<br>160 Mk 100 Mod |
| Mk 101 Mod O204—40 to<br>Mk 123 Mod O180-65 to<br>165  | 160<br>165 Mk 124                            | Mod O180-65 to                                      |
| Canop<br>Motor   | y Remover Rocket                             | 1   |
| Mk 109 Mod O   | 132  | -65 to<br>165                                       |
| Mk 109 Mod 1   | 132<br>cket Motor Divergen                   | -65 to<br>ce 165                                    |
| Mk 121 Mod O Parachut Motor  | -40 to                                       |   |
| Mk 122 Mod O   | -65 to 165                                   |   |
| a  |  |   |

Official listing maintained in NAVAR 11-100-1.1-CD.

## Table II. Propellant-Actuated Devices Summary

[As of 31 January 2003]

|                  |       |            |                             | [· ··· ·     |                      | - ,           |                |  |
|------------------|-------|------------|-----------------------------|--------------|----------------------|---------------|----------------|--|
|                  | DODIC | Propellant | Explosive<br>weight<br>(lb) | Manufacturer | Part number          | Specification | Aircraft       | Aircraft manufacturer                    |
|                  |       |            |                             | Roc          | ket Catapults (Navy) |               |                |  |
| Mk 12 Mod        | MC77  |            |                             |              | 1CTPB5.00Indian      | HeadNAVAR     | OV-10A         | 709ASIOOMIL-DTL-<br>85097/9A(AS)Rockwell |
| International    | MD72  | Corp.      |                             |              | PIN                  | 31276         | S-3A,<br>TA-4J |  |
| Mk 16 Mod        | M941  |            |                             |              | 1CTPB7.00Indian      | HeadNAVAIR    | T-2            | 736AS300MIL-DTL-<br>85097/1BLockheed     |
| California Corp. |       |            |                             |              |                      |               |                |  |

Mk 18 ModOCTPB5.00Indian HeadNAVAR 707AS100MIL-DTL-85097/12(AS)Rockwell International Corp.

 ${\sf UPCO}(1000\text{-}6) {\sf McDonnell\ Douglas}$ 

Rocket Catapults (Air Force)

CKU-7A MS-15 CTPB 6.40 Indian Head FI 1820361 MIL-C-48568 F-5E Northrup Corp. UPCO

T-38

Rocket Motors

| Mk 74 MOd<br>4904093MIL-A-<br>Aerospace Corp.<br>(Pilot)UPCO(MB- | Doubl        | 300- | OM572 Double | Base6.40Martin- | F-14A<br>F-14B<br>NF-14A<br>NF-14B<br>F-14A/B | BakerNAVAR<br>85097/8B(AS)Grumman |
|--|--------------|------|--------------|-----------------|---|-----------------------------------|
| Mk 74 Mod  | Doubl        |      | 1M572 Double | Base6.40Indian  | F-14A/B                                       | Head759AS130MIL-A-                |
| Aerospace Corp.<br>(Pilot)                                       | Doubl        |      |              |                 | F-14  | 85097/8B(AS)Grumman               |
| Mk 75 Mod  | СТРВ         |      |              |                 | AV-8B<br>NAV-8B<br>TAV-8B                     |                                   |
|  | НТРВ<br>НТРВ |      |              |                 | AV-8B<br>NAV-8B<br>TAV-8B                     |                                   |
|  | СТРВ         |      |              |                 | S-3B,<br>ES-3A<br>A-4F/M,<br>TA-4J            |                                   |
|  | СТРВ         |      |              |                 | S-3B<br>ES-3A                                 |                                   |
|  | СТРВ         |      |              |                 | S-3B<br>ES-3A                                 |                                   |
|  | СТРВ         |      |              |                 | S-3B<br>ES-3A                                 |                                   |
|  | Doubl        |      |              |                 | EA-6B   |                                   |
|  | Doubl        |      |              |                 | EA-6B   |                                   |
|  | Doubl        |      |              |                 | EA-6B   |                                   |
|  | Doubl        |      |              |                 | EA-6B   |                                   |
|  |              |      |              | O M573          |   | Double                            |

Base 6.40 Martin-BakerNAVAIR 4904094MIL-A-85097/8/B(AS)Grumman Aerospace Corp. (NFO)UPCO(MB-300-1206)

Mk 75 Mod 1M573 (NFO) Double Base6.40Indian Head759AS140MIL-A-85097/8B(AS)Grumman Aerospace Corp.

 $\label{lem:mk79} \mbox{ Mod 1 (SBR)MF212.70Indian HeadNAVAIR 672AS200MIL-A-85097/3C(AS)Hawker-Siddeley/ McDonnell TalleyPIN 50579-5$ 

Mk 79 Mod 2 (SBRMF212.70Indian HeadNAVAIR 672AS200MIL-A-85097/3C(AS)Hawker-Siddeley/ McDonnell TalleyPIN 50579-7

 $\label{thm:mass} \mbox{Mk 82 Mod OM9280.} 60 \mbox{UPCONAVAIR 944ASIOOMIL-DTL-85097/5B(OS)Lockheed California Corp. } (\mbox{Man/Seat1033-2 (UPC)McDonnell Douglas Separator, Left)}$ 

Mk 83 Mod OM9290.05UPCONAVAIR 946ASIOOMIL-DTL-85097/6A (AS) s-3B (Low Yaw Thruster)Pacific1105-1 (UPC) Scientific

Lockheed California Corp.

 $\label{localized-model} {\it Mk\,84\,Mod\,2MF571.12} \\ {\it TalleyNAVAIR\,503AS200MIL-DTL-85097/7D(OS)} \\ {\it Lockheed\,California\,Corp.} \\ {\it (Vernier\,Rocket)UPCO(50436-9)} \\ {\it (Vernier\,Rocket)UPCO(5046-9)} \\ {\it (Vernier\,Rocket)UPCO(5046$ 

(1340-2)

 $\label{localization} \mbox{Mk 85 Mod OM932} 0.10 \mbox{UPCONAVAIR 989ASIOOMIL-DTL-85097/6A(AS)Lockheed California Corp. (High Yaw Thruster) Pacific 1136-1 (UPC) Scientific$ 

Mk 86 Mod OM938 Double Base6.40Martin-BakerNAVAIR 4904171MIL-A-85097/8B(AS)Grumman Aerospace Corp. (PilotiECMO-3)UPCO(MB-200-610)

Mk 86 Mod 1M938 Double Base6.40Indian Head759AS170MIL-A-85097/8B(AS)Grumman Aerospace Corp.

(PiloUECMO-3)

Mk 87 Mod O M939 Double Base 6.40 Martin-Baker NAVAIR 4904172 MIL-A-85097/8B(AS) Grumman Aerospace Corp.

(ECMO-I)UPCO(MB-200-612)

Mk 87 Mod 1M939 Double Base6.40Indian Head759AS180MIL-A-85097/8B(AS)Grumman Aerospace Corp.

(ECMO-I)

## Table II—Continued [As of 31 January 2003]

| Device                   | DODIC | Propellant  | Explosive<br>weight<br>(lb) | Manufacturer            | Part number                         | Specification          | Aircraft                  | Aircraft manufacturer                   |
|--------------------------|-------|-------------|-----------------------------|-------------------------|-------------------------------------|------------------------|---------------------------|---|
| Mk 88 Mod O<br>(ECMO-2)  | M940  |             | 6.40                        | Martin-Baker<br>UPCO    |                                     | MIL-A-85097/8B(AS)     | EA-6B                     | Grumman Aerospace Corp.                 |
| Mk 88 Mod 1<br>(ECMO-2)  | M940  | Double Base | 640                         | Indian Head             | NAVAR 4904173<br>(MB-200-614)       | MIL-A-85097/8B(AS)     | EA-6B                     |   |
| Mk 90 Mod O<br>(Man/Seat | MC51  | Double Base | 0.60                        | UPCO                    | 759190                              | MIL-DTL-85097/5B(OS)   | s-3B<br>ES-3A             | Grumman Aerospace Corp.                 |
| Separator, Right)        |       | СТРВ        |                             |                         | NAVAR 970ASIOO                      |                        |                           | Lockheed California Corp.               |
| Mk 90 Mod 1              | MU75  |             | 0.60                        | Indian Head             | 1033-3 (UPC)                        | MIL-DTL-85097/5B(OS)   | S-3B<br>ES-3A             | Lockheed California Corp.               |
| Mk 92 Mod 1              | M933  | СТРВ        | 6.20                        | Indian Head             | NAVAR 970AS201                      | MIL-A-85097/8BAS)      | Q F-4N                    | Lockiecu camornia corp.                 |
| Mk 100 Mod O             | MD68  | Double Base | 6.60                        | Martin-Baker            | NAVAR 1175ASIOO                     | MIL-A-85097/8B         | FA-18A<br>FA- 18B         | McDonnell Douglas                       |
|                          |       | Double Base |                             |                         | MBEU-69025-2<br>NAVAR 1176AS200     |                        | F 18C                     | McDonnell Douglas                       |
| Mk 101 Mod O             | MD69  |             | 6.60                        | Martin-Baker            |                                     | MIL-A-85097/8B         | FA-<br>180                |   |
| Mk 109 Mod O             | MF56  | Double Base | 10                          | Indian Head<br>Talley   | MBEU-69028-2<br>NAVAR 1176AS300     | MIL-DTL-85097/13C      | FA-<br>18B                | McDonnell Douglas                       |
|                          |       | СТРВ        |                             | UPCO                    | P/N-50656-5<br>NAVAR 1507ASIOO      |                        | FA-<br>18D                | McDonnell Douglas (Boeing)              |
| Mk 109 Mod 1             | SS67  |             | 1.0                         | Indian Head             |                                     | MI-DTL-85097/13A(OS)   | 18A<br>FA- 18B<br>FA-     |   |
|                          |       |             |                             | UPCO                    | 1507AS201                           |                        | 180<br>FA-<br>18E         | McDonnell Douglas (Boeing)              |
| Mk 113 Mod 0/1           | MG67  |             | 0.288                       | UPCO                    |                                     | MIL-DTL-85097/1 ID(OS) | FA_<br>18F                |   |
| Mk 121 Mod O             | MT28  | СТРВ        | 0.22                        | Talley                  | NAVAR 673AS200<br>P/N 50885-1       | MIL-A-85097/15         | F 18A                     | Hawker-Siddeley/ McDonnell<br>Douglas   |
| (Divergence)             | MT29  | СТРВ        | 0.5                         | UPCO Pacific Scientific | P/N 1163-3 (UPC)<br>NAVAR 673AS300  | MIL-A-85097/16         | F 18B F<br>18C<br>FA- 18D | McDonnell Douglas                       |
| Mk 122 Mod O             |       | Double Base |                             | Martin-Baker            | 2-102370-2 (Pac Sci)<br>MBEU-146190 |                        | FA- 18E<br>FA- 18F        | McDonnell Douglas                       |
|                          |       |             |                             | UPCO                    |                                     |                        | AV-8B<br>TAV-8B           | British Aerospace/ McDonnell            |
| Mk 123 Mod O             | MT30  | 2 11 2      | 6.8                         |                         |                                     | MIL-A-85097/17         | TAV-8B                    | Douglas<br>Grumman Aerospace Corp.      |
|                          |       | Double Base |                             | Martin-Baker<br>UPCO    | MBEU-142801                         |                        | FA-18C                    | McDonnell Douglas                       |
|                          | MT31  |             | 6.8                         | 01 00                   |                                     | MIL-A-85097/17         | FA-<br>180.               |   |
| Mk 124 Mod O             |       | Double Base |                             |                         |                                     |                        | FA- 18E                   | Grumman Aerospace Corp.                 |
|                          |       |             |                             | Martin-Baker<br>UPCO    | MBEU-142802                         |                        | F 18F<br>T-45 A           | McDonnell Douglas                       |
|                          | XW36  |             | 0.25                        |                         |                                     | MIL-DTL-85097/2E       | T-45C<br>F_14 D           | British Aerospace/ McDonnell<br>Douglas |
| Mk 205 Mod 1/2           |       | СТРВ        |                             |                         |                                     |                        | FA-18C<br>F 18D           | Grumman Aerospace Corp.                 |
|                          |       | HTPB        |                             | Talley                  | NAVAR 772AS400<br>PIN 5913-5        |                        | FA_                       | Hawker-Siddeley/ McDonnell<br>Douglas   |

IHSP 03-486

|   |  |  |  | T-45C            |  |
|---|--|--|--|------------------|--|
|   |  |  |  | F_ 140           |  |
|   |  |  |  |                  |  |
|   |  |  |  | FA- 180<br>FA- 1 |  |
|   |  |  |  | BE               |  |
|   |  |  |  | FA-1             |  |
|   |  |  |  | BF               |  |
|   |  |  |  | T-45 A T-        |  |
|   |  |  |  | 45C<br>F_14 D    |  |
|   |  |  |  |                  |  |
|   |  |  |  | AV-8B            |  |
|   |  |  |  | TAV-8B           |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
|   |  |  |  |                  |  |
| - |  |  |  |                  |  |

## Table III. Total Installed Assets [As of 31 January 2003]

| PAD Device | DODIC | Aircraft | Quantity<br>installed (ea) | Total quantity installed (ea) |
|------------|-------|----------|----------------------------|-------------------------------|
|------------|-------|----------|----------------------------|-------------------------------|

## IHSP 03-486

|                            |              | ov-10           | 6       | 6          |
|----------------------------|--------------|-----------------|---------|------------|
| Mk 12 Mod 1                | MC77         |                 | 14      | 14<br>403  |
| Mk 16 Mod 1                | MD72         | S-3B            | 403     | 403<br>417 |
|                            |              |                 |         | 102        |
|                            | NAO 41       | TQC             | 192     | 192        |
| Mk 18 Mod O                | M941         | F-14A           | 25      | 79         |
| Mk 74 Mod O                | M572         | F-14B F-<br>14A | 54      |            |
| Mk 74 Mod 1                | M572         | F-14B           | 12<br>8 | 20<br>99   |
| Will 7 Tillog 1            |              |                 |         | 33         |
|                            | M573         | F-14A           | 25      | 77         |
| Mk 75 Mod O                | IVIS/S       | F-14B F-<br>14A | 52      |            |
| Mk 75 Mod 1                | M573         | F-14B           | 9       | 18<br>95   |
|                            |              |                 | 9       |            |
| Mk 82 Mod O                | M928         | TA4J            | 10      | 10<br>192  |
| WIN OZ WIOG O              |              | S-3B            | 192     | 202        |
| MK 82 Mod 1                | MU76         | TA-4J S-        |         | 14         |
|                            |              | 3B              | 14      | 216        |
| Mk 83 Mod O                | M929         | S-3B            | 202     | 202        |
|                            | 14022        |                 | 202     | 215        |
| Mk 85 Mod O                | M932         | S-3B            | 215     | 213        |
| Mk 92 Mod 1                | M933         | QF-4N           | 5       |            |
|                            |              | QF-4s           | 43      | 48         |
| Mk 86 Mod O                | M938         |                 |         | 189        |
| Mk 86 Mod 1                | M938         | EA-6B<br>EA-6 B | 189     | 43         |
|                            |              | Littob          | 43      | 232        |
| Mk 87 Mod O<br>Mk 87 Mod 1 | M939<br>M939 | EA-6B           | 110     | 110        |
|                            | 141555       | EA-6B           | 6       | 6<br>107   |
| Mk 88 Mod O                | M940         |                 |         |            |
| Mk 88 Mod 1                | M940         | EA-6B           | 103     | 103<br>13  |
|                            |              | EA-6B           | 13      | 116        |
|                            | I            |                 |         |            |

## Table III—Continued [As of 31 January 2003]

| PAD Device | DODIC | Aircraft | Quantity<br>installed<br>(ea) | Total<br>quantity<br>installed<br>(ea) |
|------------|-------|----------|-------------------------------|--|
|------------|-------|----------|-------------------------------|--|

IHSP 03-486

| Mk 90 Mod 1       | MU75<br>MU75 | S-3B         | 181   |        |
|-------------------|--------------|--------------|-------|--------|
|                   |              |              | 101   |        |
| Mk 100 Mod O      | MD68         | F 18A FA-18B |       | 181    |
|                   |              | FA- 18 C     | 181   | 181    |
|                   |              | FA-18D       | 32    | 101    |
|                   |              |              | 154   |        |
| NAI: 101 NA - d O | MD69         | FA- 18B      | 45    |        |
| Mk 101 Mod O      | WIDOS        | FA- 181)     |       |        |
|                   |              |              | 33    | 412    |
|                   | MF21         | AV-8B        | 51    |        |
| Mk 79 Mod 1       | 1011 21      | NAV-8B       |       |        |
|                   |              | TAV-8B       | 248   | 84     |
|                   |              |              | 2 - 2 |        |
|                   | MF56         | FA- 18A      | 62    |        |
| Mk 109 Mod O      | 1011 30      | FA-          | 02    |        |
| Non-NACES         |              | 18B          |       | 312    |
|                   | SS67         | FA-          | 139   |        |
| Mk 109 Mod 1      | 3307         | 18C          | 28    |        |
| Non-NACES         |              | FA-<br>18D   | 176   |        |
|                   |              | FA-          | 56    | 399    |
|                   |              | 18A          | 158   |        |
|                   | MF56         | FA-          | 22    |        |
| MK 109 Mod O      |              | 18B          | 101   | 318    |
| NACES             |              | FA-18C       | 37    | 717    |
|                   | SS67         | FA- 181)     |       |        |
| Mk 109 Mod 1      |              |              | 310   |        |
| NACES             |              | FA- 18C      | 115   |        |
|                   |              | FA- 18 D     | 59    | 540    |
|                   |              | FA- 18E FA-  | 56    |        |
|                   | N4557        | 18F          | 109   |        |
|                   | MF57         | FA-18C FA-   | 39    | 202    |
| Mk 84 Mod 2       |              | 18D          | 30    | 742    |
|                   |              | FA- 18 E     |       | 1 ,459 |
|                   |              | FA- 18F      |       |        |
|                   |              |              | 411   | 411    |
|                   |              | S-3B         | 400   |        |
|                   |              | Repaired     | 11    |        |
|                   |              | Not repaired |       |        |

## III—Continued January 2003]

Table [As of 30

|                  | [AS O  | 1 30             |                       |                          |
|------------------|--------|------------------|-----------------------|--------------------------|
| PAD Device       | DODIC  | Aircraft         | Quantity<br>installed | Total quantity installed |
| Mk 113 Mod 0/1   | MG67   | AV-8B            | 129                   |                          |
| ,                |        | NAV-8B<br>TAV-8B | 29                    |                          |
| CKU-7A           | MS15   |                  | 32                    |                          |
|                  |        |                  | 8                     |                          |
|                  |        | T-38A            | 18                    | 167                      |
| Mk 121 Mod O     | MT28   | TAV-8B           | 54                    |                          |
| Mk 122 Mod O     | MT29   | F 14D            | 54                    |                          |
| 222              | 141123 | F_ 14D           | 86                    | 58                       |
|                  |        | FA-18C<br>FA-18D | 206                   |                          |
|                  |        |                  | 155                   | 54                       |
|                  |        | FA-18F           | 51                    | 86                       |
|                  |        | T-45A            | 92                    | 00                       |
|                  |        | T-45C            | 137                   |                          |
| Mk 123 Mod O     | MT30   |                  | 140                   | 504                      |
| WIK 125 WIOG 6   | 101130 | F_14D            |                       | 277                      |
|                  |        | F 18D            |                       | 867                      |
|                  |        | FA- 18F          | 38                    | 807                      |
|                  |        | T-45A T-         | 92                    |                          |
|                  |        | 45C              | 45                    | 38                       |
| Mk 124 Mod O     | MT31   |                  | 71                    | 137                      |
|                  |        | F_ 14D           | 72                    |                          |
|                  |        | FA- 18C          |                       | 143                      |
|                  |        | FA- 18C          | 46                    | 318                      |
|                  |        | 18D              | 249                   | 46                       |
|                  |        | FA-              | 92                    |                          |
| Mk 205 Mod 1     | XW36   | 18E              | 49                    |                          |
| IVIK 205 IVIOU I | XVV30  | FA-18F           | 44                    | 434                      |
|                  | ,,,,,  | T-45A            | 71                    |                          |
| Mk 205 Mod 2     | XW36   | T-45C            | 71                    | 142                      |
|                  |        |                  |                       | 622                      |
|                  |        | AV-8B NAV-<br>8B | 47                    |                          |
|                  |        | TAV-8B           | 20                    | 126                      |
|                  |        | AV-8B            | 65                    |                          |
|                  |        | NAV-8B           | 1                     | 53                       |
|                  |        | TAV-8B           | 6                     | 179                      |
|                  |        |                  |                       | 1,3                      |

Table IV. Total Reported Installed By Lot Number

[As of 30 January 2003]

|       | Γ               | 1                | [AS OT          | 30 January 2003]      |                    |                                |                  |
|-------|-----------------|------------------|-----------------|-----------------------|--------------------|--------------------------------|------------------|
| DODIC | Model           | Lot No.          | Lot<br>quantity | Quantity<br>installed | Total<br>installed | Expiration date                | Aircraft type(s) |
| rac77 | Mk 12 Mod 1     | III 06W004 007   | 40              | 6                     |                    | October 2006                   |                  |
| 14677 | IVIK 12 IVIOG 1 | IH-96K001-007    | 10              | 6                     |                    | March 2010                     |                  |
|       |                 | IH-OOC002-009    | 14              |                       |                    | February 2012                  |                  |
|       |                 | IHM02B002-020    | 21              |                       |                    | 1 Columny 2012                 |                  |
| MD72  | Mk 16 Mod 1     |                  |                 | 30                    |                    |                                |                  |
|       |                 | UPC90B003-026    | 279             | 70                    |                    | February 2003                  |                  |
|       |                 | UPC90C003-027    | 279             | 24                    |                    | March 2003                     |                  |
|       |                 | UPC90H003-028    | 69              | 9                     | 6                  | August 2003                    |                  |
|       |                 | UPC93B004-031    | 14              |                       |                    | February 2006                  | ov-10            |
|       |                 | UPC97B001-032    | 7               | 1                     |                    | February 2010                  |                  |
|       |                 | UPC99J001-034    | 173             | 151                   |                    | September 2012                 |                  |
|       |                 | UPC99L001-035    | 183             | 127                   |                    | November 2012<br>March 2015    |                  |
| M941  | Mk 18 Mod O     | UPC02C001-036    | 172             |                       |                    | Watch 2013                     |                  |
|       |                 |                  | 1/2             |                       |                    |                                |                  |
|       |                 | IH-95C001-015    |                 | 133                   | 442                | March 2005                     |                  |
|       |                 | IH-96K001-016    | 144             | 52                    | 443                | October 2006                   |                  |
|       |                 | IH-96K001-017    | 56              | 1                     |                    | October 2006                   | TA-4J/S-3B       |
|       |                 | IH-99F002-018    | 27              | 2                     |                    | June 2009                      |                  |
| M572  | Mk 74 Mod O     | IH-OOC002-019    | 46              | 4                     |                    | March 2010                     |                  |
|       |                 | IHM02B002-020    | 31              |                       |                    | February 2012                  |                  |
|       |                 |                  | 12              |                       |                    |                                |                  |
|       |                 | MBA84B001-013    |                 | 6                     | 192                | February 2004                  |                  |
|       |                 | MBA85E001-015    | 24              | 6                     |                    | May 2005                       | T-2C             |
| M572  | Mk 74 Mod 1     | MBA85E001-017    | 18              | 13                    |                    | May 2005                       |                  |
|       |                 | MBA85H001-018    | 18              | 34                    |                    | August 2005                    |                  |
|       |                 | UPC86J001-001A]B | 126             |                       |                    | August 2006                    |                  |
|       |                 | MBA88B001-024    | 25              | 4                     |                    | February 2008                  |                  |
|       |                 | MBA88H001-026    | 15              | 9                     | 79                 | August 2008                    |                  |
| M573  | Mk 75 Mod O     | IH-94L002-003A   | 6               | 3                     |                    | November 2014<br>November 2014 |                  |
|       |                 | IH-94L002-004    |                 | 12                    | 20                 | November 2014                  |                  |
|       |                 | IH-94L002-005    | 23              | 8                     | 99                 |                                |                  |
|       |                 | 111 3 12002 003  | 15              |                       |                    |                                | F-14AJF-14B      |
|       |                 |                  | 38              |                       |                    | February 2004                  |                  |
| M573  | Mk 75 Mod 1     | MBA84B001-013    |                 | _                     |                    | May 2005                       |                  |
|       |                 | MBA85E001-015    | 24              | 4                     |                    | May 2005                       |                  |
|       |                 | MBA85E001-017    | 24              | 9                     |                    | August 2005                    |                  |
|       |                 | MBA85H001-018    | 18              | 13                    |                    | August 2006                    |                  |
| M928  | Mk 82 Mod O     | UPC86J001-001AJB | 18              | 29                    | 77                 | February 2008                  |                  |
| MU76  | MK 82 Mod 1     | MBA88B001-024    | 134             | 4                     |                    | August 2008                    |                  |
|       |                 | MBA88H001-026    | 25              | 8                     | 18                 | November 2014                  |                  |
|       |                 | IH-94L002-003A   | 15              | 2                     | 95                 | November 2014                  |                  |
|       |                 | IH-94L002-004    | 5               |                       |                    | November 2014                  | F_ 14A/F-14B     |
|       |                 | IH-94L002-005    | 22              | 12                    | 202                |                                |                  |
|       |                 |                  | 12              | 6                     | 202                | February 2009                  |                  |
|       |                 | UPC93B001-021    | 34              |                       |                    | March 2010                     |                  |
|       |                 | UPC94C001-021    | ]               | 100                   | 14                 | June 2008                      |                  |
|       |                 | 0. 0340001-022   |                 | 190                   | 216                | May 2009                       | TA-4J/S-3B       |

| <br>  |                |     | 30 January 2003] |   |                  |   |
|-------|----------------|-----|------------------|---|------------------|---|
|       | UPC99F001-003A | 391 | 12               |   | February 2010    |   |
|       | UPCOOEOOI -004 | 25  |                  |   | . 551 441 , 2510 |   |
|       | 'HMOOBû02-006  | 25  | 4                |   |                  |   |
|       | HIVIOOBUUZ-006 | 10  |                  |   |                  |   |
|       |                | 90  | 2                |   |                  |   |
|       |                | 14  |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
|       |                |     |                  |   |                  |   |
| I<br> | 1              | I   | I                | 1 |                  | 1 |

## Table [As of

| DODIC | Model | Lot No. | Lot<br>quantity | Quantity<br>installed | Total<br>Installed | Expired date | Aircraft type |
|-------|-------|---------|-----------------|-----------------------|--------------------|--------------|---------------|
|-------|-------|---------|-----------------|-----------------------|--------------------|--------------|---------------|

|       |                |                                    |     |    |     |                           | 11151 05 400 |
|-------|----------------|------------------------------------|-----|----|-----|---------------------------|--------------|
| M929  | Mk 83 Mod O    |                                    | 84  | 69 |     |                           |              |
|       |                | UPC97J002-014R                     | 96  | 77 |     | September 2004            |              |
|       |                | ESDOOBOOI-OOI                      | 119 | 56 |     | February 2007             |              |
|       |                | ESDOOH001-002                      | 113 | 30 |     | -                         |              |
|       |                |                                    |     |    |     | August 2007               |              |
| M932  | Mk 85 Mod O    |                                    | 476 |    |     |                           |              |
|       |                | UPC96J002-014                      | 176 | 93 |     |                           |              |
|       |                | UPC97D002-015                      | 100 | 64 |     | September 2003            |              |
|       |                | ESD99M001-001                      | 121 | 56 |     | April 2004                |              |
|       |                | ESDOOKOOI -002                     | 121 | 2  |     | December 2006             |              |
| 14022 |                | ESD01F001-003A                     | 57  |    |     | December 2006             |              |
| M933  | Mk 92 Mod 1    |                                    |     |    |     | June 2008                 |              |
|       |                | IH-88J001-005                      | 306 | 48 | 202 |                           |              |
| M938  | Mk 86 Mod O    | 111 003001 003                     |     |    |     | September 2004            | S-3B         |
|       |                |                                    | 12  | 9  |     | 50pto50: 200 :            |              |
|       |                | MBA84B001-013                      | 12  | 13 |     | Fabruary 2004             |              |
|       |                | MBA85E001-015                      | 16  | 21 |     | February 2004<br>May 2005 |              |
|       |                | MBA85E001-017                      | 24  | 30 |     | May 2005                  |              |
|       |                | MBA85H001-018                      | 32  | 20 | 215 | August 2005               |              |
|       |                | MBA86J001-021                      | 24  | 20 | 213 | September 2006            | 200          |
|       |                | UPC86J001-001A/B                   | 37  |    | 48  | -                         | SOB          |
|       |                | MBA86J001 H020                     | 43  | 43 | 48  | September 2006            |              |
|       |                |                                    | 7   | 2  |     | September 2006            | QF-4N/QF-4S  |
| M939  | Mk 87 Mod O    | MBA88B001H023                      | 24  | 13 |     | February 2008             |              |
|       | Will Granica G | MBA88E001-027                      | 24  | 14 |     | May 2008                  |              |
|       |                | MBA89F001-030                      | 79  | 43 |     | June 2009                 |              |
|       |                | IH-94L002-003A                     |     |    |     | November 2014             |              |
|       |                |                                    | 6   | 5  |     |                           |              |
|       |                | MBA84B001-013                      | 8   |    |     | February 2004             |              |
|       |                | MBA85E001-015                      |     | 7  | 189 | May 2005                  |              |
|       |                | MBA85E001-017                      | 12  | 9  | 43  | May 2005                  |              |
|       |                | MBA85H001-018                      | 25  | 23 | 232 | August 2005               |              |
|       |                | MBA86J001H020                      | 27  | 27 | 232 | September 2006            | EA-6B        |
|       |                | MBA86J001-021                      | 12  | 11 |     | September 2006            |              |
|       |                |                                    | 25  | 7  |     | September 2006            |              |
|       |                | UPC86J001-001A/B<br>MBA88B001 H023 | 6   | 6  |     | February                  |              |
| M940  | Mk 88 Mod O    | MBA88E001-025                      | 11  | U  |     | 2008 May                  |              |
|       |                |                                    | 10  | 6  |     | 2008 May                  |              |
|       |                | MBA88E001-028                      | 3   | 1  |     | 2008 August               |              |
|       |                | MBA88H001H029                      | 12  | 7  |     | 2008                      |              |
|       |                | MBA88E001-030                      |     |    |     | May 2008                  |              |
|       |                | MBA89F001-031                      |     | 0  |     | June 2009                 |              |
|       |                | IH-94L002-003A                     | •   | 6  | 110 | November 2014             |              |
|       |                |                                    | 1   |    | 6   |                           |              |
|       |                | MBA84B001-013                      |     | 3  | 116 | February 2004             |              |
|       |                | MBA85E001-015                      | 26  | 6  | 110 | May 2005                  | EA-6B        |
|       |                | MBA85E001-017                      | 26  | 9  |     | May 2005                  |              |
|       |                | MBA85H001-018                      |     |    |     | August 2005               |              |
|       |                | MBA86J001-021                      | 6   | 16 |     | September 2006            |              |
|       |                | MBA88E001-025                      | 8   | 11 |     | May 2008                  |              |
|       |                | MBA88B001023                       | 12  | 12 |     | February 2008             |              |
|       |                | MBA88E001-027                      | 31  | 6  |     | May 2008                  |              |
|       |                | MBA89F001-030                      | 13  | 7  |     | June 2009                 |              |
|       |                | MBAOOL002-031                      |     |    | 85  | November 2020             |              |
|       |                | IH-94L002-003A                     | 12  | 13 |     | November 2014             |              |
|       |                | IH-94L002-004                      | 6   | 30 | 31  | November 2014             |              |
|       |                |                                    | 12  | 1  | 116 |                           | EA-6B        |
|       | *              |                                    | ·!  |    |     | . "                       |              |

| 24             |  |
|----------------|--|
| 46<br>49<br>25 |  |
|                |  |
|                |  |
|                |  |
|                |  |
|                |  |
|                |  |
|                |  |
|                |  |
|                |  |

## Table

[As of

| DODIC | Model | Lot No. | Lot<br>quantity | Quantity<br>installed | Total<br>installed | Expired date | Aircraft type |
|-------|-------|---------|-----------------|-----------------------|--------------------|--------------|---------------|
|-------|-------|---------|-----------------|-----------------------|--------------------|--------------|---------------|

## IV—Continued

30 January 2003]

|      |                  |                                |     | ,   |     |                              |              |
|------|------------------|--------------------------------|-----|-----|-----|------------------------------|--------------|
| MU75 | Mk 90 Mod 1      | IH-96D001-004                  | 175 | 60  |     | April 2005                   |              |
|      |                  | IH-99H001-005                  | 106 | 95  |     | April 2008                   |              |
|      |                  | IH-OOB001-006                  | 110 | 21  |     | February 2009                |              |
| MD68 | Mk 100 Mod       |                                | 110 |     |     | -                            |              |
|      | 0                | MBA86G001-012<br>MBA86G001-013 | 57  | 24  |     | July 2004                    |              |
|      |                  | MBA86G001-015                  | 47  | 14  |     | July 2004                    |              |
|      |                  | MBA86J001-016                  | 30  | 7   | 176 | July 2004                    | S-3B         |
|      |                  | MBA86M001-017                  | 56  | 11  |     | September                    |              |
|      |                  | MBA86J001-018                  | 29  | 12  |     | 2004                         |              |
|      |                  | MBA86J001-020                  | 18  | 5   |     | December                     |              |
|      |                  | MBA87K001-024                  | 7   | 2   |     | 2004                         |              |
|      |                  | MBA87K001-025                  | 21  | 10  |     | September                    |              |
|      |                  | MBA88B001-026                  | 15  | 6   |     | 2004                         |              |
|      |                  | MBA88G001-027                  |     | 21  |     | September                    |              |
|      |                  | MBA88B001-028                  | 23  |     |     | 2004                         |              |
|      |                  | MBA88G001-029                  | 5   | 3   |     | October 2005<br>October 2005 |              |
|      |                  | MBA88G001-031                  | 11  | 40  |     | February 2006                |              |
|      |                  | MBA89A001-033                  | 55  | 3   |     | July 2006                    |              |
|      |                  | MBA89B001-032                  | 16  | 62  |     | February 2006                |              |
|      |                  | MBA89F001-034                  | 128 | 60  |     | July 2006                    |              |
|      |                  | MBA91B001-038                  | 66  | 6   |     | July 2006                    |              |
| MD69 |                  | MBA93C002-040                  | 8   | 48  |     | January 2007                 |              |
| MD09 | Mk 101 Mod O     | MBA94C003-041                  | 66  | 64  |     | February 2007                |              |
|      | IVIK 101 IVIOU O | MBA96L003-047                  | 182 | 7   |     | June 2007                    |              |
|      |                  | MBA99M003-050                  | 46  | 6   | 412 | February 2009                | FA-18A/B/C/D |
|      |                  |                                | 47  |     |     | March 2011                   |              |
|      |                  | MBA86G001-012                  | 19  | 0   |     | March 2012                   |              |
|      |                  | MBA86G001-013                  | 19  |     |     | November                     |              |
|      |                  | MBA86J001-020                  |     |     |     | 2015                         |              |
|      |                  | MBA86M001-017                  | 2   | 2   |     | December                     |              |
|      |                  | MBA87K001-024                  | 11  | 6   |     | 2017                         |              |
|      |                  | MBA87K001-025                  | 8   | 2   |     |                              |              |
|      |                  | MBA88B001-026                  | 7   | 2   |     | July 2004                    |              |
|      |                  | MBA88G001-029                  | 2   | 2   |     | July 2004                    |              |
| MF21 |                  | MBA89A001-033                  | 3   | 5   |     | September                    |              |
|      | Mk 79 Mod 1      | MBA89B001-032                  | 7   | 6   |     | 2004                         |              |
|      |                  | MBA91B001-038                  | 8   | 7   |     | December                     |              |
|      |                  | MBA93C002-040                  | 25  | 20  |     | 2004 October                 | FA-18B/D     |
|      |                  | MBA94C003-041                  |     |     |     | 2005                         |              |
|      |                  | MBA96L003-047<br>MBA93M003-050 | 30  | 12  |     | October 2005                 |              |
|      |                  |                                | 57  | 5   |     | February 2006                |              |
|      |                  |                                | 23  | 14  |     | July 2006                    |              |
|      |                  | TAC92H001-055                  | 33  |     |     | January 2007                 |              |
|      |                  | TAC93L001-056<br>TAC97D001-001 | 47  |     |     | February 2007                |              |
|      |                  | TAC97J002-001                  | 15  | 0   |     | February 2008<br>March 2011  |              |
|      |                  | IH-98A003-002                  |     | 2   |     | March 2011<br>March 2012     |              |
|      |                  | TAC99H002-002                  | 88  | 77  |     | November                     |              |
|      |                  | IH-99M002-002                  | 18  | 146 |     | 2015                         |              |
|      |                  | TACOOL002-003                  | 135 | 35  |     | 2013                         |              |
|      |                  | TAC01E002-004                  | 171 | 50  | 312 |                              | AV-8B/TAV-8B |
|      |                  | 1, (COTEOUZ-004                | 1   | 50  | 312 |                              | UA OPLIVA-OP |

IV—Continued

|   |   | 30 January 2003] |  |  |
|---|---|------------------|--|--|
| TAC01E002-005 TAC01K002-006 TACO 1 K002-007 TAC01M002-008 TAC02A002-009 TAC02E002-010 | 110<br>261<br>50<br>30<br>50<br>28<br>53<br>40<br>20<br>8<br>12 | 2 0 0 0 0 0 0 0  | December 2017  August 2003 November 2004 April 2008 September 2008 January 2009 August 2010 December 2010 November 2011 May 2012 October 2012 October 2012 December 2012 January 2013 May 2013 |  |

## Table [As of

| DODIC  | Model            | Lot No.                        | Lot<br>quantity |       | Quantity<br>nstalled | Total<br>installed | Expired date             | Aircraft type    |
|--------|------------------|--------------------------------|-----------------|-------|----------------------|--------------------|--------------------------|------------------|
|        |                  | UPC92B001-033                  | 46              | NACES | Non-                 |                    | February 2003            |                  |
|        |                  | UPC92D001-034                  | 48              | 19    | NACES                |                    | April 2003               |                  |
| MF56   | Mk 109 Mod O     | UPC92G001-035                  | 45              | 21    |                      |                    | July 2003                |                  |
|        | 100 1000         | UPC92G001-036                  | 343             | 26    | 0                    |                    | July 2003                |                  |
|        |                  | UPC92K001-038                  | 49              |       |                      |                    | October 2003             |                  |
|        |                  | UPC93A001-039                  | 35              | 10    | 251                  | 19                 | January 2004             |                  |
|        |                  | UPC93C001-041                  |                 | 26    | 0                    | 24                 | March 2004               |                  |
|        |                  | UPC93J001-042                  | 48              | 19    | 0                    | 26                 | September 2004           |                  |
|        |                  | TAC94A002-001A                 | 25              | 32    | ŏ                    | 261                | January 2005             |                  |
|        |                  | UPC94D001-043                  | 15              | 25    | 0                    | 26                 | April 2005               |                  |
|        |                  |                                | 60              | 1     | 0                    | 19                 | July 2006                |                  |
|        |                  | UPC95D001-044                  | 29              | 57    | 0                    | 32                 | July 2006                |                  |
|        |                  | UPC95G001-045                  | 27              | 29    | 0                    | 25                 | August 2006              |                  |
|        |                  | UPC95H001-046                  | 25              | 27    | 0                    | 25                 | November 2006            |                  |
|        |                  | UPC95L001-047<br>UPC96B001-048 | 20              | 25    | 46                   | 57                 | February 2007            |                  |
|        |                  | UPC96C001-048                  | 48              | 20    |                      | 29                 | March 2007<br>March 2007 |                  |
|        |                  | UPC96G001-049                  |                 |       | 111                  | 27                 | May 2007                 |                  |
|        |                  | UPC96E001-051                  | 8               | 8     |                      | 25                 | February                 |                  |
|        |                  | UPC97B001-053                  | 195             | 67    | 0                    | 20                 | 2008 July                |                  |
|        |                  | UPC97G001-054                  | 18              | 16    | 0                    | 46                 | 2008                     |                  |
| SS67   | Mk 109 Mod 1     | UPC97G001-055                  | 18              | 17    | Ö                    | 8                  | July 2008                |                  |
|        | IVIK 109 IVIOU 1 | UPC98B001-056                  | 16              | 15    | 0                    |                    | February 2009            |                  |
|        |                  | UPC99B001-057                  | 6               | 4     | 0                    | 178                | February 2010            |                  |
|        |                  | IH-98D001-001                  | 54              |       | 41                   | 16                 | April 2009               |                  |
|        |                  | TAC99D001-002                  | 51              | 54    | 164                  | 17                 | April 2010               |                  |
|        |                  | ACOOA001-003                   | 57              | 16    | 84                   | 15                 | January 2011             |                  |
| N 4557 |                  | AC01H001-005                   | 250             | 4     | 6                    | 4                  | August 2012              | FA-18A/B/C/D/E/F |
| MF57   | Mk 84 Mod 2      | TAC01K001-006                  | 273             | 50    | 18                   | 54                 | October 2012             |                  |
|        |                  | TAC01M001-007                  | 109             | 85    | 2                    | 16                 | December 2012            |                  |
|        |                  |                                | 60              | 46    | 726                  | 45                 |                          |                  |
|        |                  | TAC90M001-005A                 | 2               | 17    |                      | 214                | December 2003            |                  |
|        |                  | AC93L001-006A                  |                 |       | 39                   | 169                | November 2006            |                  |
|        |                  | TAC95J001-007A                 |                 |       | 72                   | 52                 | September 2008           | s-3B             |
| MG67   | Mk 113 Mod O     | AC96H001-001A                  | 213             |       | 83                   | 35                 | August 2009              |                  |
|        |                  | ACOOKOO 1-008                  | 107             |       | 17                   | 2                  | October 2013             |                  |
| MG67   | Mk 113 Mod 1     | AC01G001-009                   | 86              |       |                      | 1,661              | July 2014                |                  |
| IVIG07 | WIK 115 WIGG 1   |                                | 286             |       |                      | 1,001              | · · · · / = · = ·        |                  |
|        |                  |                                | 96              |       |                      |                    |                          | AV-8B/TAV-8B     |
|        | 1/11 7/4         | UPC99D001-001                  | 96              |       | 159                  |                    | April 2007               | AV-OD/TAV-OD     |
| MS15   | KU-7/A           | UPCOOG001-002                  |                 |       |                      |                    | July 2008                |                  |
|        |                  | TAC98M003-001                  | 227             |       | 8                    |                    | December 2006            |                  |
|        |                  | TACOOJ004-003                  | 237             |       |                      |                    | July 2008                |                  |
|        |                  | ACOI H004-004                  | 32              |       |                      | 411                | August 2009              |                  |
|        |                  |                                | 64              |       | 7                    |                    | 3                        | F-5E/F/T-38A     |
| MT28   | Mk 121 Mod O     | IH-95E001-046                  | 30              |       | 7                    | 159                | May 200E                 |                  |
| 0      |                  | IH-96H001-048                  | 7               |       | 3                    |                    | May 2005                 | A\/ QD/NIA\/     |
|        |                  | IH-99F001-049                  |                 |       | 21                   |                    | August 2006              | AV-8B/NAV-       |
|        |                  |                                |                 |       |                      | 8                  | June 2009                | 8B/TAV8B         |

## IV—Continued

| 30 January 2003] |   |                                |     |      |                 |  |  |  |  |  |
|------------------|---|--------------------------------|-----|------|-----------------|--|--|--|--|--|
|                  | IHMOOC001-051<br>IHMOOE001-052<br>ESDOOAOOI-OOI | 8<br>5<br>21<br>46<br>22<br>86 | 736 | 22 5 | 167<br>58<br>54 | March 2010<br>May 2010<br>January 2007 |  |  |  |  |
|                  |   |                                | 54  |      |                 |  |  |  |  |  |
|                  |   |                                |     |      |                 |  |  |  |  |  |
|                  |   |                                |     |      |                 |  |  |  |  |  |

Table [As of

IV—Continued 30 January 2003]

|       | 30 January 2003] |                              |                 |         |          |      |                    |                                |                   |
|-------|------------------|------------------------------|-----------------|---------|----------|------|--------------------|--------------------------------|-------------------|
| DODIC | Model            | Lot No.                      | Lot<br>quantity | Quantit | y Instal | led  | Total<br>installed | Expired date                   | Aircraft type     |
| MT29  | Mk 122           | UPC94C003-004                | 229             | F-14D   | F-18     | T-45 | 78                 | March 2003                     |                   |
|       | Mod O            | MBA96C003-013                | 49              |         |          |      | 32                 | March 2003                     |                   |
|       |                  | UPC97H003-005                | 192             | 19      | 34       | 25   | 162                | August 2004                    |                   |
|       |                  | MBA98J004-014                | 300             | 8       | 11       | 13   | 254                | September                      |                   |
|       |                  | MBA99J004-016                | 206             | 25      | 80       | 57   | 172                | 2008                           |                   |
|       |                  | MBAOOF004-017                | 257             | 28      | 145      | 81   | 165                | September                      |                   |
|       |                  | UPC01E005-001                | 270             | 4 2 o   | 124      | 44   | 21                 | 2009                           |                   |
|       |                  |                              | Totals          | 86      | 110      | 53   | 884                | June 2010                      |                   |
| MT30  |                  |                              |                 |         | 17       | 4    | 004                | May 2011                       |                   |
|       | Mk 123           | MBA89F001-003                | 31              | o o 13  | 521      | 277  |                    |                                |                   |
|       | Mod O            | MBA89F001-005                | 16              | 001     |          |      | 3                  |                                |                   |
|       |                  | MBA90H001-006                | 35              | 4 2     | 3        |      | 26                 | June 2004                      |                   |
|       |                  | MBA90H001-007                | 6               | o O     | 0        | 0    |                    | June 2004                      | E 14D/EA 100 E E  |
|       |                  | MBA90K001-008                | 50              | 9       | 10       | 3    | 20                 | August 2004                    | F-14D/FA-18C,E,F, |
|       |                  | UPC90L001 HOOI B             | 17              | 5 3     | О        | 1    | 5                  | August 2004                    | T-45A,C           |
|       |                  | MBA91J001-009                | 21              | 0100    | 15       | 5    | 11                 | October 2004                   |                   |
|       |                  | UPC91K001H002A               | 14              | o o 38  | 1        | 3    | 5                  | November 2005                  |                   |
|       |                  | MBA92C001-010                | 10              |         | 6        | 1    | 5                  | September                      |                   |
|       |                  | UPC93E002H005                | 27              | o o 12  | 2        | 1    | 2                  | 2006                           |                   |
|       |                  | MBA93F002-011                | 54              | 0       | 0        | 5    | 54                 | October 2006<br>March 2007     |                   |
|       |                  | UPC94B003H006                | 80              | 12      | 1<br>12  |      | 39                 | May 2008                       |                   |
|       |                  | MBA95C003-012                | 236             | 1       | 14       | 1    | 24                 | June 2008                      |                   |
|       |                  | MBA96C003-013                | 71              | 1       |          | 33   | 14                 | February                       |                   |
|       |                  | MBA97G003-014                | 33              | 10      | 8        | 20   | 33                 | 2009                           |                   |
| N4T24 |                  | MBA98J003-017                | 33              | 01      | 7        | 13   | 23                 | March 2010                     |                   |
| MT31  |                  | MBA99H003-019                | 53              | 8       | 18       | 7    | 39                 | March 2010                     |                   |
|       |                  | MBA01A003-020                | 47              | 2602    | 14       | 14   | 11                 | July 2012                      |                   |
|       | Mk 124           | MBA01E003-024                | 22              | 0000    | 21       | 9    | 3                  | September 2013                 |                   |
|       | Mod O            |                              | Totals          | 46      | 2        | 18   |                    | August 2014                    |                   |
|       |                  |                              | TOLAIS          |         | 3        | 9 o  | 319                | January 2016                   | F-14D/F-18C,D,E,F |
|       |                  | MBA89F001-004                |                 |         | 137      | 143  |                    | May 2016                       | T-45A, C          |
|       |                  | MBA89F001-005                | 57              |         |          |      | 5<br>o             | ,                              |                   |
|       |                  | MBA90H00106<br>MBA90H001-007 | 7               |         | 5        |      | 41                 |                                |                   |
|       |                  | MBA90K001-007                | 68              |         | 0        | 0    | 15                 | September                      |                   |
|       |                  | UPC90L001H001B               | 36              |         | 26       | 3    | 42                 | 2004                           |                   |
|       |                  | MBA91J001-009                | 91              |         | 15       | 0    | 6                  | September                      |                   |
|       |                  | UPC91K001H002A               | 36              |         | 26       | 4    | 24                 | 2004 August                    |                   |
|       |                  | UPC91K001H002A               | 34              |         | 3        | 2    | 5                  | 2005                           |                   |
|       |                  | MBA92C001-010                | 29              |         | 19       | 4    |                    | August 2005                    |                   |
|       |                  | UPC93D002H004                | 6               |         | 2        | 2    | 15                 | October 2005                   |                   |
|       |                  | MBA93F002-011                | 27              |         | 0        | 5    | 9                  | November 2005                  |                   |
|       |                  | UPC94B003H005                | 62              |         | 10       |      | 95                 | September 2005<br>October 2006 |                   |
|       |                  | MBA95C003-012                | 104             |         |          | 2    | 62                 | October 2006                   |                   |
|       |                  | MBA96C003-013                | 142             |         | 6        | 20   | 104                | March 2007                     |                   |
|       |                  | MBA97G003-014                | 165             |         | 36       | 24   | 21                 | April 2008                     |                   |
|       |                  | MBA98J003-017                | 71              |         | 90       | 8    | 66                 | June 2008                      |                   |
|       |                  | MBA99H003-019                | 70              |         | 13       | 8    | 40                 | March 2009                     |                   |
|       |                  | MBA01A003-020                | 66              |         | 43       | 21   | 56                 | March 2010                     | F 14/F-18/T-45    |
|       | 1                |                              | 30              |         | .5       |      |                    |                                | · _ 1-7/1 10/1-43 |

| 30 January 2003 J |               |                          |  |                        |                        |           |   |  |  |
|-------------------|---------------|--------------------------|--|------------------------|------------------------|-----------|---|--|--|
|                   | MBA01E003-024 | 84<br>76<br>37<br>Totals |  | 24<br>40<br>9 o<br>434 | 16<br>16<br>7 o<br>142 | 16<br>622 | March 2011 July 2012 September 2013 August 2014 January 2016 May 2016 |  |  |
|                   |               |                          |  |                        |                        |           |   |  |  |

## III—Continued January 2003]

Table [As of 30

| DODIC         | Model                           | Lot No.   | Lot<br>quantity                                | Quantity<br>Installed           | Total<br>installed | Expired date  | Aircraft type                                    |
|---------------|---------------------------------|---|--|---------------------------------|--------------------|---|--|
| XW36<br>x W36 | Mk 205 Mod<br>1<br>Mk 205 Mod 2 | TAC95G001-002 TAC95J001-003 TAC96A001-004 TAC98M002-001 TAC98M002-002 TACO0B002-003A TACO IB002-004 TAC01G002-006 | 112<br>69<br>36<br>77<br>50<br>60<br>126<br>24 | 26<br>19<br>35<br>30<br>18<br>3 | 51<br>138          | July 2003 September 2003 January 2004 December 2006 December 2006 February 2008 February 2009 July 2009 | AV-8B/NAV-<br>8B/TAV8B<br>AV-8B/NAV-<br>8B/TAV8B |