

MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS 1963 A

DC FILE COPY

0

RELIABILITY AND MAINTAINABILITY EVALUATION OF THE TOWER CAB DIGITAL DISPLAY SYSTEM

LEVELT

Arthur R. Moss

George C. Apostolakis

FEDERAL AVIATION ADMINISTRATION TECHNICAL CENTER

ATLANTIC CITY AIRPORT, N.J. 08405





FINAL REPORT

DECEMBER 1980

Document is available to the U.S. public through the National Technical Information Service, Springfield, Virginia 22161.

Prepared for

U. S. DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION
Systems Research & Development Service
Washington, D. C. 20590

NOTICE

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no liability for the contents or use thereof.

The United States Government does not endorse products or manufacturers. Trade or manufacturer's names appear herein solely because they are considered essential to the object of this report.

Technical Report Documentation Page

1. Report N. /2)	2. Government Accession No.	3. Recipient's Catalog No.
FAA-RD 86-164	AD-A094 079	
4. Title and Subtitle		Sy Report Date
re liability and <u>M</u> aintainai		// December \$80
TOWER CAB DIGITAL DISPLAY	SYSTEM	6. Perferming Organization Code
The second secon	one of the control of	1.176
7. Author's) Arthur R. Moss		8. Performing Organization Report No.
George C./Apost	tolekie	FAA-CT-80-32
9. Performing Organization Name and A		10. Work Unit No. (TRAIS)
Federal Aviation Administr		10.11.01.11.11.11.11.11.11.11.11.11.11.1
Technical Center	ν	11. Contract or Grant No.
Atlantic City Airport, New	w Jersey 08405	142-171-540
		13. Type of Report and Period Covered
12. Sponsoring Agency Name and Address		$\neg \qquad \forall 1 \qquad .$
U.S. Department of Transpo		Final Trans
Federal Aviation Administr		August 1979 - February 198
Systems Research and Devel Washington, D.C. 20590	robment gervice	14. Spansering Agency Code
15. Supplementary Notes		
16. Abstract		
Digital Display (TCDD) s facilities. Data were c Analysis of these data	ystems located at four Flo collected between August 25 showed that 21 chargeab	performed on eight Tower Cab orida air traffic control (ATC) , 1979, and February 29, 1980. le hardware failures occurred
Digital Display (TCDD) s facilities. Data were c Analysis of these data (excluding the telephone between-failures (MTBF)	ystems located at four Flocollected between August 25 showed that 21 chargeable lines). This corresponds	orida air traffic control (ATC) , 1979, and February 29, 1980.
Digital Display (TCDD) s facilities. Data were of Analysis of these data (excluding the telephone between-failures (MTBF) hours. In addition to the charge attributed to transitor outages included noisy	ystems located at four Flocollected between August 25 showed that 21 chargeable lines). This corresponds of 1,001 hours and a measuable hardware failures, marry, environmental, or undetelephone lines, frequent	orida air traffic control (ATC), 1979, and February 29, 1980. le hardware failures occurred to an overall system mean-time-n-time-to-repair (MTTR) of 2.9
Digital Display (TCDD) s facilities. Data were c Analysis of these data (excluding the telephone between-failures (MTBF) hours. In addition to the charge attributed to transitor outages included noisy ambient room temperatures. The measured MTBF for a corresponding predicted v	ystems located at four Flocollected between August 25 showed that 21 chargeable lines). This corresponds of 1,001 hours and a measuable hardware failures, mary, environmental, or unde telephone lines, frequent a subset of the system was	orida air traffic control (ATC), 1979, and February 29, 1980. le hardware failures occurred to an overall system mean-time-n-time-to-repair (MTTR) of 2.9 my system outages which could be fined causes occurred. These automatic restarts, and high as found to be lower than the ed MTTR is considered excessive.
Digital Display (TCDD) s facilities. Data were of Analysis of these data (excluding the telephone between-failures (MTBF) hours. In addition to the charge attributed to transitor outages included noisy ambient room temperatures. The measured MTBF for a corresponding predicted v Recommended actions for se	ystems located at four Flocollected between August 25 showed that 21 chargeab lines). This corresponds of 1,001 hours and a measure that the system was alue. The 2.9-hour measure everal design changes are in through the	prida air traffic control (ATC), 1979, and February 29, 1980. le hardware failures occurred to an overall system mean-time-n-time-to-repair (MTTR) of 2.9 by system outages which could be fined causes occurred. These automatic restarts, and high as found to be lower than the d MTTR is considered excessive.
Digital Display (TCDD) sericilities. Data were considered and sericilities. Data were considered attailments (MTBF) shours. In addition to the charge attributed to transitor outages included noisy ambient room temperatures. The measured MTBF for a corresponding predicted version of the commended actions for secons for secons and the commended actions for secons for Secons and Digital Display ARTS IIIA Reliability	ystems located at four Flocollected between August 25 showed that 21 chargeab lines). This corresponds of 1,001 hours and a measure that the system was alue. The 2.9-hour measure everal design changes are in through the	prida air traffic control (ATC), 1979, and February 29, 1980. le hardware failures occurred to an overall system mean-time-n-time-to-repair (MTTR) of 2.9 by system outages which could be fined causes occurred. These automatic restarts, and high as found to be lower than the ded MTTR is considered excessive. Included.
Digital Display (TCDD) sericilities. Data were considered and sericilities. Data were considered attailments of these data (excluding the telephone between-failures (MTBF) hours. In addition to the charge attributed to transitor outages included noisy ambient room temperatures. The measured MTBF for a corresponding predicted versions for secommended actions for secommended actions for secommended.	ystems located at four Flocollected between August 25 showed that 21 chargeab lines). This corresponds of 1,001 hours and a measure that the system was alue. The 2.9-hour measure everal design changes are in through the	prida air traffic control (ATC), 1979, and February 29, 1980. le hardware failures occurred to an overall system mean-time-n-time-to-repair (MTTR) of 2.9 by system outages which could be fined causes occurred. These automatic restarts, and high as found to be lower than the ded MTTR is considered excessive. Included.
Digital Display (TCDD) s facilities. Data were of Analysis of these data (excluding the telephone between-failures (MTBF) hours. In addition to the charge attributed to transitor outages included noisy ambient room temperatures. The measured MTBF for a corresponding predicted v Recommended actions for se 17. Key Words Tower Cab Digital Display ARTS IIIA Reliability Maintainability	ystems located at four Flocollected between August 25 showed that 21 chargeab lines). This corresponds of 1,001 hours and a measure that the system was alue. The 2.9-hour measure everal design changes are in through th Service, S	prida air traffic control (ATC), 1979, and February 29, 1980. le hardware failures occurred to an overall system mean-time-n-time-to-repair (MTTR) of 2.9 my system outages which could be fined causes occurred. These automatic restarts, and high as found to be lower than the ed MTTR is considered excessive. cluded. Statement s available to the U.S. public e National Technical Information pringfield, Virginia 22161

Form DOT F 1700.7 (8-72)

Reproduction of completed page authorized

4111/2

j		.2 .5	e 7 T		***						:.	, I	27	1		٠			_
1 2		11	ıli				į	H]	į	*					9	9
raises from Motific Matrice tr	LEBETH	3:	222	AREA	2723	MASS (unimpt)		1 22		10000		# X	'n:	2	TEMPERATURE (exect)	9.75 (de 20.00)		021	2 2
Approximate Commercians from Motoric When You Loop Matheth by	į	maillimenters continuenters		.				tilograms Lilogram Lilogr		}	millitiers Fiers		Carbic meens		1680	Colsius		a €	2
į		i 8	3		Tris	!		• J .			T _		. %	· `e		ပ္		* 9	1 4.
		M	* 1 				21						۷ ااااااا	9 	S		E		
 	7" "	ן''ן'' <u>'</u>	'!' '!' ,	'1' '1' ' 		' ' ' ' 8	' 'I'	וןיוין 		! ' '	.l.ı.	' ' 3	'	' ! ' '	' ' ' 	ן יין יין יין	ָן'יין' 	'1' '1' 1	inche
H	T. Fiel		Centimaters Centimaters	E STOREGE E	Square Continuess Carl Square meters nt2 square meters nt2	square kilomoters tun? hectares ha		grams 9 hilograms Ng				mililiars m		liters	cubic meters m ³	•	Celaius	Lampor after o) tables, see NBS M·sc. Publ. 286, 6.
Appreziente Conversions to Motrie	1 1	LENGTH	57. R		6.5 0.09	5 T	MASS (weight)	2 o 3	6.9	VOLUME	- - 4	28	0.24	3.5	6.63 K.0	TEMPERATURE (exect)	5/3 (after	auberacting 32)	ersions and more detailed D Catalog No. C13,10:29
Approximents Conv	at of the	ļ	1	11			=		Short tons (2000 lb)			fluid cances	1	guarts gailtong	cubic feet cubic yards	158	Fabrushoit	eriterature.	1 in 1.2.54 leadcity). For other exact conversions and more detailed to Units of Meghts and Messures, Price 52,25, SD Catalog No. C13,10:286.
	1		.s æ'	\$ 1	ንኔን	î)		8 2			1	ļ	• L	1	ጉን				1 in 1 2.54 Units of Weigh

PREFACE

The authors wish to express their appreciation to the FAA personnel at the Tampa, St. Petersburg, and Sarasota air traffic control facilities and to the personnel at MacDill Air Force Base for their assistance in this reliability and maintainability effort. The thoroughness, accuracy, and completeness of the data which they recorded and made available to the FAA Technical Center personnel have contributed materially to the integrity of this analysis.

Accession For
NTIS GRA&I
Unennounced Justification
B*
Distribution/
Avoil Hity dudes
Pist Conclui
A

TABLE OF CONTENTS

	Page
INTRODUCTION	1
Purpose Background	1 1
SYSTEM DESCRIPTION	1
DATA COLLECTION, REDUCTION, AND ANALYSIS	2
Data Collection Data Reduction and Analysis	2 2
RESULTS	14
MTBF and MTTR Summation (Chargeable Failures) Other System Outages Overall General Results	14 16 17
CONCLUSIONS	24
RECOMMENDATIONS	24
APPENDIX	

v

LIST OF ILLUSTRATIONS

Figure		Pag
1	Display Processor, Power Supply Chassis, and Display Unit for Typical TCDD Maintenance System	3
2	Display Processor and Power Supply Chassis for Typical Tower Cab System	4
3	Typical Tower Cab Showing Yoke Mounting for Display Unit	5
4	Remote Control Panel, Keyboard, and Trackball in TCDD Maintenance System	6
5	Keyboard and Trackball in Tower Cab System	7
6	RDBM in TCDD Maintenance System	8
7	Front Panel of RDBM	9
8	Codex 8200 Modem and RDBM used in Tower Cab System at Tampa	. 10
9	ARTS IIIA Interface Diagram	11
10	TCDD Reliability Model	13
11	Typical Connector Plug Showing Damaged Pins	21
12	Example of Potentiometer Adjustments on Bottom Side of PCB's	22
	LIST OF TABLES	
Table		Pag
1	Overall MTBF and MTTR Summation	15
2	Predicted Versus Measured MTBF Values	18
3	Recommended MTBF Specification Values for TCDD Equipment and System (Hrs)	19

INTRODUCTION

PURPOSE.

This report summarizes the reliability and maintainability evaluation which was conducted on eight Tower Cab Digital Display (TCDD) systems installed at Tampa, St. Petersburg, Sarasota, and MacDill Air Force Base in Florida. Based on the data analyzed during this evaluation, mean-time-between-failure (MTBF) and mean-time-to-repair (MTTR) values were generated. The MTBF and MTTR values are figures of merit or numerical indexes of reliability and maintainability, respectively. values were generated for each of the eight TCDD systems, the various units and equipment comprising the systems, and various combinations of the systems.

In addition to the MTBF and MTTR values, which are based upon chargeable hardware failures, this report also discusses the various system outages and problem areas caused by reasons other than chargeable failures. These include transitory malfunctions and outages as well as those due to environmental conditions, noisy telephone lines, and indeterminate causes.

BACKGROUND.

Each of the four facilities contains two TCDD systems. One system in each facility is used in the control tower cab for operational air traffic control. At the three facilities other than MacDill, the other TCDD system is used in the equipment room for maintenance; at MacDill, the other TCDD is used operationally for ground control approach (GCA).

Initially, all eight systems were to be evaluated during an official test period of 4 months; however, some were not used because of non-TCDD related causes. Consequently, the official reliability and maintainability evaluation covers

only the four systems located at St. Petersburg and MacDill Air Force Base for the period January 7 to February 29, 1980. However, in order to extend the data base, all eight systems were analyzed from the time each system became operational until just prior to the start of the official test. The time intervals for which data were collected prior to the official test are as follows:

Tampa: December 2-31, 1979

St. Petersburg: October 26, 1979 -

January 6, 1980

MacDill: August 25, 1979 -

January 6, 1980

Sarasota: September 6 -

December 31, 1979

SYSTEM DESCRIPTION

The TCDD provides a remote digital presentation of the air traffic situation generated by the Automated Radar Terminal System (ARTS) IIIA located at the Tampa terminal. information is provided to the local tower cab at Tampa as well as to the remote tower cabs at St. Petersburg, Sarasota, and MacDill Air Force Base. At the Tampa, St. Petersburg, and Sarasota tower cabs, one TCDD system is used operationally while the other serves in a maintenance or monitoring capacity. At MacDill Air Force Base, both systems are used operationally, one in the tower cab and the other for ground approach control. Each TCDD system also provides capability for the tower controller to communicate with the ARTS IIIA for the purpose of entering, deleting, or updating flight data.

Each TCDD system consists of the following modules or units:

1. Display processor (unit 1)

- 2. Power supply chassis (unit 2)
- 3. Display (unit 3)
- 4. Two keyboards (unit 4)
- 5. Remote control panel (unit 5)
- 6. Two trackballs (unit 6)
- 7. Remote display buffer memory (RDBM)

The two keyboards and trackballs are not redundant units but are used in two controller positions for each operational system. The maintenance systems at Tampa, St. Petersburg, and Sarasota include only one each of these two units.

Figure 1 shows the display processor, the power supply chassis, and the display unit for a typical TCDD maintenance system. Figure 2 shows the display processor and power supply chassis for a typical tower cab installation. Figure 3 indicates how the display unit would appear in a tower cab installation. While the unit shown is not a TCDD, it is physically sufficiently similar to show how the display unit would appear mounted in the special yoke provided.

Figure 4 shows the remote control panel, keyboard, and trackball units in the equipment room; figure 5, the keyboard and trackball units mounted in the tower cab; and figure 6, the RDBM for a typical maintenance system in relation to the other equipment in the equipment room. Figure 7 gives a close-up view of the front panel of the RDBM.

In addition to the above seven types of units or modules which comprise the TCDD system proper, the telephone lines which convey data between the ARTS IIIA and the tower cabs and the modems in the tower cabs are also included in the TCDD system configuration from the standpoint of this reliability and maintainability evaluation. Figure 8 shows the RDBM and the Codex 8200 modem used in the tower

cab system at Tampa. Figure 9 is a block diagram which shows how the eight systems located at the four air traffic control facilities interface with the ARTS IIIA at Tampa.

DATA COLLECTION, REDUCTION, AND ANALYSIS

DATA COLLECTION.

Data collection consisted of logging any event or situation which was different from the normal energized and operational status of the equipment. Such events included: shutdown of any equipment unit, preventive maintenance, hardware failures, engineering changes, and changes in system configuration.

This information was entered on standard Federal Aviation Administration (FAA) 6030.1 facility maintenance log forms for the three FAA facilities (Tampa, Sarasota, and St. Petersburg). A contractor's log form was used at MacDill Air Force Base as well as for recording additional data at the FAA facilities. The logged data included a complete history of every hardware failure as well as other malfunctions and outages including manual and automatic RDBM restarts.

DATA REDUCTION AND ANALYSIS.

From the equipment logs, each reported malfunction was analyzed to determine whether it was a chargeable failure. The criteria for chargeability are as follows:

- 1. The failure is independent; that is, it did not occur as a result of another failure or hardware modification.
- 2. The failure causes a loss or degradation of performance beyond specified or acceptable limits of the equipment unit (reliability element) in which it occurred.




FIGURE 1. DISPLAY PROCESSOR, POWER SUPPLY CHASSIS, AND DISPLAY UNIT FOR TYPICAL TCDD MAINTENANCE SYSTEM




FIGURE 2. DISPLAY PROCESSOR AND POWER SUPPLY CHASSIS FOR TYPICAL TOWER CAB SYSTEM




FIGURE 3. TYPICAL TOWER CAB SHOWING YOKE MOUNTING FOR DISPLAY UNIT




FIGURE 4. REMOTE CONTROL PANEL, KEYBOARD, AND TRACKBALL IN TCDD MAINTENANCE SYSTEM






FIGURE 6. RDBM IN TCDD MAINTENANCE SYSTEM



FIGURE 7. FRONT PANEL OF RDBM



CODEX 8200 MODEM AND RDBM USED IN TOWER CAB SYSTEM AT TAMPA FIGURE 8.




FIGURE 9. ARTS IIIA INTERFACE DIAGRAM

3. The failure requires actual maintenance effort to correct, as opposed to a transient outage which can be reset or master-cleared.

In addition to these general criteria, a failure was charged against the telephone line whenever sufficient degradation occurred to call in the telephone company.

UNIT FAILURE RATES, MTBF's, and MTTR's. The failure rates, MTBF's, and MTTR's for each of the nine types of units comprising a TCDD system were then determined for each of the eight systems evaluated. This was done by determining the total uptime (U), total number of chargeable failures (N), and total repair time (C) for each type of unit per system. These nine types of units, together with the number of enits per type per system, are as follows:

Unit Type No. of Uni	ts Per System
Display processor unit	1
Power supply chassis	1
Display	1
Keyboards	2
Remote control panel	1
Trackball	2
Buffer	1
Modem	1
Telephone lines	1

All systems used Codex 4800 modems except for the following:

Tampa - Codex 8200 modem (tower), no modem in maintenance system

St. Petersburg - One Codex 9600 modem for both tower and maintenance system

The values U and C were expressed in terms of unit-hours. In the case of the keyboards and trackballs, which are duplicated, U and C for each of these types of units consist of the sum of the corresponding quantities for each of the two units comprising the unit type for a system.

Since an underlying exponential (constant failure rate) statistical distribution is assumed for the failure and repair rates, the following formulas were used for each type of unit:

Failure rate (λ) = $\frac{N \times 10^6}{U}$ failures per million hours

MTBF = U/N hours

MTTR = C/N hours

SYSTEM FAILURE RATE, MTBF, AND MTTR. To compute the overall system failure rate, MTBF, and MTTR; a reliability model was employed to determine which of the units must be operational to achieve full and complete equipment functional capability. This model is shown in figure 10. All units are considered to be in a series from a reliability standpoint. The system failure rate, MTBF, and MTTR are expressed as follows:


System failure rate
$$(\lambda_s) = \sum_{i=1}^{9} (\lambda_i)$$

where λ_i represents the failure rate of each of the nine unit types comprising the system.

System MTBF = $10^6 / \lambda_s$ hours

System MTTR =
$$\sum_{i=1}^{9} \frac{(\lambda_i \times MTTR)}{\lambda_e}$$
 hours

In addition to the MTBF and MTTR determination considering chargeable hardware and telephone line failures only, this



report also discusses all other types of malfunctions which were experienced by the four systems at St. Petersburg and MacDill during the official test period. Finally, summation of problem areas encountered by all eight systems over the entire period of observation is presented.

RESULTS

MTBF AND MTTR SUMMATION (CHARGEABLE FAILURES).

In appendix A, tables A-1 through A-4 show the unit and system chargeable failure summations for the St. Petersburg and MacDill sites during the official test period. Only five chargeable hardware failures occurred, three of which were in the St. Petersburg maintenance system.

Also in appendix A, tables A-5 through A-12 give the unit and system chargeable failure summations for all eight systems from the time each became operational until just prior to the official test. The data collection for the four systems at Tampa and Sarasota was terminated on December 31 since these systems were not officially operable during January and February 1980. These tables show that for the period prior to the official test, comprising approximately 16,000 system-hours of operation, 23 chargeable hardware failures including telephone line outages occurred. This corresponds to an average system MTBF of 653 hours. Excluding the phone line failures, the corresponding MTBF for the pretest period would be 937.5 hours.

Table A-13 shows combined chargeable failure summations for the five operational TCDP systems (four tower systems plus the MacDill GCA system). These values include the official test period for the MacDill and St. Petersburg systems plus the pretest periods for all four sites. The unit (element) type

values for the total uptimes, number of chargeable failures, and total repair times are the sums of the corresponding quantities in tables A-1 through A-12. In the case of the modems, only Codex 4800 modems were considered in summating this element type. Twenty chargeable hardware failures (including six telephone line outages) occurred in slightly over 15,000 system-hours of operation corresponding to an average system MTBF of approximately 725 hours with a 2.56-hour MTTR.

Table A-14 provides a similar summation for the three maintenance systems (at Tampa, St. Petersburg, and Sarasota). For these three systems, eight chargeable hardware failures occurred in approximately 6,000 system hours of operation, corresponding to a system MTBF of 705 hours with a 2.37-hour MTTR.

Table 1 shows the combined total chargeable failure summation for all eight systems over the entire period of observation including the official test and the times previous to it. It is seen that 28 chargeable hardware failures occurred in slightly more than 21,000 system-hours of operation, resulting in an overall MTBF of 706.20 hours and an overall MTTR of 2.48 hours. This means that for any TCDD system, including phone lines and modems, one can expect on the average one hardware failure in slightly less than I month with an average of 2.48 hours required to repair it and restore the system to operation. Excluding the seven chargeable telephone line failures, the overall system MTBF was 1000.8 hours with an MTTR of 2.86 hours.

The location and nature of the 28 chargeable hardware failures are as follows:

1. Display Processor (Unit 1), Nine Failures

a. Shaky display. Loose printed circuit boards (PCB's).

TABLE 1. OVERALL MTBF AND MTTR SUMMATION

August 25, 1979 - February 29, 1980

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate (per million hra	MTBF (hr)	MTTR (hr)
Display Processor (unit 1)	21,170.05	· 9	18.5	425.13	2,352.23	2.05
P.S. Chassis (unit 2)	21,183.25	3	5.3	141.62	7,061.08	1.77
Display (unit 3)	21,055.03	4	28.38	189.98	5,263.76	7.09
Keyboard	36,313.15	1	2.25	27.54	36,313.15	2.25
Remote Control Panel (unit 5)	21,188.55	0				
Trackball	36,318.4	0		~-	~~	
RDBM	21,182.3	3	6.25	141.63	7,060.7	2.08
Modem (Codex 4800)	13,644.95	1	0.5	73.29	13,644.95	0.5
Telephone Line	16,793.0	7	11.0	416.84	2,399.0	1.57
SYSTEM TOTAL			72.18	1,416.03	706.20	2.48

⁻⁻ Indicates no computations made because there were no failures.

- b. Parity errors generated when using trackball. Defective Al5 (input data interface) PCB.
- c. Minus 15-volt short to ground in A22 (deflection generator) PCB.
- d. Vectors too short. Defective A21/22 (deflection generator) PCB.
- e. Flashing characters. Defective 1A20 (analog character generator) PCB.
- f. Bad retrace. Defective A2 (format generator logic A) PCB.
- g. Constant fixed off-centering. Defective Al6 (control panel logic) PCB.
- h. Vectors out of alignment. Defective 1A9 (vector ramp generator) PCB.
- Range rings not circular.
 Replaced display processor with spare.

2. Power Supply Chassis (Unit 2), Three Failures

- a. Intermittent drop-out of 28-volt power supply (recurring problem).
- b. Defective 28-volt power supply. Voltage dropped and was restored when power switch was recycled. Filter capacitor had 10-volt ripple.
- c. System down. Pin in cannon plug of power supply chassis was pulled out because of pinched cable.

3. Display (Unit 3), Four Failures

- a. Blown 28-volt fuse. Defective focus power supply.
- b. Display information shifted off screen toward north. Defective 3A2 deflection amplifier.

- c. Display went blank. Defective resistor R25 in 3A6 video unblank amplifier module (Over 34 man-hours of repair and alignment time were required due to lack of accurate up-to-date procedures.)
- d. Brightness problem. Defective 3A6 video unblank amplifier module.

4. Keyboard (Unit 4), One Failure

a. Inputted erroneous information when panel lights were turned up full. Heat from lights damaged keyboard code logic PCB 4A2.

5. RDBM, Three Failures

- a. Parity Error. Defective A7 (I/O logic) PCB 7156700.
- b. Failed performance operational and functional appraisal (POFA) test. Defective programmable read-only memory (PROM) PCB 7163360.
- c. Blank display. Defective microregister PCB 7156705.

6. Modem (Codex 4800), One Failure

a. Data link problem. Replaced Al through A4 PCB's.

7. Telephone Lines, Seven Failures

a. Tower and GCA phone lines at MacDill and maintenance phone line at Sarasota were excessively noisy requiring telephone company repair seven times.

OTHER SYSTEM OUTAGES.

In addition to the overall 28 chargeable hardware failures which were described previously, there were many other system outages which were attributed to other causes. These include transient failures which were corrected by resetting or recycling a switch,

automatic restarts or master clears, untraceable noise on telephone lines, failures due to environmental causes, and failures due to indeterminate causes. These are summarized below for the four systems at St. Petersburg and MacDill for the official test period only (January 7 to February 29, 1980). These outages were not considered to be chargeable.

- 1. Automatic Restarts Over 40 automatic RDBM restarts were logged at MacDill Air Force Base between January 4 and February 11. Some were caused by system reconfigurations, some by noise on the telephone lines, and still others by hardware glitches. The causes of the very intermittent restarts are difficult to determine.
- 2. Display Blanking Three instances of display blanking occurred at MacDill Air Force Base. One resulted in a 2-hour outage because of an ARTS IIIA communications multiplexer controller outage at Tampa. The second instance involved 6 hours of intermittent periodic display blanking caused by RDBM restarts which were attributed to noisy and marginal telephone lines. The third instance also was due to numerous automatic restarts necessitated by excessive phone line noise.

At St. Petersburg, five instances of display blanking occurred. As at MacDill, all of these occurred during January. One was transitory and was corrected by an RDBM reset. Three others were also transitory and were reset by recycling the power switch of the 9600 modem. The fifth was caused by human error when a plug was inadvertently pulled out during maintenance.

3. Phone Line Problems - Noisy phone lines constituted a recurring problem at MacDill, which uses a Codex 4800 modem in contrast to St. Petersburg, which uses a Codex 9600 modem. The noisy phone lines at MacDill were a factor in the automatic restarts and display blankings.

4. Environmental Problems - Two instances of degraded performance occurred at the St. Petersburg facility as a result of too high an ambient temperature in the maintenance system. In each case, when the room temperature reached 90° F, the degradation manifested itself. In one case, the display was shaky; in the other case, range rings were flattened on the right side. In addition to these two cases observed during the official test, two similar cases were observed at St. Petersburg during the pretest period.

OVERALL GENERAL RESULTS.

- 1. System Summary Without Telephone Lines As discussed previously, table I provides on overall summary for all eight systems, including the telephone lines. As seen from this table, seven of the 28 chargeable failures occurred in the telephone lines. If these were excluded from consideration, the overall system MTBF would then become 1001 hours with a 2.9-hour MTTR. This would correspond to an average of one chargeable failure occurring every 1.4 months with an average time of 2.9 hours required to restore the system to normal operation.
- 2. Measured Versus Predicted MTBF As discussed above, the overall measured MTBF obtained using all collected data for all eight systems (less telephone lines) was 1001 hours. While a corresponding predicted value is not available for comparison, predicted failure rates and MTBF's for various portions of the configuration are available in the contractor's reliablity design plan. Table 2 shows these predicted values compared to the corresponding measured values taken from table 1.

For a TCDD system not including the RDBM, modem, or telephone lines, a measured MTBF of 1,275 hours was obtained. This is lower than the corresponding predicted value of 1,736 hours. The overall measured MTBF for

TABLE 2. PREDICTED VERSUS MEASURED MTBF VALUES

Failure Rate In Failures Per Million Hours

MTBF (Hours)

			indi (modio)			
Element Type	Predicted	Measured	Predicted	Measured		
Display processor (unit 1)	- - ·	425.13		2,352.23		
P.S. Chassis (unit 2		141.62		7,061.08		
Display (unit 3)		189.98		5,263.76		
Units 1, 2, and 3 combined	464.525	756.73	2,152.737	1,321.5		
Keyboard (unit 4)	77.962	27.54	12,826.762	36,313.25		
Panel (unit 5)	7.28	0	137,362.64			
Trackball (unit 6)	26.285	0	38,044.51			
TOTAL (units 1 through 6, combined)	576.052	784.27	1,735.954	1,275.07		

⁻⁻ Indicates no computations made because there were no failures.

the display processor, display unit, and power supply chassis, combined, is 1,322 hours, which is lower than the corresponding predicted value of 2,153 hours.

The display processor showed the lowest measured MTBF (2,325 hours) of any of the elements in the system. The telephone lines had the second lowest measured MTBF (2,399 hours).

It is seen from table 2 that the observed MTBF for a system configuration which does not include the RDBM, modem, or telephone lines is 1275 hours versus a corresponding predicted value of 1736 hours.

Table 3 lists recommended MTBF specification values for the production TCDD equipment units and system.

3. Preventive Maintenance - At each of the sites, preventive maintenance activities were performed on a daily, semi-weekly, weekly, monthly, and quarterly basis depending on the nature

of the activity. The weekly preventive maintenance activities included special diagnostic POFA tests which exercise the logic in the various elements or units of the system.

4. Codex 4800 Versus 9600 Modems During most of this evaluation, the St. Petersburg facility was equipped with a Codex 9600 modem and the Sarasota and MacDill facilities with Codex 4800 modems. The Codex 4800 modem was used with an unconditioned telephone line and was sensitive to noise. This situation, especially at MacDill, contributed to such undesirable effects as automatic restarts and jittery displays. On-site personnel observed that the Codex 9600 modem used with a conditioned phone line resulted in better performance than a Codex 4800 modem used with unconditioned phone lines. (Note: Direct performance comparisons using conditioned and unconditioned telephone lines for each modem type were not made).

On February 8, the Codex 4800 modems at MacDill were replaced with Codex 9600 modems using conditioned phone lines.

TABLE 3. RECOMMENDED MTBF SPECIFICATION VALUES FOR TCDD EQUIPMENT AND SYSTEM (HRS)

Display processor	<u>></u> 2,000	(measured)
RDBM	<u>></u> 7,000	(measured)
Power supply	≥ 7,000	(measured)
Display	<u>></u> 5,000	(measured)
Keyboard	<u>></u> 30,000	(measured)
Trackball	≥ 30,000	(predicted)
Remote panel	<u>></u> 100,000	(predicted)
Modems	<u>></u> 10,000	(measured)
System (including all the above items)	<u>></u> 1,000	(measured)

These were operated at 9600- and 4800-bit-per-second rates for experimental purposes. The 9600-bit rate was observed by on-site personnel to have positive benefits among which were: (1) restarts lasted only 2 to 3 seconds; (2) keyboard, trackball, and quick-look entries responded faster; and (3) the tracking range did not fluctuate as it would have at the 4800-bit rate.

Even at a 4800-bit rate, site personnel reported that the Codex 9600 modem would be advantageous because it can accommodate noise which may cause jitter with the Codex 4800 modem.

By the end of this evaluation period, all sites had been equipped with Codex 9600 modems and were awaiting conditioning of the telephone lines.

5. Alignment Problems - At Sarasota, difficulty was encountered in aligning the system after replacing the cathode ray tube (CRT) which had been burned out as a result of a -15-volt short circuit. Several iterative realignments were necessary before satisfactory performance was restored.


Also at Sarasota, after another CRT replacement, alignment and trouble-shooting times were excessively long. This was caused by inaccurate obsolete procedures, many of which did not reflect hardware changes.

6. Environmental Problems - On four separate occasions, blinking, shaky targets, or other abnormal display conditions were noted in the St. Petersburg maintenance system where the ambient temperature in the equipment room reached 90° F.

7. Miscellaneous Problems

- a. <u>Keyboard Heat Problem</u> At St. Petersburg, erroneous data were outputted from the keyboard when the panel was at its highest light intensity. The keyboard code logic PCB was damaged by the excessive heat generated. Figure 5 shows this intensity control on the keyboard.
- b. Bent Pins The pins on the display processor PCB's are easily bent if they are not properly aligned before insertion. In addition, bent pin problems occurred in the connector plugs going into the keyboard, trackball, and remote panel. The problem here is that there are plastic rings in the connector plugs which engage the pins before the keying slots make contact, thereby bending the pins. Figure 11 shows a typical connector plug with damaged pins.
- c. PCB Potentiometers Many of the potentiometers mounted on PCB's have adjustments on the bottom side rather than the top edge of the PCB's. An example of this is shown in figure 12. The use of an extender board is required whenever it becomes necessary to align the potentiometer. This involves (1) powering down the equipment, (2) inserting the extender board, (3) restoring power, (4) making the alignment, (5) removing power, (6) removing the extender board, and (7) restoring power. All this increases the MTTR.
- 8. Replaced PCB's and Modules The following PCB's and modules were replaced during the period of this reliability and maintainability evaluation:

FIGURE 11. TYPICAL CONNECTOR PLUG SHOWING DAMAGED PINS



a.	Display Processor -					
	A2 - Format generator logic A PCB		Part	No.	912352	(1)
	A9 - Vector ramp generator PCB		Part	No.	912544	(1)
	Al5 - Input data interface PCB		Part	No.	912363	(1)
	Al6 - Control panel logic PCB		Part	No.	912364	(1)
	A20 - Character generator analog PCI	3	Part	No.	912375	(1)
	A22 - Deflection generator PCB		Part	No.	912362	(2)
	±15-Volt power supply		Part	No.	SPS-90D	(1)
ь.	Power Supply Chassis -					
	28-Volt power supply Lambda LO	SW-28				(2)
c.	Display Unit					
	Cathode ray tubes (CRT's)					(2)
	3A2 - Deflection amplifier module					(1)
	3A6 - Video unblank amplifier modul	le				(2)
	3PSI - Focus power supply module					(1)
đ.	Keyboard					
	4A2 - Keyboard code logic PCB		Part	No.	912371	(1)
e.	Codex 4800 Modem					
	Al - Digital card	Codex	Part	No.	33601G1	(1)
	A2 - Analog card	Codex	Part	No.	33601G2	(1)
	A3 - Digital card	Codex	Part	No.	33601G3	(1)
	A4 - Analog card	Codex	Part	No.	33601G4	(1)
f.	RDBM					
	A7 - I/O logic PCB		Part	No.	7156700	(1)
	A15 - PROM PCB		Part	No.	7163360	(1)
	Ale - Michansistan DCB		T		7156705	(1)

It has been reported that an RDBM-resident TCDD diagnostic has been developed and is currently being implemented in the Tampa TCDD systems. This diagnostic was not available to maintenance technicians during the test period. The MTTR values for the display subsystem, therefore, may improve as this new diagnostic becomes available.

CONCLUSIONS

- 1. For a Tower Cab Digital Display (TCDD) system excluding the Remote Display Buffer Memory (RDBM), the modem, or the telephone lines, the measured value was lower than the corresponding predicted value. The overall MTBF for the display processor, display unit, and power supply chassis, combined, was also lower than the corresponding predicted value. The display processor and the telephone lines had the lowest and the second lowest measured MTBF, respectively, of any of the elements in the system.
- 2. Troubleshooting and alignment times which were excessively long in some cases contributed to the high system MTTR of 2.48 hours. For instance, adjustments of potentiometers mounted on the PCB's are difficult sometimes because the adjusting screws are on the bottom side rather than the top of the potentiometer. An extender board must be used when aligning the potentiometer.
- 3. Considerable degradation of equipment performance due to noise on the telephone lines was observed by site personnel when a Codex 4800 modem and an unconditioned phone line were used. Use of a Codex 9600 modem with a conditioned phone line has reportedly improved this situation.

- 4. Degradation of equipment performance in the maintenance room occurred when the ambient room temperature reached 90° F. Normal performance was restored when the temperature dropped to 80° F or 85° F.
- 5. Erroneous data were outputted from the keyboard when the panel display light intensity was fully illuminated. The keyboard code logic printed circuit board (PCB) failed because of the excessive heat generated.
- 6. Pins on connector plugs and PCB's are easily bent if not properly aligned before insertion, and the locking rings on the plastic connector plugs break.

RECOMMENDATIONS

- 1. The mean-time-between-failure (MTBF) values shown in table 3 should be used as the minimum MTBF parameters for inclusion in the production specification.
- 2. The mean-time-to-repair (MTTR) of over 2 hours for the system is excessive. The production system specification should call for an MTTR of no more than 1 hour.
- 3. Reasons for the failure of the Tower Cab Digital Display (TCDD) maintenance system when the ambient room temperature is 90°F or greater should be investigated.
- 4. The following design changes are recommended:
- a. Consideration should be given to improving the design of the display processor to increase its MTBF.
- b. The keyboard code logic printed circuit board (PCB) 4A2 (Part

- No. 912371), which is contained within the keyboard assembly (unit 4), should either be redesigned or possibly relocated so that its performance will not be adversely affected by the heat generated when the panel light is turned up to full intensity. Temperature measurements should be made to help isolate the problem.
- c. The PCB's and connector plugs should be examined to determine design improvements which would allow for their easier insertion without bending the pins.
- d. Consideration should be given to mounting the potentiometers on the top edge of the PCB's to allow adjustment without using an extender board. This change would save the time required to turn the system off and on when inserting and removing the extender board, thereby reducing the MTTR.

- e. Consideration should be given to having all display alignments in the display unit rather than in the display processor as is now done. Alignment of the display unit would be easier and the MTTR reduced.
- f. To provide more flexible installation, consideration should be given to increasing the allowable cable length between the RDBM and the display processor from its present limit of 200 feet.
- 5. Comparative tests under controlled conditions should be made with the TCDD system using Codex 4800 and 9600 modems with both conditioned and unconditioned telephone lines for each type of modem. Based on data obtained from such tests, an appropriate recommendation concerning use of modems and telephone lines could be made.

APPENDIX A MTBF AND MTTR SUMMATIONS

LIST OF TABLES

Table		Page
A-1	Tower System, MacDill Official Test January 7 - February 29, 1980	A-1
A-2	GCA System, MacDill Official Test January 7 - February 29, 1980	A-2
A-3	Tower System, St. Petersburg Official Test January 7 - February 29, 1980	A-3
A-4	Maintenance System, St. Petersburg Official Test January 7 - February 29, 1980	A-4
A- 5	Tower System, St. Petersburg (Pretest) October 26, 1979 - January 6, 1980	A- 5
A-6	Maintenance System, St. Petersburg (Pretest) October 26, 1979 - January 6, 1980	A-6
A-7	Tower System, Tampa (Pretest) December 2 - December 31, 1979	A- 7
A-8	Maintenance System, Tampa (Pretest) December 2 - December 31, 1979	A-8
A-9	Tower System, Sarasota (Pretest) September 6 - December 31, 1979	A-9
A-10	Maintenance System, Sarasota (Pretest) September 6 - December 31, 1979	A-10
A-11	Tower System, MacDill (Pretest) August 25, 1979 - January 6, 1980	A-11
A-12	GCA System, MacDill (Pretest) August 25, 1979 - January 6, 1980	A-12
A-13	Combined Tower and GCA Systems, All Sites August 25, 1979 - February 29, 1980	A-13
A- 14	Maintenance Systems (Combined), All Sites	A-14

TABLE A-1. TOWER SYSTEM MACDILL OFFICIAL TEST

January 7 - February 29, 1980

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate (per million hrs)	MTBF (hr)	MTTR (hr)
Display						
Processor (unit 1)	1296	0				
P.S. Chassis						
(unit 2)	1296	0		* 		
Display						
(unit 3)	1296	0				
Keyboard	2592	0				
Remote Control						
Panel (unit 5)	1296	0				
Trackball	2592	0				
RDBM	1296	0				
Modem						
(Codex 4800)	1296	0				
Telephone Line	1296	0				
SYSTEM TOTAL		0	0	0		0

⁻⁻ Indicates no computations made because there were no failures

TABLE A-2. GCA SYSTEM MACDILL OFFICIAL TEST

January 7 - February 29, 1980

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate (per million hrs)	MTBF	MTTR (hr)
Display Processor (unit 1)	1296	0				
P.S. Chassis (unit 2)	1296	0			~-	
Display (unit 3)	1296	0				
Keyboard	2592	0			~~	
Remote Control Panel (unit 5)	1296	0				
Trackball	2592	0				~-
RDBM	1295.5	1	0.5	771.90	1295.5	0.5
Modem (Codex 4800)	1296	o				
Telephone Line	1296	1	1.0	771.60	1296.0	1.0
SYSTEM TOTAL		2		1543.50	647.9	0.75

⁻⁻ Indicates no computations made because there were no failures

TABLE A-3. TOWER SYSTEM ST. PETERSBURG OFFICIAL TEST

January 7 - February 29, 1980

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate (per million hrs)	MTBF (hr)	MTTR (hr)
Display		•				
Processor (unit 1)	1295.5	0		No. 100		
P.S. Chassis						
(unit 2)	1295.5	0				
Display	1005 5	0				
(unit 3)	1295.5	U				
Keyboard	2591.0	0				
Remote Control	1005 5	•				
Panel (unit 5)	1295.5	0				
Trackball	2591.0	0				
RDBM	1295.5	0				
Modem						
(Codex 9600)	647.75	0				
Telephone Line	647.75	0				
SYSTEM TOTAL		0	0	0		0

⁻⁻ Indicates no computations made because there were no failures

TABLE A-4. MAINTENANCE SYSTEM ST. PETERSBURG OFFICIAL TEST

January 7 - February 29, 1980

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate (per million hrs)	MTBF (hr)	MTTR (hr)
Display Processor (unit 1)	1295.8	0				
P.S. Chassis (unit 2)	1295.5	1	0.3	771.9	1295.5	0.3
Display (unit 3)	1289.47	1	6.33	775.51	1289.47	6.33
Keyboard	1295.8	0				
Remote Control Panel (unit 5)	1295.8	0				
Trackball	1295.8	0				
RDBM	1294.05	1	1.75	772.77	1294.05	1.75
Modem (Codex 9600)	647.9	0				
Telephone Line	647.9	0				
SYSTEM TOTAL		3	-	2320.18	431	2.80

⁻⁻ Indicates no computations made because there were no failures

EXECUTIVE SUMMARY

			~~ ~~ ~~ ~~ ~~ ~~	
			PARTS	
	OPERATIONAL	EQUIPMENT	REPLACEMENT	SPECIFICATION
EQUI PMENT/SYSTEM	PARAMETER	PARAMETER	PARAMETER	PARAMETER
RELIABILITY: (MTBF	in hours)			
CATCC-DAIR	661*	971	1304	700
NAVMACS A+	2422	2049	2220	250
CV-3333	23,839	23,839	47,677	2000
ON-143(V)5	16,173	16,173	16,173	
MAINTAINABILITY: (MTTR/MDT in h	ours)		
CATCC-DAIR	18/162	•	17.5/102	0.75
NAVMACS A+	3.4/396			
CV-3333	16.5/120		13/168	0.3
ON-143(V) 5	•		3/72	0.3
ON-143(A) 2	3/72	3/72	3/12	
AVAILABILITY:	EFFECTIVE			
CATCC-DAIR	0.9996	0.525		
NAVMACS A+	0.9627	0.9697		
CV-3333	0.9949	0.9965	0.9965	
ON-143(V)5	0.9988	0.9988	0.9988	

^{*&}quot;All Data" value is given. No operational failures (greater than 10% loss of capability) encountered.

COMMENTS/RECOMMENDATIONS

CATCC DAIR

- (1) It is recommended that ECP's and retrofits be developed to improve the reliability performance of the Control Group Console, OD-146, with emphasis on the Deflection Amplifier and the Power Supply.
- (2) It is recommended that the "Human Engineered" keyboards in the OD-58 consoles be replaced with standard typewriter/teletype style keyboards.

NAVMACS A+

- (1) Several problems associated with the paper feed rollers of the TT-624 printers were observed; however, because of the age of this model, no design changes are recommended. Use of the available pin-drive tractor-feed with edge-perforated paper to eliminate the roller problem is recommended. Other problems associated with print ribbons indicate that the TT-624 should be replaced by a newer, better design when possible.
- (2) Consideration should be given to a mod to the RD-397 air filter, which picks up paper tape chaff, clogs, and causes overheating.

CV-3333

(1) Excellent Reliability Performance.

ON-143(V) 5

- (1) Extremely Good Reliability Performance.
- (2) The baud rate problem -- described in Vol 1, para 2-4.3, and in Vol 2D, para 1-1.2 and para 4-2 -- should be resolved either by re-programming or by other means.

TABLE A-5. TOWER SYSTEM ST. PETERSBURG (PRETEST)

October 26, 1979 - January 6, 1980

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate (per million hrs)	MTBF (hr)	MTTR (hr)
Display Processor (unit 1)	1748.9	2	3.1	1143.58	874.45	1.55
P.S. Chassis (unit 2)	1752	0			~-	
Display (unit 3)	1752	0				
Keyboard	3501.75	1	2.25	285.57	3501.75	2.25
Remote Control Panel (unit 5)	1752	0				
Trackball	3504	0				
RDBM	1752	0				
Modem (Codex 9600)	876	0				
Telephone Line	876	0				
SYSTEM TOTAL		3		1429.15	699.72	1.69

⁻⁻ Indicates no computations made because there were no failures

TABLE A-6. MAINTENANCE SYSTEM ST. PETERSBURG (PRETEST)

October 26, 1979 - January 6, 1980

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate (per million hrs)	MTBF (hr)	MTTR (hr)
Display Processor (unit 1)	1749.6	1	2.4	571.56	1749.6	2.4
P.S. Chassis (unit 2)	1752	0				
Display (unit 3)	1752	0				
Keyboard	1752	0				
Remote Control Panel (unit 5)	1752	0 .			~~	
Trackball	1752	0				
RDBM	1752	0				
Modem (Codex 9600)	876	0				
Telephone Line	876	0				
SYSTEM TOTAL		1		571.56	1749.6	2.4

⁻⁻ Indicates no computations made because there were no failures

TABLE A-7. TOWER SYSTEM TAMPA (PRETEST)

December 2 - December 31, 1979

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate per million hrs)	MTBF (hr)	MTTR (hr)
Display						
Processor (unit 1)	714.4	1	0.5	1399.78	714.4	0.5
P.S. Chassis						
(unit 2)	714.9	0				
Display		•				
(unit 3)	711.2	1	3.7	1406.07	711.2	3.7
Keyboard	1429.8	0				
Remote Control						
Panel (unit 5)	714.9	0				
Trackball	1429.8	0				
RDBM	714.9	0				
Modem						
(Codex 8200)	714.9	0				
Telephone Line	714.9	0				
SYSTEM TOTAL		2		2805.85	356.4	2.1

⁻⁻ Indicates no computations made because there were no failures

TABLE A-8. MAINTENANCE SYSTEM TAMPA (PRETEST)

December 2 - December 31, 1979

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate (per million hrs)	MTBF (hr)	MTTR (hr)
Display Processor (unit 1)	713.9	1	1.0	1400.76	713.9	1.0
P.S. Chassis (unit 2)	714.9	0	0			
Display (unit 3)	714.9	0	0			
Keyboard	714.9	0	0			
Remote Control Panel (unit 5)	714.9	0	0			
Trackball	714.9	0	0			
RDBM	714.9	0	0			
Modem						
Telephone Line		~ →				
SYSTEM TOTAL		1		1400.76	713.9	1.0

⁻⁻ Indicates no computations made because there were no failures

TABLE A-9. TOWER SYSTEM SARASOTA (PRETEST)

September 6 - December 31, 1979

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate (per million hrs)	MTBF	MTTR (hr)
Display Processor (unit 1)	2285.95	2	9.5	874.91	1142.98	4.75
P.S. Chassis (unit 2)	2295.45	0				
Display (unit 3)	2172.95	1	17.35	460.2	2172.95	17.35
Keyboard	4590.9	0				
Remote Control Panel (unit 5)	2295.45	0				
Trackball	4590.0	0	٠			
RDBM	2295.45	0				
Modem (Codex 4800)	2295.45	0				
Telephone Line	2295.45	0				
SYSTEM TOTAL		3		1335.11	749	9.09

⁻⁻ Indicates no computations made because there were no failures

TABLE A-10. MAINTENANCE SYSTEM SARASOTA (PRETEST)

September 6 - December 31, 1979

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate (per million hrs)	MTBF (hr)	MTTR (hr)
Display Processor (unit 1)	2296					
P.S. Chassis		v				
(unit 2)	2293	1	3.0	436.11	2293	3.0
Display (unit 3)	2296	0				
Keyboard	2296	0				
Remote Control Panel (unit 5)	2296	0 .				
Trackball	2296	0				
RDBM	2292	1	4.0	436.3	2292	4.0
Modem (Codex 4800)	2296	0				
Telephone Line	2295	1	1.0	435.73	2295	1.0
SYSTEM TOTAL		3		1308.14	764.5	2.67

⁻⁻ Indicates no computations made because there were no failures

TABLE A-11. TOWER SYSTEM MACDILL (PRETEST)

August 25, 1979 - January 6, 1980

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate (per Million hrs)	MTBF (hr)	MTTR (hr)
Display		•				
Processor (unit 1)	3239	1	1.0	308.74	3239	1.0
P.S. Chassis (unit 2)	3238	1	2.0	308.83	3238	2.0
		_				
Display (unit 3)	3240	0				
Keyboard	6477	0				
Remote Control Panel (unit 5)	3240	0				
Trackball	6480	0				
RDBM	3240	0				
Modem (Codex 4800)	3222	0				
(Codex 4000)	3222	v				
Telephone Line	2924	4	6.0	1368.00	731.00	1.5
SYSTEM TOTAL		6		1985.57	503.63	1.5

NOTE: All failures (except telephone lines) occurred between August 26 and October 11, 1979.

⁻⁻ Indicates no computations made because there were no failures

TABLE A-12. GCA SYSTEM MACDILL (PRETEST)

August 25, 1979 - January 6, 1980

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate (per million hrs)	MTBF (hr)	MTTR (hr)
Display Processor (unit 1)	3239	. 1	1.0	308.74	3239	1.0
P.S. Chassis (unit 2)	3240	0				
Display (unit 3)	3239	1	1.0	308.74	3239	1.0
Keyboard	6480	0				
Remote Control Panel (unit 5)	3240	0 .				
Trackball	6480	0		~		
RDBM	3238	0				
Modem (Codex 4800)	3239.5	1	0.5	308.69	3239.5	0.5
Telephone Line	2924	1	3.0	342.00	2924	3.0
SYSTEM TOTAL		4		1268.17	788.54	1.42

NOTE: All failures (except telephone lines) occurred between August 26 and October 11, 1979.

⁻⁻ Indicates no computations made because there were no failures

TABLE A-13. COMBINED TOWER AND GCA SYSTEMS ALL SITES

August 25, 1979 - February 29, 1980

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate (per million hrs)	MTBF (hr)	MTTR (hr)
Display Processor		•				
(unit 1)	15,114.75	7	15.1	463.12	2,159.25	2.16
P.S. Chassis (unit 2)	15,127.85	1	2.0	66.10	15,127.85	2.0
Display (unit 3)	15,002.63	3	22.05	199.96	5,000.88	7.35
Keyboard	30,254.45	1	2.25	33.05	30,254.45	2.25
Remote Control Panel (unit 5)	15,129.85	0				
Trackball	30,259.7	0				
RDBM	15,129.35	1	0.50	66.097	15,129.35	0.5
Modem (Codex 4800)	11,348.95	1	0.5	88.11	11,348.95	0.5
Telephone Line	12,974.1	6	10.0	462.46	2,162.35	1.67
SYSTEM TOTAL		20		1,378.9	725.22	2.56

⁻⁻ Indicates no computations made because there were no failures

TABLE A-14. MAINTENANCE SYSTEMS (COMBINED)
ALL SITES

August 25, 1979 - February 29, 1980

Element Type	Total Uptime (hrs)	No. of Chargeable Failures	Total Repair Time (hrs)	Failure Rate (per million hrs)	MTBF (hr)	MTTR (hr)
Display Processor						
(unit 1)	6055.3	2	3.4	330.29	3027.6	1.7
P.S. Chassis (unit 2)	6055.4	2	3.3	330.28	3027.7	1.65
Display (unit 3)	6052.4	1	6.33	165.22	6052.4	6.33
Keyboard	6058.7	0				
Remote Control Panel (unit 5)	6058.7	o				
Trackball	6058.7	0				
RDBM	6052.95	2	5.75	330.42	3026.5	2.875
Modem (Codex 4800)	2296*	0				
Telephone Line	3818.9	1	1.0	261.86	3818.9	1.0
SYSTEM TOTAL		8		1418.07	705.18	2.37

^{*} Sarasota Pretest period only.

⁻⁻ Indicates no computations made because there were no failures