


MICROCOP

CHART





**N**A

10-

# NAVAL AIR STATION SIGONELLA (AUGUSTA BAY) FLEET MOORING UNDERWATER INSPECTION PLAN

# JULY 1983

OCEAN ENGINEERING AND CONSTRUCTION PROJECT OFFICE CHESAPEAKE DIVISION NAVAL FACILITIES ENGINEERING COMMAND WASHINGTON, D.C. 20374

86 4 ZZ 074

DISTRIBUTION STATEMENT A Approved for public release Distribution Unlimited

Unclassified SECURITY CLASSIFICATION OF THIS PAGE	AD-A167463
REPORT DOCUMENT.	
la. REPORT SECURITY CLASSIFICATION Unclassified	1b. RESTRICTIVE MARKINGS
2a. SECURITY CLASSIFICATION AUTHORITY	3. DISTRIBUTION AVAILABILITY OF REP. Approved for public release; distribution is unlimited
2b. DECLASSIFICATION/DOWNGRADING SCHEDULE	
4. PERFORMING ORGANIZATION REPORT NUMBER FPO 8345.5	5. MONITORING ORGANIZATION REPORT #
6a. NAME OF PERFORM. ORG. 6b. OFFICE SYM Ocean Engineering & Construction Project Office CHESNAVFACENGCOM	7a. NAME OF MONITORING ORGANIZATION
6c. ADDRESS (City, State, and Zip Code) BLDG. 212, Washington Navy Yard Washington, D.C. 20374-2121	7b. ADDRESS (City, State, and Zip )
8a. NAME OF FUNDING ORG. 8b. OFFICE SYM	9. PROCUREMENT INSTRUMENT INDENT #
8c. ADDRESS (City, State & Zip)	10. SOURCE OF FUNDING NUMBERSPROGRAMPROJECT TASK WORK UNITELEMENT ##ACCESS #
ll. TITLE (Including Security Classificat Naval Air Station Sigonella (Augusta Bay) Plan	
12. PERSONAL AUTHOR(S)	
13a. TYPE OF REPORT13b. TIME COVEREDFROMTO16. SUPPLEMENTARY NOTATION	14. DATE OF REP. (YYMMDD) 15. PAGES 83-07 22
17. COSATI CODES 18. SUBJE	CT TRANC (Cartinua an noverse if nos)
FIELD GROUP SUB-GROUP Under Fleet	CT TERMS (Continue on reverse if nec.) water inspection, Mooring inspection, moorings, Naval Air Station Sigonella ta Bay, Sicily
19. ABSTRACT (Continue on reverse if nece As part of COMNAVFACENGCOM's Fleet Moorin CHESNAVFACENGCOM has been assigned the re underwater inspections of fleet moorings	g Maintenance (FFM) Program, sponsibility to conduct the worldwide. This plan provides
<pre>quidelines for the underwater inspection 20. DISTRIBUTION/AVAILABILITY OF ABSTRACT SAME AS RPT.</pre>	of the fleet mooring operated (Con't) 21. ABSTRACT SECURITY CLASSIFICATION
22a. NAME OF RESPONSIBLE INDIVIDUAL Jacqueline B. Riley	22b. TELEPHONE 22c. OFFICE SYMBOL 202-433-3881

٠.

1.1

÷.,

.....

٠.

٠.

BLOCK 19 (Con't)

and maintained by the Naval Air Station (NAS), Sigonella, Sicily. The inspection is scheduled to take place in September 1983.

CHESNAVFACENGCOM has designated an Engineer-in-Charge (EIC) to provide on-site technical guidance to Underwater Construction Team One (UCT ONE) who will perform the underwater portion of the inspection. In addition, the EIC will prepare the post inspection report which will include the results of the inspection and recommendations for required maintenance actions.

# TABLE OF CONTENTS

.

Paragraph		Page
1.0	BACKGROUND	1
2.0	PROJECT RESPONSIBILITIES	1
3.0	GENERAL MOORING HISTORY	1
4.0	INSPECTION PROCEDURES     4.1   Inspection Objectives     4.2   Buoy     4.2.1   Buoy Upper Portion     4.2.2   Buoy Lower Portion     4.2.3   Bottom Jewelry     4.3   Riser     4.4   Ground Ring     4.5   Ground Legs     4.6   Anchors     4.7   Photography     4.7.1   Topside     4.7.2   Underwater	555555666
5.0	DOCUMENTATION	6
6.0	MEETINGS/BRIEFINGS	8
7.0	LOGISTICS	8
ANNEX		
А	MEASURING DEVICES AND THEIR USE	A-1
в	SAMPLE INSPECTION FORMS	B-1
С	REFERENCES	C-1

i

Accesio	on For	
NTIS DTIC Unanne Justific	TAB ounced	
By Dist: ib:	ution /	
A	vailability	Codes
Dist A-1	Avail ari Speci	

# NAVAL AIR STATION SIGONELLA UNDERWATER FLEET MOORING INSPECTION PLAN

#### 1.0 BACKGROUND

.

ţ.

•

As part of COMNAVFACENGCOM's Fleet Mooring Maintenance (FMM) Program, CHESNAV-FACENGCOM has been assigned the responsibility to conduct the underwater inspections of fleet moorings worldwide. This plan provides guidelines for the underwater inspection of the fleet mooring operated and maintained by the Naval Air Station (NAS), Sigonella, Sicily. The inspection is scheduled to take place in September 1983.

CHESNAVFACENGCOM has designated an Engineer-in-Charge (EIC) to provide on-site technical guidance to Underwater Construction Team One (UCT ONE) who will perform the underwater portion of the inspection. In addition, the EIC will prepare the post inspection report which will include the results of the inspection and recommendations for required maintenance actions.

#### 2.0 PROJECT RESPONSIBILITIES

CHESNAVFACENGCOM will develop the FM underwater insepction plan, provide technical assistance to the dive team, prepare the required inspection forms, evaluate the observed inspection data, and report and results of the inspection to interested activities.


UCT ONE will provide divers to accomplish the inspection within the allotted time frame, gather and accurately report all required data, and ensure that the required amount of diving support material/equipment is available. In addition, UCT ONE divers will perform the underwater inspection in accordance with this plan and collect the data specified in paragraph 4.0.


The activity responsible for the moorings being inspected will provide logistic support as required by the Engineer-in-Charge and the UCT dive team.


#### 3.0 GENERAL MOORING HISTORY


NAS Sigonella currently operates and maintains a Class CC Fleet Mooring located in Augusta Bay, Sicily. This mooring is installed in about 75 feet of water and was last overhauled in October 1980. Figure 1 is a schematic drawing of the mooring, including its relative geographic position, while Figure 2


1











depicts the as-built configuration of the mooring. The mooring consists of a 13-foot-long by 7-foot diameter 2nd class buoy, a 3-1/2 inch riser, a ground ring, three double legs and six 25,000-pound standard stockless anchors. Each double ground leg configuration contains a spider plate, one leg of 5 1/2 shots (495 feet) of 2-3/4 inch chain leading to an anchor, and a second ground leg consisting of 480 feet of 3-1/2 inch square link chain leading to a second anchor.

#### 4.0 INSPECTION PROCEDURES

4.1 <u>Inspection Objectives.</u> The purpose of this mooring inspection is to determine the general physical condition of the buoy and chain assembly and, when possible, to verify or update existing as-built and maintenance records. Divers will inspect only a portion of the submerged buoy hull and chain assembly in order to compile a general description of the mooring's condition. The existence of fairly consistent measurements during this inspection provides a good indication of the mooring's overall condition. It should be kept in mind that periodic underwater inspections are intended as an expedient and relatively inexpensive supplement to accurate maintenance records. As such, they cannot fully substitute for a complete inspection involving recovery of the mooring and the measurement and evaluation of each component.

One of the more important parameters used to evaluate the condition of a mooring is chain wire diameter. After the chain is cleaned to bare metal, a selective sampling of the wire diameter of chain links and connecting hardware is taken in order to determine the amount of deterioration due to corrosion and wear. "Single link" measurements are taken where chain is slack, and detect only corrosion loss. "Double link" measurements, taken where two links connect under tension, detect the combined effects of corrosion and wear. Chain links and other components which measure 90 percent or greater of original wire diameter are considered to be in "good" condition; measurement between 80 percent and 90 percent of original diameter is considered "fair" condition and is cause for the mooring to be downgraded in classification; any measurement less than 80 percent is considered "poor" and is cause for the mooring to be declared unsatisfactory for fleet use. Figure A-1 in Annex A depicts the proper method of taking both single and double link measurements.

Standard underwater inspection procedures do not call for the inspection of any part of a mooring which is buried. Ground legs and risers are observed only to the point at which they become buried; no attempt is made to locate and inspect anchors or other mooring materials which are not readily visible.

The following paragraphs contain the general inspection procedures that will be followed. Inspection check lists are contained in Annex B. **4.2 Buoy.** The geographic position of the buoy will be verified. In order to accomplish this, a transit will be used to sight the buoy from known positions ashore.

**4.2.1** <u>Buoy Upper Portion</u>. The buoy shall be observed to determine its general condition. The size of the buoy (diameter and height) should be recorded along with its freeboard. Physical damage such as holes, dents, or listing shall be described. The paint will be checked for cracking, chipping, and peeling. Hatches, openings, and penetrations will be examined and broken parts and rust will be reported.

÷.,

K

E

The buoy fenders and rubbing rails shall be checked for integrity and secure connection to the buoy.

Buoy top jewelry shall be identified and measured with calipers to find the overall outside dimensions and areas of most severe reduction in wire size. Methods for presetting calipers are contained in Annex A.

**4.2.2** <u>Buoy Lower Portion</u>. Divers shall thoroughly inspect the buoy below the waterline. The thickness of marine growth shall be recorded, three one-foot-square areas shall be selected and cleared of growth without damaging the paint and the condition of the paint will be noted.

**4.2.3 Bottom Jewelry.** The jewelry connecting the buoy to the riser shall be identified and measured with calipers. As with the topside jewelry, the overall dimensions and the smallest wire size of each type of link or shackle will be recorded.

**4.3** <u>**Riser.**</u> Three consecutive double link measurements using pre-cut gauges will be made at both ends and near the center of the riser. Procedures for the use of pre-cut gauges are contained in Annex A. The swivel and detachable links contained within the riser assembly shall be visually inspected and measured. As the divers swim down the riser, all chain links and other mooring hardware will be visually observed. Material suspected to be in worn or damaged condition will be investigated.

**4.4** <u>Ground Ring.</u> The ground ring shall be examined for general and localized wear. Caliper measurements shall be made of both the wire size in the region of most severe wear and across the inner diameter.

**4.5** <u>Ground Legs.</u> Three consecutive double link measurements of each ground leg shall be taken every 20 feet. In those cases where the ground leg chain is slack and not in tension, three single link measurements shall be taken of each selected link as shown in Figure A-1 (Annex A). Even though the grip areas are rounded, the go/no-go guages may not be able to be used for the measurement of square chain. In this event, calipers will be used for taking measurements. All connecting hardware including

detachable links, anchor joining links, pear links, end links, swivels and shackles shall be identified and measured with calipers. Worn hardware and unusual chain joining practices shall be recorded and photographed.

The legs shall be labeled A, B, and C clockwise from magnetic north and their orientation (determined by the diver's compass) sketched as in Figure 3.

4.6 <u>Anchors.</u> If an anchor is located, a pop float shall be attached to it so that the relative positions of the anchor from the mooring buoy can be observed from the surface. The anchor's position shall be recorded. The hardware connecting an anchor to its ground leg will be measured by calipers and the wire diameters recorded.

#### 4.7 Photography

**4.7.1** <u>Topside</u>. Topside photography and ashore photographs are the responsibility of the Engineerin-Charge. Film for standard size slide transparencies should be used.


Photographs will be taken of the buoy showing its general condition. Photographs of the topside jewelry and damaged buoy components will be taken as deemed appropriate by the EIC.

Photographs will be taken of ashore spare mooring material inventories and construction equipment as deemed necessary.

4.7.2 <u>Underwater</u>. Underwater photography shall be the responsibility of the dive team. The buoy bottom, bottom jewelry, worn links, swivels, ground rings, and other hardware shall be photographed wherever required to support material conditions and when environmentally feasible. Photographs shall include clear annotation as to the location of the hardware being photographed. High speed film (i.e. ASA 400) for standard size slide transparencies should be used. Because silt and other particles suspended in the water tend to reduce picture quality when illuminated, the flash should be used only when absolutely necessary to provide adequate light levels.

#### 5.0 DOCUMENTATION

The Engineer-in-Charge will document the inspection procedures used and record the data obtained by the dive team. He may require additional or alternative inspection procedures as deemed necessary during the course of the inspection. He will maintain a time log of events occurring during the



inspection, and the master inspection form. In addition, the EIC must be prepared to debrief each diver, upon his return to the surface, in order to gain immediate knowledge of what the diver observed. The information obtained from the divers will be recorded, and this data will subsequently be the basis for the development of the moorings as-built configuration and for the preparation of the Fleet Mooring Inspection Report, which will contain the results of the inspection and recommendations for corrective maintenance actions.

While on site, the EIC will investigate the availability and cost of local mooring maintenance support. In addition he will conduct a cursory inspection of any on-shore Fleet Mooring Inventory (FMI) used for maintenance and repair or ready reserve. The type, size, quantity and general condition of the inventory shall be reported.

#### 6.0 MEETINGS/BRIEFINGS

Upon arrival on site, the Engineer-in-Charge will conduct a pre-dive briefing to familiarize diving personnel with the mooring inspection procedures and to advise them of possible modifications to this inspection plan. In addition, after approval by CHESDIV, the EIC will give a post-inspection debriefing to advise station personnel of the preliminary inspection findings.

#### 7.0 LOGISTICS

Ļ

7.1 <u>UCT ONE</u>. All arrangements for messing, berthing, and transportation of diver personnel, and the acquisition of a suitable dive platform/boat, will be the responsibility of UCT 1. In addition, the following equipment will be provided by the divers in support of this inspection:

- All diving support equipment
- Measuring aids
  - 100-foot tape measures for use underwater
  - 1-, 2-, and 3-foot scales with large numbers suitable for underwater photo documentation
  - Accurate depth gauges
  - Marker tags to relocate or mark chain links or accessories
  - Calipers (24-inch minimum)
  - Go/no-go gauges
  - White slates (2) w/marker pens for underwater use

- Survey equipment
  - Compass (diver's)
  - Survey buoys with line (pop floats)
  - Surveying transits for establishing mooring buoy locations
- Underwater voltmeters
- Two Underwater still cameras (35mm) with film (color and B & W) and flash with spare batteries
- Cleaning equipment Hand tools including wire brushes, chipping hammers, and sharp chisels.

7.2 <u>CHESNAVFACENGCOM</u>. The CHESNAVFACENGCOM Engineer-in-Charge will provide the following:

- Inspection plan
- Data sheets and forms
- 35mm surface camera and film
- Drafting supplies, graph paper, scales
- Calculator
- Pre-dive briefing data
- DM-26

## ANNEX A

[

į.

## MEASURING DEVICES AND THEIR USE

402

#### ANNEX A


5

R

#### MEASURING DEVICES AND THEIR USE

Tables A-1 and A-2 outline the 80 and 90 percent measurements for mooring components. These tables are based on the standard sizes of mooring material listed in DM-26 and can be used to preset calipers before measuring various items. For example, a class BB riser type mooring will require calipers set to 3.15 inches (90 percent) and 2.8 inches (80 percent) for single link measurements on the riser. These values are then doubled obtaining 6.3 inches (90 percent) and 5.6 inches (80 percent) for double link measurements on the riser. Similarly, for the ground legs, single link measurements of 2.25 inches (90 percent) and 2.0 inches (80 percent) are obtained from Table A-1. These values are also doubled to obtain 4.5 inches and 4.0 inches for double link measurements. For the ground ring the single link measurements are determined to be 5.85 inches and 5.2 inches.

The preferred measuring devices, however, are back-to-back 80 and 90 percent "go-no go" gauges. These gauges simplify the diver's job in that, unlike calipers, they have to be damaged to be knocked out of adjustment. The locations for measuring chain links are shown in Figure A-1. Figure A-2 contains the drawings and data required to fabricate these gauges. Although these gauges provide a simpler way of sampling the wire size of chain links and some jewelry, the divers still have to carry calipers to measure ground rings and chain connecting links.



ľ ү. . . <u>.</u>... 

È

E

# (DOUBLE LINK MEASUREMENTS ARE OBTAINED BY MULTIPLYING SINGLE LINK MEASUREMENTS BY TWO) TABLE A-1. SINGLE LINK MEASUREMENTS FOR COMPONENTS OF RISER-TYPE MOORINGS

	נאו		000'(1	10,000	•	•	13,000	10.000	6.000	• 000	2,000	000
۵۹۵ ۵۵	Stockless w/Stabilizer	25,000	20,000	18,000	30,000	25.000	20,000	000,01	000. [ 1	000'6	5,000	000' (
Tachle	v)[r	2 3/4" type	21," Lype	2." type	]" type	2 3/4" Lype	21," Lype	21." Lype	2" type	1 3/4" type	1." type	۲ ۸ ۲ ۳ ۱ -
Ground	Chain AJL	2.415	2', 2.25 2.0	2. 2.025 1.8	3 2.7 2.4	2.475 2.475 2.2	25, 2.25	2'4 2.025 1.8	2 1.8 1.6	1.575	1. 1.125 1.0	3/4 .675 .675
bu	Spider	4 J 3.6 2.7 3.2 2.4	4 ] 3.6 2.7 3.2 2.4	4 ] 3.6 2.7 3.2 2.4	•	•	•	• •		•		
Ground Ring	buin	6. 5.85 5.2	6% 5.85 5.2	6', 5.85 5.2	ب هاري به اي م		4 3/4 4.275 3.8	4. 4.05 3.6	1.6	2.8	2.5	1 //8 1.6A8 1.5
	Ĩ	4" Lype	3:": { <u>v</u> pe	type	1. Lype	2 3/4' 5'	Z',"	ż.:	2: type	1 3/4.	11." Lype	3/4" type
Riser	Chain	1.2 3.6	2.8	3. 3.15 2.8	2.4	2.1/4	2.25	2". 2.025 1.8	2 1.8 1.6	· 5/5 · 1	11. 1.125 1.0	8/1 5/3.
	Ĩ	4" Lype	3'," Lype	3'," type	J' type	2 3/4 type	2'," Lype	2." Lype	2" Lype	1 3/4" type	li." tyne	1/4" Lype
Too of Buor	End Link	4's 1.285 2.92	3 15/16 3.544 3.15	3 15/16 3.544 3.15	۸/۲ ۵/۱.۲	8/C C 1.038 7.5	3 1/8 2.813 2.5	2 1/4 2.6113 2.5	2', 2.25 2.0	2's 2.025 1.8	4/C 1 5/S	-, °, 8,
loo	f-Shackle	5 3/8 4.838 4.1	4 15/16 4.44 3.75	4 15/16 4.44 3.95	4 3/16 3.769 3.35	3 //8 3.488 3.1	35 3.15 2.8	3 1/8 2.813 2.5	2 1)/16 2.531 2.25	2 7/16 2.174 1.95	9/6 1.575	1 1/16 .956 .85
Percent	Remaining	001 001 001	00 06 08	888	001 00 00 00	00 00 00 00 00 00 00 00 00 00 00 00 00	00 <b>1</b> 06 08	00 00 00 00 00 00 00 00 00 00 00 00 00	001		000	100 80
111	9	N-N	8-8	י. נ	0-0	<	<b>a</b>	U	۰. ۱	-	<b>~</b>	<u>ن</u>
							-	Copy	avail ait tull	able to Y legib	DTIC	cices no oduction

AJL measurement vary according to manufacturer, see PH-76 Assumes firm sand botton Assumes cast steel chain

- ~ ~

A-3

(DOUBLE LINK MEASUREMENTS ARE OBTAINED BY MULTIPLYING SINGLE LINK MEASUREMENTS BY TWO) TABLE A-2. SINGLE LINK MEASUREMENTS FOR COMPONENT'S OF TELEPHONE-TYPE MOORINGS

2


Ċ

	3	•		000. [1		10.000			•		1					10,000			6,000	
Anc hor '	Startless/Stabilizer	000°52		20,000		18 000		000 01	000.01		25.000		000 01	(mm, u)					000 (1	
Tackle	(hain	2 3/4	2.2	2,	2.9	2. 2.026	1.8 1.8	-	~~~~		2/12	2.2	e la com	2. <sup>(2)</sup>		2', 2,036	c)(1, 2)	•	- ~	9.1
Ground Tachle	גיי	2 .1/4" type		, , , ,	r ype		e vpe	3.	f vpe				2,1	t vpe	:	~	( vpe		~ .	ا لالي
lackle	Chider		3.2 2.4	~ •	J.2 2.4		3.2 2.4			-	-							-		
o-Ground	. N'Y		,		ع ا ۲		a vpc	÷.	l yre		- 1/4-	1 71.6	21,2	t ync			l yne		-~ -	-
1404-1	D/T-Shactte A.H · Fride	4 11/16	1.75	4 11/16	9.75	4 11/16	4.219 J.75	4 11/16	4.219	C	8/1		÷.		۲.8 ا	8/1 (	2.6.2	<.,	31/11 2	2.5
1.04				: 4	type	4	type	i.	type		~	cype	.,. .,.	type		<u>.</u>	type		.``	tyne
lou of	int i bri	4. 	2.92	÷	3.285 2.92		3.285	¥.	3.285	1 2.92	8/C C	1.018	3 J/B	1.038	2.7	8/C C	9.0JA	2.7	ש/נ כ	1.0JU 2.7
Pack and	Prevaluing and Link	001	28	100	82	100	06 08	001	2	80	out	<del>7</del> 2	100	90	HO	100	7	80	001	96 9
	Moor ing	A-A		0-0		ر۔ د		0-0			•	_	6	•		J		_	e	

All measurements vary according to wanufacturer, see DM-25 Assumes firm sand bottom Assumes cast steel chain

A-4

r . . . .



:	Single Link	Link.	Double Link	Link	:	Single Link	,ink	Double Link	Link	:	Single Link	huk	Double Link	Link
<u>a</u>	00 <b>6</b> .	COD.	.90(2D)	.80(2D)	2	0.06.	CION.	,90(2D)	.A0(21))	2	(106	(108	.801) .90(21) .80(21)	.80(21)
6-1/2	6-1/2 0 5.85	<b>b.2</b> 0	l	,	3-1/2	3.1/2 ③ 3.15	2.A0	2.A0 (1-) 6.30	5.60	2	09 T BU	1.60	1.60 3.60 3.20	3.20
9	(C) 5.40	4.80	ì			3.70	2.40	2.40 (1) 5.40	4. RO	1-7/8	1-7/R (13 1.69	1.50		
5-1/2	1	4.40	:	i	2-3/4	2-3/4 (A) 2.48	2.20	2.20 (!) 4.96	4.40	1-3/4	1-3/4	1.40	1.4U 2 3.06 2.NO	2. AO
4-1/2	2 0 4.05	3.60	,	ł	2.1/2	2-1/2 (9) 2.25	2.00	2.00 20 4.50	4.00	1-1/2	1-1/2 0 1.35	1.20	1.20 3 2.70 2.40	2.40
•	3.60	3.20	0 10 7.20 6.40		2.1/4	2-1/4 1 2.03 1.80 2 4.06	1.80	20 4.NG	3.60		1-1.14 🕒 1.125	90 <sup>°</sup> 1		

FIGURE A-2. 80/90 PERCENT "GO-NO-GO" GAUGES

A-5

#### ANNEX B

# SAMPLE INSPECTION FORMS

Figures B-1 and B-2 are two forms the EIC and divers may use to record measurements and as-built summations.

2

Ð

k.

MIDDLE ENTERS BOTTOM	UPPER END MIDDLE MIDDLE   MIDDLE MIDDLE MIDDLE   ENTERS BOTTOM MIDDLE MIDDLE   UPPER END MIDDLE MIDDLE   MIDDLE MIDDLE MIDDLE   UPPER END MIDDLE MIDDLE

B-2

E

FIGURE B-2

NOORING DATA SUMMARY FOR PREPARATION OF AS-BUIL	TS
---	----

Ż

14

Ú

.

. .

**6-1** 

.

,

N

MOORING# CLASS	LOCATION DATE
BOTTOM TYPE WATER DE	PTH MOORING CONDITION
ENGINEER-IN-CHARGE	DIVERS
BUOY TYPE DIMENSIONS CONDITION TOP HARDWARE BOTTOM HARDWARE	LEG C LENGTH EXPOSED LENGTH TYPE CHAIN LINK WIDTH WIRE DIAM.
RISER LENGTH TYPE CHAIN LINK WIDTH WIRE DIAM	LEG D LENGTH EXPOSED LENGTH TYPE CHAIN LINK WIDTH WIRE DIAM.
GROUND RING LOC. OUTER DIAM. WIRE DIAM. CONDITION	LEG CONNECTIONS
LEG A LENGTH EXPOSED LENGTH TYPE CHAIN LINK WIDTH WIRE DIAM.	OTHER
LEG B LENGTH EXPOSED LENGTH TYPE CHAIN LINK WIDTH WIRE DIAM.	

# ANNEX C

 $\mathbf{O}$ 

SF.

Ĵŧ

DE.

G

ć,

•••

ł

.

Ł

# REFERENCES

+461	Dis His	A.1.1 H 1/M1	···	PH1()	111 1 1	1	1.1 E E A 3	1.001	£ 11	
CI° 05	(411 1)ML	MUNIH	<b>V</b> A	AC1 RR	18450	טטטט				1461627
	_d	<u></u>	d	<u></u>	MISLAC	L HANDLING I	STRUCTIONS		L	
		<u> </u>								
	FROM: C}	HESNAV	FACE	NGCO	M WA	SHINGT	ON DC			
	то: <sub>N</sub>	AZ ZIG	ONEL	LA I	Т					
	INFO C	ENCUZN	IAVEL	IR LO	NDON	UK				
	C	OMFAIR	MED	NAPL	ES I	Т				
	C	MNAVF	ACEN	IGCOM	ALE	XANDRI	A VA			
	C		ITFLT	NOR	FOLK	VA				
	C	MCBLA	NT N	IORFO	LK V	A				
	L	NTNAV	FACE	NGCO	M NO	RFOLK	VA			
	L	ANTNAV	FACE	NGCO	MBRO	NAPLE	TI 2			
	N	VSUPF	АСТ	NAPL	ES I	Т				
	Ű	T ONE								
UNCLAS	וססנזא//	J//								
zne1:	FLEET MO	RING	ISNP	ECTI	ON O	F AUGU	STA BAY	' <b>,</b> IT	ALY	
L- AS	PART OF 1	гне со	MNAV	FACE	NGCO	M FLEE	T MOORI	NG M	AINTEN	ANCE {FMM}
PROGRAI	1. CHESNAN	FACEN	IGCOM	I⊒ WI	TH D	IVER S	UPPORT	FROM	υςτ ο	NE- PLANS TO
CONDUC.	T AN UNDEF	RUATER	INZ	PECT	ION	OF THE	ONE FL	EET	MOORIN	AT AUGUSTA
BAY' I.	TALY.									
		ATA IN	DICA	TES	A SI	NGLE	FREE-SW	INGI	NGIRI	SER TYPE,
	CC MOORIN	S FOR	NZE	BY A	D TY	PE SHI	PS. 0U	R RE	CORDS	INCLUDE
DISTR:										
and trees	NAME TITL CHUCH	VMBO: PHO		1.	Cui	₹δ₽Υ	TO:	90	0FP0	-1C(FP0-1C7.
	E. MCLAUGI	ILINY	~// A		·-0·					ILYO161
	THE THE O'RICI STMI	OL AND PHO	~			$\neg$				
H. 5	STEVENS	ON- CI	<u>DR, (</u>	<u>. 23</u>	USN	SECURIT	CLASSIFICATION			
	<u></u>			_	1				17	(143(2 may 85))

Γ.

È

.

•

**-**

:

.

È

E

) ×

PAGI	DTG ALL		PHILIDINLE	CLASS	SHECAT		C 1L	618 12 881 2 81 8 8 1
05° 05	DATE TIME		RR INTO	טנוטע				1571953
800k		J	يصبيحنيه فبحمد معبصاتيني	HANDLING I	STAUCTIONS	4	L	
LANTNAVI	<sup>-</sup> ል ሮፎጥሪትር o M	DRAWING	S NUMBERS	- 2J:	4036288	AND	52:40	36589 0 <b>F</b>
31. AUGUS	ST 1972.							
		***		T N 1 T IT N 1 A		TARV	PEC	DRD OF OVER-
HAULS	SHIP UTIL	IZATION	OR ANTICI	PATED	SHID N2	AGE	DURIN	S INSPECTION
PERIOD.	NO CLAS	SIFIED M	NATERIAL R	EQUIRE	D. ARE	A AN	D FAC	LITY MAPS
WITH SPI	ECIFIC MO	ORING LO	A ZNOITAN	RE REQ	UESTED.			
4. INSI	PECTION S	CHEDULE	IS 13-55	SEPTE	MBER 15	A3.	POIN.	F OF CONTACT
			. MCLAUGH					
		LVII 13 U	·	L-111 A				
{202} 43	33-3881.							
DISTR:						- <u>.                                    </u>		
DRAFTER TYPED W	AME, TITLE, OFFICE S	TMBOL PHONE		SPECIAL	INSTRUCTIONS	· <u> </u>		
TYPED NAME	TITLE OFFICE SYMB		·····					
		·						
E BIGNATURE				SECURIT	T CLASSIFICATIO	•	ł	DATE TIME GROUP

Ŀ.

Ĺ

ROUTINE

Ê

È

R 2008462 JUN 83

FM NAS SIGONELLA IT

TO CHESNAVFACENGCOM HASHINGTON DC

INFO CINCUSHAVEUR LONDON UK COMMAVFACENGCOM ALEXANDRIL VA LANINAVFACENGCOM NORFULK VA LANINAVFACENGCOMBRO NAPLES IT UCT DNE COMFAIRMED NAPLES IT CINCLANTELT NORFULK VA COMCBLANT NURFULK VA NAVSUPPACT NAPLES IT

BT UNCLAS // v11000//

SUBJ: FLEEF MOORING INSPECTION OF AUGUSTA BAY, ITALY

A. CHESNAVFACENGEOM MASHINGTON DE 2619362 MAY 83

1. REF & ADVISED THAT CHESNAVFACENGEOM, WITH DIVER SUPPORT FROM UCT ONE, PLANS TO CONDUCT AN UNDERWATER INSPECTION OF THE DNE FLEET MOORING AT AUGUSTA BAY, ITALY AND REQUESTED AODL DATA ON MAINTENANCE HISTORY, RECORD OF OVERHAUES, AND ANTICIPATED SHIP UTILIZATION DURING PROPUSED 17-22 SEP 83 INSPECTION PERIOD.

2. CONTRACT FOR INSTALLATION OF EXISTING AUGUSTA BAY A-3 MUDRING WAS AWARDED IN SEP 79, MODIFIED IN SEP 60 TO INCLUDE RESTURATION OF 30 PIECES OF ANCHOR JOINING LINKS AND SEVERAL ADJUSTMENTS TO JUINING LINKS, AND COMPLETED IN NUV 80. THERE IS NO RECORD OF MAINTENANCE PERFORMED SINCE INSTALLATION AND NO SHIP UTILIZATION OF AUGUSTA DAY MODPING IS PLANNED DURING THE INSPECTION PERIOD. AREA AND FACTLITY MAPS WITH SPECIFIC MODRING LOCATION HAVE NOT YET BEEN LOCATED. WILL BE PROVIDED WHEN AVAILABLE. BT

DLVR: CHESNAVFACENGEDM WASHINGTON DC(9) ... ACT

RTD:000-0J0/COPIES:U S

011 23/171	[ ⊐ن 1	41 0105	171/18:492	2000-62 3 .
CSR:RX7Y00175	٢			AAS SIGDAELEA

