

DISPOSITION INSTRUCTIONS

DESTROY THIS REPORT WHEN IT IS NO LONGER NEEDED. DO NOT RETURN IT TO THE ORIGINATOR.

DISCLAIMER

THE FINDINGS IN THIS REPORT ARE NOT TO BE CONSTRUED AS AN OFFICIAL DEPARTMENT OF THE ARMY POSITION UNLESS SO DESIG-NATED BY OTHER AUTHORIZED DOCUMENTS.

TRADE NAMES

USE OF TRADE NAMES OR MANUFACTURERS IN THIS REPORT DOES NOT CONSTITUTE AN OFFICIAL INDORSEMENT OR APPROVAL OF THE USE OF SUCH COMMERCIAL HARDWARE OR SOFTWARE.

×

COLUMN STR

.

REPORT DOCUMENTATION	PAGE	READ INSTRUCTIONS
REPORT NUMBER		BEFORE COMPLETING FORM 3. RECIPIENT'S CATALOG NUMBER
RL-81-9	AD-A105804	
TITLE (and Subtitio) TEST REPORT, HAWK LAUNCHER SHOCK	ARCORRED CORTNO	5. TYPE OF REPORT & PERIOD COVERES
PART NUMBER 9089062, SPRING RATE		Technical Percet
DEFLECTION TESTS	AND RESIDUAL	Technical Report
DEFINECTION TESTS		
AU THOR(a)		8. CONTRACT OR GRANT NUMBER(+)
John D. Alston		
	·	
PERFORMING ORGANIZATION NAME AND ADDRES Commander	15	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
US Army Missile Command		
ATTN: DRSMI-RL Redstone Arsenal, AL 35898		
· CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE
Commander		26 February 1981
US Army Missile Command ATTN: DRSMI-RPT		13. NUMBER OF PAGES
Redstone Arsenal, AL 35898		14
MONITORING AGENCY NAME & ADDRESSI I dittor	ant from Controlling Office)	15. SECURITY CLASS. (of this report)
		UNCLASSIFIED
		154. DECLASSIFICATION/DOWNGRADING SCHEDULE
DISTRIBUTION STATEMENT (of the abetract entered	d in Block 20, if different fro	m Report)
	·	
. SUPPLEMENTARY NOTES		
KEY WORDS (Continue on reverse side if necessary of Helical compression spring	and identify by block number)	,
HAWK launcher		
Launcher shock absorbers		
Group A spring		
Group B spring	and Infantifie by March marches)	
This report presents a desc the spring dimensional and load/ launcher shock absorber spring a	ription of the te compression chara	cteristics of the HAWK

~*

SECURITY CLASSIFICATION OF THIS PAGE (Then Data Entered)

CONTENTS

I.	INTRODUCTION	3
II.	SPRING TDP REQUIREMENTS	3
III.	TEST ITEM CONFIGURATION	3
IV.	TEST EQUIPMENT	5
v.	TEST PROCEDURE	[:] 5
VI.	TEST RESULTS	5
VII.	CONCLUSIONS	13

-

| ·

N

Accession For
NTIS GRA&I
DTIC TAB
Unannounced
Justification
By
Distribution/
Availability Codes
Avail and/or
Dist : Special
H

Page

1/2

I. INTRODUCTION

The helical compression spring, Part No. 9089062, is a component of the HAWK Launcher shock absorber.

The spring serves to return the shock absorber piston to the extended (i.e., ready) position when the piston is released after being compressed.

The shock absorber, Part No. 9091309, was redesigned in 1979, and the improved version is designated as Part No. 11567877. The spring, Part No. 9089062, is used in both configurations.

During piston return time tests conducted at Redstone Arsenal on 3 April and 10 April 1980, the shock absorber did not meet the piston return criteria specified in Note 8, Drawing 11567877, Revision A (see Technical Report RL-81-8). The spring and trapped air pressure supply the piston return force. After the shock absorber tests, the free length of the springs was found to be below the minimum specified by the spring drawing.

The tests described by this report were conducted to determine the spring dimensional and load/compression characteristics.

II. SPRING TDP REQUIREMENTS


Drawing 9089062 specifies the following spring requirements:


Material:	Music wire per QQ-W-470
Wire Dia	= .112 inches
Max O.D.	= 1.138 inches
Min I.D.	= .822 inches
Active Coils	= 26
Free Length	= 11.05 ± .30 inches = 10.75 min, 11.35 max
Max Solid Ht	= 3.14, Spring must return to free length without set
Spring Rate	<pre>= 9.0 ± 1.4 pounds/inch = 9.6 min, 10.4 max</pre>
Load	= 66.3 ± 9.9 pounds at a compressed length of 3.70 inches
Stroke	= 3.84 ± .10 inches

The drawing requirements for load and deflection are shown graphically in Figure 1.

III. TEST ITEM CONFIGURATION

Two groups of springs were tested. Group A consisted of springs removed from shock absorbers after the shock absorber tests in April. These springs have seen several use cycles during these tests and an unknown length of





service prior to these tests. Group A springs are believed to be several years old and to have been subject to hundreds of service load cycles.

Group B springs were obtained from Mr. Rick Henderson of Letterkenny Army Depot. They are new springs delivered from the manufacturer.

IV. TEST EQUIPMENT

The tests were conducted at Building 5400, Redstone Arsenal, Alabama. An Instron Universal testing machine was furnished and operated by Mr. Ray Parker of DRSMI-EMO. A two piece special test fixture, as shown in Figure 2, was designed and fabricated for the tests. The spring compressed length was measured using a steel scale graduated in hundredths of an inch, and the spring compression load was taken from the strip chart on the testing machine. A 500pound load cell was used with the machine calibrated at 200 pounds full scale.

V. TEST PROCEDURE

Prior to each test, the spring free length was measured, and the spring was mounted in the test fixture, as shown in Figure 2. The machine crosshead was then driven downward, thus compressing the spring. At each data point, the crosshead was stopped to record data. The fixture clearance (see Figure 2) was measured, and by adding 2.00 inches, the spring compressed length was obtained and recorded. The force required to hold the spring at this length was obtained from the testing machine strip chart and recorded.

The Group A (old) springs were obtained by disassembling shock absorbers and removing the springs. The springs retained the same sample code number used for the shock absorbers in the previous tests (see Technical Report RL-81-8). At the conclusion of the tests, the spring was reassembled into the same shock absorber.


Group B springs were individually packaged and had not been used previously.

At the conclusion of the Group A tests, one shock absorber assembly was tested by placing the shock absorber in the testing machine in a vertical position and compressing the piston. Load and piston movement were recorded at several data points.

VI. TEST RESULTS

The results of the Group A (old) springs are shown in Table 1. Only one cycle is shown in Table 1. All subsequent cycles showed results which were identical within the repeatability of the test fixture and test equipment. There was no significant reduction in free length. Each of the three Group A springs had a free length of .25 to .30 inches below the minimum allowed by the drawing.

The spring rates shown at the bottom of Table 1 were calculated from the test data shown in Table 1 and were calculated for the range of compressed lengths of 3.70 to 10.00. The following equation was used:



Compressed	Load (Pounds)				
Length (Inches)	Sample 34	Sample 4	Sample 6		
10.50	0	0	0		
10.00	4.6	4.0	4.2		
9.50	9.2	8.6	9.0		
9.00	13.7	12.9	13.8		
8.50	18.3	17.4	18.6		
8.00	23.1	22.0	23.2		
7.50	27.3	26.8	27.9		
7.00	32.2	31.0	32.7		
6.50	37 - 1	36.1	37 - 3		
6.00	41.5	40.1	42.7		
5.50	46.2	45.0	47.3		
5.00	51.1	50.2	52.5		
4.50	56.0	54.9	57.8		
4.00	60.8	60.4	61.9		
3.70	64.0	63.2	65.6		
3.50	65.6	64.7	67.3		
3.12	Solid	Solid	Solid		
Free Length (inches)	10.50	10.45	10.45		
Spring Rate Pounds/Inch	9.43	9.45	9.75		

~*

2

٩Ę

TABLE 1. TEST RESULTS FOR GROUP A (OLD) SPRINGS TESTED ON 24 APRIL 1980

S.R. = $\frac{\text{(Load at 3.70 C.L.)} - \text{(Load at 10.00 C.L.)}}{(10.00 - 3.70)}$

The spring rate for all three Group A springs was within tolerance and was slightly higher than nominal.

The test results for Group B (new) springs are shown in Table 2. For each of the three Group B springs there was a significant reduction in the spring free length during the first load cycle. In each subsequent cycles there was little or no change in free length. The free length both before and after the tests was within the drawing tolerance.

The spring rate from the 3.70 to 10.00 inch compressed height is shown at the bottom of Table 2. All spring rates were within tolerance. Group B springs had a slightly higher spring rate than Group A springs.

Figure 3 shows graphically the variation in spring rate for a Group A and a Group B spring with the TDP requirement superimposed.

The results of the shock absorber compression test are shown in Table 3 and Figure 4. This was a relatively crude test, and as can be seen in Figure 4, the results were rather erratic. The primary cause of the variations in load is probably due to friction in the shock absorber seals.

The total resistance to piston compression is composed of four components: friction, spring compression, trapped air pressure, and fluid flow resistance. In a slow application such as this test, the fluid flow resistance is not a factor, even though in a rapid application of force it is the dominant factor. During piston return the spring and trapped air forces are retarded by friction and fluid flow resistance.

From a dimensional analysis of the shock absorber, the following nominal conditions are calculated:

Piston Position	Spring Compressed Length (inches)	Spring Force (pounds)	Spring Compression (inches)	Spring 7 Compression		
Extended	7.54	31.6	3.51	447		
Compressed	3.69	66.2	7.36	93%		
Where: Spring Force = (Free L Compl. L.) (Spring Rate) Spring Compression = (Free L Compl. L.)						
Sp	ring % Compression		Compl. L.) Solid Ht.)			

Compressed	Free Length (inches), Load (pounds), Solid Height (inches), and Change in Free Length (inches)								
Length (inches)	Sample 1 Cycle Cycle Cycle 1 2 3		Sample 2 Cycle (Cycle (Cycle 1 2 3			Sample 3 Cycle Cycle Cycle 1 2 3			
Free Length	11.15"	10.96"	10.96*	11.14"	10.75"	10.73"	11.14"	10.96*	10.95*
10.5	5.8			5.8	2.8				
10.0	10.3	8.9	9.3	10.3	6.9	6.4	10.7	9.3	9.7
9.5	15.3								
9.0	20.2	18.8							
8.5	25.1								
8.0	30.2	28.5	28.8	28.2	24.5	24.5	30.0	28.7	28.1
7.5	35.1								
7.0	40.7	38.3							
6.5	45.7								
6.0	50.1	48.8	49.1	42.0	43.0	43.0	50.3	48.6	48.7
5.5	56.2								
5.0	61.2	58.9						•	
4.5	65.8								
4.0	71.1	69.3		61.0	61.5		61.3	69.2	70.5
3.7	74.9	73.7	74.8	65.5	65.8	64.9	63.8	72.1	72.1
3.5	77.0								
Solid Ht	3.26			3.17	3.17	3.17	3.23	3.23	3.23
Free Length	10.96	10.96	10.96	10.75	10.73	10.70	10.96	10.95	10.93
Free Length	. 19	0	0	• 39	.02	.03	.18	.01	.02
Spring Rate (lbs/inch)	10.25	10.29	10.40	8.76	9.35	9.29	8.43	9.97	9.90

~/

• 5

TABLE 2. TEST RESULTS FOR GROUP B (NEW) SPRINGS TESTED ON 19-20 MAY 1980

9

TABLE 3. TEST RESULTS FOR COMPLETE SHOCK ABSORBER ASSY TESTED ON 24 APRIL 1980

Shock Absorber Sample No. 4

Piston Travel (inches)	Load (Pounds)			
0				
.23	18			
•53	29			
•73	41			
•93	38			
1.23	51			
1.53	56			
1.83	55			
2.23	84			
2.53	81			
2.83	84.5			
3.23	102			
3.33	117			
3.43	121			

~*

۰. ۲,





Figure 3. Test results, spring.



As shown in the preceding table, in the shock absorber with piston extended, the spring is compressed to about 44% of its capacity and exerts a force of about 31.6 pounds. When the piston is fully compressed, the spring is compressed to 93% of its capacity and exerts a force of about 66.2 pounds. As can be seen in Table 3, shock absorber assembly no. 4 when tested exerted a piston return force of 121 pounds at a piston compression of 3.43 inches, which is approximately 90% of full compression.

When the piston is near full extension, the spring is the dominant force. The force exerted by the trapped air pressure rises faster than the spring force when the piston is compressed. This can be seen in Figure 4 as the higher slope of the plot of the entire shock absorber compared to the plot of spring force, and by the fact that the spring rate of 32.2 for the entire shock absorber is more than twice as large as the spring constant of 9.0 for the spring alone. At full compression the spring load and the trapped air pressure load are approximately equal.

Loss of oil would reduce the effects of trapped air pressure. The shock absorber tested was filled with the normal complement of 250 ml of oil.

VII. CONCLUSIONS

1. All springs conformed to the TDP in all characteristics tested with the exception of the free length. The old springs were slightly below the minimum allowed by the TDP. The new springs exhibited significant permanent set on the first cycle and a lesser amount on subsequent cycles. All the new springs tested were within tolerance both before and after testing.

2. For all springs tested the spring rates were within tolerance and the load versus compressed height was within tolerance throughout the spring operating range.

3. Problems in meeting piston return time requirements were not related to fabrication deficiencies in the springs.

DISTRIBUTION

No. of

Copies Commander Letterkenny Army Depot 2 ATTN: SDSLE-MMS, Mr. Taylor Chambersburg, PA 17201 IIT Research Institute ATTN: GACIAC 1 10 West 35th Street Chicago, IL 60616 1 DRCPM-HAER, Mr. Gasper DRSMI-LP, Mr. Voigt DRSMI-RL, Mr. Alston 1 4 15 DRSMI-RPR 1 DRSMI-RPT, (Record Copy) DRSMI-RPT, (Reference Copy) 1

~~

2

