UNCLASSIFIED

AD NUMBER

ADB805373

LIMITATION CHANGES

TO:

Approved for public release; distribution is unlimited.

FROM:

Distribution authorized to DoD only; Administrative/Operational Use; SEP 1943. Other requests shall be referred to National Aeronautics and Space Administration, Washington, DC. Pre-dates formal DoD distribution statements. Treat as DoD only.

AUTHORITY

NASA TR Server website

THIS PAGE IS UNCLASSIFIED

Reproduction Quality Notice

This document is part of the Air Technical Index [ATI] collection. The ATI collection is over 50 years old and was imaged from roll film. The collection has deteriorated over time and is in poor condition. DTIC has reproduced the best available copy utilizing the most current imaging technology. ATI documents that are partially legible have been included in the DTIC collection due to their historical value.

If you are dissatisfied with this document, please feel free to contact our Directorate of User Services at [703] 767-9066/9068 or DSN 427-9066/9068.

Do Not Return This Document To DTIC

Reproduced by

AIR DOCUMENTS DIVISION



HEADQUARTERS AIR MATERIEL COMMAND

WRIGHT FIELD, DAYTON, OHIO

The U.S. GOVERNMENT

IS ABSOLVED

FROM ANY LITIGATION WHICH MAY ENSUE FROM THE CONTRACTORS IN-FRINGING ON THE FOREIGN PATENT RIGHTS WHICH MAY BE INVOLVED.

HEADQUARTERS AIR MATERIEL COMMAND

WRIGHT FIELD, DAYTON, OHIO

REEL - C

349

A.T.I.

8530

A
R C-3497 8530

J52.16/387

~~RESTRICTED~~

TECHNICAL NOTES

NATIONAL ADVISORY COMMITTEE FOR AERONAUTICS

~~RESTRICTED~~

NACA
July 2, 1946
M. Bonnelle

No. 910

ATI No. 8530

SOME INVESTIGATIONS OF THE GENERAL INSTABILITY OF STIFFENED METAL CYLINDERS

VI - STIFFENED METAL CYLINDERS SUBJECTED TO COMBINED BENDING AND TRANSVERSE SHEAR

Guggenheim Aeronautical Laboratory
California Institute of Technology

CLASSIFIED DOCUMENT

This document contains classified information affecting the National Defense of the United States within the meaning of the Espionage Act, USC 50:31 and 32. Its transmission or the revelation of its contents in any manner to an unauthorized person is prohibited by law. Information so classified may be imparted only to persons in the military and naval Services of the United States, appropriate civilian officers and employees of the Federal Government who have a legitimate interest therein, and to United States citizens of known loyalty and discretion who of necessity must be informed thereof.

Washington
September 1943

NATIONAL ADVISORY COMMITTEE FOR AERONAUTICS

TECHNICAL NOTE NO. 910

SOME INVESTIGATIONS OF THE GENERAL INSTABILITY OF STIFFENED METAL CYLINDERS

VI - STIFFENED METAL CYLINDERS SUBJECTED TO COMBINED BENDING AND TRANSVERSE SHEAR

Guggenheim Aeronautical Laboratory
California Institute of Technology

This is the sixth of a series of reports covering an investigation of the general instability problem by the California Institute of Technology. The first five reports of this series cover investigations of the general instability problem under the loading conditions of pure bending and were prepared under the sponsorship of the Civil Aeronautics Administration. This report and the succeeding reports of this series cover the work done on other loading conditions under the sponsorship of the National Advisory Committee for Aeronautics.

SUMMARY

This report summarizes the work that has been carried on in the experimental investigation of the problem of general instability of stiffened metal cylinders subjected to combined bending and transverse shear at the C.I.T. This part of the investigation includes tests on 55 sheet-covered specimens. Under a loading of combined bending and transverse shear, the failure of the specimens is characterized by two distinct types of failure, namely, a bending or a shear failure. It has also been determined that the failing loads of the specimens have not been influenced by the length of the specimens.

INTRODUCTION

It is intended to give, in this report, a summary of the experimental investigation of the general instability of stiffened metal cylinders subjected to combined bending and transverse shear. The earlier work at C.I.T. on the problem of general instability of stiffened metal cylinders has been reported in references 1, 2, 3, 4, and 5. A total of 55 sheet-covered specimens has been tested to determine the effects of the combined loading of bending plus transverse shear and to determine the influence of length on the failing load.

INVESTIGATION OF LENGTH EFFECT

Inasmuch as all the pure bending specimens had a length to diameter ratio of 2.0, it was necessary to determine whether the failing loads of these specimens were influenced by the length. The purpose of this investigation was, therefore, to determine the length to diameter ratio L/D at which the failing load becomes independent of length.

Eight specimens having L/D ratios of 1.2, 1.6, 2.0, and 2.6 were tested, four in which the frame spacing was 2.0 inches and four in which the spacing was 4.0 inches. The spacing of the longitudinal and diameters was the same for all specimens, 2.62 and 20 inches, respectively.

The curves of unit strain as a function of the applied bending moment are shown in figures 7 to 11. The test procedure and method of strain measurements have been described in detail in references 2 and 4.

The failing strain as a function of the L/D ratio is shown in figure 2. It is seen that the specimens having an L/D ratio of 2 and 2.5 failed at approximately the same strain. As the L/D ratio decreases the failing strain increases somewhat and at an L/D ratio of 1.2 the increase is 12 and 23 percent for the 4- and 2-inch frame spacings, respectively. From these test results it can be concluded that the failing loads of the pure bending specimens used in the previous experiments were not influenced by the length.

INVESTIGATION OF COMBINED BENDING AND SHEAR

Description of Testing Apparatus

The testing machine, as shown in figure 71, consists essentially of four separate elements - the bed, the fixed end plate, the movable carriage, and the loading beam. The bed is 12½ feet long, 3½ feet wide, and is constructed of heavy I-beams. To one end is rigidly bolted the fixed end plate. The loading beam is a built-up box section 6 feet long - although this can be extended by splicing on additional lengths. Bolted to one end is an end plate similar to the fixed end plate. The loading beam is freely suspended in a cage or carriage which itself is free to move along the bed. The beam is suspended from two knife edges at the top of the carriage and is balanced by counterweights. With this arrangement the weight of the loading beam and end plate will not be carried by the specimen, but will always be just balanced by the counterweights.

One end of the specimen is bolted to the fixed end plate - the other to the end plate on the loading beam. A vertical upload is then applied at any desired point on the loading beam by means of a screw jack. The load is indicated by a dial gage mounted on a dynamometer which was previously calibrated in a 150,000-pound Tinius Olsen testing machine.

Method of Strain Measurement

Resistance strain gages were used to measure the strain at desired points. Essentially, this method measures the change in resistance of a wire element cemented to the specimen. The gages were calibrated by cementing a wire element of known length to a test bar and measuring the change in resistance for a known unit strain.

The gages were mounted on the neutral axis of the stiffeners and were also mounted in pairs - one on each side of the stiffener - so that the mean reading would be unaffected by bending. The resistances were measured with a Wheatstone bridge, the voltage being supplied by two dry cells. The gages were cut in and out of the bridge circuit through a mercury switch arrangement, thus avoiding large contact resistances.

During the early part of the investigation, a 3-inch-gage length was used. However, it was found that this small gage length was apparently quite sensitive to small local deformations. Also it seemed probable that the behavior of the gage was unduly influenced by the conditions at the juncture points where the leads were soldered. It was therefore decided to adopt a 16-inch-gage length. Although this gage did not permit measuring the strain at as many different points as the 3-inch gage, it yielded more consistent results.

Test Procedure

The specimen was mounted in the testing machine and the loading jack placed at the proper position to give the desired moment arm. The load was then applied in increments, the jack-dial reading and the strain-gage resistances being recorded for each increment. Also, over-all strain measurements were made at the top, bottom, and sides by means of dial gages. The over-all measurements on the sides were useful in detecting loading eccentricities. The behavior of the specimen was carefully noted as the test progressed; initial and subsequent buckles were observed and their positions, extent, and corresponding loads recorded.

Combined Loadings

In the pure bending tests, the problem of determining the maximum strain associated with the failing load was relatively simple because of the uniform loading over the length of the specimen. However, when the test specimen is subjected to combined bending and transverse shear the bending moment and the corresponding strains vary over the length of the specimen. Hence, the method of measuring, over the specimen length, a maximum mean strain at failure and assigning this measured strain to the failing load can no longer be applied. The variation of strain and the end conditions of the specimen make it particularly difficult to associate a particular strain with the failing load can The maximum moment occurs at the fixed ends; however, this maximum moment and the corresponding strain cannot be considered as being a measure of the ultimate strength of the cylinder because of the fixed-end conditions.

There are two possible methods of presenting the test data. One method would be to measure the strain at a number

of points along the length of the specimen, which could then be presented as the existing strain condition along the length of the specimen when failure occurred. Another method would be to measure the failing strain at the point at which the first buckle appears during the loading process and to consider this to be indicative of the maximum strain to which the specimen can be subjected before failure occurs.

Both methods have certain disadvantages. The first does not lend itself readily to application in practical design. It is customary, for maximum structural efficiency, to design a reinforced cylindrical structure in such a manner as to keep the stress nearly constant even though the bending moment is variable. This is usually accomplished through the geometrical taper of the section and also by tapering the effective bending material. For this reason, the designer is mostly interested in a single value of the allowable stress or strain for calculating his margins of safety. From this point of view the second method is preferable. However, the main objection here is that the validity of associating the strain condition at a point with the failure of the cylinder may be questionable.

This latter method has also one other advantage; namely, for the pure bending failure a parameter has been derived which appears to be satisfactory. In determining the influence of the transverse shear on the maximum strain at failure, it is convenient to have a single value of the strain for combined bending and shear to compare with the strain value for pure bending.

In view of the above, the following method of presentation was adopted. It was found that the initial buckle or buckles appeared over a relatively short range, being on the average about 14 inches from the fixed end for the 32-inch-diameter cylinders and 10 inches for the 20-inch-diameter cylinders. For this reason the strain at failure was considered to be the average of the strain measurements obtained with the 3-inch-wire gage over a distance extending from about 4 to 24 inches from the fixed end, or the strain measurements of the 16-inch-wire gage which extended from 6 to 22 inches from the fixed end.

The type of failure in combined bending and shear differs particularly in one respect from that of the pure bending failure. For the combined loading the failure is, in many cases, gradual - that is, the buckles, although extending

over several frames and longitudinals, slowly increase in depth and size with increasing load until a sudden collapse occurs with a marked increase in depth and size of the buckle or buckles. In the case of the pure bending specimens, the original cross-sectional shape is closely maintained until failure occurs - the failure being particularly violent and accompanied by large and deep buckles with as much as a two-thirds drop in the applied load.

From a visual observation of the failure, it appeared, during the early part of the investigation, that failure of a specimen was either of the bending or the shear type; that is, the beginning of a failure was confined to either a region of maximum compression or a region of maximum shear. The rather definite separation of the regions of failure would indicate that when a failure occurred in the compression region the failure would be nearly independent of the applied shear and would depend primarily on the state of compression strain; whereas, when failure occurred in the region of maximum shear the failure would be independent of the state of compression strain and only depend on the applied shear.

The above observations were borne out by the experimental results. In figure 3 are plotted the ratios of the compressive strain ϵ/ϵ_0 as a function of VR/M for a number of specimens of both 16-inch and 10-inch radius. In these expressions,

ϵ maximum compressive strain value (at the position previously described) for the combined loading condition

ϵ_0 same strain value for pure bending

V applied shear

R radius of the specimen

M bending moment

Since $M = VL$, where L is the distance from the applied shear load to the point where the strain is measured, it is seen that the ratio VR/M is equivalent to R/L. This presentation is merely to indicate that when the failure occurs in the compression region the maximum compressive strain is independent of the applied shear. For these specimens, the applied shear load varied from 503 to 1450

pounds for the 16-inch-radius specimens and from 710 to 2310 pounds for the 10-inch specimens. The minimum moment arm L was limited by the length of the specimen.

In figure 4 are plotted ratios of ϵ/ϵ_0 as a function of V/V_0 for one series of tests, where V_0 is the shear load which causes a pure shear failure and V is the shear load corresponding to ϵ. It is seen from this figure that specimens 116 and 117 failed at the same shear load but widely different values of ϵ (i. e., bending moment). The photographs (figs. 75 and 76) indicate that specimen 116 failed similtaneously by combined bending and shear, whereas specimen 117 failed in shear. It appears from these results that the interaction curve for this type of loading consisted essentially of two perpendicular straight lines. The photographs (figs. 72 to 74) also show types of failure.

The strains at failure, for the specimens which failed by bending, have been compared with the parameter obtained for the pure bending failures and are shown in figure 5. The test values follow the same trend as the curve for the pure bending failures; however, the experimental scatter is somewhat greater than for the pure bending specimens. It is felt that this scatter is primarily due to the following:

(a) The accuracy of the strain measurements depends on the reliability of the electric strain gages and an accuracy greater than 5.0 percent is not to be expected.

(b) Adopting a strain value at a constant distance from the fixed end as being indicative of strain at failure also leads to some inaccuracies.

A number of curves showing the variation of strain in the longitudinal direction are shown in figures 67 to 69. The distribution of normal stresses is shown for a number of specimens in figures 64 to 66. In table I the experimental and computed data are given for each specimen. The curves of strain against applied shear are shown in figures 12 to 63. The strain-gage position and the stringer number is indicated in tabular form for each set of curves. The method of numbering the stringers is indicated in figure 6.

In all specimens the longitudinal stringers were S_1 and the frames F_5 with the exception of specimens 126 and 127 in which the longitudinals were S_2 and the frames F_5. The cross-sectional dimensions of the longitudinals

and frames are shown in figure 1. The variations of the sectional parameters, ρ and I, for the longitudinal S_2 with a variation in effective width are shown in figure 70.

CONCLUSIONS

The experimental results indicate that for combined bending and transverse shear, the failure is characterized by two distinct types of failure, namely, a bending or a shear failure. If the failure is bending, the failing strain can be predicted with sufficient accuracy by means of the pure bending parameter. However, it is still necessary to determine a shear failure parameter in order to ascertain when a bending or a shear failure will occur. Because of the limitation imposed by the specimen length on the maximum shear which could be applied, it was quite difficult to obtain shear failures. In the combined bending and torsion experiments additional data on shear failures will be obtained which may be sufficient to lead to a suitable shear parameter.

Guggenheim Aeronautical Laboratory,
California Institute of Technology,
Pasadena, Calif., June 10, 1942

REFERENCES

1. Guggenheim Aeronautical Laboratory, California Institute of Technology: Some Investigations of the General Instability of Stiffened Metal Cylinders. I - Review of Theory and Bibliography. T.N. No. 905, NACA, 1943.

2. Guggenheim Aeronautical Laboratory, California Institute of Technology: Some Investigations of the General Instability of Stiffened Metal Cylinders. II - Preliminary Tests of Wire-Braced Specimens and Theoretical Studies. T.N. No. 906, NACA, 1943.

3. Guggenheim Aeronautical Laboratory, California Institute of Technology: Some Investigations of the General Instability of Stiffened Metal Cylinders. III - Continuation of Tests of Wire-Braced Specimens and Preliminary Tests of Sheet-Covered Specimens. T.N. No. 907, NACA, 1943.

4. Guggenheim Aeronautical Laboratory, California Institute of Technology: Some Investigations of the General Instability of Stiffened Metal Cylinders. IV - Continuation of Tests of Sheet-Covered Specimens and Studies of the Buckling Phenomena of Unstiffened Circular Cylinders. T.N. No. 908, NACA, 1943.

5. Guggenheim Aeronautical Laboratory, California Institute of Technology: Some Investigations of the General Instability of Stiffened Metal Cylinders. V - Stiffened Metal Cylinders Subjected to Pure Bending. T.N. No. 909, NACA, 1943.

TABLE I

Test	Long Spacing b	Frame Spacing d	Radius	Ultimate Applied Shear	Moment arm - to fixed end.	Strain at Failure	$\sqrt[4]{bd}$	ρ_x	ρ_y	$\sqrt[4]{(\rho_x\rho_y)^3}$	$\sqrt[4]{\frac{bd}{(\rho_x\rho_y)^3}}\,R$	$\sqrt[4]{\frac{(\rho_x\rho_y)^3}{bd}}\,\frac{1}{R}$	Type of Failure
75	5.06	8"	16"	1057#	128"	.00181	2.52	.1167	.02335	.0119	3390	2.95x10-4	Gen. Instability
76	"	"	"	1050	116"	.00153	"	.1167	.02335	.0119	3390	2.95 "	"
77	"	"	"	1450	92"	.001516	"	.1167	.02338	.0119	3390	2.95 "	"
78	"	"	"	995	116	.00151	"	.1167	.02335	.0119	3390	2.95 "	"
79	"	2"	"	2000	128	.00270	1.765	.1172	.02836	.0138	2070	4.83 "	"
80	"	"	"	1850	107	.00211	"	.1170	.02836	.0138	2070	4.83 "	"
81	"	"	"	2175	86	.00242	"	.1170	.02836	.0138	2070	4.83 "	"
82	"	"	"	2070	64	.00189	"	.1170	.02836	.0138	2070	4.83 "	"
83	10.12	4	"	563	126	.00154	2.52	.1117	.02677	.0128	3150	3.18 "	"
84	"	2	"	625	126	.00212	2.12	.1129	.02636	.0135	2510	3.98 "	"
85	"	"	"	915	104	.00195	"	.1127	.02836	.0134	2530	3.95 "	"
86	"	"	"	915	80	.00218	"	.1130	.02838	.0135	2510	3.98 "	"
87	"	"	"	929	66.5	.00213	"	.1130	.02836	.0138	2510	3.96 "	"
88	5.06	4	"	2118	60	.00216	"	.1170	.02677	.0132	2570	3.89 "	"
89	"	"	"	1910	66.8	.00187	"	.1169	.02677	.0132	2570	3.89 "	"
90	"	"	"	1212	126	.00209	"	.1170	.02877	.0132	2570	3.89 "	"

Note: Sheet thickness for all specimens = .010"

TABLE I (CONT'D)

Test	Long Spacing b	Frame Spacing d	Radius	Ultimate Applied Shear	Moment arm - to fixed end.	Strain at Failure	$\sqrt[4]{bd}$	P_x	P_y	$\sqrt[4]{P_x P_y^3}$	$\frac{\sqrt[4]{bd}}{\sqrt[4]{P_x P_y^3}} E$	$\frac{\sqrt[4]{P_x P_y^3}}{bd} \frac{1}{E}$	Type of Failure
91	5.06"	4"	16"	1331#	116"	.00194	2.12	.1169	.02677	.0132	2570	3.89x10-4	Gen. Instability
92	"	8	"	503	194	.00152	2.52	.1167	.02335	.0119	3390	2.95 "	"
93	"	"	"	1353	74	.00135	"	.1166	"	.0119	3390	2.95 "	"
94	2.62	"	10"	960	114	.00174	-	-	-	-	-	- -	Panel instability
95	"	"	"	1283	88.4	.00290	2.14	.1165	.02335	.0119	1800	5.55 "	Gen. Instability
96	"	"	"	1711	65	.00265	"	.1166	"	.0119	1800	5.55 "	"
97	"	"	"	2900	40.5	.00207	-	-	-	-	-	-	Shear
98	"	4	"	1310	113	.00340	1.60	.1163	.02677	.0132	1360	7.35 "	Gen. Instability
99	"	"	"	1660	68.4	.00330	"	.1164	"	.0132	1360	7.35 "	"
100	"	"	"	2250	65	.00270	-	-	-	-	-	-	Bending-Shear
101	"	"	"	3300	40.5	.00260	-	-	-	-	-	-	Shear
102	2.53	2	16	2480	137	.00282	1.50	.1160	.02836	.0137	1750	5.71 "	Gen. Instability
103	"	"	"	2860	112.4	.00277	"	.1160	"	.0137	1750	5.71 "	"
104	"	"	"	4200	89	.00343	"	.1157	"	.0137	1750	5.71 "	"
105	"	"	"	4500	65.1	.00216	-	-	-	-	-	-	Shear
106	2.62	"	10	1490	113	.00396	1.51	.1161	.02836	.0138	1090	9.17 "	Gen. Instability
107	"	"	"	2760	65	.00450	"	.1160	"	.0137	1100	9.10 "	"
108	"	"	"	4270	40.5	.00398	"	.1161	"	.0138	1090	9.17 "	"
109	5.24	8	"	450	113	.00186	2.54	.1162	.02335	.0119	2130	4.69 "	"

TABLE I (CONT'D)

Test	Long Spacing b	Frame Spacing d	Radius	Ultimate Applied Shear	Moment arm - to fixed end.	Strain at Failure	$\sqrt[4]{\frac{b}{d}}$	P_x	P_y	$\sqrt{P_x P_y}^3$	$\sqrt[4]{\frac{50}{P_x P_y}} E$	$\sqrt{\frac{P_x P_y}{50}}^3 2$	Type of Failure
110	5.24"	8"	10"	1470	40.6	.00242	2.54	.1166	.02335	.0119	2130	4.69x10-4	Gen. Instability
111	"	4	"	660	113	.00251	2.14	.1170	.02677	.0132	1620	6.17 "	"
112	"	"	"	1780	40.6	.00290	"	.1169	"	.0132	1620	6.17 "	"
113	"	"	"	930	88.4	.00266	"	.1169	"	.0132	1620	6.17 "	"
114	2.63	"	16"	1900	137	.00216	1.765	.1162	"	.0132	2160	4.63 "	"
115	"	"	"	2010	112.4	.00194	"	.1163	"	.0132	2160	4.63 "	"
116	"	"	"	2400	89	.00217	"	.1162	"	.0132	2160	4.63 "	"
117	"	"	"	2450	65.3	.00136	-	-	-	-	-	-	Shear
118	5.24	2	10	710	113	.00360	1.80	.1170	.02636	.0136	1300	7.69 "	Gen. Instability
119	"	"	"	990	66.4	.00364	"	.1170	"	.0138	1300	7.69 "	"
120	"	"	"	1460	65	.00353	"	.1169	"	.0138	1300	7.69 "	"
121	"	"	"	2310	40.6	.00374	"	.1170	"	.0138	1300	7.69 "	"
122	2.62	1	"	1665	113	.00525	1.27	.1159	.02601	.0136	930	10.75 "	"
123	"	"	"	2140	88.4	.00492	"	.1160	"	.0136	930	10.75 "	"
124	"	"	"	3220	65	.00481	"	.1160	"	.0136	930	10.76 "	"
125	"	"	"	5260	40.6	.00479	"	.1160	"	.0136	930	10.75 "	"
126	5.06	4	16	1600	109	.00207	2.12	.1150	.02677	.0131	2590	3.86 "	"
127	"	"	"	1940	89	.00192	"	.1150	"	.0131	2590	3.86 "	"
128	"	"	"	1446	137	.00208	"	.1150	"	.0131	2590	3.86 "	"
129	"	"	"	2340	65	.00205	"	.1150	"	.0131	2590	3.86 "	"



STIFFENER-S_2

AREA = .0368 I_{xx} = .000407



STIFFENER-S_1

AREA = .0324 I_{xx} = .000374



FRAME-F_9

AREA = .0291 $I_{xx} = 1.537 \times 10^{-6}$

FIG. 1


LONGITUDINAL SPACING = 246
FRAME SPACING = 20
FRAME SPACING = 40
.005
.004
.003
.002
.001
10
15
20
25

FIG. 2


o 75-78,92
□ 118-121
1.2
1.0
0.8
0.6
0.4
0.2
0
0.1
0.2
0.3
0.4
$\frac{VR}{M}$
$\frac{\epsilon}{\epsilon_0}$

Figure 3.


1.6
1.4
1.2
1.0
0.8
0.6
0.4
0.2
0
0.2
0.4
0.6
0.8
1.0
1.2
$\frac{\epsilon}{\epsilon_o}$
$\frac{V}{V_o}$

Figure 4

Fig. 5


.0050
.0040
.0030
σ/E'
.0020
.0010
0
0
2
4
6
8
10
$\frac{1}{2}\sqrt{R_1 R_2}\sqrt[4]{\frac{R_1 R_2}{bd}} \times 10^4$

FIG.5

Fig. 6

METHOD OF NUMBERING STIFFENERS



32 IN. DIAMETER



20 IN. DIAMETER

FIG 6


BENDING MOMENT INCH LBS
120,000
100,000
80,000
60,000
40,000
20,000
0
65
o o TENSION
Δ Δ COMPRESSION
+.0004
UNIT DEFORMATION

FIG 7


140,000
120,000
100,000
80,000
60,000
40,000
20,000
0
BENDING MOMENT — INCH LBS
66
68
67
TENSION
COMPRESSION
.0004
UNIT DEFORMATION

FIG 8


70
69
160,000
140,000
120,000
100,000
80,000
60,000
40,000
20,000
0
BENDING MOMENT — INCH LBS
TENSION
COMPRESSION
.0005
UNIT DEFORMATION

FIG. 9


160000
140000
120000
100000
80000
60000
40000
20000
0
BENDING MOMENT INCH LBS
72
71
TENSION
COMPRESSION
.0005
UNIT DEFORMATION

FIG 10

Fig. 11


BENDING MOMENT INCH LBS
UNIT DEFORMATION
TENSION
COMPRESSION
.0004
74
73

FIG 11


STRAIN AT FAILURE .0011
FAILING LOAD 1087 #
1100
1000
900
800
700
600
500
400
300
200
100
0
APPLIED STRESS LBS
1.0
3.4
SPECIMEN No 78
0
10
30
20
Wire No.
Gage No.
Distance from free end to center of gage
0
17-B
26 inches
"
19-M
70 "
.0004
UNIT STRAIN
FIG 12


STRAIN AT FAILURE .00153
FAILING LOAD 1050#
1000
900
800
700
600
500
400
300
200
100
APPLIED SHEAR - LBS
17-18
13-14
SPECIMEN NO. 76
0
10
20
30
Strain No.
Gage No.
Dist. from fixed end to cent. of gage
0
17-18
24 inches
"
13-14
7 "
.0004
UNIT STRAIN

FIG 13

Fig. 14


STRAIN AT FAILURE = .001615
FAILING LOAD 1450
1600
1400
1200
1000
800
600
400
200
APPLIED SHEAR LBS
19-20
13-14
SPECIMEN NO. 77
0
10
30
20
Strain No.
Gage No.
Dist. from fixed end to cent. of gage
0
19-20
39 inches
"
13-14
7
"
-.0004-
UNIT STRAIN

FIG. 14


STRAIN AT FAILURE .0015
FAILING LOAD 995 lbs
1000
900
800
700
600
500
400
300
200
100
0
APPLIED SHEAR LBS
13-14
5-6
1-2
.0004
UNIT STRAIN
SPECIMEN NO 78
0
10
30
20
String No. | Gage No | Dist. from fixed end to center of gage
0 | 13-14 | 27.0 inches
" | 5-6 | 10.5 "
" | 1-2 | 2.5 "

FIG 15


STRAIN AT FAILURE .00270
FAILING LOAD 2000 lbs
2000
1800
1600
1400
1200
1000
800
600
400
200
0
APPLIED SHEAR LBS
9-10
7-8
5-6
3-4
SPECIMEN NO. 79
0
10
30
20
String No.
Gage No.
Dist. from fixed end to cent. of gage
0
9-10
29.5 inches
" 7-8 18.5 "
" 5-6 13.25 "
" 3-4 8.5 "
.0005
UNIT STRAIN
FIG. 16


STRAIN AT FAILURE .0021
FAILING LOAD 1850 #
2000
1800
1600
1400
1200
1000
800
600
400
200
0
APPLIED STRESS LBS
9-10
7-8
5-6
3-4
SPECIMEN NO. 80
40
10
30
20
Strain Gage No. Dist. from fixed end to center of gage
0 9-10 23.25 inches
" 7-8 19.0 "
" 5-6 13.5 "
" 3-4 8.5 "
.0004
UNIT STRAIN
FIG. 17


String No.
Gage No.
Dist. from front end to cent. of gage
0
9-10
25.5 inches
"
7-8
20.25
"
"
5-6
15.5
"
"
3-4
10.25
"
"
1-2
5.25
"
0
10
30
20
SPECIMEN NO. 81
STRAIN AT FAILURE .00242
2400
FAILING LOAD 2175 lbs
2000
1600
1200
800
400
0
APPLIED SHEAR LBS
9-10
7-8
5-6
3-4
1-2
.0008
UNIT STRAIN
FIG. 18


STRAIN AT FAILURE .00189
FAILING LOAD 2070
APPLIED SHEAR LBS.
2000
1800
1600
1400
1200
1000
800
600
400
200
0
17-18
19-20
21-22
23-24
SPECIMEN NO. 82
0
10
20
30
.0004
UNIT STRAIN
String No
Gage No
Dist from fixed end to center of gage
0 17-18 20.5 inches
" 19-20 15.25 "
" 21-22 10.5 "
" 23-24 5.5 "

FIG. 19

Fig. 20


STRAIN AT FAILURE: .0056
FAILING LOAD 563#
500
400
300
200
100
0
APPLIED SHEAR LBS.
9-10
7-8
5-6
3-4
.0004
UNIT STRAIN
SPECIMEN NO. 83
0
10
30
20
String No.
Gage No.
Dist. from fixed end to cent. of gage
0
9-10
22.5 inches
"
7-8
17.5
"
"
5-6
12.5
"
"
3-4
7.5
"

FIG. 20

Fig. 21



String No.	Gage No.	Dist. from fixed end to center of gage	
0	9-10	26.0	inches
"	7-8	20.8	"
"	5-6	15.6	"
"	3-4	10.5	"
"	1-2	5.3	"

FIG. 21


STRAIN AT FAILURE .00145
FAILING LOAD 915 #
APPLIED SHEAR LBS
1000
900
800
700
600
500
400
300
200
100
0
11-12
9-10
7-8
5-6
3-4
.0006
UNIT STRAIN
SPECIMEN NO. 85
0
10
30
20
String No | Gage No | Dist. from fixed end to cent. of gage
0 | 11-12 | 28.5 inches
" | 9-10 | 23.3 "
" | 7-8 | 18.0 "
" | 5-6 | 12.8 "
" | 3-4 | 7.8 "

FIG. 22


STRAIN AT FAILURE .00218
FAILING LOAD 915#
APPLIED SHEAR LBS
1000
900
800
700
600
500
400
300
200
100
0
9-10
7-8
5-6
3-4
SPECIMEN NO. 36
0
10
20
30
Strip No
Gage No
Dist from fixed end to cent of gage
0
9-10
23.8 inches
7-8
18.5
5-6
13.5
3-4
8.3
.0004
UNIT STRAIN

FIG. 23


STRAIN AT FAILURE .00213
FAILING LOAD 929#
APPLIED SHEAR LBS
1000
900
800
700
600
500
400
300
200
100
0
9-10
7-8
5-6
3-4
SPECIMEN NO 87
0
10
20
30
.0004
UNIT STRAIN
String No
Gage No
Dist from fixed end to center of gage
0
9-10
23.3 inches
7-8
18.0
5-6
12.8
3-4
7.8

FIG 24


STRAIN AT FAILURE
.00218
FAILING LOAD 2115#
2000
1800
1600
1400
1200
1000
800
600
400
200
0
APPLIED SHEAR LBS
9-10
7-8
5-6
3-4
SPECIMEN NO. 88
0
10
20
30
String No
Gage No
Dist from fixed end to cent of gage
9-10
23.6 inches
7-8
18.4
5-6
13.1
3-4
7.8
.0004
UNIT STRAIN

FIG. 25



String No.	Gage No.	Dist. from fixed end to center of gage
0	1-2	5.5 inches
"	3-4	10.75
"	5-6	15.75
"	7-8	21
"	9-10	26.25

FIG 26


STRAIN AT FAILURE .00209
FAILING LOAD 1212 #
APPLIED SHEAR LBS
1400
1200
1000
800
600
400
200
0
.001 in
UNIT STRAIN
SPECIMEN NO. 90
0
10
30
20
Strain Gage No
Dist from fixed end to cent of gage
0
3-4
7.75 inches
1
5-6
13
2
7-8
18.26
3
9-10
23.25

FIG. 27


STRAIN AT FAILURE .00194
FAILING LOAD 1331 #
APPLIED SHEAR LBS
1400
1200
1000
800
600
400
200
0
.0004
UNIT STRAIN
SPECIMEN NO 91
10
30
20
Strain Gage No
Dist from fixed end to cent of gage
0 9-10 23.5 inches
7-8 18.3
5-6 13.0
3-4 1.8

FIG 28


STRAIN AT FAILURE .00152
FAILING LOAD 503#
500
450
400
350
300
250
200
150
100
50
0
APPLIED STRESS LBS
SPECIMEN NO. 92
0
10
30
20
Strip No. | Gage No | Dist. from Road end to cent. of gage
0 | 3-4 | 7.5 inches
5-6 | 12.75
7-8 | 17.75
9-10 | 23
.0004
UNIT STRAIN

FIG. 29


STRAIN AT FAILURE .00135
FAILING LOAD 1353#
APPLIED SHEAR LBS
1600
1400
1200
1000
800
600
400
200
0
9-10
7-8
5-6
3-4
SPECIMEN NO. 93
0
10
20
30
String No.
Gage No.
Dist. from fixed end to center of gage
0
3-4
8.25 inches
5-6
13
7-8
18
9-10
23.25
.0004
UNIT STRAIN

FIG. 30


STRAIN AT FAILURE .0029
FAILING LOAD 1283#
SPECIMEN NO. 95
0
6
18
12
APPLIED SHEAR LBS
1400
1200
1000
800
600
400
200
0
4
5-6
7
String No.
Gage No.
Dist. from fixed end to cent. of gage
0
4
7.5 inches
5-6
12.5
7
17.5
.0008
UNIT STRAIN

FIG. 31


STRAIN AT FAILURE .00265
FAILING LOAD 1711#
APPLIED SHEAR LBS
1800
1600
1400
1200
1000
800
600
400
200
0
SPECIMEN NO 96
0
6
18
12
String No.
Gage No.
Dist. from fixed end to cent of gage
0
2
2.5 inches
3
7.5
5
12.5
7
17.5
.0005
UNIT STRAIN

FIG. 32


STRAIN AT FAILURE .0034
FAILING LOAD 1810#
SPECIMEN NO. 98
0
6
18
12
7-8
5-6
3-4
APPLIED SHEAR LBS
1400
1200
1000
800
600
400
200
0
.0008
UNIT STRAIN
String No
Gage No
Dist from fixed end to cent of gage
3-4
7.5 inches
5-6
12.5
7-8
17.5

FIG. 33

Fig. 34


STRAIN AT FAILURE .0033
FAILING LOAD 1660#
SPECIMEN NO. 99
APPLIED SHEAR LBS
UNIT STRAIN
.0008
0
200
400
600
800
1000
1200
1400
1600
1800
0
6
12
18
Strain No.
Gage No.
Dist from fixed end to cent of gage
3-4
7.5 inches
5-6
12.5
8
12.5

FIG. 34


STRAIN AT FAILURE .00282
FAILING LOAD 2480#
SPECIMEN NO 102
APPLIED SHEAR LBS
2800
2400
2000
1600
1200
800
400
0
9-10
6
7-8
3-4
0
10
20
30
String No
Gage No
Dist. from fixed end to cent. of gage
0
3-4
8 inches
6
13.6
7-8
18.75
9-10
24.25
.0005
UNIT STRAIN

FIG. 35

Fig. 36


STRAIN AT FAILURE .00277
FAILING LOAD 2860#
APPLIED SHEAR LBS
3200
2800
2400
2000
1600
1200
800
400
0
11-12
9-10
5-6
3-4
7-8
-.0008-
UNIT STRAIN
SPECIMEN NO 103
0
10
30
20
String No
Gage No
Dist from front end to cent of gage
0 3-8 8 inches
1 5-6 13.5
2 7-8 18.75
3 9-10 24.25
4 11-12 29.5

FIG. 36


STRAIN AT FAILURE .00343
FAILING LOAD 4200#
APPLIED SHEAR LBS
4000
3600
3200
2800
2400
2000
1600
1200
800
400
0
11-12
9-10
5-6
3-4
7-8
SPECIMEN NO 104
0
10
20
30
String No
Gage No
Dist. from fixed end to cent of gage
0
3-4
7.875 inches
5-6
13.25
7-8
18.625
9-10
24
11-12
29.5
.00008
UNIT STRAIN

FIG 37


STRAIN AT FAILURE .00396
FAILING LOAD 1490#
SPECIMEN NO. 106
APPLIED SHEAR LBS
UNIT STRAIN
.0008
1600
1400
1200
1000
800
600
400
200
0
7-8
5-6
3
1-2
0
6
12
18
String No
Gage No
Dist. from fixed end to cent. of gage
0
1-2
2.5 inches
3
7.5
5-6
12.5
7-8
17.5

FIG. 38


STRAIN AT FAILURE .0045
FAILING LOAD 2760#
APPLIED SHEAR LBS
2800
2400
2000
1600
1200
800
400
0
SPECIMEN NO 107
UNIT STRAIN
.0008

FIG. 39


STRAIN AT FAILURE .00398
FAILING LOAD 4270#
4400
4000
3600
3200
2800
2400
2000
1600
1200
800
400
0
APPLIED SHEAR LBS
7-8
5-6
3-4
1-2
SPECIMEN NO. 108
0
6
18
12
String No.
Gage No.
Dist. from fixed end to center of gage
0
1-2
2.6 inches
3-4
7.5
5-6
12.5
7-8
17.5
.0008
UNIT STRAIN

FIG. 40


STRAIN AT FAILURE .00186
FAILING LOAD 450#
APPLIED SHEAR LBS
450
400
350
300
250
200
150
100
50
0
3-4
11-12
1-2
9-10
5
7-8
SPECIMEN NO 109
0
1
23
6
18
12
.0004
UNIT STRAIN
String No
Gage No
Dist from feed end to cent of gage
0
7-8
10.5 inches
1
5-6
6
3-4
12
1-2
18
11-12
23
9-10

FIG. 41


STRAIN AT FAILURE .00242
FAILING LOAD 1470#
1800
1400
1200
1000
800
600
400
200
0
APPLIED SHEAR LBS.
.0004
UNIT STRAIN
FIG 42
SPECIMEN NO 110
0
29
6
18
12
Strain No.
Gage No.
Dist. from head end to cent. of area
0 7-8 10.6 inches
1 6-6 "
6 5-4 "
12 1-2 "
18 11-12 "
23 9-10 "


0
6
18
12
STRAIN AT FAILURE .00251
SPECIMEN NO. 111
FAILING LOAD 660#
800
700
600
500
400
300
200
100
0
APPLIED SHEAR LBS
3-4
11-12
1-2
10
5-6
7-8
.0004
UNIT STRAIN
String No. | Gage No. | Dist. from fixed end to cent. of gage
0 | 7-8 | 10.5 inches
22 | 5-6 | "
2 | 10 | "
12 | 1-2 | "
6 | 11-12 | "
18 | 3-4 | "

FIG. 43


STRAIN AT FAILURE .0029
FAILING LOAD — 1780#
APPLIED SHEAR LBS
UNIT STRAIN
.0004
SPECIMEN NO 112
0
2
22
6
18
12
Strain No. | Gage No. | Dist from fixed end to cent. of gage
0 | 7-8 | 10.5 inches
2 | 5-6 | " "
6 | 8-4 | " "
12 | 1-2 | " "
18 | 11-12 | " "
22 | 9-10 | " "

FIG. 44


STRAIN AT FAILURE .00265
FAILING LOAD 930#
APPLIED SHEAR LBS
1000
900
800
700
600
500
400
300
200
100
0
3-4
11-12
1-2
5-6
9-10
7-8
SPECIMEN NO. 113
0
2
22
6
18
12
.0004
UNIT STRAIN
String No.
Gage No.
Dist. from fuse end to cent of gage
0 7-8 10.5 inches
2 5-6
6 3-4
12 1-2
18 11-12
22 9-10

FIG. 45

Fig. 46


STRAIN AT FAILURE 0.0216
FAILING LOAD 4900 #
APPLIED STRESS LBS
UNIT STRAIN
SPECIMEN AND INS.
0
10
20
30
40
50
60
70
80
90
100
110
120
130
140
150
160
170
180
190
200
210
220
230
240
250
260
270
280
290
300
310
320
330
340
350
360
370
380
390
400
410
420
430
440
450
460
470
480
490
500
510
520
530
540
550
560
570
580
590
600
610
620
630
640
650
660
670
680
690
700
710
720
730
740
750
760
770
780
790
800
810
820
830
840
850
860
870
880
890
900
910
920
930
940
950
960
970
980
990
1000
1010
1020
1030
1040
1050
1060
1070
1080
1090
1100
1110
1120
1130
1140
1150
1160
1170
1180
1190
1200
1210
1220
1230
1240
1250
1260
1270
1280
1290
1300
1310
1320
1330
1340
1350
1360
1370
1380
1390
1400
1410
1420
1430
1440
1450
1460
1470
1480
1490
1500
1510
1520
1530
1540
1550
1560
1570
1580
1590
1600
1610
1620
1630
1640
1650
1660
1670
1680
1690
1700
1710
1720
1730
1740
1750
1760
1770
1780
1790
1800
1810
1820
1830
1840
1850
1860
1870
1880
1890
1900
1910
1920
1930
1940
1950
1960
1970
1980
1990
2000
2010
2020
2030
2040
2050
2060
2070
2080
2090
2100
2110
2120
2130
2140
2150
2160
2170
2180
2190
2200
2210
2220
2230
2240
2250
2260
2270
2280
2290
2300
2310
2320
2330
2340
2350
2360
2370
2380
2390
2400
2410
2420
2430
2440
2450
2460
2470
2480
2490
2500
2510
2520
2530
2540
2550
2560
2570
2580
2590
2600
2610
2620
2630
2640
2650
2660
2670
2680
2690
2700
2710
2720
2730
2740
2750
2760
2770
2780
2790
2800
2810
2820
2830
2840
2850
2860
2870
2880
2890
2900
2910
2920
2930
2940
2950
2960
2970
2980
2990
3000
3010
3020
3030
3040
3050
3060
3070
3080
3090
3100
3110
3120
3130
3140
3150
3160
3170
3180
3190
3200
3210
3220
3230
3240
3250
3260
3270
3280
3290
3300
3310
3320
3330
3340
3350
3360
3370
3380
3390
3400
3410
3420
3430
3440
3450
3460
3470
3480
3490
3500
3510
3520
3530
3540
3550
3560
3570
3580
3590
3600
3610
3620
3630
3640
3650
3660
3670
3680
3690
3700
3710
3720
3730
3740
3750
3760
3770
3780
3790
3800
3810
3820
3830
3840
3850
3860
3870
3880
3890
3900
3910
3920
3930
3940
3950
3960
3970
3980
3990
4000
4010
4020
4030
4040
4050
4060
4070
4080
4090
4100
4110
4120
4130
4140
4150
4160
4170
4180
4190
4200
4210
4220
4230
4240
4250
4260
4270
4280
4290
4300
4310
4320
4330
4340
4350
4360
4370
4380
4390
4400
4410
4420
4430
4440
4450
4460
4470
4480
4490
4500
4510
4520
4530
4540
4550
4560
4570
4580
4590
4600
4610
4620
4630
4640
4650
4660
4670
4680
4690
4700
4710
4720
4730
4740
4750
4760
4770
4780
4790
4800
4810
4820
4830
4840
4850
4860
4870
4880
4890
4900
4910
4920
4930
4940
4950
4960
4970
4980
4990
5000
5010
5020
5030
5040
5050
5060
5070
5080
5090
5100
5110
5120
5130
5140
5150
5160
5170
5180
5190
5200
5210
5220
5230
5240
5250
5260
5270
5280
5290
5300
5310
5320
5330
5340
5350
5360
5370
5380
5390
5400
5410
5420
5430
5440
5450
5460
5470
5480
5490
5500
5510
5520
5530
5540
5550
5560
5570
5580
5590
5600
5610
5620
5630
5640
5650
5660
5670
5680
5690
5700
5710
5720
5730
5740
5750
5760
5770
5780
5790
5800
5810
5820
5830
5840
5850
5860
5870
5880
5890
5900
5910
5920
5930
5940
5950
5960
5970
5980
5990
6000
6010
6020
6030
6040
6050
6060
6070
6080
6090
6100
6110
6120
6130
6140
6150
6160
6170
6180
6190
6200
6210
6220
6230
6240
6250
6260
6270
6280
6290
6300
6310
6320
6330
6340
6350
6360
6370
6380
6390
6400
6410
6420
6430
6440
6450
6460
6470
6480
6490
6500
6510
6520
6530
6540
6550
6560
6570
6580
6590
6600
6610
6620
6630
6640
6650
6660
6670
6680
6690
6700
6710
6720
6730
6740
6750
6760
6770
6780
6790
6800
6810
6820
6830
6840
6850
6860
6870
6880
6890
6900
6910
6920
6930
6940
6950
6960
6970
6980
6990
7000
7010
7020
7030
7040
7050
7060
7070
7080
7090
7100
7110
7120
7130
7140
7150
7160
7170
7180
7190
7200
7210
7220
7230
7240
7250
7260
7270
7280
7290
7300
7310
7320
7330
7340
7350
7360
7370
7380
7390
7400
7410
7420
7430
7440
7450
7460
7470
7480
7490
7500
7510
7520
7530
7540
7550
7560
7570
7580
7590
7600
7610
7620
7630
7640
7650
7660
7670
7680
7690
7700
7710
7720
7730
7740
7750
7760
7770
7780
7790
7800
7810
7820
7830
7840
7850
7860
7870
7880
7890
7900
7910
7920
7930
7940
7950
7960
7970
7980
7990
8000
8010
8020
8030
8040
8050
8060
8070
8080
8090
8100
8110
8120
8130
8140
8150
8160
8170
8180
8190
8200
8210
8220
8230
8240
8250
8260
8270
8280
8290
8300
8310
8320
8330
8340
8350
8360
8370
8380
8390
8400
8410
8420
8430
8440
8450
8460
8470
8480
8490
8500
8510
8520
8530
8540
8550
8560
8570
8580
8590
8600
8610
8620
8630
8640
8650
8660
8670
8680
8690
8700
8710
8720
8730
8740
8750
8760
8770
8780
8790
8800
8810
8820
8830
8840
8850
8860
8870
8880
8890
8900
8910
8920
8930
8940
8950
8960
8970
8980
8990
9000
9010
9020
9030
9040
9050
9060
9070
9080
9090
9100
9110
9120
9130
9140
9150
9160
9170
9180
9190
9200
9210
9220
9230
9240
9250
9260
9270
9280
9290
9300
9310
9320
9330
9340
9350
9360
9370
9380
9390
9400
9410
9420
9430
9440
9450
9460
9470
9480
9490
9500
9510
9520
9530
9540
9550
9560
9570
9580
9590
9600
9610
9620
9630
9640
9650
9660
9670
9680
9690
9700
9710
9720
9730
9740
9750
9760
9770
9780
9790
9800
9810
9820
9830
9840
9850
9860
9870
9880
9890
9900
9910
9920
9930
9940
9950
9960
9970
9980
9990
10000


STRAIN AT FAILURE .00216
FAILING LOAD 1900#
APPLIED SHEAR LBS
2000
1800
1600
1400
1200
1000
800
600
400
200
0
5-6
25-26
3-4
27-28
1-2
SPECIMEN NO. 114
0
10
30
20
.0004
UNIT STRAIN
String No
Gage No
Dist from fixed end to center of gage
20
1-2
14.0 inches
16
27-28
24
3-4
13
25-26
27
5-6

FIG 47



Strain No	Gage No	Dist from head end to center of gage
0	15-16	14.5 inches
1	17-18	"
4	19-20	"
35	12	"
55	9-10	"
7	21-22	"
10	23-24	"
30	7-8	"

FIG 48


STRAIN AT FAILURE .00194
FAILING LOAD 2010#
2000
1800
1600
1400
1200
1000
800
600
400
200
00
APPLIED SHEAR LBS
SPECIMEN NO 115
0
10
20
30
Strain No
Gage No
Dist from fixed end to cent of gage
20 1-2 16.5 inches
24 3-4 "
16 27-28 "
27 5-6 "
13 25-26 "
.0004
UNIT STRAIN

FIG 49


String No.
Gage No.
Dist. from fixed end to cent of gage
0 15-16 14.5 inches
1 13-14 "
39 17-18 "
4 11-12 "
36 19-20 "
7 9-10 "
33 21-22 "
10 7-8 "
30 23-24 "
0
10
20
30
SPECIMEN NO. 116
STRAIN AT FAILURE .00217
FAILING LOAD 2400#
APPLIED SHEAR LBS
2800
2400
2000
1600
1200
800
400
0
23-24
7-8
21-22
9-10
11-12-19-20
13-14-17-18
15-16
.0004
UNIT STRAIN

FIG. 50


Strain No
Gage No.
Dist. from fixed end to center of gage
20
2
48 inches
24
27-28
"
16
3-4
"
27
25
"
43
5-6
"
1.0
30
36
33
30
27
24
20
16
13
10
7
4
SPECIMEN NO. 116
STRAIN AT FAILURE .00217
FAILING LOAD 2400#
2800
2400
2000
1600
1200
800
400
0
APPLIED SHEAR LBS
.0004
UNIT STRAIN
FIG. 51


STRAIN AT FAILURE .0036
FAILING LOAD 710#
APPLIED SHEAR LBS
800
700
600
500
400
300
200
100
0
5-6
1-12
1-2
5-6
9-10
11-12
.0008
UNIT STRAIN
SPECIMEN NO 118
0
2
22
6
18
12
Strain No.
Gage No.
Dist from fixed end to gage
0 7-8 10.5 inches
2 5-6 "
6 3-6 "
12 1-2 "
18 11-12 "
22 9-10 "

FIG 52


STRAIN AT FAILURE .00364
FAILING LOAD 990#
APPLIED SHEAR LBS
1000
900
800
700
600
500
400
300
200
100
0
3-4
11-12
1-2
5-6
9-10
7-8
.0008
UNIT STRAIN
FIG. 58
SPECIMEN NO. 19
2
0
22
6
18
12
Strain Gage No.
Dist. from fixed end to cent. of gage
0 7-8 10.8 inches
2 5-6 "
6 3-4 "
12 1-2 "
18 11-12 "
22 9-10 "


STRAIN AT FAILURE .00853
FAILING LOAD 1460#
1400
1200
1000
800
600
400
200
0
3-4
11-12
1-2
9-10
5-6
7-8
.0008
UNIT STRAIN
SPECIMEN NO 120
0
2
22
6
18
12
String No. | Gage No. | Dist. from fixed end to center of gage
0 | 7-8 | 10.5 inches
2 | 5-6 | "
6 | 3-4 | "
12 | 1-2 | "
18 | 11-12 | "
22 | 9-10 | "

FIG 54


2
0
22
6
18
12
String No.
Gage No.
Dist. from fixed end to cent. of gage
0 7-8 10.5 inches
2 5-6 "
6 3-4 "
12 1-2 "
18 11-12 "
22 9-10 "
SPECIMEN NO 121
STRAIN AT FAILURE .00374
FAILING LOAD 2310 lbs
2800
2400
2000
1600
1200
800
400
0
APPLIED SHEAR LBS
3-4
11-12
1-2
5-6
9-10
7-8
.0008
UNIT STRAIN

FIG. 55


SPECIMEN NO. 122
0
6
18
12
STRAIN AT FAILURE .00525
FAILING LOAD 1663#
String No. | Gage No. | Gage Leng. | Dist. from fixed end to cent. of gage
1 | 9-10 | 3 | 17 inches
1 | 11-12 | " | 10.5
1 | 13-14 | " | 4
0 | 15-16 | 18 | 10.5
23 | 17-18 | " | 10.5
1600
1400
1200
1000
800
600
400
200
0
APPLIED SHEAR LOAD
9-10
11-12
13-14
15-16
17-18
.0016
UNIT STRAIN

FIG 56


SPECIMEN NO. 123
Strain Gage No
Gage Leng
Dist from fixed end to cent. of gage
1 9-10 3 4 inches
1 11-12 " 11
1 13-14 " 18
0 15-16 16 10.5
23 17-18 " 10.5
STRAIN AT FAILURE .00492
FAILING LOAD 2140#
APPLIED SHEAR LAS
2400
2000
1600
1200
800
400
0
9-10
11-12
13-14
15-16
17-18
.0016
UNIT STRAIN
FIG 57


STRAIN AT FAILURE .00481
FAILING LOAD 3220#
APPLIED SHEAR LBS
3200
2800
2400
2000
1600
1200
800
400
0
9-10
11-12
13-14
15-16
17-18
.0016
SPECIMEN NO. 124
0
6
12
18
Strong No. | Gage No. | Gage Long | Dist. from fixed end to cent. of gage
1 | 9-10 | 3 | 4 inches
1 | 11-12 | " | 10.5
1 | 13-14 | " | 17
0 | 15-16 | 16 | 10.5
23 | 17-18 | " | 10.5

FIG. 58



String No	Gage No	Dist. from fwd. end to cent. of gage
1	9-10	4 inches
1	11-12	10.5
1	13-14	17
0	15-16	10.5
23	17-18	10.5

FIG. 59


SPECIMEN NO. 126
0
10
30
20
STRAIN AT FAILURE .002074
String No. | Gage No. | Gage Leng. | Dist. from fixed end to cent. of gage
2 | 1-2 | 8 | 75 inches
2 | 3-4 | " | 14
2 | 5-6 | " | 20.5
0 | 7-8 | 16 | 14
38 | 29A | " | 14
FAILING LOAD 1600 #
1600
1400
1200
1000
800
600
400
200
0
APPLIED SHEAR LBS
1-2
3-4
5-6
7-8
29A
.0008
UNIT STRAIN

FIG. 60

Fig. 61



String No.	Gage No.	Gage Lang	Dist. from fixed end to cent of gage
38	1-2	3	7.6 inches
"	3-4	"	14
"	5-6	"	20.5
0	7-8	16	14
2	23-24	"	14

FIG. 61



Strain Gage No	Gage No	Dist from near end to center of gage
2	1-2	7.5 inches
"	3-4	14 "
"	5-6	20.5 "
0	7-8	14 "
38	9-10	14 "

FIG. 62

Fig. 63


STRAIN AT FAILURE .00205
0
10
30
20
String No. | Gage No. | Dist. from fixed end to cent. of gage
38 | 1-2 | 7.5 inches
" | 3-4 | 14 "
" | 5-6 | 20.5 "
0 | 7-8 | 14 "
SPECIMEN NO. 129
FAILING LOAD 2340 #
2400
2000
1600
1200
800
400
0
1-2
3-4
5-6
7-8
.0008
UNIT STRAIN

FIG. 63

Fig. 64



STRAIN DISTRIBUTION - SPECIMEN NO. 114

FIG. 64

Fig. 65



STRAIN DISTRIBUTION - SPECIMEN No. 115

FIG. 65



STRAIN DISTRIBUTION - SPECIMEN No. 11A

FIG. 66



LENGTHWISE DISTRIBUTION OF STRAIN FOR VARIOUS LOADS

FIG. 67


SPECIMEN NO. B1
2125#
1600#
1000#
DISTANCE FROM FIXED END (INCHES)
0
10
20
30
40
50
60
STRAIN X 10⁻⁶
30
20
10
LENGTHWISE DISTRIBUTION OF SHEAR FOR VARIOUS LOADS
FIG 68


I/I₀
P/P₀
2W₀
FIG 70



Fig. 71

Testing apparatus.

Fig. 72 (Specimen no. 107)

Top view of specimen which failed in compression. All specimens were loaded so that compression side was on top.

Fig. 73 (Specimen no. 107)

Side view of compression failure. Small buckles at sides appeared at failure.



Fig. 74 (Specimen no. 108)
Top view showing compression failure. At failure, buckles extended slightly over the sides.



Fig. 75 (Specimen no. 116)
Failure occurred by simultaneous bending and shear. Note shear buckles on side and compression buckle on top.



Fig. 76 (Specimen no. 117)

Top view of specimen which failed in shear. Note absence of compression buckles on top.



Fig. 77 (Specimen no. 117)

Side view of shear failure. Note that the shear buckles extend into the tension zone.



Fig. 78 (Specimen no. 119)

Compression failure. Note failure occurred over relatively small region near fixed end.



Fig. 79 (Specimen no. 121)

Compression failure.

REEL - C
349
A.T.I.
8530

TITLE: Some Investigations of the General Instability of Stiffened Metal Cylinders - VI - Stiffened Metal Cylinders Subjected to Combined Bending and Transverse Shear

AUTHOR(S): (Not known)

ORIGINATING AGENCY: National Advisory Committee for Aeronautics, Washington, D. C.

PUBLISHED BY: (Same)

ATI- 8530

DIVISION: (None)

SUBJ. ACCESS CO. TN-910

PUBLISHED ACCESS CO.

DATE	DOC. CLASS.	COUNTRY	LANGUAGE	PAGES	ILLUSTRATIONS
Sept '43	Unclass.	U.S.	Eng.	102	photos, tables, graphs, drwgs

ABSTRACT:

Investigation was conducted to determine the instability of stiffened metal cylinders subjected to combined bending and transverse shear. These tests were made on 55 sheet-covered specimens. Under a loading of combined bending and transverse shear, the failure of the specimens is characterized by two distinct types of failure, namely, a bending or shear failure. It is also pointed out that the failing loads of the specimens have not been influenced by the length of the specimens.

DISTRIBUTION: Request copies of this report only from Originating Agency

DIVISION: Stress Analysis and Structures (7)
SECTION: Structural Theory and Analysis Methods (2)

ATI SHEET NO.: R-7-2-34

SUBJECT HEADINGS: Cylinders - Stress analysis (28505); Cylinders, Stiffened - Instability (28610)

TITLE: Some Investigations of the General Instability of Stiffened Metal Cylinders - VI - Stiffened Metal Cylinders Subjected to Combined Bending and Transverse Shear

AUTHOR(S): (Not known)

ORIGINATING AGENCY: National Advisory Committee for Aeronautics, Washin ton, D. C.

PUBLISHED BY: (Same)

ATI- 8530

DIVISION: (None)

ORIG. AGENCY NO. TN-910

PUBLISHING AGENCY NO.

DATE	DOC. CLASS.	COUNTRY	LANGUAGE	PAGES	ILLUSTRATIONS
Sept '43	Unclass.	U.S.	Eng.	102	photos, tables, graphs, drwgs

U

ABSTRACT:

Investigation was conducted to determine the instability of stiffened metal cylinders subjected to combined bending and transverse shear. These tests were made on 55 sheet-covered specimens. Under a loading of combined bending and transverse shear, the failure of the specimens is characterized by two distinct types of failure, namely, a bending or shear failure. It is also pointed out that the failing loads of the specimens have not been influenced by the length of the specimens.

P20/11

DISTRIBUTION: Request copies of this report only from Originating Agency

DIVISION: Stress Analysis and Structures (7)

SECTION: Structural Theory and Analysis Methods (2)

SUBJECT HEADINGS: Cylinders - Stress analysis (28505); Cylinders, Stiffened - Instability (28610)

240 407

ATI Sh
Air De

AD-B805 373

DX

Wright-Patterson Air Force Base
Dayton, Ohio

[illegible]

[illegible]

[illegible] 1945

Classification cancelled per authority
of List NACA dd. 28 Sept 1945
George R. Jordan, USCO. 29 Apr 1949