# UNCLASSIFIED

# AD NUMBER

## AD457917

## NEW LIMITATION CHANGE

TO

Approved for public release, distribution unlimited

## FROM

Distribution authorized to U.S. Gov't. agencies and their contractors; [Administrative/Operational Use; 1 Feb 1965. Other requests shall be referred to U.S. Naval Civil Engineering Lab., Port Hueneme, CA.

# AUTHORITY

USNCBC ltr, 24 Oct 1974

THIS PAGE IS UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.



#### EVALUATION OF PAINT SYSTEMS FOR USE IN RADIOISOTOPE LABORATORIES

Y-F015-06-06-902

Type B

by

J. B. Crilly and S. H. Bassett

#### ABSTRACT

Two paints, one based on epoxy resin and the other a strippable coating, were tested on concrete and on wood and compared to bare stainless steel for ease of cleaning of radioactive contaminants. It was found that the epoxy paint, Plasite 7122, provides a surface that can be easily decontaminated. This paint is in routine use at the Atomic Energy Commission's Los Alamos Scientific Laboratory, where it is employed to coat surfaces that are routinely exposed to radioactive contamination, and has been found to provide a readily cleanable surface.

The strippable coating, Fuller's Stripcoat, intended to be removed and replaced when contaminated, was effective for aqueous contaminant solutions but was ineffective for oily contaminants, which dissolved and penetrated the coating.

> Qualified requesters may obtain copies of this report from DDC. The Laboratory invites comment on this report, particularly on the results obtained by those who have applied the information.

#### INTRODUCTION

To resist contamination, the surfaces of materials of construction should be smooth and unbroken, chemically inert, nonabsorbent, and hydrophobic.<sup>1</sup> Of the materials, wood, concrete, and stainless steel, only stainless steel can be considered to possess these characteristics. Wood and concrete can be made to present such surface characteristics if coated with a paint which provides a contaminationresistant surface.

Mechanisms by which a radioactive species becomes affixed so as to contaminate a material are similar to those by which similar, nonradioactive substances adhere under liter conditions.<sup>2</sup> Coatings which are known to be chemically resistant to reagents are suitable prospects for testing for resistance to their radioactive counterparts. In this investigation the coatings tested were any epoxy-resin-based paint and a strippable coating. The paint was considered to be a permanent surface for the base material; the strippable coating was to be removed and replaced when contaminated. The epoxy coating was applied to concrete and to wood, while the strippable coating was applied to painted wood only. They were compared to bare stainless steel for resistance to contamination and ease of decontamination. The results are supplemented by the results of other experimenters and evaluated in light of experience with the epoxy coating at the Los Alamos Scientific Laboratory.

#### **TEST PROCEDURE**

The epoxy coating selected by the Bureau of Yards and Docks for evaluation was Plasite 7122, a product of the Wisconsin Coating Corporation, Green Bay, Wisconsin. The strippable coating was Fuller's Stripcoat, supplied by the W. P. Fuller Company, San Francisco, California.

Ten  $2 \times 6 \times 16$ -inch segments of concrete blocks were undercoated with a fill coat of Plasite 9028 and topcoated with Plasite 7122. Ten  $1/4 \times 6 \times 16$ -inch plywood panels were coated with Plasite 7122, and ten others were undercoated with enamel conforming to Federal Specification TT-E-489, a medium oil-alkyd resin paint, and overcoated with the Fuller's Stripcoat. Ten  $1/8 \times 6 \times 16$ -inch unpainted stainless steel panels were used for the comparison.

The contaminants used were radioactive phosphorus in tri-n-butyl phosphate, and "aged mixed fission products," which constitute an aqueous solution of such isotopes as zirconium-93, cesium-135, cesium-137, and cerium-144 obtained from fission of uranium-235. The tri-n-butyl phosphate was used to test the effects of an oily substance on the test surfaces; the aged mixed fission products were used to test the effects of aqueous solutions.

An 80-microliter increment of contaminant preparation was spotted on the test panel and allowed to stand 15 minutes prior to initial measurement. Measurement of radioactivity was made in triplicate with a Geiger-Mueller detector positioned in a lead brick chamber 10 millimeters above the contaminated surface. The panel was then scrubbed ten times with a paper towel soaked in an aqueous solution of "Tide," a commercial detergent, then rinsed and dried with paper toweling and remeasured for radioactive contamination. This procedure was repeated for 30 additional scrubbings, and again for 40 additional scrubbings. If the panel still showed significant radioactive contamination, it was scrubbed ten times with moistened "Comet," a commercial household cleanser, applied with a paper towel, followed by rinsing, drying, and remeasuring. Two cycles of 20 and then 30 additional cleanser scrubbings were made, and a final measurement was taken.

#### TEST RESULTS

The data presented in Tables I through IV have been corrected for radioactive decay, instrument resolution, and background activity as described in the Appendix. Average values obtained from triplicate runs are presented in the form of bar graphs, Figures 1 and 2.

The stainless steel, Table I, was almost completely resistant to the oily tri-n-butyl phosphate; the first washing reduced its radioactivity to approximately the background count rate of 34 counts per minute. The tri-n-butyl phosphate contamination of the Plasite on concrete, Table II, and Plasite on wood surfaces, Table III, was reduced by the first washing to about 50 times the background measurement. Repeated scrubbing, according to the experimental procedure, resulted in about another sevenfold reduction in contaminant. The Fuller's Stripcoat, Table IV, was soluble in the tri-n-butyl phosphate, which therefore penetrated to the TT-E-489 enamel beneath it. Stripping the panel of its coating failed to remove the test spot. Thus, for tri-n-butyl phosphate, the stainless steel surface is easiest to clean; the Plasite on concrete and Plasite on wood can be cleaned satisfactorily; but the Stripcoat does not leave a clean subsurface when stripped off and is unsatisfactory for this sort of contaminant.

The aqueous solution of aged mixed fission products did not penetrate the Stripcoat, and in this case stripping the panel of its coating successfully removed the test spot. This contaminant on Plasite on concrete was removed by the first washing to about 30 times background radioactivity, and after the first cleanser scrubbing the measurement was reduced nearly to background level. This contaminant on Plasite on wood was reduced to about 500 times background measurement by the first washing, and repeated scrubbings resulted, finally, in a reduction in contamination to about five times background. The aged mixed fission products adhered so strongly to the stainless steel that a chemical adsorption or an exchange reaction might be suspected. At the end of the scrubbing procedure the contamination was still about 150 times background. Some further reduction to about nine times background, was achieved by soaking 84 hours in a strong solution of a chelating agent, "Versene."

#### TAKARAZUKA RADIATION LABORATORY RESULTS

Since this work was begun, a report of extensive work on "Radioactive Contamination and Decontamination of Coatings" has appeared.<sup>3</sup> The coatings and surfaces tested, arranged in order of "cleanability," were the following:

> Polyurethane Strippable coating Acrylic lacquer Melamine alkyd Acrylic lacquer containing nitrocellulose Glass Nitrocellulose lacquer Polyvinyl chloride-acetate copolymers Polyethylene Silicon resin Epoxy resin polyamide cured Alkyd Aluminum Stainless steel Lead

The contaminants used were acidic aqueous solutions of radioactive phosphoric acid, sulfuric acid, sodium iodide, barium chloride, and fission products. Decontaminating solutions were moderately strong acids instead of the mild detergent used in the work at NCEL. The rating system was essentially that of Tompkins and Bizzel,<sup>4</sup> who investigated the susceptibility of some 75 proprietary paints, plastics, and floor coverings to contamination and ease of decontamination.



Figure 1. Contamination by tri-n-butyl phosphate.



Figure 2. Contamination by aged mixed fission products.

The work reported in Reference 3 shows an increase in ease of cleaning by a factor of nearly 1,000 between stainless steel and the polyurethane coating, which was easiest to clean. The work reported here is in substantial agreement with previous reports<sup>3,4</sup> in that it shows an epoxy coating to be more easily cleaned of aqueous contaminants than stainless steel.

#### **IN-SERVICE EVALUATION OF PLASITE 7122**

Two laboratories at the Atomic Energy Commission's Scientific Laboratory at Los Alamos, New Mexico, were visited for the purpose of evaluating Plasite 7122 under routine use in a radioactive environment. In one laboratory, work in progress included process development for the preparation of plutonium, while americium, curium, and berkelium compounds were being worked with in the other. These two laboratories are maintained similarly.

Work is conducted in approximately  $5 \times 5 \times 10$ -foot dry boxes. Some of the special-use boxes, constructed of mild steel and coated with Plasite 7122 according to the paint manufacturer's directions, have been in use for 12 years. The paint was inspected and no evidence of blistering, checking, cracking, chalking, or rusting was found. In some of the corrosive-use dry boxes, the Plasite has shown a tendency to discolor, but again no failure due to blistering, chalking, or rusting has occurred.

Flooring materials of rubber mat, vinyl tile, concrete, and steel are painted with Plasite 7122. This floor paint has held up under cloth overshoe scuffing and daily detergent-and-water mopping for approximately 2 years between repaintings.

In the event of accidental spills, decontamination is effected with an aqueous sodium citrate and soap cleaning solution and by removal of paint as necessary. Removal and replacement of steel or concrete is not found to be necessary; it is protected by the paint. After decontamination, the affected area is repainted with Plasite 7122. Due to some lot to lot differences in color, repainted areas often appear somewhat unsightly.

#### FINDINGS AND CONCLUSIONS

The strippable coating worked either very well or not at all, depending upon whether or not it was dissolved by the contaminant. Removal of the coating contaminated with the aqueous solution of aged mixed fission products effectively removed all of the contaminant; the tri-n-butyl phosphate dissolved the coating and the contaminated spot did not strip off, and so the coating was ineffective.

The Plasite on concrete and Plasite on wood surfaces can be cleaned of contamination by both tri-n-butyl phosphate and aged mixed fission products. These surfaces are satisfactory.

The stainless steel was easy to cleanse of tri-n-butyl phosphate and is a satisfactory surface for exposure to this contamination. It was difficult to cleanse of aged mixed fission products, and its resistance to this sort of aqueous contamination is questionable.

The Plasite 7122 brand of  $e_1 roxy$  resin paint has been used by the Los Alamos Scientific Laboratory to coat surfaces that are routinely exposed to a radioactive environment. This activity is primarily interested in the protection against radioactive contamination afforded by this paint. Experience has shown this protection to be satisfactory.

#### ACKNOWLEDGMENT

Dr. L. B. Gardner of the Physics Division, NCEL, corrected the data for errors due to Geiger tube resolution, decay of radioactive samples, and background activity. He supplied the Appendix, describing the analysis of data.

#### Appendix

#### DATA ANALYSIS

All counting data was analyzed by published techniques, utilizing the computer programs PDC, DATORG, RESOL, DCISON, STAT, and DECAY. Counting data was corrected for decay back to 1200 on 3 June 1964, the time of the first observations. Correction for the background count rate of 34 counts per second was included. The same counting system (1.4-mg/cm<sup>2</sup> mica end-window detector and Berkeley scaler Model 2000) was used throughout. The same perpendicular distance from source to test panel was also used throughout, although the geometry cannot be said to be constant because of the possibility of spreading sample material during washing of the panels.

Two different radioactive materials were used in these experiments: aged mixed fission products and tri-n-butyl phosphate tagged with phosphorus-32. The effective half-life of the mixed fission products over the period of these experiments was separately determined to be 147 days, by following the decay of a sample evaporated on a planchet. The half-life of the tri-n-butyl phosphate was taken to be 14.5 days based on the half-life of phosphorus-32.

The variation of count rate with sample size was studied separately. In this study 1-centimeter squares were marked off around the center of the panel, and 0.1 milliliter of radioisotope was pipetted in each square. Separate panels were used for each of the two isotopes. After each successive grouping of squares around the center of the panel, beginning with four squares followed by additional encirclements or squares, the count rate was determined as a function of the perpendicular distance from the panel to the detector's window. From this data, the distance of 10 millimeters was selected for the performance of the decontamination experiments.

By separate experiment, in which the decay of a highly active sample of 9.9-minute copper<sup>62</sup> was measured, the dead time of the counting system was determined to be 3.26 x 10<sup>-6</sup> minutes.

	Average Count Rate (counts/min)			
Measurement	Mixed Fission Products Contamination	Tri-n-butyl Phosphate Contamination		
Initial	17,100,000	80,400		
10 detergent scrubs	19,300	40		
40 detergent scrubs	15,100			
80 detergent scrubs	12,600			
10 cleanser scrubs	7,820			
30 cleanser scrubs	6,240			
60 cleanser scrubs	5,560			

### Table I. Cleanability of Stainless Steel (corrected data)

### Table II. Cleanability of Plasite on Concrete (corrected data)

	Average Count Rate (counts/min)			
Measurement	Mixed Fission Products Contamination	Tri-n-butyl Phosphate Contamination		
Initial	4,950,000	60,600		
10 detergent scrubs	1,050	1,450		
40 detergent scrubs	729	1,160		
80 detergent scrubs	596	1,100		
10 cleanser scrubs	61	787		
30 cleanser scrubs		360		
60 cleanser scrubs		180		

	Average Count Rate (counts/min)			
Measurement	Mixed Fission Products Contamination	Tri-n-butyl Phosphate Contamination		
Initial	9,490,000	322,000		
10 detergent scrubs	18,600	1,690		
40 detergent scrubs	14,900	1,330		
80 detergent scrubs	13,900	1,280		
10 cleanser scrubs	1,510	964		
30 cleanser scrubs	377	552		
60 cleanser scrubs	156	232		

## Table III. Cleanability of Plasite on Wood (corrected data)

### Table IV. Performance of Stripcoat on TT-E-489 (corrected data)

	Average Count Rate (counts/min)			
Measurement	Mixed Fission Products Contamination	Tri-n-butyl Phosphate Contamination		
Initial	5,230,000	Contaminant dissolved and penetrated the Stripcoat		
Stripped	34			

#### REFERENCES

1. H. Wells. "Decontaminable surfaces," in United Kingdom Atomic Energy Authority, Authority Health and Safety Branch report AHSB (S) R 57: Decontamination; a symposium held at Risley on 20 March 1963, pp. 1–14. Risley, Warrington, Lancashire, England, June 1963.

2. W. J. Colclough. "Methods of assessing decontaminable surfaces," in United Kingdom Atomic Energy Authority, Authority Health and Safety Branch report AHSB (S) R 57: Decontamination; a symposium held at Risley on 20 March 1963, pp. 15–26. Risley, Warrington, Lancashire, England, June 1963.

3. R. Kuninori and M. Hazue. "Radioactive contamination and decontamination of some protective coatings," Official Digest, vol. 36, no. 470, March 1964, pp. 256–267.

4. P. C. Tompkins and O. M. Bizzel. "Working surfaces for radiochemical laboratories: Glass, stainless steel, and lead," Industrial and Engineering Chemistry, vol. 42, no. 8, Aug. 1950, pp. 1469–1475; Also, P. C. Tompkins, O. M. Bizzel, and C. D. Watson, "Working surfaces for radiochemical laboratories: Paints, plastics, and floor materials," Industrial and Engineering Chemistry, vol. 42, no. 8, Aug. 1950, pp. 1475–1481.

#### DISTRIBUTION LIST

SNDL Code	No. of Activities	Total Copies	
	1	10	Chief, Bureau of Yards and Docks (Code 42)
23A	1	1	Navai Forces Commanders (Taiwan only)
39B	2	2	Construction Battalions
39 D	5	5	Mobile Construction Battalions
39E	3	3	Amphibious Construction Battalions
39F	1	2	Construction Battalion Base Units
A2A	1	1	Chief of Naval Research - Only
A3	2	2	Chief of Naval Operation (OP-07, OP-04)
A5	5	5	Bureaus
В3	2	2	Colleges
E4	1	2	Laboratory ONR (Washington, D. C. anly)
E5	1	1	Research Office ONR (Pasadena only)
E16	1	1	Training Device Center
F9	7	7	Station — CNO (Boston; Key West; San Juan; Long Beach; San Diego; Treasure Island; and Radman, C. Z. only)
F17	6	6	Communication Station (San Juan; San Francisco; Pearl Harbor; Adak, Alaska; and Guam only)
F41	1	1	Security Station
F42	1	1	Radio Station (Oso and Cheltanham only)
F 48	1	۱	Security Group Activities (Winter Harbor only)
F61	2	2	Naval Support Activities (London and Naples only)
F77	1	1	Submarine Base (Groton, Conn. only)
F81	2	2	Amphibious Bases
H3	7	7	Hospital (Chelsea; St. Albans, Portsmouth, Va.; Beaufort; Great Lakes; San Diego; and Camp Pendleton only)
H6	1	1	Medical Center
1L	2	2	Administration Command and Unit – BuPers (Great Lakes and San Diego only)
73	1	1	U. S. Fleet Anti-Air Warfore Training Center (Virginia Beach only)
J 19	1	I	Receiving Station (Brooklyn only)
J34	1	1	Station - BuPers (Washington, D. C. only)

#### DISTRIBUTION LIST (Cont'd)

SNDL Code	No. of Activitios	Total Copies	
J46	1	1	Personnel Center
J48	1	1	Construction Training Unit
J60	1	1	School Academy
J65	1	1	School CEC Officers
J84	1	1	School Postgraduate
J90	1	1	School Supply Corps
J95	1	1	School War College
.199	1	1	Communication Training Center
L1	11	11	Shipy ard s
L7	4	4	Laboratory – BuShips (New London; Panama City; Carderock; and Annapolis only)
∟26	5	5	Naval Facilities — BuShips (Antigua; Turks Island; Barbados; San Salvador; and Eleuthera only)
L42	2	2	Flout Activities - BuShips
M27	4	4	Supply Center
M28	6	6	Supply Depot (except Guantanamo Bay; Subic Bay; and Yokosuka
M61	2	2	Aviation Supply Office
וא	G	18	BuDocks Director, Overseas Division
N2	9	27	Public Works Offices
N5	3	9	Construction Battalion Center
N6	5	5	Construction Officer-in-Charge
N7	1	1	Construction Resident-Officer-in-Charge
N9	6	12	Public Works Center
N14	1	1	Housing Activity
R9	2	2	Recruit Depots
R10	2	2	Supply Installations (Albany and Barstow only)
R20	1	1	Marine Corps Schools (Quantico)
R64	3	3	Marine Corps Base
R66	1	1	Marine Corps Camp Detachment (Tengan only)
VIAI	6	6	Air Station
W1A2	35	35	Air Station
WIB	8	8	Air Station Auxiliary

SNDL Code	No. of Activities	Total Copies	
w1c	3	3	Air Facility (Phoenix; Naha; and Naples only)
WIE	6	6	Marine Corps Air Station (except Quantico)
พ۱н	9	9	Station - BuWeps (except Rota)
	1	1	Deputy Chief of Staff, Research and Development, Headquarters, U. S. Marine Corps, Washington, D. C.
	۱	١	President, Marine Corps Equipment Board, Marine Corps School, Quantico, Va.
	1	۱	Chief of Staff, U. S. Army, Chief of Research and Development, Department of the Army, Washington, D. C.
	۱	1	Office of the Chief of Engineers, Assistant Chief of Engineering for Civil Works, Department of the Army, Washington, D. C.
	1	١	Chief of Engineers, Department of the Army, Washington, D. C., Attn: Engineering Research and Development Division
	1	۱	Chief of Engineers, Department of the Army, Washington, D. C., Attn: ENGCW-OE
	1	3	Headquarters, U. S. Air Force, Directorate of Civil Engineering, Washington, D. C., Attn: AFOCE-ES
	۱	1	Commanding Officer, U. S. Naval Construction Battalion Center, Port Hueneme, Calif., Attn: Materiel Dept., Code 140
	1	۱	Deputy Chief of Staff, Development, Director of Research and Development, Department of the Air Force, Washington, D. C.
	۱	1	Director, National Bureau of Standards, Department of Commerce, Connecticut Avenue, Washington, D. C.
	۱	2	Office of the Director, U. S. Coast and Geodetic Survey, Washington, D. C.
	۱	20	Defense Documentation Center, Building 5, Cameron Station, Alexandria, Va.
	1	2	Director of Defense Research and Engineering, Department of Defense, Washington, D. C.
	1	2	Director, Bureau of Reclamation, Washington, D. C.
	۱	1	Faculaties Officer, Code 108, Office of Naval Research, Washington, D. C.
	1	١	Foderal Aviation Agency, Office of Management Services, Administrative Services Division, Washington, D. C., Attn: Library Branch

#### DISTRIBUTION LIST (Cont'd)

.

.

#### DISTRIBUTION LIST (Cont'd)

No. of Activities	Total Copies	
١	2	Commander Naval Beach Group Two, U. S. Naval Amphibious Base, Little Creek, Norfolk, Va.
1	1	Commander, Pacific Missile Range, Technical Documentation Section, P. O. Box 10, Point Mugu, Calif., Attn: Code 4332
۱	2	U. S. Army Engineer Research and Development Laboratories, Attn: STINFO Branch. Fort Belvoir, Va.
۱	١	Systems Engineering Group, Deputy for Systems Engineering, Directorate of Technical Publications and Specifications, Wright-Patterson AFB, Ohio
1	1	Paint Laboratory, U. S. Engineers Office, Clock Tower Building, Rock Island, III.
1	1	Puget Sound Naval Shipyard, Technical Library, Code 245.1D, Bremerton, Wash.
1	1	U. S. Air Force, Air University Library, Maxwell Air Force Base, Ala.
1	۱	John A. Feroli, Technical Assistant, Engineering Testing, Development and Proof Services, U. S. Army Aberdeen Proving Ground, Md.

.

<ul> <li>U. S. Naval Civil Engineering Jabo-Jony EVALUATION OF PAINT SYSTEMS FOR USE IN RADIOISOTOPE EVALUATION OF PAINT SYSTEMS FOR USE IN RADIOISOTOPE LABORATORIES, by J. B. Crilly and S. H. Basseth T.R.363 15 p. illus 1 Feb 65 Official Use Only</li> <li>I. Prints - Radioisotope laboratories I. Y-F015-06-00-902</li> <li>Two points, one based on epoxy resin and the other a strippoble coating, were tested an concrete and on wood and compared to bare stainless steel for ease of cleaning of andiaactive easily decontamination, and has been found to provide a surface that can be contention. It was found that the epoxy paint, Plasite 7122, provides a surface that can be contention. It was found that is ambleved to bare stainless steel for ease of cleaning of andiaactive easily decontamination, and has been found to provide a readinely cleanable surface. The trippoble conting. Fulls's Stripcont, intended to be removed and replaced when combin- niced, was effective for openeous contaminant solutions but was ineffective for only contaminant, which disolved and penetrated the conting.</li> </ul>	<ul> <li>U. S. Naval Civil Engineering Laboratory</li> <li>U. S. Naval Civil Engineering Laboratory</li> <li>EVALUATION OF PAINT SYSTEMS FOR USE IN RADIOISOTOPE</li> <li>LABORATORIES, by J. B. Crilly and S. H. Bassett</li> <li>TR-363 15 p. illus</li> <li>I. Feb 65 Official Use Only</li> <li>I. Points – Radioisotope laboratories</li> <li>I. V-F015-06-06-902</li> <li>Two paints, are based on epoxy resin and the other a strippoule costing, were tested on concrete and on wood and compared to bare stolleds and the other a strippoule costing, were tested on concrete and on wood and compared to bare stolleds a strippoule costing, were tested on content the epoxy paint, Plosite 7122, provides a surface that can be existly decontaminated. This paint is in routine use of the Atomic Energy Commission's Las Alamos Scientific Laboratory, where it is employed to cont surfaces that are noutinely exposed to adjocitive communition, and has been found to provide a randity cleanable surface. The strippoble costing, were instant solutions but was ineffective for oily contominants, which discloved and penetrated the costing.</li> </ul>
<ul> <li>U. S. Navel Civil Engineering Jaboratory EVALUATION OF PAINT SYSTEMS FOR IN RADIOISOTOPE LABORATORIES, by J. B. Crilly and S. H. Basett TR-363 15 p. illus J Fab 65 Official Use Only</li> <li>J. Paints – Radioisotope laboratories J. Y-F015-06-06-902</li> <li>Two painty, are based an epoxy resin and the other a strippable coarting, were tested on concrete and on wood and compared to bute stunieles steel for ease of cleaning of radioactive contract and on wood and compared to bute stunieles steel for ease of cleaning of radioactive contracter and on wood and compared to bute stunieles steel for ease of cleaning of radioactive contractive contaminants. It was found that the epoxy point, Plassis 1722, provides a surface that can be easily decontaminated. It is paint is in routine use at the Abonic Energy Commission's Las Alamos Scientific Laboratory, where it is employed to cost surfaces that are radiity elecantamination. The strippable costing, Fuller's Stripcost, intended to be removed and replaced when contam- instred, was fictive for queoso contage.</li> </ul>	<ul> <li>U. S. Navel Civil Engineering Laboratory EVALUATION OF PAINT SYSTEMS FOR USE IN RADIOISOTOPE LABORATORLES, by J. B. Crilly and S. H. Basseth TR-363 15 p. illus 1 Feb 65 Official Use Dnly</li> <li>J. Paints - Radioiscrope laboratories 1. Y-F015-06-06-902</li> <li>Two paints, one based on epoxy resin and the other a strippable carting, were tested on contrainants. It was found that the expany point, Plaste 1722, provides a surface that can be easily decontunination, and hos the antic use of cleaning of natioactive contrainants. It was found that the epoxy point, Plaste 7122, provides a surface that can be easily decontunination, and hos been found to provide a readily clearable surface. The strippable conting, Fuller's Stripcost, intended to be removed and replaced when contrain- incled, was effective for oqueous combinism solutions but was ineffective for oily commismus, which dissolved and penetrated the conting.</li> </ul>

.

•

.

. .

Unclassified				
Security Classification				
DOCUMEN	T CONTROL DATA - R&		the overall center is classified)	
1. ORIGINATIN & ACTIVITY (Corporate author)	musking annotation must be an	2.4. REPOI	AT SECURITY CLASSIFICATION	
U. S. Naval Civil Engineering Laborato	vrv	Unclassified		
Port Hueneme, California 93041	/	26. GROUP		
- REPORT TITLE		L		
Evaluation of Paint Systems for Use in F	Radioisotope Laborator	ies		
4. DESCRIPTIVE NOTES (Type of report and inclusive dat	••)	. <u></u>	·····	
Final Subtask, April 1964 – August 196	4			
5. AUTHOR(S) (Lest name, list name, initial)				
Crilly, J. B.				
Bashett, S. H.				
. REPORT DATE	74. TOTAL NO. OF P	AGES	75. NO. OF REFS	
1 February 1965	15		4	
SA. CONTRACT OR GRANT NO.	SA. ORIGINATOR'S RE	PORT NUM	NER(S)	
а раојест но. Y-F015-06-06-902	TR-363			
e.	Sb. OTHER REPORT (	NO(3) (Any	other numbers that may be easigned	
d.				
10. AVAILABILITY/LIMITATION NOTICES				
Qualified requesters may obtain copies	of this report from DD	юс.		
11. SUPPLEMENTARY NOTES	12. SPONSORING MILI	TARY ACTI	IVITY	
For Official Use Only	BUDOCKS			
13. ABSTRACT	<u>-l</u>			
Two paints, one based on epoxy r concrete and on wood and compared to contaminants. It was found that the ep easily decontaminated. This paint is in Los Alamos Scientific Laboratory, where exposed to radioactive contamination, o	esin and the other a si bare stainless steel fo oxy paint, Plasite 712 routine use at the Ate e it is employed to co and has been found to	trippable r ease of 2, provic omic Ene at surfac provide	a coating, were tested on f cleaning of radioactive les a surface that can be orgy Commission's es that are routinely a readily cleanable	

The strippable coating, Fuller's Stripcoat, intended to be removed and replaced when contaminated, was effective for aqueous contaminant solutions but was ineffective for oily contaminants, which dissolved and penetrated the coating.

DD 1508 1473 0101-807-6800

surface.

Unclassified Security Classification

Unclassified Security Classification						
	LIN	K A	LIN	K 8	LIN	ĸc
	ROLE	WT	ROLE	WT	ROLE	WT
Paints Protective Coatings Epoxy Resins Protection Decontamination Surfaces Radioisotopes Radioactivity Contamination	8 8 4 4 9 3 3 3 3					
INSTRU	ICTIONS	<u> </u>	<u> </u>			<u> </u>
<ol> <li>ORIGINATING ACTIVITY: Enter the name and address of the contractor, subcontractor, grantee, Department of De- fense activity or other organization (corporate suthor) issuing the report.</li> <li>REPORT SECURITY CLASSIFICATION: Enter the over- ell security classification of the report. Indicate whether "Restricted Date" is included. Marking is to be in accord- ance with appropriate security regulations.</li> <li>GROUP: Automatic downgrading is specified in DoD Di- rective 5200, 10 and Armed Forces Industrial Manusi. Enter the group number. Also, when applicable, show that optional markings have been used for Group 3 and Group 4 as author- ized.</li> <li>REPORT TITLE: Enter the complete report title in all capital letters. Titles in all cases should be unclassifica- tion, show title classification in all capitals in parenthesis immediately following the title.</li> <li>DESCRIPTIVE NOTES: If appropriate, enter the type of report, e.g., interim, progress, summary, annual, or final. Give the inclusive dates when a specific reporting period is covered.</li> <li>AUTHOR(S): Enter the name(s) of author(s) as shown on or in the report. Enter last name, first name, middle initial. If military, show rank and branch of service. The name of the principal author is an absolute minum requirement.</li> <li>REPORT DATE: Enter the date of the report as day, month, year, or month, year. If more than one date appears on the report, use date of publication.</li> <li>NUMISER OF REFERENCES: Enter the total number of references cited in the report.</li> <li>CONTRACT OR GRANT NUMBER: If appropriate, enter the applicable number of the contract or grant under which the report was written.</li> <li>&amp; CONTRACT OR GRANT NUMBER: If appropriate, enter the applicable number of the contract or grant under which the report was written.</li> <li>&amp; CONTRACT OR GRANT NUMBER: If appropriate, enter the applicable number of the contract or grant under which the report was written.</li> <li>AVAILA</li></ol>	imposed by security such as: (1) "Qualified report from (2) "Foreign 4 report by I (3) "U. S. Got this report users shal (4) "U. S. mil report dire shall reque (5) "All distri- ified DDC If the report has Services, Departme- Cate this fact and e 11. SUPPLEMENT tory notes. 12. SPONSORING the departmental pr ing for) the researc 13. AISTRACT: 1 summary of the doc it may also appear port. If additional be attached. It is highly den for short phrases the formation in the pay There is no lin ever, the suggested 14. KEY WORDS: or short phrases the words but will be for text. The assignment	requesting requests DDC:: mico-incer DDC is m rement directly is request is request is request is request is request bution of users sh bution of users sh a been fun is been fun is been fun is been fun is a been	estion, us ers may ob ment and c a subhoriz agencies : from DDC, through ncies may DDC. Ot gh f this repo all reques rnished to merce, fo price, if k TFS: Use extra bastract g dicative of abstract g abstract g abstract g required. the sessification of the required. at the abs graph of the sessification of the region 150 ds are tech terize a re the region 150 ds are tech terize a re tech terize a re tech terize a re tech terize a re tech terize	ing stan tain cop ilasemin ed." may obta obtain c her quall rt is con t through the Offi r sale to nown f for add includ	dard state iss of thi ation of thi in copies qualified copies of fied user trolled. C the public trolled. C the public trolled. C the public trolled construct the public trolled construct trolled	his his his of DDC 

#### Unclassified Security Classification

.

.