

AD

AUG 1 6 1968

-111

CCL REPORT NO. 251

FINAL REPORT

STORAGE OF ETHYLENE GLYCOL ANTIFREEZE IN UNLINED TIN CONTAINERS

BY

JAMES H. CONLEY

JULY 1968

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

U. S. ARMY COATING & CHEMICAL LABORATORY

Aberdeen Proving Ground Maryland

> Reproduced by the CLEARINGHOUSE for Federal Scientific & Technical Information Springfield Va. 22151



DDC AVAILABILITY NOTICE

Qualified requestors may obtain opies of this report from Defense Documentation Center, Cameron Station, Alexandria, Virginia 22314

THE FINDINGS IN THIS REPORT ARE NOT TO BE CONSTRUED AS AN OFFICIAL DEPARTMENT OF THE ARMY POSITION, UNLESS SO DESIGNATED BY OTHER AUTHORIZED DOCUMENTS.

DESTROY THIS REPORT WHEN IT IS NO LONGER NEEDED. DO NOT RETURN IT TO THE ORIGINATOR.

Ì

\$10

UNCLASSIFIED

A Start March

«., »

CCL REPORT NO. 251

FINAL REPORT

STORAGE OF ETHYLENE GLYCOL ANTIFREEZE IN UNLINED TIN CONTAINERS

BY

JAMES H. CONLEY

JULY 1968

AMCMS CODE NO. 5025.11.80300

DEPARTMENT OF THE ARMY PROJECT NO. 1G024401A109

U. S. ARMY COATING AND CHEMICAL LABORATORY ABERDEEN PROVING GROUND MARYLAND

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

UNCLASSIFIED

i

ABSTRACT

3

The object of this study was to investigate the effect of pH on the package stability of mercaptobenzothiozole-borax inhibited ethylene glycol antifreeze compounds. The antifreeze compounds were packaged in unlined tin plated containers for a two-year period.

Results show that antifreeze compounds with pH values below 10.3 caused corrosion in less than six months. Containers filled with compounds having pH values above 10.3 showed some corrosion in one year and were generally unsatisfactory after two years storage. Most of the attack was at the junction of the bottom and side seams of the containers.

.

TABLE OF CONTENTS

Page No.

TITLE PAGE	ī
ABSTRACT	11
INTRODUCTION	1
DETAILS OF TEST	2
RESULTS OF TEST	2
DISCUSSION AND CONCLUSIONS	3
RECOMMENDATIONS	3
REFERENCES	3 - 4
APPENDIX A	5
Tables I - V	5 - 9
APPENDIX B	10
Phótograph 1	11
DISTRIBUTION LIST	12 - 14
DD FORM 1473	15

III

I. INTRODUCTION

Aberdeen Proving Ground, Maryland, was directed by AMC program directive AMCMS Code No. 5025.11.80300 dated 22 September 1967 to investigate improved antifreeze compounds.

A large number of commercial antifreeze compounds in use today contain combinations of borate type inhibitors and mercaptobenzothiazole (MBT) or alkali metal salts of mercaptobenzothiazole. These compounds are usually packaged in tin containers, some of which have organic liners. They contain less than 0.05% MBT and are packaged at pH values of about 9.5. This is less than the desired amount of MBT needed for good service performance.

Corrosion difficulties have been encountered in the packaging of ethylene glycol antifreezes, especially if large amounts of MBT are present in the inhibitor system. MBT caused some corrosion in tin plated containers around the soldered side seam and considerably more at the point of junction of the side and bottom seams.

Undiluted ethylene glycol containing borax as an inhibitor composes Federal Specification 0-A-548, Type 1, antifreeze. This material is specified for Army use by TB-ORD-651. It has an acidic pH (below 7.0) and tends to cause corrosion of tin containers in storage. Chemically, MBT is an acid. However, in diluted glycol mixtures in which the pH is buffered above 7.0, the presence of MBT greatly enhances the inhibitive properties of borax. Therefore, it is one of the constituents of Federal Specification 0-1-490a, inhibitor, Corrosion, Liquid Cooling System. This material is used in conjunction with 0-A-548, Type 1, antifreeze and is specified for Army use by TB-ORD-651.

Preliminary data in CCL Reports No. 86 and No. 100 showed that tin panels immersed in undiluted ethylene glycol containing borax and 0.25% MBT were unsatisfactory after 8 months storage. Test solution pH values were below 7.0. Tin panels in solutions with pH values of 10.5 and containing 3% water were satisfactory after 8 months storage. Data also showed that tin panels in solutions containing 0.5% NACAP and 3% water were unsatisfactory both at low pH values and at pH values up to 10.5.

The present study was initiated to determine if an antifreeze compound containing enough MBT to give satisfactory service performance could be stored in unlined tin plated containers for a two year period by increasing the packaged pH value.

IV. DISCUSSION AND CONCLUSIONS

The data clearly shows that antifreeze compounds containing mercaptobenzothiazole packaged in unlined tin plated containers at pH values below 10.3 caused corrosion in six months. Antifreeze compounds with pH values above 10.3 caused corrosion at the junction of the side and bottom seams in two years. Data in CCL Report No. 210 showed that antifreeze compounds having pH values above 8.5 are deleterious to both solder and aluminum radiator components during vehicle operation. If these metals are used, the most desirable pH values are in the range of from 7.5 to 8.2. Therefore, the problem of packaging antifreeze compounds becomes a function of the pH versus the type of container. The military have overcome this problem by specifying separate containers for the coolant and the inhibitor combination. This is not the most desirable solution from the logistics standpoint and causes some confusion in the field. It would be much better if a single package could be used.

V. RECOMMENDATIONS

It is recommended that a study of the storage of antifreeze in polyclefin containers be conducted. This will eliminate metal attack, will eliminate dual packaging of the coolant and inhibitor, simplify procurement and assure the use of the specified amount of inhibitor in the field. At the present time commercial antifreeze suppliers are in the process of switching to polyclefin containers.

VI. REFERENCES

1. Authority - AMC program directive AMCMS Code No. 5025.11.80300 dated 22 September 1967.

2. TB-ORD-651, Use of Antifreeze Solutions in Engine Cooling Systems, dated 10 April 1964.

3. Federal Specification O-A-548a, Antifreeze, Ethylene Glycol, Inhibited, Type I, dated 30 December 1958.

4. Federal Specification 0-1-490a, Inhibitor, Corrosion, Liquid Cooling System, dated 26 April 1965.

5. Federal Specification PPP-C-96, Cans, Metal, 28 Gage and Lighter, dated 29 March 1955.

6. CCL Report No. 86, Study of a Newly Developed Inhibitor for Ethylene Glycol in Storage, dated December 1959.

7. CCL Report No. 100, Storage of Ethylene Glycol With Various Inhibitors, dated March 1961.



APPENDIX A

NAMES NOT THE OWNER STREET

1

1

TABLE I

Composition of Test Solutions - Percent by Weight

		Se	ries A		
	1	2	3	4	
Ethylene Glycol Distilled Water	90.85 4.85	90.85 4.85	90.85 4.85	90.85 4.85	90.85 4.85
Borax Sodium Mercaptobenzothiazole (NACAP)	4.00	4.00	4.00 0.30		4.00 0.30
Added Sodium Hydroxide	0.84	0.85	0.86	0.87	0.90
	_		ries B		
	1	2	3	4	5
Ethylene Glycol	90.90	90.90	90.90	90.90	90.90
Distilled Water	4.90	4.90	4.90	4.90	4.90
Borax Sodium Mercaptobenzothiazole	4.00	4.00	4.00	4.00	4.00
(NACAP)	0.20	0.20	0.20	0.20	0.20
Added Sodium Hydroxide	0.84	0.85	0.86	0.87	0.90
		Se	ries C		
	<u> </u>	2	3	4	5
Ethylene Glycol	90.05	90.95	90.95	90.95	90.95
Distilled Water	4.95	4.95	4.95	4.95	4.95
Borax Sodium Marcontobernathianala	4.00	4.00	4.00	4.00	4.00
Sodium Mercaptobenzothiazole (NACAP)	0.10	0.10	0.10	0.10	0.10
Added Sodium Hydroxide	0.84	0.85	0.86	0.87	0.90

5

<u>م</u>.

. .

TABLE	ł	I
-------	---	---

125

Initial pH Values of Test Solutions

	Pkg pH	50% рН	<u>30% рн</u>
1 - A	8.30	9.50	9.8 5
2 - A	8.58	9.62	9.85
3 - A	8.80	9.82	10.05
4 - A	10.32	10.42	10.49
5 - A	10.80	11.02	11.08
1 - B	8.23	9.47	9,82
2 - B	8.38	9.62	9.93
3 - B	8.55	9.75	10.02
4 - B	8.88	9.93	10.20
5 - B	10.65	10.82	10.85
1 - C	8.12	9.42	9.72
2 - C	8.25	9.50	9.85
	8.55	9.75	10.05
. 3 ~ C 4 - C	9.30	10.13	10.32
5 - C	10.65	10.85	10.89

TABLE III

.

Inspection of Containers After Six Months Storage

	됩	Can Aupearance Filled	Can Appearance Empty
	8.50	Black over most surfaces	Surface dark and pitted
	8.65	Mod. sediment at seam joint	V. sl. pitting at seam joints
	8.88	Sl Mod. sediment at seam joint	V. sl. pitting at seam joint
	10.08	V. sl. sediment	V. sl. pitting at seam joint
	11.52	0.K.	0.K.
	8.30	Rusty sed. at bottom joint	V. sl. pitting at seem joint
	8.42	Rusty sed. at bottom joint	Sl. pitting at seam joint
	8.58	V. sl. sed. at bottom joint	V. sl. pitting at seam joint
	8.92	Sl. sed. at bottom joint	V. sl. pitting at seam joint
	11.12	V. sl. rusting at bottom joint	V. sl. pitting at seam joint
- 6	8.15	V. sl. sed. at bottom joint	V. sl. pitting at seam joint
	8.32	V. sl. sed. at bottom joint	V. sl. pitting at seam joint
	8.55	V. sl. sed. at bottom joint	V. sl. pitting at seam joint
	9,02	Mod. sed. at bottom joint	Mod. pitting at seam joint
	11.08	0.K.	0.K.

小学校園の学校大学校のなどを見たってきる。 こうちゅうしょうきょう

1

THE PROPERTY OF

1

7

.

•

TABLE IV

24

والمتعادة والمتعادة والمعادية والمعادية والمتعادة والمتعادة والمتعادية والمتعادة والمتعادة والمعادية والمعادية والمعاد

Inspection of Containers After One Year's Sturage

×. ę.

1 - A 8.58 2 - A 8.72 3 - A 8.99 4 - A 10.53 5 - A 11.49 3 - B 8.25 3 - B 8.25 3 - B 8.25 3 - B 8.25 1 - B 8.52 1 - C 8.30 1 - C 8.30 2 - C 8.30	Black over entire surface Heavy sed. at seam joint, vapor phase corrosion Mod Heavy sed., vapor phase corrosion Light sed. at seam joint, vapor phase corrosion Rusty sed. at seam joint, vapor phase corrosion Rusty sed. at seam joint, vapor phase corrosion Mod. sed. at seam joint, vapor light sed. at seam joint, vapor bhase corrosion Mod. sed. at seam joint, vapor light rusty sed. at seam joint Light rusty sed. at seam joint,	Surface dark & pitted, heavy corr. on seam S1. pitting at seam joint, 2 heavy spots S1. pitting at seam joint, 2 heavy spots S1. pitting at seam joint V. s1. pitting on side seam near bottom S1. pitting at seam joint Pitted over 1/2 bottom seam, spots on seam side S1. pitting at seam joint, scattered spots S1. pitting at seam joint & all over side seam V. s1. pitting at seam joint & sots on side seam V. s1. pitting at seam joint, spots on side seam S1. pitting at seam joint, spots on side seam
	vapor phase corrosion Light rusty sed. at seam joint Heavy rusty sed.	<pre>side seam Sl. pitting at seam joint, spots on side seam Pitting over 1/2 of bottom seam & side</pre>
-	0.K.	seam Sl. pitting at seam joint. spots on

TABLE V

Inspection of Containers After Two Year's Storage

		Hd	Can Appearance Filled	
	1-A	8.35	Mod. sed. mod-heavy pitting on side and bottom ioint	Modhe at be
	2-A	8.68	Mod. sed. at joint, pitting on side seam and along bottom seam with scattered shots	Scatte
	3-A	8.78	Mod. sed. at joint, corrosion all along side seam, vapor phase corrosion	Scatte: ting hotro
	4 4 1 1 1 1	10.50	V. sl. sed. pitting on side seam Solo clear creat corrector s citting on	sl. pit
		<u>.</u>	sour crear, spor corrosion & pitting on side seam, vapor phase corrosion	pitt
	89	8.22	Mod. sed., sl. pitting on side seam	sl. pli
9	2-B	8.37	Mod. sed., simod. pitting on side &	Slmod
	3-B	8.52	bottom seam, vapor phase corrosion Mod. sed., sl. pitting on side seam	ting Sl. pii
	4-B	8.93	Mod. sed., slmod. pitting on side	sl. pit
	5-8	11.10	seam, vapor pnase corrosion Soln. clear, sl. pitting on side seam and bottom joint	joint V.sl. joint
	1-0	8.12	Mod. sed., mod. pitting on side seam	S1mod
	2-C	8.28	Sl. sed., sl. pitting on side seam	Sl. pit
	3-0	8.42	Sl. sed., sl. pitting on side seam, venor chase corrosion	sl. pit
	4-C	00.6		sl. pii
	5-C	11.18	Soln. clean, v. sl. sed. at bottom joint	sl. pi t joint

eavy pitting on side, sl. pitting red spot corrosion, sl.-mod. pitat bottom seam joint ottom joint

Can Appearance Empty

com joint tting on side seam and bottom joint red sput corrosion, sl.-mod. piton side seam, sl. pitting at

1

eavy pitting on side seam, v. sl. ing at bottom joint

tting on side seam & bottom joint d. pitting on side seam, sl. pit-

tting on side seam, sl.-mod. pitat bottom joint

tting on side seam and bottom at bottom joint

pitting on side and bottom seam

d. pitting on side seam and om joint

tting on side seam and at bottom

tting on side seam and at bottom

tting on side seam and at bottom tting on side seam, mod. pitting

joint



ميرو



And the second state of the second se

	CONTROL DAT		
(Security classification of title, body of abstract and in			the overall report in classified)
1 ORIGINATING ACTIVITY (Corporate author)			RT SECURITY C LASSIFICATION
U. S. Army Coating & Chemical La Aberdeen Proving Ground, Marylan		25 GROU	nclassified
Aberdeen Froving 0: bund, haryran			
S REPORT TITLE			
STORAGE OF ETHYLENE GLYCOL ANTIF	REEZE IN UNLI	NED TIN CON	TAINERS
	·····		
4. DESCRIPTIVE NOTES (Type of report and inclusive dates Final Report			
S. AUTHOR(5) (Last name, first name, initial)	*** *** ******************************		
CONLEY, JAMES H.			
S REPORT DATE	7. TOTAL NO	. OF PAGES	76. NO. OF REFS
JULY 1968 Re. CONTRACT OF GRANT NO.			8
AMCMS Code No. 5025.11.80300		OR'S REPORT NUN	18 Z M(J)
5. PROJECT NO.	CCL #	()	
1G024401A109		BAAT MAIPL 14	
-	this report)	- 07 1 NO(3) (AN)	other numbers that may be assign
d. 10. AVAILANILITY/LIMITATION NOTICES			·····
Qualified Requestors may obtain	conies of th	is report fr	om Defense
Documentation Center. Distribut			
11. SUPPLEMENTARY NOTES		IG MILITARY ACT	
		Army Materie	1 Comman d
	Washin	gton, D. C.	
13 ABSTRACT			
>-> The object of this study wa			
the package stability of mercapt glycol antifreeze compounds. Th			
in unlined tin plated containers			
	na anna an da d	utah ali ualu	as balay 10.3
Desciles share that and france			
Results show that antifree caused corrosion in less than si			
caused corrosion in less than si compounds having pH values above			
caused corrosion in less than si compounds having pH values above and were generally unsatisfactor	ry after two	years storag	of the containers.
caused corrosion in less than si compounds having pH values above	ry after two	years storag side seams	of the containers.
caused corrosion in less than si compounds having pH values above and were generally unsatisfactor	ry after two	years storag side seams	of the containers.
caused corrosion in less than si compounds having pH values above and were generally unsatisfactor	ry after two	years storag side seams	of the containers.
caused corrosion in less than si compounds having pH values above and were generally unsatisfactor	ry after two	years storag side seams	of the containers.
caused corrosion in less than si compounds having pH values above and were generally unsatisfactor	ry after two	years storag side seams	of the containers.
caused corrosion in less than si compounds having pH values above and were generally unsatisfactor	ry after two	years storag side seams	of the containers.
caused corrosion in less than si compounds having pH values above and were generally unsatisfactor	ry after two	years storag side seams	of the containers.
caused corrosion in less than s compounds having pH values above and were generally unsatisfactor attack was at the junction of th	ry after two	years storag side seams	of the containers.
caused corrosion in less than si compounds having pH values above and were generally unsatisfactor	ry after two	side seams Uncl	assified assification

12、これにはなるのであるのないというです。 いちまいちょう いい

•

(r • 1

		ifie	
Securi	iv C	lassif	ication

KEY WORDS		Lik	IK A	LIN	KB		NK C
NET WURUS		ROLL	. w1	ROLL	WT	14701 F	<i>"</i> <u>-</u>
							1
Antifreeze							1
Tin containers				ł			
Mercaptobenzolthiazole		ł					
Storage							
							l
		1					
		1					
							İ
			l	1			
							1
			ļ				1
INST	NUCTIONS	5	<u>I</u>	L	d	.	
ORIGINATING ACTIVITY: Enter the name and address	10. AVA		r v /1.1 M 17	TATION	NOTICES	Enter	nv lim-
f the contractor, subcontractor, grantee, Department of De-	itations	on further	dissemi	nation of	the report	i, other t	han those
ense activity or other organization (corporate author) issuing the report.	imposed such as:	by securi	ty classi	fication,	using sta	ndard sta	tements
a. REPORT SECINATY CLASSIFICATION: Enter the over-	(1)	"Qualifie	ed reques	ters may	obtain co	pies of t	his
Il security classification of the report. Indicate whether Restricted Data" is included. Marking is to be in accord-		report fro	m DDC.'	,			
nce with appropriate security regulations.	(2)	"Foreign report by	DDC is	ement an not autho:	d dissemi rized."	nation of	f thi s
b. GROUP: Automatic downgrading is specified in DoD Di- ective 5200.10 and Armed Forces Industrial Manual. Enter	(3)	"U. S. G	overnmen	t agencie	s may ob	tein copi	es of
he group number. Also, when applicable, show that optional		this repo	rt directl	y from DI	X. Othe	r qualifie	d DDC
narkings have been used for Group 3 and Group 4 as author- zed.		USETS SIL	ut reque	er rinou g e	•		
. REPORT TITLE: Enter the complete report title in all	(4)	"U. S. m	ilitery as	encies m	av obtain	copies o	of this
apital letters. Titles in all cases should be unclassified. I a meaningful title cannot be selected without classifica-		report di	reculy fro	m DDC.	Other qua	lified us	iers
on, show title classification in all capitals in parenthesis		shall req	uest thro	ugn			."
mmediately following the title.	(5)	"All die	ribution	of this re	port is co	ntrolled	Qual-
. DESCRIPTIVE NOTES: If appropriate, enter the type of eport, e.g., interim, progress, summary, annual, or final.					est throu		•
live the inclusive dates when a specific reporting period is overed.	1						
. AUTHOR(S): Enter the name(s) of author(s) as shown on	If th	e report i 1, Departs	as been	furnished ommerce.	to the Of for sale	ífice of T to the pu	fechnical blic, ind
r in the report. Enter last name, first name, middle initial. f military, show rank and branch of service. The name of	cate this	s fact and	l enter th	e price, i	f known.		
he principal author is an absolute minimum requirement.		PPLEME	NTARY N	OTES: U	Jse for ad	lditional	explana-
REPORT DATE: Enter the date of the report as day,	tory not	ONSORIN	G MILIT	ARY ACT	1V/TY: 1	Enter the	name of
nonth, year; or month, year. If more than one date appears in the report, use date of publication.	the dens	artmental.	project o	ffice or L	aboratory	sponsori	ing (pay-
a. TOTAL NUMBER OF PAGES: The total page count		the resea TRACT:					
hould follow normal pagination procedures, i.e., enter the unber of pages containing information.	enmonen	of the d	ocument i	ndicative	e of the re	port, eve	en though
b. NUMBER OF REFERENCES: Enter the total number of	port. If	addition	n elsewh I space i	ere in the is require	d, a cont	inuation	sheet
eferences cited in the report.	shall be	e attached					
a. CONTRACT OR GRANT NUMBER: If appropriate, enter he applicable number of the contract or grant under which	DON'S DE	highly d unclassi	ified. Ea	ch paragr	aph of th	e al strac	ct shall
he report was written.	I and with	h an indic	ation of	the milita	rv securi	(V CIRSSI	rication
bb, dc, & 8d. PROJECT NUMBER: Enter the appropriate nilitary department identification, such as project number,	(C), or ((U).					
subproject number, system numbers, task number, etc.	The	re is no l	imitation	on the le	ngth of th	e abstra	ct. How
a. ORIGINATOR'S REPORT NUMBER(S): Enter the offi-		e sugges					aful term
nal report number by which the document will be identified and controlled by the originating activity. This number must	index entries for cataloging the report. Key words must be					je usea a	
e unique to this report.		d en that	NO SPCUT	itv classi	Incation I	s require	ea. Taeu.
bb. OTHER REPORT NUMBER(S): If the report has been assigned any other report numbers (either by the originator	Ciana a	uch as ecoject code	minment	model des	signation.	, trade अ	ime, mili
or by the sponsor), also enter this number(s).	Lev wo	nde hut wi	ill be foll	owed by	an indica	tion of te	SCUUIC ST
	context	. The as	signment	of links.	, rules, a	nd weigh	15 15
	1 option						
			Ur	ic lass i	fied		

.