

UNCLASSIFIED

AD NUMBER
ADB262379
NEW LIMITATION CHANGE
TO Approved for public release, distribution unlimited
FROM Distribution authorized to U.S. Gov't. agencies only; Test and Evaluation; Nov 86. Other requests shall be referred to Commander, Naval Air Test Center, Patuxent River, MD 20670-5304.
AUTHORITY
USAMRMC ltr, 15 May 2003

THIS PAGE IS UNCLASSIFIED

REPORT NO: SA-125R-86

COPY NO. 12

Quick Response REPORT

RESULTS OF WEIGHTED DROGUE TRAY MODIFIED LUU-2B/B
FLARE SEPARATION TESTS FROM SUU-25F/A/FA-18 AIRCRAFT

by

Mr. Bruce Julian

7 November 1986

SECOND INTERIM REPORT

Distribution limited to U.S. Government agencies only; Test and Evaluation; November 1986. Other requests for this document must be referred to Commander, Naval Air Test Center, Patuxent River, Maryland 20670-5304.

Prepared for:

NAVAL AIR SYSTEMS COMMAND
AIRTASK A540-5406/159-5/5201000002
WORK UNIT A54062D/01

20001221 071



**NAVAL AIR TEST CENTER
PATUXENT RIVER, MARYLAND**

DEPARTMENT OF THE NAVY
NAVAL AIR TEST CENTER
PATUXENT RIVER, MARYLAND 20670-5304

A540-5406/159-5/5201000002
A54062D/01
SA-125R-86
7 November 1986

From: Commander, Naval Air Test Center, Patuxent River, Maryland 20670-5304
To: Commander, Naval Air Systems Command (AIR-540), Naval Air Systems Command Headquarters, Washington, D.C. 20361

Subj: NAVAIRTESTCEN QUICK RESPONSE REPORT SA-125R-86, RESULTS OF WEIGHTED DROGUE TRAY MODIFIED LUU-2B/B FLARE SEPARATION TESTS FROM SUU-25F/A/FA-18 AIRCRAFT, SECOND INTERIM REPORT, AIRTASK A540-5406/159-5/5201000002, WORK UNIT A54062D/01

Ref: (a) Meeting between Mr. B. Julian (NAVAIRTESTCEN)/Mr. K. Sanders (NAVAIRSYSCOM) of 5 Sep 1986

1. As a result of the meeting conducted at NAVAIRSYSCOM on 5 September 1986, flight testing was initiated using modified LUU-2B/B flares with weighted drogue trays loaded in SUU-25F/A's carried on board F/A-18 aircraft. Flight testing began on 24 September 1986 with two SUU-25F/A dispensers loaded on a vertical ejector rack (VER) on station 8 of an F/A-18 aircraft. Only the outboard dispenser was loaded and the inboard was carried in order to create the desired airflow pattern. The loaded dispenser contained six flares: two flares in tubes 1 and 2 and one forward flare in tubes 3 and 4. In tubes 1 and 2, only the aft flares were armed with ejection cartridges. The dispenser was loaded in this configuration in order to evaluate the separation characteristics of both forward and aft flares without having to fire a forward flare with the plastic spacer tee. The spacer tee posed a major concern for fear that it might separate from the end cap of the forward flare and impact the stabilator.
2. The flight was conducted at 400 KCAS, 5,000 ft, straight and level 1.0 g. All four flares separated satisfactorily even though two flares had their end caps come off before clearing the stabilator. One of these end caps approached to within approximately 8 in. of the stabilator. The flares all appeared to be at least 2 ft beneath and 6 in. to 1 ft outboard of the stabilator. The third flare showed a slight pitching up motion before clearing the stabilator, but its translation was no more than 5 to 10 deg.
3. After reviewing the on board and ground station films, it was decided to fly a second flight at 450 KCAS in the same configuration and similar flight conditions. This flight was given the additional coverage by a photochase aircraft and the on board real-time video performance was improved.
4. The 450 KCAS flight was conducted on 25 September 1986. On the first live run, real-time video coverage showed the flare beginning to pitch up shortly after release. The flare translated approximately 60 to 70 deg as it passed the stabilator. This unsatisfactory separation, in close proximity to the stabilator, led to the immediate termination of the test. The aircraft was instructed to return to base for inspection. Postflight inspection revealed that no store-to-aircraft collision had occurred.
5. Although the on board film revealed that the flare was outboard of the stabilator as it rotated, the separation trend was nonetheless unacceptable and this series of tests was terminated. The ejection velocity of the flare was determined from film analysis to be approximately 30 ft/sec. This ejection velocity is well within the range of that experienced by aft flares in other LUU-2B/B tests.

6. In response to the failure of the weighted drogue tray system, an effort was made to conduct a ground test using a SUU-25F/A mounted on centerline station 5 of an F/A-18A aircraft. Previous fit tests had shown the store to be compatible on this station. However, in our effort, the full scale development aircraft's fuel connection in the centerline parent station interfered with the electrical connector on the dispenser. In addition, the swaybraces on the rack would not make contact with the dispenser even when adjusted full down. Furthermore, with the pod suspended in the rack, the clearance of a perfectly stable level flare would only clear the belly of the aircraft by approximately 2 to 4 in. This places considerable doubt on the ability of a centerline pod mounting to provide flare capability.

7. Analysis of the unexpected behavior in a modified flare that had previously performed satisfactorily up to 550 KCAS on F-4J aircraft has led to the following hypothesis: unlike the F-4J and the A-4M testbeds previously used in the tests of the modified LUU-2B/B in conjunction with the SUU-25F/A, the F/A-18 aircraft's parent stations have a 3 deg nosedown attitude. Review of on board film indicates that this nosedown attitude may reach 5 to 7 deg during flight when the SUU-25F/A's are mounted on VER's. The flight path of the ejected flares is upward at this offset angle which immediately reduces the potential clearance between the flare and the stabilator. In addition, as the flight path of the flare is angled upward, the aft end of the flare enters the relative wind air flow before the forward end clears the turbulent stagnation area immediately aft of the dispenser. The application of this high pressure air flow to the aft end and a low pressure flow to the forward end causes a moment force which initiates the rotation of the flare. This effect is amplified as the flare travels further upward in its angled trajectory.

8. NAVAIRTESTCEN proposes a two fold plan of attack to develop an F/A-18/SUU-25F/A flare capability. First, a hardback adapter needs to be developed that would attach to the SUU-25F/A and give the dispenser a lower displacement and remove the current dispenser nosedown attitude. This adapter would be jettisonable with the dispenser and, thus, have no requirement for electrical interface with aircraft software. Second, the Naval Weapons Support Center, Crane, Indiana, needs to develop another concept to stabilize the flare other than the weighted drogue tray. The engineering requirements to develop a drogue tray system that exhibits repeatable tray separation are immense; however, the danger to aircraft and aircrews should this system fail has already been demonstrated by the history of drogue tray incidents.

9. Any questions or information in this matter should be directed to our point of contact, Mr. C. B. Julian (SA81F), AUTOVON 356-4171, or commercial (301) 863-4171.


J. Q. HOEG
By direction

DISTRIBUTION:

NAVAIRSYSCOM (AIR-540)	(2)
NAVAIRSYSCOM (AIR-530)	(5)
NWSC Crane, IN (CODE 5061B1)	(4)



REPLY TO
ATTENTION OF

DEPARTMENT OF THE ARMY
US ARMY MEDICAL RESEARCH AND MATERIEL COMMAND
504 SCOTT STREET
FORT DETRICK, MD 21702-5012

MCMR-RMI-S (70-1y)

15 May 03

MEMORANDUM FOR Administrator, Defense Technical Information
Center (DTIC-OCA), 8725 John J. Kingman Road, Fort Belvoir,
VA 22060-6218


SUBJECT: Request Change in Distribution Statement

1. The U.S. Army Medical Research and Materiel Command has reexamined the need for the limitation assigned to technical reports written for this Command. Request the limited distribution statement for the enclosed accession numbers be changed to "Approved for public release; distribution unlimited." These reports should be released to the National Technical Information Service.

2. Point of contact for this request is Ms. Kristin Morrow at DSN 343-7327 or by e-mail at Kristin.Morrow@det.amedd.army.mil.

FOR THE COMMANDER:

Encl


PHYLLIS M. RINEHART
Deputy Chief of Staff for
Information Management

ADB266022	ADB265793
ADB260153	ADB281613
ADB272842	ADB284934
ADB283918	ADB263442
ADB282576	ADB284977
ADB282300	ADB263437
ADB285053	ADB265310
ADB262444	ADB281573
ADB282296	ADB250216
ADB258969	ADB258699
ADB269117	ADB274387
ADB283887	ADB285530
ADB263560	
ADB262487	
ADB277417	
ADB285857	
ADB270847	
ADB283780	
ADB262079	
ADB279651	
ADB253401	
ADB264625	
ADB279639	
ADB263763	
ADB283958	
ADB262379	
ADB283894	
ADB283063	
ADB261795	
ADB263454	
ADB281633	
ADB283877	
ADB284034	
ADB283924	
ADB284320	
ADB284135	
ADB259954	
ADB258194	
ADB266157	
ADB279641	
ADB244802	
ADB257340	
ADB244688	
ADB283789	
ADB258856	
ADB270749	
ADB258933	