## UNCLASSIFIED

## AD NUMBER

### AD829986

## LIMITATION CHANGES

## TO:

Approved for public release; distribution is unlimited.

## FROM:

Distribution: Further dissemination only as directed by Army Materiel Command, Rock Iskand, IL 61802, 26 MAR 1968, or higher DoD authority.

# AUTHORITY

TECOM ltr 26 May 1971

THIS PAGE IS UNCLASSIFIED

FOR INFORMATION ONLY, ACTION BY HIGHER AUTRONITY FENDING



:0

86

0

2

00

AD-RDT&E PROJECT NO USATECOM PROJECT NO 1-4-2528-33

STATEMENT #5 VURLED TO THE

Mar. any Moterial M. S.H. insunch, M. 61202 Cont

SERVICE TEST

OF

PRODUCT IMPROVED COMPONENTS FOR SHERIDAN WEAPON

SYSTEM (CLOSED BREECH SCAVENGER SYSTEM)

FIRST PARTIAL REPORT

BY

CAPTAIN VADEN K. WATSON

AND

SP4 TRUMAN E. SICKS SCIENTIFIC AND ENGINEERING

26 MARCH 1968

**US ARMY** ARMOR & ENGINEER BOARD FORT KNOX, KENTUCKY



### Distribution Statement

This document may be further distributed by any holder <u>only</u> with specific prior approval of Project Manager, SHERIDAN.

### Disposition Instructions

Destroy this report when no longer needed. Do not return it to the originator.

#### Disclaimer

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents. The use of trade names in this report does not constitute an official endoresement or approval of the use of such commercial hardware or software. This report may not be cited for purposes of advertisement.

÷



DEPARTMENT OF THE ARMY HEADQUARTERS, U.S. ARMY TEST AND EVALUATION COMMAND ABERDEEN PROVING GROUND, MARYLAND 21005

AMSTE-BB-S

3 APR 1968

SUBJECT: First Partial Report, Service Test of Product Improved Components for Sheridan Weapon System (Closed Breech Scavenger), USATECOM Project No. 1-4-2528-33

Project Manager, SHERIDAN U.S Army Materiel Command ATTN: AMCPM-SH Rock Island Arsenal Rock Island, Illinois 61202

1. The subject report covers a limited, expedited test which was conducted primarily for the purpose of evaluating the air compressor.

2. The report is approved and forwarded for information. Final analysis on suitability of the closed breech scavenger system will be made upon completion of the service, engineering and tropic tests.

FOR THE COMMANDER:

1 Incl as (2 cys)

WHEELER, lonel, GS Cċ r, Arm Mat Test Dir Dł

Copies furnished: CG, USAMC, ATTN: AMCPM-SH-W, 2 cys PM, SHERIDAN, ATTN: AMCPM-SH-D, 3 cys PM, M60 Tanks, ATTN: AMCPM-N60, 1 cy CG, USAMC, ATTN: AMCRD, 1 cy PM, SHILLELAGH, ATTN: AMCPM-SM, 2 cys CG, USCONARC, ATTN: ATIT-RD-MD, 4 cys CG, USACDC LnO, USATECOM, 10 cys DA, ACSFOR, ATTN: LTC Milia, 3 cys DEPARTMENT OF THE ARMY CPT Watson/726-3300/4-4449 UNITED STATES ARMY ARMOR AND ENGINEER BOARD Fort Knox, Kentucky 40121

#### 2 6 MAR 1968

#### STEBB-AR-C

SUBJECT: First Partial Report of Service Test of Product Improved Components for Sheridan Weapon System (Closed Breech Scavenger System), USATECOM Project No 1-4-2528-33

TO: Commanding General US Army Test and Evaluation Command ATTN: AMSTE-BB-S Aberdeen Proving Ground, Maryland 21005

#### 1. REFERENCES

a. Msg, TEC 1276, AMSTE-BB-S, HQ USATECOM, 27 Feb 68, subject: Prefactory Evaluation of Air Compressor for M551 Scavenger System, USATECOM Project No 1-4-2528-33.

b. Ltr, AMSTE-BB-S, HQ USATECOM, 5 Mar 68, subject: Test Directive, Service Test of Product Improved Components for Sheridan Weapon System, USATECOM Project No. 1-4-2528-33, w 4 incl.

2. RESPONSIBILITIES. The Armor Division, US Army Armor and Engineer Board, Fort Knox, Kentucky, was responsible for preparing the test outline, test execution, and preparing the test report.

3. BACKGROUND. The Sheridan Weapon System has had continuing problems with the removal of residual propellant gas and residue resulting from the combustible cartridge case. Inadequate removal of the propellant gas results in high carbon monoxide concentration in the turret, an explosive gaseous mixture which upon ignition becomes a flareback, and smoke in the crew compartment. Residue from combustible cartridge case ammunition presents a safety hazard which may result in the ignition of the case of a subsequently loaded round. To alleviate these problems, an open breech  $CO_2$  bore scavenger was developed. This type scavenger reduced the magnitude of the toxic gas concentration and flarebacks from conventional ammunition firing, but did not function for missile firing, nor at cold temperatures, and did not remove adequately hazardous cartridge case residue. Subsequently, the Sheridan Project Manager has developed a scavenging system that introduces compressed air into the weapon prior to block opening. Engineer design tests of this Closed Breech Scavenger have been conducted and the engineering test is currently in progress at Aberdeen Proving Ground.

4. DESCRIPTION OF MATERIEL

a. The test item is a 4-stage air compressor, 4 cubic feet/ minute, 3 HP electric motor with a cooling fan, and air drier. The compressed air reservoir is a 1,430-cubic inch cylinder at 3,200 PSIG. The low pressure outled is 780 PSIG (STATIC) and 630 PSIG when purging. A solenoid value opens for 1.7 seconds after firing, allowing an average of 12 cubic feet of compressed air into the tube to scavenge the tube and breech or aft cap of the missile.

b. The compressor automatically starts when the cylinder pressure drops below 2,800 PSIG and stops when it builds up to 3,200 PSIG. The scavenger will operate in the missile mode but the compressor is prevented from operating by design because the 150 ampere electrical drain of the compressor could recycle the missile.

5. TEST OBJECTIVES

a. To assess the capability of the compressor to withstand the vehicle environment.

b. To determine if the compressor, the remainder of the scavenger system, and the restowage of turret is compatible with crew functions.

c. To determine time required to recharge the compressed air bottle, and to assess the bottle capacity and compressor recharge rate with regard to its adequacy for firing missions.

d. To describe any residue not cleaned by the scavenger.

6. SUMMARY OF RESULTS. Testing of the Closed Breech Scavenger System was conducted by the Combat Vehicle Branch of the Armor Division of the US Army Armor and Engineer Board from 7 March until 16 March at Fort Knox, Kentucky, in accordance with the test directive (ref la and b). Results are based on operation of the compressor for 50 hours and the firing of 58 rounds. The system was subjected to vehicle operation over highway, secondary roads, and cross country for a total of 496 miles.

2

STEBB-AR-C SUBJECT: First Partial Report of Service Test of Product Improved Components for Sheridan Weapon System (Closed Breech Scavenger System), USATECOM Project No 1-4-2528-33

a. <u>Preoperational Inspection and Physical Characteristics</u>. The test item was subjected to a preoperational inspection and all electrical modifications examined. The compressor is approximately 22.5 inches long, 10 inches wide, 14 inches high, and weighs 50 pounds. (See incl 1.) The air reservoir cylinder is 29 inches high and 12 inches in diameter, and weighs 62 pounds.

#### b. Installation and Compatibility with Related Equiptent.

(1) A modified shallow key gun/launcher tube was installed. The modified gun tube, without a bore evacuator, (incl 1) had a 1/4-inch hole drilled at the 7 o'clock position slanted to the rear of the breech. Modifications inside the turret required relocation of one ammunition rack, machine gun spare parts kit, asbestos mittens, fire extinguisher and M37 loader's periscope within the turret and relocation of one box of 7.62mm ammunition to the outside of the turret, and a reduction in the size of the oddment box under the loader's seat. (See incl 2 and 3 for compressor installed in vehicle and relocation of ammunition racks.) These modifications and the installation of the scavenger system required 88 man-hours. Removal of the standard gun-launcher tube and installation of the modified tube required 24 man-hours.

(2) The test system was found to be compatible with the vehicle and crew with the following exceptions.

(a) Manual purge valve. Located too far forward for convenient operation. (See para 2.1, incl 8, and photograph at incl 4.)

(b) Main compressor switch. Is so located that it can be turned on and off by the loader accidentally bumping the switch with his shoulder. (See para 2.2, incl 8, and photograph at incl 5.)

(c) Pressure gauge size and location. Both high and low pressure gauges are difficult to read because of the small scale and the high pressure gauge does not face the loader when he is in the loading position. (See para 2.3, incl 8.) Also, the high pressure gauge is red-lined at 600 PSIG when the recommended minimum pressure level is 1,000 PSIG. (3) The test system had no effect on the communication capabilities of the vehicle with or without the compressor running.

#### c. Functioning Characteristics.

٦

(1) Time recovery and pressure drop tests were conducted on the test system. (See incl 9 and 10 for pressure drops and recovertimes.) At the rate of fire of one round per minute, the system has a self-recovery characteristic. Due to the change in temperature, the system tends to return to ambient following the rapid drop induced by the pressure loss of each purge. This average recovery of 100 to 200 PSIG requires approximately 40 to 50 seconds. At the higher rates of fire, this recovery pressure is lost. This loss plus the shorter operating time of the compressor results in reaching the minimum purging pressure after fewer rounds. Firing at one round per minute, with the compressor operating, 10 or possibly 11 rounds can be fired before minimal purging pressure is reached. At this time, 3- to 4minute buildup is necessary for each additional round. Ten rounds can be fired from the bottle without the compressor operating although the purging pressure of the last round will be marginal.

(2) The average time to recharge the bottle to full capacity from 0 PSIG is 45 minutes, from 1,000 PSIG is 30.5 minutes and from 2,000 PSIG is 12.2 minutes. The average time required to replenish the turret ammunition racks from hull stowage is 3.5 minutes. This time included traversing the turret, posting the loader and gunner outside the vehicle for security, transferring 10 rounds and locking them in racks, and then traversing back to a ready position. This reloading time will allow a buildup in pressure for one additional round.

(3) Tests on battery rundown times were conducted by operating the compressor, with master switch on, communication equipment on, and the vehicle engine off. After an average of 22 minutes, the compressor would begin to operate erratically and the instrument lights dim. At this time if the compressor was turned off the engine could still be started using the vehicle batteries.

(4) A total of 58 live rounds was fired with the test system in operation. Two rounds were not fired because of one misfire and one round being damaged when the breech closed. This damage was the result of improper loading or possibly a long round. No problems were encountered when 10 rounds were fired with a full bottle and the compressor off.

(a) Throughout the test, no burning residue was experienced. However, nonburning residue to some extent was evident in the breech cavity after each round was fired. After two or three STEBB-AR-C SUBJECT: First Partial Report of Service Test of Product Improved Ccorponents for Sheridan Weapon System (Closed Breech Scavenger System), USATECOM Project No 1-4-2528-33

rounds had been fired, the residue accumulation was such that it could be scraped out of the breech cavity. (See incl 6.) Additional rounds did not increase this accumulation or did it ever completely burn itself off. This residue accumulation was found primarily at the base of the cylinder wall of the breech cavity in a 1/2-inch strip.

(b) A second type of residue was sometimes evident. This appeared as a thin film of molten residue sprayed around the walls of the gun chamber. Once during the test, when one round was fired, this molten residue was sprayed onto the gun tubes recess between 7 and 10 o'clock approximately 5 inches forward. (See incl 6.)

(c) On only one other occasion was there any residue observed in the gun tube itself and that was a small flake at 3 o'clock, 14 inches forward.

(5) An inspection of the system midway through the test revealed an appreciable amount of water in the bottle, hoses, and telescoping adapter. (See para 1.3, incl 8.) Also bubbles were found in one of the air hoses. (See para 1.2, incl 8.) The system was then dried out and the hose replaced. Two days later when the vehicle began operation at 0530 hours, the system was actuated 10 times to accumulate compressor operating time. After the bottle had been recharged, it was actuated once and approximately half the bottle was released before it automatically closed. Another attempt resulted in the expenditure of the rest of the bottle. The Fort Knox weather station gave the temperatures for that morning as: 26°F at 0530, 30°F at 0930, and 33°F at 1030. The system was recharged and 7 rounds fired at the range with no difficulties encountered. At 1000 hours, immediately after firing, the system was purged 10 times and it again emptied the bottle to 0 PSIG and air continued to escape from the tube. At this time, all of the fittings of the system had a heavy coating of frost and the compressor could only be stopped by turning off the master switch. Erratic action of the solenoid valve under these conditions suggests that moisture in the line may have frozen and thus impaired normal functioning.

d. Reliability

(1) A total of 496 miles of facility vehicle operation was accumulated on the test system. Most of the mileage was crosscountry operation (350 miles). The remaining mileage was 93 miles on secondary roads and 53 miles on highway. (2) During cross-country operation, a series of combat situations involving firing of the gun-launcher were simulated for simulated firing data. (See incl 11.)

(3) Three of the exercises were run using a total of 14 rounds of live ammunition. These exercises were conducted to accumulate realistic hours on the compressor.

(4) Five rounds of live ammunition were carried on the vehicle throughout all cross-country operation. These were the last rounds to be fired and no problems were encountered.

(5) After 40.1 hours of operation, the compressor continued to operate after the main compressor switch had been turned off. Investigation by the compressor manufacturer's technical representative revealed that a set of contact points in a relay had fuzed together making a closed circuit. (See para 1.1, incl 8, and photograph at incl 7.) Since this relay was a part of the compressor it was considered a compressor failure. The relay was replaced and the test continued. A total of 50 hours was accumulated on the compressor during the test.

#### e. Human Factors Engineering

(1) Noise level readings were taken inside the turret with and without the compressor operating. This noise level evaluation was conducted by the Experimental Psychology Division, US Army Medical Research Laboratory at Fort Knox, Kentucky. (See incl 12.) Their results showed that a danger to personnel would only exist during prolonged continuous operation with both the vehicle and compressor running.

(2) The heat generated by the compressor is rated by the manufacturer as 230 BTU per minute Heat dissipation presented no problems under the conditions of this testing although it may become critical during hot-weather operations.

(3) During the test, two rounds were fired without the benefit of any scavenging operation. After this firing, the crew reported that there was a high concentration of fumes inside the turret. The absence of the bore evacuator understandably would cause a higher concentration of gaseous fumes than is normally experienced in a vehicle which incorporates a bore evacuator.

7. CONCLUSIONS. The US Army Armor and Engineer Board concludes that duration of the test was insufficient to determine suitability. STEBB-AR-C

SUBJECT: First Partial Report of Service Test of Product Improved Components for Sheridan Weapon System (Closed Breech Scavenger System), USATECOM Project No 1-4-2528-33

8. RECOMMENDATIONS. The US Army Armor and Engineer Board recommends that additional testing be conducted on a system modified to correct all deficiencies and as many shortcomings as feasible noted at inclosure 8.

MARSHALL WALLACH Colonel, Armor President

13 Incl

- Photographs
  Deficiencies and
- Shortcomings
- 9-10. Pressure Drops and
- Recovery Time Data 11. Simulated Firing Dat
- Simulated Firing Data
  US Army Medical Research
- Laboratory Report
- 13. Distribution List



1



US ARMY ARMOR AND ENGINEER BOARD USATECOM PROJ NO 1-4-2528-33 FORT KNOX, KY PHOTO NO 68-141 AND 68-176

> CLOSED BREECH SCAVENGER SYSTEM FOR SHERIDAN WEAPONS SYSTEM

**UPPER:** COMPRESSOR

LOWER: LEFT GUN TUBE WITH BORE EVACUATOR (M81)

RIGHT GUN TUBE WITHOUT BORE EVACUATOR THAT WAS INSTALLED FOR CBS TEST (M81E1)



US ARMY ARMOR AND ENGINEER BOARD USATECOM PROJ NO 1-4-2528-33 FORT KNOX, KY PHOTO NO 68-177 AND 68-184

> CLOSED BREECH SCAVENGER SYSTEM FOR SHERIDAN WEAPONS SYSTEM

UPPER: COMPRESSOR INSTALLED IN VEHICLE WITH WIRE GUARD.

LOWER: VIEW FROM DRIVER'S COMPARTMENT OF COMPRESSOR AND TWO AMMUNITION RACKS.



US ARMY ARMOR AND ENGINEER BOARD USATECOM PROJ NO 1-4-2528-33 FORT KNOX, KY PHOTO NO 68-186

> CLOSED BREECH SCAVENGER SYSTEM FOR SHERIDAN WEAPONS SYSTEM

VIEW FROM LOADER'S HATCH SHOWING COMPRESSOR INSTALLED UNDER ODDMENT BOX. THE LOADER'S SEAT AND TRAY COVER ARE IN UP POSITION AND COMPRESSOR AIR FILTER ACCESS PLATE REMOVED. RIGHT SIDE (3 RACKS): THE COMPRESSOR INTAKE SIDE. LEFT SIDE (2 RACKS): THE COMPRESSOR EXHAUST SIDE.

INCL 3



US ARMY ARMOR AND ENGINEER BOARD USATECOM PROJ NO 1-4-2528-33 FORT KNOX, KY PHOTO NO 68-172 AND 68-170 CLOSED BREECH SCAVENGER SYSTEM FOR SHERIDAN WEAPONS SYSTEM (COAXIAL MACHINE GUN NOT MOUNTED) UPPER: SYSTEM INSTALLED WITH LOW AND HIGH PRESSURE GAUGES, QUICK DISCONNECT CHAIN, AND TELESCOPING ADAPTOR INTO GUN TUBE. LOWER: ARROW INDICATES MANUAL PURGE VALVE HANDLE.



US ARMY ARMOR AND ENGINEER BOARD USATECOM PROJ NO 1-4-2528-33 FORT KNOX, KY PHOTO NO 68-171 AND 68-182

> CLOSED BREECH SCAVENGER SYSTEM FOR SHERIDAN WEAPONS SYSTEM

UPPER: MAIN COMPRESSOR SWITCH.

LOWER: COMPRESSED AIR CYLINDER INSTALLED.



US ARMY ARMOR AND ENGINEER BOARD USATECOM PROJ NO 1-4-2528-33 FORT KNOX, KY PHOTO NO 68-191 AND 68-188A

> CLOSED BREECH SCAVENGER SYSTEM FOR SHERIDAN WEAPONS SYSTEM

UPPER: RESIDUE REMOVED FROM BREECH CAVITY AFTER FIRING THREE ROUNDS.

LOWER: ARROW INDICATES MOLTEN RESIDUESPRAYED ON WALL OF GUN TUBE AFTER ONE ROUND.





US ARMY ARMOR AND ENGINEER BOARD USATECOM PROJ NO 1-4-2528-33 FORT KNOX, KY PHOTO NO 68-207 AND 68-201

> CLOSED BREECH SCAVENGER SYSTEM FOR SHERIDAN WEAPONS SYSTEM

UPPER: CONTACT POINTS THAT HAD FUSED TOGETHER IN COMPRESSOR RELAY

LOWER: ARROW INDICATES BURST BUBBLE IN AIR HOSE

DEFICIENCIES AND SHORTCOMINGS

Equipment Performance Reports were not submitted to cover the system failures and other limitations noted.

S
ENCIES
r i
$\simeq$
4
0
ICI
DEF
in i
5
•

	Deficiency	Suggested Corrective Action	Remarks
1.1	The compressor relay contact points fuzed together.	None	See para 6d(5).
1.2	Bubbles formed in the cover- ing of a high pressure hose.	None	See para 6c(5).
1.3	Water was found in the system.	None	See para 6c(5).
	2.	SHORTCOMINGS	
	Shortcoming	Suggested Corrective Action	Remarks
2.1	Manual purge valve is so located that it is not easily accessible.	None	See para 6b(2)(a).
2.2	Main compressor switch could be turned off accidentally.	None	See para 6b(2)(b).
2.3	Considerable difficulty in	None	See para 6b(2)(c).

reading pressure gauges.

Incl 8

PRESSURE DROPS AND RECOVERY TIME (Continuous Purging with Compressor Running)

Initial Cylinder Pressure 3050 PSIG.

Initial Regulator Pressure 760 FSIG.

Initial	L Regulator Fr	Initial Regulator Pressure 760 PSIG.						
	Ч	1 Rd/Min	N	Rd/Min	m	3 Rd/Min	4	4 Rd/Min
Rounds	Pressure Drop (PSIG)	Self Recovery Pressure (PSIG)	Pressure Drop (PSIG)	Self Recovery Pressure (PSIG)	Pressure Drop (PSIG)	Self Recovery Pressure (PSIG)	Pressure Drop (PSIG)	Self Recovery Pressure (PSIG
Ч	2600	2750	2600	0	2600	0	2600	0
ĩN	2350	2500	2250	c	2100	0	2200	, 0
m	2 i.00	2300	2050	0	2000	0	1950	0
-7	1950	2100	1850	0	1750	0	1750	0
S	1700	1900	1600	0	1500	0	1500	0
Q	1550	1750	1400	0	1350	0	1300	0
7	1400	1550	1200	0	0011	0	0011	0
80	1200	1350	1000	0	950	0	006	0
6	1050	1200	850	0	800	0	700	0
10	800	1000	700	0	650	0	600	0
11	200	850						

### PRESSURE DROPS AND RECOVERY TIME (With Compressor Running)

Initial Cylinder Pressure 3050 PSIG

Initial Regulator Pressure 760 PSIG (STATIC)

#### TWO ROUNDS PER MINUTE

Rounds	Pressure Drop (PSIG)	Recovery <u>Time (Min)</u>	Cut Off Pressure (PSIG)
l	2600	4.75	3050
2	2250	9.05	3050
3	2050	12.25	3050
4	1850	16.95	3050
5	1600	19.50	3050
6	1400	22.95	3050
7	1200	26.75	3050
.8	1.000	30.25	3050
9	850	33.95	3050
10	700	37.25	3050

### FOUR ROUNDS PER MINUTE

Rounds	Pressure Drop (PSIG)	Recovery <u>Time (Min)</u>	Cut Off <u>Pressure (PSIG)</u>
l	2600	4.95	3050
2	2200	8.95	3050
3	1950	12.50	3050
4	1750	16.66	3050
5	1500	19.55	3050
6	1300	23.50	3050
7	1100	27.50	3050
8	900	32.25	3050
Incl 10 9 10	700 600	35•75 39•50	3050 3050

.

Incl 11

### LETTER REPORT NO. 16

#### NOISE EVALUATION OF M-551 RECONNAISSANCE

#### VEHICLE AND ASSOCIATED EQUIPMENT

Carl E. Guthrie Otto J. Dilly Michel Loeb, Ph.D.

Experimental Psychology Division US ARMY MEDICAL RESEARCH LABORATORY Fort Knox, Kentucky 40121

March 1968

Traumatic Origins of Hearing Loss Work Unit No. 017 Army Aviation Medicine Task No. 00 Army Aviation Medicine DA Project No. 3A025601A819

## NOISE EVALUATION OF M-551 RECONNAISSANCE VEHICLE AND ASSOCIATED EQUIPMENT

In response to a request by the U. S. Army Armor and Engineer Board, Ft. Knox, Ky., an evaluation of the noise characteristics of the M-551 Reconnaissance Vehicle and associated equipment was made. The noise produced by the vehicle while stationary was recorded on a 1525-A General Radio data recorder, employing a Type 1551-P1-25 microphone. These data were later analyzed in the laboratory on a 1558-AP General Radio octave band analyzer. (It was also played into a Brüel and Kjåer 1/3 octave band analyzer to determine whether any narrow band components were present. None were found.)

Readings were taken at four operating positions with the motor running and with the air compressor (Walter Kidde and Company) for the gun scavenging system both on and off. Overall levels and octave band levels are given in Table 1.

Insert Table 1 about here

#### **DISCUSSION**

Note that with the compressor off and the vehicle stationary, the octave band levels do not exceed 90 dB. Referred to the advisory standards for noise exposure, the obtained levels are slightly below "hese considered

2

hazardous (TB MED 251), with no ear protection. It does not follow, however, that hazardous noise will be absent with the vehicle moving; past experience with tracked vehicles suggests that the opposite may be true.

With the compressor on, the noise levels without ear protection must be considered excessive for the octave bands, centered at 125, 250, 500, 1,000, 2,000, and 4,000 Hz. The approximate protection afforded by the CVC helmet would be 5, 7, 7, 10, 17, and 25 dB (according to a U. S. Army QM Lab Rept. No. EP-181). If the helmet is worn, the exposure at 500 Hz would still be potentially hazardous at all four operating positions, and at 1 KHz it would be, at least marginally hazardous for three of the four positions. At 250 Hz the loader's exposure would also be considered hazardous.

If the compressor were run only briefly after each firing, however, the possibility of hazard would be minimized considerably, probably to the vanishing point.

#### **RECOMMENDATIONS**

1. There would appear to be no hazard to hearing when the vehicle is stationary with the engine running, and the compressor is off.

3

2. If the compressor is run continuously, acceptable ear protection (as described in TB MED 251) should be worn.

3. No assessment of hazard to hearing in the moving vehicle has been made.

#### REFERENCES

1. TB MED 251. Noise and Conservation of Hearing. HQ, DA, Washington, D. C., 1905.

4

2. Cohen, A. US Army QM Lab Rept. No. EP-151, Natick, Mass., 1961 (Now Pioneer Lab).

		_	Driver	100	26	88		89	98	95	89	89	80	67
pe rating	sor On	Position	Tank Cmdr	66	88	95	92	16	94	93	88	88	82	20
Different Operating	<b>Comp ressor</b>	Operating	Gunner	1 02	56	88	16	8	8	8	06	87	85	74
at		U	Loader	107	94	98	93	98	103	1 03	93	92	88	77
Overall (OA) and Octave Band (OB) Levels Positions			Driver	42	88	83	87	80	80	80	70	57	44	37
ctave Ba	sor Off	Position	Tank Cmdr	ļ	85	62	87	81	78	76	70	58	46	40
A) and O	Compressor	Operating	Gunner	93	89	87	88	78	81	80	73	60	50	42
)verall (C ositions		0	Loader	93	87	86	89	78	81	80	72	61	49	42
Table 1. C F				OA	31.5 Hz	63	125	250	500	1,000	2,000	4,000	8, 000	16,000
							нC		Fred F	רי 				

S

UNCLASSIFIED

Security Classification

Security Classification			
DOCUMENT (Security classification of title, body of abstract and in	CONTROL DATA - RE		
(Security classification of fifte, body of abetract and in 1. ORIGINATING ACTIVITY (Corporate author)	dexing ennotation must be e		RT SECURITY C LASSIFICATION
US Army Armor and Engineer Board			ASSIFIED
Fort Knox, Kentucky 40121		25 GROU	
S REPORT TITLE SERVICE TEST OF PRODUCT IMPROVED COM BREECH SCAVENGER SYSTEM)	PONENTS FOR SHER	IDAN WEA	PONS SYSTEM (CLOSED
4. DESCRIPTIVE NOTES (Type of report and inclusive dates) First Partial Report			
S. AUTHOR(S) (Last name, first name, initial)	······		
WATSON, Vaden K., Captain SICKS, Truman E., SP4, Scientific an	d Engineering		
S. REPORT DATE 26 March 1968	74 TOTAL NO OF	PAGES	75. NO OF REFS
SA. CONTRACT OR GRANT NO.	98. ORIGINATOR'S R	EPORT NUN	1
5. PROJECT NO.	US Army Te Project No		valuation Command 8-33
с.	9b. OTHER REPORT this report)	NO(S) (Any	other numbers that may be assigned
d.			
10. AVAILABILITY/LIMITATION NOTICES			
This document may be further distrib approval of Project Manager SHERIDAN		er <u>only</u>	with specific prior
11. SUPPLEMENTARY NOTES	12 SPONSORING MIL Project Man. US Army Mat. ATTN: AMCPI Rock Island	ager SHE eriel Co M-SH	
Test of Product Improved C Breech Scavenger System) was conduct (USAARENBD) at Fort Knox from 7-16 M the capability of the compressor to if the compressor, the remainder of turret is compatible with crew funct the compressed air bottle, and to as charge rate with regard to its adequ residue not cleaned by the scavenger pressor for 50 hours, firing of 58 r roads and cross country for 496 mile general compatible with crew functio from minimum firing pressure of 1,00 burning residue experienced in firin in breech cavity after each round. compressor contact point failure, wa of test was insufficient to determin tional testing be conducted on a sys as many shortcomings as feasible.	ed by US Army Arm arch 1968. Test withstand the vel the scavenger sy ions; to determi sess the bottle acy for firing m . Results are b ounds, and movem s. Restowage of ns. Time requir 0 psi to maximum g 58 rounds. No Reliability defi ter in system. e suitability.	mor and objecti hicle en stem, an ne time capacity issions, ased on ent over the tur ed to re pressur nburning ciencies USAARENE	Engineer Board ves were: to assess wironment; to determin d the restowage of the required to recharge and compressor re- , and to describe any operation of the com- paved and unpaved ret components was in charge the air bottle re was 31 minutes. No g residue was evident include hose failure, D concluded duration D recommended addi-
as many shortcomings as reasible.			

DD . SAN 4 1473

.

\_

#### UNCLASSIFIED

Security Classification

Security Classification		1 1.16	K A	L LIN	KB	1	IK C
KEY WORDS		ROLE	WT	ROLE	WT	ROLE	WT
Closed Breech Scavenger Sheridan M551 Compressor							
							-
INST	RUCTIONS	5					
1. ORIGINATING ACTIVITY: Enter the name and address of the contractor, subcontractor, grantee, Department of De- fense activity or other organization (corporate author) issuing the report. 2a. REPORT SECURITY CLASSIFICATION: Enter the over- all security classification of the report. Indicate whether	itations imposed such as: (1)	on further by securit	dissemin y classif d request	ATION N lation of t fication, u	he report using stat	, other the ndard stat	en those ements
"Restricted Data" is included. Marking is to be in accord- ance with appropriate security regulations. 2b. GROUP: Automatic downgrading is specified in DoD Di- rective 5200. 10 and Armed Forces Industrial Manual. Enter the group number. Also, when applicable, show that optional markings have been used for Group 3 and Group 4 as author- ized.	(2)	"Foreign report by "U. S. Go	announce DDC is n vernment t directly	ement and tot authori agencies from DD	ized." i may obt	ain copie	s of
3. REPORT TITLE: Enter the complete report title in all capital letters. Titles in all cases should be unclassified. If a meaningful title cannot be selected without classifica- tion, show title classification in all capitals in parenthesis immediately following the title.	(4)		ectly from	encies ma n DDC. C igh			
4. DESCRIPTIVE NOTES: If appropriate, enter the type of report, e.g., interim, progress, summary, annual, or final. Give the inclusive dates when a specific reporting period is covered.	(5)			of this rep hall reque			Qual-
5. AUTHOR(S): Enter the name(s) of author(s) as shown on or in the report. Enter last name, first name, middle initial. If military, show rank and branch of service. The name of the principal author is an abaclute minimum requirement.	Services cate this	Departme	enter the	urnished t mmerce, f price, if DTES: Ut	or sale t known	o the publ	lic, indi
Closed Breech Scavenger Sheridan M551 Compressor	tory note 12. SPC the depa	na. NSORING rtmental p	MILITA	RY ACTI fice or lat	VITY: E poratory :	nter the n sponsoring	ame of g (pay-
74. TOTAL NUMBER OF PAGES: The total page count should follow normal pagination procedures, i.e., enter the number of pages containing information.	13. ABST summary it may al	RACT: E of the dou	nter an a sument in elsewhe	bstract gi dicative of re in the l	ving a br of the rep body of t	rief and fa port, even he technic	ctual though cal re-
references cited in the report. Sa. CONTRACT OR GRANT NUMBER: If appropriate, enter	shall be It is	attached. highly des	irable th	at the ab	stract of	classified	d re-
the report was written. 86, 80, 8 Sd. PROJECT NUMBER: Enter the appropriate	end with	an indica formation	tion of th	h paragram ne military ragraph, r	security	y classific	cation
subproject number, system numbers, task number, etc.	There	e is no lim	itation of length	n the long is from 1	rth of the 50 to 225	abstract. words.	How-
cial report number by which the document will be identified and controlled by the originating activity. This number must be unique to this report.	14. KEY or short index en	WORDS: phrases th tries for c	Key work at character	ds are tec cterize a the repo	hnically report an rt. Key	meaningfu d may be words mus	used as
95. OTHER REPORT NUMBER(S): If the report has been assigned any other report numbers (either by the originator or by the sponsor), also enter this number(s).	fiers, su tary proj key word	ch as equi ect code r ls but will The assi	pment me ame, geo he follo	y classifi odel desig ographic l wed by an of links, r	gnation, ( ocation, indicati	trade name may be us on of tech	e, mili- led as inical

•

٠