



Report USNA-EPRD-40 AD A0 597 POLAROGRAPHY OF RDX HYDROLYSIS PRODUCTS IN EFFLUENT OF ION EXCHANGE COLUMN TREATMENT OF RDX WATER, (10) Assistant Professor John V./Prestia Chemistry Department U. S. Naval Academy Annapolis, Maryland 21402 Final Report for provided 1 July 2976 - 31 August 1976 Unlimited Distribution 31 un This document has been approved Prepared for: for public release and sale; its distribution is unlimited. Naval Sea Systems Command Department of the Navy, Code 0332 Washington, D. C. 20362 Energy-Environment Study Group U. S. Naval Academy 205 Rickover Hall Annapolis, Maryland 21402 408 548 058

REPORT DOCUMENTATION	PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO	. 3. RECIPIENT'S CATALOG NUMBER
USNA-EPRD-40		
4. TITLE (and Subtitle)	+	5. TYPE OF REPORT & PERIOD COVER
POLADOCDADHY OF DOY HYDDOLYSTS DD	NI STOUGG	Final
FEELIENT OF ION FYCHANGE COLUMN T	PEATMENT	July 1976 - June 1977
OF PDX WATER	NEATHENT	6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(+)		B. CONTRACT OR GRANT NUMBER(.)
Assistant Professor John V. Prest	ia	
9. PERFORMING ORGANIZATION NAME AND ADDRESS		AREA & WORK UNIT NUMBERS
U. S. Naval Academy		
Annapolis, Maryland 21402		
11 CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE
Naval Soa Systems Command		30 June 1977
Department of the Navy		13. NUMBER OF PAGES
Washington D C 20362		9
14. MONITORING AGENCY NAME & ADDRESS(II differen	at from Controlling Office)	15. SECURITY CLASS. (of this report)
Energy-Environment Study Group		
205 Rickover Hall		
U. S. Naval Academy		154. DECLASSIFICATION DOWNGRADIN SCHEDULE
Annapolis, Maryland 21403		
16. DISTRIBUTION STATEMENT (of this Report)		A STREET STOP B
	2019	
	A Star Apple	and for public release;
	De De	bolien Unimited
17. DISTRIBUTION STATEMENT (of the abstract entered	in Block 20, if different fr	om Report)
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary an	nd identify by block number	")
Belevenephy		
pov De	composition	
RDX Hydrolycic Products	drolysis	
NUA HYDROTYSIS PRODUCES NI	tramines	
20. ABSTRACT (Continue on reverse elde il necessary and	d identity by block number,	Panid Scan Single Sween
RUX in water solution can be meas	detection is a	bout 0 5 ppm
Polarography. The lower limit of	detection is a	bout 0.5 ppm.
FORM 1472		
DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOI	LETE	
3/14 UIU2-UI4- 00VI		
S/N 0102-014-6601		

1- 19

INTRODUCTION

Dr. John Hoffsommer of NSWC, White Oak, Maryland has studied the hydrolysis of RDX in basic solution and has noted its decomposition along with the nature of the products of this hydrolysis. The same kind of hydrolysis of RDX has been noted on an ion exchange column (Amberlite 410- Strongly basic form) and it is this process that has been investigated as a possible method for treating waste streams from loading and/or dimilitarization operations. It would be highly desirable to have a monitoring device on the effluent side of this column in order to know when the column has failed, or when the column needs to be regenerated. This study involves the use of Rapid Scan Single Sweep Polarography as a means of analyzing the effluent from the ion exchange column for monitoring purposes. This was suggested in that previous work done in this laboratory has shown that RDX does in fact show distinct reduction waves when this technique is employed.¹

¹Prestia, John V. USNA-EPRD-39 Report "Poloargraphy of Ordnance Compounds," (Jun 1976)

NTIS DDC		White Buff	e Section Section	
INANNO IU s e is	JNCED ATION			
by Distribi	TION/A	VAILAE	ILITY CODA	S

-1-

EXPERIMENTAL

All measurements were made using a PAR Model 170 Electrochemical System employing the Rapid Scan Single Sweep Polarographic technique. Measurements were made vs. the Standard Calomel Electrode (SCE) and all voltages reported on this basis. Before reduction, the solutions were flushed with nitrogen gas for 15 minutes to expel dissolved oxygen which is known to interfere in the potential range of interest (-0.1 to -1.5 volts vs. SCE). The actual measurement was made using a hanging mercury drop electrode (a new drop for each sweep) in a still solution with a platinum wire as the current carrying electrode.

RDX solutions and dimethylnitramine were supplied by Dr. John Hoffsommer of NSWC.

As long as care was taken to remove oxygen and maintain a clean capillary in the hanging mercury drop electrode assembly, reproducibility of curves for the same or similar samples was very good.

RESULTS

Supporting Electrolyte

Previous work indicated that the reduction waves of RDX were not altered when a change was made from KC1 solutions to acetate buffers.¹ Since the pH of effluent of the ion exchange column was found to be about 10, it was decided to try a phosphate buffer with a nominal pH of 8-9 as the supporting electrolyte. Both 0.1 M KC1 and 0.1 M phosphate buffer were used, but saturated solutions of RDX give identical reduction waves in the two media. In fact, when the RDX solution is run alone without additional electrolyte of any ind, the same polarogram results. Utilization of this fact is not practical, however, since at low concentrations of RDX (simple dilution with water to about one (1) ppm) the amount of electronic noise that develops in the recorder makes the polarogram useless. All work reported then is that done in 0.1 M phosphate buffer with a nominal pH of 8-9.

Difficulties

The experimental technique, although straightforward, requires utmost care in order to obtain meaningful results. A considerable amount of time was spent in finding the optimum conditions necessary to obtain good polarograms as a matter of routine. Obviously, it is necessary to maintain glassware, electrodes, gas probes, etc. scrupulously clean as the instrument and the technique are very sensitive to trace amounts of impurities and foreign matter. The most important consideration, however, and the one factor that requires the most care is the condition of the capillary from which the mercury drop hangs. Anomalous results were explained in terms of the hanging mercury drop electrode in practically 100% of the cases where deviations from expected were noted.

Monitoring of RDX

The essence of this study is the ability to monitor RDX in a given stream, the effluent of the ion exchange column degradation in this case. A sample of the RDX feed to the column (NSWC Cycle #1, 8 June 76) was diluted 1 to 6 with phosphate buffer and the polarogram recorded. See Figure 1. Since the concentration of RDX as given by Hoffsommer for this sample was 37.5 ppm, the actual concentration in the measured solution was 6.3 ppm. Figure 2 shows the

¹Ibid.





corresponding polarogram for the effluent from the same column, taken at the same time. The RDX concentration in this solution was 0.38 ppm and therefore upon dilution of 1 to 6 with the buffer, the resultant concentration was about 0.06 ppm. It is obvious that the instrument can distinguish between these two solutions with ease. These experiments were repeated with samples from NSWC Cycle #6 and NSWC Cycle #8 of July 1976 with identical results. Some attempt was made to set a lower limit to the concentration of RDX that can be detected by this method. Drop size, sweep rate, and sensitivity adjustment of instrument are undoubtedly involved in this determination, but by using the effluent samples as a starting point (see Figure 2) small samples of the RDX feed were injected as an RDX, spike. Based on a limited number of qualitative experiments, it is estimated that RDX concentrations of about 0.5 ppm would be detected if present in the effluent from the column.

Products of Decomposition

The products of decomposition of RDX on the ion exchange column have been identified by Hoffsommer² as NO₂, N₂, NH₃, N₂O, CH₂O, and HCOO⁻. Of these, two would be expected to be retained by the anion column, N₂ is known to be inert to reduction under the conditions of the polarographic technique used and the remaining three (NH₃, N₂O, and CH₂O) must be considered as possible active species at the electrode under the applied potential. Attempts were made to put NH₃ and CH₂O into the polarographic cell and examine the resultant polarograms, but only a limited amount of work was done in this area. No apparent reduction waves resulted but in any case, the date is suspect and this work would have to be repeated. One point should be made however, that the flushing with nitrogen may in fact alter the amount of NH₃ and or CH₂O that would remain in solution.

Reduction Characteristics of Other Nitro Compounds

Since many ordnance compounds are nitro compounds, RDX is in particular a nitramine, a few qualitative measurements were made on nitromethane, nitrobenzene, and dimethylnitramine. Both nitromethane and nitrobenzene show peaks in the current vs. potential plots obtained in the range of -0.4 to -0.5 volts vs. SCE. Figure 3 is the polarogram obtained when the phosphate buffer was spiked with dimethylnitramine.

²Hoffsommer, J.C., private communication.



RECOMMENDATIONS

It is apparent that Rapid Scan Single Sweep Polarography at a hanging Mercury Drop Electrode is sensitive to small concentrations of RDX in water solutions. Extensive use of a buffer has been made in this work, but there are hints that little or no additional electrolyte may be needed. The system is to the point of development that installation of a polarograph on the effluent side of a treatment process is the next step. An instrument such as that described by Becktel and Whitnack is the obvious choice.³

³Becktel, W.J. and G.C. Whitnack, NWC TP 5860 Part 2 (Sept. 1976).

DISTRIBUTION EPRD-40

- 1 Academic Dean USNA Yard Mail Stop 1c
- 2 Chief of Naval Material (Mr. Lynne Harris) MAT 03421, Room 1044 CP#5 Washington, D. C. 20360
- 1 Division of Mathematics ξ Science USNA Yard Mail Stop 9a
- 1 Chemistry Department Chairman USNA Yard Mail Stop 9b
- 12 Defense Documentation Center Defense Supply Agency Cameron Station Alexandria, VA 22314
 - 1 Director of Research USNA Yard Mail Stop lc
 - 2 Naval Academy Library (1 to Catalog Dept.) USNA Yard Mail Stop 10a
 - 2 Naval Facilities Engineering Command Hq. (Mr. S.M. Hurley, Code 03) 200 Stovall Avenue Alexandria, VA 22332
 - 2 Commanding Officer (Code 25111) Navy Environmental Support Office Naval Construction Battalion Center Port Hueneme, CA 93043
 - 2 Superintendent U. S. Naval Postgraduate School Monterey, CA 93940
 - 1 Naval Sea Systems Command Hq. (Mr. W.W. Blaine, Code 0332) Washington, D. C. 20362
 - 1 Dr. Gerald Whitnack Naval Weapons Center China Lake, CA 93555

