## **UNCLASSIFIED**

# AD NUMBER AD035574 CLASSIFICATION CHANGES TO: unclassified FROM: confidential LIMITATION CHANGES

## TO:

Approved for public release; distribution is unlimited.

## FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors;

Administrative/Operational Use; DEC 1952. Other requests shall be referred to Naval Proving Ground, Dahlgren, VA.

## AUTHORITY

31 Dec 1964, DoDD 5200.10; USNSWC ltr dtd 29 Jan 1976



CONFIDENTIAL
SECURITY INFORMATION

U. S. NAVAL PROVING GROUND DAHLGREN, VIRGINIA

REPORT NO. 1060

RESEARCH, DEVELOPMENT, AND TESTS OF AIRCRAFT ROCKET FUZE SYSTEMS

22nd Partial Report

EXPERIMENTAL BALLISTIC TEST OF MODIFIED MK 149 NOSE FUZE

Task

FINAL Report

Assignment NPG-Re2b-11-t-52

Copy No. 24

Classification <u>CONFIDENTIAL</u> <u>SECURITY INFORMATION</u>

1

THIS REPORT HAS BEEN DELIMITED

AND CLEARED FOR PUBLIC RELEASE

UNDER DOD DIRECTIVE 5200.20 AND

NO RESTRICTIONS ARE IMPOSED UPON

ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED.

#### PART.A

## SINOPRIS

- 1. Insamuch as the Mk 149 rocket nose fuze in present service use has consistently failed the 25 ft. acceptance drop test, Swank, Inc., manufacturer of the fuze under contract from the Navy, proposed a modification which they felt would correct this failure and make the fuse safer to handle. Samples of the fuze were submitted to the Naval Proving Ground for ballistic evaluation.
- 2. a. This test was conducted to determine the operability of the modified fuze under the following conditions:

Part	Desired Velocity	Target	Oblimity
1	1800 ft./sec.	1/8" mild steel	0•
2	1800 ft./sec.	1/8" mild steel	Maximum for consistent operation
3 .	1800 ft./sec.	240 or greater homogeneous armor plate	Maximum for consistent operation

#### 3. It is conduced that:

- a. The modified Mk 149 nose fuze will function consistently in a 5.0 rocket head Mk 6 upon 1/8 MS at 0° obliquity.
- b. The fuze will function consistently in a 5"0 rocket head Mk 6 upon 1/8" MS at obliquities up to and including 75°.
- c. The fuze as modified will function upon 3.50 Class B armor in Mk 25 shaped charge heads up to obliquities of 70°. However, 70° seems to be the critical angle and functioning at this angle cannot be considered as consistent.
- d. The modified fuze compares favorably ballistically in all respects with the present Mk 149 fuze. In addition, the Naval Ordnance Laboratory reports it will successfully pass the 25 ft. drop test.

CONFIDENTIAL SECURITY INFORMATION CONFIDENTIAL

## NPG REPORT NO. 1060

## Experimental Ballistic Test of Modified Mk 149 Nose Fuze

#### TABLE OF CONTENTS

WNOPSIS	
BLE OF CONTENTS	
UTHORITY	
EFERENCES	
ACKGROUND	
BJECT OF TEST	- 27 - 17
ERIOD OF TEST 4	
EPRESENTATIVES PRESENT	
DESCRIPTION OF ITEM UNDER TEST	
DESCRIPTION OF TEST EQUIPMENT	
PROCEDURE	
RESULTS 6	
conclusions	
경영 속이 많이 모든 이 경우를 되는데 하시다. 이 시하는 모든 모든 것이다.	
APPENDIX A - IMPACT RECORDS	O (Incl)
APPENDIX B - SUMMARY OF RESULTS	(Incl)
APPENDIX C - NPG PHOTOGRAPHS FIGURES 1-9	(Incl)
APPENDIX D - DISTRIBUTION 1-2	(Incl)

## PART B

#### INTRODUCTION

#### AUTHORITY:

This test was authorized by reference (a) and conducted under Task Assignment NPG-Re2b-11-1-52.

#### REPURENCES:

- a. NOL Spdltr DP:HSW:dlg NP/NOL/X1-1(2628) Ser 3438 of 6 June 1952
- b. NPG Work Request from NOL 8003-A of 12 June 1952 c. NPG Work Request from NOL 8003-B of 16 July 1952
- d. NOL Spdltr TF:CLP:obt NP/NOL/X1-1(2852) Ser 4194 of 15 July 1952

#### 3. BACKGROUND:

Inasmuch as the Mk 149 rocket nose fuze in present service use has consistently failed the 25 ft. acceptance drop tost, Swank, Inc., manufacturer of the fuze under contract from the Navy, proposed a modification which they felt would correct this failure and make the fuze safer to handle. Samples of the fuze were submitted to the Naval Proving Ground for ballistic evaluation.

#### OBJECT OF TEST:

a. This test was conducted to determine the operability of the modified fuze under the following conditions:

Part	Desired Velocity	Target	Obliquity
2	1800 ft./sec.	1/8" mild steel	00
2	1800 ft./sec.	1/8" mild steel	Maximum for consistent operation
3	1800 ft./sec.	200 or greater homogoneous armor plate	Maximum for consistent operation

NOTICE: THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE

NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING

OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 and 794.

THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN

ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW

#### CONFIDENTIAL

Experimental Ballistic Test of Modified Mk 149 Nose Fuze

#### 5. PERIOD OF TEST:

	Date Project Letter Dates Necessary Material Received	6 June 1952 18 June 1952
<b>D</b> •	Dates Medessary material necessed	22 July 1952
	Date Commenced Test Test Completed	23 June 1952 21 August 1952

#### 6. REPRESENTATIVES PRESENT:

Mr.	C.	L.	Pettingill
Mr.	L.	J.	Shkolnik

Naval Ordnance Laboratory Naval Ordnance Laboratory

#### PART C

#### DETAILS OF TEST

## 7. DESCRIPTION OF ITEM UNDER TEST:

a. The Mk 149 nose fuze was developed for use with various fin-stabilized aircraft rockets. It is a point detonating, air-arming fuze.

b. Arming is accomplished by a combination of air stream and acceleration forces acting as the rocket is launched. Figure 1 shows the general arrangement of the fuze. Acceleration retracts the setback block, releasing the firing pin propeller assembly. The propeller, acted on by the air stream, screws the firing pin out until the shutter is released. The shutter is then rotated into the armed position by the shutter spring. It is locked by a detent in such a position that the detonator in the shutter is in line with the firing pin and the lead-in to the booster.

c. The modification to the fuze consists of a redesign in the firing pin. As manufactured by Swank, Inc. of Attleboro, Mass., it is now a two piece pin with the forward section hollowed out. The diameter of the pin has been slightly increased and the firing pin guide has been changed correspondingly (see Figure 2). The shoulder on the firing pin has been altered so that slippage past the shutter has been prevented. This modification is intended to weaken the firing pin to a point where it will collapse on a drop of 25 ft. or more instead of driving through into the booster.

CONFIDENTIAL SECURITY INFORMATION

## 8. DESCRIPTION OF TEST EQUIPMENT:

Launcher: NPG 1050 ft.

Propulsion: 500 HVAR Mk 10 Mod 5 rocket motors

Camera: 35mm Mitchell

Velocity: Potter Chronograph and Oscillograph

#### 9. PROCEDURE:

a. Part I of this test consisted of firing rounds against 1/8" mild steel plate at 0° obliquity. The fuzes were assembled in 5"0 rocket heads Mk 6 Mod 1 TNT loaded. Propulsion in all phases of the test was accomplished by two 5"0 HVAR motors in tandem, to obtain a desired velocity of 1800 ft./sec.

- plate at obliquities ranging from 45° to 75° to determine the maximum for consistent operability. Owing to a premature Letonation on the 2nd round, smoke-puff loaded heads (250-300 grams, black powder) replaced the TNT loaded heads as requested by reference (d). Reference (c), which requested the use of smoke-puff loaded heads instead of HE loaded heads, superseded reference (b) at this time. A 35mm Mitchell camera was used to record the fuze action upon impact. At the time of the premature detonation, it was believed that the cause might have been a shearing of the pin joining the two sections of the firing pin. An air jet test, as requested in reference (c), was therefore performed on four fuzes to determine the ability of this assembly pin to withstand the shearing forces which occur at the end of the firing pins forward travel. This test consisted of securing the inert rounds, containing modified, inert Mk 149 fuzes, to a table immediately in front of the Naval Proving Ground air jet. When the air jet had reached its maximum velocity (500 M.P.H.), the arming wire was removed by the use of a lanyard. When the propeller ceased to spin, indicating the end of the firing pin screw-out, the air jet was turned off.
- c. Part III of the test consisted of firing medified fuzes in 5%0 shaped charge heads Mk 25 against 3%50 Class B armor to determine the maximum obliquity for consistent operation against thick armor targets. The heads were TNT loaded.

CONFIDENTIAL SECURITY INFORMATION

## 10. RESULTS:

a. The results are summarized below:

#### PART I

	'21			1
No. Rds.	Striking Velocity	Target	Obl.	Results
4	1800	1/8" MS	0°	4 HO
		PART II	, .	
2 1 1 1 2	1800 1800 1300 1300 1800	1/8" HS 1/4" MS 1/8" MS 1/8" HS 1/8" MS	50° 50° 50° 560°	1 HO, 1 Dud 1 Dud 1 HO 1 HO 1 HO on launcher,
1 1 1 6 3 2	1300 1300 1300 1800 1800 1800	1/8" HS 1/8" ME 1/8" HS 1/8" HS 1/8" HS 1/4" HS 3/8" HS	60° 70° 70° 75° 75°	1 Dud 1 H0 1 H0 1 H0 1 H0 5 H0, 1 Missed Target 3 H0 2 H0
* .		PART III		
1 2 6 1	1800 1800 1800 1800	3-7/16" Class B 3-3/8" Class B 3-7/16" Class B 3-7/16" Class B	55° 65° 70° 75°	HO 2 HO 3 HO, 2 Duds, 1 LO 1 Dud

- b. On round 2 of Part II, there was a premature detonation which damaged the launcher (Figure 3). It was believed at the time that this may have been caused by a shearing of the pin joining the two sections of the firing pin thus allowing the lower part of the pin to slide into the detonator. However, after the premature detonation of the smoke-puff leaded head on round 18, the remnants of a bird were found at the scene indicating that perhaps the trouble occurred as a result of the round striking such an obstacle on the rails. On round 20 a dead catbird (Dumetella carolinensis) weighing 1.1 oz. was secured at the launcher muzzle so that the firing pin of the nose fuze would strike it (Figure 4). The fuze detonated upon impact with the bird confirming suspicions and relieving the fuze of responsibility for the premature detonations. The test was temporarily delayed until an alarm system could be installed on the launcher to drive off the birds to prevent further fuze action on the launcher.
- c. Rounds 3 through 11 of Part II did not have the acceleration setback pin in the fuzes removed. It was found that in using two motors for propulsion the head motor was still accelerating at the target, thus preventing the fuze from arming. This condition was corrected by using a single motor on rounds 6 through 11 so that acceleration was completed prior to target impact.
- d. No impacts above 75° obliquity were attempted because of the poor striking accuracy at these high angles.
- e. Figure 5 1s a typical view of fuze detonation after impact with 3/8" MS plate at 75° obliquity.
- f. The rounds that were duds on Part III deflagrated on the side wall of the butt.
- g. On round 2 of Part III, a bulge 9" x 12" was produced on the back side of the plate approximately 13"0 behind the opening. Back spalling of the target plate occurred on rounds 3 and 6 (see Figures 6 through 9). This behavior is ascribed to the reflection and reenforcement of shock waves in the plate arising from the detonation of the rocket head in its proximity as in the case of the squash-head projectile. Figure 9 shows a sketch of the area in which spalling occurs, further indicating that consistent functioning can not be reasonably effected with this round at impact angles of 70° or greater because of the geometry of the nose.

#### PART D

#### CONCLUSIONS

#### 11. It is concluded that:

- a. The modified Mk 149 nose fuze will function consistently in a 500 rocket head Mk 6 upon 1/8" MS at 0° obliquity.
- b. The fuze will function consistently in a 5%0 rocket head Mk 6 upon 1/8" MS at obliquities up to and including 75°.
- c. The fuze as modified will function upon 3"50 Class B armor in Mk 25 shaped charge heads up to obliquities of 70°. However, 70° seems to be the critical angle and functioning at this angle cannot be considered as consistent.
- d. The modified fuze compares favorably ballistically in all respects with the present Mk 149 fuze. In addition, the Naval Ordnance Laboratory reports it will successfully pass the 25 ft. drop test.

The tests upon which this report is based were conducted by: F. W. KASDORF, Rocket Battery Officer Rocket Battery Division Terminal Ballistics Department

This report was prepared by: R. G. SONG, Ensign, USNR, Rocket Battery Firing Officer Rocket Battery Division Terminal Ballistics Department

This report was reviewed by:

R. H. LYDDANE, Director of Research Terminal Ballistics Department

E. L. LEVSTIK, Lieutenant Commander, USNR
Terminal Ballistics Batteries Officer Terminal Ballistics Department

W. B. ROBERTEON, Lieutenant Commander, USN Terminal Ballistics Officer Terminal Ballistics Dopartment

C. C. BRAMBLE, Director of Research Ordnance Group

APPROVED: J. F. EYRNE Captain, USN Commander, Naval Proving Ground

> E. A. RUCKNER Captain, USN Ordnance Officer

By direction

#### U. S. NAVAL PROVING GROUND DAHLGREN, VIRGINIA

This report is transmitted for your information and file. Additional information may be obtained by addressing:

Chief, Washington USAF Engineering Field Office Room 4040, Main Novy Building Washington 25, D.C.

The telephone extension is 62471 or 65568 on the Department of Defense Exchange.

Twenty-Second Partial Report

on

Research, Development, and Tests of Aircraft Rocket Fuze Systems

Final Report

on

Experimental Ballistic Test of Modified Mk 149 Nose Fuze

Project No.: NPG-Re2b-11-1-52 Copy No.: 24

No. of Pages: 9

CONFIDENTIAL SECURITY INFORMATION

Date: DEC 3 1952

*		AL PROVING GROUN REN, VIRGINIA	ID IMPACT NO. 40093
r	DARLO	nen, vindinia	IMPACT DATE 8-20-52
			MPG TEST NCL-2222-1.25
OBJECT_	Functioning Te	est of Modified	Mk. 149 Rocket Nose Fuza
i	u 500 Rocket He	d Mk 25 va Plat	to #RD277
Reference: MPGNot, 11	tr		dated 6 June 1952
Reference: Bucks 11	tr. NOL Spoltr De	Redigite BE/MOD/XT-	1 dated 6 June 1952
Task Assignment No.	NPUERE26-11-12-9	50:	_dated
Task Assignment No.	RGET NPG SI CONT	no. 1660 .	ROCKET
Gage 3 75 C1	lassB	HRAD: Cal.	Type Shaped Charge  Hod   No Wt. 51 35#  Houdaille Corp.  RHCZ-7-HA-52
Maker Carna	9	Hark 25	Mod No. Wt. 51 35#
No. <u>30277</u> 01	roup	Maker	loudaille Corp.
Dimensions 12/4	X 4060	Lot No.	RHCZ-7-HA-52
OBLIQUITY	550	Fuzes 1	16# 16# 16# 16#
			l ad (as fired) 51.35# 5" Mk. 10 Mod 5
Thickness at 1mp	act 385	Wt. of her	ad (as fired) 51 35#
No. of impact on	plate /		
Dist. from neares	st impact O	MOTOR: Cal	. '5" Mr. 10 Mod 5
Dist. from near (	edres75" andiri	MOTOR Tem	D. 860 W+ 80 30-
Impact area	2-1/2" X L"		UND: Nark Mod 140.655
Spall: Front	Back <u>L" X L</u> -	3/4 COMPLETE RO	UND: NarkMod
Dish 0	Spur 1"	Wt. (as f	110.65 $\frac{1}{6}$
Cracks 0		Wt. (burn	ed)
Cracks O Punching (throw Back Button (thr	n) (started)		
Back Button (thr	OAD) (BEWSEOG)	OTHER INFOR	
Bulge Through opening	0	ALN	3MDA-267-S-51
intender cheming	2-3// 7 7 3"	T.ATTECHER	1050Ft. Hocket Launcher
	,	2010101122	TO JOP G. ROCK & C. Lauricher
	ROCKET	PERFORMANCE Mean	
Wideht	Velocite	f/a. Simble	1732 Residual
Fuze functioning	49100103	TAP: ON WINNINGS	1/1/2 Negrada
		w Order) (None)	
Distance of burst			23
Condition of recov			.======================================
	Head Vas	in (EFFECTIVE)	(INEFFECTIVE) condition.
REMARKS:			
Photo No. #19-51102		Signed F.	W. Kander
CONTRE	DENTIAL		F.W.Kasdorf
CONFI	ノシハ・エスススム	<del></del>	
EECUDITY II	NFORMATION		ORD. ENG.

U. S. NAVAL PROVING GROUND DAHLGREN, VIRGINIA

	IMPACT DATE 8-20-52
	NPG TEST NO. 17=2222-1.25
OBJECT Functioning les	at of Modified Mk. 149 Rocket Nose Fuza
	aud Mk.25 vs Plate #BD277.
Reference: MPG 11r DP <del>HSW-dle HP/NOL</del>	dated dated
INVIOLOTOROUS (DIRECTO LAN ) 1/2 3/3	<u> </u>
Task Assignment No. Non-Hezh-1!-1-52	dated
PLATE TARGET	ROCKET
Gage 3"5 Class B	HEAD: Cal. 5" Type Shaped Charge
Maker Carnesie	Mark 25 Mod 1 No Wt.51.46
No. <u>BD277</u> Group -	Maker Houdwille Corp.
Dimensions 124" X 406"	Lot No. RHCZ -7-HA-52
OBLIQUITY 65°	Pules Mk.149 No.24
PENETRATIONComplete .	Boosters
Thickness at impact 3,5	
No. of impact on plate 5	Wt. of head (as fired) 51.46
Dist. from nearest impact 17"	MOTOR: Cal. 5" Mk. 10 Mod 5
Dist. from near edges Too and L68"	
Disc. Iron near edges 100 and 108"	Motor temp. 86° Vit.83.70
Impact area 3" X 6" "	1/3 COMPLETE ROUND: MarkMod
Spall: Front 0 Back 3" 212" Dish 0 Spur 1"	
	Wt. (as fired) 140.16# Wt. (burned)
Cracks 0 Punching (thrown) (started)	Mr. (purnac)
Back Button (thrown) (started)	OTHER INFORMATION
Bulge 0 Through opening 2" \(\lambda 2-3/\(\lambda\)"	ALN: RMDA-207-S-51
Through opening 2" X 2-3/4"	LAULCHER 1050 Ft. Rocket Launcher
a Sanja	LAUSCHER 1050 Ft. Rocket Launcher
ROCKET P	PERFORMANCE
	Mean
FlightVélocity, f	/s: Striking 1686 Residual
Puze functioning	r
Explosive action (High Order) (Lov	Order) (None)
Distance of burst behind plate	
Condition of recovered round	
Head Ags 1	B (EFFECTIVE) (LEFFECTIVE) condition.
REMARKS:	
Photo No. 1102	Signed F. W. Kassler
CONFIDENTIAL	
CONFIDERA	F. Kasdorf
CAN THE STREET	ORD. ENG.
CONFIDENCE	

U.S. NAVAL	PROVING GROUND IMPACT NO. 40095
	IMPACT DATE 8-20-52
	TRA RESE WA III 2222 7 3
	NPG TEST NO. <u>T-2222-1.</u> 2
OBJECT Functioning Test	of Modified Mk. 149 Rocket Nose Fuze
	nd Mk.25 vs Plate #BD277
Reference: HIGHE ItrHOL Spilty OF:HSW:	dated dlg NP/NOL/X1-1(2646) - 3438 of 6 June 1952
Task Assignment No. NPG-Re2b-11-1-52.	dated
N PE Gligort	20. 7060
PLATE TARGET	ROCKET
Gage 3#4 Class	HEAD; Cal . 50 Type Shaped Charge
Maker, Carnegie	Nerk 25 No Wt. 51 164
No. AD277 Group	Maker Roudellla Corp.
Dimensions 324" X 406"	Lot No. RHCZ-7-HA-52
	Filler: TypeatCompatt. 164
OBLIQUITY	Fuzes Mk.1/9 Nb.25
PRESTRATION Complete	Boosters
Thickness at impact. 345	Vt. of head (as fired) 51.164
Mo. of impact on plate	
Dist. from nearest impact 28"	MOTOR: Cal. 5" Mk. 10 Nod 5
Dist. from heer edges 12n and 112m	ROTOP TOND. SOME SEE AS 25 E
Spall: Front 0 Back 0-1/2"	COMPLETE ROUND: Nark Mod
Dish a Spur 1"	Wt. (as fired) 139.51#
Cracks	Wt. (as fired) 139.51#
Punching (thrown) (started)	
Back Button (thrown) (additional)	OTHER LEMMENTION
Bulge	ATN: PHOA-267-9-51
Through opening 1 1 1 1 5/8#	
	LAUCHER 1050 Millooket Launcher
NOCKET PI	ERFORMANCE
	Meen
Flight Velocity, f	e: Striking 1698 Residual
Fuse functioning 777 August 7	
Explosive action (High Order) (Low Distance of burst behind plate	Order) (MGB+),
Condition of recovered round	
Head Was 1	(MAPPECTIVE) (MAPPECTIVE) condition.
2.4	
REMARKS:	
Photo No. NP9-51102 HDQ CHRONT A T.	Signed F.W. Kasdan
COMMINICAL	
CONTRACTION	F.W. Kadorf
SECURITY IN TOURATION	ORD. ENG
Shows	CALLO .

	PROVING GROUND IMPACT NO. 40106
	IMPACT DATE 8-21-52
The state of the state of	NPG TEST NO. T-2222-1.25
OBJECT Functioning Tes	t of Modified Mk.149 Rocket Nose Fuze
Reference: NPG ltr. (2622) Ser 343:	d Mk.25 vs Cl.B Plate.
Reference: BUOWE 1tr NO. Sheltr DP: HSJ:	dis NP/NON/XI-1 dated o June 1952
Task Assignment No. MPG-Re20-11-1-52	dated
PLATE TARGET	ROCKET
Gage 305 Class B	HEAD: Cal. 5" Type Shaped Charge Nark 25 Mod 1 NoWt. 51.93#
Maker Carnezie No. BD277 Group	Maker Houdestle Com
Dimensions 124" X 406"	Lot No. PHCZ-Z-HA-52
	Filler: Type et CompWe. 16#
OBLIQUITY 75°	Maker Houdaille Corp.  Lot No. RHCZ-7-HA-52  Piller: Type st Comp We 16#  Puzes Mk.149 No.26
PENETRATION A: 150	Boosters
Thickness at impact 3.5	Wt. of head (as fired) 51.93#
No. of impact on plate o	
Dist. from nearest impact	MOTOR: Cal.5" Mk. 10 Mod 5
Dist. Irom mear edgesand o	Motor temp. 80° Wt.89.30#
Impact area	_
Spall: Front Back	CCMPLETE ROUND: MarkMod
Dish Spur ¢	Wt. (as fired) 141.23#
Cracks	Wt. (burned)
Punching (thrown) (started)	
Back Button (thrown) (started)	OTHER INFORMATION
Bulge	AIA: RMD4-267-S-51
Through opening	TANKAN MENERAL
	LAUSCHER 1050Ft Rocket Launcher
ROCKET PI	ERFORMANCE
	Mean
Plight Velocity, f.	s: Structure 1693 Residual
Puze functioning	· · · · · · · · · · · · · · · · · · ·
	Order) (None)
Distance of burst behind plate	
Condition of recovered round	n (EFFECTIVE) (IMEPFECTIVE) condition.
Terr Are 17	d (EFFECTIVE) (INEFFECTIVE) CONDICTOR.
REMARKS:	
*************	
Photo No.	Signed F. W. Kasslary
CONFIDENTIAL	
TRENI	. F.W.Kasdorf
MAN PLANTION	ORD. ENG.
A CORPORATION OF THE PROPERTY	

# 0

U. S. NAVAL PROVING GROUND IMPACT NO. 40108

	DARLGREN,	ÄTVATUTY		^
			IMPAC	T DATE 8-21-52
	* z		NPG T	EST NO.1-2.22-1.25
OBJECT Fund	tioning Test	of Modifie	d Mk. 149	Rocket Nose Fuze
Reference: MPG ltr.			dated	
Reference: BuOrd ltr. NOL S	pditr Dp:HSd:di	E MF/NOL/X1-		
Task Assign To. 2628			dated	6 June 1952
PLATE TARGET N	1020-11-1-12 1PG August re	. 1060	ROCK	ET
Gage 375 Class	В	HEAD: Cal.	5" T	ype Shaped Charge
Maker Carnegie				No Wt. 51.10#
No. BU277 Group		Maker		le Corp.
Dimensions 124" X 406	)"	Lot No.	RHCZ -	7-HA-52
OBLIQUITY 70°	···· <del>·</del>	Filler: Fuzes	Mk.149	0m/8 16# · No.28
PENETRATION Complete Thickness at impact		Boosters		
Thickness at impact	95		ad (as fir	ed) 51.10 <sub><math>\hat{\pi}</math></sub>
No. of impact on plate	9		(	
Dist. from nearest impag		MOTOR: Cal	L. 5 m Mk.	10 Mod 5
Dist. from near edges 550	# 91101 30H	Motor ten	₩• <u>86°</u>	Wt.88.45#
Impact area 3n x	811 0 1/21 V			
Spall: Front Ba	cks 5/2/2 f2	DONNERS RE	OUED: Mark	Mod
Spall: Front Bac Dish Spur Cracks	1-1/2"			139.55#
01-01-0		Wt. (bur	Tea)	
Punching (thrown) (star Back Button (thrown) (x	real	OTHER INFO	DMART OW	
Bulge 0	audi Auding		N: RMDA-26	7:0-51
	5 1-3/4"		N: HMUA-20	"u "u
sin and abane of	· .	LAUNCHER		ocket Launcher
	ROCKET PERF	ORMANCE Mela	• 4	
	elocity, f/s:		1702 F	Residual
Puze functioning	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	1	· · · · · · · · · · · · · · · · · · ·	·
Explosive action (High O Distance of burst behind	rder) (Low Or	der (vone	<u></u>	
Condition of recovered ro		<del></del>		
	Head was in (	REPROPERT	(IMEPPECT)	VE) condition.
	<u> </u>	22012107	120011	· · · · · · · · · · · · · · · · · · ·
REMARKS:				
		·····		
	TATE TO			
Photo No. NP9-51103	ALT Way	Signed	W Kan	land.
CONFIDE	ATION	0	m Hara	<u> </u>
CULTANTOR	MARK			F.W.Kusdorf
CONFIDE INFOR				
51.60				ORD.ENG.

		7)
· 艾德·拉拉·拉勒·特里·	U. S. NAVAL PROVING GROUD DAHLGREN, VIRGINIA	UND IMPACT NO. 40109
		IMPACT DATE 8-21-52
	A.	FG TEST NO. T-2222-1.2
OBJECTF	unctioning Test of Modif	ied Mk 1/0 Rocket Nose Tuze 8 Cl.B Plate.
<u>in</u>	5.0 Rocket Head Mk. 25 v	s Cl.B Plate.
eference: NPG   ltr. mo	L Spilte Decksagate approx/ra	dated
eference: Bull tr. (2	62 Vision of the State of the S	dated
ask Assignment No.	G. No.25-37-3142	dated 6 June 1942
n:	VPG Greent 220. 10 = 0	an a commen
PLATE TARGET		ROCKET
286 (7000	D WEAD. Col	Fra Charles Aller
250 707 01085	B HARD: CAL	Hod 1 No Wt. 51.02#
eker Garnagia ov BD277 Group		
imensions 124		
1201131 0113	Piller.	Typeast Comp & los
BLIQUITY 70°	Fuzes	Mk.149 No.29
		300,29
enetration	Bocsters	3
Thickness at impact	Boosters C Wt. of h	end (as fired) 51.02#
No. of impact on plate		
Dist. from nearest im	pact @ MOTOR: Ca	1. 5 <sup>th</sup> Mr. 25 Nod 1
Dist. from nearest im	pact o MOTOR: Ca	1. 54 Mk. 25 Nod 1 Wt.88.40
Dist. from Mear edges	pact o MOTOR: Ca and o Motor te	1. 5 <sup>H</sup> Mk. 25 Nod 1 mp. 86° Wt.88.40
Dist. from mear edges Impact area Spall: Front	Back . 9 COMPLETE R	CUMD: Mark Hod
Dist. from mear edges Impact area Spall: Front Dish Spu	Back 9 COMPLETE R	OUND: Mark Hod
Dist. from Mear edges Impact area Spall: Pront Dish Spu Cracks	Back 9 COMPLETE R T 0 Wt. (as Wt. (bur	OUND: Nark Hod
Dist. from Mear edges Impact area Spall: Front Dish Spu Cracks Punching (thrown) (s	Back 9 COMPLETE R T 0 Wt. (as tarted) 6	OUND: Mark Hod Mired) 139.429 ned)
Dist. from Mear edges Impact area Spall: Front Dish Spu Cracks Punching (thrown) (s Back Button (thrown)	Back 9 COMPLETE R  T 0 Wt. (se tarted) % (started) OTHER INFO	OUND: Mark Hod Atred) 139.42* ned) RMATION
Dist. from Mear edges Impact area Spall: Front Dish Spu Cracks Punching (thrown) (s Back Button (thrown) Bulge	Back 9 COMPLETE R T 0 Wt. (as tarted) 6	CUMD: Mark Hod Mired) 139.625 ned)  RMATION  ALN: RMDA-267-5-51
Dist. from Mear edges Impact area Spall: Front Dish Spu Cracks Punching (thrown) (s Back Button (thrown)	Back g COMPLETE R  Wt. (as Wt. (bur tarted) a OTHER IMPO	COUND: Mark Hod Marcol 139.42% ned)  RMATION ALN: RMDA-207-5-51
Dist. from Mear edges Impact area Spall: Front Dish Spu Cracks Punching (thrown) (s Back Button (thrown) Bulge	Back g COMPLETE R  Wt. (as Wt. (bur tarted) a OTHER IMPO	COUND: Mark Mod Mired) 139.42# ned)  RMATION  ALN: RMDA-207-5-51
Dist. from Mear edges Impact area Spall: Front Dish Spu Cracks Punching (thrown) (s Back Button (thrown) Bulge	Back g COMPLETE R  Wt. (as Wt. (bur tarted) 6 (started) OTHER INFO	COUND: Mark Hod Marcol 139.42* ned)  RMATION  ALN: RMDA-207-5-51
Dist. from Bear edges Impact area Spall: Front Dish Spu Cracks Punching (thrown) (s Back Button (thrown) Bulge	Back g COMPLETE R  Wt. (as  Wt. (bur  tarted) 6  (started) OTHER INFO  LAUNCHER  ROCKET PERFORMANCE	COUND: Mark Mod Mired) 139.42# ned)  RMATION  ALN: RMDA-207-5-51
Dist. from mear edges Impact area Spall: Front Dish Spu Cracks Punching (thrown) (s Back Button (thrown) Bulge Through opening	Back g COMPLETE R  Wt. (as  Wt. (bur  tarted) 6  (started) OTHER INFO  LAUNCHER  ROCKET PERFORMANCE Mean	Mark Mod Mired) 139.625  ned)  RMATION  ALN: RMDA-207-5-51  1050 Ft.Rocket Leuncher
Dist. from hear edges Impact area Spall: Front Dish Spu Cracks Funching (thrown) (s Back Button (thrown) Bulge Through opening	Back g COMPLETE R  Wt. (as  Wt. (bur  tarted) 6  (started) OTHER INFO  LAUNCHER  ROCKET PERFORMANCE Mean	Mark Mod Mired) 139.42* ned)  RMATION  ALN: RMDA-207-5-51
Dist. from mear edges Impact area Spall: Front Dish Spu Cracks Punching (thrown) (s Back Button (thrown) Bulge Through opening	Back g COMPLETE R Wt. (as Wt. (bur tarted) 6 (started) OTHER IMPO LAUNCHER ROCKET PERFORMANCE Mean Velocity, f/s: SOFFEEDER	Mark Mod Mired) 139.625 ned)  RMATION ALN: RMDA-207-5-51  1050 Ft.Rocket Leuncher
Dist. from hear edges Impact area Spall: Front Dish Spu Cracks Funching (thrown) (s Back Button (thrown) Bulge Through opening Viight Fure functioning Explosive action (High	Back g COMPLETE R Wt. (as Wt. (bur tarted) 6 (started) OTHER INFO  LAUNCHER  ROCKET PERFORMANCE Mean Velocity, f/s: SOUTHER	Mark Mod Mired) 139.625 ned)  RMATION ALN: RMDA-207-5-51  1050 Ft.Rocket Leuncher
Dist. from Mear edges Impact area Spall: Front Dish Spu Cracks Punching (thrown) (s Back Button (thrown) Bulge Through opening  Plight Dist of functioning Explosive action (High Distance of burst behind	Back g COMPLETE R Wt. (as Wt. (bur tarted) 6 (started) OTHER IMPO LAUNCHER ROCKET PERFORMANCE Mean Velocity, f/s: Seventers Order) (Low Order) (None d plate	Mark Mod Mired) 139.625 ned)  RMATION ALN: RMDA-207-5-51  1050 Ft.Rocket Leuncher
Dist. from their edges Impact area Spall: Front Dish Spu Cracks Punching (thrown) (s Back Button (thrown) Bulge Through opening Explosive action (High Distance of burst behin	Back g COMPLETE R Wt. (as Wt. (bur tarted) 6 (started) OTHER IMPO LAUNCHER ROCKET PERFORMANCE Mean Velocity, f/s: Services Urder) (Low Order) (Mone d plate round	Mired) 139.425 ned) 139.425 ned)  RMATION ALN: RMDA-207-5-51  1050 Ft.Rocket Leuncher
Dist. from Mear edges Impact area Spall: Front Dish Spu Cracks Punching (thrown) (s Back Button (thrown) Bulge Through opening Plight Dist opening Explosive action (High Distance of burst behin	Back g COMPLETE R Wt. (as Wt. (bur tarted) 6 (started) OTHER IMPO LAUNCHER ROCKET PERFORMANCE Mean Velocity, f/s: Seventers Order) (Low Order) (None d plate	Mired) 139.425 ned) 139.425 ned) 139.425 ALN: RMDA-207-5-51 L050 Ft.Rocket Leuncher
Dist. from hear edges Impact area Spall: Front Dish Spu Cracks Punching (thrown) (s Back Button (thrown) Bulge Through opening Puze functioning Explosive action (High Mistance of burst behin Condition of recovered	Back g COMPLETE R Wt. (as Wt. (bur tarted) 6 (started) OTHER IMPO LAUNCHER ROCKET PERFORMANCE Mean Velocity, f/s: Services Urder) (Low Order) (Mone d plate round	COUND: Mark Mod Mired) 139.427 ned)  RMATION ALN: RMDA-207-5-51  1050 Ft.Rocket Leuncher
Dist. from hear edges Impact area Spall: Front Dish Spu Cracks Funching (thrown) (s Back Button (thrown) Bulge Through opening Explosive action (High Distance of burst behin Condition of recovered	Back g COMPLETE R Wt. (as Wt. (bur tarted) 6 (started) OTHER IMPO LAUNCHER ROCKET PERFORMANCE Mean Velocity, f/s: Services Urder) (Low Order) (Mone d plate round	Mark Mod Mired) 139.428 ned)  RMATION ALN: RMDA-207-5-51  1050 Ft.Rocket Leuncher  1750 Residual  (IMEPFECTIVE) condition
Dist. from hear edges Impact area Spall: Front Dish Spu Cracks Funching (thrown) (s Back Button (thrown) Bulge Through opening Explosive action (Right Condition of recovered  REMARKS:	Back g COMPLETE R Wt. (as Wt. (bur tarted) 6 (started) OTHER IMPO  LAUNCHER  ROCKET PERFORMANCE Mean Velocity, f/s: Sevente d plate round Head Vas in (EFFECTIVE)	Mark Mod Mired) 139.425 ned)  RMATION ALN: RMDA-207-5-51  1050 Ft.Rocket Leuncher  1750 Residual  (IMEPFECTIVE) condition
Dist. from hear edges Impact area Spall: Front Dish Spu Cracks Punching (thrown) (s Back Button (thrown) Bulge Through opening Plight Pure functioning Explosive action (High Condition of recovered	Back g COMPLETE R Wt. (as Wt. (bur tarted) 6 (started) OTHER IMPO  LAUNCHER  ROCKET PERFORMANCE Mean Velocity, f/s: Sevente d plate round Head Vas in (EFFECTIVE)	Mired) 139.428 ned) 139.428 ned) RMATION ALN: RMDA-207-5-51 1050 Ft.Rocket Leuncher  (IREVECTIVE) condition
Dist. from hear edges Impact area Spall: Front Dish Spu Cracks Funching (thrown) (s Back Button (thrown) Bulge Through opening  Plight Explosive action (Right Distance of burst behin Condition of recovered	Back g COMPLETE R Wt. (as Wt. (bur tarted) 6 (started) OTHER IMPO LAUNCHER ROCKET PERFORMANCE Mean Velocity, f/s: Sevente d plate round Head Vas in (EFFECTIVE)	Mired) 139.428 ned) 139.428 ned) RMATION ALN: RMDA-207-5-51 1050 Ft.Rocket Leuncher  (IREVECTIVE) condition
Dist. from hear edges Impact area Spall: Front Dish Spu Cracks Funching (thrown) (s Back Button (thrown) Bulge Through opening  Plight Explosive action (Right Distance of burst behin Condition of recovered	Back g COMPLETE R Wt. (as Wt. (bur tarted) 6 (started) OTHER IMPO LAUNCHER ROCKET PERFORMANCE Mean Velocity, f/s: Sevente d plate round Head Vas in (EFFECTIVE)	Mired) 139.42# ned)  RMATION ALN: RMDA-207-5-51  1050 Ft.Rocket Leuncher  (IREV.ECTIVE) condition
Dist. from hear edges Impact area Spall: Front Dish Spu Cracks Funching (thrown) (s Back Button (thrown) Bulge Through opening  Plight Explosive action (High Condition of recovered	Back g COMPLETE R Wt. (as Wt. (bur tarted) 6 (started) OTHER IMPO LAUNCHER ROCKET PERFORMANCE Mean Velocity, f/s: Sevente d plate round Head Vas in (EFFECTIVE)	ALN: RMDA-207-5-51  1050 Ft.Rocket Leuncher  1750 Residual  (IMPLECTIVE) condition
Dist. from hear edges Impact area Spall: Front Dish Spu Cracks Funching (thrown) (s Back Button (thrown) Bulge Through opening	Back g COMPLETE R Wt. (as Wt. (bur tarted) 6 (started) OTHER IMPO LAUNCHER ROCKET PERFORMANCE Mean Velocity, f/s: Sevente d plate round Head Vas in (EFFECTIVE)	COUND: Mark Mod Mired) 139.428 ned)  RMATION ALN: RMDA-207-5-51  1050 Ft.Rocket Leuncher  (IRRESECTIVE) condition

	H, VIRGINIA
DANIE	IMPACT DATE 8-21-52
	•
• 20°	NPG TEST NC.T-2222-1.25
OBJECT Functioning Tag	t of Modified Mk 149 Rocket Nose Fuze
in 500 Rocket Head	a Mk.25 vs Cl.B Plate.
deference: NPG ltr. NOL Smaltr DP:HS	SW: de MP/30L/X1-1dated
leference: 340 tr. (2628) Ser 3438 o	of dated 6 June 1952
Pask Assignment No. NPG-Re2b-11-1-1	12 dated
PLATE TARGET NEW GROOT	ROCKET
TIME INDUST	ROCKET
lage 3n5 Class	HRAD: Cal. 5" TypeShaped Charge
laker Curnegie	Mark 25 Mod 1 No Vt. 51.42#
to. <u>TT695 Group 3-751-322</u>	Maker Houdaille Corp
Dimensions 113" X 284"	Lot No. RHCZ-7-HA-51
	Filler: Typeast Comp 1. 16#
OBLIQUITY 70°	Puzes Mk.149 No.30
ENETRATION Complete	Boosters
Thickness at impact 3.75	Wt. of head (as fired) 51.425
No. of impact on plate 1	MARON AND THE MARKET
Dist. from nearest impact	MOTOR: Cal. 5" Mr. 10 Mod 5
Dist. from near edges 166" and 61"	Motor temp. 86° Wt 89.25
Impact area 3-3/4" X 7-1/2" X Spall: Front 0 Back-1/2" A	5-COMPLETE ROUND: Nark Mod
Dish 0 Spur 2"	Wt. (as fired) 140.67#
	Wt: (burned)
Punching (thrown) (started)	
Back Button (thrown) (interted)	OTHER INFORMATION
Bulge	ALN: RMA-267-3-51
Through opening 1-1/2" X 2-1/2"	n _n _n_n
<u> </u>	LAUACHER 1050 Ft. Rocket Launcher
5.	
ROCKET PE	ERFORMANCE
	Mean
Flight Velocity, f/	/s: 3000 1773 Residual
Puze functioning Explosive action (High Order) (Low	
	Order) (NOBe)
Distance of burst behind plate	
Condition of Pecovered round	a (EFFECTIVE) (IMEFFECTIVE) condition.
Mond was 12	APPROVING (AMERICALITY CORRECTION.
REMARKS:	
1 Int.	
Photo No.	Signed F. W. Kassorif
The second second	214
COLUMN INFORMATIO	F.W. Kusdorf
SECULIFICA	OHD. ENG.
<b>*</b>	• UND • UND

	L PROVING GROUND IMPACT NO. 40111
DABLIGRI	en, virginia impact date 8-21-52
	NPG TEST NO. T-2222-1.2
OBJECT Functioning To in 5.0 Rocket Head	Mk.25 vs Cl.BPlate.
Reference: WPA 1tr	deted
Reference: BuOrd 1tr. NOL Spdltr IP	HSW:dle HP/NOT/X1_dated
EPG-Re2b-11-1	of dated 6 June 1952
PLATE TARGET NO Com	no. 1060 ROCKET
Gage 305 Class B	HRAD: Cal. 5" Type Shaped Charge Mark 25 Mod 1 No Wt.51.46# Maker Houdaille Corp. Lot No. MCZ-7-HA-51 Filler: Type Shaped Charge
Carnacia	Mark 25 Mod 1 No Wt. 51 4.6#
No. 55695 Group 3-751-322	Houdaille Corp.
113" A 384"	Riller: Type of Compyte 16
OBLIQUITY 70°	Puzes Mk.149 No.31
PENETRATION	Boosters
Thickness at impact	Wt. of head (as fired) 51.46#
Thickness at impact No. of impact on plate	
Disc. ifor neresc interce	MOTOR: Cal. 5" Mk. 10 Mod 5
Dist. from near edges and K	Motor temp. 80° Wt 89.45#
Impact area Constant Spall: Front Back Constant Spur	
Spall: Pront Back w	COMPLETE ROUND: Mark Nod_
Dish Spur	Wt. (as fired) 140.91; Wt. (burned)
Cracks	wt. (burned)
Punching (thrown) (started) © Back Button (thrown) (started)	OTHER INFORMATION
Bulge ©	والمرابع والم
Through opening	ALN: RMDA -207-3-51
tin-ordin obeatus	LAUMCHER 1050 Ft. Rocket Launcher
ROCKET P	ERFORMANCE
	Mean
Flight Velocity, f	/s: Striking 1779 Residual
Puze functioning	
	(Trder) (Nobe)
Distance of burst behind plate	
Condition of recovered round Head Vas 1	n (RPFECTIVE) (IMRFFECTIVE) condition.
Tega Age 1	n (EPPECTIVE) (IMEPFECTIVE) condition.
REMARKS: CONFIDENTIA	
Photo No. SPICE INFORMATIO	
Photo No.	Signed F. W. Kandard
	F.W.Kusdorf
	ORD. END.

v. s.	NAVAL PROVING GROUND IMPACT NO. 40112 AHLGREN, VIRGINIA
	IMPACT DATE 8-21-52
	NPG TEST NOT-2222-1,25
OBJECT Functioni in 5"0 Roc	ng Test of Modified Mk. 149 Rocket Nose Fuze ket Heud Mk.25 vs Cl.B Plate.
Reference. EDG 1th	dated
Reference: Propeyltr. (0620) c.	dated 5 June 1992
Task Assignment No	dated dated
PLATE TARGET	ROCKET
Gage 375 Class b	HEAD: Cal. 5" Type Shaped Charge
Maker Carnagia	Mark 25 Mod 1 No Vt. 51,13#
No. 17695 Group C-751-	A22 Maker Houdelile Corp.
Dimensions 117. Vien.	Pillan. Transcot County 144
OBLIQUITY 75°	HRAD: Cal. 5" Type Shaped Charge  Mark 25 Mod 1 No Wt. 51.13#  322 Maker Houdaille Corp.  Lot No. RHCZ-7-HA-51  Filler: Typeast CompMt. 16#  Fuzes Mk.149 No.32
PENETRATION Complete	Boosters
Thickness at impact (6)	5 Wt. of nead (as fired) 51.13#
No. of impact on plate	
Dist. from nearest impact	23" MOTOR: Cal. 5" Mk. 10 Mod 5 1.70" Motor temp. 86° Wt.88.80#
Dist. from Dear edges 1/2 nand	170" Notor temp. 86° Wt.88.80#
Impact area 2-1/4" x 7-1	/2"   COMPLETE ROUND: Mark   Mod   Wt. (as firsd)   139.93#   Wt. (burned)
Spall: Front O Back 3	N X COMPLETE ROUND: Mark Mod
Disk o Spur	Wt. (as fired) 139.93#
Cracks	wt. (burned)
Punching (theme) (started)	ANUDO THOODMANTON
Bulge 0	AT No. Shift A De 2 - 1 - 5
Through opening 1-1/2" X	ALN: RMDA-267-0-51
THE OREM OPERATING 1-1/2"	LAUNCHER 1050Ft. Rooket Launcher
**	TOSOFT ROCKET LAUTCHER
ROC	KET PERFORMANCE
	Mean
Flight Veloci	ty, f/a: SENIEULE 1768 Residual
Fuze functioning	
Explosive action (High Order)	(Low Order) (None)
Distance of burst behind plate	
Condition of recovered round	
Head	was in (RPFECTIVE) (INEFFECTIVE) condition.
REMARKS:	
Photo No. CONFIDEN	TIALL
Photo No.	ACION Signed 7 W Karden
SECURITY INFORM	ATION
	B.W. Kasdorf
	ORD. ENG.

TABLE I

# SUNVARY OF RESULTS


No.	1982	Fuse No.	Rooket		(ft./sec.) Obtained	<u>061.</u>	Target	Action	
1	6-23	5	Mk 6	1800	1874	00	1/8" MB	HO on Impact	
2	6-28	6	Mk 6	1800	1836	00	1/8" 18	HO on Impact	
3	6-23	7	Mk 6	1800	1837	00	1/8" MS	HO on Impact	
4	6-23	8	kk 6	1800	1.863	00	1/8" VE	HO on Impact	
				PAR	e II				
1	6-25	9	Mk 6	1800	1858	50°	1/8" 198	HO on Impact	
2	6-23	10	Mk 6	1800	1600	60°	1/8" KS	HO on Launcher	
	0-60	10	FR 0	1000			1/0 1/3	at 1012' point	
8	7-24	33	10k 6	1800	1896	60°	1/8" WS	Dud	•
4	7-24	34	Mk 6	1800	1791	50°	1/8" V3	Dud	
5	7-24	35	Mk 8	1800	1882	50°	1/4" MS	Dud	
6	7-24	36	Mk 6	1800	1311	50°	1/8" 1'8	HO on Impact	
7	7-25	37	Mk 6	1300	1297	55°	1/8 15	HO on Impact	
8	7-25	88	Vy. 6	1800	1292	ອບາ	1/8" XS	HD on Impact	:
8	7-25	39	Vk 6	1300	1296	65°	1/8" VS	HO on Impact	
10	7-25	40	Mk 6	1300	1295	70°	1/8" MS	HO on Impact	
11	7-25	11	Mk 6	1800	1923	70°	1/8" MS	HO on Impact	
12	7-28	12	Mk 6	1800	1794	75°	1/8" 38	HO on Impact	
15	7-28	13	Mk 6	1800	1795	75°	1/8" MS	HO on Impact	
14	7-28	14	Mk 6	1800	1833	75°	1/8" NS	Missed Target	
15	7-28	15	Mc 6	1800	1791	·75°	1/8" NS	HO on Impact	
16	7-28	16	Mk: 6	1800	1769	750.	1/8" MS	HO on Impact	
17	7-28	17	Mk: 6	1800	1789	75°	1/8" VS	HO on Impact	
18	7-29	18	Mk 6	. 1800	1818	750	1/4" MB	HO on Launcher	
			×	2. 6.				at 800' point	
19	7-29	19	Mk 6	1800	1826	75°	1/4" MS	HO on Impact	
20	7-29	20	Mk 6	1800	1776	75°	1/4" MS	HO on Impact	
21	7-29	21	Mk 6	1800	1818	75°	3/8" MS	HO on Impact	
22	7-30	22	Wk 6	1800	1772	75°	3/8" 1'S	HO at Launcher Mussle	

# TABLE I (Continued)


Rd.	Impact No.	Date Fired 1952	Fuse No.	Rooket Bead	Velocity Desired	(ft./sec.) Obtained	061.	<u>Target</u>	fuse Accion
					PART	111			
1	40093	8-20	28	Mk 25	1800	1732	55°	5 7/16 Clase B	EO
2	40094	8-20	24	Mk 25	1800	1386	65°	3 7/16" Class 8	
. 3	40095	8-20	25	Mk 25	1800	1698	700	3 7/16" Class B	
4	40106	8-21	26	Mk 25	1800	1693	75°	3 7/16" Class B	
5	40107	8-21	27	Vk 25	1800	1696	700	3 7/16" Class B	
6	40108	8-21	28	Mk 25	1800	1708	70°	3 7/16" Class B	BO
. 7	40109	8-21	. 29	Mk 25	1800	17.50	700	3 7/16" Class B	Dud
8	40110	8-21	30	Mk 25	1800	1773	700	3 3/8" Class B	HO
9	40111	8-21	51	MK 25	1800	1779	700	3 3/8" Class B	LO
10	40112	8-21	52	Vk 25	1800	1768	65 °	3 3/8" Class B	HO





# MARK 149 A.I.R. NOSE FUZE



SECTION "A" - "A"








- n .. n.

4 12 14 <u>.</u>..

Experimental test of Modified Mk 149 Nose Fuze in 500 Rocket Head Mk 6 SECURITI INFORMATION View: Dead catbird (weighing 1.1 ozs) suspended in rails at muzzle end of launcher to test possibility of fuze action upon impact with such an obstacle.



*		
rate - Security information containing the Modified om rd. 3. pact Dimensions Exit noe Exit x6" 2 3/4"x3" x6" 1"x1 5/8"		
CONFIDENT Heads Mk 25 resulting fr ion Entre te 2 172" te 3" te 4"		
Shaped Charge Rocket Head.  d. 2 and large spall restriction (Complete Complete Comp		
21 August 19 cts with 570 opening on r Striking Velocity ( 1732 1686 1698 Figure 6		
armor after im Note bulge behi ot Oblesias B 550 Shasa B 650		
NP9-51102 View of 3"5 Class B Mn 149 nose fuze. N Rd. No. 3 7/16" ( 2 3 7/16" ( 3 3 7/16" (		

II ON 148	
TY INFORMATION Modified Mk 145 mensions Exit 1 x 3 4"	
25 containing Impact Di Entrance 3 x8"	
WFIDE	
Rocket Head	
52 5.0 Shaped Charge triking 1702 1702	
of of Sylvanian VV	
Aug 1mp ind rigu	
af 9a 51	
Barmor plate arge spall arget 0	
Class Barmor Note large spa  Target  3 7/16" Class	THE STREET OF SHIPS AND A PROPERTY OF THE SHIPS AND A
.55	
NP9-51103 View of 3 nose fure Rd. No.	

=

Experimental test of modified Ex 149 Nose Fuze in 5.0 Shaped Charge Head Mk 25. View: Fragment resulting from Spall on the hackside of a 3.5 Class B Armor Plate on rd. 3. This biece measured 6"x5 1/2"x1/4". · Figure 4



U.S.N.P.G. DAHLGREN, VIRGINIA




FIG. 4- EXPERIMENTAL BALLISTIC TEST OF MODIFIED MK 149
ROCKET NOSE FUZE
VIEW: MOD. MK 144 FUZE IN 5.0 ROCKET HEAD MK 25 (SHAPED
CHARGE) WITH 5' HVAR MOTOR VS. 3.5 CLASS B ARMOR
PLATE AT 70° OBLIQUITY, NOTE SPALL THROWN FROM BACK
FACE DUE TO EXPLOSIVE WAVES TRANSMITTED THROUGH
PLATE ON IMPACTS ABOVE 65° OBLIQUITY.

O

CONFIDENTIAL SECURITY INFORMATION

27 AUGUST 1952

5 5

.

## DISTRIBUTION

3 4 4	Rureau of Ordnance Ad3 Re2 Re2b Re3d	1 1 2
	Re3e Re2c	i
	Chief of Ordnance Department of the Army Attn: ORDTX-AR	2
	Commanding General Aberdeen Proving Ground Aberdeen, Maryland Attn: Technical Information Section Development and Proof Services	1
	Commander, Operational Development Force U. S. Atlantic Fleet, U. S. Naval Base Norfolk 11, Virginia	2
	Navy Research Section Library of Congress Washington 25, B. C. (via BUORD Re2b)	2
	Chief of Ordnance Department of the Army Attn: CRDTQ	1
,	BUAER Attn: Armament Section	2
	NATC, Patuxent River, Maryland	3
	Naval Linison Officer USAFPGC, Eglin Field, Florida	ì
,	NOTS, Inyokern, California	- <b>1</b>

CONFIDENTIAL SECURITY INFORMATION

APPENDIX D

## CONFIDENTIAL

#### NPG REPORT

Experimental Ballistic Test of Mcdified Mr 149 Rose .

# DISTRIBUTION (Continued)

U. S. Air Force AMC Engineering Field Office Room 1833, Main Navy Building Navy Department, Washington, D. C.	 2
Commander (DF) Naval Ordnance Laboratory (Fuzes)	3
NOP, Macon, Georgia	1
Picatinny Arsenal Dover, New Jersey	1
NOTS, Inyokern, California Rocket Reports	 1
Chief of Ordnance, Department of the Army Attn: ORDIU	1
Commanding General Air Force Armament Center Eglin Air Force Base, Florida Attn: Technical Library	1
Local: OF OV Pile	1 1 1