#### UNCLASSIFIED

ΑТ	\ N	TT	TT	ID.	$\Box$
AI	<i>)</i>	V	ЛV	חו	ER

#### AD866982

#### LIMITATION CHANGES

#### TO:

Approved for public release; distribution is unlimited. Document partially illegible.

#### FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors;

Administrative/Operational Use; 01 NOV 1969. Other requests shall be referred to Assistant Chief of Staff for Force Development (Army), Attn: FOR-OT-UT, Washington, DC 20310. Document partially illegible.

#### **AUTHORITY**

AGO D/A ltr, 29 Apr 1980

THIS REPORT HAS BEEN DELIMITED

AND CLEARED FOR PUBLIC RELEASE

UNDER DOD DIRECTIVE 5200.20 AND

NO RESTRICTIONS ARE IMPOSED UPON

ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.

# Best Available Copy



S

99

# DEPARTMENT OF THE ARMY OFFICE OF THE ADJUTANT GENERAL WASHINGTON, D.C. 20310

IN REPLY REFER TO

AGDA (M) (26 Feb 70) FOR OT UT 694050

12 March 1970

SUBJECT. Operational Report - Lessons Learned, Headquarters, 11th Transportation Battalion, Period Ending 31 October 1969

SEE DISTRIBUTION

1. Subject report is forwarded for review and evaluation in a pridative with paragraph 4b, AR 525-15. Evaluations and corrective actions should be reported to ACSFOR OT UT, Operational Reports Branch, within 90 days of receipt of covering letter.

2 Information contained in this report is provided to insure appropriate benefits in the future from lessons learned during current operations and may be adapted for use in developing training material.

BY ORDER OF THE SECRETARY OF THE ARMY:

1 Incl

as

ROBERT E. LYNCH

Colonel, MC

Acting The Adjutant General

DISTRIBUTION:

Commanding Generals

US Continental Army Command

US Army Combat Developments Command

US Army Materiel Command

Commandants

US Army War College

US Army Command and General Staff College

US Army Armor School

US Army Engineer School

US Army Field Artillery School

US Army Infantry School

US Army Ordnance School

Deputy Chiefs of Staff

US Army Transportation School

Office, Chief of Staff, US Army

Protective marking cancelled when separated from inclosure.

UNCLASSIFIED REPORT

DISTRIBUTION NO FOREIGN WITHOUT APPROVAL OF ASSISTANT CHIEF OF STAFF FOR FORCE DEVELOPMENT (ARMY) ATTN FOR OT UT. WASHINGTON, D.C. 20310

Reproduced by the CLEARINGHOUSE for Federal Scientific & Technical Information Springfield Va. 22151

Copies furnished:

FOR OFFICIAL USE ONLY

22

# DEPARTMENT OF THE ARM/ Headquarters, 11th Transportation Battalion (Terminal) APO 96384

AVCA SGN TC XE S3

1 November 1969

SUBJECT:

Operational Report-Lessons Learned 11th Transportation Battalion (Terminal) Period Ending 31 October 1969, RCS CSFOR - 65 (R2)

THRU:

Commanding Officer
4th Transportation Command (Tml C)
ATTN: AVCA SGI TC GCPT
APO 96243

Commanding General
US army Support Command, Saigon
ATTN: AVCA SGN GO
APO 96491

Commanding General 1st Logistical Command ATTN: AVCA SGN GO O APO 96384

Deputy Commanding General United States Army, Vietnam ATTN: AVHGC DST APO 96375

Commander in Chief United States Army, Pacific ATTN: GPOP-OT APO 96558

TO:

Assistant Chief of Staff for Force Development (ACSFOR)
Department of the Army
Washington, D.C. 20310

#### 1. Section 1. Operations: Significant Activities.

On 1 August 1969 CPT James M. Starling assumed command of the 402nd Transportation Company (TT).

On 2 August 1969, The Asbury Victory was moored at Cat Lai Buoy three. The buoys were out of alignment, but this was the only available berth. The FCR OT UT

694050 Inclosure

FOR OFFICIAL USE ONLY

Protective marking is excluded from automatic termination (Para 18, AR 345-15).

AVCA SGN TC XB 83

SUBJECT: Operational Report-Isosons Loamer. 1911. Lengton of Battalion (Terminal) Period Ending 51 October 1913, ECS OSF No. 5 (D2)

malalignment of the buoy was compounded by a 12 - 14 knot tidal current running abeam of the vessel, causing an extreme strain on the moorang lines. Five lines were used both fore and aft to secure the vessel. At approximately 2235-hrs, 2 Aug, the ship broke loose from the stern (upriver) buoy and swung around with the outgoing tide. The ship was swung back and resecured with six lines aft at 0830, 3 Aug. At approximately 1210 hrs, 3 Aug, the stern lines parted again and the ship swung with the outgoing tide. The CO 11th Trans. Bu recommended that the vessel master move downviver and drop anchor, however the vessel master would not move the ship without a pilot. The vessel swung with the tide until 0800, 4 Aug when the pilot arrived. It took approximately 12 hrs to unfoul the ship's anchor from the buoy chain and an additional gift to move downriver to a safe anchorage.

On 5 August 1969, the ABCT tug Seminole arrived in Cat Lai Harbor with barge BC6481, loaded with 421 short tons of ammunition. The tug boat did not check in with operations personnel but merely left the barge at the buoy. Operations personnel saw the barge being left and went to invertigate. Unon arrival at the location, it was discovered that the targe was listing to one side, that the barge was not secured, and that all the cargo had shifted. The list was due to a hole in the barge. The barge was placed alongside of hatch no. 3 of the Asbury Victory, and the cargo was cross-loaded onto another barge. The operation required two stevedore gangs, employed at extra labor rates, and took 41 hrs and 45 min to complete. This cross-loading also caused delay in the discharge of the Asbury Victory. The water was pumped out of BC6481, bringing the hole above the water line until the barge could be reprired.

On 7 August 1969, the downriver buoy at Cat Lai was raised and repaired. This buoy had sunk on 31 July 69 immediately after the Occidental Victory had been secured to it. A five inch hole was discovered in the top of the ency which had apparently been caused by a sharp object, disproving the theory that it had been punctured by a tugboat.

On 7 August 1969, the 1099th Transportation (ormany (MB) brought its deadline rate down to zero when a t ton vehicle was returned from field maintenance.

On 7 Fugust 1969, the LCM 8195 was turned over to Harbor Craft Company (Provisional) for use as a floating barge repair facility.

On 11 August 1969, the 402nd Transportation Company (TT) received its annual 1st Log CMMI. The company was rated ursatisfactory with a 68% overall score.

On 12 August 1969, at approximately 0200 hrs, two (2) 107mm rockets were fired into Cat Lai Harbor. One round landed harmlessly in the water; however the second round hit the <u>Kimbro Victory</u> which was berthed at Cat Lai one. The round pierced the ship and exploded inside hatch four Which was empty. Other hatches were loaded with ammunition. Major Abernathy, CMAC Arty, examined the

2

AVCA SGN TC XB S3

1 November 1969
SUBJECT: Operational Report-Lessons Learned 11th Transportation Battalion
(Terminal) Period Ending 31 October 1969, RCS CSFOR - 65 (R2)

vessel, compared information with reports from flash observation towers, and determined that the rocket was fired from a patch of nipa palm approximately 100 - 200 meters from the east wall of the Cat Lai Compound. MAJ Thuong, Sensitive Area Commander at Cat Lai, called a security meeting on 14 August 1969 and the situation was discussed. It was decided that the nipa palm should be burned or cut down from the area where the rockets were fired. This has since been accomplished.

On 12 August 1969, four ICM-8s returned to Cat Lai from a supply mission to the 277th Supply and Service Battalion located at Tay Ninh. Each boat hauled a 12 ton S&P trailer loaded with cargo. This was the second commitment to this area for boats from the 1099th Transportation Company (MB). There were no enemy contacts during either trip.

The dolphins at Alpha Pier Cogido Barge Site, were completed on 14 August 1969 and the pier was immediately put into use.

On 15 August 1969, the Cogido Barge Site received several small arms rounds. These caused a temporary halt in operations.

On 19 August 1969, a class on marihuana and drugs was given to 35 officers and key NCOs of the 11th Trans Bn (Tml) by a CID team. Graphic demonstrations by the CID experts gave the interested audience a clearer picture of the hazards of various narcotics. Major areas of discussion included leagal search, source and effects of marihuana, and recent marihuana rulings by the Military Court of Appeals.

On 22 August 1969 local national stevedores staged a sit-down strike at 1400 hrs at Cogido. Stated reason for this was that "the work is too dangerous." Negotiations with the group failed to resolve the problem. They were told to go back to work or they would be fired. Three of the fouteen returned to work. The rest were informed they would be fired.

On 21 August 1969, the LCM 18 received from two to six AK47 rounds from the river bank just south of Cal Lai Harbor. There was no damage.

On 1 September 1969, security lights powered by a 5 kw generator were installed on the island at Cogido. The CO of the 402nd TC acted on suggestion of LTC McLean (4th TC PM) that lights on this small island would substantially improve the waterfront security at this critical barge site.

On 2 September 1969, Mr Toyama, Saigon Support Command, initiated crane operations and maintenance classes in the 402nd Transportation Company area. This will result in a sufficient number of crane operators trained, licensed, and maintenance oriented.

On 3 September 1969, the LCM-14 became stuck on a sandbar in the vicinity of

AVCA SGN TC XB S3

1 November 1969
SUBJECT: Operational Report-Lessons Learned 11th Transportation Eattalion
(Terminal) Period Ending 31 October 1969, RCS CSFOR - 65 (R2)

VC Island as it was hauling a load of ammunition from Cat Lai to the Cogido Barge Site. A PBR also got stuck as it tried to extricate the ICM. Adequate security was provided for the crafts and they remained mired in the mud until the tide came in six hours later. The ICM-14 was damaged in efforts to pull it off the bar as a three inch hole was torn in the boat.

On 4 September 1969, the new operations building at Cat Lai was completed and officially accepted by COL Stendeback, 4th TC DCO and LTC Shannon, CO 11th Trans Bn, who assisted the DCO in cutting the red ribbon in a Grand Opening Ceremony.

On 5 September 1969, the 402nd Trans Co created a railhead discharge platoon in order to handle the increased rail shipments from Saigon to Ho Nai.

On 5 September 1969, the MHE section of the 402nd Trans Co moved from the company area to the Cogido Barge Site, resulting in better maintenance supervision of MHE at Cogido.

The CO, S2, and S3 of the 11th Trans Bn attended a meeting at Gia Dinh Province Hq on 6 September 1969. The subject of the meeting was the security of Cat Lai and Nha Be. The assemblage consisted of district representatives, sensitive area commanders, advisors, and other interested persons. The main point discussed was that Sensitive Area Commanders are not given the authority to carry out the responsibilities they are charged with. Civilian police, Vietnamese Army, VN Navy, US Army, and US Navy are operating as individual units and are not properly supporting the Sensitive Area Commander. Ifinutes of the meeting were forwarded to CMAC HQ for consideration and necessary action.

On 7 September 1969, at approximately 2000hrs one Cat Lai based US Sailor was KIA and one was WIA. They had been traveling by jeep on Cat Lai road when they were ambushed by five or six Viet Cong. The ambush had been laid using a claymore mine supported by rockets and small arms. The claymore missed; however they were hit by two RPG rockets, kneeking their jeep off the road into a rice paddy. One man was killed outright and the other was shot by the VC, but by playing dead while the enemy took his wallet, he lived through the ambush. Additional sightings of VC along Cat Lai road have consed the battalion to require all US military personnel at Cat Lai traveling on the road to wear a steel pot and flak jacket. Additionally, travel is restricted to daylight hours.

On 8 September 1969, at the Binh Hoa Barge Site, while off loading 250 lb bombs, a 20 ton truck mounted crane toppled from the pier into the river.

At 0215 hours on 8 September 1969, a Vietnamese crewman fell off the ST 2153 while securing a barge to buoy #1 at Cogido. In the search for his body, a helicopter hit some power lines and fell into the river resulting in the loss of another life.

On 8 September 1969, the 33rd Ranger Battalion (Vietnamese) encountered a VC force of 5 soldiers in the area where a US Jeep was ambushed on 7 September. One VC was killed and four escaped. One AK-47 and two B-40 rocket launchers were captured. Map of ambush plan was found.

On 9 September 1969, eight VC with weapons were spotted 2500 meters from the Cat Lai Compound. A sweep of the area resulted in negative contact.

On 15 September 1969, the new Cat Lai Dunnage Pier was officially accepted by MAJ McBurney, 11th Trans Bn XO, from CPT Soldel, 30 41st Engineer Company (Port Construction).

On 16 September 1969, a young Victnamese was shot in the leg as he attempted to steal lumber from a train at Ho Nai Railhead. The youth failed to halt or heed warning calls and shots. Efforts are being made to improve conditions at this civilian railhead. The US area will be fenced off.

On 17 September 1969, the 11th Trans En obtained clearance to test fire weapons on VC Island. An LCM-8 was dispatched and twenty-three (23) new personnel fired their weapons for familiarization.

Thunderstorms hit the 402nd Transportation Company (TT) on 23 September 1969. Two buildings were damaged but no one was injured.

A Victnamese railway engineer was shot at Ho Nai Railhead on 25 September 1969 after he failed to heed warning calls and shots. He was stealing Budweiser Beer. Efforts are being increased to provide better security for the site and thus prevent further incidents.

On 26 September 1969, a Swimmer Sapper Class was conducted at Cat Lai by LT COMDR Costello, 1st Log FM office. The highlight of the class was a demonstration in which a sapper, completely undetected, tied a false charge to the barge carrying local dignitaries.

At approximately 2300 hrs, 26 September 1969, the Clarksburg Victory broke loose from the stern (upriver) mooring buoy of Cat Lai Two, five lines having parted for no apparent reason. The ship swing around on the bow (downriver) mooring buoy and the anchor was dropped to prevent losing the ship should the bow lines have parted. The ship was swinging around with the incoming tide and was resecured early in the morning on 27 September. At 0945, 27 September the ship broke loose again from the stern buoy. It appeared that the upriver buoy was pulled from its I cation but it is not known whether it happened the first or the second time the ship broke loose. The ship was moved to a location downstream of Cat Lai Four at 1500 hours, 27 September and was worked while swinging from the hook with no further incidents.

On 3 October 1969, the long awaited and much needed water barge arrived at

### FOR OFFICIAL USE ONLY

NOT REPRODUCIBLE

AVCA SGN TC XB S3

1 November 1969
SUBJECT: Operation Report-Lessons Learned 11th Transportation Battalion
(Terminal) Period Ending 31 October 1969 RCS CSFOR - 65 (R2)

Cat Lai. Previously the only source of water supply for the 11th Transportation Battalion had been a 5,000 gallon tanker.

10 pallet jacks were received at Cat Lai on 3 October 1969. These will be used in areas on ships where electric forklifts cannot maneuver.

On 3 October 1969, there was another vehicle shot at on Cat Lai road. One round went through the windshield of a truck belonging to the 402nd Transportation Company. Another round was fired at the rear of the vehicle as it sped by.

On 3 October 1969, two LCM-8s of the 1099th Transportation Company (Medium Boat) were committed for riverine insertion extraction operations with 3rd ARVN Ranger Units conducting sweeps on VC Island.

The ammunition handling system advanced one step towards automation on 3 October 1969 with the use of preprinted tally forms.

On 4 October 1969, an ARVN  $2\frac{1}{2}$  ton truck was destroyed and one ARVN received a wound in his chest, the results of an ambush on Cat Lai road.

From 6 through 10 October 1969, HHD, 124th Trans Co (TS), and 1099th Trans Co (MB) were inspected by the Inspector General, US Army Support Command, Saigon. All three companies passed the AGI with flying colors.

On 6 October 1969, a survey was held at Cat Lai to determine if sentry dogs could be used in Cat Lai Harbor to bolster security. Recommendation was that dogs could not be used effectively on barges because of the danger of moving around with a trainer. Sentry dog must be on a leash.

Another vehicle was fired at on Cat Lai road on 7 October. This time it was a Navy vehicle. No damage or injuries resulted.

On 9 October 1969, the ST 2109 was ambushed on the Dong Nai river as it was pulling the daily ammunition tow from Cai Lai to Cogido barge site. Two rocket rounds hit the vessel and five soldiers were injured. Two hours after the ambush, two VC surrendered to US soldiers. They voluntarily turned in one M-14 rifle.

On 14 October 1969, the three hour defensive driving course was completed. 175 men participated and were trained, the total number eligible.

There was a strike by drivers of Peril Trucking Company on 15 and 16 October 1969. This caused a delay in cargo movement at the Ho Nai Railhead where these trucks are utilized.

On 17 October 1969, the 402nd Transportation Company (TT) passed the 1st Log

AVCA SGN TC XB S3 ! November 1969
SUBJECT: Operational Report-Lessons Learned 11th Transportation Battalion
(Terminal) Period Ending 31 October 1969 RCS CSFOR - 65 (R2)

CMMI reinspection.

On 21 October 1969, HHD 11th Transportation Battalion (Tml) passed the 1st Log CMMI reinspection in maintenance management with a score of 93.

On 22 October 1969, the 1099th Transportation Company (Medium Boat) supported various infantry units by providing transportation in the winding waterways of the Mekong Delta. Units supported were the 1st Infantry Division, 82nd Airborne Division, 3rd ARVN Ranger Group, 5th ARVN Ranger Group, 6th ARVN Ranger Group, and Thu Duc Regional Forces.

The battalion's attached medical detachment treated 1,055 Vietnamese during this reporting period. This is one of our major ways of establishing good relations with the Vietnamese people. However, on 15 October the doctor assigned to the detachment was reassigned. This leaves the 11th Battalion without the services of a MD.

- 2. Section 2, Lessons Learned: Commander's Observations, Evaluations, and Recommendations.
  - a. Personnel.
  - (1) Personnel Utilization.
- (a) OBSERVATION: Recent personnel turnover has resulted in overages in some MOSs and shortages in other MOSs. To maintain mission efficiency, personnel have had to be cross-trained or trained on-the-job to fill shortage areas. Selection of those personnel for cross-training or on-the-job training has included personal, informal interviews and subsequent placement in accordance with individual desires to the maximum extent possible. These personal interviews coupled with frequent visits to job sites have shown that most of these personnel perform best in job areas they have requested.
- (b) EVALUATION: In maintaining mission efficiency, individual desires are an important consideration when, because of MOS imbalances, personnel must be trained on the job or cross-trained.
- (c) RECOMMENDATION: That Commanders conduct personal, informal interviews and assign personnel in accordance with individual desires when MOS imbalance situations exist.
  - (2) Enlisted Promotions Versus Morale.
- (a) OBSERVATION: Enlisted promotions to E4 and E5 prior to 31 August 1969 were extremely sparse. During September and October 1969, there were enough allocations made available to promote all personnel to the grades of

AVCA SGN TC XB S3

1 November 1969
SUBJECT: Operational Report-Lessons Learned 11th Transportation Battalion
(Terminal) Period Ending 31 October 1969, RCS CSFOR - 65 (R2)

E4 and E5 that were eligible and recommended. Prior to the influx of these allocations, morale had dropped to a very low state, job performance began to deteriorate, and a "don't care" attitude was emerging. After the promotion of deserving individuals in September there was an immediate change in attitude and job performance, and morale increased. Promotions received in October produced the same results, but, to a greater degree.

- (b) EVALUATION: Morale is directly affected by lack of promotions.
- (c) RECOMMENDATION: That action be taken to insure a steady flow of promotion allocations rather than a long period with none and then a large number.
  - b. Intelligence. None.
  - c. Operations.
  - (1) Sinking of Buoys in Cat Lai Harbor.
- (a) OBSERVATION: On 31 July 1969, a buoy located in the southern end of Cat Lai Harbor sank. The buoy, typical of the type used at Cat Lai, was hollow and it sank after being punctured by a sharp object.
- (b) EVALUATION: Raising and repairing sunkon buoys is time consuming and very expensive.
- (q) RECOMMENDATION: All buoys should be filled with styrofoam so that they will not sink when punctured.
  - (2) Use of Kenner Ski Barges.
- (a) ICM-8s are being used in Cat Lai Harbor at night to provide security for buoys and ammunition laden barges. This practice became necessary due to the increase in sapper activities and the fact that the 11th Transportation Battalion (Tml) did not have any other floating craft to use for security. Adequate MT support could not be obtained. Recently two Kenner Ski Barges have been acquired and have replaced three ICM-8s in the harbor. These barges are highly mobile and are highly effective when used in harbor patrols.
- (b) EVALUATION: Kenner Ski Barges can be successfully utilised on harbor patrols.
- (c) RECOMMENDATION: Kenner Ski Barges should be used whenever possible to replace floating craft that are being used to provide security for harbors in the Republic of Vietnam.
  - (3) Well Deck Barres.

AVCA SGN TC X8 S3

1 November 1969

SUBJECT: Operational Report-Lessons Learned 11th Transportation Battalion
(Terminal) Feriod Ending 31 October 1969, RCS CSFOR - 65 (R2)

- (a) OBSERVATION: During the monsoon season, well deck barges fill with rainwater and become liabilities. US Coast Guard requirements are such that well deck barges may not be loaded with ammunition if water in them will touch the cargo. Electric forklifts cannot be used in these barges because the exposure to water causes loss of traction and shorting of electrical components. Considerable man-hours and tug boat time are lost trying to pump out the water. Ammunition is still subject to damage even if these barges are loaded when dry as the next rain will usually fill the wells to a point where the bottom layer of cargo is resting in water.
- (b) EVALUATION: Well barges are impractical and expensive for ammunition and other cargo subject to water damage in monsoon areas.
- (c) RECOMMENDATION: That flat deck barges be used for ammunition and other cargo subject to water damage.
  - d. Organization. None.
  - e. Training.
  - (1) Swimming Ability.
- (a) OBSERVATION: Many personnel of this unit working on or near the river were unable to swim. Mandatory swimming lessons were recently begun to train nonswimmers with the ultimate goal being prevention of drowning accidents. The lessons are well received by the majority of those personnel participating as they realize this ability could save their lives in the future.
- (b) EVALUATION: Swimming ability is important and can be taught with relative ease to most nonswimmers if properly presented.
- (c) RECOMMENDATION: All personnel who work on or near water be given swimming tests and nonswimmers be given lessons.
  - f. Logistics.
  - g. Communications. Nono.
  - h. Material. None.
  - i. Other.
  - (1) Bunker Construction.
- (a) OBSERVATION: Bunker walls erected so that upright braces are on the outside of the boards used for fill retention are considerably stronger and longer lasting than those walls constructed by nailing fill retention boards to the outside of upright braces.

AVCA SGN TC XB:S3 1 November 1969 SUBJECT: Operational Report-Lessons Learned 11th Transportation Battalion (Terminal) Period Ending 31 October 1969, RCS CSFOR - 65 (R2)

- (b) EVALUATION: During heavy rain, the dirt fill used in most bunker walls soaks up considerable water. This water-soaked dirt expands and seriously tasks the holding ability of nails if the fill retention boards are fitted outside the upright braces. When the fill retention boards are nailed on the inside, the upright braces gain considerable additional support.
- (c) RECOMMENDATION: That bunker designs be changed to fit the fill retention boards inside the upright braces.

#### (2) Vehicle Rusting.

- (a) OBSERVATION: It has been observed that the floors are rusting out in our t ton trucks, utility. There are two reasons for this. First, all vehicles are washed in the Dong Nai River which has a high salt content and secondly, all vehicles have make shift floor mats in them which tend to trap this salt water between the mat and the metal flooring.
- (b) EVALUATION: A combination of moisture and salt water causes vehicles to rust.
- (c) RECOMMENDATION: All floor mats and rugs be removed from military vehicles in high moisture zones.

3 Incl

as

WILLIAM J. SHANNON

Man

LTC, TC Commanding AVCA SGN TC GCPT(31 Oct 69) lst Ind SUBJECT: Operational Report of the 11th Transportation Battalion for Period Ending 31 October 1969 RCS CSFOR-65 (R2)

DA, HQ, 4th Transportation Command (Tml C), APO 96243

17 Nov 69

TO: Commanding Officer, US Army Support Command, Saigon, ATTN: AVCA SGN GO, APO 96491

- 1. The Operational Report of the 11th Transportation Battalion for Period Ending 31 October 1969 RCS CSFOR-65 (R2) is forwarded in accordance with USARV Reg 525-15.
- 2. Section 2, Item a, Para (1), PERSONNEL UTILIZATION: This headquarters is aware of the MOS problem in each unit, at the present time. Each man is interviewed before any assignment is made. In this way each man is placed in a position best suited to his abilities. Then, the process of on-the-job training is started, so as to make each man as efficient as possible in his new MDS. At the present, and in the future, this headquarters, will place a greater amount of attention toward the OJT Program, so as to maintain mission efficiency. This headquarters sees no chance of this problem being resolved in the near future, due to the great amount of turn-over within RVN.
- 3. Section 2, Item a, Para (2), ENLISTED PROMOTIONS VERSUS MORALE: This headquarters understands the direct effect promotions have on morale, but we have no control over incoming allocations. Allocations are allotted to units by vacancies within the unit. Also, DA has overall control of promotions, so as to keep each MOS, per grade, at a given level Army wide.
- Section 2, Item c, Para (2) concur.
- Section 2, Item c, Para (3) concur.

FOR THE COMMANUER:

TEL: Tiger 3735

with 14+Abi MAJ, AGC

Adjutant General

AVCA SGN GO S (1 Nov 69) 2d Ind SUBJECT: Operational Report - Lessons Learned, 11th Transportation Battalion, Period Ending 31 October 1969, RCS CSFOR (R2)

HQ, US Army Support Command, Saigon, APO 96491 9 DEC 1969

- TO: Commanding General, 1st Logistical Command, ATTN: AVCA GO-MH,
- 1. Reference Section 2, paragraph c(1), page 8. NONCONCUR. The cost of modifying all buoys could not be amortized. More attention should be paid to mooring procedures to prevent collision.
- 2. Reference Section 2, paragraph c(2), page 8. CONCUR with the use of Kenner Ski Barges or Boston Whalers for harbor patrol craft. The use of these smaller craft allows LCM-8s to be utilized for their intended purpose of cargo transport. The 485th Trans Co had insufficient PBRs for security in the Cat Lai Harbor (1-PBR day, 2 PBRs night). The 11th Trans Bn is supplementing this over all security with Kenner Ski Barges. These craft are excellent for close in security around barges
- 3. Reference Section 2, paragraph e, page 9. CONCUR. The Civilian Safety Director 4th TC has implemented a program of swimming training
- 4. Reference Section 2, paragraph i(1), page 9. Unfortunately the construction of bunkers vary widely throughout RVN and their design is mainly based upon the types of construction material available. CONCUR with the use of upright braces on the outside of bunkers. Additionally, units should contact their local engineer to determine the best possible use of materials available.
- 5. Lessons Learned, observations and recommendations are concurred in by this command with the above exceptions. A copy of this indorsement has been furnished the originating and 1st Indorsing headquarters.

FOR THE COMMANDER:

TEL: LEN 2604

CPT AGC

ASST AG

AVCA GO-MH (1 Nov 69) 3d Ind SUBJECT: Operational Report - Lessons Learned of the 11th Transportation Battalion for period ending 31 October 1969 RCS CSFOR-65 (R2)(U)

- DA, Headquarters, 1st Logistical Command, APO 96384 7 JAN 1976
- TO: Commanding General, United States Army, Vietnam, ATTN: AVHGC-DST APO 96375
- 1. The Operational Report Lessons Learned submitted by Headquarters, 11th Transportation Battalion for the quarterly period ending 31 October 1969 is forwarded.
- 2. Pertinent comments follow:
- a. Reference item concerning enlisted promotions versus morale, page 7, paragraph a(2). Concur. However, the even flow of allocations cannot be controlled at this level because allocations are received from HQ, USARV and are distributed to the SUPCOM's IAW AR 600-200.
- b. Reference item concerning sinking of buoys in Cat Lai harbor, page 8, paragraph c(1). Concur. The concept appears feasible, however some buoys (lighted or sound) have machinery or equipment working spaces within the buoy that would have to be kept clear. This would provide another use for excess styrofoam generated during unpacking operations. However, closer attention to navigation and prevention of damage to buoys should be emphasized. This headquarters sent a message on this subject to all support commands on 8 December 1969 reaffirming the Coast Guard's concern for damaged navigational aids.
- c. Reference item concerning well deck barges, page 8, paragraph c(3). Concur. 11th Trans Bn has undertaken a vigorous program of "Red Lining" barges to purge the ammunition system of the well deck HF and IC type barges. The intent is to place this type barge off hire and retain primarily BC and IO barges for ammunition. This depends on the cargo pack being suitable for open storage. The system is currently using mostly open deck barges and experiencing little difficulty during the dry season. No adverse effects are expected during the monsoon season.
- 3. Concur with the basic report as modified by this and previous indorsements.

AVCA GO-MH (1 Nov 69) 3d Ind SUBJECT: Operational Report - Lessons Learned of the 11th Transportation Battalion for period ending 31 October 1969 RCS CSFCH-65 (R2)(U)

FOR THE COMMANDER:

TEL: LBN 4839

CF: USASUPCOM, SGN 4th Trans Comd 11th Trans Comd Monus P. Aufler THE Social D. STAFFORD

1Lt. AGC
Asst Adjutant General

AVHGC-DST (1 Nov 69) 4th Ind SUBJECT: Operational Report-Lessons Learned 11th Transportation Battalion (Terminal) Period Ending 31 October 1969, RCS CSFOR-65 (R2)

HEADQUARTERS, UNITED STATES ARMY, VIETNAM, APO San Francisco 96375 7 1 14% (1979)

TO: Commander in Chief, United States Army, Pacific, ATTN: GPOP-DT, APO 96558

1. This headquarters has reviewed the Operational Report-Lessons Learned for the quarterly period ending 31 October 1969 from Headquarters, 11th Transportation Battalion (Terminal) and comments of indorsing headquarters.

#### 2. Comments follow:

- a. Reference item concerning "Enlisted Promotions versus Morale", page 7, paragraph 2a(2); 1st Indorsement, paragraph 3, and 3d Indorsement, paragraph 2a; concur. This headquarters is aware of direct effect promotions have on morale. However, allocations are determined by the Department of the Army based on Army wide strength projections. Allocations received are distributed to the field by this headquarters in proportion to cumulative vacancies and personnel eligible for promotion.
- b. Reference item concerning "Bunker Construction", section II, page 9, paragraph 2i(1), and 2d Indorsement, paragraph 4; concur. This is standard construction practice in RVN. No action by higher headquarters is required.
- c. Reference item concerning "Vehicle Rusting", page 10, paragraph 2i(2); concur. Floor mats and rugs may be removed from vehicles when deemed necessary by the local commander. In addition, the metal flooring of vehicles should be rinsed with fresh water after operation in or near salt water when practicable.

FOR THE COMMANDER:

MAJ. AGC.

Assisiant Adjutant General

Cy furn: 11th Trans Bn 1st Log Comd GPOP-DT (1 Nov 69) 5th Ind

SUBJECT: Operational Report of HQ, 11th Transportation Battalion (Terminal)
for Period Ending 31 October 1969, RCS CSFOR-65 (R2)

HQ, US Army, Pacific, APO San Francisco 96558 29 JAN 70

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D.C. 20310

This headquarters concurs in subject report as indorsed.

FOR THE COMMANDER IN CHIEF:


C. L. SHORTT CPT, AGC AVCA SGN TC XD 53

1 November 1969

SUBJECT: Operational Report-Lessons Learned 11th Transportation Battalion

(Terminal) Period Ending 31 October 1969 RCS CSFOR - 65 (R2)

11th Transportation Battalion (Terminal) Organizational Structure



AVCA SGN TC XB S3

1 November 1969
SUBJECT: Operational Report-Lessons Learned 11th Transportation Battalion
(Terminal) Period Ending 31 October 1969, RCS CSFOR - 65 (R2)

11th Transportation Battalion (Terminal) Cargo Movement Summary

MONTH	SITE	DISCHARGED	BACKLOADED	TOTAL
August	Cat Lai	52064 S/T	0	52064 S/T
	Cogido	31839 S/T	172 S/T	32011 S/T
	Binh Hoa	6208 S/T	474 S/T	6682 S/T
	TOTALS:	90111 S/T	646 S/T	90757 S/T
September	Cat Lai	49799 S/T	545 S/T	50344 S/T
	Cogido	31038 S/T	1553 S/T	32591 S/T
	Binh Hoa	4915 S/T	139 S/T	5054 S/T
	TOTALS:	85752 S/T	2237 S/T	87989 S/T
October •	Cat Lai	59060 S/T	0	59060 S/T
	Cogido	37691 S/T	624 S/T	38315 S/T
	Binh Hoa	5076 S/T	0	5076 S/T
	TOTALS: 1	.01,827 S/T	<b>624</b> S/T	.102;451 S/T
GRAND TOTAL:	2	277,690 S/T	3507 s/T	281,197 S/T

ANDA SCN TO XB \$3

1 Nevember 1969

SUBJECT: Operational Report-Lessons Learned 11th Transportation Battalion
(Terminal) Period Ending 31 October 1969, RCS CSFOR - 65 (R2)

#### 1099th Transportation Company (Medium Boat)

#### Cargo and Personnel Movement Summary

	AUGUST	SEPTEMBER	OCTOBER
Personnel:	2,605	2,788	2,835
General Cargo:	2,158 tons	2,085 tons	2,058
S/T Ammunition:	27	27	20

Greatly charactic state of little. Body of abstract and industrial most be construct that the context open the context of th	DOCUMENT CONTROL DATA - R & D				
HQ, OACSFOR, DA, Washington, D.C. 20310  FOR OFFICIAL USE ONLY a. new Protective marking is sexcluded from automatic termin ation.  Operational Report - Lessons Learned, HQ, 11th Transportation Battalion  4. Datemetry Notes of unit engaged in counterinsurgency operations. 1 Aug 69 to 31 Oct 69.  EXPERIENCES of unit engaged in counterinsurgency operations. 1 Aug 69 to 31 Oct 69.  CO, 11th Transportation Battalion  F. REPORT USES  I NOVEMBER 1969  22  STA. TOTAL NO. OF PASES  A. NO. OF REFS  22  A. ONCEPTION NO.  A. PROJECT NO.  B. OFFICIAL USE ONLY a. new Protective marking is action.  Operational Use of Counterins and Counterins and Counterins at Counterins and Counte	(Security classification of title, body of abstract and indusing annualion must be entered when the overall report is classified)				
AND POWER TATE  A REPORT VILE  A REP	I ORIGINATING ACTIVITY (Corporate author)				
Excluded from Automatic termin ation.  Operational Report - Lessons Learned, HQ, 11th Transportation Battalion  * Observer notes (Type of report and includers doing)  Experiences of unit engaged in counterinsurgency operations. 1 Aug 69 to 31 Oct 69.  **AUTOMIN(First name, middle initial, fast name)  CO, 11th Transportation Battalion  **REPORT VALIT  1 November 1969  22  **AUTOMIN OF PARTS  1 November 1969  3 A. TOTAL HO. OF PARTS  1 November 1969  4 Oct THE REPORT NOUS (Any other numbers that may be assigned this report)  **AUTOMIN (Any other numbers that may be assi	HO. DACSFOR, DA. Washington, D.C. 20310				
Operational Report - Lessons Learned, HQ, 11th Transportation Battalion  - Obscriptive Notes (Type of report and inclusive dates)  Experiences of unit engaged in counterinsurgency operations, 1 Aug 69 to 31 Oct 69.  **Authority increase, middle inclusive has now included and inclusive and included and i	ing, choston, but, washington, bior 20010				
Operational Report - Lessons Learned, HQ, 11th Transportation Battalion  - GESCHIPTIVE NOTES (Type of report and militarine dates)  Experiences of unit engaged in counterinsurgency operations, 1 Aug 69 to 31 Oct 69.  - AUTHORNI (First news). middle India. Institutes)  CO, 11th Transportation Battalion  - REPORT GAIS  - REPORT OAIS  - REPORT OAIS  - REPORT OAIS  - REPORT OAIS  - NA  - OACSFOR, DA, Washington, D.C. 20310  - SETTEMBUTION STATEMENT  - NA  - OACSFOR, DA, Washington, D.C. 20310  - OACSFOR, DA, Washington, D.C. 20310	3. REPORT TITLE				
DESCRIPTIVE NOTES (Type of report and inclusive dates)  Experiences of unit engaged in counterinsurgency operations, 1 Aug 69 to 31 Oct 69.  **AUTHORIBUTION seeds, middle initial, last news)  CO, 11th Transportation Battalion  **REPORT UAIE  1 November 1969  22  1 NOVEMBER 1969  22  23  4 OCTIVER REPORT NOTES (Any other numbers that may be easigned date report)  A PROJECT NO.  N/A  COUNTER REPORT NOTES (Any other numbers that may be easigned date report)  A OCTIVER REPORT NOTES (Any other numbers that may be easigned date report)  OACSFOR, DA, Washington, D.C. 20310  D. ABSTRACT  D. PORM 1472		acion.			
DESCRIPTIVE NOTES (Type of report and inclusive dates)  Experiences of unit engaged in counterinsurgency operations, 1 Aug 69 to 31 Oct 69.  **AUTHORIBUTION seeds, middle initial, last news)  CO, 11th Transportation Battalion  **REPORT UAIE  1 November 1969  22  1 NOVEMBER 1969  22  23  4 OCTIVER REPORT NOTES (Any other numbers that may be easigned date report)  A PROJECT NO.  N/A  COUNTER REPORT NOTES (Any other numbers that may be easigned date report)  A OCTIVER REPORT NOTES (Any other numbers that may be easigned date report)  OACSFOR, DA, Washington, D.C. 20310  D. ABSTRACT  D. PORM 1472	Operational Report - Lessons Learned, HO.	11th Transportation Battalion			
EXPERIENCES Of Unit engaged in counterinsurgency operations, 1 Aug 69 to 31 Oct 69.  ** AUTHORIT (Pinz names, middle initial, last names)  CO, 11th Transportation Battalion  ** REPORTUAIS  10. NOTAL NO. OF PAGES  12. 10. OF PAGES  12. 10. OF PAGES  13. OF PAGES  14. OF PAGES  15. OF PAGES  16. OF PAGES  16. OF PAGES  17. SUPPLEMENTARY NOTES  N/A  18. SPONSORING MILITARY ACTIVITY  OACSFOR, DA, Washington, D.C. 20310  18. ABSTRACT  20. OACSFOR, DA, Washington, D.C. 20310					
CO, 11th Transportation Battalion  5. REPORT UAIS 1 NOVEMBER 1969 22 50. CONTRACT OR GRANT NO. 5. PROJECT NO. N/A 6. DOTHER REPORT NOISI (Any other mambers that may be assigned as report NOISI (Any					
1. NEPORT 1969 2. CONTRACT OR GRANT NO.  5. PROJECT NO.  N/A  1. SUPPLEMENTARY NOTES  N/A  20	Experiences of unit engaged in counterinsu  s. Author(s) (First name, middle initial, last name)	rgency operations, 1 Aug 69 to 31 Oct 69.			
1. NEPORT 1969 2. CONTRACT OR GRANT NO.  5. PROJECT NO.  N/A  1. SUPPLEMENTARY NOTES  N/A  20					
1. NEPORT 1969 2. CONTRACT OR GRANT NO.  5. PROJECT NO.  N/A  1. SUPPLEMENTARY NOTES  N/A  20	CO, 11th Transportation Battalion				
1 November 1969  5. PROJECT NO.  N/A  C.  D. OTHER REPORT NOIS (Any other numbers that may be assigned mile repert)  11. SUPPLEMENTARY NOTES  N/A  12. SPONSORING MILITARY ACTIVITY  OACSFOR, DA, Washington, D.C. 20310  13. ABSTRACT					
SE. CONTRACT OR GRANT NO.  S. PROJECT NO.  N/A  C.  SD. ORIGINATOR'S REPORT NUMBERIS)  694050  SD. OTHER ST. OTHER ST. OTHER NUMBERIS  694050  SD. OTHER ST. OTHER ST. OTHER NUMBERIS  694050  SD. OTHER ST. OTHER					
694050  D. OTHER REPORT NOIS (Any other numbers that may be sessigned define report)  II. SUPPLEMENTARY NOTES  N/A  OACSFOR, DA, Washington, D.C. 20310  II. ABBYRACT					
N/A  50. OTHER REPORT NOIS) (Any other mumbers that may be assigned  4.  10. DISTRIBUTION STATEMENT  N/A  OACSFOR, DA, Washington, D.C. 20310  13. ABSTRACT	B. CONTRACT OR GRANT NO.	DE ORIGINATOR'S REPORT NUMBER(S)			
TI. SUPPLEMENTARY NOTES  N/A  12. SPONSORING MILITARY ACTIVITY  OACSFOR, DA, Washington, D.C. 20310	8. PROJECT NO.	60/050			
TI. SUPPLEMENTARY NOTES  N/A  DACSFOR, DA, Washington, D.C. 20310  13. ABSTRACT  20	N/A	094030			
10. DISTRIBUTION STATEMENT  11. SUPPLEMENTARY NOTES  N/A  OACSFOR, DA, Washington, D.C. 20310  13. ABSTRACT  20	с.	9b. OTHER REPORT NOIS) (Any other numbers that may be exalgred this report)			
10. DISTRIBUTION SYSTEMENT  11. SUPPLEMENTARY NOTES  N/A  OACSFOR, DA, Washington, D.C. 20310  13. ABSTRACT  20					
11. SUPPLEMENTARY NOTES  N/A  OACSFOR, DA, Washington, D.C. 20310  13. ABSTRACT  20					
N/A OACSFOR, DA, Washington, D.C. 20310	TO. DISTRIBUTION STATEMENT				
N/A OACSFOR, DA, Washington, D.C. 20310					
N/A OACSFOR, DA, Washington, D.C. 20310					
13. ABSTRACT  20	11. SUPPLEMENTARY NOTES	12. SPONSORING MILITARY ACTIVITY			
13. ABSTRACT  20		·			
20 FOR 14.73	N/A	OACSFOR, DA, Washington, D.C. 20310			
DD 10m 1472	19. ADSTRACT				
DD 10m 1472					
DD 10m 1472					
DD 10m 1472					
DD 10m 1472					
DD 10m 1472					
DD 10m 1472	•				
DD 10m 1472					
DD 10m 1472					
DD 10m 1472					
DD 10m 1472					
DD 10m 1472					
DD 10m 1472					
DD 10m 1472					
DD 10m 1472		· ·			
DD 10m 1472					
DD 10m 1472					
DD 10m 1472					
DD 10m 1472					
DD rom 1473	2	0			
DD FOR 1473					
	DD 100 1473	UNCLASSIFIED			

UNCLASSIFIED
Security Classification