BTIC FILE COPY








Hexavalent Chromium Reduction Pretreatment Process Evaluation Randolph AFB TX

NANCY S. HEDGECOCK, 1Lt, USAF, BSC

SEPTEMBER 1990

Final Report




Distribution is unlimited; approved for public release

AF Occupational and Environmental Health Laboratory (AFSC)
Human Systems Division
Brooks Air Force Base, Texas 78235-5501

90 11 19 199

ISCLAIMER NOTICE



THIS DOCUMENT IS BEST QUALITY AVAILABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

NOTICES

When Government drawings, specifications, or other data are used for any purpose other than a definitely related Government procurement operation, the Government incurs no responsibility or any obligation whatsoever. The fact that the Government may have formulated, or in any way supplied the drawing, specifications, or other data, is not to be regarded by implication, or otherwise, as in any manner licensing the holder or any other person or corporation; or conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

The mention of trade names or commercial products in this publication is for illustration purposes and does not constitute endorsement or recommendation for use by the United States Air Force.

The Public Affairs Office has reviewed this report, and it is releasable to the National Technical Information Service, where it will be available to the general public, including foreign nations.

This report has been reviewed and is approved for publication.

Air Force installations may direct requests for copies of this report to: Air Force Occupational and Environmental Health Laboratory (AFOEHL) Library, Brooks AFB TX 78235-5501.

Other Government agencies and their contractors registered with the DTIC should direct requests for copies of this report to: Defense Technical Information Center (DTIC), Cameron Station, Alexandria VA 22304-6145.

Non-Government agencies may purchase copies of this report from: National Technical Information Service (NTIS), 5285 Port Royal Road, Springfield VA 22161

Consultant, Bioenvironmental

Engineering

NANCY S. HEDGECOCK, ILt, USAF, BSC EDWIN C. BANNER III, Colonel, USAF, BSC Chief, Environmental Quality Division

REPORT DOCUMENTATION PAGE

Form Approved
OMB No 0704-0188


Public reporting burden for this collection of information is estimated to average. I neur per response unriging the time for reviewing instructions collections gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden instruste or un, other aspect of this collection of information, including suggestions for reducing this burden. Washington Headquarters Services Turneforate for information on Originations and Reputs. 1215 Defferson Davis Holdway Suite 1294, Artington, VAI 12204-4302 and to the Office of Management and Budget. Paperwork Reduction Project 10 (64-0198), Washington Levillation (College) and College of Management and Budget. Paperwork Reduction Project 10 (64-0198), Washington Levillation (College) and College of Management and Budget. Paperwork Reduction Project 10 (64-0198), Washington Levillation (College) and College of Management and Budget. Paperwork Reduction Project 10 (64-0198), Washington Levillation (College).

collection of information, including suggestions t Davis Highway, Suite 1204, Arlington, VA, 72202-	4302, and to the Office of Management and	Budget Paperwork Reduction Pro	jert (0704-01)	38) Washington EC 20503	
1. AGENCY USE ONLY (Leave blank	September 1990	3. REPORT TYPE AN Final	D DATES 11 May		
4. TITLE AND SUBTITLE	3eptember 1990	1 11101		DING NUMBERS	
Hexavalent Chromium Re- Evaluation, Randolph A 6. AUTHOR(S)		Process			
Nancy S. Hedgecock, 1L	t, USAF, BSC				
7. PERFORMING ORGANIZATION NA	ME(S) AND ADDRESS(ES)		_	ORMING ORGANIZATION RT NUMBER	
AF Occupational and Environmental Health Laboratory Brooks AFB TX 78235-5501			AF0EHL Report 90-165EQ00163JHH		
9. SPONSORING/MONITORING AGE	NCY NAME(S) AND ADDRESS(ES)	10. SPONSORING MONITORING AGENCY REPORT NUMBER		
Same as Blk 7					
11. SUPPLEMENTARY NOTES		··	L	 	
12a. DISTRIBUTION / AVAILABILITY S	TATEMENT		126. DIS	TRIBUTION CODE	
Statement A. Unlimite	d, approved for publ	ic release			
13. ABSTRACT (Maximum 200 words)		<u> </u>		
appropriate percentage Pretreatment personnel	valuation at Randolph luate an experimenta etermine if base pers it would no longer be: (1) Obtain appro cyanide removal on ea solution before disch analyze the sludge	n AFB (RAFB) on 1 l in-situ chromic sonnel could safe be considered a b oval from TWC to ach drum of waste narging the waste for hexavalent ch	ll May um redu ely and nazardo perfor e; (3) ewater nromium	90. The scope of action process. I effectively treat ous waste. In the pretreatment Do not mix the to the sanitary 1; (5) Sample and 114 works; (6)	
14. SUBJECT TERMS Hexavalent chromium	pretreatment proces	ss evaluation		15. NUMBER OF PAGES	
Experimental in-situ chromium reduction process Randolph AFB				16. PRICE CODE	
17. SECURITY CLASSIFICATION 11 OF REPORT	8. SECURITY CLASSIFICATION OF THIS PAGE	19. SECURITY CLASSIFI OF ABSTRACT	CATION	20. LIMITATION OF ABSTRACT	
Unclassified	Unclassified	Unclassified		none	

(This page left blank)

ACKNOWLEDGMENT

The author greatly appreciates the hardwork provided by the entire sampling team during the survey at Randolph AFB. I would also like to thank Capt Shaffer, Chief, Bioenvironmental Engineering, and his staff for performing industrial hygiene monitoring during the survey and 12 FTW/MALE personnel for their assistance during the survey.



CONTENTS

		Page
	Std Form 298 Acknowledgment	i i i i
I.	INTRODUCTION	1
[[.	DISCUSSION	1
	A. Base DescriptionB. BackgroundC. In-situ Treatment ProcessD. Survey ProceduresE. Results	1 1 1 2 4
III.	CONCLUSIONS	4
IV.	RECOMMENDATIONS	5
	References	6
	APPENDIX Request Letter	. 7
	Distribution List	11

I. INTRODUCTION

On 2 April 1990, Headquarters Air Training Command (ATC) requested that the Air Force Occupational and Environmental Health Laboratory, Environmental Quality Branch (AFOEHL/EQE) evaluate an experimental in-situ chromium reduction process at Randolph AFB (see Appendix). The objective of the survey was to determine if base personnel could safely and effectively treat the chromium waste so that it would no longer be considered a hazardous waste.

The survey was conducted by Capt Linda B. Albrecht, 1Lt Nancy S. Heugecock. 1Lt Shelia P. Scott, and Amn Christopher Feagin on 11 May 1990.

II. DISCUSSION

A. Base Description

Randolph AFB is located in San Antonio, Texas and is the home of the 12th Flying Training Wing, Headquarters ATC, Air Force Recruiting Service, and Air Force Manpower and Personnel Center.

B. Background

Prior to 1990, Randolph AFB Corrosion Control personnel stripped paint from aircraft using methylene chloride. The stripper was rinsed from the aircraft using copious amounts of water and discharged to the sanitary sewer. After stripping, the aircraft was treated with alodine (50% chromic acid) to prime the aluminum surface for painting. The process rinsewater was discharged to the sanitary sewer. Later, Corrosion Control personnel began collecting and drumming the waste methylene chloride, alodine, and rinsewater. This procedure produced 700 drums of hazardous waste in a very short time.

To eliminate the methylene chloride from the wastestream, all aircraft are now stripped using plastic bead blasting. However, the alodine treatment waste is still a hazardous waste due to hexavalent chromium concentrations. The base is in the process of purchasing (within the year) an alodine pretreatment process. The pretreatment process will reduce the hexavalent chromium to trivalent chromium. The waste can then be discharged to the sanitary sewer.

During the interim, 12 FTW/MALE has devised an in-situ treatment process to reduce the hexavalent chromium in the alodine treatment waste to trivalent chromium. Trivalent chromium is not a regulated hazardous waste.

C. In-situ Treatment Process

Randolph AFB Corrosion Control personnel strip paint from aircraft using plastic media blasting. The stripped planes are then treated with alodine to prime the aluminum surfaces for painting. The alodine waste is put into 55-gallon drums for pretreatment.

Cyanide removal is performed by adding approximately 10 ml Clorox bleach to the drum contents and bubbling the solution for 10 minutes before beginning the chromium pretreatment process.

The caromium pretreatment process is as follows:

- 1. An air bubbling device is placed in the drum and connected to an air line.
- 2. Sulfuric acid is added until a pF of 2 is reached (hexavalent chromium is reduced to trivalent chromium).
- 3. Sodium bisulfite is added to the solution forming chromium hydroxide.
- 4. Sodium hydroxide is added to raise the pH to 10 (causing the chromium hydroxide to flocculate and settle to the bottom of the drum).

After the pretreatment process, the resulting wastewater is pumped through a sand filter and discharged to the sanitary sewer. The base plans to dispose of the sludge as hazardous waste.

D. Survey Procedures

Ten drums were selected for a pretreatment process trial run. The drums were numbered 1-10. Drums 1, 2, and 4 contained chromium trioxide. Drums 3, 5, 6, and 10 contained alodine waste. Drums 7, 8, and 9 contained alodine mixed with methylene chloride (from the old stripping process). Pretreatment was not attempted on drums 7, 8, or 9. Samples were taken from each drum using a composite liquid waste sampler (COLIWASA) before and after pretreatment (see Figure). The samples were analyzed for cyanide, total chromium, and hexavalent chromium. Analyses were performed at AFOEHL. Table 1 contains the analytical and preservation methods used.

TABLE 1. ANALYSIS AND PRESERVATION METHODS

Analysis	Preservation	Method	
Cyanide	H ₂ S	A412D	
Total Chromium	HNO ₃	E218	
Hexavalent Chromium	HNO ₃	A312A	

Note: A - Standard Methods for the Evaluation of Water and Wastewater

E - EPA Methods for Chemical Analysis of Water and Wastes



Figure: Survey Sampling Procedures

E. Results

In this section the analytical results before and after pretreatment will be reviewed. Hexavalent chromium results will be compared to the chromium limit (5.0 mg/L) set forth in 40 CFR Part 261.24. Total chromium results include both hexavalent and trivalent chromium content and are for information only. Cyanide results are provided as information to be used for personnel health and safety purposes. Table 2 contains analytical results for each waste drum.

TABLE 2. ANALYTICAL RESULTS Cyanide, Total Chromium, and Hexavalent Chromium Concentrations (mg/L)

DRUM	$[CN]_{\underline{i}}^{-}$	[CN]	Tot[Cr] _i	Tot[Cr] _f	[cr ⁺⁶] _i	[Cr ⁺⁶] _f
1	0.018	-	1135.0	-	1135.0	-
2	0.040	0.018	119.5	966.0	75.0	1420.0
3	5.0	· • ·	103.4	170.7	132.0	<0.05
4	0.068	0.025	124.0	-	124.0	-
5	5.0	<0.005	87.4	170.6	93.0	<0.05
6	10.0	-	109.0	116.0	117.0	<0.05
10	1.625	-	23.9	40.8	11.25	<0.05
LEGEND:						_

 $[CN]_{\underline{i}}$ - initial cyanide concentration (mg/l) - final cyanide concentration (mg/l)

 $Tot[Cr]_{i}$ - initial total chromium concentration (mg/1)

Tot[Cr] - final total chromium concentration (mg/l)

Totto:

[Cr⁺⁶]
- into:
- final hexavalence
- sample not taken - initial hexavalent chromium concentration (mg/l) final hexavalent chromium concentration (mg/l)

III. CONCLUSIONS

- A. Analysis of Drums 1, 2, and 4. Drums 1, 2, and 4 contained chromium trioxide. Pretreatment was attempted on Drum 2, but it could not be accomplished because the pH could not be lowered using sulfuric acid. Since pretreatment was not possible on Drum 2, it was not attempted on Drums 1 or 4. The cyanide concentrations were low (0.018, 0.04, and 0.068 mg/L, respectively). The initial hexavalent chromium concentrations (1135.0, 75.0, and 124.0 mg/L, respectively) exceed the limit (5.0 mg/L). Drum 2 final hexavalent chromium concentration of 1420.0 mg/L exceeds the limit (5.0 mg/L). The final concentration is greater than the initial concentration because the initial sample was taken before the sludge at the bottom of the drum was mixed into solution with the air bubbler.
- B. Analysis of Drums 3, 5, 6, and 10. Drums 3, 5, 6, and 10 contain alodine waste. Cyanide removal was performed on Drum 5. The initial cyanide concentration (5.0 mg/L) was low. After cyanide removal, the cyanide

concentration (<0.005 mg/L) was below analytical detection limits. The initial hexavalent chromium concentrations (132.0, 93.0, 117.0 and 11.25 mg/L, respectively) exceed the limit (5.0 mg/L). Pretreatment was performed on each drum. The final hexavalent chromium concentrations (<0.05 mg/L) were below analytical detection limits and do not exceed the limit (5.0 mg/L). Therefore, the analysis performed on this limited number of drums shows that the process effectively removes cyanide and reduces hexavalent chromium to trivalent chromium.

C. Depending on the quantity of waste generated, the sampling strategy using 10 drums may not be an adequate number of samples to statistically prove that the process works.

IV. RECOMMENDATIONS

- A. The base should assure that the pretreatment process is fully sanctioned by the Texas Water Commission (TWC). Also the base should develop a waste analysis plan for the pretreatment process which includes the percentage of pretreated drums that should be sampled in order to further verify that the pretreatment process routinely works. The waste analysis plan should be approved by the TWC. According to base personnel, the TWC will approve the pretreatment process upon receipt of analytical results showing that the process does indeed work. The pretreatment process is a rather primitive one; however, it does effectively reduce the hexavalent chromium to trivalent chromium.
- B. Cyanide removal should be performed on each drum before chromium reduction. The removal process is simple and eliminates the possibility of the final wastestream containing cyanide.
- C. Care should be taken when moving the drums after the pretreatment process. It is possible for the gelatinous metal precipitate to go back into solution, especially if the solution is mixed or allowed to sit for a long period of time. Therefore, the pretreatment process should be performed as close to the point where the wastewater will be discharged to the sanitary sewer as possible. Also, the wastewater should be discharged to the sanitary sewer as soon after pretreatment as possible.
- D. The sludge should be sampled and analyzed to determine if it contains any hexavalent chromium. If the sludge contains hexavalent chromium at concentrations above the limit (5.0 mg/L), it should be disposed as hazardous waste. If the hexavalent chromium concentration is below the limit, the sludge can be disposed as municipal waste.
- E. Bioenvironmental Engineering should continue to monitor the air for cyanide and chromic acid mist on a routine basis.
- F. Pretreatment personnel should always wear faceshields, gloves, and aprons during the process. Extreme caution should be taken when adding chemicals to the drums.

References

- 1. Electroplating Wastewater Pollution Control Technology, George C. Cushnie, Jr., Pollution Technology Review No. 115, Noyes Publications, 1985.
- 2. Samplers and Sampling Procedures for Hazardous Waste Streams, EPA-600/2-80-018, Jan 1980.
- 3. United States Environmental Protection Agency, "Identification and Listing of Hazardous Waste," 40 CFR 261.

Appendix
Survey Request Letter

(This page left blank)

DEPARTMENT OF THE AIR FORCE



HEADQUARTERS AIR TRAINING COMMAND (ATC) RANDOLPH AIR FORCE BASE TX 78150-5001

2 APR 1990

ATTN 01 SGPB (7-3764)

SONDECT Request for On-Site Consultant Services - Randolph AFB

to USAF OEHL/CC

- 1. In accordance with the provisions of AFR 161-17, the attached request for consultant services is forwarded for your consideration. The Randolph bioenvironmental engineer is asking for an on-site survey of an experimental hazardous waste treatment procedure.
- 2. Their request for priority status has been overcome by events. HQ ATC/DEEV has provided the necessary funds to immediately dispose of the 700 drum inventory. Also, chemical paint stripping operations have been replaced at Randolph by bead blasting and once the existing drums of paint stripping wastes are disposed of, no more will be produced.
- 3. According to ATC/DEEV an alodine pretreatment process (similar to the one at Sheppard) will be instituted at Randolph within a year's time. Until then, the base would still like to proceed with testing their chromium treatment procedure. I believe that base bioenvironmental engineering personnel can conduct the industrial hygiene monitoring portion and I have informed Lt Shaffer of this.
- 4. The underlying assumption is that in-situ chrome reduction (to below 5 mg/l) of the alodine waste will render the waste non-hazardous and the resulting "process rinse water" can be disposed of through the sanitary sewer system. Recommend that your evaluation include an assessment of the disposal requirements for the final alodine waste stream.
- 5. I have asked Lt Shaffer to check with both the TAQ and the TWC to determine if the proposed demonstration treatment process requires preapproval or permitting by the State of Texas regulators.
- 6. Please feel free to contact the Randolph BEE office directly to set up consultant visit dates and to readjust the survey parameters in light of the recent developments.

DAVID A. HADDEN, Colonel, USAF, BSC Command Bioenvironmental Engineer

DCS/Medical Services & Training

Variet A. Haller

1 Atch USAF Clinic Randolph/SGPB Ltr, 29 Mar 90

cc: USAF Clinic Randolph/SGPB, wo atch

Distribution List

	Copies
HQ AFSC/SGPB Andrews AFB DC 20334-5000	1
HQ USAF/SGPA Bolling AFB DC 20332-6188	1
HQ ATC/SGPB Randolph AFB TX 78150-5001	2
HQ ATC/DEEV Randolph AFB TX 78150-5001	1
AAMRL/TH Wright-Patterson AFB OH 45433-6573	1
7100 CSW Med Cen/SGB APO New York 09220-5300	1
Det 1, AFOEHL APO San Francisco 96274-5000	1
USAFSAM/TSK Brooks AFB TX 78235-5301	1
USAFSAM/ED/EDH/EDZ Brooks AFB TX 78235-5301	1 ea
Defense Technical Information Center (DTIC) Cameron Station	0
Alexandria VA 22304-6145	2
HQ USAF/LEEV Bolling AFB DC 20330-5000	1
HQ AFESC/RDV Tyndall AFB FL 32403-6001	1
USAF Clinic Randolph/SGPB Randolph AFB TX 78150-5000	2
12 FTW/MALE Randolph AFB TX 78150-5000	2
HSD/XA Brooks AFB TX 78235-5000	1