# UNCLASSIFIED

# AD NUMBER

## AD805278

## LIMITATION CHANGES

# TO:

Approved for public release; distribution is unlimited.

# FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors; Administrative/Operational Use; SEP 1966. Other

requests shall be referred to Air Force Flight Dynamics Lab., Wright-Patterson AFB, OH 45433.

# AUTHORITY

AFFDL ltr 29 Dec 1971

THIS PAGE IS UNCLASSIFIED

AFFDL-TR-66-43 PART XI

805278

# **AIRCRAFT GROUND-FLOTATION INVESTIGATION**

## PART XI -- DATA REPORT ON TEST SECTION 10

W. BRABSTON and W. HILL, JR.

U. S. ARMY ENGINEER WATERWAYS EXPERIMENT STATION

4 85

TECHNICAL REPORT AFFDL-TR-66-43, PART XI

#### **SEPTEMBER 1966**

This document is subject to special export controls and each transmittal to foreign governments or foreign nationals may be made only with prior approval of the Air Force Flight Dynamics Laboratory (FDFM), Wright-Patterson AFB, Ohio, 45433.

AIR FORCE FLIGHT DYNAMICS LABORATORY RESEARCH AND TECHNOLOGY DIVISION AIR FORCE SYSTEMS COMMAND WRIGHT-PATTERSON AIR FORCE BASE, OHIO NOTICES

When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication or otherwise as in any manner-licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

100

Copies of this report should not be returned to the Research and Technology Division unless return is required by security considerations, contractual obligations, or notice on a specific document.

200 - December 1966 - C0192-15-275

il.

# AIRCRAFT GROUND-FLOTATION INVESTIGATION

## PART XI - DATA REPORT ON TEST SECTION 10

W. BRABSTON and W. HILL, JR.

This document is subject to special export controls and each transmittal to foreign governments or foreign nationals may be made only with prior approval of the Air Force Flight Dynamics Laboratory (FDFM), Wright-Patterson AFB, Ohio, 45433.

#### FOREWORD

The investigation described herein constitutes one phase of studies conducted during 1964 and 1965 at the U. S. Army Engineer Waterways Experiment Station (WES) under U. S. Air Force Project No. 410-A, MIPR No. AS-4-177, "Development of Landing Gear Design Criteria for the CX-HIS Aircraft." (The CX-HIS is now designated C-5A.) This program was sponsored and directed by the Landing Gear Group, Air Force Flight Dynamics Laboratory, Research and Technology Division, Mr. R. J. Parker, Project Engineer.

These tests were conducted by personnel of the WES Flexible Pavement Eranch, Soils Division, under the general supervision of Messrs. W. J. Turnbull, A. A. Maxwell, and R. G. Ahlvin, and the direct supervision of Mr. D. N. Brown. Other personnel actively engaged in this study were Messrs. C. D. Burns, D. M. Ladd, W. N. Brabston, H. H. Ulery, Jr., and W. J. Hill, Jr. This report was prepared by Messrs. Brabston and Hill.

Directors of WES during the conduct of this investigation and preparation of this report were Col. Alex G. Sutton, Jr., CE, and Col. John R. Oswalt, Jr., CE. Technical Director was Mr. J. B. Tiffany.

Publication of this technical documentary report does not constitute Air Force approval of the report's findings or conclusions. It is published only for the exchange and stimulation of ideas.

スマシ

KENNERLY H. DIGGES Chief, Mechanical Branch Vehicle Equipment Division AF Flight Dynamics Laboratory

#### ABSTRACT

This data report describes work undertaken as part of an overall program to develop ground-flotation criteria for the C-5A aircraft. A test section was constructed to a width adequate for two test lanes. Each lane was divided into two items having different subgrade CBR values and different traffic surfaces. Item 1 was surfaced with modified Tll aluminum landing mat and item 2 with M8 steel landing mat. Both traffic lanes were subjected to traffic of a single-wheel load assembly consisting of one  $56 \times 16$ , 32-ply aircraft tire inflated to 250 psi. A 50,000-lb load was used on one lane and a 75,000-lb load on the other lane.

The information reported herein includes layout of the test lanes, characteristics and print dimensions of the load assembly tires, and data collected on soil strengths, surface deformations and deflections, and drawbar pull. The traffic-coverage level is given at which each test item was considered failed.

## CONTENTS

Dat	-
PR	ve.
	<u> </u>

SECTION I: INTRODUCTION	1
SECTION II: DESCRIPTION OF TEST SECTION AND LOAD VEHICLE	2
Description of Test Section	2 2
SECTION III: APPLICATION OF TRAFFIC, FAILURE CRITERIA, AND DATA COLLECTED	3
Application of Traffic	3 3
SECTION IV: BEHAVIOR OF ITEMS UNDER TRAFFIC AND TEST RESULTS	5
Lane 23A	5 6
SECTION V: PRINCIPAL FINDINGS	8

iv

## ILLUSTRATIONS AND TABLES

1.	Application of traffic on Test Section 10	3
2.	Test load vehicle	11
3.	Lanes 23A and 23B, item 1, prior to traffic	11
4.	Lane 23A, item 1. Transverse straightedge shows	
	roughness at 32 coverages (failure)	12
5.	Lanes 23A and 23B, item 2, prior to traffic	12
6.	Lane 23A, item 2. Transverse straightedge shows	
	roughness at 2 coverages (failure)	13
7.	Lane 23B, item 1. Transverse straightedge shows	
	roughness at 4 coverages (failure)	13
8.	Lane 23B, item 2. Transverse straightedge shows	
	roughness at 2 passes (failure)	14
9.	Layout of Test Section 10 and summary of test results	15
10.	Layout of surfaced items	16
11.	Tire-print dimensions and tire characteristics	17
12.	Average cross-section deformations	18
13.	Permanent profile deformations	10
14.	Average deflections	20
		20

## Table

Figure

1.	Summary of Traffic Data,	Test Section 10	9
2.	Summary of CBR, Density,	and Water Content Data,	_
	Test Section 10		10

v

#### SUMMARY

Tests on Section 10 are one phase of a comprehensive research program to develop ground-flotation criteria for heavy cargo-type aircraft. Section 10 was laid out to accommodate two test lanes, lanes 23A and 23B, each of which was divided into two items having different subgrade CBR values and different traffic surfaces (figure 9). Item 1 was surfaced with modified TLI aluminum landing mat and item 2 with M8 steel landing mat. Both lanes were subjected to traffic of a single-wheel load assembly consisting of one 56x16, 32-ply aircraft tire inflated to 250 psi. A 50,00 lb load was used on lane 23A and a 75,000-lb load was used on lane 23B. Figure 11 gives pertinent tire-print dimensions and tire characteristics.

The lanes were trafficked to failure in accordance with criteria designated in Part I of this report. Data were recorded throughout testing to give a behavior history of each item. Using the test criteria mentioned above, it was possible to directly compare the effects of trafficking with different loads on a single-wheel assembly. Basic performance data are summarized in the following paragraphs.

#### Lane 23A

Item 1

The item was considered failed due to roughness at 32 coverages. The rated CBR of the item was 3.0.

#### Item 2

The item was considered failed due to roughness at 2 coverages. The rated CBR of the item was 3.8.

## Lane 23B

## Item 1

The item was considered failed due to roughness at 4 coverages. The rated CBR of the item was 3.5.

#### Item 2

The item was considered failed due to roughness after 2 passes of the load vehicle. The rated CBR of the item was 3.9.

#### AIRCRAFT GROUND-FLOTATION INVESTIGATION

#### PART XI DATA REPORT ON TEST SECTION 10

#### SECTION I: INTRODUCTION

The investigation reported herein is one phase of a comprehensive research program being conducted at the U. S. Army Engineer Waterways Experiment Station (WES), Vicksburg, Miss., as part of U. S. Air Force Project No. 410-A, MIPR No. AS-4-177, to develop ground-flotation criteria for the C-5A, a heavy cargo-type aircraft. Specifically, the tests reported herein were conducted to compare the trafficking effect on landing mat surfaces of a single-wheel landing-gear assembly carrying different test loads.

Prosecution of this investigation consisted of constructing two similar traffic lanes and subjecting them to traffic of a single-wheel tracking assembly with test loads of 50,000 and 70,000 lb.

This report presents a description of the test section and wheel assembly, and gives results of traffic. Equipment used, types of data and method of recording them, and general test criteria are summarized in this part; more complete explanations and illustrations appear in Part I of this report.

#### SECTION II: DESCRIPTION OF TEST SECTION AND LOAD VEHICLE

#### Description of Test Section

Test Section 10 (figure 9) was constructed within a roofed area in order to allow control of the subgrade CBR (California Bearing Ratio) in the test items. In construction of the test section, an 80- by 36-ft area was excavated to a depth of 24 in. and then backfilled in five compacted lifts with a heavy clay soil (buckshot; classified as CH according to the Unified Soil Classification System, MIL-STD-619). The fill material used was a local clay with a plastic limit of 27, liquid limit of 58, and plasticity index of 31. Gradation and classification data for the subgrade material are given in Part I.

Two traffic lanes, each divided into two items, were constructed in the test section. Different subgrade strengths were obtained in the items (figure 9) by controlling the water content and compaction effort. Item 1 was surfaced with modified T11 aluminum landing mat and item 2 with M8 steel landing mat (figure 10). The landing mats used are described and illustrated in Part I.

#### Loaa Vehicle

The load vehicle used for trafficking Section 10 is shown in figure 2. Load cart construction, details of linkage between the load compartment and prime mover, and method of applying load are explained in Part I. For trafficking lanes 23A and 23B, a single-wheel assembly was used with 50,000- and 75,000-lb loads, respectively. A 56x16, 32-ply aircraft tire with a 250-psi tire inflation pressure was used on both lanes. Tire-print data and pertinent tire characteristics are given in figure 11.

#### SECTION III: APPLICATION OF TRAFFIC, FAILURE CRITERIA, AND DATA COLLECTED

#### Application of Traffic

The load vehicle was operated to produce uniform traffic coverage on the test lanes. The load cart was driven forward and backward along the same track, then shifted laterally and the forward-backward operation repeated. In this manner, two coverages of traffic were applied to the test lane as the vehicle progressed from one side of the lane to the other. Figure 1 is representative of the general method of applying uniform coverages to the test lanes.



LANE 23A

LANE 238

Figure 1. Application of traffic on Test Section 10

#### Failure Criteria and Data Collected

Failure criteria used in this investigation and descriptive terms used in presentation and discussion of data in all parts in this report are presented in Part I. A general outline of types of data collected is given in the following paragraphs. Details on apparatus and procedure for obtaining specific measurements are given in Part I.

#### CBR, water content, and dry density

CBR, water content, and dry density of the subgrade were measured for each test item prior to application of traffic, at intermediate coverage levels, and at failure. After traffic was concluded on an item, a measure of subgrade strength termed "rated CBR" was determined. Rated CBR is generally the average CBR value obtained from all the determinations made in the top 12 in. of soil during the test life of an item. In certain instances, extreme or irregular values may be ignored if the analyst decides that they are not properly representative.

#### Surface roughness, or differential deformation

Surface roughness, or differential deformation, measurements were made using a 10-ft straightedge at various traffic-coverage levels on all items. Dishing effects of individual mat panels were recorded.

#### Deformations

Deformations, defined as permanent cumulative surface changes in cross section or profile of an item, were charted by means of level readings at pertinent traffic-coverage levels.

#### Deflection

Deflection of the test surface under an individual static load of the tracking assembly was measured at various traffic-coverage levels. Level readings on the item surface on each side of the load wheel and on a pin and cap device directly beneath the load wheel provided deflection data. All mat deflection was for practical purposes recoverable, i.e. total deflection equaled elastic (spring-back) deflection. The pin and cap device for measuring deflection directly beneath load wheels was applied to the subgrade through a hole (existing or cut) in the mat.

#### Rolling resistance

Rolling resistance, or drawbar pull, measurements were performed with the load vehicle over each test item at designated coverage levels. Three types of drawbar measurements were taken: (a) maximum force required to overcome static inertia and commence forward movement of the load cart, termed "initial DBP"; (b) average force required to maintain a constant speed once the load vehicle is in motion, termed "rolling DBP"; and (c) maximum force obtained during the constant speed run, termed "peak DBP."

#### Mat breaks

Mat breaks were inspected, classified by type, and recorded at various coverage levels.

#### SECTION IV: BEHAVIOR OF ITEMS UNDER TRAFFIC AND TEST RESULTS

#### Lane 23A

#### Behavior of items under traffic

Item 1. Figure 3 shows item 1 prior to traffic. During the first 2 coverages, a large number of center-line rivets sheared. Traffic was continued to 32 coverages at which time the item was considered failed due to roughness (figure 4). The rated CBR for the item was 3.0.

Item 2. Figure 5 shows item 2 prior to traffic. The item deformed rapidly under traffic and at 2 coverages was considered failed due to roughness (figure 6). The rated CBR for the item was 3.8.

#### Test results

Results of trafficking lane 23A are summarized in table 1. Soil test data are given in table 2. Table 1 contains drawbar pull values for the load vehicle operated over an asphalt-paved strip for comparison with drawbar pull values recorded on the test lane.

Item 1. Item 1 was considered failed due to roughness at 32 coverages. A large number of center-line rivet failures occurred with trafficking. The following information was obtained from traffic tests on item 1.

- a. <u>Roughness</u>. Table 1 shows differential deformation measurements at 2 and 32 coverages. At failure the average transverse, diagonal, and longitudinal differential deformations were 3.09, 2.40, and 1.03 in., respectively. Dishing of individual mat panels averaged 0.36 in. at failure.
- b. <u>Deformations</u>. Figure 12 shows average cross-section deformations at 2 and 32 coverages for each of two typical mat runs. Figure 13 shows a profile plot of the item at the same coverage levels. Severe transverse differential deformations are evident and were the principal roughness factor contributing to failure.
- c. <u>Deflection</u>. Average elastic mat deflections under static load of the load wheel assembly for three positions of the assembly relative to mat end joints are plotted in figure 14. Deflection at 32 coverages was greatest for each position. Elastic soil deflection at failure was 1.6 in.
- d. <u>Rolling resistance</u>. Drawbar pull values recorded at 2 and 32 coverages are shown in table 1. No significant change in drawbar value occurred with trafficking.
- e. Mat breaks. The number and type of mat breaks resulting from

trafficking are given in table 1. A large number of center-line rivet failures were recorded at failure.

Item 2. Item 2 was considered failed due to roughness at 2 coverages. The following information was obtained from traffic tests on item 2.

- a. Roughness. Table 1 shows differential deformations a 2 coverages. Average values at failure were 1.22, 2.00, and 1.81 in. for transverse, diagonal, and longitudinal measurements, respectively. Dishing of individual mat panels was slight and averaged 0.25 in. at failure.
- b. Deformations. Average cross-section deformations at 2 coverages for two typical mat runs are plotted in figure 12. A very significant factor in cross-section deformations was the mat uplift along both sides of the lane. Figure 13 shows the longitudinal irregularities that contributed to early failure of the item.
- c. <u>Deflection</u>. Average elastic mat deflections under static load of the wheel assembly are plotted in figure 14 for three positions of the assembly relative to mat end joints.
- d. <u>Rolling resistance.</u> Drawbar pull values measured at 2 coverages are shown in table 1.
- e. <u>Mat breaks</u>. No mat breaks were observed after the item failed. The M8 mat conformed to the shape of the deformed subgrade without breaking.

#### Lane 23B

# Behavior of items under traffic

<u>Iter 1.</u> Figure 3 shows item 1 prior to traffic. The mat surface deformed and many rivet failures occurred with initial coverages. The item was considered failed due to roughness at 4 coverages with the prima failure factor being excessive transverse differential deformations (figure 7). The rated CBR for the item was 3.5.

Item 2. Figure 5 shows item 2 prior to traffic. The subgrade was severely deformed with the first pass of the load vehicle. The item was considered failed due to roughness after 2 passes (figure 8). The rated CBR for the item was 3.9.

#### Test results

Results of trafficking lane 23B are summarized in table 1. Soil test data are given in table 2. Table 1 contains drawbar pull values for the load vehicle operated over an asphalt-paved strip for comparison with drawbar pull values recorded on the test lane.

Item 1. Item 1 was considered failed due to roughness at 4 coverages. A large number of center-line rivet failures occurred with trafficking. The following information was obtained from traffic tests on item 1.

- a. <u>Roughness</u>. Table 1 shows the differential deformations that existed at failure of the item. The principal roughness factor was transverse differential deformation which averaged 3.47 in. at failure. Diagonal and longitudinal differential deformations averaged 3.19 and 1.03 in., respectively. Dishing of individual mat panels was slight, averaging 0.25 in. at failure.
- b. <u>Deformations</u>. Figure 12 shows average cross-section deformations at 4 coverages for two typical mat runs. Mat uplift at the lane edges contributed to the cross-section deformation. No profile deformation data were obtained on this item.
- c. <u>Deflection</u>. Average elastic mat deflections under static load of the wheel assembly for three positions of the assembly relative to mat end joints are plotted in figure 14. Only small differences in deflection occurred for the different positions.
- d. <u>Rolling resistance</u>. Drawbar pull values at 4 coverages are shown in table 1.
- e. <u>Mat breaks</u>. The number and type of mat breaks resulting from traffic are shown in table 1. Center-line rivet failures far exceeded other types of mat breaks.

Item 2. Item 2 was considered failed due to roughness after 2 passes of the load vehicle.

- a. <u>Roughness</u>. Table 1 shows maximum and average values of transverse differential deformation at 2 passes. The average measurement was 2.37 in. No measurements were made of longitudinal and diagonal differential deformations.
- b. Deformations, deflection, and rolling resistance. No measurements were made of cross-section and profile deformations, deflections, or rolling resistance.
- c. Mat breaks. No breaks occurred in the M8 mat with trafficking.

#### SECTION V: PRINCIPAL FINDINGS

From the foregoing discussion, the principal findings relating test load, wheel assembly, tire inflation pressure, surface type, subgrade CBR, and traffic coverages are as follows:

Load, Wheel Assembly, and Tire Pressure	Type of Surface	Rated Subgrade CBR	Coverages at Failure
50,000-1b load; single- wheel assembly; 56x16, 32-ply tire with 250-	Modified Tll aluminum mat	3.0	32
psi inflation pressure	M8 steel landing mat	3.8	2
75,000-1b load; single- wheel assembly; 56x16, 22 plu time with 250-	Modified Tll aluminum mat	3.5	14
psi inflation pressure	M8 steel landing mat	3.9	2 passes

		Remarks		Failed due to rough- ness at 32 cover- ages	Failed due to rough- ness at 2 coverages			Failed due to rough- ness at 4 coverages	Failed due to rough- ness at 2 passes	
	Elestic	Deflec- tion (in.)		1.6	1.9	8		2.0	8	1
	eflec- of ed on	Joint of Panel		2.0	2.5	ł		2.9	:	1
	iotal D (in.) wi r Line o Welf	Point of Panel		2. S	5.0	t		2.7	;	1
	Average tion Center Assembly	Point of Panel		1.6	3°.3	ł		5.7	8	;
		Roll-		2.9	2.4	1.0	٠	1.9	8	1.1
		(ltdps) Peak		4°T	5.8	3.1		8 6	8	4.2
DI 10	L C	Ini- tial		8.7	7.7	1.7		12.1	:	5.5
SECTION		ving v.)		0.31	0.25	:		0.25	:	1
TEST (	р.)	DLRI Mar		0.38 0.44	0.25	:		0.25	ł	8
DATA,		Avg	1e 23A	0.65 2.40	2.00	1	16 23B	3.19	8	:
WFFIC	tion (1	ALL A	Lar	0.75	2.25	1	Int	3.50	1	:
OF T	former	Avg		0.72	1.22	1		3.47	2.37	1
UNITAL CONTRACT	De la companya	Pra Max		0.88 3.38	1.50	8		°.4	3.00	:
63	Yerent	gi- inal Avg		0.59	1.81	8		1.03	1	
	H	Lon tud Max		0.63	2.25	ł		1.13	ł	1 <b>I</b> -
		* 64		11	:	1		CN .	1	8
		Brea				8 8		8	1	8
		Mat		93	8	ł		249	1	9
	e	5 ml		7 67	8	:		54	8	1
		21		1 10	8	t		8	1	8
		Rated CBR			3.0			3.5	3.9	
		Cover-		g v	Q			4	2 passes	
		Test Item		l sodified T11 aluminum landing mat	2 18 steel Landing mat	sphalt test strip		l bdifled T11 aluminum lending met	2 B steel lending mat	sphalt test strip

Note: A single-wheel assembly with a 56x16, 32-ply tire inflated to 250 psi was used for trafficking lanes 23A and 23B. The test loads were 50 and 75 kips for lanes 23A and 23B, respectively. \* Break types are defined and illustrated in Part I.

TABLE 1

4

Test Item#	Type of Surface	No. of Traffic Coverages	Depth (in.)	CBR	Water Content (%)	Dry Density (1b/cu ft)
		L	ane 23A			
1	Modified Tll aluminum landing mat	0	0 6 12 18	2.7 3.2 3.1 3.9	29.6 30.3 30.2 27.6	89.9 88.6 89.7 92.4
		32	0 6 12 18	2.8 3.1 2.8 3.8	30.9 29.5 30.5 26.8	89.5 91.5 90.2 93.3
2	M8 steel landing mat	0	0 6 12 18	3.8 3.5 3.3 3.6	28.6 28.2 28.3 30.1	90.8 91.7 91.4 89.4
		2	0 6 12 18	3.7 4.5 4.0 4.4	30.0 28.8 28.6 30.4	89.3 91.9 92.4 89.7
		L	ane 23B			
1	Modified Tll aluminum landing mat	0	0 6 12 18	2.7 3.2 3.1 3.9	29.6 30.3 30.2 27.6	89.9 88.6 89.7 92.4
		4	0 6 12 18	3.3 4.5 4.1 3.9	30.3 28.6 28.6 27.1	89.4 92.8 90.9 92.9
2	M8 steel landing mat	0	0 6 12 18	3.8 3.5 3.3 3.6	28.6 28.2 28.3 30.1	90.8 91.7 91.4 89.4
		2 passes	6 12 18	3.4 3.5 5.8 5.4	29 5 29,4 28,9 29.	90.9 91.5 91.5 92.6

TABLE 2 SUMMARY OF CER, DENSITY, AND WATER CONTENT DATA, TEST SECTION 10

Note: For coverage-failure information, see remarks column in table 1. \* Subgrade material was heavy clay (buckshot; classified as GH) in all items.



Figure 2. Test load vehicle



Figure 3. Lanes 23A and 23B, item 1, prior to traffic





Figure 6. Lane 23A, item 2. Transverse straightedge shows roughness at 2 coverages (failure)



Figure 7. Lane 23B, item 1. Transverse straightedge shows roughness at 4 coverages (failure)









A ......



ie.

Figure 12





Figure 14

UNCLASSIFIED			
Security Classification		-	
DOCUMENT CO	NTROL DATA - RE	D	the example second is also ailiadh
1. ORIGINATING ACTIVITY (Corporate author)		2a. REPO	AT SECURITY CLASSIFICATION
U. S. Army Engineer Waterways		NCLASSIFIED	
Experiment Station		28. enou	•
		1	
3. REPORT TITLE	madel and		and the second
Part VI Data Peport on Test Sect	gation		
FAIT AL DATA REPORT ON LESS DECK			
4. DESCRIPTIVE NOTES (Type of report and in "usive dates)			
Final Technical Report			
5. AUTHOR(3) (Leet name, first name, initial)			
Brabston, W. N.			
HIIL, W. J., Jr.			
S. REPORT DATE	74. TOTAL NO. OF P	AGES	75. NO. OF REFS
September 1960	20		
Se. CONTRACT OR GRANT NO.	Sa. ORIGINATOR'S RI	EPORT NUN	ABER(\$)
MIPR AS-4-177	A DEDT OD	66 13	Dente MT
4104	AFFUL-IK-	00-43,	PART AL.
c.	SA. OTHER REPORT	NO(3) (Any	other numbers that may be applied
	N N	one	
		Joot F	
trols and each transmittal to foreig	n dovernments	or fo	reign nationals may
be made only with prior approval of	the Air Force	Fliah	t Dynamics Laborator
(FDFM), Wright-Patterson AFB, Chio 4	5433.		
11. SUPPL EMENTARY MOTES	12. SPONSORING MILI	TARY ACT	IVITY
	Air Force	Flight	Dynamics Laboratory
	Kesearch a	nd Tec	nnology Division
13 ABCTBACT	Ar System	COMM	id, wrarb, outo
This data report describes the re	sults of work	under	taken as part of an
overall program to develop ground-fl	otation crite	ria fo	r the C-5A aircraft.
			and the second state of the second
		_	

Security Classification

#### UNCLASSIFIED

Security Classification

The Martin and a contract of the second s	LINK A		LINK D		LINK C	
KEY WORDS	ROLE	WT	ROLE	WT	ROLE	WT
Aircraft Ground Flotation Rolling Resistance Rear Area Airfields Support Area Airfields Forward Area Airfields Vehicle Mobility						

INSTRUCTIONS

1. ORIGINATING ACTIVITY: Enter the name and address of the contractor, subcontractor, grantee, Department of Defense activity or other organization (corporate author) issuing the report.

2a. REPORT SECURITY CLASSIFICATION: Enter the overall security classification of the report. Indicate whether "Restricted Data" is included. Marking is to be in accordance with appropriate security regulations.

25. GROUP: Automatic downgrading is specified in DoD Directive 5200.10 and Armed Forces Industrial Manual. Enter the group number. Also, when applicable, show that optional markings have been used for Group 3 and Group 4 as authorized.

3. **REPORT TITLE:** Enter the complete report title in all capital letters. Titles in all cases should be unclassified. If a meaningful title cannot be selected without classification, show title classification in all capitals in parenthesis immediately following the title.

4. DESCRIPTIVE NOTES: If appropriate, enter the type of report, e.g., interim, progress, summary, annual, or final. Give the inclusive date, when a specific reporting period is covered.

5. AUTHOR(S): Enter the same(s) of suthor(s) as shown on or in the report. Enter last name, first name, middle initial. If military, show same and branch of service. The name of the principal author is an absolute minimum requirement.

6. REPORT DATE: Enter the date of the report as day, month, year; or month, year. If more than one date appears on the report, use date of publication.

7a. TOTAL NUMBER OF PAGES: The total page count should follow normal pegination procedures, i.e., enter the number of pages containing information.

75. NUMBER OF REFERENCES: Enter the total number of references cited in the report.

8. CONTRACT OR GRANT NUMBER: If appropriate, enter the applicable number of the contract or grant under which the report was written.

86, 8c, 8 8d. PROJECT NUMBER: Enter the appropriate military department identification, such as project number, subproject number, system numbers, task number, etc.

9a. ORIGINATOR'S REPORT NUMBER(5): Enter the official report number by which the document will be identified and controlled by the originating activity. This number must be unique to this report.

9b. OTHER REPORT NUMBER(5): If the report has been assigned any other report numbers (either by the originator or by the sponsor), also enter this number(s).

10. AVAILABILITY/LIMITATION NOTICES: Enter any limitations on further dissemination of the report, other than those imposed by security classification, using standard statements such as:

- (1) "Qualified requesters may obtain copies of this report from DDC."
- (2) "Foreign announcement and dissemination of this report by DDC is not authorized."
- (3) "U. S. Government agencies may obtain copies of this report directly from DDC. Other qualified DDC users shall request through
- (4) "U. S. military agencies may obtain copies of this report directly from DDC. Other qualified users shall request through

(5) "All distribution of this report is controlled. Qualified DDC users shall request through

If the report has been furnished to the Office of Technical Services, Department of Commerce, for sale to the public, indicate this fact and enter the price, if known.

11. SUPPLEMENTARY NOTES: Use for additional explanatory notes.

12. SPONSORING MILITARY ACTIVITY: Enter the name of the departmental project office or laboratory sponsoring (paying for) the research and development. Include address.

13. ABSTRACT: Enter an abstract giving a brief and factual summary of the document indicative of the report, even though it may also appear elsewhere in the body of the technical report. If additional space is required, a continuation sheet shall be attached.

It is highly desirable that the abstract of classified reports be unclassified. Each paragraph of the abstract shall end with an indication of the military security classification of the information in the paragraph, represented as (TS), (S), (C), or (U).

There is no limitation on the length of the abstract. However, the suggested length is from 150 to 225 words.

14. KEY WORDS: Key words are technically meaningful terms or short phrases that characterize a report and may be used as index entries for cataloging the report. Key words must be selected so that no security classification is required. Identiflers, such as equipment model designation, trade name, military project code name, geographic location, may be used as key words but will be followed by an indication of technical context. The assignment of links, rules, and weights is optional.

> UNCLASS IF IBD Security Classification